SIXTH EDITION

TECHNICAL DRAWING
AND ENGINEERING COMMUNICATION



David L. Goetsch • William S. Chalk • John A. Nelson • Raymond L. Rickman

BOOK CONDITION LABEL

Allan Hancock College Bookstore

Title Of Book Technical drawing

Manager Signature J. Duea

Date 9/6/18

Book has: Binding worn & taped . Back Cover Taped On

Writing in ink _____

Minimal water damage (pages) _____

Minimal torn cover ✓ & torn bottom inside cover

Other back cover

Book will not be checked in or bought b

If any additional damage is noted upon r

TECHNICAL DRAWING
AND ENGINEERING COMMUNICATION

SIXTH EDITION

Digitized by the Internet Archive
in 2022 with funding from
Kahle/Austin Foundation

https://archive.org/details/technicaldrawing0000unse_d5k5

TECHNICAL DRAWING
AND ENGINEERING COMMUNICATION

SIXTH EDITION

David L. Goetsch • William S. Chalk
John A. Nelson • Raymond L. Rickman

DELMAR
CENGAGE Learning™

Australia • Brazil • Japan • Korea • Mexico • Singapore • Spain • United Kingdom • United States

DELMAR
CENGAGE Learning™

Technical Drawing and Engineering Communication, 6E
David L. Goetsch

Vice President, Career and Professional Editorial: Dave Garza
Director of Learning Solutions: Sandy Clark
Senior Acquisitions Editor: James DeVoe
Managing Editor: Larry Main
Editorial Assistant: Tom Best
Vice President, Career and Professional Marketing: Jennifer McAvey
Marketing Director: Deborah S. Yarnell
Marketing Manager: Jimmy Stephens
Marketing Coordinator: Mark Pierro
Production Director: Wendy Troeger
Production Manager: Mark Bernard
Content Project Manager: Michael Tubbert
Art Director: B. Casey
Technology Project Manager: Joe Pliss

© 2010 Delmar, Cengage Learning

ALL RIGHTS RESERVED. No part of this work covered by the copyright herein may be reproduced, transmitted, stored or used in any form or by any means graphic, electronic, or mechanical, including but not limited to photocopying, recording, scanning, digitizing, taping, Web distribution, information networks, or information storage and retrieval systems, except as permitted under Section 107 or 108 of the 1976 United States Copyright Act, without the prior written permission of the publisher.

For product information and technology assistance, contact us at **Professional & Career Group Customer Support, 1-800-648-7450**

For permission to use material from this text or product, submit all requests online at **cengage.com/permissions**
Further permissions questions can be emailed to **permissionrequest@cengage.com**

Library of Congress Control Number: 2008928947

ISBN-13: 978-1-4283-3583-7

ISBN-10: 1-4283-3583-8

Delmar
5 Maxwell Drive
Clifton Park, NY 12065-2919
USA

Cengage Learning products are represented in Canada by Nelson Education, Ltd.

For your lifelong learning solutions, visit **delmar.cengage.com**

Visit our corporate website at **cengage.com**

Notice to the Reader
Publisher does not warrant or guarantee any of the products described herein or perform any independent analysis in connection with any of the product information contained herein. Publisher does not assume, and expressly disclaims, any obligation to obtain and include information other than that provided to it by the manufacturer. The reader is expressly warned to consider and adopt all safety precautions that might be indicated by the activities described herein and to avoid all potential hazards. By following the instructions ?contained herein, the reader willingly assumes all risks in connection with such instructions. The publisher makes no representations or warranties of any kind, including but not limited to, the warranties of fitness for particular purpose or merchantability, nor are any such representations implied with respect to the material set forth herein, and the publisher takes no responsibility with respect to such material. The publisher shall not be liable for any special, consequential, or exemplary damages resulting, in whole or part, from the readers' use of, or reliance upon, this material.

Printed in U.S.A
1 2 3 4 5 XX 10 09 08

Brief Contents

PREFACE x

SECTION 1: Basics 1

INTRODUCTION: Graphic Communication and Technical Drawing 2

1 CAD and Technical Drawing 23

2 Technical Drawing with Instruments 37

3 Manual Lettering, Sketching, and Line Techniques 77

4 Geometric Construction 103

SECTION 2: Technical Drawing Fundamentals 156

5 Spatial Visualization and Multiview Drawings 158

6 Sectional Views 201

7 Auxiliary Views 236

8 Descriptive Geometry 260

9 Patterns and Developments 337

10 Dimensioning and Notation 371

11 Solid/3D Modeling: Computational Design and Analysis 444

SECTION 3: Design Drafting Applications 464

12 Geometric Dimensioning and Tolerancing . . 466

13 Fasteners 511

14 Springs 557

15 Cams 574

16 Gears 590

17 Assembly and Detail Drawings for Design 610

18 Pictorial Drawings 659

SECTION 4: Related Technologies, Applications, and Processes 696

19 Welding 698

20 Modern Manufacturing: Materials, Processes, and Automation 723

21 Drafting Applications: Pipe, Structural, Architectural, Civil Engineering, and GIS 770

22 The Design Process 840

APPENDIX A: Tables 890

GLOSSARY 925

INDEX 973

Contents

PREFACE x

Section 1

Basics

INTRODUCTION: Graphic Communication and Technical Drawing 2

Graphic communication • Drawings described • Types of drawings • Types of technical drawings • Purpose of technical drawings • Applications of technical drawings • Regulation of technical drawings • What students of technical drawing, drafting, and CAD should learn • Technical drawing and quality/competitiveness • Summary • Review questions • Introduction problems

CHAPTER 1: CAD and Technical Drawing 23

Overview of CAD • Key computer and CAD concepts • CAD systems • CAD workstation components • CAD software • The Internet in design and drafting • Summary • Review questions

CHAPTER 2: Technical Drawing with Instruments 37

Conventional instruments • Conventional drafting requisites • Drawing sets • Scales • Measuring • Ink tools • Technical pens • Mechanical lettering sets • Butterfly scriber • Airbrush • Paper sizes • Whiteprinter • Files • Care of drafting equipment • Use of appliqués • Use of burnishing plates • Typewritten text • Overlay drafting • Scissors drafting techniques • Summary • Review questions • Chapter 2 problems

CHAPTER 3: Manual Lettering, Sketching, and Line Techniques 77

Talking sketching • Freehand lettering • Freehand lettering techniques • Line work • Sketching • Types of sketches • Sketching materials • Sketching techniques • Summary • Review questions • Chapter 3 problems

CHAPTER 4: Geometric Construction 103

Geometric nomenclature • Elemental construction principles • Polygon construction • Circular construction • Supplementary construction • Summary • Review questions • Chapter 4 problems

Section 2

Technical drawing Fundamentals

CHAPTER 5: Spatial Visualization and Multiview Drawings 158

Spatial visualization • Orthographic projection • Planning the drawing • Sketching procedure • Centering the drawing • Technical drawing conventions • Visualization • First-angle projection • Summary • Review questions • Chapter 5 problems

CHAPTER 6: Sectional Views 201

Sectional views • Cutting-plane line • Direction of sight • Section lining • Multisection views • Kinds of sections • Sections through ribs or webs • Holes, ribs and webs, spokes and keyways • Aligned sections • Fasteners and shafts in section • Intersections in section • Summary • Review questions • Chapter 6 problems

CHAPTER 7: Auxiliary Views 236

Auxiliary views defined • Secondary auxiliary views • Partial views • Auxiliary section • Half auxiliary views • Oblique surfaces, viewing planes, and auxiliary view enlargements • Summary • Review questions • Chapter 7 problems

CHAPTER 8: Descriptive Geometry 260

Descriptive geometry projection • Steps used in descriptive geometry projection • Notations • Fold lines • Bearings, slope, and grade • Applied descriptive geometry • Topographic topics • Vectors • Summary • Review questions • Chapter 8 problems

CHAPTER 9: Patterns and Developments 337

Developments • Parallel line development • Radial line development • Triangulation development • True-length diagrams • Notches • Bends • Summary • Review questions • Chapter 9 problems

CHAPTER 10: Dimensioning and Notation 371

Dimensioning systems • Dimension components • Laying out dimensions • Steps in dimensioning • Specific dimensioning techniques • Summary of dimensioning rules • Notation • Rules for applying notes on drawings • Group technology • Summary • Review questions • Chapter 10 problems

CHAPTER 11: Solid/3D Modeling: Computational Design and Analysis 444

Factors in using visualization • Understanding data • Modeling techniques • Types of visualization images • Methods of representing variables • Relationships • Engineering visualization applications • Case studies • Summary • Review questions

Section 3

Design Drafting Applications

CHAPTER 12: Geometric Dimensioning and Tolerancing 466

Summary of geometric dimensioning and tolerancing terms • Geometric dimensioning and tolerancing defined • Modifiers • Feature control symbol • True position • Circularity (roundness) • Cylindricity • Angularity • Parallelism • Perpendicularity • Profile • Runout • Concentricity • Summary • Review questions • Chapter 12 problems

CHAPTER 13: Fasteners 511

Classifications of fasteners • Threads • Screw thread forms • Tap and die • Threads per inch (TPI) • Pitch • Single and multiple threads • Right-hand and left-hand threads • Thread relief (undercut) • Screw, bolt, and stud • Rivets • Keys and keyseats • Grooved fasteners • Spring pins • Fastening systems • Retaining rings • Summary • Review questions • Chapter 13 problems

CHAPTER 14: Springs 557

Spring classification • Helical springs • Flat springs • Terminology of springs • Required spring data • Other spring design layout • Standard drafting practices • Section view of a spring • Isometric views of a spring • Summary • Review questions • Chapter 14 problems

CHAPTER 15: Cams 574

Cam principle • Basic types of followers • Cam mechanism • Cam terms • Cam motion • Laying out the cam from the displacement diagram • Timing diagram • Dimensioning a cam • Summary • Review questions • Chapter 15 problems

CHAPTER 16: Gears 590

Kinds of gears • Gear ratio • The involute curve • Pitch diameter and basic terminology • Pitch diameter (D) • Diametral pitch (P) • Gear blank • Pressure angle, base circle, and center-to-center distance • Rack • Gear train • Required tooth-cutting data • Measurements required to use a gear tooth caliper • Bevel gear • Worm and worm gear • Materials • Design and layout of gears • Summary • Review questions • Chapter 16 problems

CHAPTER 17: Assembly and Detail Drawings for Design 610

Technical drawings and the engineering department • The engineering department • Systems company • Design section • Working drawings: detail and assembly • Title block • Numbering system • Drawing revisions: ECRs and ECOs • Application engineering • Quotation department • Mass production company • Design for manufacturability (DFM) • DFM guidelines • Design for assembly (DFA) • DFA guidelines • Personal technical file • Invention agreement • Patent drawings • Summary • Review questions • Chapter 17 problems

CHAPTER 18: Pictorial Drawings 659

Purpose of pictorial drawings • Oblique drawings • Isometric drawings • Axonometric: drawing and projection • Other oblique drawings • Perspective drawings • Summary • Review questions • Chapter 18 problems

Section 4

Related Technologies, Applications, and Processes

CHAPTER 19: Welding 698

Welding processes • Basic welding symbol • Size of weld • Length of weld • Placement of weld

• Intermittent welds • Process reference • Contour symbol • Field welds • Welding joints • Types of welds • Multiple reference line • Spot weld • Projection weld • Seam weld • Welding template • Design of weldments • Summary • Review questions • Chapter 19 problems

CHAPTER 20: Modern Manufacturing: Materials, Processes, and Automation 723

Engineering materials • Traditional manufacturing processes • Casting • Forging • Extruding • Stamping • Machining • Special workholding devices • Heat treatment of steels • Nontraditional machining processes • Automation and integration (CAM and CIM/FMS) • Computer-aided manufacturing (CAM) • Industrial robots • CIM/FMS • Just-in-time manufacturing (JIT) • Manufacturing resource planning (MRPII) • Statistical process control (SPC) • Summary • Review questions

CHAPTER 21: Drafting Applications: Pipe, Structural, Architectural, Civil Engineering, and GIS 770

Types of pipe • Types of joints and fittings • Types of valves • Pipe drawings • Dimensioning pipe drawings • Structural drafting • Pre-engineered metal buildings • Architectural drafting • Civil engineering drafting • Geographic information systems • Summary • Review questions • Chapter 21 problems

CHAPTER 22: The Design Process 840

Time • Learning the design process • The design process: phases and steps • Design projects: routine and non-routine • Modern design practices and standards • Summary • Review questions • Chapter 22 problems

APPENDIX A: Tables 890

GLOSSARY 925

INDEX 973

Preface

Purposes

Technical Drawing and Engineering Communication is intended for use in such courses as basic and advanced drafting, engineering graphics, descriptive geometry, mechanical drafting, machine drafting, tool and die design and drafting, and manufacturing drafting. It is appropriate for those courses offered in comprehensive high schools, area vocational schools, technical schools, community colleges, trade and technical schools, and at the freshman and sophomore levels in universities.

Prerequisites

There are no prerequisites. The text begins at the most basic level and moves step by step to the advanced levels.

It is as well-suited for students who have had no previous experience with technical drawing as it is for students with a great deal of prior experience.

How to Use This Book

Technical Drawing and Engineering Communication is a comprehensive teaching and learning tool that contains several special features to promote the student's development and to make learning easier. Students and instructors can make use of the following features:

Career Profiles located in the Section Opener focus on the occupations of specific individuals. These profiles were chosen as representative of the types of jobs that students could acquire after completing an education in drafting. The career profiles also relate directly to the content covered in the section.



Career Profile

JON WHITNEY

Many objects have inclined surfaces that are not always parallel to the regular planes of projection. For example, in Figure 7-1, the front view is correct as shown, but the top and right-side views do not correctly represent the inclined surface. To truly represent the inclined surface and to show its true shape, an auxiliary view must be drawn. An auxiliary view has a line of sight that is perpendicular to the inclined surface, as viewed looking directly at the inclined surface. Auxiliary views are always projected 90° from the inclined surface.

An auxiliary view can be constructed from any of the regular views. An auxiliary view projected from the front view would appear as it does in Figure 7-1. This is referred to as a front view auxiliary. An auxiliary view projected from the top view would appear as it does in Figure 7-2. This is referred to as a top view auxiliary. An auxiliary view projected from the right-side view would appear as it does in Figure 7-3. This is referred to as a side view auxiliary. Note in each case that the auxiliary view is projected 90° from the inclined or slanted surface and is viewed from a line of sight 90° to the inclined or slanted surface, or as viewed looking directly down upon the inclined surface.

Many objects have inclined surfaces that are not always parallel to the regular planes of projection. For example, in Figure 7-1, the front view is correct as shown, but the top slined surface. Auxiliary views are always projected 90° from the inclined surface.

An auxiliary view can be constructed from any of the regular views. An auxiliary view projected from the front view would appear as it does in Figure 7-1. This is referred to as a front view auxiliary. An auxiliary view projected from the top view would appear as it does in Figure 7-2. This is referred to as a top view auxiliary. An auxiliary view projected from the right-side view would appear as it does in Figure 7-3. This is referred to as a side view auxiliary. Note in each case that the auxiliary view is projected 90° from the inclined or slanted surface and is viewed from a line of sight 90° to the inclined or slanted surface, or as viewed looking directly down upon the inclined surface.

Many objects have inclined surfaces that are not always parallel to the regular planes of projection. For example, in Figuhe inclined surface, as viewed looking directly at the inclined surface. Auxiliary views are always projected 90° from the inclined surface.

An auxiliary view can be constructed from any of the regular views. An auxiliary view projected from the front view would appear as it does in Figure 7-1. This is referred to as a front view auxiliary. An auxiliary view projected from the top view would appear as it does in Figure 7-2. This is referred to as a top This is referred to as a side view auxiliary. Note in each case that the auxiliary view is projected 90° from the inclined or slanted surface and is viewed from a line of sight 90° to the inclined or slanted surface, or as viewed looking.

CAREER PROFILE

Chapter Objectives at the beginning of each chapter identify the skills and knowledge that students will acquire from reading the material. When students have finished the chapter, they should review the objectives to ensure that they have met each one.

The **Chapter Outline** lists the title of each major topic covered in the chapter. This provides a preview of the content coverage.

Key Terms, listed at the beginning of each chapter, are important words and phrases that students will encounter as they study the chapter. Each key term is highlighted in *italics* at the first significant use in the text, and is included in the glossary or index at the back of the book.

Industry Application is a boxed article that explains how the skills and knowledge discussed in the chapter may be applied to a real-world job-related setting. A variety of skills will be covered, including math, science, communications, and computers.

A chapter **Summary** provides a recapitulation of the key topics covered in the chapter. This enables students to reassess their comprehension of the material before proceeding to the end-of-chapter questions and problems.

Review Questions are written to ensure that students have adequately read the chapter and that they understand the material. These questions prepare students for class tests given by the instructor and for the certification test offered by the American Design and Drafting Association. (Visit the American Design and Drafting Association web site at **www.adda.org** to learn about the certification programs and ADDA


1

CAD and Technical Drawing

KEY TERMS

CAD system
CAM
CD-ROM
Computer graphics (CG)
Hardware
Microprocessor
Mouse
Plotter
Printer
Software
Solid modeling

CHAPTER OUTLINE

Overview of CAD • Key computer and CAD concepts • CAD systems • CAD workstation components • CAD software • Summary • Review questions

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the concept of CAD.
- Explain key CAD concepts including: computer graphics, computer-aided manufacturing, computer-integrated manufacturing, computer-aided engineering, hardware, software, operating system, and application program.
- Define the term *CAD system.*
- List and explain the most common components in a CAD workstation.
- Explain the concept of CAD software.
- Demonstrate the process for selecting a CAD system.
- Explain the concept of modeling.
- Explain the concept of parametric design.

23

CHAPTER OUTLINE

INDUSTRY APPLICATION

KEY TERMS

CHAPTER OBJECTIVES


CAD and Technical Drawing 33

Industry Application

Mark Sutton had been an excellent drafting and design student at Brookview Academy. He proved to be particularly adept at CAD. Consequently, it surprised no one when the chairman of Brookview's Drafting and Design Department asked Sutton to be a student representative on a faculty committee to purchase new plotters for the CAD lab.

At the first meeting of the committee it became apparent that no consensus existed concerning what type of plotters to purchase. One instructor favored flatbed pen plotters because they resembled traditional drafting boards. The resemblance helped him "relate better to the plotters." Another instructor recommended electrostatic plotters, but suggested that low-resolution models be purchased to save funds. She hoped to have funds left over to purchase some precision measurement tools for her mechanical drafting classes.

After two meetings and three hours of discussion and debate, the committee was no closer to achieving consensus than it was at the outset of its deliberations. In order to gain a better perspective, the committee chair asked the members to take a week to investigate, think, and research the issue. He asked the members to meet in a week. Before that meeting, each member was to hand him a sealed one-page recommendation with supportive rationale.

Mark Sutton, feeling somewhat intimidated by it all, decided to give the chair not his opinion but the opinion of practitioners. During the interim week he visited several companies and talked with five different drafting managers. Although their reasons differed somewhat, all five recommended microgrip plotters. Sutton, in preparation for the next meeting, prepared a one-page recommendation containing the reasons given by the various drafting managers.

The committee chair collected all of the sealed recommendations the day before the scheduled committee meeting and studied them overnight. The next day he opened the meeting by saying, "One of our members put a lot of effort into formulating a recommendation. I'd like to read it to you." Sutton slumped in his seat and his face flushed as the chair read his recommendation and reasons. The reasons Sutton had given were adaptability, flexibility, and relatively inexpensive pricing. Discussion began and within ten minutes the committee had formed a consensus around Sutton's recommendation. The other recommendations were put aside.

Once the decision to purchase microgrip plotters had been made, one of the committee members asked, "Whose recommendation did we adopt?" The chair smiled, nodded at Sutton, and said, "Our student member."

Design Software/Solid Modeling

Design software enables a number of specific design tasks to be undertaken on a CAD system. The most frequently used of these include solid modeling, finite element analysis, kinematics, and simulation. *Solid modeling* involves constructing a mathematical, geometric model of a design part and displaying it on the monitor screen. A solid model is the most accurate, most realistic type of geometric model that CAD systems are currently capable of producing.

The most important difference between a solid model and the wireframe type of geometric model is that the wireframe model defines only the exterior of the object. A solid model, on the other hand, defines not only the exterior of the object, but the interior as well. Additional capabilities such as shading and coloring differentiate surfaces of the solid model, making it even more realistic and easy to understand, *Figures 1-17, 1-18,* and *1-19.*

Finite-element analysis is another frequently used design capability of CAD software. Most design products require some type of analysis involving stress, temperature, heat, and other types of calculations. The finite-element analysis capability allows the computer to divide the object into a series of small rectangular and triangular objects such that the surface of the geometric model appears to be a grid, *Figure 1-20.* In this way, the computer is able to analyze how each individual grid position will behave under certain types of stress and strain and other conditions, as well as how the entire object will behave under these conditions.

Kinematic software that can be run on CAD systems is popular among engineers and designers

membership.) These questions do not require a computer or drafting materials.

Chapter Problems contain drawing projects that allow students to test their drafting skills. Advanced problems are marked by **icons**. These special icons have been placed adjacent to the advanced drawing projects to indicate the engineering and design field the drawing pertains to. These icons call out a specific drafting field or discipline.

Delmar's Drafting Web Site is located at **www.Delmar.com/drafting**. This site is a tool to be used in conjunction with the material in this text. The site has links to industrial organizations, industry web sites, drafting certification sites, and the *Technical Drawing and Engineering Communication* **Online Companion™**. This Online Companion provides access to equivalents tables, fits tables, dimensions tables for screws and nuts, and much more.

Content Overview

Chapters 1–18 are to be used to help students develop the design and drafting skills that are fundamental to *all* drafting fields. Instructors are encouraged to use all



of these chapters to build a solid footing of design and drafting knowledge for students.

Chapters 19–22 allow students to develop advanced knowledge and skills beyond the fundamentals.

Instructors are encouraged to use these chapters to help their students develop an in-depth understanding of these discipline areas: Welding; Modern Manufacturing: Materials, Processes, and Automation; Drafting Applications: Pipe, Architectural, and Civil Engineering.

Chapter 22, The Design Process, is important in preparing the student for entry into the job force. The steps of the design process are defined and the reader is taught how to be creative in analyzing and solving problems. Modern design processes such as DFM, DFA, rapid prototyping, and reverse engineering are addressed.

Innovations

An advantage of the text is that it has evolved during a time when the world of technical drawing and design is going through a period of major transition from manual to automated techniques. Computer-aided drafting (CAD) has become the standard tool, but elements of the traditional methods and tools remain.

This transition created a need for a major text that deals with both CAD and traditional knowledge and skills. *Technical Drawing and Engineering Communication* fills this need. Even though the world of technical drawing and design has become automated, drafters and designers will still need to know the traditional basics and technical drawing fundamentals. Therefore, the fundamentals are treated in depth in this text.

What has changed, and will continue to change, is the way that drafters and designers prepare technical drawings. For this reason, CAD is treated in depth, and most of the drawings and illustrations were prepared on various CAD systems. Along with this treatment, *Technical Drawing and Engineering Communication* offers students and instructors a special blend of the manual and automated knowledge and techniques that will be needed into the twenty-first century.

Another advantage of the text is that it was written after the latest update of the most frequently used drafting standard—the ANSI series. Consequently, all dimensioning and tolerancing material in *Technical Drawing and Engineering Communication* is based on this most recent edition of the standard.

New Features in the Sixth Edition

The Sixth Edition is based on the concept that "less is more." After polling a wide cross-section of instructors who use this textbook, the authors eliminated material reviewers thought was superfluous. This was done so that new material could be added where appropriate without increasing the size of the book and, in turn, the cost. A summary of changes for the Sixth Edition follows:

- The name of the book was changed to reflect the movement in the field away from the traditional name and concept of "drafting." Because technicians in this field prepare drawings and other forms of documentation to communicate engineering concepts and information, the newly adopted title of the book for the Sixth Edition is *Technical Drawing and Engineering Communication*.
- In Sections 1 through 3 (Introduction and Chapters 1–18), changes were made based on reviewer feedback. For example, Chapter 1 was modernized in terms of both photographs and content. In Chapter 2, the section on scaling was enhanced to include more information and examples of how to read certain scales. In Chapter 3, a section was added on how to use a lettering guide. In addition, several corrections to drawings were made based on reviewer feedback.
- In Section 4, Chapters 22 and 23 were eliminated based on reviewer feedback. Chapter 24—The Design Process—became Chapter 22 in the Sixth Edition and is now the last chapter in the book.
- Section 5 (Chapters 25 and 26) was eliminated altogether based on reviewer feedback. However, since some instructors do use these chapters for preparing students to find, get, and keep jobs, the author developed a new supplemental text entitled *The Successful Drafting Technician* that contains all of the information that was covered in Chapters 25 and 26 of the Fifth Edition (updated) and much more. Success strategies covered in this supplemental text include the following: 1) master your school subjects, 2) be a smart job seeker, 3) build your career on a foundation of integrity, 4) understand your employer's "big picture" and where you fit into it, 5) apply self-discipline and time management, 6) be a good team player, team builder, and team leader, 7) be an effective communicator, 8) be a critical thinker, 9) learn to work well in a diverse setting, 10) adopt a positive "can-do" attitude toward your work, 11) learn how to prevent and resolve conflict on the job, and 12) persevere when the job becomes difficult. This supplemental text will be available at a nominal cost concurrent with the Sixth Edition.
- The "fit tables" contained in Chapter 10, Dimensioning and Notation, were left in Chapter 10 where they have been, but were also repeated in the Appendix. This recommendation came from reviewers who find it easier to locate these tables in the Appendix once they are past Chapter 10 in their instruction.

Tested and Proven Features

- An enhanced supplement package contains a new Workbook, Instructor's Manual, e.resource CD-ROM with electronic instructional material, and access to World Class Learning™ distributed learning courseware.
- Chapter 22 (The Design Process) covers modern design practices and standards.
- Discipline-specific icons highlight the drawing problems, enabling the reader to quickly choose problems pertaining to his or her drawing field.
- Chapter 1 (CAD and Technical Drawing) has been updated to contain Internet coverage.
- Review questions are formatted as multiple-choice and true/false for rapid testing and grading.
- New drawing problems are contained in the primary drawing chapters.
- Boxed articles covering real-world applications exist in all chapters. This reinforces the relevance of the chapter content to today's job environment.
- New math problems are contained in selected chapters for additional practice.
- Step-by-step explanations of drawing procedures and techniques.
- Written in language students will understand; technical terms are defined as they are used.
- Unique black and plum color format depicts isometric views more clearly than "flat" black-and-white drawings.
- Text and illustrations are located in *direct* relationship to each other wherever possible.
- Real-world techniques are highlighted in the Industry Application boxed articles.
- Although the emphasis is on mechanical drafting, other pertinent drafting subjects are included for a comprehensive, well-rounded approach to technical drawing.
- Contains in-depth drafting applications in architectural, structural, civil, and piping.

The Learning Package

The complete ancillary package was developed to achieve two goals:

1. To assist students in learning the essential information needed to prepare for the exciting field of drafting.
2. To assist instructors in planning and implementing their instructional programs for the most efficient use of time and other resources.

The *Technical Drawing and Engineering Communication* package was created as an integrated whole. Supplements are linked to and integrated with the text to create a comprehensive supplement package that supports students and instructors, beginning or veteran. The package includes:

Workbook—This newly revised and expanded workbook assists in developing the skills needed to create and read technical drawings. Advanced coverage includes dimensioning and tolerancing and commercial components such as fasteners, gears, cams, and springs. ISBN: 1-4018-5761-2.

Instructor's Manual—This ancillary contains general information, lesson plans, objective tests, and solutions to the text problems and review questions. Solutions are also provided for the *Workbook*, including the solutions to the CAD problems. ISBN: 1-4018-5763-9.

e.resource™—This is an educational resource that creates a truly electronic classroom. It is a CD-ROM containing tools and instructional resources that enrich your classroom and make your preparation time shorter. The elements of *e.resource* link directly to the text and tie together to provide a unified instructional system. With *e.resource* you can spend your time teaching, not preparing to teach. ISBN: 1-4018-5764-7.

Features contained in *e.resource* include:

- **Syllabus:** Lesson plans created by chapter. You have the option of using these lesson plans with your own course information.
- **Chapter Hints:** Objectives and teaching hints that provide the basis for a lecture outline that helps you to present concepts and material. Key points and concepts can be graphically highlighted for student retention.
- **Answers to Review Questions:** These solutions enable you to grade and evaluate end-of-chapter tests.
- **PowerPoint® Presentation:** These slides provide the basis for a lecture outline that helps you to present concepts and material. Key points and concepts can be graphically highlighted for student retention.
- **Computerized Test Bank:** Over 800 questions of varying levels of difficulty are provided in true/false and multiple-choice formats so you can assess student comprehension.
- **CAD Drawing Files:** Drawing files are provided that link to problems in the *Workbook*. Students download the files to complete the problems.

Acknowledgments

The authors would like to acknowledge the efforts of many people without whose assistance this project would not have been completed. Special acknowledgment is made to Evan Yares who revised and updated Jerry L. Roiter's Chapter 11, "Solid/3D Modeling: Computational Design and Analysis." We thank Deborah M. Goetsch for her assistance with photography and typing.

The following individuals reviewed the manuscript and made valuable suggestions to the authors. The authors and the publisher greatly appreciated their contributions to this textbook.

Sharon Bagby, Texas State Technical College

Steven P. Bauer, The Pennsylvania State University, DuBois

Glenn Frostholm, Augusta Technical College

Jerry M. Gray, West Georgia Technical College

Carrie Miller, Middle Georgia Technical College

Alicia O'Kelley, Western Dakota Technical Institute

About the Authors



David L. Goetsch is Vice President and Professor of Design, Drafting, Quality, and Safety at Okaloosa-Walton College in Niceville, Florida. His drafting and design program has won national acclaim for its pioneering efforts in the area of computer-aided drafting (CAD). In 1984, his school was selected as one of only 10 schools in the country to earn the distinguished Secretary's Award for an outstanding Vocational Program. Professor Goetsch is a widely acclaimed teacher, author, and lecturer on the subject of drafting and design. He won Outstanding Teacher of the Year honors in 1976, 1981, 1982, 1983, and 1984. In 1986 he won the Florida Vocational Association's Rex Gaugh Award for outstanding contributions to technical education in Florida. In 2003, Dr. Goetsch was selected as the University of West Florida's Distinguished Alumnus. He entered education full time after a successful career in design and drafting in the private sector, where he spent more than eight years as a Senior Drafter and Designer for a subsidiary of Westinghouse Corporation. He was elected Florida's Outstanding Economic Development person in 1992 and 1996. He is president of The Management Institute (TMI) and does consulting in the areas of design, drafting, quality, and safety. This is his 56th book.



Professor Emeritus **William S. Chalk** taught for 31 years in the College of Engineering at the University of Washington in the departments of General, Mechanical, and Nuclear engineering, and was Director of Nuclear Engineering Laboratories from 1976 to 1983. Professor Chalk had seven years of experience in industry with the Link-Belt Company and has worked with Boeing Airplane Company, The Puget Sound Naval Shipyard, and The Sandia Corporation.

Always interested in the practical applications of education, Professor Chalk has conducted a number of nationwide design workshops for industry. He is a

recipient of Western Electric's Outstanding Instructor of the Year award. In addition, he is a former associate editor of *Design Graphics Journal*.

Professor Chalk holds a master's degree in mechanical engineering from the University of Washington and has participated in design training workshops at Dartmouth College and Stanford University. He is the coauthor of an engineering graphics text and workbook and is the author of a past ASEE paper.

Professor Chalk continues to be active in engineering by lecturing to engineers who plan to take engineering license examinations, and by lecturing in summer programs.

Raymond L. Rickman is chairman of the Manufacturing and Technology Department and Professor of Design and Drafting at Okaloosa-Walton College.

Professor Rickman has extensive experience in the private sector and the classroom and is a consultant on the subject of geometric dimensioning and tolerancing. He is a member of the ANSI Y14.5 technical committee and the co-author of several career mathematics textbooks.



Jerry L. Roiter, author of Chapter 11, "Solid/3D Modeling: Computational Design and Analysis," has been teaching at the university level since 1972. He is currently a faculty member at the University of Wisconsin. Prior to beginning teaching he worked in industry as a designer and continues to work in industry on a regular basis as well as serving as a consultant.

He was formerly Assistant Director of Visualization at the Cornell National Supercomputer Facility. He holds the bachelor of science, master of arts, and doctor of philosophy degrees.

Evan Yares, contributing author of Chapter 11, "Solid/3D Modeling: Computational Design and Analysis," is a strategic CAD consultant, working with vendors and users to help make CAD both easier and more productive. He is a contributor to several magazines, including CADalyst and Computer Graphics World, and is a well-known speaker on CAD subjects.

TECHNICAL DRAWING
AND ENGINEERING COMMUNICATION

SIXTH EDITION

SECTION 1

Basics

1 CAD and Technical Drawing

2 Technical Drawing with Instruments

3 Manual Lettering, Sketching, and Line Techniques

4 Geometric Construction

Career Profile

JON WHITNEY

In college, Jon Whitney studied English. On a whim, he applied to graduate school for architecture, and it ended up being the right decision.

After the three-and-one-half-year program, he began as a drafter at Goshow Architects in New York City. This meant he was responsible for turning architects' visions into dimensioned schematics. He would often go on-site to take measurements, then bring them back to insert into the AutoCAD program. After a superior reviewed his drawings, Whitney served as a drafter for three years, a typical amount of time for someone just out of an architecture master's program (although many drafters choose to keep drafting indefinitely).

While serving as a drafter, Whitney accumulated credits toward his IDP (internship development program); when you get enough credits, you can begin the year-long testing process to get your architecture license. Whitney is currently in the midst of that testing. Now that he is a junior project manager, he is still drafting, but he also coordinates multiple projects, each of which can be in a different stage of the process.

The first stage is the schematic phase. At this predesign stage, Whitney is likely to create a not-to-scale schematic by hand, making bubble diagrams to give a broad, general look at the project. For instance, how would a loft space look if it was adapted for office use? Often this stage is conceptual and artistic.

The next stage is design development, at which point the drawing starts to become more technical. This involves refining the schematic, starting to put down dimensions and materials. How big will the walls dividing offices be? Will they be made of masonry or steel? Do they need windows? Whitney may also call in subcontractors (hazmat, mechanical engineers, landmarks conservancy consultants, etc.) if necessary.

Next, Whitney and his team will create construction documents, the technical drawings that are given to the contractor at the start of the project. These must be as clear as possible; in fact, Whitney says, this stage is never completed. One can always go one level deeper with detail. Therefore, you should do as much as possible in the allotted time. As a drafter, Whitney used to work primarily in this phase. Now, most mornings he will spend a few hours reviewing drawings (done either by himself or one of his drafters) with a red pen, looking for everything from spelling errors to technical problems. He must also look for clarity and any misleading information. In essence, the client is paying for the comprehensive and accurate packet of drawings and specifications developed here.

Next comes the bidding and contractor selection. Once a contractor is chosen, the architect hands over the construction documents and work on the project begins. In the construction administration phase, the architect and drafters may be called in to provide clarifying drawings on an unpredicted on-site issue. (The floor plan may be 4″ off, or perhaps there is a pipe behind a wall that wasn't noted in the drawings.)

Being a project manager has been a big, but exciting, change for Whitney. He's gotten to step outside the tunnel vision required of drafters and has been able to get a broader look at each project. As a result, he sees each plan go from an artistic idea to a technical reality.

Introduction

Graphic Communication and Technical Drawing

OUTLINE

Graphic communication • Drawings described • Types of drawings • Types of technical drawings • Purpose of technical drawings • Applications of technical drawings • Regulation of technical drawings • What students of technical drawing, drafting, and CAD should learn • Technical drawing and quality/competitiveness • Summary • Review questions • Introduction problems

OBJECTIVES

Upon completion of this introduction, students should be able to do the following:

- Explain the concept of graphic communication.
- Define the term *drawing.*
- Differentiate between artistic and technical drawings.
- List and explain the types of technical drawings.
- Explain the purpose of technical drawings.
- Explain the different applications of technical drawings.
- Explain the concept of the regulation of technical drawings.
- Describe the role of design and drafting in promoting quality and competitiveness.

KEY TERMS

Axonometric projections
Cabinet
Cavalier
Design for manufacturability
Design process
Drafters
Drafting
Drafting technicians
Drawing
Graphic communication
Oblique projections
Orthographic projections
Parallel projection
Perspective projections
Projection
Projector
Technical drawing

Graphic Communication

Graphic communication involves using visual material to relate ideas. Drawings, photographs, slides, transparencies, and sketches are all forms of graphic communication. Most children are able to draw before they are able to write. This is graphic communication. When one person sketches a rough map in giving another directions, this is graphic communication. Any medium that uses a graphic image to aid in conveying a message, instructions, or an idea is involved in graphic communication. One of the most widely used forms of graphic communication is the drawing.

Drawings Described

A *drawing* is a graphic representation of an idea, a concept, or an entity that actually or potentially exists in life. The drawing itself is: (1) a way of communicating all necessary information about an abstraction, such as an idea or a concept; or (2) a graphic representation of some real entity, such as a machine part, a house, or a tool, for example.

Drawing is one of the oldest forms of communication, dating back even farther than verbal communication. Cave dwellers painted drawings on the walls of their caves thousands of years before paper was invented. These crude drawings served as a means of communicating long before verbal communications had developed beyond the grunting stage. In later years, Egyptian hieroglyphics were a more advanced form of communicating through drawings.

The old adage "one picture is worth a thousand words" is still the basis of the need for technical drawings.

Types of Drawings

There are two basic types of drawings: artistic and technical. Some experts believe there are actually three types: the two mentioned and another type that combines these two. The third type is usually referred to as an illustration or rendering.

Artistic Drawings

Artistic drawings range in scope from the simplest line drawings to the most famous paintings. Regardless of their complexity or status, artistic drawings are used to express the feelings, beliefs, philosophies, or abstract ideas of the artist. This is why the lay person often finds it difficult to understand what is being communicated by a work of art.

In order to understand an artistic drawing, it is sometimes necessary to first understand the artist. Artists often take a subtle or abstract approach in communicating through their drawings. This gives rise to the various interpretations often associated with artistic drawings.

Technical Drawings

The technical drawing, on the other hand, is not subtle or abstract. It does not require an understanding of its creator, but only an understanding of technical drawings. A *technical drawing* is a means of clearly and concisely communicating all of the information necessary to transform an idea or a concept into reality. Therefore, a technical drawing often contains more than just a graphic representation of its subject. It also contains dimensions, notes, and specifications.

The mark of a good technical drawing is that it contains all of the information needed by individuals for converting the idea or concept into reality. The conversion process may involve manufacturing, assembly, construction, or fabrication. Regardless of the process involved, a good technical drawing allows the conversion process to proceed without having to ask designers or drafters for additional information or clarification.

Figure 1 and ***Figure 2*** contain samples of technical mechanical drawings that are used as guides by the people involved in various phases of manufacturing the represented parts. Notice that the drawings contain a graphic representation of the part, dimensions, material specifications, and notes.

Illustrations or Renderings

Illustrations or renderings are sometimes referred to as a third type of drawing because they are neither completely technical nor completely artistic; they combine elements of both, as shown in ***Figures 3, 4, 5,*** and ***6*** (pages 5 to 6). They are technical in that they are drawn with mechanical instruments or on a computer-aided drafting system, and they contain some degree of technical information. However, they are also artistic in that they attempt to convey a mood, an attitude, a status, or other abstract, non-technical feelings.



FIGURE 1 *Technical drawing (mechanical).*

Types of Technical Drawings

Technical drawings are based on the fundamental principles of projection. A *projection* is a drawing or representation of an entity on an imaginary plane or planes. This projection plane serves the same purpose in technical drawing as is served by the movie screen in a theater.

As can be seen in ***Figure 7*** (page 7), a projection involves four components: (1) the actual object that the drawing or projection represents, (2) the eye of the viewer looking at the object, (3) the imaginary projection plane (the viewer's drawing paper or the graphics display in a computer-aided drafting system), and (4) imaginary lines of sight called *projectors*.

Two broad types of projection, both with several subclassifications, are parallel projection and perspective (converging) projection.



FIGURE 2 *Technical drawing (mechanical).*

Parallel Projection

Parallel projection is divided into the following three categories: orthographic, oblique, and axonometric projections.

Orthographic projections are drawn as multiview drawings that show flat representations of principal views of the subject, ***Figure 8*** (page 7). *Oblique projections* actually show the full size of one view and are of three varieties: *cabinet* (half-scale), *cavalier* (full-scale), and general (between half and full-scale). ***Figures 9*** and ***10*** (page 7) show cavalier and cabinet projections. *Axonometric projections* are three-dimensional drawings and are of three different varieties: isometric, dimetric, and trimetric, ***Figures 11, 12,*** and ***13*** (page 8).

Perspective Projection

Perspective projections are drawings that attempt to replicate what the human eye actually sees when it views an object. That is why the projectors in a perspective drawing converge. There are three types of perspective projections: one-point, two-point, and three-point projections, ***Figures 14, 15,*** and ***16*** (page 8).

FIGURE 3 *Rendering.*

FIGURE 4 *Rendering.*

Purpose of Technical Drawings

To appreciate the need for technical drawings, one must understand the design process. The design process is an orderly, systematic procedure used in accomplishing a needed design.

Any product that is to be manufactured, fabricated, assembled, constructed, built, or subjected to any other type of conversion process must first be designed. For example, a house must be designed before it can be built. An automobile must be designed before it can be manufactured. A printed



FIGURE 5 *Mechanical illustration* (Courtesy Ken Elliott).



FIGURE 6 *Mechanical illustration* (Courtesy Ken Elliott).

circuit board must be designed before it can be fabricated.

The Design Process

The *design process* is an organized, step-by-step procedure in which mathematical and scientific principles, coupled with experience, are brought to bear in order to solve a problem or meet a need. The design process has five steps. Traditionally, these steps have been (1) identification of the problem or need, (2) development of initial ideas for solving the problem, (3) selection of a proposed solution, (4) development and testing of models or prototypes,



FIGURE 7 *The projection plane.*



FIGURE 8 *Orthographic multiview drawing.*



FIGURE 9 *Oblique projection (cabinet).*



FIGURE 10 *Oblique projection (cavalier).*

and (5) developing working drawings, *Figure 17* (page 9).

The age of computers has altered the design process slightly for those companies that have converted to computer-aided design and drafting. For these companies, the expensive, time-consuming fourth step in the design process—the making and testing of actual models or prototypes—has been substantially altered, *Figure 18.* This fourth step has been replaced with three-dimensional computer models that can be



FIGURE 11 *Axonometric projection (isometric).*



FIGURE 12 *Axonometric projection (dimetric).*



FIGURE 13 *Axonometric projection (trimetric).*



FIGURE 14 *One-point perspective projection.*



FIGURE 15 *Two-point perspective projection.*



FIGURE 16 *Three-point perspective projection.*

quickly and easily produced on a CAD system using the database built up during the first three phases of the design process, *Figure 19.*

Whether in the traditional design process or the more modern computer version, working drawings are an integral part of the design process from start to finish. The purpose of technical drawings is to document the design process. Creating technical drawings to support the design process is called *drafting*. People who do drafting are known as *drafters* or *drafting technicians*. The words "draftsman" or "draughtsman" are no longer used.



FIGURE 17 *The design process (manual).*



FIGURE 18 *The design process (CAD).*

In the first step of the design process, technical drawings are used to help clarify the problem or the need. The drawings may be old ones on file or new ones created for the purpose of clarification. In the second step, technical drawings—often in the form of sketches or preliminary drawings—are used to document the various ideas and concepts formed. In the third step, technical drawings—again, usually preliminary drawings—are used to communicate the proposed solution.

If the traditional fourth step in the design process is being used, preliminary drawings and sketches from the first three steps will be used as guides in constructing models or prototypes for testing. If the more modern fourth step is being used, the database built up during documentation of the first three steps can be used in developing three-dimensional computer models. In both cases, the final step is the development of complete working drawings for guiding individuals involved in the conversion process. *Figure 20* is a working drawing documenting the design of a simple mechanical part. The drawing was produced manually. *Figure 21* is the same drawing produced on a CAD system.

FIGURE 19 *Mountain bike helmet surface modeled using SURFCAM by Surfware* (Courtesy Surfware Inc.).

Applications of Technical Drawings

Technical drawings are used in many different applications. They are needed in any setting that involves design and in any subsequent form of conversion process. The most common applications of technical



FIGURE 20 *Simple mechanical drawing (manual).*



FIGURE 21 *Simple mechanical drawing (CAD).*

drawings can be found in the fields of manufacturing, engineering, architecture, and construction and in all of their various related fields.

Architects use technical drawings to document their designs of residential, commercial, and industrial buildings, ***Figures 22*** and ***23***. Structural, electrical, and mechanical (heating, ventilating, air conditioning [HVAC], and plumbing) engineers who work with architects also use technical drawings to document those aspects of the design for which they are responsible, ***Figures 24, 25,*** and ***26***.

Surveyors and civil engineers use technical drawings to document such work as the layout of a new subdivision or the marking-off of the boundaries for a piece of property, ***Figure 27***. Contractors and construction personnel use technical drawings as their blueprints in converting architectural and engineering designs into reality, ***Figures 28*** and ***29*** (pages 11–12).

Technical drawings are equally important to engineers, designers, and various other individuals working



FIGURE 22 *Technical drawing (architectural).*

FIGURE 23 *Technical drawing (architectural).*



FIGURE 24 *Technical drawing (structural).*



FIGURE 25 *Technical drawing (electrical).*



FIGURE 26 *Technical drawing (HVAC).*



FIGURE 27 *Technical drawing (civil).*



FIGURE 28 *Architectural/engineering drawing.*



FIGURE 29 *Architectural/engineering drawing.*

in the manufacturing industry. Manufacturing engineers use technical drawings to document their designs. Technical drawings guide the collective efforts of individuals who are concerned with the same common goal, *Figures 30* and *31* (pages 14–15).

Regulation of Technical Drawings

Technical drawing practices must be regulated because of the diversity of their applications. Just as the English language must have certain standard rules of grammar, the graphic language must have certain rules of practice. This is the only way to ensure that all people attempting to communicate using the graphic language are speaking the same language.

Standards of Practice

A number of different agencies have developed standards of practice for technical drawing. The most widely used standards of practice for technical drawing and drafting are those of the U.S. Department of Defense (DOD), the U.S. military (MIL), the American National Standards Institute (ANSI), and the American Society of Mechanical Engineers (ASME).

The American National Standards Institute does not limit its activities to the standardization of technical drawing and drafting practices. In fact, this is just one of the many fields for which ANSI maintains a continuously updated set of standards.

Standards of interest to drafters, designers, checkers, engineers, and architects are contained in the "Y" series of ANSI standards. *Figure 32* (page 15) contains a list of ANSI standards frequently used in technical drawing and drafting specifications.

What Students of Technical Drawing, Drafting, and CAD Should Learn

Many people in the world of work use technical drawings in various forms. Engineers, designers, checkers, drafters, CAD technicians, and a long list of related occupations use technical drawings as an integral part of their jobs. Some of these people must be able to actually make drawings; others are required only to be able to read and interpret drawings; some must be able to do both.

What students of technical drawing, drafting, and CAD should learn depends on how they will use technical drawings in their jobs. Will they make them? Will they read and interpret them? This textbook is written for students in the fields of engineering, design, drafting, and architecture, among others, who must be able to make, read, and interpret technical drawings. These students should develop a wide range of knowledge and skills, *Figure 33* (page 15).

The learning required of technical drawing students can be divided into three categories: fundamental knowledge and skills, related knowledge, and advanced knowledge and skills.

In the fundamentals category, students of technical drawing, drafting, and CAD should develop knowledge and skills in the areas of drafting equipment; fundamental drafting techniques such as line work, lettering, scale use, and sketching; basic CAD system operation; geometric construction; multiview drawing; sectional views; descriptive geometry; auxiliary views; general dimensioning; and notation.

In the related knowledge category, students should develop a broad knowledge base in the areas of related math, welding, shop processes, and media and reproduction.

In the advanced category, students should develop knowledge and skills in the areas of development, geometric dimensioning and tolerancing, threads and fasteners, springs, cams, gears, machine design drawing, pictorial drawing, drafting shortcuts, and CAD/CAM technology and operations. The latter area represents a significant change in techniques used to create, maintain, update, and store technical drawings, *Figures 34* and *35*.

Figures 36 through *40* (pages 16–20) contain examples of several different kinds of technical drawings taken from the "real world" of drafting.

Technical Drawing and Quality/Competitiveness

Companies that design and manufacture products or design and build structures operate in a competitive environment. Surviving and succeeding in the intensely competitive modern marketplace requires companies to focus more attention than ever before on quality. Such concepts as flexible manufacturing, computer-integrated manufacturing (CIM), just-in-time manufacturing (JIT), ISO 9000, and statistical process control (SPC) are all attempts at improving quality and competitiveness.

As effective as these concepts may be at improving the quality of manufacturing processes, they cannot overcome a poor design or misinterpretations that result from poorly prepared technical drawings. The best way to ensure quality and the competitive edge it can give a company is to do the following: (1) design good quality from the outset and, (2) prepare



ITEM	DESCRIPTION	SPEC	ITEM	DESCRIPTION	SPEC	ITEM	DESCRIPTION	SPEC
1	3-VALVE MANIFOLD		8	1/2"T. TEE		20	1/4" UNION	
2	1/2" VALVE		9	1/2"T. X 1/4"P. TEE		21	1/2" NIPPLE	
3	1/4" VALVE		10	1/2"T. X 1/2"P. ELBOW				
4	1/2" TEE		11	1/4" PIPE				
5	1/2" X 1/4" TEE		12	1/2" TUBING				
6	1/2" PIPE		19	1/2" UNION				
7	1/2"T. X 1/2"P. CONN.		17	1/2" 90° ELBOW				

THE RUST ENGINEERING COMPANY

INSTRUMENTATION INSTALLATION DETAIL
D/P CELL TRANSMITTERS FOR LIQUID AND STEAM SERVICE

DRAWN
CHECKED
APPROVED

REVISION DETAIL NUMBER DATE
CF-040001

FIGURE 30 *Isometric mechanical drawing* (Courtesy The Rust Engineering Company).



FIGURE 31 *Isometric piping schematic* (Courtesy Engineering Graphics Inc.).

DECIMAL INCH SIZE AND FORMAT	Y14.1M
LINE CONVENTIONS AND LETTERING	Y14.2M
MULTIVIEW AND SECTION	Y14.3M
PICTORIAL DRAWING	Y14.4M
DIMENSIONS AND TOLERANCING	Y14.5M
SCREW THREADS	Y14.6
GEARS, SPLINES, AND SERRATIONS	Y14.7.1
CASTINGS AND FORGINGS	Y14.8M
ENGINEERING DRAWING PRACTICES	Y14.100M

FIGURE 32 *Sample list of drafting standards.*

LEARNING CHECKLIST FOR STUDENTS OF TECHNICAL DRAWING

FUNDAMENTAL KNOWLEDGE AND SKILLS	RELATED KNOWLEDGE	ADVANCED KNOWLEDGE AND SKILLS
DRAFTING EQUIPMENT	MATH	DEVELOPMENT AND INTERSECTIONS
FUNDAMENTAL DRAFTING TECHNIQUES	WELDING	GEOMETRIC DIMENSIONING AND TOLERANCING
SKETCHING	MEDIA AND REPRODUCTION	THREADS AND FASTENERS
GEOMETRIC CONSTRUCTION	MANUFACTURING	SPRINGS
VISUALIZATION	MATERIALS AND PROCESSES	CAMS
MULTIVIEW DRAWING		GEARS
SECTION VIEWS		MACHINE DESIGN DRAWING
GRAPHICAL DESCRIPTIVE GEOMETRY		PICTORIAL DRAWING
AUXILIARY VIEWS		DRAFTING SHORTCUTS
GENERAL DIMENSIONING		CAD TECHNOLOGY
NOTATION		
BASIC CAD SYSTEM OPERATION		

FIGURE 33 *Checklist for students of technical drawing.*

technical drawings that accurately and properly communicate the design to those who will manufacture or build it.

Quality can be defined as the extent to which a product conforms to or exceeds the customer's expectations. In design and manufacturing, customer expectations are typically communicated in the form of specifications. Consequently, in this field, quality is often viewed as the extent to which specifications are met or exceeded. Companies that

FIGURE 34 *Typical CAD technology* (Courtesy Baystate Technologies Inc.).

consistently meet or exceed customer expectations are more competitive.

In addition to designing in quality, it is important to develop a design that is as easy as possible to manufacture. Often there will be several different design options that will meet or exceed customer expectations. When this is the case, the design chosen should be the one that is easiest to manufacture. This concept is known as *design for manufacturability (DFM)* and is covered in Chapter 17.



FIGURE 35 *Typical CAD system.*

Technical drawing plays a key role in determining the ultimate quality of a product. A good technical drawing is one that properly and conveniently



FIGURE 36 *Structural steel drawing* (Courtesy Sigma Design).



FIGURE 37 *Piping drawing* (Courtesy Engineering Graphics Inc.).



FIGURE 38 *Prestressed concrete drawing* (Courtesy Sigma Design).

communicates all of the information needed to transform a design into a product that meets or exceeds customer expectations. Anything less can detract from the quality of the product. The following examples illustrate this connection:

- An incorrect dimension on a technical drawing can cause the part to be produced at the wrong size. Each successive copy produced becomes waste.
- A dimension that is left off a technical drawing or just improperly placed can cause manufacturing



FIGURE 39 *Architectural drawing* (Courtesy Sigma Design).

personnel to interrupt their work to calculate the dimension or dimensions they need. The worst-case result is that they make a computation error and, consequently, produce a faulty part. The best-case result is that the interruption decreases productivity and, in turn, competitiveness.

- An entry left off a parts list can cause purchasing personnel to order an insufficient amount of material and, as a result, interrupt the flow of the manufacturing process.
- An improperly drawn view can cause a part to be manufactured in the wrong configuration.



FIGURE 40 *Mechanical pictorial drawing* (Courtesy Fruchaut Corporation).

These are only a few examples of how technical drawings can affect the ultimate quality of a product. By doing so they also affect the competitiveness of the company that manufactures the product. This book is designed to help students learn how to produce designs and technical drawings that make a positive contribution to quality and competitiveness.

Industry Application

DESIGN FOR MANUFACTURABILITY

Metal Tech Manufacturing Company (MTM) had a reputation for high-quality products produced on time. Unfortunately, so did its principal competitor. Both companies kept their personnel and their processes up-to-date and working at peak performance levels. For years neither company could gain a sustainable competitive advantage over the other—not until MTM decided to adopt *design for manufacturability (DFM)* as a competitiveness strategy.

MTM created DFM teams for all of its products. These teams were composed of design, drafting, and manufacturing personnel. Their charge was to develop designs that met the needs of customers, but could be manufactured as efficiently and in turn as economically as possible. In other words, with the DFM approach, designers had to consider not just functionality, but also manufacturability. A good product was no longer one that met the customer's needs in terms of function. It also had to be efficiently and economically manufactured.

The traditional attitude of "we designed it; making it is your problem" was replaced with "let's design it so that it works, and so that it can be efficiently produced." With manufacturing personnel involved in the design process, MTM's engineers and drafters found themselves being sent back to the drawing board frequently during the early stages of adopting DFM. Every time this happened the design was simplified, and the manufacturing process was streamlined as a result. Soon DFM became second nature, and MTM saw its production costs fall by 32 percent. The company was able to pass the savings along to customers and, as a result, within a year of adopting DFM had almost doubled its sales.

Summary

- Graphic communication involves using visual material to relate ideas. Drawings, sketches, slides, photographs, and transparencies are all forms of graphic communication.
- A drawing is a graphic representation of an idea, a concept, or an entity that actually or potentially exists in life.
- Artistic drawings are used to express the feelings, beliefs, philosophies, or abstract ideas of the artist. Technical drawings are used to clearly and concisely communicate all of the information necessary to transform an idea or concept into reality.
- Types of technical drawings include graphic, oblique, and axonometric projections (parallel projections), and one-, two-, and three-point perspective (perspective projections).
- The purpose of technical drawings is to document the design process.
- The principal applications of technical drawings are manufacturing, engineering, architecture, and construction.
- Technical drawings are regulated by such organizations as the U.S. Department of Defense, the U.S. military, the American National Standards Institute, and the American Society of Mechanical Engineers.
- Design and drafting can promote good-quality competitiveness by ensuring that high quality is designed in from the outset and ensuring that all drawings accurately communicate the design.

Review Questions

Answer the following questions either true or false.

1. A drawing is a graphic representation of an idea, a concept, or an entity that actually or potentially exists in life. T
2. The old adage "a picture is worth a thousand words" is still the basis of the need for technical drawings. T
3. The two basic types of drawings are practical and technical. F
4. Technical drawings can be subtle or abstract. T
5. Artistic drawings are commonly used in the manufacturing field. F
6. A good technical drawing is one that properly and conveniently communicates all the information needed to transform a design into a product that meets or exceeds customer expectations. T

Answer the following questions by selecting the best answer.

1. Which of the following is **not** a component of a projection?
   a. Imaginary lines of sight called projectors
   (b.) Three-dimensional view
   c. The eye of the viewer looking at the object
   d. The imaginary projection plane

2. Which of the following is a subdivision of a parallel projection?
   (a.) Trimetric projection
   b. Cavalier projection
   c. Cabinet projection
   d. Oblique projection

3. Which of the following is **not** a type of perspective projection?
   a. One-point
   b. Two-point
   c. Three-point
   (d.) Four-point

4. Which of the following is **not** a step in the design process?
   a. Identify a problem or a need.
   b. Identify ideas to solve the problem.
   (c.) Obtain examples of several different kinds of technical drawings taken from the real world of drafting.
   d. Select a proposed solution.

5. Which of the following is **not** a field that uses technical drawings extensively?
   a. Manufacturing
   (b.) Retail
   c. Engineering
   d. Architecture and construction

6. Which of the following is **not** a U.S. organization that regulates technical drawing practices?
   a. American Society of Mechanical Engineers (ASME)
   b. U.S. Department of Defense (DoD)
   (c.) International Standards Organization (ISO)
   d. U.S. military (MIL)

Introduction Problems

To the student:

The majority of problems available for you in this text are related to technical drawing; however, additional problems are included that aim to do the following:

- Introduce you to the design process.
- Develop your critical thinking skills.
- Involve you in team activities.
- Exercise your imagination and creativity.
- Give you practice in using basic mathematics.
- Introduce you to some product design concepts.

You will need a scientific hand calculator with the usual functions; addition, subtraction, multiplying, dividing, trigonometric functions, logarithms, etc. Some problems may have more information than you need to set up the problem for solution. Some problems may have more than one solution, which is typical of real-life problems in industry.

PROBLEM 1

In a team of three or four students, discuss how the design of products might differ from present designs if everyone had only a thumb and an index finger on each hand. Summarize your ideas in freehand sketches and report orally to the rest of the class.

PROBLEM 2

Figure 7 illustrates the concept of a projection plane (for third-angle projection). In a team of three or four students, discuss how you would go about preparing a device to illustrate this concept to a class of junior high school students. As an aid to your discussions, follow the steps in the design process described in Figure 17. Prepare a freehand sketch of your final solution. Include materials and approximate dimensions.

PROBLEM 3

The weight of the flanged hub shown in Figures 20 and 21 needs to be calculated. The hub is steel with a density of 0.28 pounds per cubic inch. A suggestion for doing this type of calculation is to break up the object into convenient parts for doing the calculations. Separate the flanged hub into a hollow cylinder and a flange with one large hole and four small ones. Calculate the volume of metal and multiply by the density of steel. Use the format shown in the figure for Problem 4-30 (page 152) for your solution presentation.

PROBLEM 4

Optimization in product design usually means satisfying the design requirements for the least cost. For a box design, least cost means using the least amount of material. Assume that a square box with an open top is to have a volume of 50 cubic inches. To visualize the optimum conditions for the box, prepare a plot of TOTAL AREA OF MATERIAL versus dimension D. That is, plot AREA on the vertical axis, dimension D on the horizontal axis.

Select a trial dimension H. Then calculate the total area of the material. The suggested axes and calculation steps are given in the following figure:



V = VOLUME = 50 in^3
$= D^2H$
EXAMPLE CALCULATION:
LET H = 2 in
$50 = D^2(2)$
$D = \sqrt{25}$
D = 5 in
$AREA = D^2 + 4\,DH$
$= (5)^2 + 4(5)(2)$
$= 65\ in^2$



Try different values of H.
Calculate and plot A.
Construct a best fit curve through the A points.
Lowest point of A Curve determines H.

PROBLEM 5

A student was asked to study Figure 33 (page 15) to compare what skills and knowledge the student already had to the topics listed in the checklist. One comment the student had was, "I believe that math should be on all three lists." What is your opinion regarding math and why? Discuss this question in a group of three or four and document your conclusions.

1

CAD and Technical Drawing

KEY TERMS

CAD system
CAM
CD-ROM
Computer graphics (CG)
CPU
Digitizer
Display monitor
Fixed disk drive
Hardware
Microprocessor
Mouse
Plotter
Printer
Software
Solid modeling

CHAPTER OUTLINE

Overview of CAD • Key computer and CAD concepts • CAD systems • CAD workstation components • CAD software • Summary • Review questions

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the concept of CAD.
- Explain key CAD concepts including: computer graphics, computer-aided manufacturing, computer-integrated manufacturing, computer-aided engineering, hardware, software, operating system, and application program.
- Define the term *CAD system.*
- List and explain the most common components in a CAD workstation.
- Explain the concept of CAD software.
- Demonstrate the process for selecting a CAD system.
- Explain the concept of modeling.
- Explain the concept of parametric design.

This chapter provides a comprehensive treatment of modern computer-aided drafting as well as a section on using the Internet as a tool in design and drafting. These topics are covered conceptually rather than from the perspective of a specific vendor or Internet provider.

Overview of CAD

The dawning of the age of computers brought significant change to the fields of design, drafting, and engineering. The computer also brought corresponding changes to all of the various other fields related to design, drafting, and engineering. Although we think of the computer as a relatively recent tool, computers are actually not new. In fact, the first computer was developed in the 1830s by a British mathematician named Charles Babbage. Babbage's computer was a mechanical number-crunching machine that by today's standards was a dinosaur. However, many of the principles upon which Babbage based his Difference Engine are the same principles upon which today's microprocessor-based electronic computers are based.

Regardless of their relative speed and size, what makes computers such invaluable tools is their ability to store data, perform basic logic functions, and make mathematical computations. The ability to electronically link computers has allowed the design, drafting, and engineering functions in a company to be part of a fully integrated whole that includes marketing, accounting, manufacturing, and shipping.

Because of the computer's abilities, the design, drafting, and engineering functions of analysis, problem solving, and documentation (drawings, parts lists, specifications, etc.) have been significantly improved. So much so, in fact, that engineers have been able to explore new theories that were previously beyond their reach, and drafting technicians have been able to perfect new practices that have revolutionized the ways in which designs are documented.

Modern CAD workstations such as the one depicted in ***Figure 1-1*** had their origins in the 1950s when the United States Air Defense Command first used light pens for data entry. The next major development in the history of CAD occurred in 1963 at the Massachusetts Institute of Technology (MIT) in Boston, Massachusetts, when Professor Ivan Sutherland demonstrated his Sketchpad. The Sketchpad was a device that used a light pen to enter graphic data into a computer. Then, in 1964, IBM released the first commercially marketed CAD system. However, it was the development of the programmable integrated circuit in the 1960s that opened the door for the modern

FIGURE 1-1 *CAD workstation* (Courtesy Advanced Technologies Center).

personal computer–based CAD system. It is still the tiny but powerful microprocessor—a device that is based on integrated circuit technology—that is the fundamental enabling device in today's ever smaller but more capable CAD systems.

Key Computer and CAD Concepts

There are several computer concepts with which today's design and drafting technician should be familiar. Building on these, there are several CAD concepts that should be part of the technician's knowledge base. All of these concepts represent knowledge that should become second nature to computer-literate design and drafting personnel.

The first two of these concepts are analog and digital computers. Of the two, it is the digital computer that people use most. For example, the personal, laptop, and notebook computers used in business, design, drafting, engineering, and manufacturing are all digital. Analog computers can be used to measure continuous physical properties such as heat, pressure, depth, and speed. Consequently, they are used most often to monitor and control mechanical, electronic, and hydraulic systems.

The most immediately noticeable difference between analog and digital computers is in how they display information for human use. Digital computers can display information in a readable form that requires no translation (i.e., using alphanumeric characters). Analog computers feed information back in ways that require interpretation or special devices for translation. Perhaps the best example of this difference is the clock. A clock with moving hands is an analog device. It measures the continuous passing of time. As time passes, the clock hands move accordingly. The clock face is inscribed with numbers

ANALOG CLOCK



DIGITAL CLOCK

FIGURE 1-2 *Analog and digital clock.*

arranged in a specified order that allows people to translate the positions of the hands into hours and minutes. A digital clock, on the other hand, simply displays the time using alphanumeric characters, *Figure 1-2.* CAD systems use digital computers.

Another important computer concept is microminiaturization. This concept accounts for the tendency of computers to become ever smaller, yet more powerful. The key enabling ingredient in the ongoing microminiaturization process is the programmable integrated circuit or IC chip, *Figure 1-3.* These microchips are placed on printed circuit boards that, because of the size of the chips, can now fit hundreds of components into a relatively small area. Integrated circuits allowed for the development of the microprocessor, the key technology in today's small but powerful computers.



FIGURE 1-3 *Intel chip.*

The rapid growth of the use of computers in the world of design and drafting brought forth a deluge of new, and often confusing, terms. Such terms as CAD, CADD, CG, CAE, AD, and hundreds of others spawned by the computer revolution began to be heard in drafting and design departments. As a result, drafting and design practitioners found themselves confused by it all.

The reader should be conversant in the language of computers as it applies to design and drafting. The first step is to develop an understanding of the term "computer-aided drafting" or CAD.

Before attempting to form a definition for CAD, the definition of "drafting" should be thoroughly understood. Most people think of drafting as simply the drawing of plans. True, drafters do draw plans. However, this is a very limited definition because drafters do much more than draw plans.

To understand drafting in its broadest sense, one must begin with the design process. The design process is an organized, systematic procedure used to accomplish a design that is needed to solve a problem or meet a need, *Figure 1-4.* Each step in the design process requires various types of documentation,



FIGURE 1-4 *The modern design process.*

such as sketches, preliminary drawings, working drawings, calculations, bills of material, parts lists, and schedules. Producing or "drafting" this documentation is the job of the drafter. Therefore, drafting means producing the documentation required in support of the design process.

With this understanding of drafting as a concept, one may now begin to develop an understanding of CAD. Computer-aided drafting or CAD means using the computer and peripheral devices in producing the documentation needed to support the design process. Put another way, CAD means using the computer and peripheral devices to do drafting.

A well-informed drafter should be able to distinguish CAD from among the various other related terms frequently heard in modern drafting settings, such as AD, CADD, CAE, CG, and CAM.

CAD is usually taken to mean computer-aided drafting, but it can also be used to mean computer-aided design. It is up to the person using the term to make the distinction. AD means automated drafting, and it is synonymous with CAD or computer-aided drafting. Originally, AD was used when referring to the use of the computer to do drafting, and CAD was used when referring to the use of the computer as a design tool. However, AD did not catch on because it is a less distinctive term than CAD. Consequently, CAD began to be used to mean both computer-aided drafting and computer-aided design.

CADD is the acronym for computer-aided design and drafting. This is a broad concept in which a computer system is used for both design and drafting. CAE is the acronym for computer-aided engineering, which is sometimes used instead of computer-aided design.

CG is short for *computer graphics*. This is a term that is used and misused a great deal. It is sometimes used in place of CAD (drafting). However, in reality, it is a much broader term. CG means using the computer and peripheral devices for producing any type of graphic image, technical or artistic.

None of these terms has been formally standardized. However, there is a definite trend toward greater use of CAD when speaking of drafting and when speaking of design. We will follow this practice in this textbook.

The manufacturing equivalent of CAD is computer-aided manufacturing, or *CAM*. CAM refers to computer-controlled automation of the various manufacturing processes used in modern industry. CAD/CAM links together the processes of design, drafting, and manufacturing. The CAD/CAM process involves designing a product on the computer, using the computer to produce necessary documentation,

CAD SYSTEM =

HARDWARE + SOFTWARE + USERS

FIGURE 1-5 *Components of a CAD system.*

and using the database stored in the computer from the design and drafting phases to issue the manufacturing instructions to automated machines and industrial robots.

CAD Systems

People who use the term *CAD system* are usually referring to a configuration of computer hardware, or the tools of the CAD technician. However, this is a misuse of the term. CAD hardware is just one of the three components that must be present in order to have a CAD system.

A CAD system actually consists of hardware, software, and users, ***Figure 1-5***. A collection of CAD hardware is properly referred to as a hardware configuration. In order to turn a hardware configuration into a CAD system, software and well-trained users must be added.

CAD Workstation Components

Hardware is the term given to the computer's physical equipment or devices. Many different companies manufacture CAD hardware. Consequently, numerous configurations are on the market. However, a typical hardware configuration consists of a display monitor, input devices, output devices, storage devices, and a central processing unit (CPU), ***Figure 1-6***.



FIGURE 1-6 *Typical hardware configuration* (Courtesy Hewlett-Packard Co.).

Display Monitor

The *display monitor* is an output device that displays the information on which the CAD technician is working. As any type of documentation is created, it is displayed on the screen of the terminal, *Figures 1-7* and *1-8*.

Checklist of Widely Used Input Devices

- ✓ Keyboard
- ✓ Mouse
- ✓ Digitizing Tablet
- ✓ Puck
- ✓ Stylus
- ✓ Trackball
- ✓ Joystick
- ✓ Light Pen
- ✓ Touch Panels
- ✓ Voice Recognition Devices

FIGURE 1-7 *Checklist of widely used input devices.*

Checklist of Widely Used Output Devices

- ✓ Pen Plotters
  - ▸ Drum
  - ▸ Flatbed
  - ▸ Microgrip
- ✓ Dot Matrix Plotter
- ✓ Electrostatic Plotter
- ✓ Printer/Plotters
  - ▸ Inkjet Printer/Plotter
  - ▸ Laser Printer/Plotter
  - ▸ Dot Matrix Printer

FIGURE 1-8 *Checklist of widely used output devices.*

The most common type of monitor is the raster display. Raster displays create images by illuminating pixels (picture elements) on the screen. The more pixels available on the screen for illumination, the higher the quality of the image. High resolution produces a high-quality image. Storage-tube displays create images by tracing them on the back of the display screen with an electron beam as with refresh displays. However, unlike refresh displays, storage-tube images are stored and do not have to be refreshed. Graphics displays may be color or monochrome (amber or green) devices.

Most CAD configurations use a raster display monitor. These devices are similar to modern television sets in that the image is created by an electron beam that scans the back of the screen, illuminating pixels. The process is known as raster scanning.

The nature of the CAD technician's work demands that he or she have a large viewing area. Consequently, most CAD workstations use at least 17″ displays, and many use 21″ models or larger.

Resolution is an issue when selecting a display monitor. It has to do with the level of detail that can be distinguished on a display. The more pixels per inch, the higher the resolution. The resolution of a display monitor and the image on the display are products of a video display card. This card determines the number of pixels per inch on the display monitor. A typical monitor will have $1{,}600 \times 1{,}200$ pixels or more.

Color is another important feature of display monitors. Like resolution, color is a function of the video display card. Colors on a display are produced in much the same way as an artist produces them on a canvas; by mixing different colors. Most displays can produce 256 different colors. A color display requires more video memory and processing power in the computer, and with higher resolution even more memory and processing power are needed. Because of this, video cards often have their own processor (known as a video accelerator) and their own memory.

CAD technicians need to understand the specifications that are typically given for display monitors. Displays are rated according to their ability to refresh the screen—in other words, according to how fast the video display card can "repaint" the pixels, which it must do constantly in order to retain the image. The rating given for a display contains two specifications, one for vertical pixels and one for horizontal pixels. A low rating would be 60 Hz. The modern CAD display monitor should be in the higher ranges currently available, or eye fatigue will be a problem and productivity will suffer.

Input Devices

Input devices are those used by CAD technicians to interact with the CAD system. There are numerous different kinds of input devices, some that are used independently and some in conjunction with each other, *Figure 1-7.*

The keyboard is one of the most frequently used input devices in a CAD system. Keyboards are used for entering text, system commands, X-Y or X-Y-Z coordinates, and any other type of alphanumeric input.

Most CAD systems have keyboards that contain both the standard alphanumeric keys and special auxiliary keys. The special auxiliary keys may be part of the separate numeric pad or a group of display control keys.

Keying is the process used for entering text on drawings, entering certain system commands, entering dimensions not entered automatically, and for logging on to the system. Keys may also be used for cursor control.

The *mouse* is a widely used input device used for issuing commands and moving the screen cursor to different locations. There are two types of mice. One type (mechanical) has a roller on its underside that detects movement and transfers that movement to the screen cursor. The other type (optical) detects movement by reflecting a light beam off a special surface and transfers that movement to the cursor. Both have one to three buttons for command selection.

The *digitizer* is a special electromechanical input device used to convert graphic data, such as a sketch or a drawing, into digital data as it is input. A digitizer can be used for a number of different functions. It can be used in conjunction with a stylus or puck to control the screen cursor and it can be used to create, locate, and manipulate graphic and alphanumeric data.

A touch panel allows commands to be given and options selected by touching the display screen with the finger. Touch-panel displays sense the pressure or heat from the finger.

An emerging input technology is the voice recognition device. Commands are made into a microphone, and the system is trained to recognize the user's voice. CAD technicians can expect to use this technology in the future as it continues to develop.

Output Devices

Hard copy output from a CAD system is produced by various types of *plotters* and *printers, Figure 1-8.* Pen plotters use pens of just one or a variety of colors to produce drawings on paper, vellum, or film. There are three broad categories of pen plotters: drum, flatbed, and microgrip.

A drum plotter consists of a long cylinder and a moveable pen carriage. The medium (paper, vellum, or film) moves back and forth over the cylinder while the pen carriage moves simultaneously over the medium.

With flatbed plotters the medium is mounted on a flat surface above which is a movable pen carriage. The medium remains static while the pen carriage moves over it along both an X and a Y axis. The surface area on a flatbed plotter corresponds to the standard sizes of drafting media (i.e., A, B, C, D, E).

Microgrip plotters resemble drum plotters and work in a similar manner. The term "microgrip" comes from the tiny rollers that grip the edge of the medium, moving it back and forth as the pen carriage moves simultaneously. Microgrip plotters are popular because they are flexible, adaptable, and relatively inexpensive.

Key factors to consider when selecting pen plotters are accuracy, acceleration, repeatability, and speed, *Figure 1-9.* Accuracy is the difference between what should be drawn and what actually is expressed in thousandths of an inch. Acceleration is a measure of how long it takes the pen carriage to get up to plotting speed (like measuring how long it takes an automobile to go from 0 to 60 miles per hour). Acceleration is expressed in Gs (for gravitational force).

Pen speed is a measure of how fast the pen moves across the medium. A fast pen speed typically produces a higher-quality, more consistent line. A slower speed produces a darker line because the ink has



FIGURE 1-9 *Selection factors for pen plotters.*

more time to flow. However, a slow speed can also lead to ink bleeding and blotting. Repeatability is the ability of the plotter to redraw the same line over and over. With poor repeatability there will be double lines or progressively thickened lines.

The dot matrix plotter produces the image by printing a series of dots on the medium. The key evaluating component in a dot matrix plotter is a selenium drum that is electrostatically charged. The process of converting an image into dots is called rasterization.

Electrostatic plotters use a special type of medium that is coated so that toner or ink will adhere to it under an electrostatic charge. The process of rasterization converts the computerized image into dots and the dots are applied to the medium electrostatically, *Figure 1-10.*

Resolution (the number of dots per inch) is an issue for both dot matrix and electrostatic plotters. The more dots per inch, the better the resolution.

Printer/plotters are output devices that can do double duty; they can be used as printers for alphanumeric output and as plotters for graphic output. An inkjet printer/plotter uses the rasterization process to convert the image or data into dots. Each dot then receives a tiny drop of ink, *Figure 1-11.* A laser printer/plotter also makes use of the rasterization process but uses a beam of light and an electrostatically charged medium to produce the image, *Figure 1-12.*

Dot matrix printers are used less and less, but they still may be found in some offices. With this device the dots are applied in one of two ways. The first way is a mechanical process in which a carbon or ink ribbon is struck by pins arranged in a print head (similar to an old mechanical typewriter). The other way is a thermal process in which heat is used to apply the dots.

FIGURE 1-10 *LED plotter* (Courtesy CalComp).



FIGURE 1-11 *Inkjet printer* (Courtesy CalComp).

FIGURE 1-12 *IBM network printer 12* (Courtesy IBM Corp.).

Storage Devices

In drafting and design departments of the past, all drawings and other documentation were stored in filing cabinets, in hanging files, and in drawing cabinets. In modern drafting and design departments, documentation is stored electronically. *Figure 1-13* is a checklist of storage devices associated with modern CAD systems.

Checklist of Widely Used Storage Devices

- ✓ Fixed Disk Drive
- ✓ Floppy Disk Drive
- ✓ Zip Drive
- ✓ CD-ROM Drive
- ✓ Optical Disk Drive
- ✓ Magnetic Tape Storage

FIGURE 1-13 *Checklist of widely used storage devices.*

Central Processing Unit

The central processing unit *(CPU)* in the computer consists of two major components—the control section and the arithmetic/logic section—as well as internal storage and interfacing mechanisms to tie it to peripherals, *Figure 1-14.* It should be noted that although the main memory is often housed in the same console as the two components of the processing unit, it is not contained on the same printed circuit board (except in the case of the microcomputer). Consequently, the control section and the arithmetic/logic section taken together are called the central processing unit of the computer. When the control section and the arithmetic/logic section are both placed on a single silicon chip, you have a *microprocessor.*

The purpose of the control section is to direct all activities of the computer as set forth in stored programs. It controls the arithmetic/logic section, input and output operations, the transmittal of data to and from storage, and all other operational functions of the computer. The arithmetic/logic section performs all addition, subtraction, multiplication, division, and other mathematical operations and compares data so that logical decisions can be made by the computer.

One of the four characteristics that set a computer apart from other machines is that it can modify program instructions by making logical decisions. A computer has this capability because the arithmetic/logic section of the central processing unit is able to make the types of comparisons needed for such logical decisions.



FIGURE 1-14 *Central processing unit.*

CAD Software

Software is the term for the nonmechanical components of a computer system. Such components include computer programs, documentation of those programs, and the various types of technical and reference manuals that go with the system. However, when most people use the term software, they are talking strictly about computer programs. A computer program is a specially coded set of instructions that directs the computer in performing all operations.

People who are trained to write programs are called computer programmers. You do not have to know how to program a computer to be an efficient and effective computer user. Most computer users do not know how to program a computer. However, it is helpful to understand what computer programs do.

Computers are capable of doing only what they are programmed to do. People write computer programs. Consequently, people control computers. Communicating with a computer by means of a computer program is similar to talking with a person from another country; one must use that person's language, or a language the person understands.

CAD software allows the computer to do what the user wants it to do when issuing commands and selecting options. There are many different types of CAD software produced by many different vendors. However, regardless of the type or the vendor, all CAD software has the following features: (1) commands for generating basic geometric shapes and figures, (2) viewing controls that determine what appears on the screen and how, and (3) modifying commands for editing, revising, and correcting.

CAD software is generally divided into two broad categories. Drafting software allows users to generate 2-, 2½-, and 3-dimensional drawings and other related documentation. Design software enhances the capabilities of designers.

Drafting Software

Drafting software allows users to accomplish 2-, 2½-, and 3-dimensional drafting tasks. Two-dimensional (2D) tasks include orthographic drawings, bills of material, parts lists, and a variety of other types of



FIGURE 1-15 *Drawing produced on a CAD system* (Courtesy Sigma Design).

documentation, such as tables, charts, and schedules. Two-and-one-half-dimensional (2½D) drawings are oblique drawings.

Oblique drawings show the length, width, and depth of an object all on the same view. Three-dimensional (3D) drawings are isometric, dimetric, trimetric, or perspective drawings. Three-dimensional drawings are sometimes referred to as wireframe drawings. This is to differentiate them from the more complex solid models, which are sometimes developed in support of the design process. A 3D wireframe model defines only the exterior of the object. *Figures 1-15* (page 31) and *1-16* are examples of 2D CAD drawings.



FIGURE 1-16 *Drawing produced on a CAD system* (Courtesy Tektronix Inc.).

Industry Application

Mark Sutton had been an excellent drafting and design student at Brookview Academy. He proved to be particularly adept at CAD. Consequently, it surprised no one when the chairman of Brookview's Drafting and Design Department asked Sutton to be a student representative on a faculty committee to purchase new plotters for the CAD lab.

At the first meeting of the committee it became apparent that no consensus existed concerning what type of plotters to purchase. One instructor favored flatbed pen plotters because they resembled traditional drafting boards. The resemblance helped him "relate better to the plotters." Another instructor recommended electrostatic plotters, but suggested that low-resolution models be purchased to save funds. She hoped to have funds left over to purchase some precision measurement tools for her mechanical drafting classes.

After two meetings and three hours of discussion and debate, the committee was no closer to achieving consensus than it was at the outset of its deliberations. In order to gain a better perspective, the committee chair asked the members to take a week to investigate, think, and research the issue. He asked the members to meet in a week. Before that meeting, each member was to hand him a sealed one-page recommendation with supportive rationale.

Mark Sutton, feeling somewhat intimidated by it all, decided to give the chair not his opinion but the opinion of practitioners. During the interim week he visited several companies and talked with five different drafting managers. Although their reasons differed somewhat, all five recommended microgrip plotters. Sutton, in preparation for the next meeting, prepared a one-page recommendation containing the reasons given by the various drafting managers.

The committee chair collected all of the sealed recommendations the day before the scheduled committee meeting and studied them overnight. The next day he opened the meeting by saying, "One of our members put a lot of effort into formulating a recommendation. I'd like to read it to you." Sutton slumped in his seat and his face flushed as the chair read his recommendation and reasons. The reasons Sutton had given were adaptability, flexibility, and relatively inexpensive pricing. Discussion began and within ten minutes the committee had formed a consensus around Sutton's recommendation. The other recommendations were put aside.

Once the decision to purchase microgrip plotters had been made, one of the committee members asked, "Whose recommendation did we adopt?" The chair smiled, nodded at Sutton, and said, "Our student member."

Design Software/Solid Modeling

Design software enables a number of specific design tasks to be undertaken on a CAD system. The most frequently used of these include solid modeling, finite element analysis, kinematics, and simulation. *Solid modeling* involves constructing a mathematical, geometric model of a design part and displaying it on the monitor screen. A solid model is the most accurate, most realistic type of geometric model that CAD systems are currently capable of producing.

The most important difference between a solid model and the wireframe type of geometric model is that the wireframe model defines only the exterior of the object. A solid model, on the other hand, defines not only the exterior of the object, but the interior as well. Additional capabilities such as shading and coloring differentiate surfaces of the solid model, making it even more realistic and easy to understand, *Figures 1-17*, *1-18*, and *1-19*.

Finite-element analysis is another frequently used design capability of CAD software. Most design products require some type of analysis involving stress, temperature, heat, and other types of calculations. The finite-element analysis capability allows the computer to divide the object into a series of small rectangular and triangular objects such that the surface of the geometric model appears to be a grid, *Figure 1-20*. In this way, the computer is able to analyze how each individual grid position will behave under certain types of stress and strain and other conditions, as well as how the entire object will behave under these conditions.

Kinematic software that can be run on CAD systems is popular among engineers and designers



FIGURE 1-17 *Solid model* (Courtesy SolidWorks Corporation).



FIGURE 1-19 *Solid model of a machined gear* (Image courtesy of SolidWorks Corporation).



FIGURE 1-18 *Solid model of a machined and welded part* (Courtesy SolidWorks Corporation).

because it saves them a great deal of time and trouble. In the past, mechanical engineers and designers had to build cardboard models or elaborate drawings of the various types of mechanical linkages they designed. The cardboard models were used to determine if the required motion or linkage would actually work in the finished product as intended in the design. This is not a cost-effective way to design a linkage mechanism. With kinematic software, the engineers and designers can create a geometric model of the linkage, display it on the monitor, and introduce motion to determine if the linkage works as designed. If the



FIGURE 1-20 *Finite-element analysis* (Courtesy McAuto).

linkage does not work and revisions are required, designers and engineers can make the adjustments much faster and more easily using the various other capabilities of CAD systems.

Simulation software is available for CAD systems that allows electronic designers and engineers to test and verify the performance of a circuit before sending the design to production. In the past, electronic designers and engineers had to build live prototypes and test them to ensure that they worked properly before sending the circuits to production. This was a time-consuming and expensive process.

Simulation software is available for CAD systems that allows electronic designers and engineers to test and verify the production. By taking advantage of the many additional capabilities of CAD systems, designers and engineers can quickly and easily make corrections and revisions to circuits when simulation testing detects the need for them.

Summary

- Regardless of their relative speed and size, what makes computers such invaluable tools is their ability to store data, perform basic logic functions, and make mathematical computations. The ability to electronically link computers has allowed the design, drafting, and engineering functions of a company to be part of a fully integrated whole that includes marketing, accounting, manufacturing, and shipping.
- Modern CAD workstations had their origins in the 1950s when the United States Air Defense Command first used light pens for data entry. The next major development in the history of CAD occurred in 1963 at the Massachusetts Institute of Technology (MIT) when professor Ivan Sutherland demonstrated his Sketchpad. IBM released the first commercially marketed CAD system in 1964.
- All computers are either digital or analog. Analog computers are used to measure continuous physical properties such as heat, pressure, depth, and speed. They are used most often to monitor and control mechanical, electronic, and hydraulic systems. The digital computer is the type that most people recognize and use. Today's personal, laptop, and notebook computers are digital.
- Microminiaturization is the process that accounts for the fact that over time computers have gotten progressively smaller, but simultaneously more powerful. The enabling ingredient in the microminiaturization process is the programmable integrated circuit, which allowed the development of the microprocessor—the key component of today's small but powerful computers.
- Computer-aided design and computer-aided drafting are both referred to as CAD. Computer-aided manufacturing or CAM involves using the computer to enhance the capabilities of the production components of a company. Computer graphics is a broad term that encompasses the use of the computer and peripheral devices to produce any type of graphic image, either technical or artistic.
- CAD systems have three broad components: hardware, software, and users. CAD workstations consist of a display monitor (typically a raster display), various input devices, various output devices, various storage devices, and the central processing unit or CPU.
- CAD software has the following features: (1) commands for generating basic geometric shapes, figures, etc.; (2) viewing controls that determine what appears on the screen and how; and (3) modifying commands for editing, revising, and correcting. Drafting software allows users to produce 2-, 2½-, and 3-dimensional drawings and other types of design documentation. Design software extends the designer's capabilities with such functions as solid modeling, finite-element analysis, kinematics, and simulation.

Review Questions

Answer the following questions either true or false.

1. The sketchpad was a major development in the evolution of CAD.
2. The modern CAD workstation originated in the late 1940s.
3. Documenting the design process is the responsibility of drafting technicians.
4. Computer graphics is a broader concept than CAD.
5. The analog computer is the type that most people recognize and use.
6. CAD workstations usually use a *raster* type of display monitor.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** true regarding what makes computers such valuable tools?
   a. Their ability to store data

b. Their ability to perform basic logic functions
c. Their ability to perform mathematical computations
d. Their ability to provide linkages that guide the user

2. Which of the following is **not** one of the three broad components of a CAD system?
   a. Input device
   b. Hardware
   c. Software
   d. Users
3. Which of the following is **not** an input device?
   a. Keyboard
   b. Digitizer
   c. Mouse
   d. CPU
4. Which of the following is **not** a feature of CAD software?
   a. Commands for generating basic geometric shapes, figures, etc.
   b. Commands that control mechanical, electronic, and hydraulic systems
   c. Viewing controls that determine what appears on the screen and how
   d. Modifying commands for editing, revising, and correcting
5. Which of the following is **not** a type of CAD design software?
   a. Wireframe software
   b. Word processing software
   c. Finite-element analysis software
   d. Kinematic software

2

Technical Drawing with Instruments

KEY TERMS

Adjustable curve
Appliqué
Bow compass
Burnishing
Compass
Decimal-inch scale
Drawing surface
Drop-bow compass
Dry transfer sheet
French curve
Full-divided scale
Hardware
Irregular curves
Kilo
Lettering machines
Milli
Open-carriage typewriter
Open-divided scale
Overlay drafting
Scissors drafting
Scriber templates
Stick
T-square
Transfer cards
Whiteprinter

CHAPTER OUTLINE

Conventional instruments • Conventional drafting Requisites • Drawing sets • Scales • Ink tools • Technical pens • Mechanical lettering sets • Butterfly scriber • Airbrush • Paper sizes • Whiteprinter • Files • Care of drafting equipment • Use of appliqués • Use of burnishing plates • Typewritten text • Summary • Review questions • Chapter 2 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Recognize the most frequently used conventional drafting instruments and their purposes.
- Describe the contents of a typical drawing set and the purpose of each item.
- Demonstrate the proper use of scales, including the mechanical engineer's, architect's, civil engineer's, and metric scale.
- Demonstrate how to read the following precision measurement instruments: micrometer, vernier caliper, microfinish comparator, and the ellipses instrument.
- Explain the two types of technical pens, their respective uses, and how to properly clean them.
- Demonstrate the proper use of a mechanical lettering set.
- Demonstrate the proper use of a butterfly scriber.

(continued)

(CHAPTER OBJECTIVES continued)

- Explain the uses of the airbrush.
- Describe the various standard sizes of paper used in drafting in both inches and millimeters.
- Explain how the whiteprinting process works.
- Explain the term *appliqué* and how the various kinds are used.
- Explain the term *burnishing plate* and how one is used.
- Describe the concept of overlay drafting.
- Describe the concept of scissors drafting.

Note to Instructors and Students

A survey of users of this text indicates that there are three main approaches to teaching design and drafting: (1) begin students on the CAD system without instruction in conventional methods or instruments, (2) begin students with instruction in conventional methods and instruments before introducing them to CAD, and (3) begin students on the CAD system, but provide instruction in conventional methods and instruments for historical purposes. To accommodate all of these instructional methodologies, the authors continue to provide this chapter on the use of conventional drafting and design instruments based on the assumption that instructors who prefer to begin students on the CAD system may simply skip this chapter.

The advent of computer-aided drafting or computer-aided design (CAD) has radically changed the instruments used to produce technical drawings. In fact, one rarely hears the term instruments used in a modern technical drawing setting. Instead one hears terms such as hardware, software, and systems. The tools used in a modern drafting department have changed continually over the years. Such changes are often associated with CAD, but in reality the tools used to produce technical drawings have always been in a state of continual evolution and always will be.

Engineers, designers, and drafters who are old enough can remember when technical drawings were prepared in ink on linen using T-squares. Technological changes eventually saw T-squares superseded by parallel bars that were, in turn, superseded by drafting machines. Linen was replaced by vellum. Templates replaced various mechanical instruments. Overlay and scissors drafting techniques eliminated a certain amount of duplication.

These non-automated developments continued (and to a much lesser extent still continue) until the giant leaps in technical drawing technology brought about by CAD occurred. With the advent of CAD, conventional drafting instruments began to be used less and less. However, they have not yet completely faded away, and it will be years before they do.

Therefore, this chapter covers first the conventional instruments and then the *hardware* and systems associated with CAD. In this way, students who wish to learn about the evolution of technical drawing instruments, techniques, and media from the past to the present may do so. This approach is recommended to help today's technical drawing personnel gain a perspective on where they fit into the evolutionary process with regard to their profession.

Conventional Instruments

In drafting, no lines are made freehand. Each and every line is drawn using some kind of a drafting tool. It is up to the drafter to own a complete set of standard drafting tools in order to be fully functional.

When purchasing conventional drafting equipment, care must be taken to obtain high-quality equipment from a reliable dealer. It is advisable to consult with an experienced drafter, a drafting instructor, or a reputable dealer.

The following is a list of the minimum required drafting equipment. Special templates and special equipment must be added to this list, depending upon the field of drafting and, in some cases, the actual product manufactured by the company. Each of the following pieces of equipment is illustrated in this chapter.

- Drawing board—24″ × 36″ (60 cm × 90 cm) minimum size
- T-square (parallel straightedge or drafting machine) to suit board
- 45° triangle—8″ (20 cm) size
- 30°–60° triangle—8″ (20 cm) size
- Triangular scale (depending upon the field of drafting)
- Center wheel bow compass—6″ (115 cm) with extension bar
- Drop bow compass (recommended)
- Irregular curves (two or three different configurations)
- Dividers—6″ (15 cm)
- Drafting brush
- Mechanical drafting pencils with lead
- Protractor or adjustable triangle
- Erasing shield

- Eraser
- Lead pointer with steel cutting wheel (pencil)
- Lead sandpaper or flat file (for compass lead)
- Circle template
- Ellipse template
- Drafting tape or drafting dots
- Calculator
- Dry cleaning pad (optional)

The following is a list of the required inking supplies.

- Technical pen #2½ (for lettering scriber)
- Technical pen #1 (for lettering scriber)
- Technical pen #0 (for lettering scriber)
- India ink—black
- Pen cleaning solvent
- Lettering scriber
- Lettering template #100
- Lettering template #175
- Lettering template #290
- Compass adaptor for pen

Note that some specialized or expensive equipment is often furnished by the company.

Conventional Drafting Requisites

Drawing Table

Drawing tables are available in a variety of styles. Most are adjustable up and down and can tilt to almost any angle from vertical 90° to horizontal, ***Figures 2-1*** and ***2-2***.

FIGURE 2-1 *Drafting table* (Courtesy Alvin & Co.).

FIGURE 2-2 *Drafting table* (Courtesy Alvin & Co.).

Drawing Surface

The *drawing surface,* whether it is a drawing tabletop or drawing board, must be flat, smooth, and large enough to accommodate the drawing and some drafting equipment. If a *T-square* is used on a drawing board, at least one edge of the board must be absolutely true. Most high-quality drafting boards have a metal edge to ensure against warpage and against which to hold the T-square securely.

Standard drafting boards range in size from small, 12″ × 17″ (30 cm × 43 cm), to large, 31″ × 42″ (78 cm × 105 cm). Standard drafting tabletops range in size from 31″ × 42″ (78 cm × 105 cm) to 37½″ × 60″ (94 cm × 150 cm).

Lighting

It is important that the drawing surface be fully lighted without any shadows, ***Figure 2-3***.

Top Cover

The drafting board should have a top cover that protects the board surface and provides a perfect drawing surface. A good top cover actually seals over holes made by compass points, and it is easily cleaned, ***Figure 2-4***.



FIGURE 2-3 *Fluorescent lamp* (Courtesy Waldman Lighting).



FIGURE 2-4 *Drafting board top cover* (Courtesy Modern School Supplies Inc.).



FIGURE 2-5 *Equipment organizer* (Courtesy Stacor Corp.).

Efficiency

To be fully efficient at drafting, one must keep all equipment clean, correctly adjusted and/or sharpened, and stored in a convenient location, ready for use at all times. It is good drafting practice to store each piece of equipment in a specific location and return it to its location after use. An organizer, such as the one shown in *Figure 2-5*, aids in keeping all equipment in its place.

Left-Handed Drafters

Most drafting equipment is designed for the right-handed drafter, although left-handed types of drafting machines can be purchased. The T-square is simply placed on the right side of the drafting board by left-handed drafters, but everything else is right-handed. The left-handed drafter has to adapt. The lettering scriber is especially difficult to manipulate.

T-Square

While T-squares are not used today in industry, they do provide a parallel straightedge for the beginning drafter. The T-square is used to draw horizontal lines. Draw lines only against the upper edge of the blade. Make sure the head is held securely against the left edge of the drawing board to guarantee parallel lines, *Figure 2-6*. The T-square is composed of two parts: the head and the blade, *Figure 2-7*. The two parts are fastened together at an exact right angle. The blade must be straight and free of any nicks or imperfections. A transparent acrylic edge is recommended since this allows the drafter to see the drawing underneath the edge. T-squares can be purchased with adjustable heads for drawing specific angles.

Parallel Straightedge

The parallel straightedge is always parallel, regardless of where it is placed upon the drawing surface. Parallel control is accomplished by a system of cords and pulleys, *Figure 2-8*. The parallel straightedge replaced the T-square in industry and is still used somewhat today. Most straightedges come with a transparent acrylic edge, and some have rollers for a smooth gliding action. Some have a locking brake that permits the straightedge to be locked in any position.

Drafting Machines

A drafting machine is a device that attaches to the drafting table and replaces both the T-square and the

FIGURE 2-6 *T-square and other traditional instruments* (Courtesy Teledyne Post).



FIGURE 2-7 *Parts of the T-square* (Courtesy Hearlihy and Co.).

parallel straightedge. There are two basic kinds of drafting machines. One is the arm type, ***Figure 2-9,*** and the other, the newer, is the track type, ***Figure 2-10.*** On both types, a round head holds two straightedges at right angles to each other. The head can be rotated to set the straightedges at any angle. Most machines are available with interchangeable straightedges marked with different scales along their edges.



FIGURE 2-8 *Parallel straightedge* (Courtesy Modern School Supplies Inc.).



FIGURE 2-9 *Arm-type drafting machine* (Courtesy Teledyne Post).



FIGURE 2-10 *Track-type drafting machine* (Courtesy Alvin & Co.).

Drafting machines replace straightedges, scales, triangles, and protractors. They increase accuracy and greatly reduce drafting time. A drafting machine is one of the few tools that can be purchased either as a right-handed or a left-handed instrument.



FIGURE 2-11 *Protractor with vernier.*

FIGURE 2-13 *Drafting machine head with digital readout* (Courtesy Consul & Mutoh Ltd.).



FIGURE 2-14 *Transparent and metal drafting machine straightedges with scale* (Courtesy Vemco Corp.).



FIGURE 2-12 *Reading the vernier.*

Most drafting machines have a protractor and a vernier, which permit readings to 5 minutes of an arc, *Figure 2-11*. Notice that zero on the protractor is in line with the zero on the vernier. The vernier is graduated in 5-minute increments from zero to 60 minutes. To read the vernier, first read the protractor, *Figure 2-12*. In this example, the zero on the vernier points between 18° and 19°. On the vernier, notice that the only line that lines up with a line on the protractor is the 45; thus, this is read as 18°45′. Some drafting machine heads simplify this process by adding a digital readout, see *Figure 2-13*.

Drafting machine straightedges come in sizes of 9″ (23 cm), 12″ (30 cm), and 18″ (45 cm), graduated or ungraduated, in both transparent plastic and aluminum scale, *Figure 2-14*.

A drafting machine, although a precision instrument, should be checked for accuracy at least once a

FIGURE 2-15 *Complete drafting set* (Courtesy Alvin & Co.).

FIGURE 2-16A *Spring-bow compass* (Courtesy Vemco Corp.).

week. The instructions for checking and adjusting a drafting machine are included with the manufacturer's information.

Drawing Sets

Typical drawing sets include *compasses*, dividers, and a ruling pen, ***Figure 2-15***. Many sets include a variety of tools not normally used by the drafter. It is recommended that only those tools actually needed be purchased.

Compasses

There are two main types of compasses: the friction-joint type and the spring-bow type. The friction-joint type is still widely used for lightly laying out pencil drawings that will be inked. The disadvantage of this type of compass is that the setting may slip when strong pressure is applied to the lead.

The spring-bow type of compass, ***Figure 2-16A***, is best for pencil drawings and tracings because it retains its setting even when strong pressure is applied to obtain dark lines. The spring, located at the top of the compass, holds the legs securely against the adjusting screw. The adjusting screw is used to make fine adjustments. Technical pen adapters allow ink attachments to be used, ***Figure 2-16B***.

Compass leads should extend approximately 3/8″ (0.9 cm). The metal point of the compass extends slightly more than the lead to compensate for the distance the point penetrates the paper, ***Figure 2-17***. The lead is sharpened with a sandpaper paddle to

FIGURE 2-16B *Pen adapter* (Courtesy Vemco Corp.).



FIGURE 2-17 *Bow compass lead and metal points.*



FIGURE 2-18 *Bow compass lead point shape* (Courtesy Drafting for Trades and Industry, Basic Skills, Nelson, Delmar Publishers Inc.).

produce clean, sharp lines. The flat side of the lead faces outward in order to produce circles of very small diameter, ***Figure 2-18***. Sharpen with a paddle in the direction of the arrow, as shown, in order to keep the lead sharp longer.

To draw a circle with the *bow compass*, the compass is revolved between the thumb and the index finger, ***Figure 2-19***. Pressure is applied downward on the metal point to prevent the compass from jumping out of the center hole.

Drop-Bow Compass

The *drop-bow compass*, ***Figure 2-20***, is used for circles of .03″ (0.08 cm) to .50″ (1.3 cm) diameter. The compass is adjusted to the required radius. The center point is located on the circle or arc swing point and held in place with the index finger. Rotate the knurled head of the compass between the thumb and second finger.

FIGURE 2-20 *Drop-bow compass* (Courtesy Vemco Corp.).

Bow Compass with Lead Clutch

In order to eliminate the process of sharpening compass leads, some drafters use a compass with a lead clutch of 0.5-mm lead, ***Figure 2-21***. This compass saves time and ends messy lead sharpening. Special compasses are designed only for inking, ***Figures 2-22*** and ***2-23***. An adaptor to attach to a standard compass to draw ink lines is illustrated in ***Figure 2-24***.



FIGURE 2-19 *Drawing a circle with a bow compass.*

FIGURE 2-21 *Bow compass with special clutch* (Courtesy B. Carter Lykins).



FIGURE 2-22 *Inking bow compass* (Courtesy Koh-I-Noor Rapidograph).

FIGURE 2-23 *Inking drop-bow compass* (Courtesy Koh-I-Noor Rapidograph).

FIGURE 2-24 *Standard compass ink adapter* (Courtesy Koh-I-Noor Rapidograph).

Beam Compass

A beam compass, *Figure 2-25*, is used to draw large circles or arcs. Fine line adjustments can be obtained and locked in place. Beam compasses come in sizes from 1″ (33 cm) bars and up.

Adjustable Curve

An *adjustable curve*, *Figure 2-26*, has a locking knob and is used to draw any radius from 6.75″ to 200″ (17 cm to 500 cm). This tool takes over where the ordinary compass leaves off, and it eliminates the beam compass.

Divider

A divider is similar to a compass except that it has a metal point on each leg. It is used to lay off distances and to transfer measurements, *Figure 2-27*.



FIGURE 2-25 *Beam compass* (Courtesy Vemco Corp.).



FIGURE 2-26 *Adjustable curve* (Courtesy Hoyle Products Inc.).



FIGURE 2-27 *Divider* (Courtesy Vemco Corp.).

Proportional Dividers

Proportional dividers are used to enlarge or reduce an object in scale. This tool has a sliding, adjustable pivot that varies the scale, *Figure 2-28.*

Triangle

Two standard triangles are used by drafters. One is a 30–60-degree triangle, usually written as 30°–60° triangle.

The other is a 45-degree triangle and the protractor, written as 45° triangle. The 45° triangle consists of two 45-degree angles, and one 90-degree angle, *Figure 2-29A.*

FIGURE 2-28 *Proportional dividers* (Courtesy Modern School Supplies Inc.).



FIGURE 2-29 *(A) 45° angle, and (B) 30°–60° triangle.*

The 30°–60° triangle contains a 30-degree angle, a 60-degree angle, and a 90-degree angle, *Figure 2-29B.*

Triangles are made of plastic and come in a variety of sizes other than those mentioned. When lines are laid out, triangles are placed firmly against the upper edge of the straightedge. Pencils are placed against the left edge of the triangles and lines are drawn upward, away from the straightedge. Parallel angular lines are made by moving the triangle to the right after each new line has been drawn, *Figure 2-30.*

Adjustable Triangle

An adjustable triangle may take the place of both the 30°–60° and 45° triangles, *Figure 2-31.* It is recommended, however, that this tool be used only for



FIGURE 2-30 *Drawing parallel angular lines.*

FIGURE 2-31 *Adjustable triangle* (Courtesy Modern School Supplies Inc.).

drawing angles that cannot be made with the two standard triangles. The adjustable triangle is set by eye and thus is not as accurate as the solid triangle.

Template

A template is a thin, flat piece of plastic containing various cutout shapes, ***Figures 2-32, 2-33,*** and ***2-34.*** It is designed to speed the work of the drafter and to make the finished drawing more accurate. Templates are available for drawing circles, ellipses, plumbing fixtures, bolts and nuts, screw threads, electronic symbols, springs, gears, and structural metals, to name just a few uses.

Templates come in many sizes to fit the scale being used on the drawing. A template should be used wherever possible to increase accuracy and speed. It is preferable to purchase templates that are stamped and not molded, because molded templates become brittle in time and break.

French Curves

French curves are thin, plastic tools that come in an assortment of curved surfaces, ***Figure 2-35.*** They are used to produce curved lines that cannot be made with a compass. Such lines are referred to as *irregular curves*. Most good French curves are actually segments of such geometric curves as ellipses, parabolas, hyperbolas, and the like.

Using a French Curve

To use a French curve, the irregular curve must be defined by a series of dots. Lightly connect straight lines to get a general idea of where the curved line is going. If the line makes an abrupt turn, a line lightly



FIGURE 2-32 *Circle template* (Courtesy Timely Products Co.).



FIGURE 2-33 *Ellipse template* (Courtesy Timely Products Co.).



FIGURE 2-34 *Bolt and nut template* (Courtesy Timely Products Co.).



FIGURE 2-35 *Assortment of French curves* (Courtesy Modern School Supplies Inc.).



FIGURE 2-36 *Drawing an irregular curve* (Courtesy Koh-I-Noor Rapidograph).

sketched in place of the straight lines may be more useful. Starting from one side or the other, line up the French curve along as many points as possible and draw a dark line connecting these points, *Figure 2-36*. Readjust and align the French curve along all additional points, and continue drawing the curved line. Proceed in this manner until the line is completed.

Adjustable Curve

Adjustable curves form smooth curves. *Figure 2-37* shows a flexible steel measuring tape that measures the perimeter of the curve to be drawn. The curve is held by friction between many layers of interlocking channels.



FIGURE 2-37 *Using an adjustable curve* (Courtesy Hoyle Products Inc.).

Protractor

A protractor is used to measure and lay out angles, *Figure 2-38*. It can be used in place of a drafting machine or an adjustable triangle.

To use the protractor, place the center point (located at the lower edge of the protractor) on the corner point of the angle. Align the base of the protractor along one side of the angle. The degrees are read along the semicircular edge.

Pencils and Leads

Lead for a mechanical drafting pencil comes in 18 degrees of hardness, ranging from 9H, which is very hard, to 7B, which is very soft, *Figure 2-39*. For drafting purposes, the scale of hardness is as follows: 3H



FIGURE 2-38 *Protractor* (Courtesy Alvin & Co.).

FIGURE 2-39 *Lead-lines chart (left) and grades of lead (right).*

FIGURE 2-40 *Drafting lead.*

or 4H lead is recommended for layout work, and 2H, H, or HB leads are recommended for all other lines. Experiment with various leads to determine which ones give the best line thickness. This varies depending upon the pressure applied to the point while drawing lines. *Figure 2-40* shows lead for a mechanical drafting pencil.

Regular pencils are sharpened with a pencil sharpener. It is important that enough wood is removed to ensure that the lead, not the wood, of the pencil comes in contact with the straightedge or triangle edges.

Lead Holders and Leads

Lead holders hold sticks of lead, *Figure 2-41*. The leads designed for lead holders come in the same range of hardness as those for regular mechanical pencils and are used for the same purposes. The main advantage is that they are more convenient to use. Leads are usually sharpened in a lead pointer. Electric lead pointers are fully automatic. A slight downward pressure of the lead starts the motor action, *Figure 2-42*. This machine produces a perfectly tapered point and eliminates all loose clinging graphite.

FIGURE 2-41 *Lead holders* (Courtesy Staedtler Inc.).



FIGURE 2-42 *Lead pointer.*

Sandpaper Paddle

A sandpaper paddle consists of several layers of sandpaper attached to a small wooden holder, *Figure 2-43.* The sandpaper is used to sharpen compass leads only. Do not sharpen leads over a drawing because the graphite will smear the drawing surface.

Erasers

Various kinds of erasers are available to a drafter. One of the most commonly used is a soft, white block-type eraser, *Figure 2-44. Figure 2-45* shows a pencil-type eraser with an adjustable clutch. If one develops good drawing habits, erasing can be kept to a minimum.

Electric Eraser

An electric eraser speeds up corrections. Some models take a 7″ (17.5 cm)-long eraser strip. The model illustrated in *Figure 2-46* has a slip clutch to hold the eraser strip in place.



FIGURE 2-43 *Sandpaper paddle* (Courtesy Keuffel & Esser Co.).

FIGURE 2-44 *Block-type eraser* (Courtesy Staedtler Mars).



FIGURE 2-45 *Pencil-type eraser with clutch* (Courtesy Staedtler Mars).

FIGURE 2-46 *Electric eraser with slip clutch* (Courtesy Rotex Co.).

A cordless erasing machine can be used with or without the standard electric cord, and it uses rechargeable NiCad batteries, *Figure 2-47.* As the eraser is placed in the stand, the batteries are recharged.

Electric erasers do save time, but care must be taken not to burn through the drawing paper. This can be avoided by using an erasing shield and placing a thick sheet of paper beneath the drawing to cushion it.

Erasing Shield

An erasing shield restricts the erasing area so that correctly drawn lines will not be disturbed during the erasing procedure. It is made from a thin, flat piece of

FIGURE 2-47 *Rechargeable electric eraser* (Courtesy Rotex Co.).



FIGURE 2-48 *Erasing shield* (Courtesy Alvin & Co.).

metal with variously sized cutouts, ***Figure 2-48.*** The shield is used by placing it over the line to be erased and erasing through the cutout.

Drafting Brush

The drafting brush is used to remove loose graphite and eraser crumbs from the drawing surface, ***Figure 2-49.*** Do not brush off a drawing surface by hand because this tends to smudge the drawing. Drafting brushes come in various sizes from 10½″ to 14″ (26 cm to 35 cm). The bristles can be either horsehair or nylon, and they can be cleaned with warm, soapy water.

Dry Cleaning Powder

Dry cleaning powder is used to keep drawings clean, avoid smearing, and speed up the drafting process. Cleaning powder comes in cans or pads (***Figure 2-50***)

FIGURE 2-49 *Drafting brush* (Courtesy Alvin & Co.).

FIGURE 2-50 *Dry cleaning powder* (Courtesy Hearlihy & Co.).



FIGURE 2-51 *A variety of drafting scales* (Courtesy Koh-I-Noor Rapidograph).

and is sprinkled over the drawing before starting. It is also used throughout the drawing process. It should be removed periodically as it soaks up dust and grime and replaced with new powder. It is imperative that all cleaning powder be removed from a drawing before placing it into a whiteprinter because the powder will stick to the roller. If good drawing habits are followed, dry cleaning powder becomes less necessary.

Scales

Various kinds of scales are used by drafters, ***Figure 2-51.*** Several different scales are included on each instrument. Scales save the drafter the work of computing new measurements every time a drawing is made larger or smaller than the original.

Scales come open divided and full divided. A *full-divided scale* is one in which the units of measurement are subdivided throughout the length of the scale. An *open-divided scale* has its first unit of measurement

subdivided, but the remaining units are open or free from subdivision.

Mechanical Engineer's Scale (Fraction)

Mechanical engineer's scales are divided into inches and parts to the inch. To lay out a full-size measurement, use the scale marked 16. This scale has each inch divided into 16 equal parts or divisions of 1/16″. It is used by placing the 0 on the point where measurement begins and stepping off the desired length, *Figure 2-52.*

To reduce a drawing by 50 percent, use the scale marked 1/2. The large 0 at the end of the first subdivided measurement lines up with the other unit measurements that are part of the same scale. The large numbers crossed out in *Figure 2-53* go with the 1/4 scale starting at the other end. These numbers are ignored while using the 1/2 scale. To lay out 1¾″ at the 1/2 scale, read full inches to the right of 0 and fractions to the left of 0.

The 1/4 scale is used in the same manner as the 1/2 scale. However, measurements of full inches are made to the left of 0 and fractions to the right, because the 1/4 scale is located at the opposite end of the 1/2 scale, *Figure 2-54.*



FIGURE 2-52 *Regular full-size scale.*



FIGURE 2-53 *Half-size scale.*



FIGURE 2-54 *Quarter-size scale.*



FIGURE 2-55 *Architectural scale (full size).*



FIGURE 2-56 *Architectural scale (half size).*

Architect's Scale

The purpose of the architect's scale is primarily for drawing large buildings and structures, although the full-size scale is used frequently for drawing smaller objects. Because of this, the architect's scale is generally used for all types of measurements. It is designed to measure in feet, inches, and fractions of an inch. Measure full feet to the right of 0, inches and fractions of an inch to the left of 0. The numbers crossed out in *Figure 2-55* correspond to the 1/2 scale. They can be used, however, as 6″ because each falls halfway between full-foot divisions. Measurements from 0 are made in the opposite direction of the full scale because the 1/2 scale is located at the opposite end of the scale, *Figure 2-56.*

With the ten overlapping scales, a drawing may be made in various sizes from full size to 1/28 size. Since the architect's scale is showing divisions reciprocating feet and inches, a scale marked 1″ = 1′0″ makes a drawing with this scale 1/12 size.

EXAMPLES

3/4″ = 1′0″	would be 1/16 size	(3/4 × 1/12)
1/4″ = 1′0″	would be 1/48 size	(1/4 × 1/12)
1/2″ = 1′0″	would be 1/24 size	(1/2 × 1/12)
1″ = 1′0″	would be 1/12 size	(1 × 1/12)

Full size is measured on the full-size side of the architect's scale, where each division is 1/16.

Half size is measured by using the full-size side and dividing each measurement by 2.

Quarter size is measured by using the 3″ = 1′0″ scale. 3″ = 1′0″ would be 1/4 size (3 × 1/12 = 3/12 = 1/4).

Scale does not = size

Incorrect	1/4 scale ≠ 1.4 size
Correct	1/4 scale = 1/48 size

Mechanical Engineer's Scale (Decimal)

The mechanical engineer's scale is divided into inches and parts of an inch in decimal units. Each inch is divided into ten units or one tenth of an inch (.1). Each tenth is divided into five units where each is .02 hundredths of an inch. When using this scale, it is important to note that for accuracy of machined parts, measurements in thousandths of an inch are often required. When reading this scale, although .02 is often thought of as two hundredths of an inch, it is also 20 thousandths of an inch, written as .020. Another example would be one tenth. One tenth can be written as .1 in decimal form or 1/10 in fractional form. One tenth is one tenth of an inch written as .1. However, one tenth is also 10 hundredths of an inch or 100 thousandths of an inch. Mechanical engineers, machinists, and quality assurance inspectors generally speak in terms of thousandths of an inch when designing, manufacturing, and inspecting parts. Therefore, drafting technicians who use this scale should practice thinking in thousandths of an inch, ***Figure 2-57.***

To read the mechanical engineer's scale (decimal), place the 0 at the point where the measurement begins and step off the desired length, ***Figure 2-58.*** The measurement in this example reads 1.660″. When viewing the scale, the correct measurement can be determined by breaking the measurement up into its individual components. The individual components of 1.660 are 1.000″, .6″, and .06″. The reading, therefore, is 1.660″, ***Figure 2-58.*** Additional examples are provided in ***Figures 2-59*** and ***2-60,*** where the scale readings are 2.320 and 3.040, respectively.



FIGURE 2-57 *Mechanical engineer's scale.*



FIGURE 2-58 *Reading the mechanical engineer's scale.*



FIGURE 2-59 *Mechanical engineer's scale.*



FIGURE 2-60 *Mechanical engineer's scale.*

Civil Engineer's Scale

A civil engineer's scale is also called a *decimal-inch scale*. The number 10, located in the corner of the scale in *Figure 2-61,* indicates that each graduation is equal to 1/10 of an inch or .1″. Measurements are read directly from the scale. The number 20, located in the corner of the scale shown in *Figure 2-62,* indicates that it is 1/20 of an inch.

Using the same scale for civil drafting, one inch equals two hundred feet, *Figure 2-63,* and one inch equals one hundred feet, *Figure 2-64.*

Metric Scales

The metric system uses the meter (m) as its basic unit of linear measurement. A meter is 3.281 feet long or about 3⅜″ longer than a yardstick. Its multiples or parts are expressed by adding prefixes. These prefixes represent equal steps of 1,000 parts. The prefix for a thousand (1,000) is kilo; the prefix for a thousandth (1/1,000) is milli. One thousand meters (1,000 m), therefore, equals one kilometer. One thousandth (1/1,000 m) equals one millimeter (1.0 mm). Consider the following comparisons of metric measurements to American standard measurements:

- One millimeter (1.0 mm) = 0.001 meter = .03937 inch
- One thousand millimeters (1,000 mm) = 1.0 meter (1.0 m) = 3.281 feet
- One thousand meters (1,000 m) = 1.0 kilometer (1.0 km) = 3281.0 feet

A metric scale is used if the millimeter is the unit of linear measurement. Common ratios of metric scales include: 1:100, 1:50, 1:20, 1:40, 1:80, and 1:33⅓, *Figure 2-65.*



FIGURE 2-61 *Civil engineer's scale.*



FIGURE 2-62 *Civil engineer's scale (half size).*



FIGURE 2-63 *Civil engineer's scale (half size).*



FIGURE 2-64 *Civil engineer's scale.*

Pocket Steel Ruler

The drafter should make use of a pocket steel ruler. The pocket steel ruler is the easiest of all measuring tools to use. The inch scale, *Figure 2-66,* is 6″ long, and is graduated in 10ths and 100ths of an inch on one side and 32nds and 64ths on the other side.

The metric scale is 150 millimeters long (approximately 6″) and is graduated in millimeters and half millimeters on one side, *Figure 2-67.* Sometimes metric pocket steel rulers are graduated in 64ths of an inch on the other side.

How to Read a Micrometer Graduated in Thousandths of an Inch (.001″)

A micrometer consists of a highly accurate ground screw or spindle that is rotated in a fixed nut, thus opening or closing the distance between two measuring faces on the ends of the anvil and spindle, *Figure 2-68.* A piece of work is measured by placing it between the anvil and spindle faces and rotating the spindle by means of the thimble until the anvil and spindle both contact the work. The desired work dimension is then found from the micrometer reading indicated by the graduations on the sleeve and thimble, as described in the following paragraphs.

Since the pitch of the screw thread on the spindle is 1/40″ or 40 threads per inch in micrometers that are graduated to measure in inches, one complete revolution of the thimble advances the spindle face toward or away from the anvil face precisely 1/40 or .025″.



FIGURE 2-65 *Metric scale.*



FIGURE 2-66 *Steel scale (inch)* (Courtesy L. S. Starrett Co.).



FIGURE 2-67 *Steel scale (metric)* (Courtesy L. S. Starrett Co.).

The reading line on the sleeve is divided into 40 equal parts by vertical lines that correspond to the number of threads on the spindle. Therefore, each vertical line designates 1/40 or .025″ and every fourth line, which is longer than the others, designates hundreds of thousandths. For example: the line marked "1" represents .100″, the line marked "2" represents .200″, and the line marked "3" represents .300″, and so forth.



FIGURE 2-68 *Micrometer* (Courtesy L. S. Starrett Co.).

The beveled edge of the thimble is divided into 25 equal parts, with each line representing .001″ and every line numbered consecutively. Rotating the thimble from one of these lines to the next moves the spindle longitudinally 1/25 of .025″ or .001″; rotating two divisions represents .002″, and so forth. Twenty-five divisions indicate a complete revolution: .025 or 1/40 of an inch.

To read the micrometer in thousandths, multiply the number of vertical divisions visible on the sleeve by .025″, and to this add the number of thousandths indicated by the line on the thimble that coincides with the reading line on the sleeve.

EXAMPLE (See *Figure 2-69*):

The 1″ line on the sleeve is visible, representing .100″

Three additional lines are visible, each representing .025″. Thus, 3 × .025″ = .075″

The third line on the thimble coincides with the reading line on the sleeve, each line representing .001″. Thus, 3 × .001″ = .003″

The micrometer reading is 100″ + .075″ + .003″ = .178″

An easy way to remember how to read a micrometer is to think of the various units as if you were making change from a ten-dollar bill. Count the figures on the sleeve as dollars, the vertical lines on the sleeve as quarters, and the divisions on the thimble as cents. Add up your change and put a decimal point instead of a dollar sign in front of the figures.

Micrometers come in both English and metric graduations. They are manufactured with an English size range of 1 inch through 60 inches and a metric size range of 25 millimeters to 1,500 millimeters. The micrometer is a very sensitive device and must be treated with extreme care.



FIGURE 2-69 *Reading a micrometer* (Courtesy L. S. Starrett Co.).

Vernier Caliper

Vernier calipers can measure both the outside and the inside of an object, *Figures 2-70* and *2-71*. Use the bottom scale when measuring an outside size. Use the top scale when measuring an inside size.



FIGURE 2-70 *Caliper—outside measurement.*



FIGURE 2-71 *Caliper—inside measurement.*

Microfinish Comparator

The microfinish comparator is a handy tool for the drafter to approximate surface irregularities. Various kinds of microfinish comparators are available. *Figure* 2-72 illustrates a comparator for cast surfaces.

Ellipses Instrument

Two unique instruments are used to draw large ellipses. With these tools, the height and width of the ellipse are measured, locked in, and quickly drawn. A template is used to draw small ellipses.

Ink Tools

Some fields of drafting, such as civil (map) drafting, require that all drawings be done in ink. Some companies ink their drawings so that they can be reduced and filed on film. All artwork that is to be reproduced by camera, such as in the field of technical illustration,



FIGURE 2-72 *Microfinish comparator* (Courtesy GAR Electroforming Div., Mite Corp.).



FIGURE 2-73 *Technical inking pen* (Courtesy Koh-I-Noor Rapidograph).

is done in ink. Ink drawing is no more difficult than pencil drawing, *Figure* 2-73.

Technical Pens

The key to successful inking is a good technical pen, *Figure* 2-74. Technical pens are produced in two styles. Notice the ends of the two pens in the Figure 2-74; one has a tapered end, the other a straight end. The tapered pen is used primarily for artwork; the straight-end style is used for drafting and mechanical lettering. Pens are available in various sizes and styles of penholder sets, *Figures* 2-75 and 2-76.

Technical pen points are manufactured of stainless steel, tungsten, or jewels. The stainless steel point is chromium plated for use on tracing paper or vellum. Tungsten points are long-wearing for use on abrasive, coated plotting film or triacetate. Jewel points are used on a plotter that has a controlled pen force.

Pen points are available in thirteen standard sizes of varying widths, *Figure* 2-77. For general drafting inking, numbers .45/1 and .70/2½ are recommended.

Cleaning Technical Pens

Pens should be cleaned when they get sluggish or before storing them for long periods of time. The parts

FIGURE 2-74 *Drafting and art technical pens* (Courtesy Koh-I-Noor Rapidograph).



FIGURE 2-75 *Revolving pen holder* (Courtesy Koh-I-Noor Rapidograph).



FIGURE 2-76 *Flat pack pen holder* (Courtesy Koh-I-Noor Rapidograph).



FIGURE 2-77 *Pen sizes* (Courtesy Staedtler Mars).



FIGURE 2-78 *Internal parts of a technical inking pen.*

of most technical inking pens are similar to those shown in *Figure 2-78.* When not in use, technical pens should be kept in a storage clamp or else capped to prevent ink from drying in the point. If a pen does get clogged, remove the point and hold it under warm tap water. This normally softens the ink. If the ink has dried, use an ultrasonic cleaner or a mild solvent. If the pens will not be used for a week or more, all ink should be removed and the pens stored empty and clean. Care must be taken when removing and replacing the cleaning needle. An ultrasonic cleaner is used quickly and efficiently to clean technical pens.

Cleaning

Pens can be ruined by improper cleaning. Study steps 1 through 5 and follow them closely when cleaning pens. (Refer again to *Figure 2-78.*)

STEP 1 Remove the cap and the ink container.

STEP 2 Soak the body of the pen in hot water. The ink container should also be soaked if ink has dried in it.

STEP 3 After soaking, remove the pen body from the water. Hold the knurled part of the body with the top downward. Unscrew and remove the point section. Remove the end of the cleaning needle weight. Do not bend the cleaning needle or it will break.

STEP 4 Immerse all body parts in a good pen-cleaning fluid or hot water mixed half with ammonia.

STEP 5 Dry and clean.

Filling

To fill the pen, follow Steps 1 through 5:

STEP 1 Unscrew and remove the knurled lock ring.

STEP 2 Remove the ink container. Leave the spacer ring in place.

STEP 3 Fill the ink container with lettering ink. Do not fill it more than 3/4″ from the top.

STEP 4 Hold the filled container upright and insert the pen body into the container.

STEP 5 Replace the knurled lock ring.

Ink

A high-quality, fast-drying ink must be used in technical pens for the best results. The ink must be black and erasable, and it must not crack, chip, or peel, *Figure 2-79.* Keep inks out of extremely warm or cold temperatures. The bottles or jars should be kept



FIGURE 2-79 *Drawing ink* (Courtesy Alvin & Co.).

airtight, and the excess ink should be cleaned from the neck of the container to keep it from drying in the cap. Inks in large containers should be transferred to smaller bottles or directly into pens, **away from working areas to avoid the possibility of spillage.**

Mechanical Lettering Sets

Lettering sets come in a variety of sizes and templates, *Figure 2-80.* All sets contain a scriber, various pen sizes, and templates.

Scriber Templates

Scriber templates consist of laminated strips with engraved grooves that are used to form letters. A tracer pin moving in the grooves guides the scriber pen (or pencil) in forming the letters, *Figure 2-81.*

Guides for different sizes and kinds of letters are available for any of the lettering devices. Different point sizes are made for special pens so that fine lines can be used for small letters and wide lines for large letters. Scribers may be adjusted to form vertical or slanted letters of several sizes from a single guide by simply unlocking the screw underneath the scriber and extending the arms, *Figure 2-82.*

One of the principal advantages of lettering guides is that they maintain uniform lettering. This is especially useful where many drafters are involved.



FIGURE 2-80 *Lettering set* (Courtesy Keuffel & Esser Co.).

FIGURE 2-81 *Forming letters with a scriber* (Courtesy Kohl-I-Noor Rapidograph).

Another important use is for the lettering of titles and note headings and numbers on drawings and reports.

Letters used to identify templates are:

U = UPPERCASE

L = LOWERCASE

N = NUMBERS

Thus, a template identified as 8-ULN means it is 8/16″ high (1/2″) and has uppercase letters, lowercase letters, and numbers.



FIGURE 2-82 *Scribers are adjustable.*

Industry Application

John McRae, director of the Design and Drafting Department at MicroTron Engineering, has a problem. He can remember a time when MicroTron had trouble finding drafting technicians with CADD skills. But over time, the computer has become a standard design tool. Now all new applicants have excellent CADD skills. Unfortunately, they have no knowledge of how to make technical drawings with instruments.

MicroTron, like many companies, still has occasion to use traditional drafting instruments—particularly when revising the drawings for older jobs that are still active. Sometimes it is more economical to revise drawings manually than to convert them to an electronic format. McRae's problem is that only a couple of the drafting technicians in his department know how to use traditional instruments, and many of them can't operate technical pens or mechanical lettering sets. McRae intends to call the local technical school and community college and ask why students are no longer learning to use instruments. In his words, " . . . even the best word processing technician still has to use a typewriter occasionally."

Tracing Pin

Better, more expensive scribers use a double tracing pin, *Figure 2-83*. The blunt end is used for single-stroke lettering templates or very large templates that have wide grooves. The sharp end is used for very small lettering templates, double-stroke letters, or script-type lettering using a fine groove. Most tracing pins have a sharp point, but some do not. Always screw the cap back on the unused end after turning the tracing pin to the desired tip. Be careful with the points because they will break if dropped and can cause a painful injury if mishandled.



FIGURE 2-83 *Double tracing pen.*

Standard Template

Learning to form mechanical letters requires a great deal of practice. *Figure 2-84* shows a template having three sets of uppercase and lowercase letters. Practice forming each size letter and number until they can be made rapidly and neatly. Use a very light, delicate touch so as not to damage the template, scriber, or pen.

Size of Letters

The size or height of the lettering on a template is called out by the number used to identify each set. Sizes are in thousandths of an inch. A #100 is .100" high, or slightly less than an eighth of an inch; a #240 is .240" high, or slightly less than a quarter of an inch.

Another system to determine template size uses simple numbers. These numbers are placed above the number 16 to indicate the fraction height of the letter. For instance, the number 3 placed above the number 16 would read as 3/16" in height.



FIGURE 2-84 *Lettering template.*



FIGURE 2-85 *Ink pens used for lettering.*

Pens

There are two types of pens: the regular pen and the reservoir pen, *Figure 2-85*. The regular pen must be cleaned after each use. The reservoir pen should be cleaned when it gets sluggish or before being stored for long periods of time. This procedure is the same as it is for the cleaning of technical pens as described previously.

Butterfly Scriber

Basic Parts

The butterfly-type scriber shown in *Figure 2-86* is a delicate, precision tool that does its job without requiring any adjustments, repairs, or maintenance. The clear plastic base of the scriber bears the setting chart used in adjusting the pen arm for enlargements, reductions, verticals, and slants to be produced by tracing the engraved letters of a letter guide template.

The pen arm of the scriber holds the pen accessories for the various jobs to be performed. The pen and the arm have a thumb-tightening screw device for securing the pen being used and an adjustable pressure post screw with locking nut for controlling the amount of pressure at which the pen is set. The pressure post rides on the surface of the work when in use, and it is used only in conjunction with the swivel knife. The bull's-eye setting marker at the opposite end of the pen arm offers a concise, accurate means of setting the scriber for the various percentages and angles desired.

The tracing pin is the hardened tool steel point used in tracing the template letter. The tail pin serves as the pivot point for the triangular action of the scriber. This pin travels in the center groove of the template.



FIGURE 2-86 *Butterfly scriber* (Courtesy Letterguide Inc.).

Operation of the Butterfly Scriber

The butterfly scriber, a precision lettering tool, is the key to producing clean, sharp, controlled lettering. The setting chart, using the bull's-eye at the end of the pen arm for a marker, begins at the outer edge with a starting line marked "vertical." In this position, the scriber produces a vertical letter of normal size with the template being used. To enlarge this letter, set the bull's-eye at a position above the 100 percent intersection. At 120 percent, the scriber produces a letter 20 percent greater in height than it does at 100 percent. A reduction can be produced by setting the bull's-eye at a position below the 100 percent intersection. Variations in height range from 100 up to 140 percent and down to 60 percent. The extreme settings produce condensed letters, and the intermediate settings produce headings, subheadings, or large or small letters.

Slants in all sizes are easily produced by setting the bull's-eye on a line other than the vertical line. Normal slants or italics are produced in all height adjustments by setting the bull's-eye on either the 15° or 22½° line, and at the desired percent of height of the letter on the template.

Variations may be produced in slants ranging from 0° to 50° forward. Tracing the engraved template letter requires a very light and delicate touch. This results in more accurately traced letters and less wear on the equipment. Each lettering application requires its own specific pen and will place at the fingertips of the drafter the very best in standard typeface and hand-lettered alphabets for fast, easy rendering.

Special Effects

By using one's imagination many special effects can be achieved, *Figures 2-74, 2-88,* and *2-89*.



FIGURE 2-87 *Adjustable scriber creates special effects* (Courtesy Letterguide Inc.).



FIGURE 2-88 *Sample lettering styles* (Courtesy Letterguide Inc.).



FIGURE 2-89 *Additional special effects* (Courtesy Letterguide Inc.).

Airbrush

Airbrush guns are used for such purposes as production designing, pictorial rendering, portrait figure rendering, architectural rendering, and technical illustration. There are two kinds of airbrushes: the single-action type and the double-action type. In the single-action airbrush, the trigger controls the flow of air only. The fluid control is adjusted in front by the nozzle. In the double-action airbrush, the trigger controls both the flow of air and the amount of fluid to be sprayed, *Figure 2-90*.



FIGURE 2-90 *Airbrush* (Courtesy Badger Airbrush Co.).

INCHES			MILLIMETERS	
SIZE	DIMENSIONS		SIZE	DIMENSIONS
A	8 1/2 x 11	9 x 12	A-4	210 x 297
B	11 x 17	12 x 18	A-3	297 x 420
C	17 x 22	18 x 24	A-2	420 x 594
D	22 x 34	24 x 36	A-1	594 x 841
E	34 x 44	36 x 48	A-0	841 x 1189

FIGURE 2-91 *Paper sizes.*

Paper Sizes

The two standard paper sizes are classified as "architectural" and "engineering" sizes. Engineering, also defined as American National Standards Institute or ANSI sizes begin with A-size ($8\frac{1}{2}'' \times 11''$). Architectural sizes begin with A-size that is $9'' \times 12''$. The basic standard metric size for paper is A-4 (210×297 millimeters), ***Figure 2-91***. Examples of paper folded to A-size are shown in ***Figure 2-92***.

Borders

The location of the borders varies with each size sheet of paper, ***Figure 2-93A*** (page 65). This chart indicates the various standard borders used today. A standard horizontal border is shown in ***Figure 2-93B*** (page 65). A standard vertical border is shown in ***Figure 2-93C*** (page 66).

Zoning

Zoning is used to pinpoint a particular detail on a drawing. The exact rectangular zone is located by the use of numbers running horizontally and letters running vertically in the margins. By extending these imaginary lines, the exact rectangular zone, Zone 7-C, is located as shown in ***Figure 2-93A***. Note the corresponding



FIGURE 2-92 *Paper folded to A-size.*

(A)



STANDARD BORDER SIZES

DRAWING SIZE	A	B	C	D	E	F
A HORIZONTAL	8.5	11.0	.25	.38	2 AT 4.25	2 AT 5.50
A VERTICAL	11.0	8.5	.38	.25	2 AT 5.50	2 AT 4.25
B	11.0	17.0	.62	.38	4 AT 2.75	4 AT 4.25
C	17.0	22.0	.50	.75	4 AT 4.25	4 AT 5.50
D	22.0	34.0	1.00	.50	4 AT 5.50	8 AT 4.25



ZONE IDENTIFICATION
SEE ZONE ABOVE

(B)



FIGURE 2-93 *(A) Standard border sizes and (B) standard horizontal border* (Courtesy Bishop Graphics Co.).



(C)

FIGURE 2-93 *(Continued) (C) Standard vertical border* (Courtesy Bishop Graphics Co.).

symbol below the chart. The number at the left (1) indicates the page number and the number at the top right (7) indicates the corresponding number on the horizontal margin. The letter at the lower right (C) indicates the corresponding letter in the vertical margin.

Whiteprinter

Many types of whiteprinters are available for use in drafting rooms. A *whiteprinter,* reproduces a drawing through a chemical process. Most of these machines work on the same basic principle, ***Figure 2-94***. A bright light passes through the translucent original drawing and onto a coated whiteprint paper. The light breaks down the coating on the whiteprint paper, but wherever lines have been drawn on the original drawing, no light strikes the coated sheet. Then the whiteprint paper is passed through ammonia vapor for developing. This chemical developing causes the unexposed areas—those that were shaded by lines on the original—to turn blue or black.

Most whiteprinters have controls to regulate the speed and flow of the developing chemical. Each type of machine requires different settings and has different controls. Before operating any whiteprinter, read all of the manufacturer's instructions.

Today, whiteprinters are rarely seen in drafting rooms. The technology of choice is now a wide format digital plain paper printer or inkjet plotter. Most digital printers can be equipped with scanners to facilitate both copying of hard copy drawings as well as scanning of drawings for archiving or electronic distribution, ***Figure 2-95***.

Files

A finished drawing represents a great deal of valuable drafting time and is, therefore, a costly investment. Drawings must be stored flat in a clean storage area, ***Figure 2-96***. Vertical drawing storage is provided by hangers, ***Figure 2-97***. Most engineering firms keep their files in fireproof and theft-proof vaults.



FIGURE 2-94 *Whiteprinter process.*

FIGURE 2-95 *Multifunction (print/copy/scan) digital plain paper system* (Courtesy Océ North America).

FIGURE 2-96 *Drawing file system* (Courtesy Safco Products).



FIGURE 2-97 *Vertical drawing file* (Courtesy Safco Products).

Care of Drafting Equipment

Drafting tools are precision instruments, and the proper care will ensure that they last a lifetime.

Plastic Tools

Plastic drafting tools, such as T-squares, parallel straightedges, templates, and triangles, should be wiped immediately after use with a damp cloth to remove ink or graphite that may stain the tools or be carried to the next drawing. Once a plastic instrument is stained, a mild soap or ammonia solution

will dissolve many water- and oil-based inks. Be careful *not* to use a solvent such as paint thinner, lacquer thinner, or alcohol.

Plastic drafting tools should be kept out of direct sunlight and away from warm surfaces to prevent them from becoming brittle, cracked, and warped. They should be stored in a flat position with cloth or paper between them to avoid scratching the surface.

A great number of plastics are used in drafting instruments. Most are made from either styrene or acrylic plastic. Styrene is a more flexible and softer plastic than acrylic. Although acrylic instruments are harder, they are more prone to chipping. Because both types of plastic are relatively soft, plastic drafting instruments should never be used for a cutting edge.

Compasses

Almost all compasses are made of brass that is chrome or nickel-plated. To clean these instruments, use a mild solution of soap and water to remove residue and dirt. Compasses should not normally need oiling, unless they are kept in a damp area that could cause rust. If a compass is oiled unnecessarily, there is a risk of soiling the next drawing on which it is used.

Tables and Chairs

Wooden drafting furniture is cared for in the same manner as any other wooden furniture. It may be polished or waxed with ordinary products. Do not polish the insides of drawers or cabinets. These areas may retain the wax, which can then be transferred to drawings.

Steel furniture can be cleaned with soap and water and then waxed.

The gears and joints on adjustable drafting tables are lubricated at the factory and generally do not require further oiling. Additional oiling increases the risk of getting oil or grease on a drawing.

The tops of most drafting tables are coated with a vinyl film such as melamine or a phenol-laminate material. A glass cleaner or mild ammonia solution is used to clean these surfaces.

Use of Appliqués

The word *appliqué* is a generic term used to describe a variety of shortcut products used in drafting. These products include items such as tapes, pads, and various other ready-made appliqués for creating printed circuit board artwork, ***Figure 2-98***. These same materials may also be used for a variety of tasks in other drafting fields, ***Figure 2-99***. For example, architects use tapes for making lines and walls on floor plans.



FIGURE 2-98 *Tapes and pads for printed circuit board drafting.*

Transfer cards are used primarily as substitutes for mechanical lettering, but any type of symbol or frequently used piece of graphic data can be placed on a transfer card. Transfer cards are especially designed to fit against a parallel bar, drafting rule, or other straightedge for ease of alignment. Symbols are transferred from the card by rubbing them with a blunt point.

Dry transfer sheets are designed according to the same principles as transfer cards. The major differences are that transfer sheets are just that, sheets—not cards. Dry transfer sheets are used a great deal in architectural drafting and technical illustration. The transfer is made by rubbing the symbols on the sheet with a blunt, rounded point or a special burnisher.

Dry transfer materials do have some drawbacks. The heat of ammonia-developing print machines tends to lift dry transfer material from the sheet. In addition, the material may dry out and crack with age.

Use of Burnishing Plates

Burnishing is another shortcut for creating graphic symbology fast and easily. *Burnishing* involves placing a specially textured plate under the drafting medium (usually paper or vellum) and rubbing the drafting surface with a pencil. The pencil may be soft and dark or light and hard, depending on the amount of emphasis desired. Two of the most commonly used symbols on burnishing plates are bricks and stone, but any symbol could be made into a plate.



FIGURE 2-99 *Sample appliqué* (Courtesy A.D.S./Linex Inc.).

One weakness of burnishing plates is that the symbols they produce do not reproduce well.

Typewritten Text

Text on drawings and other types of documentation consists of dimensions, notes, and callouts. Creating text, or lettering, is one of the slowest, least productive manually performed tasks in drafting. Typewritten text is a shortcut for improving on lettering in manual drafting situations.

A number of different methods for typing text are used in drafting. The most frequently used are the open-carriage typewriter and the lettering machine. The *open-carriage typewriter* is any brand of typewriter that has been specially designed to hold larger-than-normal media, such as drawings, bills of material, and parts lists. Once a drawing is completed and ready for annotation, the drafter or engineering secretary rolls it into an open-carriage typewriter and types the required text. Typewritten text is fast, neat, and consistent, *Figures 2-100* and *2-101*.



FIGURE 2-100 *Typewritten text on drawings.*



FIGURE 2-101 *Typewritten text on drawings.*

FIGURE 2-102 *Kroy lettering samples.*

Lettering machines provide another means for accomplishing typewritten text. Lettering machines are used primarily for titles on drawings, but they may be used in any situation where Leroy lettering is used.

Lettering machines, such as the Kroy machine, output the letters on a clear tape that is pressed onto the drawing surface, *Figure 2-102.* Lettering machines are capable of producing text in a number of different sizes and styles. There are some drawbacks to this shortcut. The machine and its type fonts are expensive.

Summary

- The most frequently used conventional drafting instruments include the following: drawing board, triangles, scales, compasses, irregular curves, dividers, drafting brush, mechanical pencils, protractors, adjustable triangle, erasing shield, eraser, lead pointer, flat tile or lead sandpaper, circle template, ellipse template, drafting tape or dots, calculator, and dry cleaning pad.
- A typical drawing set will include dividers, various compasses, and ink attachments.
- The most frequently used scales are the mechanical engineer's, architect's, civil engineer's, and metric scales.
- Precision measuring instruments that technical drawing students should be able to use include the following: micrometer, vernier caliper, microfinish comparator, and the ellipses instrument.
- Technical pens are produced in two styles. The tapered pen is used primarily for artwork. The straight-end style is used for technical drawing.
- The butterfly scriber consists of the following parts: bull's-eye handle, trail pin, height adjustment screw, pen tightening screw, pen arm, tracer pin, tail pin slot, calibrations for italics, and calibrations for height variations.
- The airbrush is used for such purposes as production designing, pictorial rendering, portrait figure rendering, architectural rendering, and technical illustration.
- Standard paper sizes in inches are as follows: A = 8½ × 11, B = 11 × 17, C = 17 × 22, D = 22 × 34, and E = 34 × 44. Standard sizes in millimeters are as follows: A-4 = 210 × 297, A-3 = 297 × 420, A-2 = 420 × 594, A-1 = 594 × 841, and A-0 = 841 × 1,189.
- In the whiteprinting process an original drawing is placed on top of coated whiteprint paper (coated side up). The two are exposed to intense light that burns off all of the coating except that covered by the pencil or ink lines of the original drawing. The original drawing is then removed, and the whiteprint paper is exposed to ammonia vapors. These vapors turn the remaining coating a deep purplish-blue color, creating a print of the original.
- Appliqués are various types of ready-made products that can be applied to an original drawing in the same way as tape is applied. They are time-saving devices.
- Burnishing plates are used to create graphic symbology quickly. A burnishing plate is a specially textured device that is placed under an original drawing. The paper surface is then rubbed to create the image in question.

Review Questions

Answer the following questions either true or false.

1. Dry cleaning powder is used after the completion of a drawing to clean up any specks or smearing. F
2. The transfer card and the dry transfer sheet are not used to perform the same drafting function.
3. For drafting purposes, a 3H or 4H lead is recommended for layout work, and 2H, H, or HB leads are recommended for all other lines. T
4. The friction-joint type compass is recommended for drafting because the setting stays secure even when strong pressure is applied.
5. A drafting brush is used to remove loose graphite and eraser crumbs from the drawing surface. T
6. In most cases, scissors drafting can save much time.
7. An easy way to remember how to read a micrometer is to compare it to making change for a $1 bill.
8. An open-divided scale is one in which the units of measurement are subdivided throughout the length of the scale.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** a type of drafting triangle?
   a. 30°–60°
   b. 45°
   c. Beam triangle
   d. Adjustable triangle
2. Which of the following drafting tools is **not** commonly used to draw horizontal lines?
   a. T-square
   b. Drafting machine square
   c. Protractor
   d. Parallel bar
3. Which of the following paper sizes are commonly used in industry today to produce engineering drawings?
   a. 8.5 × 11
   b. 9 × 12
   c. 22 × 34
   d. Both b and c
4. Which of the following is **not** an important feature/use of the drawing surface or top cover?
   a. To provide a perfect drawing surface
   b. A metal edge that ensures against warpage
   c. Must be easily cleaned
   d. To cover over the holes made by the compass
5. Which of the following is **not** true regarding the vernier protractor?
   a. Permits readings to 5 minutes of an arc
   b. Is graduated in increments from 0 to 60 minutes
   c. Takes the place of the arm-type drafting machine
   d. The zero on the protractor is in line with the zero on the vernier.
6. Which of the following pieces of hardware would typically **not** be a part of a modern CAD configuration?
   a. Graphics display
   b. Copier
   c. Keyboard
   d. Digitizer
7. The word *appliqué* in drafting describes:
   a. A variety of shortcut products
   b. The variance from a specified dimension or design requirement
   c. A special device for holding the work in a machine tool
   d. None of the above
8. Which of the following is **true** regarding the Kroy lettering machine?
   a. It outputs the letters on a clear tape.
   b. It is an expensive piece of equipment.
   c. The fonts and sizes of letters are very limited.
   d. Both a and b.
9. Which of the following is **not** true regarding the whiteprinter?
   a. Most of them work on different basic principles.
   b. It reproduces a drawing through a chemical process.
   c. The chemical used is ammonia.
   d. The chemical developing causes the exposed areas to turn black or blue.

Chapter 2 Problems

Unless otherwise specified, use the format shown in Problem 4-37 (page 161) to present your solutions to the following problems.

PROBLEM 2-1

On an A-size sheet of paper, lay out lines to scale as indicated:

Scale 16 (Figure 2-52)

5-7/16″

3-5/8″

Scale 1/2 (Figure 2-53)
- 9-1/2″
- 11-3/8″

Scale 1/4 (Figure 2-54)
- 11-3/8″
- 7-7/8″

Scale 1 (Figure 2-55)
- 3″–8-1/2″
- 4″–1-3/4″

Scale 1/2 (Figure 2-56)
- 5″–9-3/4″
- 7″–8-1/4″

Scale 10 (Figure 2-57)
- 3-3/8″
- 5-7/16″

Scale mm (Figure 2-61)
- 42.5 mm
- 37.7 mm

PROBLEM 2-2

Assume that a whiteprinter, Figure 2-93, can process paper at 25 feet per minute (fpm). Approximately how many seconds would the printer take to print a D-size drawing the long way? (Dimension B. See Figure 2-91.) Note that the paper passes through the printer two times while traveling a total of 26″.

PROBLEM 2-3

A rich uncle says to you that he will contribute to your education by giving you a check equal to a stack of one-dollar bills equal to your height. How large should the check be? A micrometer shown in Figure 2-64 would be helpful. What else could you do to determine the thickness of a one-dollar bill?

PROBLEM 2-4

At a certain time of day a drafter used a standard steel tape to measure the shadow of a 1.8 m tall person.

The shadow measured approximately 0.9 m. Next, the drafter measured the shadow of a nearby water tower and found it to be approximately 7.7 m. Determine the approximate height of the water tower by using two methods.

1. Use a proportional equation.
2. Use trigonometry.

PROBLEM 2-5

Read the micrometer shown to determine the outside dimension of a typical drafting pencil.



PROBLEM 2-6

Prepare sketches to show how you would use a 30°–60° triangle with a 45° triangle in conjunction with a T-square to construct lines at the following angles to the horizontal: 15°, 75°, 105°, and 165°.

Refer to Figure 2-30.

Problems 2-7 through 2-12

Carefully measure each line in inches, or in millimeters if metric is indicated. Neatly enter your answers on a sheet of paper. For extra practice, measure each line full size as given, half size as given, quarter size as given, or ten-times scale as assigned by the instructor.

PROBLEM 2-7

FULL SIZE

1)
2)
3)
4)
5)
6)
7)
8)
9)
10)

PROBLEM 2-8

HALF SIZE

1)
2)
3)
4)
5)
6)
7)
8)
9)
10)

PROBLEM 2-9

3/4 SCALE

1)
2)
3)
4)
5)
6)
7)
8)
9)
10)

PROBLEM 2-10

METRIC (FULL SIZE) MILLIMETERS

1)
2)
3)
4)
5)
6)
7)
8)
9)
10)

PROBLEM 2-11

METRIC (HALF SIZE) MILLIMETERS

1)
2)
3)
4)
5)
6)
7)
8)
9)
10)

PROBLEM 2-12

METRIC (QUARTER SIZE) MILLIMETERS

1)
2)
3)
4)
5)
6)
7)
8)
9)
10)

Problems 2-13 through 2-28

Construct each object by using the given dimensions. Use consistent thick, black object lines throughout. Keep all corners tight and sharp. Where indicated, draw thin, black center lines.

PROBLEM 2-13



PROBLEM 2-14



PROBLEM 2-15



PROBLEM 2-16



PROBLEM 2-117



PROBLEM 2-18



PROBLEM 2-19



PROBLEM 2-20



PROBLEM 2-21



PROBLEM 2-22



PROBLEM 2-23



PROBLEM 2-24



PROBLEM 2-25



PROBLEM 2-26



PROBLEM 2-27



PROBLEM 2-28



3

Manual Lettering, Sketching, and Line Techniques

KEY TERMS

Axonometric sketching
Boardroom sketching
Center line
Conversational sketching
Cutting plane line
Dimension line
Extension line
Hidden line
Isometric (sketching)
Line work
Oblique sketching
Orthographic sketching
Perspective sketching
Phantom line
Text
Visible line

CHAPTER OUTLINE

Talking sketching • Freehand lettering • Freehand lettering techniques • Line work • Sketching • Types of sketches • Sketching materials • Sketching techniques • Summary • Review questions • Chapter 3 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the concept of talking sketching, including the two kinds.
- List the various styles of freehand lettering and the characteristics of good lettering.
- Explain the techniques one must know in order to do freehand lettering.
- Illustrate the various types of lines used on technical drawings.
- Illustrate the four types of sketches.
- Explain what materials are needed in order to make sketches.
- Demonstrate the most commonly used sketching techniques.

Note to Instructors and Students

Although modern CAD technologies have altered radically the way that design documentation is prepared, there is still a need for engineers, designers, and CAD technicians to develop their skills in the areas of sketching, hand lettering, and line work. Sketches remain an important form of communication between engineers, designers, and the CAD technicians who will convert their ideas into finished drawings and other types of documentation. Consequently, the authors continue to offer this chapter and recommend that instructors use it to help students develop the sketching, lettering, and line work skills they will need in the workplace.

Talking Sketching

Two types of sketching, which are often neglected in technical drawing texts but nevertheless complement the skills of a successful drafter, designer, or engineer, are conversational sketching and boardroom sketching.

Conversational Sketching

Conversational sketching usually occurs between two or more individuals huddled around a drafting board or a cafeteria table. The one doing the talking combines several types of sketches in one drawing as the idea is talked through. The first part of the sketch is most likely an orthographic view, the easiest projection to draw rapidly. Then, as the talking progresses, a pictorial is used to give the observers a feeling of depth. For example, a designer communicating an idea for an AM/FM receiver would begin with the orthographic view, *Figure 3-1*, and finish with a pictorial, *Figure 3-2*. A drafter, designer, or engineer sketches rapidly while talking and doesn't have time to develop a single specific kind of sketching, such as orthographic views, an isometric, an oblique, or a two-point perspective.

Boardroom Sketching

Communication with more individuals than a drafting board can accommodate requires a more visible surface for the larger group. The drawing surface for



FIGURE 3-1 *Talking sketch (orthographic view).*



FIGURE 3-2 *Talking sketch completed with pictorial.*

boardroom sketching sometimes is a chalkboard, but more often is a pastel-colored porcelainized enamel, a glass panel, or a dry-erase surface. All of these surfaces require a special marker and can be erased with a cloth.

Good quality talking sketches, like good quality sketching discussed earlier in this chapter, require practice to develop visible lines and especially to develop lettering large enough to be read by those sitting at the back of the room.

Note that sketching and lettering on overhead projectors is another medium for talking sketching. Practice to make sure that all those present can read all the lettering and see the lines. Additional comments on the use of overhead projectors are in Chapter 24.

Freehand Lettering

Text is an important part of a technical drawing. Not all information required on technical drawings can be communicated graphically, the most obvious being dimensions. *Text* on technical drawings consists of dimensions, notes, legends, and other data that are best conveyed using alphanumeric characters, *Figure 3-3*.

Several different ways are used to create text on technical drawings. The traditional method is by freehand lettering. Other methods include such mechanical lettering techniques as scriber templates, typewritten notation, and typed lettering generated by computer-aided drafting systems. This chapter focuses on freehand lettering. Other methods are described elsewhere in this text.

Lettering Styles

There are numerous different lettering styles or fonts, *Figure 3-4*. The standard style for freehand lettering on technical drawings, as established in American National Standards document Y14.2M-1992, is



FIGURE 3-3 *Examples of text on a technical drawing.*

THIS IS CALFLISCH FONT

THIS IS MATHEMATICAL FONT

THIS IS CHICAGO FONT

THIS IS LITHOS FONT

THIS IS ROSEWOOD FONT

THIS IS CURLZ FONT

THIS IS SABON FONT

THIS IS BRUSH FONT

FIGURE 3-4 *Sample lettering fonts.*

SINGLE - STROKE GOTHIC

LETTERING SAMPLE

FIGURE 3-5 *Single-stroke Gothic lettering.*

single-stroke Gothic lettering. Vertical, single-stroke Gothic letters are the most universally used of the various styles available to drafters, ***Figure 3-5.***

Some modifications of the standard Gothic configuration of letters are often made, without actually changing from the Gothic style of lettering. One way is through the use of uppercase and lowercase letters, ***Figure 3-6,*** but this is seldom acceptable on technical drawings. Another method is to condense or extend the letters, ***Figure 3-7.***

UPPERCASE GOTHIC
lowercase Gothic

FIGURE 3-6 *Uppercase and lowercase Gothic lettering.*

EXTENDED VARIATION

CONDENSED VARIATION

FIGURE 3-7 *Extended and condensed variations of Gothic lettering.*

SAMPLE OF INCLINED LETTERING

FIGURE 3-8 *Inclined Gothic lettering.*

The most common way of modifying Gothic letters is to incline them slightly to the right, ***Figure 3-8.*** Inclined lettering is easier to make as it lends itself to a natural direction of wrist action. The correct angle of the inclined elements is a two-unit incline to the right for each five units of letter height or at 68° using a letter guide. Errors are not as detectable with inclined letters as they are with vertical elements. Because the inclined elements are longer, they are easier to read. However, inclined lettering is not universally accepted, and caution must be exercised not to conflict with customary drafting styles. A backhanded or left-leaning inclination is never an acceptable modification.

Characteristics of Good Lettering

Good freehand lettering, regardless of whether it is uppercase or lowercase, condensed or extended, or vertical or inclined, must have certain characteristics. These requisites include neatness, uniformity, stability, proper spacing, and speed.

Neat lettering is important so that the information being conveyed can be easily read. Few things detract from the appearance and quality of a technical drawing more than sloppy lettering, ***Figure 3-9.***

For uniformity, all letters should be the same in height, proportion, and inclination. A necessary tactic for maintaining uniformity is the use of guidelines, ***Figure 3-10.*** The customary heights of characters in technical drawing are 1/8″ (3 mm) for regular text, and 3/16″ (4.5 mm) for headings and titles.

The proper stability or balance of letters is an important characteristic in freehand lettering. Each

SLOPPY LETTERING IS DIFFICULT TO READ

FIGURE 3-9 *Sloppy lettering is difficult to read.*

UNIFORMITY ← GUIDELINES

FIGURE 3-10 *Guidelines improve uniformity.*

B E F R 3 8 2 TOP HEAVY

B E F R 3 8 2 CORRECT FORM

FIGURE 3-11 *Top-heavy letters are not balanced.*

SPACING WITHIN WORDS
SHOULD BE CLOSE.

SPACING BETWEEN WORDS
SHOULD BE FAR.

FIGURE 3-12 *The proper spacing of letters and words.*

THIS IS A PROPERLY SPACED SENTENCE.

THISISANIMPROPERLYSPACEDSENTENCE.

FIGURE 3-13 *Spacing between words is important.*

letter should appear balanced and firmly positioned to the human eye. Top-heavy letters are not balanced because they appear about to topple over, ***Figure 3-11.***

The proper spacing of letters and words is important, and it takes a lot of practice to accomplish. A good rule of thumb to follow in terms of spacing is to use close spacing within words, and far spacing between words, ***Figure 3-12.*** The proper positions of letters relative to one another in words is accomplished by spacing the letters in the word equally in the area, not by trying to equalize the spacing between letters. This becomes automatic if the drafter concentrates on the word being lettered, not on each letter. Another rule of thumb for spacing is to allow the width of one round letter, such as O, C, Q, or G, between words. ***Figure 3-13*** illustrates how this type of spacing can make the lettering much easier to read.

In the modern drafting room, because time is money, speed in freehand lettering is critical. Typically, freehand lettering is one of the slowest, most time-consuming tasks drafters must perform. It takes many hours of practice to develop freehand lettering that is neat, uniform, balanced, properly spaced, and fast. Some drafters never reach this goal. Those who do, reach it through constant practice coupled with continual efforts to improve.

Freehand Lettering Techniques

Freehand lettering techniques are learned by knowing what grades of lead to use, how to make the basic lettering strokes, and how to use guidelines, and by constantly practicing and trying to improve.

Lettering in ink has been greatly simplified in recent years. Old-fashioned tools, such as adjustable-nib ruling pens and speedball pens, have been replaced by the less cumbersome, easier-to-use technical pen, *Figure 3-14*. When lettering in ink, drafters still use light guidelines made with pencil lead. The actual lettering is done with the desired pen point size. Commonly used pen points for lettering in ink are sizes 0, 1, and 2, which are standard American sizes. In metrics, these point sizes represent line widths of 0.35 mm, 0.50 mm, and 0.60 mm.

All letters and numbers are created using six basic strokes, *Figure 3-15*. The first stroke is a single stroke made downward and to the right at approximately 45°. The second stroke is made downward and to the left at approximately 45°. The third stroke is vertical and is made from top to bottom. Stroke number four is horizontal and is made from left to right. The fifth stroke is a half-circular stroke to the left, made from top to bottom. The sixth stroke is a half-circular stroke to the right, made from top to bottom. All alphanumeric characters can be created using combinations of these six strokes. *Figure 3-16* shows how these strokes are used for making selected characters.



FIGURE 3-14 *Modern technical pens* (Courtesy Keuffel & Esser Co.).



FIGURE 3-15 *Basic strokes used for lettering.*

Lettering Guidelines

Guidelines are a critical part of freehand lettering. Uniformity, neatness, and stability cannot be achieved without using guidelines.

A lettering guide is used to guidelines as shown in *Figure 3-17*. One type of lettering guide, *Figure 3-17*, can be used to lay out the vertical, horizontal, and inclined guide lines as well as text spacing for good freehand lettering. The lettering guide has a fixed rectangular part and a round disk that can be rotated inside that fixed part. The rectangular part has two scales on it and the disk has two scales on it. In addition to the four scales, there are five rows of holes, *Figure 3-17*. The scale on the far left hole pattern is present to 1/8″ spacing. It can be used to create lines with 1/8″ spacing between them on any multiple of 1/8″ up to 2″ spacing.

The scale to the immediate right of the far left scale is a metric scale. This scale is on the rotating disk and ranges from 2 mm to 10 mm with three odd values of 3.08, 6.1, and 9.75 mm. These values correspond closely to the inch equivalents of 1/8″, 1/4″, and 3/8″ respectively. This scale is used in conjunction with the mark that has an "M" above it, *Figure 3-17*. When the disk is rotated and the number on the scale lines up with the mark that has the "M" above it, the spacing between the holes that are connected by the line is equal to the value selected. *Figure 3-18* shows the 6.1 lined up with the mark below the "M." The spacing between the holes connected by the line is 6.1 mm.

FIGURE 3-16 *Forming uppercase Gothic letters and numerals—vertical style.*



FIGURE 3-17 *Settings on the lettering guide.*

The hole pattern below the 3/5 notch and the 2/3 mark is used in conjunction with the scale located at the bottom of the disk. The scale graduation is in 32nds of an inch and ranges from 3/32 to 10/32 of an inch, *Figure 3-18*. When the disk is rotated and the number on the scale lines up with the mark on the bottom of the rectangular part, the spacing between the holes that are connected by the line is equal to the value shown. *Figure 3-18* shows the 6 lined up with the mark. The spacing between the holes connected by the line is 6/32 or 3/16 inch.

To use the lettering guide, the base of the guide is placed in contact with the parallel bar or other straight edge. The pencil is inserted into the hole and used to pull the guide across the paper while maintaining contact with the straight edge. A line is lightly drawn by the pencil as the guide is pulled across the paper. The pencil is then inserted into another hole, connected by the line to the first hole, and an additional line is created as the guide is pulled across the paper in the opposite direction. The spacing between the guidelines created is equal to the value selected, *Figure 3-10* and *3-18*.



FIGURE 3-18 *Metric settings on the lettering guide.*

Line Work

Line work is the generic term given to all of the various techniques used in creating the graphic data on technical drawings. Mechanical line work is made using either mechanical pencils or technical pens. Such devices as parallel bars, drafting machines, triangles, scales, and numerous other tools are used to guide the line-making. Because inking is dealt with in the first chapter, this chapter focuses on pencil line work.

Characteristics of Lines

Twelve types of lines are used in manual drafting. Each has its own individual characteristics. The *visible line* is solid, thick, and dark. It is used to represent the outline of the features that are visible in a given view of an object. The *hidden line* is a thin line formed by a series of short dashes separated by even shorter breaks. It is used to indicate features that are not visible in a given view of an object. *Dimension lines* and *extension lines* are solid, thin lines of approximately the same width as hidden lines. Dimension lines may be broken for the dimension and should have arrowheads for terminations. Extension lines start with a 1/16″ break away from the visible lines of the object and represent an extension of the visible features of the object to accommodate dimension lines. Dimension lines are normally drawn perpendicular to extension lines with the arrowhead terminating at the extension line.

The *center line* is broken with one short dash in its center that is repeated approximately every 1.25″. It is the same width as the hidden, dimension, and extension lines. It is used to show the center of circular features or to represent symmetry. The *phantom line* is a solid, thin line that resembles a center line except that it has two short dashes that are repeated approximately every two inches. It is used to represent a moveable feature in its different positions, a repeated detail, or a repeated pattern. *Viewing plane lines* and *cutting plane lines* are thick like the visible line and consist of two styles. One type resembles a hidden line and the other type resembles a phantom line. The viewing plane line is used to show where a viewing plane is being placed as well as to indicate the direction in which the resulting section is to be viewed. The *cross-hatching line* also known as the *section line* or *section lining*, is used in sectional views of drawings. It is a thin, solid line used in sectional views to indicate material that touches the cutting plane as it slices through the object.

Freehand break lines and *mechanical break lines* are both used to show when an object is broken so as to save drawing space. The freehand break line is also used to show interior features in sectional drawings and is a solid, thick line produced without the aid of a straight edge. The mechanical break line is a solid, thin line with at least one zig zag in it. It is created with the use of a straight edge. The *stitch line* is a solid, thin line used to indicate where there is sewing or stitching. All lines used on technical drawings should closely match those in ***Figure 3-19.***

Horizontal and Vertical Lines

Horizontal lines are formed by pressing the straightedge (T-square, parallel bar, drafting machine scale, and so forth) against the worksheet with one hand and moving the pencil with the other. Uniformity of



FIGURE 3-19 *Line types used on technical drawings.*



FIGURE 3-20 *Maintaining uniformity of lines.*

line widths and weights can be achieved by holding the pencil at approximately 60° from the drawing surface, maintaining an even pressure downward, and slowly revolving the pencil axially as it moves across the drawing surface, *Figure 3-20*. This keeps the lead tip symmetrical.

Vertical lines are created according to the same principles, except that the drafter's hand moves upward rather than from left to right. The angle of inclination, the amount of pressure, and the rotating motion are the same as they are for horizontal lines.

Angular Lines

Many modern devices are available to assist drafters in making angular lines. These include protractors, adjustable triangles, and adjustable arms on drafting machines. However, most angular lines can be created simply by using the standard 30°–60° and 45° triangles alone and in various combinations, *Figures 3-21, 3-22, 3-23,* and *3-24*. These standard tools create angles of 15°, 30°, 45°, 60°, and 75°.



FIGURE 3-21 *Making angular lines with the 45° triangle.*



FIGURE 3-22 *Making angular lines with the 30°–60° triangle.*



FIGURE 3-23 *Making 15° angles.*



FIGURE 3-24 *Making 75° angles.*

Parallel Lines

Parallel lines can be created in a number of different ways. Vertical (and horizontal) parallel lines are made by simply moving the straightedge the required distance and making each successive line, ***Figure 3-25.***

Parallel lines at angles can be created by using the 30°–60° and 45° triangles in combination much the same as they are used for making angular lines. When one uses triangles to create angular lines, the first line is created at the desired angle. Aligning one edge of a triangle to the line, register any side of the second triangle against one of the non-aligned edges of the first triangle. Holding the second triangle to prevent it from moving and sliding the first triangle along the engaged edge of the second triangle will reposition the originally aligned edge to any desired parallel position. Successive parallel lines are created in the same way, ***Figure 3-26.***



FIGURE 3-25 *Making vertical parallel lines.*



FIGURE 3-26 *Creating successive parallel lines.*



FIGURE 3-27 *Making perpendicular lines.*



FIGURE 3-28 *Creating a line perpendicular to a nonvertical or nonhorizontal line.*

Perpendicular Lines

Drawing perpendicular lines can be accomplished in a manner similar to drawing parallel lines. Horizontal and vertical perpendicular lines can be created by using a straightedge and a triangle, ***Figure 3-27.***

Creating a line perpendicular to a nonhorizontal or nonvertical line is accomplished by using triangles in conjunction with a straightedge, ***Figure 3-28.*** Line 1 in this figure is drawn first. Then the 45° triangle is slid along the 30°–60° triangle, and the perpendicular line is created with the opposite side of the 45° triangle.

Sketching

Even in the world of high technology and computers, sketching is still one of the most important skills for drafters and designers. Sketching is one of the first steps in communicating ideas for a design, and it is used in every step thereafter. It is common practice for designers to prepare sketches that are turned over to drafters for conversion to finished working drawings. ***Figure 3-29*** is an example of a typical design sketch.

Sketching Lines

The lines used in creating sketches closely correspond to those used in creating technical drawings except, of course, that they are not as sharp and crisp. ***Figure 3-30*** illustrates the various types of lines used in making sketches.



FIGURE 3-29 *Typical design sketch.*



FIGURE 3-30 *Lines used in sketching.*



FIGURE 3-31 *Sample design sketch.*

The basic line types are: visible line, hidden line, center line, dimension line, sectioning line, extension line, and cutting plane line. These lines represent the various lines available for creating sketches. The character of each line, as illustrated in *Figure 3-31*, should be closely adhered to when making sketches.

Types of Sketches

The types of sketches correspond to the types of technical drawings. There are four types of sketching: orthographic, axonometric, oblique, and perspective, *Figures 3-32, 3-33, 3-34,* and *3-35.*

Orthographic sketching relates to flat, graphic facsimiles of a subject showing no depth. Six principal views of a subject may be incorporated in an orthographic sketch: top, front, bottom, rear, right side,



FIGURE 3-32 *Orthographic sketch.*



FIGURE 3-33 *Axonometric sketch.*



FIGURE 3-34 *Oblique sketch.*



FIGURE 3-35 *Perspective sketch.*



FIGURE 3-36 *Six principal views in orthographic sketching.*



FIGURE 3-37 *Three types of axonometric sketches.*

and left side, ***Figure 3-36.*** The views selected for use in a sketch depend on the nature of the subject and the judgment of the sketcher.

Axonometric sketching may be one of three types: isometric, dimetric, or trimetric, ***Figure 3-37.*** The type most frequently used is *isometric,* in which length and width lines recede at 30° to the horizontal and height lines are vertical, ***Figure 3-38.*** In sketching, the use of these terms is academic as they relate to proportional scales and angle positions of height, width, and depth, which are only estimated in sketching.

Oblique sketching involves a combination of a flat, orthographic front surface with depth lines receding at a selected angle of 30°, 60° or 45° (usually 45°), ***Figure 3-39.***



FIGURE 3-38 *Isometric sketch.*



FIGURE 3-39 *Oblique sketch.*



FIGURE 3-40 *One-point perspective sketch.*



FIGURE 3-41 *Two-point perspective sketch.*

Perspective sketching involves creating a graphic facsimile of the subject. Consequently, depth lines must recede to a hypothetical vanishing point (or points), ***Figures 3-40*** and ***3-41***. In fact, all pictorial sketches naturally tend to assume characteristics of perspective sketches as a result of how the eye views the apparent relative proportions of objects. This is not necessarily undesirable.

Sketching Materials

An advantage of sketching is that it requires very few material aids. Whereas drafters must have a complete collection of tools, equipment, and materials in order to do working drawings, sketching requires nothing more than a pencil and a piece of paper. It is not uncommon for a sketch to be drawn on a paper napkin during a hurried luncheon meeting.

Sketching done in an office environment requires three basic materials: pencil, media (paper or graph paper), and an eraser. Graph paper simplifies the sketching process considerably, especially for students just learning, and it should be used freely.

Sketching Techniques

Sketches, as with drawings, consist of straight and curved lines. With practice, drafters can become skilled in creating neat, sharp, clear examples—straight or curved—of all the various line types introduced previously. When sketching, the following general rules apply.

1. Hold the pencil firmly, but not so tightly as to create tension or hand fatigue.
2. Grip the pencil approximately one inch to one and one-half inches up from the point.
3. Maintain a comfortable angle between the pencil and the sketching strokes.
4. Draw horizontal lines from left to right using short, slightly overlapping strokes.
5. Draw vertical lines from top to bottom using short, slightly overlapping strokes.
6. Draw curved lines using short, slightly overlapping strokes.

In addition to these general rules, some specific techniques are used in making the various line types for sketching.

Industry Application

"Don't they teach sketching in school any more? I can't find one drafting technician in this department who can make a decent sketch." Dan Johnson, chief drafter for Precision Machining, Inc. (PMI), had been frustrated when he made this statement. The problem he had faced at the time was simple. He needed to send a drafting technician into the field to make sketches of several parts for a warehouse full of machines that were to be refurbished and retrofitted. PMI had a contract to machine the parts. Unfortunately, the machines were old enough that technical drawings of the parts were no longer available.

Johnson's only option was to send a drafting technician to the warehouse armed with a sketch pad and micrometers. The parts would be measured, sketches would be made, and the drafting department would have the information needed to create a new technical drawing package. It was after seven technicians in a row had told Johnson that they either never learned sketching or had forgotten how that the chief drafter had vented his frustration. Fortunately for Johnson, Maria Sims overheard him. Sims was PMI's newest junior drafting technician, having graduated from Clark County College of Technology just a month earlier. Sims told Johnson that not only could she make comprehensive, accurate, readable sketches, but that she could read a micrometer, too. She was given the assignment on the spot and her sketching skills served her well.

Johnson was so impressed with his newest junior drafting technician that he not only promoted her, he asked her to give the entire department a seminar on sketching.

Sketching Straight Lines and Curves

Making straight lines on graph paper is a simple process of guiding the pencil using the existing lines. If graph paper is not available, pencil dots can be positioned to plot the path of the line, *Figure 3-42*. In this figure, the sketcher enters a series of pencil dots on the paper that provide a basic outline of the shape of the object. Then, with a series of short, slightly overlapping strokes, the pencil dots are connected, *Figures 3-43, 3-44,* and *3-45*. This technique is also used for curved lines, *Figure 3-46*.

Sketching Circles

Figure 3-47 illustrates a series of six steps that can be used for sketching a circle. Vertical and horizontal center lines are sketched, which positions the center of the circle (Step 1), and the radial distances of the desired circle size are marked on each of these lines, equidistant from the center (Step 2). A square is drawn symmetrically around the center, with the sides located at the radial line marks (Step 3). On the diagonals of the square (Step 4), the radial distances

FIGURE 3-42 *Dots used as guides in sketching.*

FIGURE 3-43 *Using dots in sketching lines.*

FIGURE 3-44 *Continuing the sketch by connecting the dots.*



FIGURE 3-45 *Completing the sketch made by using dots as guides.*

FIGURE 3-46 *Using dots in sketching curved lines.*



FIGURE 3-47 *Sketching a circle.*

are again marked off from the center (Step 5). This provides four positions for the circumference to pass through at the sides of the square, and four more positions on the diagonals of the square. The right half of the circle is sketched in from top to bottom using short, slightly overlapping strokes, and then the left half is sketched in the same manner (Step 6).

Sketching Ellipses

A similar technique is used for sketching ellipses on an orthographic view, except that the square becomes a rectangle, *Figure 3-48*. Ellipses are oriented on the pictorial of the object being sketched as shown in the diagram in *Figure 3-49*.



FIGURE 3-48 *Sketching an ellipse.*



FIGURE 3-49 *Orienting an ellipse on an object.*

Proportion in Sketching

Sketches are not done to scale, but it is important that they be made proportionately accurate. All of the various components of a sketch should be kept in proportion to those of the actual object. This technique takes a great deal of practice to master.

Some methods for achieving proportion recommend using a pencil or a strip of paper as a simulated scale. These techniques are not only unrealistic in terms of the real world, they defeat the very purpose of sketching. A skilled sketcher must learn to maintain proportion without the use of tools and aids. The best device for accomplishing proportion in sketching is the human eye. With practice, the drafter can become proficient in maintaining proportion without the use of extraneous, time-consuming devices. The following general rules relating to proportion will also help.

STEP 1 In sketching, use graph paper whenever possible.

STEP 2 Examine the object to be sketched and mentally break it into its component parts.

STEP 3 Beginning with the largest components (width and height), estimate the proportion, such as the width is 4/3 times the height or 5/2 times the height, and so on.

STEP 4 Lay out the largest component according to the proportions decided upon in Step 3. Use construction line squares and rectangles to block in irregularly shaped components, *Figure 3-50.*

Repeat Steps 3 and 4 until the entire object is finished.



FIGURE 3-50 *Blocking in components.*

Orthographic Sketching

Orthographic sketching may involve sketching any combination of the six principal views of the subject. The top, front, and right-side views are normally selected for representing an object in an orthographic sketch. However, these views are not always appropriate. The sketcher must learn to choose the most appropriate views. These are the views that show the most detail and the fewest hidden lines. A good rule of thumb to use in selecting views is to select the views that would give you all of the information you would need if you had to make the object yourself.

Once the views have been selected, the orthographic sketch may be laid out using the techniques set forth earlier in this chapter. To ensure that the sketched views align, the entire sketch should be blocked in before adding details, *Figure 3-51.* Once the layout is blocked in, the details can be added one view at a time, *Figures 3-52, 3-53,* and *3-54.*

Axonometric Sketching

As was mentioned earlier, there are three types of axonometric projection: isometric, dimetric, and



FIGURE 3-51 *Blocking in an orthographic sketch.*



FIGURE 3-52 *Completing the top view.*



FIGURE 3-53 *Completing the front view.*



FIGURE 3-54 *Completing the sketch.*

trimetric. Isometric projection is used in sketching. Dimetric and trimetric projection have little application in sketching, due to the difficulty in proportioning scale values of depth, width, and height. Isometric views have the same scaling value in all three directions, eliminating the need to vary proportions among the three directions. In an isometric sketch, height lines are vertical and width and depth lines recede at approximately 30° and 150° (180°–30°) from the horizontal.

The first step in creating an isometric sketch is to lay out the isometric axis, ***Figure 3-55.*** All normal lines will be parallel to one of the axis lines. The next step is to block in the object by using construction lines, ***Figure 3-56.*** Five steps in the development of an isometric sketch are shown in ***Figures 3-57, 3-58, 3-59, 3-60,*** and ***3-61.***

Oblique Sketching

Oblique sketching involves laying out the front view of an object and showing the depth lines receding at an angle (usually 45°) from the horizontal. Oblique sketching is particularly useful for dealing with an object having round components. Oblique sketching



FIGURE 3-55 *The isometric axis in sketching.*



FIGURE 3-56 *Blocking in the object.*



FIGURE 3-57 *Step 1 in making an isometric sketch.*

allows round components to be drawn round, rather than elliptical.

Using the blocking-in method, the flat front surface of the object is laid out. The depth is then



FIGURE 3-58 *Step 2 in making an isometric sketch.*



FIGURE 3-59 *Step 3 in making an isometric sketch.*



FIGURE 3-60 *Step 4 in making an isometric sketch.*



FIGURE 3-61 *Step 5 in making an isometric sketch.*



FIGURE 3-62 *Step 1 in making an oblique sketch.*



FIGURE 3-63 *Step 2 in making an oblique sketch.*

blocked in using parallel lines, and the sketch is completed by outlining the exposed profile of the rear surface. ***Figures 3-62, 3-63,*** and ***3-64*** illustrate three steps in creating an oblique sketch.

Perspective Sketching

Perspective sketching closely approximates how the human eye actually sees an object. Two common types of perspective sketches are one-point and two-point perspectives.



FIGURE 3-64 *Step 3 in making an oblique sketch.*

A one-point perspective sketch is similar to an oblique sketch, except that depth lines recede to a vanishing point instead of receding parallel to one another, *Figure 3-65.* In constructing a one-point perspective, the following procedures apply.

STEP 1 Lay out the flat front surface of the object by using the blocking-in method, *Figure 3-66.*



FIGURE 3-65 *One-point perspective sketch.*



FIGURE 3-66 *Step 1 in making a one-point perspective sketch.*

STEP 2 Select and mark a single vanishing point. Project all points on the front surface back to the vanishing point, *Figure 3-67.*

STEP 3 Estimate the depth of the object and mark it off on all line projectors, *Figure 3-68.*

STEP 4 Complete the sketch by outlining the exposed profile of the rear surface, *Figure 3-69.*



FIGURE 3-67 *Step 2 in making a one-point perspective sketch.*



FIGURE 3-68 *Step 3 in making a one-point perspective sketch.*



FIGURE 3-69 *Step 4 in making a one-point perspective sketch.*



FIGURE 3-70 *Two-point perspective sketch.*

A two-point perspective resembles an isometric sketch, except that width and depth lines recede to the left and right vanishing points rather than receding in parallel, ***Figure 3-70.***

In constructing a two-point perspective, the following procedures apply.

STEP 1 Lay out the two-point perspective frame, which consists of the vertical height line, the vanishing point left, the vanishing point right, and the receding lines (all estimated locations), ***Figure 3-71.*** The horizon line when positioned below the view provides a view of the bottom of the object, and when positioned above it shows the top. The vanishing points must be on the horizon.

STEP 2 Block in the object, estimating the length and width for proportion, ***Figure 3-72.***

STEP 3 Lay out the details, lightly giving special attention to proportion, ***Figure 3-73.***

STEP 4 Complete the two-point perspective sketch, ***Figure 3-74.***



FIGURE 3-71 *Laying out the two-point perspective frame.*



FIGURE 3-72 *Blocking in the object.*



FIGURE 3-73 *Laying out the details.*



FIGURE 3-74 *Completing the two-point perspective sketch.*

Summary

- Talking sketching is of two types: conversational and boardroom sketching. Conversational sketches are developed as two or three individuals discuss an idea. Boardroom sketches are developed on a marker board, chalkboard, or flip chart while a group discusses an idea.
- Freehand lettering may be done in several styles, including Block, Fast, Futura, Leroy, Old English, Times, and Helvet. Single-stroke Gothic lettering may be done in upper- or lowercase, extended or condensed, and vertical or inclined styles. The characteristics of good lettering are neatness, uniformity, stability, proper spacing, and speed.
- Students should be able to make and demonstrate the proper use of the following types of lines: visible, hidden, crosshatching, center, dimension, extension, leader, cutting plane, freehand break, mechanical break, phantom, and stitch.
- Students should be able to illustrate the following types of sketches: orthographic, axonometric, oblique, and perspective.
- The materials needed for making sketches are pencils, paper or graph paper, and an eraser.
- Sketching techniques with which students should be proficient are making straight lines, curves, circles, and ellipses. Students should also be proficient in maintaining proper proportion when sketching.

Review Questions

Answer the following questions either true or false.

1. The standard style of freehand lettering on technical drawings is vertical, single-stroke Arial.
2. The correct slope of slanted lettering is a two-unit incline to the right for each five units of letter height.
3. Three strokes are required to make the letter B.
4. In regard to space left between words, it is a rule of thumb to leave the width of one round letter such as Q, C, or O.
5. Uniformity, neatness, and stability can all be achieved without using guidelines.
6. A setting of 8 on a lettering guide will produce letters 1/4″ high.
7. *Line work* is a term used to describe one specific technique used to create graphic data on technical drawings.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** a characteristic of good freehand lettering?
   a. Neatness
   b. Speed

c. Uniformity
d. Incline

2. Which of the following is **not** one of the basic line types used on technical drawings?
   a. Angular, perpendicular, nonhorizontal, nonvertical
   b. Visible, hidden, crosshatch
   c. Cutting plane, freehand break, mechanical
   d. Center, dimension, extension, leader
3. Which of the following is an advantage of sketching compared to mechanical drawing?
   a. It requires few material aids.
   b. It can be mastered without much practice.
   c. It can be done with just a pencil and piece of paper.
   d. Both a and c.
4. Which axonometric projection is preferred for sketching?
   a. Isometric
   b. Dimetric
   c. Trimetric
   d. Quadmetric
5. Which kind of projection exhibits a circle as an elliptic shape?
   a. Mercator
   b. Isometric
   c. Multiview
   d. Auxiliary
6. How many principal views are there in an orthographic projection?
   a. Two
   b. Four
   c. Six
   d. Eight
7. Guidelines are a critical part of freehand lettering because:
   a. They improve uniformity.
   b. They improve neatness.
   c. They improve stability.
   d. All of the above.
8. What is the customary height of characters in a technical drawing?
   a. 1/16″ for regular text and 3/16″ for headings and titles
   b. 1/8″ for regular text and 3/16″ for headings and titles
   c. 1/8″ for regular text and 1/2″ for headings and titles
   d. 1/4″ for regular text and 1/2″ for headings and titles
9. Which of the following is a type of axonometric sketch?
   a. Perspective
   b. Orthographic
   c. Oblique
   d. Trimetric

Chapter 3 Problems

Problems 3-1 through 3-9 are intended to give beginning drafters experiences in visualizing that objects are made of convenient shapes and features. Visualizing these shapes and features will help you to completely specify an object's dimensions. Another objective of these nine problems is to encourage you to use approximations, when appropriate, to obtain ballpark answers before diving into detailed calculations.

Problem 3-22 will be used here as an example to illustrate the requirements for the nine problems. Assume that you have been asked to calculate the weight of the object in Problem 3-22, which is made of aluminum with a density of 0.097 pounds per cubic inch. To make a ballpark calculation, consider the base to be 1″ × 2″ × 4″ or a volume of approximately 8 cubic inches and the vertical portion 1/2″ × 1½″ × 4″ or 3 cubic inches. A total of 8 + 3 = 11 cubic inches, which multiplied by the density equals approximately 1.0 pound. The correct volume is calculated by deducting the semicircular 1″ radius hole and deducting some volume for the rounded corners of 1/2″ radius. The correct volume is found to be 9.84 cubic inches. Multiply by the density to obtain 0.954 pounds for the correct weight.

Unless otherwise specified, use the format shown in Problem 4-37 to present your solutions for the following problems.

PROBLEM 3-1

Assume that the object in Problem 3-17 is aluminum. Calculate its weight.

PROBLEM 3-2

Assume that the object in Problem 3-18 is aluminum. Calculate its weight.

PROBLEM 3-3

Assume that the object in Problem 3-21 is aluminum. Calculate its weight.

PROBLEM 3-4

Assume that the object in Problem 3-23 is steel with a density of 0.28 pounds per cubic inch. Calculate its weight.

PROBLEM 3-5

Assume that the object in Problem 3-28 is brass with a density of 0.32 pounds per cubic inch. Calculate its weight.

PROBLEM 3-6

Assume that the object in Problem 3-29 is brass with a density of 0.32 pounds per cubic inch. Calculate its weight.

PROBLEM 3-7

Assume that the object in Problem 3-31 is steel with a density of 0.28 pounds per cubic inch. Calculate its weight.

PROBLEM 3-8

Assume that the object in Problem 3-33 is steel with a density of 7,765 kilograms per cubic meter. Calculate its weight in kilograms. Note that one kilogram equals 2.2 pounds. Also, the squares in Problem 3-33 are given as 10 mm or .010 m.

PROBLEM 3-9

Assume that the object in Problem 3-25 is cast iron with a density of 6,933 kilograms per cubic meter. Calculate its weight in kilograms.

Problems 3-10 through 3-13

The following problems are intended to give the beginning drafter practice in making neat uppercase, vertical, and Gothic-style letters and numbers. On an A-size sheet of vellum, carefully lay out light .12 spaces as shown. Use .50 borders all around and ***be sure to skip a space*** *between lines of letters or numbers. Practice letters, numbers, words, sentences, and paragraphs, as given.*

PROBLEM 3-10



PROBLEM 3-11



PROBLEM 3-12

.12 (3)

GOOD LETTERING TAKES PRACTICE

.09 (2)

IMPROVEMENT IN LETTERING REQUIRES EFFORT

PATIENCE AND HARD WORK EQUALS GOOD LETTERING

SINGLE-STROKE, UPPERCASE, VERTICAL GOTHIC LETTERING IS USED IN THE MECHANICAL DRAFTING FIELD

PROBLEM 3-13

.12 (3)

LETTERING IS EXTREMELY IMPORTANT. IT MUST BE NEAT, LEGIBLE, CLEAR, AND IN PROPORTION AND MUST BE DONE IN A REASONABLE AMOUNT OF TIME

.09 (2)

Problems 3-14 through 3-33

These problems are intended to give the beginning drafter practice in sketching. On an A-size sheet of vellum, neatly sketch the top, front, and right-side views of each pictorial figure shown. The grid is provided for proportion only. Try to keep the object in scale as you sketch; keep all parallel lines parallel, and sketch as neatly as possible. Do not use any drawing instruments. Add all lines, including hidden lines and center lines.

Next, sketch each object from your three-view drawings into isometric pictorial views.

PROBLEM 3-14



PROBLEM 3-15



PROBLEM 3-16



PROBLEM 3-17



PROBLEM 3-18



PROBLEM 3-19



PROBLEM 3-20



PROBLEM 3-21



PROBLEM 3-22



PROBLEM 3-23



PROBLEM 3-24



PROBLEM 3-25



PROBLEM 3-26



PROBLEM 3-27



PROBLEM 3-28



PROBLEM 3-29



PROBLEM 3-30



PROBLEM 3-31



PROBLEM 3-32



PROBLEM 3-33



Problems 3-34 through 3-37

These few problems are intended to provide future drafters, designers, and engineers with experiences in developing an appreciation for sketching from memory, for recording preliminary design ideas, and for orally communicating technical ideas while sketching.

PROBLEM 3-34

Visit a facility and mentally (no notes or rough sketches) study an object, such as a machine component, an object or a tool in a shop, a part of an automobile, or a piece of sports equipment with a goal in mind that upon returning to class you will sketch the object(s) from memory. Then, prepare orthographic or isometric-type sketches.

The skill emphasized here is that if you observe and study an object as though you were required to sketch it later, you will **see more** than if you just casually look at it. Develop this skill collecting technical ideas for designing.

PROBLEM 3-35

Sketch orthographic views and an isometric of a representative object to be used as your nameplate for a desk, to match your career interests. For example; a bridge could represent a career in construction or civil engineering; a pressurized tank, for welding; an airplane, for flying; a computer, for computer science; and so on.

PROBLEM 3-36

Sketch orthographic views of your design of one of the following.

a. a modern chair
b. a storage cabinet for
  1. wardrobe
  2. drafting tools
  3. typical home use garden tools
c. a basic outline of a sports car
d. a basic outline of an electric car
e. a cabinet for trophies
f. a two-person skateboard
g. an outdoor logo for your school
h. a toolbox for:
  1. car maintenance tools
  2. woodworking tools
  3. hobbies (fishing, models, etc.)

PROBLEM 3-37

Visit one of the locations listed and select a device, not too complicated, to sketch. Make a rough sketch (for your use only) for later use in a drafting class. Be prepared to sketch the device, while describing its attributes (shape, size, function, material, aesthetic properties, etc.) to either another student or at the board, to the class.

a. metal shop
b. wood shop
c. electronics shop
d. hardware
e. store
f. garage
g. kitchen
h. computer

4

Geometric Construction

KEY TERMS

Acute angle
Altitude
Angle
Bisect
Central angle
Chord
Circle
Circumference
Concentric circle
Cone
Conic section
Cylindrical helix
Diameter
Eccentric circle
Epicycloid
Equilateral triangle
Helix
Hemisphere
Hypocycloid
Involute
Isosceles triangle
Lead
Line
Obtuse angle
Obtuse angle triangle
Ogee curve
Parallelogram
Point
Pole
Polygon
Polyhedron
Prism
Pyramid
Quadrant
Quadrilateral
Radius
Right angle
Right triangle
Scalene triangle
Sector
Segment
Semicircle
Sphere
Tangent point
Triangle
Truncated

CHAPTER OUTLINE

Geometric nomenclature • Elemental construction principles • Polygon construction • Circular construction • Supplementary construction • Summary • Review questions • Chapter 4 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Define the most frequently used terms in geometric nomenclature.
- Properly apply the elemental principles of geometric construction.
- Demonstrate the proper procedures for polygon construction.
- Demonstrate the proper procedures for circular construction.
- Demonstrate the proper procedures for supplementary construction, including the following: spiral; helix; involute of a line, triangle, square, and circle; and cycloidal curve.

To be truly proficient in the layout of both simple and complex drawings, the drafter must know and fully understand the many geometric construction methods used. These methods are illustrated in this chapter and are basically simple principles of pure geometry. These simple principles are used to develop a drawing with complete accuracy, and in the fastest time possible, without wasted motion or any guesswork. Applying these geometric construction principles gives drawings a finished, professional appearance.

In laying out the various geometric constructions, it is important to use a very sharp, 4H lead and to be extremely accurate at all times. Always draw light construction lines that can hardly be seen when held at arm's length. These light construction lines should not be erased as this takes up valuable drawing time, and they can also be reused to check layout work if necessary.

Geometric Nomenclature

Points in Space

A *point* is an exact location in space or on a drawing surface, ***Figure 4-1***. A point is actually represented on the drawing by a crisscross at its exact location. The exact point in (drawing) space is where the two lines of the crisscross intersect. When a point is located on an existing line, a light, short, dashed line or crossbar is placed on the line at the location of the exact point. Never represent a point on a drawing by a dot, except for sketching locations. This is not accurate enough, and it is considered to be poor drafting practice.

Line

A straight line is the shortest distance between two points, ***Figure 4-2***. It can be drawn in any direction. A *line* can be straight, an arc, a circle, or a free curve, as illustrated in ***Figure 4-3***. If a line is indefinite, and the ends are not fixed in length, the actual length is a matter of convenience. If the end points of a line are important, they must be marked by means of small, mechanically drawn crossbars, as described by a point in space.



FIGURE 4-1 *Points in space or on a surface.*



FIGURE 4-2 *A straight line is the shortest distance between two points.*



FIGURE 4-3 *Kinds of lines.*

Straight lines and curved lines are considered to be parallel if the shortest distance between them remains constant. The symbol used for parallel lines is //. Lines that are tangent and at 90° are considered perpendicular. The symbol for perpendicular lines is ⊥ (singular), ***Figure 4-4***, and ⊥'s (plural). The symbol for an angle is ∠ (singular) and ∠'s (plural). To draw an angle, use the drafting machine, a triangle, or a protractor. For extra accuracy, use the vernier on the drafting machine or a vernier protractor.

Angle

An *angle* is formed by the intersection of two lines. There are three major kinds of angles: right angles, acute angles, and obtuse angles, ***Figure 4-5***. The *right angle* is an angle of 90°. An *acute angle* is an angle at less than 90°, and an *obtuse angle* is an angle at more than 90°. Note that a straight line is 180°. Figure 4-5 also illustrates the complementary and supplementary angles of a given angle.



FIGURE 4-4 *Perpendicular lines.*



FIGURE 4-5 *Kinds of angles.*

There are 360 degrees (360°) in a full circle. Each degree is divided into 60 minutes (60′). Each minute is divided into 60 seconds (60″). Example: 48°28′38″ is read as 48 degrees, 28 minutes, and 38 seconds. To convert minutes and seconds to decimal degrees, divide minutes by 60 and seconds by 3,600.

EXAMPLE:

$21°18'27'' = 21° + (18.60)° + (27.3600)° = 21.3075°$

To convert decimal degrees to degrees, minutes, and seconds, multiply the degree decimal by 60 to obtain minutes, and the minute decimal by 60 to obtain seconds.

EXAMPLE:

$77.365° = 77° + (.365 \times 60)' = 77°21'.9'$

$77°21'.9' = 77°21' + (.9 \times 60)'' = 77°21'54''$

A vernier may be used to measure and read off minutes and seconds of a degree. The vernier scale is discussed in Chapter 1.

Triangle

A *triangle* is a closed plane figure with three straight sides and three interior angles. The sum of the three internal angles is always exactly 180°, half of the 360° in a full circle. *Figure 4-6* shows the various kinds of triangles: a right triangle, an equilateral triangle, an isosceles triangle, a scalene triangle, and an obtuse angle triangle.

A *right triangle* is a triangle having a right angle or an angle of 90°. The two sides forming the right angle are called legs, and the third side (the longest) is the hypotenuse. Any triangle inscribed in a semicircle is a right triangle, *Figure 4-7*.

An *equilateral triangle*, as its name implies, is a triangle with all sides of equal length. All of its interior angles are also equal. An *isosceles triangle* has two



FIGURE 4-6 *Kinds of triangles.*



FIGURE 4-7 *Any triangle inscribed within a semicircle is a right triangle.*

sides of equal length and two equal interior angles. A *scalene triangle* has no equal sides or angles. An *obtuse angle triangle* is a triangle having an obtuse angle greater than 90°, with no equal sides.

Polygon

A *polygon* is a closed plane figure with three or more straight sides, *Figure 4-8*. More specifically, shown in the figure are regular polygons, meaning that all sides are equal in each of these examples. The most important of these polygons as they relate to drafting are probably the triangle with three sides, the square with four sides, the hexagon with six sides, and the octagon with eight sides.

Quadrilateral

A *quadrilateral* is a plane figure bounded by four straight sides. When opposite sides are parallel, the quadrilateral is also considered to be a *parallelogram*, *Figure 4-9*.



FIGURE 4-8 *Examples of polygons.*



FIGURE 4-9 *Quadrilaterals.*

Circle

A *circle* is a closed curve with all points on the circle at the same distance from the center point. The major components of a circle are the diameter, the radius, and the circumference, ***Figure 4-10.***

The *diameter* of a circle is the straight distance from one outside curved surface through the center point to the opposite outside curved surface. The diameter of a circle is twice the size of the radius.

The *radius* of a circle is the distance from the center point to the outside curved surface. The radius is half the diameter and is used to set the compass when drawing a diameter.

The *circumference* of a circle is the distance around the outer surface of the circle. To calculate the circumference of a circle, multiply the value of π (use the approximation 3.1416) by the diameter. A chart similar to the one found in Appendix A may be used.

Other important parts of a circle are the central angle, the sector, the quadrant, the chord, and the segment, ***Figure 4-11.***

A *central angle* is an angle formed by two radial lines from the center of the circle.



FIGURE 4-11 *Other parts of a circle.*



FIGURE 4-10 *The major components of a circle.*



FIGURE 4-12 *Concentric and eccentric circles.*



FIGURE 4-13 *Polyhedrons (solids).*

A *sector* is the area of a circle lying between two radial lines and the circumference.

A *quadrant* is a sector with a central angle of 90°, and usually with one of the radial lines oriented horizontally.

A *chord* is any straight line whose opposite ends terminate on the circumference of the circle. (A diameter is a chord passing through the center of the circle.)

A *segment* is the smaller portion of a circle separated by a chord.

Concentric circles are two or more circles with a common center point, ***Figure 4-12.***

Eccentric circles are two or more circles without a common center point, ***Figure 4-12.***

A *semicircle* is half of a circle.

Polyhedron

A *polyhedron* is a solid object bounded by plane surfaces. Each surface is called a face. If the faces are equal, regular polygons, the solid figure is a regular polyhedron, ***Figure 4-13.***

Prism

A *prism* is a solid having ends that are parallel, matched polygons, and sides that are parallelograms, ***Figure 4-14.*** This definition also applies to round or circular objects, such as a cylinder. When the polygon on one end of a prism is not parallel to the other end, it is said to be *truncated.* The *altitude* of a prism is the perpendicular distance between its end polygons (or bases).



FIGURE 4-14 *Prisms.*

Pyramid and Cone

A *pyramid* is a polyhedron having a polygon as its base. Three or more triangles form its lateral sides, which meet at a common vertex, ***Figure 4-15.*** A *cone* is a pyramid with a central axis and an infinite number of sides that form a continuous curved lateral surface. When the vertex of a pyramid or cone has been removed by a plane that intersects all the lateral



FIGURE 4-15 *Pyramids.*



FIGURE 4-16 *Truncated prism and pyramid.*



FIGURE 4-17 *Sphere.*

sides (which forms a new polygon), the pyramid or cone is said to be truncated, *Figure 4-16.*

Sphere

A *sphere* is a closed surface, every point on which is equidistant from a common point or center, *Figure 4-17.* If a sphere is cut into two equal parts, the parts are called *hemispheres. Poles* are two reference measuring positions on the surface of the sphere on opposite sides of its center.

Elemental Construction Principles

The remaining portion of this chapter is devoted to illustrating step-by-step the many geometric construction principles used by the drafter to develop various geometric forms. It is important that each step be fully understood and followed. As the beginning drafter uses these geometric construction principles, various shortcuts will become evident, thus reducing the drawing time and increasing accuracy even more. At the end of the chapter, each of these techniques is incorporated or used in some way to complete the problems.

How to Bisect a Line

To *bisect* a line means to divide it in half or to find its midpoint. In the given process, a line will also be constructed at the exact center point of exactly 90°.

GIVEN: Line A-B, *Figure 4-18A.*

STEP 1 Set the compass approximately two-thirds of the length of line A-B and swing an arc from point A, *Figure 4-18B.*

STEP 2 Using the same compass setting, swing an arc from point B, *Figure 4-18C.*

STEP 3 At the two intersections of these arcs, locate points X and Y, *Figure 4-18D.*

STEP 4 Draw a straight line connecting point X with point Y. Where this line intersects line A-B is the bisect of line A-B, *Figure 4-18E.* Line X-Y is also perpendicular to line A-B at the center point.

How to Bisect an Angle

To bisect an angle means to divide it in half or to cut it into two equal angles.

GIVEN: Angle ABC, *Figure 4-19A.*

STEP 1 Set the compass at any convenient radius and swing an arc from point B, *Figure 4-19B.*



FIGURE 4-18 *(A) How to bisect a line; (B) Step 1; (C) Step 2.*



FIGURE 4-18 *(Continued) (D) Step 3; (E) Step 4.*

STEP 2 Locate points X and Y on the legs of the angle and swing two arcs of the same length from points X and Y, respectively, *Figure 4-19C.*

STEP 3 Where these arcs intersect, locate point Z. Draw a straight line from B to Z. This line will bisect angle ABC and establish two equal angles: ABZ and ZBC, *Figure 4-19D.*

How to Draw an Arc or Circle (Radius) through Three Given Points

GIVEN: Three points in space at random: A, B, and C, *Figure 4-20A.*

STEP 1 With straight lines, lightly connect points A to B, and B to C, *Figure 4-20B.*

STEP 2 Using the method outlined for bisecting a line, bisect lines A-B and B-C, *Figure 4-20C.*

STEP 3 Locate point X where the two extended bisectors meet. Point X is the exact center of the arc or circle, *Figure 4-20D.*

STEP 4 Place the point of the compass on point X and adjust the lead to any of the points A, B, or C (they are the same distance), and swing the circle. If all work is done correctly, the arc or circle should pass through each point, as shown in *Figure 4-20E.*



FIGURE 4-19 *(A) How to bisect an angle; (B) Step 1; (C) Step 2; (D) Step 3.*

How to Draw a Line Parallel to a Straight Line at a Given Distance

GIVEN: Line A-B, and a required distance to the parallel line, *Figure 4-21A.*

STEP 1 Set the compass at the required distance to the parallel line. Place the point of the compass at any location on the given line, and swing a light arc whose radius is the required distance, *Figure 4-21B.*

STEP 2 Adjust the straightedge of either a drafting machine or an adjustable triangle so that it lines up with line A-B, slide the straightedge up or down to the extreme high point, which is the tangent point of the arc; then draw the parallel line, *Figure 4-21C.*

NOTE: The distance between parallel lines is measured on any line that is perpendicular to both.



FIGURE 4-20 *(A) How to draw an arc or circle (radius) through three given points; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4.*

How to Draw a Line Parallel to a Curved Line at a Given Distance

GIVEN: Curved line A-B, and a required distance to the parallel line, *Figure 4-22A.*

STEP 1 Set the compass at the required distance to the parallel line. Starting from either end of



FIGURE 4-21 *(A) How to draw a line parallel to a straight line at a given distance; (B) Step 1; (C) Step 2.*



FIGURE 4-22 *(A) How to draw a line parallel to a curved line at a given distance; (B) Step 1; (C) Step 2.*



FIGURE 4-23 *(A) How to draw a perpendicular to a line from a point on the line (method 1); (B) Step 1; (C) Step 2; (D) Step 3.*

the curved line, place the point of the compass on the given line and swing a series of light arcs along the given line, *Figure 4-22B*.

STEP 2 Using an irregular curve, draw a line along the extreme high points of the arcs, *Figure 4-22C*.

How to Draw a Perpendicular to a Line from a Point on the Line (Method 1)

GIVEN: Line A-B with point P on the same line, *Figure 4-23A*.

STEP 1 Using P as the center, make two arcs of equal radius or one continuous arc (R1) to intercept line A-B on either side of point P, at points S and T, *Figure 4-23B*.

STEP 2 Swing larger but equal arcs (R2) from each of points S and T to cross each other at point U, *Figure 4-23C*.

STEP 3 A line from U to P is perpendicular to line A-B at point P, *Figure 4-23D*.

How to Draw a Perpendicular to a Line from a Point on the Line (Method 2)

GIVEN: Line A-B with point P on the line, *Figure 4-24A*.

STEP 1 Swing an arc of any convenient radius whose center O is at any convenient location not on line A-B, but positioned to make the arc cross line A-B at points P and Q, *Figure 4-24B*.

STEP 2 A line from point Q through center O intercepts the opposite side of the arc at point R, *Figure 4-24C*.

STEP 3 Line R-P is perpendicular to line A-B. (A right triangle has been inscribed in a semicircle.) See *Figure 4-24D*.

How to Draw a Perpendicular to a Line from a Point Not on the Line

GIVEN: Line A-B and point P, *Figure 4-25A*.

STEP 1 Using P as a center, swing an arc (R1) to intercept line A-B at points G and H, *Figure 4-25B*.

STEP 2 Swing larger-but-equal-length arcs (R2) from each of the points G and H to intercept each other at point J, *Figure 4-25C*.

STEP 3 Line P-J is perpendicular to line A-B, *Figure 4-25D*.

How to Divide a Line into Equal Parts

GIVEN: Line A-B, *Figure 4-26A*.

STEP 1 Draw a line 90° from either end of the given line. A 90° line from point B is illustrated in *Figure 4-26B*, but either end or either direction will work as well.



FIGURE 4-24 *(A) How to draw a perpendicular to a line at a point (method 2); (B) Step 1; (C) Step 2; (D) Step 3.*



FIGURE 4-25 *(A) How to draw a perpendicular to a line from a point not on the line; (B) Step 1; (C) Step 2; (D) Step 3.*

STEP 2 Place a scale with its zero at point A of the given line. If three equal parts are required, pivot the scale until the three-inch measurement (or any length representing three equal units of measure: 30, 60 and 90 mm, for example) is on the perpendicular line drawn in Step 1. Place a short dash at these points. The example in *Figure 4-26C* shows these dashes at the 1″ and 2″ marks.

STEP 3 Project lines downward from these points and add short hash marks where these projected lines cross the original given line A-B. This divides the line A-B into three equal parts. Check all work, comparing your final step with *Figure 4-26D*. An example of equal spacing, where equally spaced holes are required with a given length, is illustrated in *Figure 4-26E*.



FIGURE 4-26 *(A) How to divide a line into equal parts; (B) Step 1; (C) Step 2; (D) Step 3; (E) An example of equal spacing within a given length.*



FIGURE 4-27 *(A) How to divide a line into proportional parts; (B) Step 1; (C) Step 2.*

How to Divide a Line into Proportional Parts

GIVEN: Line A-B, *Figure 4-27A. Problem:* Locate point X at 2/3 of the distance from point A to point B.

STEP 1 Draw a line 90° from either end of the line. A 90° line from point B is illustrated in *Figure 4-27B.*

STEP 2 Place a scale with its zero on point A of the given line. Because a 2/3 proportion is required, pivot the scale until any multiple of three units of measure intersects the perpendicular line drawn in Step 1. In this example, 6 is used, representing three two-unit increments. The 2/3 position of this length is two two-unit increments, or the

four position, where a hash mark is made, as shown in *Figure 4-27C*. Projecting this point downward to line A-B, it becomes point X, which is 2/3 the overall distance from point A.

How to Transfer an Angle

GIVEN: An angle formed by two straight lines, 0A-0B, *Figure 4-28A*, and one location of where the transferred angle begins (point 0′), *Figure 4-28B*.

STEP 1 Refer to *Figure 4-28C*. Draw an arc through both legs of a given angle (R1) and then duplicate this radius at the transferred angle location, *Figure 4-28D*.

STEP 2 Transfer the chord length between the two angle legs at the intersection of the arc (R2) to the arc at the transfer angle location.

STEP 3 A line from the arc center to the intersection of arc and chord length forms the second line, forming an angle equal to the original, *Figures 4-28E* and *4-28F*.

How to Transfer an Odd Shape

GIVEN: Triangle ABC, *Figure 4-29A*.

STEP 1 Letter or number the various corners and point locations of the odd shape in counterclockwise order around its perimeter. In this example, place the compass point at point A of the original shape and extend the lead to point B. Refer back to *Figure 4-29A*. Swing a light arc at the new desired location, *Figure 4-29B*. Letter the center point as A′ and add letter B′ at any convenient location on the arc. It is a good habit to lightly letter each point as you proceed.

STEP 2 Place the compass point at letter B of the original shape, *Figure 4-29C*, and extend the compass lead to letter C of the original shape.

STEP 3 Transfer this distance, B-C, to the layout, *Figure 4-29D*.

STEP 4 Going back to the original object, place the compass point at letter A, *Figure 4-29E*, and extend the compass lead to letter C.

STEP 5 Transfer the distance A-C as illustrated in *Figure 4-29F*. Locate and letter each point.

STEP 6 Connect points A′, B′, and C′ with light, straight lines. This completes the transfer of the object, *Figure 4-29G*. Recheck all work and, if correct, darken lines to the correct line weight.



FIGURE 4-28 *(A) How to transfer an angle; (B) Given: Point 0′; (C) Step 1; (D) Transferred angle; (E) Step 2; (F) Step 3.*



FIGURE 4-29 *(A) How to transfer an odd shape; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5; (G) Step 6.*

How to Transfer Complex Shapes

A complex shape can be transferred in exactly the same way by reducing the shape into simple triangles and transferring each triangle by using the foregoing method.

GIVEN: An odd shape, A, B, C, D, E, F, G, *Figure 4-30A*. Letter or number the various corners and point locations of the odd shape in clockwise order around the perimeter, *Figure 4-30A*. Use the longest line or any convenient line as a starting point. Line A-B is chosen here as the example.

STEP 1 Lightly divide the shape into triangle divisions, using the baseline if possible. Transfer each triangle in the manner described in *Figures 4-29A* through *4-29G*. Suggested triangles to be used in example *Figure 4-30A* are ABC, ABD, ABE, ABF, and ABG, *Figure 4-30B*.

STEP 2 This completes the transfer. Check all work and, if correct, darken in lines to correct line thickness. See *Figure 4-30C*.

How to Proportionately Enlarge or Reduce a Shape

GIVEN: A rectangle, *Figure 4-31A*. *Problem:* To enlarge or reduce its size proportionately.

STEP 1 Draw a line from corner to corner diagonally and extend it as shown in *Figure 4-31B*.

STEP 2 The rectangle is enlarged to any size proportionately if the vertical and horizontal sides are located from the extended diagonal line, *Figure 4-31C*.

STEP 3 The rectangle is reduced proportionately if the vertical and horizontal lines are located on the unextended diagonal line, *Figure 4-31D*.



FIGURE 4-30 *(A) How to transfer complex shapes; (B) Step 1; (C) Step 2.*



FIGURE 4-31 *(A) How to proportionately enlarge or reduce a shape; (B) Step 1; (C) Step 2; (D) Step 3.*

Polygon Construction

How to Draw a Triangle with Known Lengths of Sides

GIVEN: Lengths 1, 2, and 3, *Figure 4-32A.*

STEP 1 Draw the longest length line, in this example length 3, with endpoints A and B, *Figure 4-32B.* Swing an arc (R1) from point A whose radius is either length 1 or length 2; in this example, length 1.

STEP 2 Using the radius length not used in Step 1, swing an arc (R2) from point B to intercept the arc swung from point A at point C, *Figure 4-32C.*

STEP 3 Connect A to C and B to C to complete the triangle, *Figure 4-32D.*

How to Draw an Equilateral Triangle

GIVEN: A baseline and the given length of each side, *Figure 4-33A.*

STEP 1 Either adjust the drafting machine angle to 60° or use a 30°–60° triangle and project



FIGURE 4-32 *(A) How to draw a triangle with known lengths of sides; (B) Step 1; (C) Step 2; (D) Step 3.*



FIGURE 4-33 *(A) How to draw an equilateral triangle; (B) Step 1; (C) Step 2.*

from points A and B at 60° using light lines, *Figure 4-33B*. Allow light construction lines to cross as shown; do not erase them.

STEP 2 Check to see that there are three equal sides and, if so, darken in the actual triangle by using correct line thickness, *Figure 4-33C*. Care should be exercised in constructing the sharp corners. Again, do not erase the light construction lines.

How to Draw a Square

GIVEN: The location of the center and the required distance across the "flats" of a square, *Figure 4-34A*.

STEP 1 Lightly draw a circle with a diameter equal to the distance around the flats of the square. Set the compass at half the required diameter, *Figure 4-34B*.

STEP 2 Using a triangle, lightly complete the square by constructing tangent lines to the circle. Allow the light construction lines to project from the square, as shown, without erasing them, *Figure 4-34C*.

STEP 3 Check to see that there are four equal sides and, if so, darken in the actual square by using the correct line thickness, *Figure 4-34D*. Care should be exercised in constructing the sharp corners. Again, do not erase the light construction lines.



FIGURE 4-34 *(A) How to draw a square; (B) Step 1; (C) Step 2; (D) Step 3.*

Industry Application

A CLASSROOM DEBATE: WHY SHOULD WE LEARN THIS?

The drafting class at Franklin Grove Community College was halfway through its lesson on geometric construction and some of the students were becoming frustrated. "This is the most boring, tedious work I've ever done," said one student. "Why should we learn this when the computer will do it for us anyway?" Overhearing this comment, the instructor, John Diamond, asked the class to stop working and gather around.

This is what he told the class.

"I know that geometric construction can be tedious and boring. I didn't enjoy learning how to make them either when I was a student, but I'm glad I did. I began teaching technical drawing around the time that CADD was in its infancy. Software developers were having problems back then trying to build programs that could create good technical drawings. One problem was that the personal computer hardware of the time had neither the memory nor the processing power to create complex technical drawings. Of course, time and technology would solve this problem."

"Another problem was that computer programmers didn't understand geometric constructions or other technical drawing techniques well enough to write programs that would do what drafting technicians and engineers needed them to do. What they needed was someone who really understood geometric constructions to advise the computer programmers. That's where I became involved. Because I understood geometric constructions to a sufficient level of detail to explain them to computer programmers, I was hired as a consultant. Not only did I make extra money, but I was involved in the original development of one of today's most successful CADD programs."

"You see, it's always better to understand the *why* behind the *how*. Not learning geometric constructions before learning CADD is like not learning mathematical computations before using a calculator. The student who depends on the computer instead of learning fundamentals such as geometric construction will be like the auto mechanic who can only change parts because he does not know how to diagnose the problem."

* The names in this article have been changed to protect privacy.

How to Draw a Pentagon (5 Sides)

GIVEN: The location of the pentagon center and the diameter that will circumscribe the pentagon, *Figure 4-35A*.

STEP 1 Locate point A at the top-center of the circle and, using a drafting machine, position an angle of 72° (360/5) from the horizontal (or 18° from the vertical) through point A to locate point B where the angle crosses the circumference of the circle, *Figure 4-35B*.

STEP 2 Draw a horizontal line from point B to locate point C on the circumference of the circle on the opposite side, *Figure 4-35C*.

STEP 3 Set the compass at the distance from point B to point C, and swing this distance from the points as illustrated in *Figure 4-35D* to locate points X and Y.

STEP 4 Lightly connect the points. Check to see that there are five equal sides and, if correct, darken in the actual pentagon, taking care to construct five sharp corners, *Figure 4-35E*.

How to Draw a Hexagon (6 Sides)

GIVEN: The location of the required center and the required distance across the flats of a hexagon, *Figure 4-36A*.

STEP 1 Lightly draw a circle with a diameter equal to the distance across the flats of the hexagon. Set the compass at half the required diameter, *Figure 4-36B*.

STEP 2 Draw two horizontal lines tangent to the curve, or two vertical lines if the hexagon is to be oriented at 90° to the illustrated position, *Figure 4-36C*.

STEP 3 Using a 30°–60° triangle, lightly complete the hexagon by constructing tangent lines to the circle, *Figure 4-36D*. Allow the light construction lines to extend as shown; do **not** erase them.



FIGURE 4-35 *(A) How to draw a pentagon; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4.*



FIGURE 4-36 *(A) How to draw a hexagon; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4.*

STEP 4 Check to see that there are six equal sides and, if so, darken in the actual hexagon by using correct line thickness and taking care to construct six sharp corners, ***Figure 4-36E.*** Again, do not erase the light construction lines.

How to Draw an Octagon (8 Sides)

GIVEN: The location of the required center and the required distance across the flats of an octagon, ***Figure 4-37A.***

STEP 1 Lightly draw a circle with a diameter equal to the distance across the flats of the octagon.



FIGURE 4-37 *(A) How to draw an octagon; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4.*

Set the compass at half the required diameter, *Figure 4-37B.*

STEP 2 Lightly draw two horizontal lines and two vertical lines tangent to the circle, as illustrated in *Figure 4-37C.*

STEP 3 Using a 45° triangle, lightly complete the octagon by constructing tangent lines to the circle, *Figure 4-37D.* Allow the light lines to extend.

STEP 4 Check that there are eight equal sides and, if so, darken in the actual octagon by using correct line thickness and taking care to construct eight sharp corners, *Figure 4-37E.* Again, do **not** erase the light construction lines.

Circular Construction

How to Locate the Center of a Given Circle

GIVEN: A circle without a center point, *Figure 4-38A.*

STEP 1 Using the drafting machine or T-square, draw a horizontal line across the circle approximately halfway between the **estimated** center of the given circle and the uppermost point on the circumference. Label the end points of the chord thus formed as A and B, *Figure 4-38B.*

STEP 2 Draw perpendicular lines (90°) downward from points A and B. Locate points C and D where these two lines pass through the circle, *Figure 4-38C.*

STEP 3 Carefully draw a straight line from point A to point D and from point C to point B. Where these lines cross is the exact center of the given circle. Place a compass point on the center point; adjust the lead to the edge of the circle and swing an arc to check that the center is accurate, *Figure 4-38D.*

Alternatively, the intersection of perpendicular bisectors of any two nonparallel chords serve to locate the center. This is a modification of the previous construction for passing a circle through any three non-aligned points.

Tangent Points

A *tangent point* is the exact location or point where one line stops and another line begins. Tangent also means to "touch." As an example, a tangent point is the exact point where a curved line stops and a straight line begins, *Figure 4-39.*

How to Locate Tangent Points

The tangent point is a point 90° from the straight line to the swing point of the curved line. Place a light hash mark at each tangent point. It is a good habit to



FIGURE 4-38 *(A) How to locate the center of a given circle; (B) Step 1; (C) Step 2; (D) Step 3.*



FIGURE 4-39 *Tangent points.*

always find all tangent points on the object in all views before darkening in the drawing.

The tangent points for a right-angle bend are illustrated in *Figure 4-40A*. The tangent points for an acute angle bend are illustrated in *Figure 4-40B*. The tangent points for an obtuse angle bend are illustrated in *Figure 4-40C*.

In each preceding example, a light line is constructed 90° from the straight line to the exact swing point of the radius. Find all the tangent points before darkening in the final work. Always darken in all compass work first, followed by the straight lines.

The tangent point between two arcs or circles is the exact point where one arc or circle ends and the next arc or circle begins. The tangent point could also be where one arc or circle touches another arc or circle, *Figure 4-40D*.

The tangent point is found by drawing a straight line from the swing point of the first arc or circle to the swing point of the second arc or circle, *Figure 4-40E*. Place a short, light dash at the exact tangent point.

How to Construct an Arc Tangent to a Right Angle (90°)

GIVEN: A right angle (90°), lines A and B, and a required radius, *Figure 4-41A*.

STEP 1 Set the compass at the required radius and, out of the way, swing a radius from line A and one from line B, as illustrated in *Figure 4-41B*.

STEP 2 From the extreme high points of each radius, construct a light line parallel to line A



FIGURE 4-40 *How to locate tangent points (A) On a right angle; (B) On an acute angle; (C) On an obtuse angle; (D) Between arcs or circles; (E) Tangent points between arcs or circles.*



FIGURE 4-41 *(A) How to construct an arc tangent to a right angle; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Example of an arc tangent to two lines at a right angle.*

and another line parallel to line B, *Figure 4-41C.*

STEP 3 Where these lines intersect is the exact location of the required swing point. Set the compass point on the swing point and lightly construct the required radius, *Figure 4-41D.* Allow the radius swing to extend past the required area, as shown in the figure. It is important to locate all tangent points (T.P.) before darkening in.

STEP 4 Check all work and darken in the radius by using the correct line thickness. Darken in connecting straight lines as required. Always construct compass work first, followed by straight lines. Leave all light construction lines, *Figure 4-41E.*

An example of an arc tangent to two lines at a right angle (90°) is illustrated in *Figure 4-41F.*

How to Construct an Arc Tangent to an Acute Angle (Less than 90°)

GIVEN: An acute angle, lines A and B, and a required radius, *Figure 4-42A.* Follow the same procedure as outlined in the preceding example.

STEP 1 Set the compass at the required radius and, out of the way, swing a radius from line A and one from line B, as illustrated in *Figure 4-42B.*

STEP 2 From the extreme high points of each radius, construct a light line parallel to line A and another line parallel to line B, *Figure 4-42C.*

STEP 3 Where these lines intersect is the exact location of the required swing point. Set the compass point on the swing point and lightly construct the required radius, *Figure 4-42D.* Allow the radius swing to extend past the required area, as shown in *Figure 4-42D.*

STEP 4 Check all work and darken in the radius using the correct line thickness. Darken in connecting straight lines as required. Always construct compass work first, followed by straight lines. Leave all light construction lines, *Figure 4-42E.*

An example of an arc tangent to two lines at an acute angle (22°) is illustrated in *Figure 4-42F.*

How to Construct an Arc Tangent to an Obtuse Angle (More than 90°)

GIVEN: An obtuse angle between lines A and B, and a required radius, *Figure 4-43A.* Follow the same procedure as outlined in the two preceding examples.

STEP 1 Set the compass at the required radius and, out of the way, swing a radius from line A



FIGURE 4-42 *(A) How to construct an arc tangent to an acute angle; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Example of an arc tangent to two lines at an acute angle.*

and one from line B, as illustrated in *Figure 4-43B.*

STEP 2 From the extreme high points of each radius, construct a light line parallel to line A and one parallel to line B, *Figure 4-43C.*

STEP 3 Where these lines intersect is the exact location of the required swing point. Set the compass point on the swing point and lightly construct the required radius. Allow the radius swing to extend past the required area, as shown in *Figure 4-43D.*

STEP 4 Check all work and darken in the radius by using the correct line thickness. Darken in connecting straight lines as required. Always construct compass work first, followed by straight lines. Leave all light construction lines, as shown in *Figure 4-43E.*

An example of an arc tangent to two lines at an obtuse angle (120°) is illustrated in *Figure 4-43F.*

How to Construct an Arc Tangent to a Straight Line and a Curve

GIVEN: Straight line A, an arc B with a center point, and a required radius, *Figure 4-44A.*

STEP 1 Set the compass at the required radius and, out of the way, swing a radius from the



FIGURE 4-43 *(A) How to construct an arc tangent to an obtuse angle; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Example of an arc tangent to two lines at an obtuse angle.*

given arc B and one from the given straight line A, *Figure 4-44B*.

STEP 2 From the extreme high points of each radius, construct a light straight line parallel to line A, and construct a radius outside the given arc B equal to the required radius, as illustrated in *Figure 4-44C*.

STEP 3 Where these lines intersect is the exact location of the required swing point. Set the compass point on the swing point and lightly construct the required radius, *Figure 4-44D*. Allow the radius swing to extend past the required area as shown. Locate all tangent points (T.P.) before darkening in.

STEP 4 Check all work, darken in the radius by using the correct line thickness. Darken in the arcs first and the straight line last, *Figure 4-44E*.

An example of an arc tangent to a straight line and a curve is illustrated in *Figure 4-44F*.

How to Construct an Arc Tangent to Two Radii or Diameters

GIVEN: Diameter A and arc B with center points located, and the required radius, *Figure 4-45A*.

STEP 1 Set the compass at the required radius and, out of the way, swing a radius of the required length from a point on the



FIGURE 4-44 *(A) How to construct an arc tangent to a straight line and a curve; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Example of an arc tangent to a straight line and a curve.*

circumference of given diameter A. Out of the way, swing a required radius from a point on the circumference of a given arc B, *Figure 4-45B.*

STEP 2 From the extreme high points of each radius, construct a light radius outside of the given radii A and B, as illustrated in *Figure 4-45C.*

STEP 3 Where these arcs intersect is the exact location of the required swing point. Set the compass point on the swing point and lightly construct the required radius, *Figure 4-45D.* Allow the radius swing to extend past the required area as shown. Before darkening in, it is important to locate all tangent points (T.P.), *Figure 4-45D.*

STEP 4 Check all work, darken in the radii by using the correct line thickness. Darken in the arcs or radii in consecutive order from left to right or from right to left, thus constructing a smooth connecting line having no apparent change in direction, *Figure 4-45E.*

An example of an arc tangent to two radii is illustrated in *Figure 4-45F.*

How to Draw an Ogee Curve

An *ogee curve* is used to join two parallel lines. It forms a gentle curve that reverses itself in a neat, symmetrical geometric form.



FIGURE 4-45 *(A) How to construct an arc tangent to two radii or diameters; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Example of an arc tangent to two radii.*

GIVEN: Parallel lines A-B and C-D, *Figure 4-46A.*

STEP 1 Draw a straight line connecting the space between the parallel lines. In this example, from point B to point C, *Figure 4-46B.*

STEP 2 Make a perpendicular bisector to line B-C to establish point X, *Figure 4-46C.*

STEP 3 Make perpendicular bisectors to the lines B-X and X-C, *Figure 4-46D.*

STEP 4 Draw a perpendicular from line A-B at point B to intersect the perpendicular bisector of B-X, which locates the first required swing center. Draw a perpendicular



FIGURE 4-46 *(A) How to draw an ogee curve; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5; (G) Step 6.*

from line C-D at point C to intersect the perpendicular bisector of C-X, which locates the second required swing center, *Figure 4-46E.*

STEP 5 Place the compass point on the first swing point, adjust the compass lead to point B, and swing an arc from B to X. Place the compass point on the second swing point and swing an arc from X to C, *Figure 4-46F.* This completes the ogee curve.

NOTE: Point X is the tangent point between arcs. Check and, if correct, darken in all work.

An example of an ogee curve is illustrated in *Figure 4-46G.*

Conic Sections

A *conic section* is a section cut by a plane passing through a cone. These sections are bounded by various kinds of shapes. Depending upon where the section is cut, the shape can be a triangle, a circle, an ellipse, a parabola or a hyperbola, *Figures 4-47A* through *4-47E*.

Triangle

Figure 4-47A. This shape results when a plane passes through the apex of the cone.

Circle

Figure 4-47B. This shape results when a plane passes through the cone, parallel with the base and perpendicular to the axis.



FIGURE 4-47 *(A) Triangle section; (B) Circle section; (C) Ellipse section; (D) Parabola section.*



FIGURE 4-47 *(Continued) (E) Hyperbola section.*

Ellipse

Figure 4-47C. This shape results when a plane passes through the cone inclined to the axis.

Parabola

Figure 4-47D. This shape results when a plane passes through the cone parallel to one element.

Hyperbola

Figure 4-47E. This shape results when a plane passes through the cone parallel with the axis of the cone.

How to Draw an Ellipse, Concentric Circle Method

GIVEN: The location of the center point, the major diameter, and the minor diameter, *Figure 4-48A.*

STEP 1 Lightly draw one circle equal to the major diameter and another circle equal to the minor diameter, *Figure 4-48B.*

STEP 2 Divide both circles into 12 equal divisions by passing lines through the center at every 30°. Number points 1 through 5 in clockwise consecutive order on the major diameter, positioning the 3 location on the right horizontal axis. Number points 7 through 11 in clockwise consecutive order, positioning the 9 location on the left horizontal axis. Point 6 is on the lower vertical axis at the minor diameter, and point 12 is on the upper vertical axis at the minor diameter, *Figure 4-48C.* If the ellipse were to be positioned at 90° from this example, the point locations would be rotated accordingly.

STEP 3 Project down from point 1 on the major diameter and to the right from point 1 on the minor diameter. Where these lines intersect is the exact location where point 1 will be on the ellipse, *Figure 4-48D.*

STEP 4 Project down from point 2 on the major diameter and to the right from point 2 on the minor diameter. Where these lines intersect is the exact location where point 2 will be on the ellipse, *Figure 4-48E.*

STEP 5 This completes the first quadrant of the ellipse. Continue around the circle to locate points 4, 5, 6, 7, 8, 9, 10, and 11 in the same manner, except in reverse, *Figure 4-48F.*

STEP 6 Lightly draw straight lines connecting points 1 through 12 in order to get a general idea of the ellipse outline, *Figure 4-48G.*

STEP 7 Darken in the ellipse by using an irregular curve. Carefully connect all the points with a smooth, continuous line of the correct thickness, *Figure 4-48H.* It is sometimes helpful to divide into 10° or 15° spaces the two ends where the ellipse curves the fastest in order to have more points around the extreme ends. In this example, this is done between points 2 and 4, and 8 and 10.

Examples of ellipses are illustrated in *Figure 4-48,* showing how a rotated circle would look at 0°, 15°, 45°, 60°, and 90°.

How to Draw a Trammel Ellipse

GIVEN: A major or minor axis of a required ellipse, and any located point through which the ellipse must pass, *Figure 4-49A.* If a major axis is given, mark the end points A and B. If the minor axis is given, as is shown in the figure, mark the end points C and D. Mark as P the known location of where the ellipse must pass.

STEP 1 Draw a perpendicular bisector of the given axis to locate the unknown axis position, crossing the known axis at a point that will become 0, *Figure 4-49B.*



FIGURE 4-48 *(A) How to draw an ellipse (concentric method); (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5; (G) Step 6; (H) Step 7; (I) Example of ellipses at various degrees.*

STEP 2 Mark an end corner of a separate strip of paper as point 0, and mark along the edge of the strip one-half of the distance A-B or C-D, whichever is known. Mark this point on the strip as A' or C' to correspond to the known axis, ***Figure 4-49C***. Position the strip so that point 0 lies on the known point through which the ellipse must pass.



FIGURE 4-49 *(A) Trammel ellipse; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5.*

Position the other strip mark on the axis that is not represented by the half-length on the strip, at the position (of two possible positions) that is nearest to the ellipse center.

STEP 3 With the strip positioned as specified in Step 2, mark the strip where it crosses the other axis. The length of end point 0 to this new position represents one-half of the unknown axis length, and it should correspondingly be labeled as A′ or C′, *Figure 4-49D.*

STEP 4 Using the two marked strip locations, reposition the strip so that the mark representing one-half of the major axis always lies on the minor axis, and the mark representing one-half of the minor axis always lies on the major axis. Repeat as needed to establish enough points for constructing the ellipse, *Figure 4-49E.*

STEP 5 Using a French curve, pass a smooth line through each of these established points, *Figure 4-49F.*

How to Draw a Foci Ellipse

GIVEN: Major and minor axes of a required ellipse. The end points of the major axis are labeled A and B, the end points of the minor axis are labeled C and D, and the ellipse center is labeled 0, *Figure 4-50A.*



FIGURE 4-50 *(A) How to draw a foci ellipse; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5; (G) Step 6.*

STEP 1 Swing a radius of one-half of the major axis (0A) from the end point of the minor axis (C or D) to locate the focal points E and F at the points where the arc crosses the major axis, *Figure 4-50B.*

STEP 2 Select a random array of points on the major axis between one focal point and the ellipse center. (Space those at the ends more closely.) Number these in consecutive order, *Figure 4-50C.*

STEP 3 Swing an arc whose radius is the distance from point B to number 1. Swing this distance from focal point F. Intersect this arc with an arc whose radius is the distance from point A to the same numbered point, number 1 in this example, but whose center is at focal point E, *Figure 4-50D.*

STEP 4 Repeat Step 3, but reverse the focal point positions of the arc centers, *Figure 4-50E.*

STEP 5 Repeat Steps 3 and 4 for each point selected in Step 2, *Figure 4-50F.*

STEP 6 Connect the points into a smooth curve by using a French curve, *Figure 4-50G.*

How to Locate the Major and Minor Axes of a Given Ellipse with a Located Center

GIVEN: An ellipse, with center 0 located, *Figure 4-51A.*

STEP 1 From the ellipse center 0, draw a circle at a radius that allows intersecting the ellipse at any four locations. Label these points in successive order 1, 2, 3, and 4, moving clockwise around the ellipse center, *Figure 4-51B.*

STEP 2 Draw a rectangle by connecting each of the labeled points in successive order. As shown in *Figure 4-51C,* the major and minor axes are parallel to these sides, found by drawing perpendicular bisectors of two consecutive sides.

STEP 3 Draw the major and minor axes parallel to sides 1-2 and 2-3 through point 0, *Figure 4-51D.*



FIGURE 4-51 *(A) How to locate the major and minor axes of a given ellipse; (B) Step 1; (C) Step 2; (D) Step 3.*



FIGURE 4-52 *(A) How to draw a tangent to an ellipse at a point on the ellipse; (B) Step 1; (C) Step 2; (D) Step 3.*

How to Draw a Tangent to an Ellipse at a Point on the Ellipse

GIVEN: An ellipse and a point P on its perimeter, *Figure 4-52A*. If not provided, locate the major axis A-B, minor axis C-D, and focal points E and F.

STEP 1 Draw E-P and F-P, *Figure 4-52B*.

STEP 2 Bisect the angle EPF, *Figure 4-52C.*

STEP 3 Draw a perpendicular to the angle bisector of angle EPF at point P. This is the required tangent, *Figure 4-52D.*

How to Draw a Tangent to an Ellipse from a Distant Point

GIVEN: An ellipse and a distant point P, *Figure 4-53A.*

STEP 1 If not provided, locate the major axis A-B and focal points E and F, *Figure 4-53B.*

STEP 2 Swing an arc R1 from point P to pass through either focal point. F is selected for this example, *Figure 4-53C.*

STEP 3 Swing an arc whose radius is equal to the major axis from the other focal point (E in this example). Intersect the arc from Step 2 at points R and S, *Figure 4-53D.*



FIGURE 4-53 *(A) How to draw a tangent to an ellipse from a distant point; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5.*

STEP 4 Extend the lines from E to each of points R and S to cross the ellipse at U and V, *Figure 4-53E*.

STEP 5 The two possible points of tangency of the two possible lines from point P are U and V. Select and draw either, or both, *Figure 4-53F*.

How to Draw a Parabola (Method 1)

GIVEN: The front view and plan view of cone ABC with cutting plane X-Y, *Figure 4-54A*.

STEP 1 Locate points Y′ and Y″ in the plan view. In the front view, place the point of the compass on point Y and position the lead on point X. Swing point X to the extended baseline and down into the plan view, as illustrated in *Figure 4-54B*.

STEP 2 Locate a point along line X-Y (in this example, point D) and, using point Y as a swing point, swing point D to the extended baseline and down into the plan view. In the front view, reset the compass to a distance equal to the horizontal distance from the cone axis to the outer edge (identified as length 1), illustrated in *Figure 4-54C*.



FIGURE 4-54 *(A) How to draw a parabola (method 1); (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4.*

Transfer this distance to the plan view. Project point D down into the plan view and, where point D intersects the arc, locate points D′ and D″. Project these points to the right, intersecting with point D from above at the actual intersection points D′ and D″.

STEP 3 Choose other points along line X-Y in the front view and project them over and down as described in Step 2, *Figure 4-54D.*

STEP 4 Using an irregular curve, connect all points. This completes the parabola, *Figure 4-54E.*



FIGURE 4-55 *(A) How to draw a parabola (method 2); (B) Step 1; (C) Step 2; (D) Step 3.*

How to Draw a Parabola (Method 2)

GIVEN: Required rise A-B, and required span A-C. *Problem:* Construct a parabola within the required rise and span, *Figure 4-55A.*

STEP 1 Divide half the span distance A-0 into any number of equal parts. (In this example, 4 equal parts are used.) See *Figure 4-55B.* Divide half the rise A-B into equal parts amounting to the square of the equal parts in Step 1 (in this example, 42 = 16 equal parts).

STEP 2 From line A-0, each point on the parabola is offset by a number of units equal to the square of the numbers of units from point 0, *Figure 4-55C.* For example, point 1 projects 1 unit; point 2 projects 4 units; point 3 projects 9 units, and so forth.

STEP 3 Using an irregular curve, connect the points to form a smooth parabolic curve, *Figure 4-55D.*

How to Find the Focus Point of a Parabola

GIVEN: A parabolic curve with points A, 0, and B, *Figure 4-56A. Problem:* Find the focus point of the parabola A0B.



FIGURE 4-56 *(A) How to find the focus point of a parabola; (B) Step 1; (C) Step 2.*

STEP 1 Draw a line from point A to point B. Continue the center line to a point equal to length X, distance Y, to find point C, *Figure 4-56B.*

STEP 2 Draw a line from point C to point A and bisect it. The intersection of the bisect line and the axis is the focus of the parabola, *Figure 4-56C.*

How to Draw a Hyperbola (Method 1)

GIVEN: The front view and plan view of cone ABC with cutting plane X-Y, *Figure 4-57A.*

STEP 1 Locate points Y′ and Y″ in the plan view. In the front view, place the point of the compass on point Y and set the lead to point X. Swing point X to the extended baseline and down to the plan view, as illustrated in *Figure 4-57B.*

STEP 2 Locate a point along line X-Y (in this example, point D). Using Y as a swing point, swing point D to the extended baseline and down into the plan view. In the front view, reset the compass to a distance equal to the horizontal distance from the cone axis to



FIGURE 4-57 *(A) How to draw a hyperbola (method 1); (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4.*

the outer edge (length 1), as illustrated in *Figure 4-57C*. Transfer the arc to the plan view; where the arc intersects with the cutting plane line X-Y, project to the right, and where these points intersect with point D from above is the actual location of points D′ and D″.

STEP 3 Choose other points along line X-Y in the front view and project them over and down as described in Step 2, ***Figure 4-57D***.

STEP 4 Using an irregular curve, connect all points. This completes the hyperbola, *Figure 4-57E*.

How to Draw a Hyperbola (Method 2)

GIVEN: Coordinates, a square whose sides equal the transverse axis, and points A and B, *Figure 4-58A*.

STEP 1 With the center at the intersection of the diagonal lines from opposite corners of the square, place the compass lead at the corner of the given square and swing arcs to intersect the horizontal line through the center. This locates focus A and focus B. Progressing outward along the horizontal line, mark off equal spaces of arbitrary length from the focus points, *Figure 4-58B*.

STEP 2 Set the compass at dimension X (A-1) and swing an arc from focus A. Set the compass at dimension Y (B-1) and swing an arc from focus B, *Figure 4-58C*.

STEP 3 Follow the same procedure for as many points as are required (in this example, six points). Set the compass at distance A-2 and swing from focus A. Set the compass at distance B-2 and swing from focus B, and so on, *Figure 4-58D*.

STEP 4 Using an irregular curve, carefully complete the hyperbola curve, *Figure 4-58E*.



FIGURE 4-58 *(A) How to draw a hyperbola (method 2); (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4.*



FIGURE 4-59 *(A) How to join two points by a parabolic curve (given: 90° angle); (B) Given: Less than 90° angle; (C) Given: More than 90° angle; (D) Step 1; (E) Step 1; (F) Step 1; (G) Step 2; (H) Step 2; (I) Step 2.*

How to Join Two Points by a Parabolic Curve

GIVEN: Points X and Y with 0 an assumed point of tangency, *Figures 4-59A, 4-59B,* and *4-59C.*

STEP 1 Divide line X-0 into an equal number of parts; divide 0-Y into the same number of equal parts, *Figures 4-59D, 4-59E,* and *4-59F.*

STEP 2 Connect corresponding points, *Figures 4-59G, 4-59H,* and *4-59I.* Using an irregular curve, draw the parabolic curve as a smooth, flowing curve.

Supplementary Construction

How to Draw a Spiral

GIVEN: Crossed axes, *Figure 4-60A.*

STEP 1 Divide the circle into equal angles (in this example, 30°). Set the compass at a required



FIGURE 4-60 *(A) How to draw a spiral.*



FIGURE 4-60 *(Continued) (B) Step 1; (C) Step 2.*

radius and draw various diameters to suit, evenly spaced, as illustrated in ***Figure 4-60B***.

STEP 2 Starting any place along the angles, step over one angle and up one diameter until the required spiral is completed, ***Figure 4-60C***.

How to Draw a Helix

A *helix,* a form of spiral, is used in screw threads, worm gears, and spiral stairways, to mention but a few uses. A helix is generated by moving a point around and along the surface of a cylinder with uniform angular velocity about its axis. A *cylindrical helix* is simply known as a helix, and the distance measured parallel to the axis traversed by a point in one revolution is called the *lead.*

GIVEN: The top and front views of a cylinder with a required lead, ***Figure 4-61A***.

STEP 1 Divide the top view into an equal number of spaces (12 in this example). Draw a line equal to one revolution and/or circumference, project the lead distance from the end, and label all points per ***Figure 4-61B***.



FIGURE 4-61 *(A) How to draw a helix; (B) Given views.*



FIGURE 4-61 *(Continued) (C) Steps 1 and 2; (D) and (E).*

STEP 2 Divide the circumference into the same amount of equal spaces, and project each from the inclined line to the corresponding point projected from the front view, *Figure 4-61C.*

STEP 3 Connect all points of the helix, and draw as hidden lines the lines that would disappear from view on an actual helix form, *Figure 4-61D.* Notice that a right-hand helix is illustrated. To construct a left-hand helix, simply project all the points in the opposite direction, *Figure 4-61E.*

How to Draw an Involute of a Line

The curved path of a point on a string as it unwinds from a line, a triangle, a square, or a circle is an *involute.* The involute is used to construct involute gears. The involute forms the face and part of the flank of the teeth of the gear.

GIVEN: Line A-B, *Figure 4-62A.*



FIGURE 4-62 *(A) How to draw an involute of a line; (B) Step 1.*

STEP 1 Extend line A-B, as illustrated in *Figure 4-62B*. Set the compass at the length A-B, and, using point B as the swing point, swing semicircle A-C. With the compass set at length A-C, and, using point A as the swing point, swing semicircle A-D. Continue in this manner, alternating between points A and B until the required involute is completed, as shown in the figure.

How to Draw an Involute of a Triangle

GIVEN: Triangle ABC, *Figure 4-63A*.

STEP 1 Extend straight lines from the triangle, as illustrated in *Figure 4-63B*. Set the compass at length A-C, and, using point A as the swing point, swing semicircle A-C. With the compass set at length B-D, and, using point B as the swing point, swing semicircle B-E. Continue similarly around the triangle until the required involute is completed, as shown in the figure.

How to Draw an Involute of a Square

GIVEN: Square ABCD, *Figure 4-64A*.

STEP 1 Extend straight lines from the square, as illustrated in *Figure 4-64B*. Set the compass at length A-B, and using point A as the swing point, swing semicircle A-E. With the compass set at length B-E, and, using point B as the swing point, swing semicircle B-F. Continue in the same manner around the square until the required involute is completed, as shown in the figure.

How to Draw an Involute of a Circle

GIVEN: Circle A, *Figure 4-65A*.

STEP 1 Divide the circle into a number of equal parts and number each point clockwise around the circle (in this example, 12 equal parts). Project a line perpendicular to the radius at each point in a clockwise direction, *Figure 4-65B*.



FIGURE 4-63 *(A) How to draw an involute of a triangle; (B) Step 1.*



FIGURE 4-64 *(A) How to draw an involute of a square; (B) Step 1.*



FIGURE 4-65 *(A) How to draw an involute of a circle; (B) Step 1; (C) Step 2.*

STEP 2 Set the compass at length 1-2, and, using point 2 as the swing point, swing semicircle 1-2. With the compass set at length 1-2 plus 2-3, and, using point 3 as the swing point, swing semicircle 1-3. Continue in the same manner around the circle until the required involute is completed, as shown in *Figure 4-65C.*

How to Draw a Cycloidal Curve

GIVEN: A required span of a cycloid.

STEP 1 As the span represents the rolling distance of one revolution of a diameter, divide the span length by π to find the required diameter. Divide the span into an equal number of divisions. Twelve is a convenient number, *Figure 4-66A.*

STEP 2 Draw the rolling diameter tangent to the given span at point 0/12. Divide this diameter into the same number of equal spaces as in the Step 1 span division. Consecutively number the radial end points of these divisions to make them meet their corresponding number of the span divisions as the diameter rolls along the span, *Figure 4-66B.*

STEP 3 At each span division draw the rolling diameter tangent to the span in the rolled position, with the division numbers of span and diameter matching at their contact point. Locate the point 0/12 position on the diameter at each of these locations, marked with a small cross, *Figure 4-66C.*

STEP 4 Connect all the point 1 diameter division positions with a smooth curve to complete the cycloidal curve, *Figure 4-66D.*

NOTE: If the given span is a concave arc, a hypocycloid will be drawn, Figure 4-67. If the span is convex, an epicycloid will be drawn, Figure 4-68.



FIGURE 4-66 *(A) How to draw a cycloidal curve Step 1; (B) Step 2; (C) Step 3; (D) Step.*



FIGURE 4-67 *A hypocycloid.*



FIGURE 4-68 *An epicycloid.*

Summary

- Geometric nomenclature primarily of the following concepts: points in space, line, angle, triangle, polygon, quadrilateral, circle, polyhedron, prism, pyramid, cone, and sphere.
- Elements and polygon construction principles consist primarily of how to do the following: bisect a line, bisect an angle, draw an arc or circle through three points, draw a line parallel to a straight line at a given distance, draw a line perpendicular to a line at a point, draw a line parallel to a curved line at a given distance, draw a perpendicular to a line from a point not on the line, divide a line into equal parts, divide a line into proportional parts, transfer an angle, transfer an odd shape, transfer complex shapes, proportionately enlarge or reduce a shape, draw a triangle with sides of known length, draw a square, draw a pentagon, and draw a hexagon.
- Circular construction consists primarily of knowing how to do the following: locate the center of a given circle; construct an arc tangent to a right angle, an acute angle, an obtuse angle, a straight line, a curve, and two radii or diameters; draw an ogee curve; draw an ellipse using the concentric circle method; draw a trammel ellipse; draw a foci ellipse; locate the major and minor axes of a given ellipse with a located center; draw a tangent to an ellipse at a point on the ellipse and from a distance point; draw a parabola; find the focus point of a parabola; draw a hyperbola; and join two points by a parabolic curve.
- Supplementary constructions require knowing how to do the following: draw a spiral; draw a helix; draw an involute of a line, triangle, square, and circle; and draw a cycloidal curve.

Review Questions

Answer the following questions either true or false.

1. A right angle is an angle of 90°. T
2. An acute angle is an angle at more than 90°.
3. An obtuse angle is an angle at more than 90°. F
4. There are six types of polygons. T
5. Geometric construction procedures are not particularly important to the drafter. F
6. Lines that are tangent and at 90° are considered perpendicular.

Answer the following questions by selecting the best answer.

1. Which of the following is not a part of a circle?
   a. Angle
   b. Center
   c. Sector
   d. Quadrant
2. Which of the following is true regarding a line?
   a. The shortest distance between two points
   b. Can be drawn in any direction
   c. Can be straight, an arc, a circle, or a free curve
   d. All of the above
3. Which of the following is true regarding the sum of three internal angles of a triangle?
   a. Always exactly 180°
   b. Always half of the 360° in a full circle
   c. Equal to half the sum of the three straight sides
   d. Both a and b
4. The circumference of a circle can be calculated by:
   a. Multiplying π by the diameter of the circle
   b. Dividing the diameter of the circle by π
   c. Multiplying π by 2 times the radius
   d. Both a and c
5. Which of the following is not a kind of triangle?
   a. Equilateral
   b. Obtuse
   c. Quadrilateral
   d. Scalene
6. A point in space is represented on a drawing by:
   a. A crisscross at its exact location
   b. A dot at its exact location
   c. A crossbar on an existing line
   d. Both a and c
7. Which of the following is **not** true regarding concentric and eccentric circles?
   a. Concentric circles have a common center point.
   b. Eccentric circles have no common center point.
   c. Concentric circles have no common center point.
   d. Two or more circles with a common center point are called concentric.
8. Which of the following is not true regarding an angle?
   a. There are three major types of angles.
   b. There are four major types of angles.
   c. An obtuse angle is one of the major types of angles.
   d. An angle is formed by two intersecting lines.

Chapter 4 Problems

Conventional Instructions

The following problems are intended to give the beginning student practice in the many geometric construction techniques used to develop drawings. Accuracy, line work, neatness, speed, and centering are stressed. It is recommended that dimensions not be added to problems at this time. The beginning student should practice using drafting instruments and correct line thicknesses, and should concentrate on developing good drafting habits.

The steps to follow in laying out all drawings throughout this book are:

STEP 1 All geometric construction work should be made very accurately using a sharp 4H lead.

STEP 2 All geometric construction work must be laid out very lightly.

STEP 3 Do **not** erase construction lines. If constructed lightly, they will not be seen on the whiteprint copy.

STEP 4 Make a rough sketch of each problem before beginning to calculate the overall shape.

STEP 5 Lightly draw each problem completely first.

STEP 6 Locate all tangent points as you proceed. Make short, light dashes at each tangent point.

STEP 7 Try to center the problem in the work area.

STEP 8 Check each dimension for accuracy.

STEP 9 Darken in the drawing by using the correct line thickness and the following steps:

- Locate and draw all center lines with a thin black line.
- Darken in all diameters by using a compass.
- Darken in all radii by using either a compass or a circle template.
- Darken in all horizontal lines, either from right to left or from left to right.
- Recheck all dimensions.
- Check all lines for correct thickness.
- Fill out the title block by using light guidelines and neat lettering.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, and then begin the project.

PROBLEM 4-1

Triangular spaces are utilized for rigidity in frames and trusses. The scissors truss shown is typical of trusses premade for house construction. Using the dimensions and slopes given, lay out an approximate truss and determine approximate lengths of the 2 × 4s. Assume that a lumber store near you has 2 × 4s in stock in 8-, 10-, 12-, and 16-foot lengths. How many and what lengths of 2 × 4s are needed? (Note that the actual dimensions of standard 2 × 4s are $1\frac{1}{2}'' \times 3\frac{1}{2}''$.) Approximately what percentage of the lumber is wasted?



NOTE: SPECIAL GUSSET PLATES (NOT SHOWN) ARE USED AS JOINTS

PROBLEM 4-2

The given drawing shows preliminary measurements to determine the distance across the river from line AB to the outcropping of rock on the other side. Using the information given, calculate the shortest distance from the 1,000′-long line to the rocks.



PROBLEM 4-3

The following X,Y coordinates in feet for determining the border of an oddly shaped parcel of property are as follows: A(0,0), B(110,–30), C(190,0), D(130,40), E(130,110), F(0,60). You are given the task of determining the area of the parcel. Suggestion: Lay out the parcel to scale and divide the parcel into convenient areas for calculating.

PROBLEM 4-4

The rectangular frame shown needs a diagonal to ensure the frame's rigidity. The frame is made up of $3 \times 3 \times 1/4$ structural steel angles and 1/4″ steel gusset plates. Thirty-five frames are to be made. Your task is to lay out the frame to the dimensions given and determine the length of the diagonal based on information given in the drawing. Then assume that the standard length of available structural angles is 20′ and determine how many 20′ lengths are required for the 35 frames. What percentage of the structural angles will probably be wasted?



PROBLEM 4-5

A ski slope designer made the sketch shown, which shows contour lines for a particular portion of a ski run. The numbers on the lines are elevations in feet, and A is 100′ from B in a horizontal direction. You are requested to determine the angle and percentage slope of the terrain between A and B.



PROBLEM 4-6

Calculate the volume of the notched tubular object shown by utilizing equations for the areas of segments of a circle. Then calculate the weight of the object by multiplying the volume by the density of the material.



STEEL 0.28 lb/in^3

PROBLEM 4-7

Construct an ellipse using the concentric circle method shown in Figure 4-48. Minor diameter = 25 mm. Major diameter = 40 mm.

PROBLEM 4-8

Divide the work area into four equal spaces. In the upper left-hand space, draw an inclined line 3.25″ long. Bisect this line. Show all construction lines lightly.

In the upper right-hand space, draw an acute angle with intersecting lines, each approximately 2.75″ long. Bisect this angle. Show all light construction lines.

In the lower left-hand space, draw an inclined line 2.88″ long. Divide this line into five spaces. Show all light construction lines.

In the lower right-hand space, draw an inclined line 3.125″ long. Divide this line into three proportional parts 2, 3, and 4. Show all light construction lines.

PROBLEM 4-9

Divide the work area into four equal spaces. In the center of the upper left-hand space, draw an equilateral triangle having sides of 2.0. Bisect the interior angles. Show all light construction lines.

In the center of the upper right-hand space, draw a square having sides of 2.0. Show all light construction lines.

In the center of the lower left-hand space, draw a hexagon having the distance of 2.0 across the flats. Show all light construction lines.

In the center of the lower right-hand space, draw an octagon having the distance of 2.0 across the flats. Show all light construction lines.

PROBLEM 4-10

Divide the work area into four equal spaces. In the upper left-hand space, draw two lines intersecting at 60° and draw an arc with a .88 radius tangent to the two lines. Show all light construction lines.

In the upper right-hand space, draw two lines intersecting at 120° and draw an arc with a .625 radius tangent to the two lines. Show all light construction lines.

In the lower left-hand space, draw two lines intersecting at 90° and draw an arc with 1.25 radius tangent to the two lines. Show all light construction lines.

In the lower right-hand space, draw an ellipse with a major diameter of 3.00 and a minor diameter of 1.75.

PROBLEM 4-11

Divide the work area into four equal spaces. In the upper left-hand space, center a line 10 mm long and label it line A-B. Construct a straight line involute with five arcs.

In the upper right-hand space, center a triangle with sides equal to .25 and label the triangle ABC. Construct a triangular involute with five arcs.

In the lower left-hand space, center a square with sides equal to 10 mm and label the square ABCD. Construct a square involute with five arcs.

In the lower right-hand space, center a circle with a diameter of 1.00. Construct a circle involute with as many arcs as space will allow.

PROBLEM 4-12

Divide the work area into four equal spaces. In the center of the upper left-hand space draw a spiral with 30° spaces, at 4 mm increments, for one 360° rotation. In the center of the upper right-hand space, draw two lines at right angles intersecting a point 0. One line is to be 3.5″ long, and the other 2.5″ long. Draw a parabolic curve between these two lines.

In the center of the lower left-hand space, draw a rectangle 2.0″ × 4.50″ in size. Label the 2.0″ side as the rise and the 4.50″ as the span. Construct a parabola (Method 2) and locate the focus point.

In the center of the lower right-hand space, draw a line 80 mm long, and label its end points A and B. Locate a point on line A-B at 5/8 of the line's length from point A. Label the point X.

Problems 4-13 through 4-26

Using the art for Problems 4-13 through 4-26, center each object within the work area using correct line thickness.

Do not erase light construction lines.

Locate and draw a light, short dash at all tangent points. Do not dimension objects.

PROBLEM 4-13



PROBLEM 4-14



PROBLEM 4-15



PROBLEM 4-16



PROBLEM 4-17



PROBLEM 4-18



PROBLEM 4-19



PROBLEM 4-20



PROBLEM 4-21



PROBLEM 4-22



PROBLEM 4-23



PROBLEM 4-24



PROBLEM 4-25



PROBLEM 4-26



Problems 4-27 through 4-32

On an A-size sheet of vellum, carefully construct each of the assigned figures. Use thin, black center lines and thick, black object lines. Leave all light construction work. Do not add dimensions.

PROBLEM 4-27



PROBLEM 4-28



PROBLEM 4-29



PROBLEM 4-30



PROBLEM 4-31



PROBLEM 4-32



PROBLEM 4-33

Design and lay out to scale a clock face to match your interest(s) in technology.

PROBLEM 4-34

Find a logo for one of the following. Prepare a drawing of it.

- **a.** an automobile
- **b.** a computer company
- **c.** an airline
- **d.** a product of your choice
- **e.** an organization

PROBLEM 4-35

Refer to the figures indicated in this chapter and do the following:

- **a.** Figure 4-22—Draw a curve parallel to a curve similar to the lower edge of the object for Problem 4-9.
- **b.** Figure 4-30—Reproduce the drawing for Figure 4-30 and transfer it.
- **c.** Figure 4-46—Change the spacing of lines A-B and C-D and draw an ogee curve to join them.
- **d.** Figure 4-61—Draw the helix shown.
- **e.** Figure 4-65—Follow the steps and draw an involute curve.

NOTE: The involute curve is the basis for the profiles of spur gears and helical gears.

- **f.** Figure 4-68—Construct the epicycloid shown.

PROBLEM 4-36

The golden section shown is attributed to the Greeks who used it as a guide to create pleasing proportions for architecture, sculpture, and pottery. Three nested golden sections can be formed by following the construction pattern shown. Note that the ratio of the sides of each golden rectangle is 1.618 to 1.

(2.618)/(1.618) = 1.618; and (4.236)/(2.618) = 1.618

(For interest, check the ratios of the sides of credit cards and some food packaging.) Refer to the following figure and reconstruct the three golden rectangles. Then lay out some shelves for a living room for books and hi-fi equipment. Include vertical dividers that incorporate the golden section proportions.



PROBLEM 4-37

The freehand sketch given shows a format for a typical classroom engineering problem statement and solution. On a sheet of 8 ½ × 11″ (A-size) paper redo the statement (GIVEN and FIND) and the solution. Use a straightedge for the sketch and diagrams and good lettering style for the statement and solutions.



PROBLEM 4-38

You have been asked to help an individual lay out a tentative plan for a service garage with parking facilities. The commercially zoned lot measures 25 m × 35 m. Sketch no. 1 shows a preferred arrangement of the service-pits building with parking. Lay out the lot using the given information. Use a scale to make the best use of an A-size drawing.



SKETCH NO. 1



ENVELOPE OF SPACE REQUIRED PER PIT



PARKING SLOT GEOMETRY

SECTION 2

Technical Drawing Fundamentals

5 Spatial Visualization and Multiview Drawings

6 Sectional Views

7 Auxiliary Views

8 Descriptive Geometry

9 Patterns and Developments

10 Dimensioning and Notation

11 Solid/3D Modeling: Computational Design and Analysis

Career Profile

ALEXANDER TORRES

Graduating with a master's degree in fine arts, Alexander Torres thought he might become a painter—but then reality (and bills!) set in. Having studied technical drawing in high school and then gone on to get a degree in engineering and drafting, he knew that he *did* have experience in a more lucrative field.

Using the skills learned in college and high school, he started doing illustrations and flowcharts for companies like Lockheed Martin. After a few years, he found his way into magazine work, which required both his drafting skills and his artistry.

Today, as a technical illustrator for *TK* magazine, he often has to create drawings that communicate the ideas explained in an article. The function of these schematics is part artistic (to illustrate the point: He recently used drafting software to draw a candy bar, to metaphorically show that when working with motherboards you need to break it into its components) and part functional (the art must often explain complex parts of computers in ways that mere text cannot).

On this day, he has just been handed an article about circuit boards. His first move in planning the drawing: Read the abstract. He will then go over the concept with the editors to find out what they are looking for—do they want a dynamic look (in which case he might present an orthographic projection) or true representation? If the latter, what focal point should he take? In drawing something like this, he tries to look at the real thing. If he doesn't have it accessible at home, he will search the Internet. These will help him to visualize the drawing that he is about to do. Then Torres does a pencil sketch, organizing the information so that it will work in a rectilinear format.

He will then plug in numbers into Infinity, a computer drafting system that allows him to build in 3D—a benefit because then he can move the point of view of the camera as needed. Sometimes he may decide that a fisheye view will help the object jump off the page; other times he must stick with the realistic focal point. Either way, the artist in him tries to ensure that the final product will not be merely technical and accurate, but also an element that draws the reader into the magazine.

5

Spatial Visualization and Multiview Drawings

CHAPTER OUTLINE

Spatial visualization • Orthographic projection • Planning the drawing • Sketching procedure • Centering the drawing • Technical drawing conventions • Visualization • First-angle projection • Summary • Review questions • Chapter 5 Problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the concept of spatial visualization.
- Demonstrate proficiency in the use of spatial visualization.
- Demonstrate proficiency in the use of orthographic projection.
- Demonstrate proficiency in all five steps of planning a drawing.
- Demonstrate proficiency in centering a drawing.
- Demonstrate proficiency in making proper use of technical drawing conventions.
- Demonstrate proficiency in applying visualization techniques.
- Explain the difference between third- and first-angle projections.

KEY TERMS

Blind hole
Conventional break
Counterbored hole
Countersunk hole
Fillets
Fold line
Foreshortening
Front view
Hidden lines
Orthographic projection
Perspective projection
Principal viewing planes
Right-side view
Rounds
Runouts
Spatial visualization
Spotfaced hole
Tapered hole
Through hole
Top view

Drafters, designers, and engineers follow a design process to solve technical product problems and use technical drawings to document and develop their ideas. The steps in the process leading to the technical drawings, primarily working drawings, were noted in the general comments in the Introduction. In Chapter 2, the drawing tools used to prepare the drawings were discussed, followed by another chapter that emphasized the first format drafters, designers, and engineers use to record their ideas, sketching techniques. This chapter focuses on the ever-present challenge to a design person to prepare multiview drawings, to scale, of technical, three-dimensional concepts on a two-dimensional surface so that the users of the drawings will clearly understand, in three dimensions, what the design person had in mind, and have sufficient information to accurately produce the concept.

Providing accurate shape descriptions of objects by drawing methods requires that three-dimensional object information be presented in a flat, two-dimensional drawing space. This is usually done by drawing images of the object from multiple directions. Commonly shared methods and interpretations are essential for all who make or use such drawings. Technical drawings seldom use more than lines to outline an object's features. Visual qualities, such as color and texture, are more accurately specified by written requirements.

Viewing an object by eye creates a depth distortion. This phenomenon is recreated in a field of drawing called *perspective projection*, ***Figure 5-1***. This distortion occurs because the visual rays used to create the image in the viewer's eye are not parallel. This distortion, while useful in providing the illusion of distance, results in a loss of image accuracy and fails to provide the information needed for most detailed technical communication. In order to develop multiview drawings, you must be proficient in the concept of spatial visualization.

Spatial Visualization

We see the world in three dimensions. When we look at an object, it has height, length, and depth. But when working in engineering or drafting, we sometimes have to communicate our ideas in a two-dimensional format. Making two-dimensional representations of three-dimensional objects or looking at a two-dimensional representation and visualizing the object in three dimensions requires a skill known as *spatial visualization*.

Spatial visualization is the act of (1) forming an accurate mental picture of how a three-dimensional object will look when represented in a two-dimensional format or (2) forming an accurate mental picture of how a three-dimensional object will look based on the information given in a two-dimensional representation. Some people are innately talented at spatial visualization and some are not. However, with practice most people can become proficient at spatial visualization.

Two-Dimensional Spatial Visualization

To gain a better understanding of the concept of spatial visualization, try the following experiment:

1. Pick up your copy of this book and look at it as a three-dimensional object (see ***Figure 5-2***).
2. Now orient the book so that your line of sight is perpendicular to the front cover. You should see no depth—just a flat surface. This is part of the concept of orthographic projection used when constructing multiple views of an object. Orthographic projection is covered later in this chapter.
3. Repeat Step 2 for all sides of the book. You should see the following sides: front, back, top, bottom, right side, and left side (see ***Figure 5-3***).
4. At this point, do not concern yourself with the orientation of the six views of the book shown in Figure 5-3.



FIGURE 5-1 *Perspective projection.*



FIGURE 5-2 *Three-dimensional view of this book.*

Orienting views is important, but it is covered later in this chapter. For now you need only concentrate on visualizing what the views should look like in a two-dimensional format, and you should understand that any three-dimensional object has these six views when applying the concept of orthographic projection. Even a plain globe has six views (all six would look the same).

Try this experiment with several other objects that are conveniently available, such as a chair, soda can, computer mouse, coin, or any other object that is handy. But this time, try to visualize each view without actually turning the object around and looking at it. Based on what you can see in three dimensions, what would the front, back, right side, left side, top, and bottom of the object look like in two dimensions? Make a sketch of each view of each object. This is a convenient experiment that can be conducted almost anywhere. Continue the experiment for a week with various objects in your environment, and you will find yourself becoming skilled at two-dimensional spatial visualization.

Three-Dimensional Spatial Visualization

Visualizing what a three-dimensional object will look like when drawn in two dimensions is half of the spatial visualization challenge. The other half involves using a two-dimensional representation of an object as the basis for visualizing what the actual object will look like in three dimensions. For example, look at the two-dimensional drawing in ***Figure 5-4***. How would this object look in three dimensions?

Looking at the front and back views, you can see that the object in question is shaped like an L. By looking at the right and left sides, you can discern how wide the object is. The top and bottom views show in which directions the legs of the L point. With this information and a little practice, you can determine that the three-dimensional object in question would look like ***Figure 5-5***.

The ability to apply spatial visualization is important to engineers and drafting technicians. For most people, developing this skill takes time, patience, and practice—lots of practice. Fortunately, spatial visualization is a concept that can be practiced anywhere. Until your spatial visualization skills are well developed, practice it on objects in your environment.

Solid modeling software (Chapter 11) is making spatial visualization easier for engineers and drafting technicians by doing much of the work for them. But you cannot develop a three-dimensional solid model



FIGURE 5-3 *Orthographic views of this book.*



FIGURE 5-4 *Multiple views of an object.*



FIGURE 5-5 *Three-dimensional view of an object.*

every time you need to visualize an object. Consequently, it is important to develop your skills in applying spatial visualization manually.

Orthographic Projection

Orthographic projection is the most accurate term for shape description wherein an undistorted image of the object appears in a flat, transparent, but imaginary projection plane. A projection plane may be thought of as an imaginary pane of glass, with an object underneath it or behind it, ***Figure 5-6A***. Viewed from the side, the pane of glass appears as a line, ***Figure 5-6B***. Assume that light beams emitting from the surfaces of the object are projected to the projection plane, and that each light beam from each exposed surface is directed toward the viewing plane, ***Figures 5-6C*** and ***D***. The image shown in Figure 5-6A traces the path of each light beam as it intersects the viewing plane. This image is called a projection, and it illustrates the features of the exposed surfaces of the object.

Normal Surfaces

The surface images of the figures just described do not represent the size and shape of their corresponding real surfaces. Rectangular surfaces appear as parallelograms. The lengths of edges are shorter in the image than their actual lengths (a phenomenon called *foreshortening*). However, if the viewing plane were positioned parallel to several of the object's surfaces, as shown in ***Figure 5-7A***, then the image appearing in that viewing plane would provide the actual size and shape of those surfaces, as shown in ***Figure 5-7B***. A surface that is parallel to a viewing plane is said to be "normal" to the viewing plane.

A simple object, such as the cannonball in ***Figure 5-8***, needs only one view to describe its true size and shape. An object such as the flat gasket in ***Figure 5-9*** needs only one view and a callout stating its required thickness. The callout can be noted on the drawing, as illustrated, or listed in the title block under "material." ***Figure 5-10A*** shows an object with a viewing plane placed in a normal position relative to some surfaces of the object, resulting in the orthographic views shown in ***Figure 5-10B***. The sizes and shapes of the object's normal surfaces are shown in perfect outline in the orthographic view, but the viewer still cannot determine other features of the object. For example, ***Figures 5-10C***, ***5-10D***, and ***5-10E*** are different objects that provide exactly the same projected view. Furthermore, not all the surfaces of the projected views of Figures 5-10C and 5-10E are shown in their real size and shape as they are not normal to the viewing plane. There is no way to fully distinguish these without additional information.



FIGURE 5-6 *(A) Imaginary windowpane in front of object; (B) side view of windowpane; (C) and (D) reversed projection.*



FIGURE 5-7 *(A) Viewing plane parallel to surfaces; (B) viewing plane provides actual size and shape of surfaces.*



FIGURE 5-8 *Simple one-view drawing.*

Two Orthographic Views

In order to present the images of each viewing plane in a flat drawing area, one of the viewing planes must be repositioned to lie in the same plane of the drawing as the other. The procedure used to do this is to create a *fold line* where the imaginary perpendicular-orthographic-viewing planes meet each other along



FIGURE 5-9 *Simple one-view drawing.*

the straight edge of intersection, as shown in ***Figure 5-11A***. Figure 5-11A shows the object in Figure 5-10A with a second viewing plane in position. The fold line acts as a hinge as the two intersecting viewing planes are swung into the same plane, ***Figure 5-11B***. The resulting orthographic views are shown in ***Figure 5-11C***. Each view contains the image of a 90° rotated view or projection of the other. In this procedure, the features and surfaces are always aligned to each other and thus can be located.

Conversely, the same two orthographic views are shown in ***Figures 5-11D, 5-11E,*** and ***5-11F*** in haphazard relationship to each other, putting them each in error and making it impossible to determine surface positions or the real shape of the object.

Labeling Two Views

Figures 5-12A and ***B*** show the positioning of two adjoining orthographic viewing planes to describe the object shown in Figure 5-10C. The orthographic view that presents the most characteristic shape of the object is usually selected and identified as the *front view.* Once this view is selected, the orthographic view that is projected to the right of the front view is identified as the *right-side view.* The front view is often referred to as the front elevation, and the right-side view is referred to as the right profile.

Figure 5-13A shows viewing planes with view images that accurately describe Figure 5-10D. But finished orthographic drawings should not include the borders of viewing planes. For example, ***Figure 5-13B*** shows the views without the borders. Viewing planes were earlier identified as imaginary; therefore, the



FIGURE 5-10 *(A) Viewing plane in a normal position; (B) orthographic view of the object; (C) different object with the same orthographic view; (D) another object with the same orthographic view; (E) another object with the same orthographic view.*



FIGURE 5-11 *(A) Fold line; (B) fold line acts as a hinge; (C) projecting features from one view to the next view; (D), (E), and (F) incorrect positioning of views.*



FIGURE 5-12 *(A) Positioning of two adjoining orthographic viewing planes; (B) two adjoining orthographic viewing planes flattened out.*



FIGURE 5-13 *(A) Viewing planes and images; (B) orthographic drawing omitting viewing planes.*

fold line is imaginary also. Often, fold lines are needed for view constructions, as illustrated later in this chapter and future chapters (especially Chapter 8), but in general, fold lines are removed on technical drawings.

The distance of the image from the fold line identifies the object's location from the viewing plane. The drafter decides what this distance will be in order to make the best use of the space on the drawing paper and to provide room for dimensions and notes, see *Figure 5-14*.

Multiple Orthographic Views

Figure 5-15A shows two orthographic views that do not completely describe the object. Multiple interpretations of the objects are possible, causing the viewer to be misled by inadequate information. Correctly interpreted, the object appears as shown in *Figure 5-15B*. Incorrect interpretations are shown in *Figures 5-15C, 5-15D,* and *5-15E*.

A third viewing plane is commonly used to ensure adequate definition of the represented object. The



FIGURE 5-14 *Only two views are required.*



FIGURE 5-15 *(A) Orthographic views of an object; (B) correct interpretation; (C) and (D) incorrect interpretations.*



(E)

FIGURE 5-15 *(Continued) (E) Incorrect interpretation.*



FIGURE 5-16 *Third viewing plane added.*



(A)



(B)

FIGURE 5-17 *(A) Orthographic view of an object; (B) three principal planes.*



(A)

FIGURE 5-18 *(A) Transparent box.*

third viewing plane is usually above the object and perpendicular to the other two. It is called the *top view.* The top view is sometimes called the plan view in construction-related drawings. This third view is shown in *Figure 5-16.*

Select the views to best present the object's shape and make the most efficient use of the drawing area, *Figure 5-17A,* or to maintain the orientation of the object that is most easily understood by the reader, as illustrated in *Figure 5-17B.* Recall that the view selected should be an attempt to show the most characteristic shape of an object. For example, seeing a building drawn sideways makes reading the drawing very awkward.

The three viewing planes in Figure 5-16 are called *principal viewing planes,* as they are all perpendicular to one another. Orient the front view first. Three other principal planes complete the "box"; they make up the sides of a transparent box that completely surrounds the object, *Figure 5-18A. Figure 5-18B* shows



FIGURE 5-18 *(Continued) (B) Fold lines selection; (C) resulting multiple views.*

the possible fold line selections that could be used with orthographic views on the principal planes. *Figure 5-18C* shows the six principal views.

Object Description Requirements

The six views of Figure 5-18C are not all necessary to provide sufficient information; three are sufficient for this object. The common arrangement of top, front, and right-side views is shown in *Figure 5-19*. The top view aligns directly above the front view, and the right-side view aligns directly to the right of the front view. Both the top view and the right-side view images are the same distance behind the front view projection plane. See dimension b in *Figure 5-20*.

Dimension Transfer Methods

Figure 5-19 shows a method of transferring dimensions between the top and right-side views. This method, used only with principal views, employs a line at 45° to the fold lines of the principal planes.



FIGURE 5-19 *Transferring dimensions—45° projection method.*



FIGURE 5-20 *Transferring dimensions—compass method.*

Use a compass for a different method shown in Figure 5-20.

Figure 5-21 shows the transfer method, which is usually the most accurate. It is the method used in descriptive geometry discussed in Chapter 8. Draw the front and top views first and arbitrarily position a fold line between them. Recall that the fold line must be perpendicular to the projection lines between views. Construct a second fold line perpendicular to the projection lines that will go to the right to be used for the right-side view. This second fold line can be at any distance from the front view. Once the fold line is drawn, the distances from it to the right-side view must agree with distances to the top view, dimensions a, b, and c. Transfer these dimensions with a scale or dividers. If the front and right-side views are drawn first, then construct a fold line for the top view in a similar manner.

Hidden Lines

Figure 5-22 is an isometric view of an object. The orthographic top, front, and right-side views are illustrated in *Figure 5-23*. *Hidden lines* represent feature outlines, for example, intersections of plane surfaces, real but invisible, and are used in each viewing plane where appropriate.







FIGURE 5-21 *Transferring dimensions—transfer method.*

A hidden line may be covered by a visible (solid) object line in a particular view. This concept is shown in



FIGURE 5-22 *Isometric view of an object.*



FIGURE 5-23 *Orthographic views of the same object.*

Figures 5-24A and *5-24B.* Figure 5-24B shows surface B aligned behind the solid line of intersection of plane A with the inclined plane. As expected in orthographic projection, there are many hidden lines covered by solid lines. Mentally perceiving where the hidden lines lie in orthographic views requires visualization.

Figure 5-25 shows typical hidden line length and spacing, approximately 1/8″ to 1/4″ long spaced approximately 1/32″ to 1/16″ (3.2 mm to 6.4 mm and .8 mm to 1.6 mm, respectively). The lengths and spaces can vary depending on the feature and the space available on the drawing, but consistency is encouraged. Hidden lines are narrower than solid lines. Use the accepted drafting practices of hidden line applications shown in *Figure 5-26.*

Center Lines

Center lines are used primarily as locations of circular, cylindrical, or spherical features. They can also be used to specify locations of other principal symmetries as well, such as the center line of a ship or a rocket. Crossed perpendicular center lines indicate a two-coordinate location of where an axis exists. A single center line indicates the path of an axis. Identify all axes, on all views, of circular features except for noncritical radii, Figure 5-26.



FIGURE 5-24 *(A) Isometric view of an object; (B) object line takes precedence over hidden line.*

FIGURE 5-25 *Average hidden line construction.*



FIGURE 5-26 *Hidden line drafting practices.*



FIGURE 5-27 *Surface categories.*

Surface Categories

Recall that normal surfaces are parallel to one of the principal projection planes of the imaginary transparent box surrounding the object. In ***Figure 5-27,*** these surfaces are identified as the top, front, and right side. The viewing planes containing these images are identified as horizontal, frontal, and profile projection planes, respectively. A normal surface's true size and shape appear in one of the principal views, ***Figure 5-28,*** but the surface appears as an edge view, a line, in the other principal views.

Surfaces A, B, and C, Figures 5-27 and 5-28, are inclined surfaces. They are not parallel to any one of the principal viewing planes, but each inclined surface is perpendicular to one of them. For example, inclined plane A is perpendicular to the frontal projection plane. Moreover, a surface that is perpendicular to a viewing plane will appear as an edge or line when projected on that plane. Surface A appears smaller than its true size in both the top and right-side views, Figure 5-28, because of foreshortening.



FIGURE 5-28 *Orthographic views.*

Inclined surfaces B and C are configured similarly to surface A, with B perpendicular to the profile projection plane, and C is perpendicular to the horizontal projection plane. Surface D is not perpendicular to any of the principal projection planes and is therefore categorized as an oblique plane. It appears foreshortened in all of the principal projection planes.

The transparent box of principal projection planes that surround cylindrical surfaces uses the cylindrical axis as the line of orientation, ***Figure 5-29.*** If the cylindrical axis is made perpendicular to one of the principal viewing planes, then the cylindrical surface appears as a circle or an arc. Figure 5-29 shows a cylinder whose axis is perpendicular to the top horizontal principal projection plane, and the circular image that results in the top view is shown in ***Figure 5-30.*** The curved surface of the cylinder cannot be classified as normal, inclined, or oblique. Plane surface A in Figure 5-30 is inclined to the horizontal viewing plane and shows as an ellipse in the right-side view. If surface A were at 45° to the horizontal viewing plane, a circle would appear as surface A in the right-side view.



FIGURE 5-29 *Object inside transparent box.*



FIGURE 5-30 *Circular image results in this top view.*



FIGURE 5-31 *(A) Isometric view of an object; (B) sketches of object to determine front view.*

Planning the Drawing

Before beginning a three-view drawing of any object, make preliminary sketches of the object. Sketches of the object in *Figure 5-31A* are shown in *Figure 5-31B*. The sketches were used as an aid in selecting the best front view and its best position. Sketches are helpful in selecting the required views and their positions.

How to Prepare a Three-View Drawing

STEP 1 Visualize the object to be sure you have a good mental picture of it.

STEP 2 Decide which view to use as the front view by sketching the object in several positions, Figure 5-31B. Keep in mind the following:

- The front view is the most important view; viewers see this one first.
- The front view should show the most basic profile; for example, use a side view of a vehicle with the wheels on the ground.
- The front view should appear stable; place the heavy part at the bottom.
- The front view should be positioned to minimize the number of hidden lines in all views; this enhances visualization.

STEP 3 Decide how many views are needed to completely illustrate the object.

STEP 4 Decide, keeping in mind the guidelines in Step 2, in which position to place the front view. Study *Figures 5-32, 5-33, 5-34,* and *5-35* to understand why 5-35 is the best position for the object from Figure 5-31A.

STEP 5 Decide on the best placement of the views in the work area, usually centered. Work neatly.



FIGURE 5-32 *Poor front view—too many hidden lines.*



FIGURE 5-33 *Poor front view—unstable, too many hidden lines.*



FIGURE 5-34 *Poor front view—unstable.*



FIGURE 5-35 *Best position—front view.*



FIGURE 5-36 *Positioning the views within the work area.*

Positioning the Views within the Work Area

The example shown on the left of *Figure 5-36* is centered, but poor judgment was exercised in using the space on the drawing. Space is wasted on both sides, and little room is available at the top and bottom for dimensions and notes. An inch (25.4 mm) of space near the borders is desirable. The example shown on the right in Figure 5-36 is balanced and well centered. Try to keep open spaces evenly distributed around views. A systematic method for centering views is discussed next, after some comments on a general sketching procedure for centering views.

Sketching Procedure

Sketch efficiently by doing it freehand, quickly, and only to approximate scale on a sheet of practice drawing paper. First, select the front view, using the guidelines previously discussed, and sketch a light outline of the object in approximately the best position. Next, sketch outlines of the top and right-side views. Locate center lines of important features. Finally, heavy in the outline and center lines.

Centering the Drawing

Figures 5-37 and *5-38* show a simple object and a procedure used to center a sketch of the object within a specified work area. The simple object in Figure 5-37 is shown in a dimensioned isometric



FIGURE 5-37 *Centering views horizontally.*



FIGURE 5-38 *Centering views vertically.*

drawing. The views of the object in both figures are to be sketched freehand. Use an 8½ × 11″ practice sheet, and follow the procedure given. There is no need to use a scale, but a drawing sheet with fade-out lines would be helpful.

Calculate the total horizontal distance needed for the front view plus the right-side view by adding the front view width of 4.0 plus 2.0 for the depth of the right-side view, for a total of 6.0″. To center these views, subtract 7.0 from 11.0 to get 4.0. Divide this into thirds for the spacing at each end and between views. D = 1.66″. (See Figure 5-37.)

Calculate the total vertical distance needed for the front view plus the top view by adding the front view height of 2.5, plus 2.0 for the depth of the object, for a total of 4.5″. To center these views, subtract from 8.5 to get 4.0, and divide this in thirds for the upper and lower and between-view spacing, D = 1.33″. (See Figure 5-38.)

Try an alternate approach for centering a drawing. Lay out to scale on a practice sheet, with drawing instruments, outlines of the front view and the right-side view with a 1.0″ space between the two views. Next, lay out the top view with a 1.0″ space between the front and top views. Next, place a good drawing sheet over the practice sheet and move it around until the drawing is basically centered. Finally, trace the drawing onto the good sheet.

Numbering for Making Drawings

Sometimes a multiview drawing of an object, to be prepared from an isometric drawing, is so complicated that the person making the drawing is not quite sure how some part of a view will look. These more difficult drawings are easier to visualize if points of the various features are numbered, and then systematically analyzed. Think of the corners of the features as lines connecting points. For instance, think of each line as connecting two points in space, ***Figure 5-39.*** If the ends of a line can be found, all that needs to be done to complete the line is to connect the ends. Once the ends have been found and numbered in one view, the same can be done in other views by simple projection. ***Figure 5-40*** is an isometric view of a simple object, simple for discussion purposes. Each end of each line has been assigned a number.



FIGURE 5-39 *A line is made up of two points in space.*



FIGURE 5-40 *Given: An isometric view of an object.*



FIGURE 5-41 *Number one view.*



FIGURE 5-42 *Project numbers into the top view.*

Use the following steps for practice in numbering and analyzing drawings.

STEP 1 Lightly draw the basic shape outline of the required views and the 45° projection line, ***Figure 5-41.***

STEP 2 Assign the numbers from the isometric sketch to each corner of the view.

STEP 3 Project these points up to the top view, and number them as shown in ***Figure 5-42.*** Start with the number seen first, followed by a comma or slash, and then the number hidden.

STEP 4 Project these points from the front view to the right-side view, and project the same numbered points from the top view via the 45° line. The exact position of each point is located where the projection lines cross; number them, ***Figure 5-43.*** Projecting and locating points can be done with alternative methods, as shown in Figures 5-20 and 5-21.

NOTE: If a point can be located in any two of the three views, it can be projected into the third view.

STEP 5 Connect points together, for example, point 1 to point 2, 3 to 4, and so on, until all the line connections are made. Check



FIGURE 5-43 *Project numbers into the right-side view.*

the planes made by the lines. Refer to the isometric view, Figure 5-40, as needed.

COMMENT: These steps describe how to make a complicated drawing. Read and understand a complicated drawing already made by first locating and numbering points on an object in at least three views. Connect the numbers and systematically study the object, line by line, plane by plane.

Technical Drawing Conventions

Assume now that preliminary sketching has been done to locate the best positions for views of an object for a multiview drawing, and that the views are going to be drawn, to scale, with the drawing tools discussed in Chapter 2. The following topics are important for multiview, technical drawings.

- Rounds and Fillets
- Runouts
- Treatment of Intersecting Surfaces
- Curve Plotting
- Cylindrical Intersections
- Incomplete Views
- Aligned Features
- How to Represent Holes
- Conventional Breaks

The following discussions on recommended techniques for preparing multiview technical drawings all emphasize the same message: effective communication of three-dimensional concepts, that is, to enhance the visualization process for the use of the drawings.

Rounds and Fillets

Metal casting processes require an object's material to flow into cavities and corners in a mold. Sharp corners are not only undesirable on a casting but are also difficult to cast, so *rounds* are specified for outside corners and *fillets* for inside corners. Cast objects tend to crack



FIGURE 5-44 *Rounds and fillets.*



FIGURE 5-45 *Runouts.*

due to the strain placed on the metal during cooling. Fillets distribute the strain and alleviate the tendency to crack. Rounds and fillets improve an object's ability to withstand cyclic fatigue loading, and also enhance the appearance of an object, ***Figures 5-44*** and ***5-45***.

Runouts

Runouts are curved surfaces formed where a flat and a curved surface meet, Figure 5-45. To find the exact intersection where a runout occurs, locate the tangent points of the curved surfaces, ***Figure 5-46***. Project these tangent points into the next appropriate view and add the runouts as shown in ***Figure 5-47***. Note the direction of each runout.



FIGURE 5-46 *Locate the tangent points.*



FIGURE 5-47 *Complete runouts at tangent points.*



FIGURE 5-49 *Intersecting surfaces.*

Treatment of Intersecting Surfaces

Figures 5-48 through *5-51* show how to illustrate various intersecting surfaces. In these examples, rounds, fillets, and runouts have been omitted to simplify the drawings. In actual practice, rounds, fillets, and runouts would have been added. In Figure 5-48, the flat surface meets the cylinder sharply (see top view), making a visible edge necessary in the front view. The meeting point in the top view is the exact location of the object line in the front view and right-side view.

In Figure 5-49, the flat surface blends into the cylinder, stopping at the point of tangency. In the top view, the tangent point is located at the center line and blends in at that location in the front view.

In Figure 5-50, the surface blends into the cylinder, stopping at the point of tangency, similar to Figure 5-49 except on an angle. The tangent point is projected into the front view and right-side view.



FIGURE 5-50 *Intersecting surfaces.*



FIGURE 5-48 *Intersecting surfaces.*



FIGURE 5-51 *Intersecting surfaces.*

In Figure 5-51, the radius blends into the base, stopping at the point of tangency. In the top view a line is drawn extending to the tangent point of the arc in the front view.



FIGURE 5-52 *Curve plotting (Step 1).*

Curve Plotting

Curved surfaces in multiview drawings need to be projected into other views. Follow the steps listed to plot a curved surface.

STEP 1 Lightly complete the basic outline of each view, *Figure 5-52*. Locate the center of an arc, point X.

STEP 2 Draw the arc and divide it into equal spaces, *Figure 5-53*. Use 30° spacing for smaller arcs, but 10° spacing for larger ones. If accuracy is not needed, use larger spacing to save time.

STEP 3 Number the points in order clockwise, Figure 5-53.

STEP 4 Project these points up to the 45° axis line, and to the left to the top view, *Figure 5-54*.

STEP 5 Project from the right-side view to the slanted surface in the front view and locate each point, *Figure 5-55*.

STEP 6 Project these points up from the front view to the top view.



FIGURE 5-53 *Curve plotting (Steps 2 and 3).*



FIGURE 5-54 *Curve plotting (Step 4).*



FIGURE 5-55 *Curve plotting (Step 5).*



FIGURE 5-56 *Curve plotting (completed).*

STEP 7 Number the points 1 through 7 in the top view, where the numbered lines from the right-side view intersect the numbered lines from the front view, *Figure 5-56*.

NOTE: The method shown in Figure 5-21 could be used for projecting and locating curves.

Cylindrical Intersections

If there is a considerable difference in the diameters of each of the intersecting cylinders, then use a straight line for the intersection, *Figures 5-57A* and *5-57B*. If there is little difference between the intersecting cylindrical diameters, then use a simple arc, constructed or approximated through three points, *Figures 5-58A* and *5-58B*.

In sheet metal construction, locate the actual edge of intersection as shown in *Figures 5-59* and *5-60*. Figure 5-59 shows line elements on each of two intersecting cylindrical surfaces. The line elements are parallel to their respective cylindrical axes and to a common (frontal) viewing plane. For example, line elements number 1 on each cylinder are the same distance from the frontal viewing plane. Also, the line elements numbers 2, 3, and 4 are each the same distance from the frontal plane, respectively. Use this relationship of the elements to construct a curved line of intersection between the large cylinder and the smaller cylinder shown in Figure 5-59.

STEP 1 Refer to *Figure 5-60A* and locate line elements 1, 2, 3, and 4 on the smaller cylinder in the right-side view. Project them into the front view.



FIGURE 5-57 *(A) Cylindrical intersections (straight line); (B) cylindrical intersections (straight line).*



FIGURE 5-58 *(A) Cylindrical intersections (arc); (B) cylindrical intersections (arc).*



FIGURE 5-59 *Two intersecting cylindrical surfaces.*



FIGURE 5-60 *(A) Step 1; (B) Step 2.*

STEP 2 Locate a fold line between the front and right-side views, *Figure 5-60B*, at a distance A from the center line of the large cylinder. Locate a fold line at the distance A from the top view.

Transfer the distances labeled 1 through 4 in the right-side view to the top view as shown.

Next, because each corresponding line element from each cylinder is parallel to the front viewing plane and the same distance from it, they must intersect. Fit a curve through the points of intersection, Figure 5-60B. In a like manner, complete the lower portion of the intersection.

Incomplete Views

A drawing can be absolutely correct but confusing, as in *Figure 5-61*. The left- and right-side views are correct, but they are difficult to read due to the overlapping of the details on both ends of the bracket. Omit some of



FIGURE 5-61 *Overlapping views—poor practice.*



FIGURE 5-62 *Omitting some details—better practice.*

the features in order to make a view clearer and easier to understand, *Figure 5-62*. For example, the right-side view shows only the right-side details. Omitting some of the details in a view for clarity is a standard practice used in technical drawing. Sometimes a note is added such as, "only right side shown."

Aligned Features

Show features at their actual distance from an axis or center line, rather than in the projected or foreshortened position. *Figure 5-63A* is an isometric view of a symmetrical part. *Figure 5-63B* indicates how this symmetrical part appears confusing in conventional projection (top illustration), but gives a better indication of the part's symmetry when projected from the aligned position (lower illustration).

Chapter 6 has additional information on aligning views for clarity.

How to Represent Holes

Since products contain various kinds of holes, be able to draw each kind and, therefore, be able to identify different kinds of holes when reading drawings.



FIGURE 5-63 *(A) Isometric view of a symmetrical part; (B) aligned projection.*

Plain Holes

A *through hole* goes completely through an object; a *blind hole* is machined to a specific depth. Through holes and blind holes constitute the majority of plain holes in products, ***Figure 5-64.*** The drawing at the left in Figure 5-64 shows a top view and a front view of a through hole.

Holes are usually drilled. A drilled hole is not as accurate as a reamed hole. For example, the tolerance for a 1″ diameter drilled hole might be ±.002″, but ±.0002″ for a 1″ diameter reamed hole. A hole, specified in a callout to be reamed, is first drilled to a size approximately .015″ smaller in diameter than the size specified, and then reamed to the callout specifications.



FIGURE 5-64 *Through hole and blind hole.*

The drafter, designer, or engineer specifies the reamed hole required; the machinist selects the proper drill.

A blind hole is drilled to a specific depth, Figure 5-64.

Twist drills as shown in the figure have a conical point of approximately 118° for general-purpose drilling. The full depth of the hole is called out for the cylindrical portion of the hole only.

Tapered Holes

A *tapered hole,* ***Figure 5-65,*** must be drilled first .015″ smaller in diameter than the smallest diameter of the tapered hole, and then reamed.



FIGURE 5-65 *Tapered hole.*



FIGURE 5-66 *Countersunk hole.*

Countersunk Holes

A *countersunk hole* is usually a plain through hole with an upper portion enlarged conically, ***Figure 5-66,*** most often to 82° to accommodate standard, flat head machine screws. A machinist makes the countersink to a depth that produces a specified diameter slightly larger than the head of the flat head screw.

Counterbored Holes

A *counterbored hole* is usually a plain through hole with an upper portion enlarged cylindrically, ***Figure 5-67,*** to a specified diameter and depth. A callout would specify the through hole to be slightly larger than the fastener, and the counterbore to be slightly larger than the head of the fastener and slightly deeper than the height of the head.

Spotfaced Holes

A *spotfaced hole* is essentially a plain through hole with a shallow counterbore, ***Figure 5-68,*** deep enough to provide a flat surface for a head of a bolt, machine screw, or a nut for a threaded member.

Conventional Breaks

Use a *conventional break* for an effective way to draw long objects of constant cross section, such as a pipe, tubing, structural members, or shafting, on a relatively small sheet of drawing paper. A long pipe, drawn to 1/4 size, is shown in ***Figure 5-69A,*** but redrawn to full size, with a conventional break, in ***Figure 5-69B.*** This presents a much clearer understanding of the pipe, or other member, especially if there are holes to be located and dimensioned at either end.

Kinds of Conventional Breaks

Three kinds of breaks are commonly used in technical drawings: the S, the Z, and the freehand. Follow the steps in ***Figure 5-70*** for constructing an S break for a shaft or tube. The S break may be drawn with instruments or done freehand. Use ***Figure 5-71A*** as a guide for constructing a Z break, usually used for long, wide parts, of constant cross section. The Z part is usually done freehand.

The freehand break, ***Figure 5-71B,*** is only one example of the use of the freehand break line. For example, broken-out sections will be discussed in Chapter 6.

Visualization

Visualization is the process of re-creating a three-dimensional image of an object in a person's mind, using the evidence and clues provided by orthographic



FIGURE 5-67 *Counterbored hole.*



FIGURE 5-68 *Spotfaced hole.*



FIGURE 5-69 *Conventional breaks.*



FIGURE 5-70 *S break.*



FIGURE 5-71 *Z break and freehand break.*

drawings. This process has been the focus of much investigation, often used for studying a person's ability to perceive (such as in intelligence tests). The goal of reading an orthographic drawing is to visualize accurately information about the relative positions of an object's surfaces and geometric features.

There is some evidence that an active what-if imagination is a key ingredient in the visualization process. For example, a solid line circle in a view causes a what-if visualizer to seek further evidence. If an adjoining view has a solid line rectangle, bisected by a center line (axis) that aligns with the circle's center, a solid cylinder is indicated, ***Figure 5-72.*** If the aligned rectangle has hidden lines, a hole is indicated, ***Figure 5-73.*** A single orthographic view seldom is capable of providing three-dimensional evidence, and the reader must consider two or more views simultaneously in seeking an understanding of feature outlines.

Engineering drawings all follow the same procedures, and none are any more or less difficult to read than another. However, the quantity of geometrical information varies considerably among drawings, and the time required to interpret the information varies accordingly.

Visualization practice using simple drawings is required by most individuals to gain experience in mental three-dimensional image construction. Even experienced designers often use modeling clay to form a three-dimensional object from orthographic views. Some build models out of cardboard and glue. Some do quasi-isometric drawings of the overall object, based on the orthographic views, and then systematically try to draw in lines, planes, and solids until all parts of the puzzle fit into a three-dimensional concept. Chapter 18 has excellent guidelines for creating pictorial drawings from orthographic views.

FIGURE 5-72 *Visualization of an object.*



FIGURE 5-73 *Visualization of an object.*

First-Angle Projection

While the United States, Britain, and Canada use the third-angle projection multiview drawing system, most of the rest of the industrial world uses first-angle projection.

The main difference between the two systems is the position of the projection plane. Recall the following sentence from the beginning of this chapter: "A projection plane may be thought of as an imaginary pane of glass, with an object underneath it or behind it, Figure 5-6A." That is, it is observer first,



FIGURE 5-74 *First-angle projection.*



FIGURE 5-75 *(A) Third-angle projections symbol; (B) first-angle projection symbol.*

then projection plane, and last, the object. For first-angle projection, it is observer first, then the object, and last, the projection plane.

First-angle projection, like third-angle projection, starts with the front view as the most important view.

Refer to ***Figure 5-74*** and imagine that the observer is at the left of the front view and looking toward the object, the letter E. What the observer sees, looking at the object, is on the projection plane behind the object, that is, observer-object-plane. Next, imagine that the observer is above the front view and looking toward the object.

What the observer sees is the top view, which is placed below the object on the drawing.

Due to the increase in the international exchange of parts and drawings, the projection method used should be indicated on the drawing, with the standard symbol, or the name of the country issuing the drawing. The standard symbol is usually placed on a drawing in or near the title block. ***Figure 5-75A*** shows the standard symbol used to denote third-angle projection. ***Figure 5-75B*** shows first-angle projection. Note that in Figure 5-75A the observer is assumed to be at the right of the front view (F.V.) and what the observer sees is shown in the right-side view (R.S.V.). In Figure 5-75B the observer is also assumed to be at the right of the object and what the observer sees is shown in a right-side view, but the projection plane is behind the object.

Industry Application

Mary Anderson had never seen anything like it. Her company, Precision Metal Components (PMC), had recently teamed with a German company on a large contract to manufacture parts for automobile engines.

The plan was for the German partner to provide a set of existing drawings that PMC personnel would revise as necessary depending on design changes.

Anderson had expected metric dimensioning, so that aspect of the drawings came as no surprise. What she hadn't expected was the arrangement of views on the drawings. "Look at these drawings!" said Anderson. "The top view is where the front view should be, and the left side is where the right side should be." In every respect the drawings were well drawn. In fact, they were some of the best drawings Anderson had ever seen, except, that is, for the arrangement of views. Anderson couldn't understand how someone could produce a set of drawings that could be so perfect in every way but one. It didn't make sense.

As she pondered the question, Anderson remembered a different angle of projection she had learned in school. Taking her old technical drawing book off the shelf, Anderson blew away the accumulated dust and turned to the chapter on orthographic projection. She soon had her answer. While the United States uses third-angle projection, the method Anderson and her team are accustomed to, Germany uses first-angle projection.

Anderson made copies of the pertinent pages for her team members. Smiling, Anderson commented to no one in particular, "We are going to need a little training before we revise this drawing package."

Summary

- Spatial visualization is the act of forming an accurate mental picture of how a three-dimensional object will look when represented in a two-dimensional format or forming an accurate mental picture of how a three-dimensional object will look based on the information given in a two-dimensional representation.
- Students studying orthographic projection techniques should master the following: projecting normal surfaces, projecting two orthographic views, projecting multiple orthographic views, deciding how many views and which views are needed to adequately describe an object, how to transfer dimensions between views, proper use of hidden lines, proper use of center lines; and projection of inclined surfaces.
- Planning the development of a typical drawing requires five steps: (1) visualize the object; (2) select which view will be the front view; (3) decide how many views are needed; (4) decide where to place the front view; and (5) decide on the best placement of the other views.
- Properly centering a drawing within a specialized work area requires the use of simple mathematical calculations. The amount of space occupied by the various views to be drawn (vertically and horizontally) is subtracted from the space available. The remaining space is then divided proportionally.
- Students should learn to make proper use of the following technical drawing conventions: rounds and fillets, runouts, intersecting surfaces, curve plotting, cylindrical intersections, incomplete views, aligned features, holes, and conventional breaks.
- Students should learn how to mentally visualize an object in orthographic views and how to visualize from orthographic views to the object.
- First-angle projection is used in the industrialized countries of the world except the United States, Great Britain, and Canada. With first-angle projection you have the viewer first, then the object, and last the projection plane.

Review Questions

Answer the following questions either true or false.

1. Before beginning a three-view drawing, it is a good practice to make preliminary sketches of the object.
2. The work area on a drawing is the size of the piece of paper you are working with.
3. An orthographic projection is the most accurate description of shape wherein an undistorted image of the object appears in the flat, transparent, but imaginary projection plane.
4. Runout is the formation of a curved surface where a flat and a curved surface meet.
5. Fillets are interior rounded intersections between two surfaces.
6. The usual depth (call off) for a counterbored hole is **slightly** deeper than the height of the head of the fastener.
7. The lightly constructed 45° angle projection line is used to represent visual rays.
8. A micrometer is used in dimensioning a blind hole.
9. Three views should be used to describe an object.
10. All drawings should be lightly numbered.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** a frequent use of center lines?
   a. The location of a circular or cylindrical feature
   b. The location of an intersection of inclined planes
   c. The location of a spherical feature
   d. To specify the location of other principal symmetries
2. The difference between an inclined plane and an oblique plane is:
   a. Position in the drawing.
   b. Different projection angle.
   c. Inclined planes are used in third-angle projection only.
   d. Inclined planes are not parallel to any normal surface, but are perpendicular to at least one. Oblique planes are neither parallel nor perpendicular.
3. Which of the following is **true** regarding ways to draw a cylindrical intersection?
   a. If there is a considerable difference in the dimensions, use a straight line for the intersection.
   b. If there is little difference in the dimensions, use a simple arc.
   c. Both a and b.
   d. Neither a nor b.

4. Where is the third-angle projection multiview system used?
   a. The United States
   b. Britain
   c. Canada
   d. All of the above
5. What is the main difference between the first-angle and the third-angle projection?
   a. The standard symbols
   b. The time required to interpret the information
   c. The position of the projection plane
   d. None of the above
6. To illustrate a countersunk hole, what angle is used to draw the countersunk portion?
   a. 81°
   b. 82°
   c. 83°
   d. 84°
   e. None of the above

Chapter 5 Problems

The following problems are intended to give the beginning student experience in visualizing objects that are made of convenient shapes and features. Visualizing these shapes and features will help you to completely dimension an object.

Problem 3-22 (page 105) will be used here as an example to illustrate the requirements for the problems.

Assume that you have been asked to calculate the weight of the object in Problem 3-22, which is made of aluminum with a density of 0.097 pounds per cubic inch.

You calculate the volume to be 9.84 cubic inches, which when multiplied by 0.097 pounds per cubic inch equals 0.954 pounds. Unless otherwise specified, use the format shown in Problem 4-37 (page 167) to present your solutions to the following problems.

PROBLEM 5-1

Assume that the object in Problem 5-8 is cast iron with a density of 0.25 pounds per cubic inch. Calculate the weight of the object in pounds.

PROBLEM 5-2

Assume that the object in Problem 5-14 is steel with a density of 7,765 kilograms per cubic meter. Calculate the weight of the object in kilograms.

PROBLEM 5-3

Assume that the object in Problem 5-18 is aluminum with a density of 0.097 pounds per cubic inch. Calculate the weight of the object in pounds.

PROBLEM 5-4

Assume that the object in Problem 5-27 is aluminum with a density of 0.097 pounds per cubic inch. Calculate the weight of the object in pounds.

PROBLEM 5-5

Assume that the object in Problem 5-41 is steel with a density of 7,765 kilograms per cubic meter. Calculate the weight of the object in kilograms.

PROBLEM 5-6

Assume that the object shown here is steel with a density of 0.28 pounds per cubic inch. Calculate the weight of the object in pounds.



STEEL SHAFT

Conventional Instructions

The following problems are intended to give the beginning student practice in visualizing the multiview system, choosing and sketching the required view, using drafting instruments, and using correct line thickness.

As these are beginning problems, no dimensions will be used at this time.

The steps to follow in laying out all drawings throughout this book are:

STEP 1 Study the problem carefully.

STEP 2 Choose the view with the most detail as the front view.

STEP 3 Position the front view so that there will be the least number of hidden lines in the other views.

STEP 4 Make a sketch of all required views.

STEP 5 Center the required views within the work area with a 1″ (25 mm) space between each view.

STEP 6 Use light projection lines. Do **not** erase them.

STEP 7 Lightly complete all views.

STEP 8 Check to see that all views are centered within the work area.

STEP 9 Check to see that there is a 1″ (25 mm) space between all views.

STEP 10 Carefully check all dimensions in all views.

STEP 11 Darken in all views by using correct line thickness.

STEP 12 Recheck all work, and, if correct, neatly fill out the title block by using light guidelines and neat lettering.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order; then begin the project.

Problems 5-7 through 5-17

Construct a three-view drawing of each object, using the listed steps.

PROBLEM 5-7



PROBLEM 5-8



PROBLEM 5-9



PROBLEM 5-10



PROBLEM 5-11



PROBLEM 5-12



PROBLEM 5-13



PROBLEM 5-14



PROBLEM 5-15



PROBLEM 5-16



PROBLEM 5-17



PROBLEM 5-18

Construct a three-view drawing of this object. Project points 1, 2, and 3 into the right-side view and into the top view. Complete all views by using the listed steps.



PROBLEM 5-19

Construct a three-view drawing of this object. Project points 1 through 8 into the top view and into the front view. Complete all views by using the listed steps.



PROBLEM 5-20

Construct a three-view drawing of this object. Project points 1 through 6 into the front view and into the right-side view. Complete all views by using the listed steps.



PROBLEM 5-21

Construct a three-view drawing of this object. Project points 1 through 7 into the right-side view and into the front view. Complete all views by using the listed steps.



PROBLEM 5-22

Construct a three-view drawing of this object. Project points 1 through 7 into the right-side view and into the top view. Complete all views by using the listed steps.



PROBLEM 5-23

Construct a three-view drawing of this object. Locate and number 12 points around the 1.5 diameter hole. Project points 1 through 12 into the front view and into the right-side view. Complete all views by using the listed steps.



Problems 5-24 through 5-31

Construct a three-view drawing of each object, using the listed steps.

PROBLEM 5-24



PROBLEM 5-25



PROBLEM 5-26



PROBLEM 5-27



PROBLEM 5-28



PROBLEM 5-29



PROBLEM 5-30



PROBLEM 5-31



PROBLEM 5-32

Construct a four-view drawing of this object (front, top, right, and left-side views). Use the listed steps.



Problems 5-33 through 5-42

Construct a three-view drawing of each object, using the listed steps.

PROBLEM 5-33



PROBLEM 5-34



PROBLEM 5-35



PROBLEM 5-36



PROBLEM 5-37



PROBLEM 5-38



PROBLEM 5-39



PROBLEM 5-40



PROBLEM 5-41



PROBLEM 5-42



Problems 5-43 through 5-56

Choose the front view and construct a three-view drawing of the objects in Problems 5-43 through 5-56, using the listed steps.

PROBLEM 5-43



PROBLEM 5-44



PROBLEM 5-45



PROBLEM 5-46



PROBLEM 5-47



PROBLEM 5-48



PROBLEM 5-49



MATERIAL THICKNESS .125
INTERNAL RADII .0125

PROBLEM 5-50



PROBLEM 5-51



PROBLEM 5-52



PROBLEM 5-53



PROBLEM 5-54



PROBLEM 5-55



PROBLEM 5-56



PROBLEM 5-57

For practice in reading multiview drawings that have already been drawn, study the pattern of the sample responses related to the following numbered multiview drawing, and then complete the surface analyses as indicated.

Sample Responses

1. Surface 25-26 in R is 5-6-10-9 in T
2. Surface 16-17 in F is 29-30 in R
3. Surface 16-17 in F is 2-3-6-10-11-7 in T

Complete the Responses

1. Surface 13-14-15-16 in F is _____ in T
2. Surface 24-25-26-27-28 in R is _____ in T
3. Surface 29-25-26-27-30 in R is _____ in T
4. Surface 8-7-12-11 in T is _____ in F
5. Surface 13-14 in F is _____ in T
6. Surface 29-25-24 in R is _____ in F
7. Surface 11-7-2 in T is _____ in F
8. Surface 11-7-2 in T is _____ in R
9. Surface 32-30-27-28 in R is _____ in T
10. Surface 6-5-9-10 in T is _____ in F



PROBLEM 5-58

Six possible T views, all correctly drawn, are shown for the one F view. Draw an A view for each one of the T views.



PROBLEM 5-59

The steel end-cover shown has eight through holes 9/16″ diameter for 1/2″ diameter fillister head cap screws. (See Appendix A.) Change the callout for the holes, to be counterbored. (Refer to Chapter 10 for callouts.) The heads of the cap screws will not protrude above the surface of the cover. (This change is for safety reasons; some counterbored holes are specified for aesthetic reasons.) Prepare a two-view drawing of the cover, with the new callout and the dimensions. Show one hole in cross section, in a separate view.



PROBLEM 5-60

Visit a lab or shop listed, and do a field sketch (rough sketch) of a piece of apparatus (not too complicated). Later, use the sketch to prepare a multiview drawing of the apparatus. Show approximate dimensions and note general materials.

a. Chemistry lab
b. Physics lab
c. Metal shop
d. Wood shop
e. Electrical/Electronics shop
f. Computer lab

PROBLEM 5-61

Visit a track and field area and a gymnasium and do a field sketch (rough sketch) of one of the following. Later, use the sketch to prepare a multiview drawing of the item sketched. Give approximate dimensions and note general materials.

a. Hurdle
b. Starting block
c. Javelin
d. High-jump post
e. Horse
f. Springboard (used with a horse)
g. Parallel bars
h. Other

PROBLEM 5-62

Visit a weight room and do a field sketch (rough sketch) of a portion of a complicated assembly or all of a relatively simple assembly. Later, use the sketch to prepare a multiview drawing of the item sketched. Give approximate dimensions and note general materials.

PROBLEM 5-63

Do a conceptual design of a contemporary desk lamp for a student's desk. That is, do the general outline of the lamp only, not the insides. Prepare a multiview drawing of the lamp and indicate approximate sizes.

PROBLEM 5-64

Design a ladder for use around a typical home. Use wood and fasten the rungs to the side rails with glue, unless otherwise directed. Prepare a multiview drawing of the ladder, to scale, with approximate dimensions. (A "Z" break may be useful here.)

PROBLEM 5-65

Utilize the following anthropometric data and design one of the objects listed. Use the dimensions given or use your own body dimensions as a guide. Prepare a multiview drawing of the design, with approximate dimensions and general materials.

A door (standard height 6′8″ to 7′; doorknob or handle, 38″ above floor)
A working counter for the center of a kitchen (standard height 36″ to 40″)
A bar stool (standard height 27″ to 30″)
A simple workbench (standard height 36″)
A computer workplace (25″ to 26″ knee clearance)

PROBLEM 5-66

Design a simple metal grill for use over an open fire, collapsible and small enough to fit in a backpack. Prepare a multiview drawing of the grill. Include approximate dimensions.

PROBLEM 5-67

Design, for a junior high school science class, an inexpensive, easy to assemble, portable, demonstration apparatus for illustrating the change of supporting force, F, (in pounds) in the diagonal member BC as the angle θ is changed, while the weight W is constant.

Refer to the frame outline shown. Prepare a multiview drawing of the design, with approximate dimensions, and note the materials used. (A scale may need to be designed; for example, use a spring with a pointer attached, calibrated for different forces pulling on the spring.)



PROBLEM 5-68

Design an easy-to-assemble apparatus for a junior high school science class. It should be portable and inexpensive to demonstrate two facets of a pendulum. First, demonstrate how the period (a complete cycle back and forth) of a pendulum changes with a change in length. Second, demonstrate how the period doesn't change with a change in weight for any one length.

Prepare a multiview drawing of the design, indicate approximate dimensions, and note the materials in general. The equation for the period T of a pendulum is $T = 2\pi \times$ square root of (length/g). The g in the equation is the gravity constant. If the length is in meters and the gravity constant equals 9.81 meters/second squared, then the period will be in seconds. For example, a swing (a type of pendulum) with a length of 12 meters and your best friend in the swing, would have a period of approximately 6.9 seconds. (This would be about a 40′ long swing.)

PROBLEM 5-69

The drawing shown is for a special aluminum circular sealing plate, used on an experimental apparatus. The plate has a groove for an O-ring seal and threaded holes for a pressure transducer. A similar plate is needed for another project, but the outside diameter is to be changed to 200 mm, and the threaded holes on the 41 mm bolt circle are to be drilled and tapped for a metric fastener M8 × 1.25. The depth of the threaded portion of holes varies from 1 times the diameter of the fastener if the material is steel, to 2 times the fastener diameter for aluminum. Prepare a similar drawing for the circular plate and use your own judgment for the changes in the dimensions. Note that the title block has been omitted for convenience; however, the third-angle projection symbol is shown. Note: Problem 5-69 is a "real-world" drawing. It does not conform to standard drafting conventions in all cases.



6

Sectional Views

KEY TERMS

Aligning of features
Assembly section
Auxiliary section
Balloon
Broken-out section
Cutting-plane line
Full section
Half section
Offset section
Parts list
Removed section
Revolved section (Rotated section)
Section lining
Sectional view
Thinwall section

CHAPTER OUTLINE

Sectional views • Cutting-plane line • Direction of sight • Section lining • Multisection views • Kinds of sections • Sections through ribs or webs • Holes, ribs and webs, spokes and keyways • Aligned sections • Fasteners and shafts in section • Intersections in section • Summary • Review questions • Chapter 6 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Describe the concept of a sectional view.
- Define what is meant by a cutting plane.
- Illustrate section lining.
- Know how to prepare the following kinds of sections: full, offset, half, broken-out, revolved, removed, auxiliary, thinwall, and assembly.
- Know how to deal with the following in sections: ribs, webs, holes, spokes, fasteners, shafts, and keyways.
- Explain aligned sectioning.
- Know how to treat intersections in sections.

Sectional Views

A *sectional view* communicates more information about objects with complicated internal features than the conventional multiview drawing method can with hidden lines. The multiview drawing method, discussed in Chapter 5, is an excellent way to illustrate various external features of an object; however, complicated internal features are difficult to illustrate with hidden lines only. Sectional views solve the problem.

Sectional views are somewhat similar to x-ray images and very similar to magnetic resonance imaging in that each one shows internal details of an object not otherwise available to the observer.

A sectional view is a view of the surfaces that would be seen if an object could be cut open. The view is commonly referred to as a cross section, or simply section, ***Figure 6-1.***

Hidden lines are omitted in sectional views, unless it is absolutely necessary to illustrate some unique feature.

This hidden-line convention and other sectioning conventions described in ASME Y14.3M-1994 are part of the language of technical drawing. Discussions of the conventions follow.

Cutting-Plane Line

The *cutting-plane line* indicates the path that an imaginary cutting plane follows to slice through an object. Think of the cutting-plane line as a saw blade that is used to cut through the object. The cutting-plane line is represented by a thick black dashed line, as shown in ***Figure 6-2.*** The line on top is the newer cutting-plane line; sizes are approximated and spaced by eye. If the cutting-plane line passes through the center of the object, and it is very obvious where the cutting plane is located, it can be omitted. This is the drafter's decision.

Direction of Sight

The drafter must indicate the direction in which the object is to be viewed after it is sliced or cut through. This is accomplished by adding a short leader and arrowhead to the ends of the cutting-plane line, ***Figure 6-3.*** These arrowheads indicate the direction of sight. Letters are usually added to the ends of the



FIGURE 6-1 *Sectional view.*



FIGURE 6-2 *Cutting-plane line.*



FIGURE 6-3 *The direction of sight.*

cutting-plane line to indicate exactly what cutting plane is used. The cutting plane extends past the object by approximately 1/2″, as shown.

Section Lining

Section lining shows where the object is sliced or cut by the cutting-plane line. Section lining is represented by thin black lines drawn at 45° to the horizon, unless there is some specific reason for using a different angle. Section lining is spaced by eye from 1/16″ (1.5 mm) to 1/4″ (6 mm) apart, depending upon the overall size of the object. The average spacing used for most drawings is .13″ (3 mm), ***Figure 6-4.*** Section lines must be of uniform thickness (thin black) and evenly spaced by eye.



FIGURE 6-4 *Section lining.*



FIGURE 6-5 *Two parts with section lining.*

If a cutting plane passes through two parts, each part has section lines using a 45° angle or other principal angle. These section lines should not be aligned in the same direction and should not be joined together at the common visible edge, ***Figure 6-5.*** If the cutting plane passes through more than two parts, the section lining of each part must be drawn at a different angle. When an angle other than 45° is used, the angle should be 30° or 60°. Section lining should **not** be parallel with the sides of the object to be section lined, ***Figure 6-6.***

In past years, section lining used various symbols to indicate the type of material used to make the object. These symbols used only general-type identifications such as cast iron, steel, brass, aluminum, and so forth. (Refer ahead to Figure 6-33 [page 219] for examples). Today, because there are so many different kinds of material, section lining symbols have been eliminated, and a single, all-purpose section lining is used (as illustrated in Figure 6-4). Specific information as to the type of material is given in the title block under "material," Figure 6-34 (page 219).



FIGURE 6-6 *Section lining angle.*



FIGURE 6-7 *Multisection views.*

Multisection Views

When an object is very complicated and cut in more than one place, each cutting-plane line must be labeled starting with section A-A, followed by B-B, and so forth, *Figure 6-7.*

Kinds of Sections

Nine kinds of sections are used today in industry.

- Full section
- Offset section
- Half section
- Broken-out section
- Revolved section (rotated section)
- Removed section
- Auxiliary section
- Thinwall section
- Assembly section

Some sections are made up of a combination of the nine kinds of sections. Each is explained in full detail in the following paragraphs.

Full Section

A *full section* is simply a section of one of the regular multiviews that is sliced or cut completely in two. See the given problem, *Figure 6-8*, a regular three-view drawing of an object.

Determine which view contains many hard-to-understand hidden lines. In this example, it is the front view. Add a cutting plane to either the top view or the right-side view. In this example, the top view is chosen. Indicate how the front view is to be viewed, that is, the direction of sight. After determining where the object is to be sliced or cut and viewed, change the front view into section A-A, *Figure 6-9.*

Think of the object as a pictorial drawing, *Figure 6-10.* An imaginary cutting-plane line is passed



FIGURE 6-8 *Given: Regular three views of an object.*



FIGURE 6-9 *Section A-A added.*



FIGURE 6-10 *Pictorial view of the object.*



FIGURE 6-11 *Imaginary cutting plane added.*



FIGURE 6-12 *Pictorial view of the full section.*

through the object, ***Figure 6-11.*** The front portion is removed and the remaining section is viewed by the direction of sight, ***Figure 6-12.***

Notice that section lining is applied only to the area the imaginary cutting plane passed through. The back side of the hole and the back sides of the notches are not section lined.

Offset Section

Many times, important features do not fall in a straight line as they do in a full section. These important features can be illustrated in an *offset section* by bending or offsetting the cutting-plane line. An offset section is very similar to a full section, except that the cutting-plane line is not straight, ***Figure 6-13.***

Note that the features of the countersunk holes A, projection B with its counterbore, and groove C with a shoulder are not aligned with one another. The cutting plane line is added, and changes of direction



FIGURE 6-13 *Offset section.*

Industry Application

John Diesel, a CAD technician in an automotive company, was approached by his chief engineer, who described a fuel tank problem to John. Production needed the volume of an oddly shaped fuel tank, 30″ long and partially elliptical-rectangular in cross section. The tank had been detailed but had not been built. Did John have any ideas?

One solution John proposed was to construct a prototype of the tank and measure the volume. John also noted that a less-expensive method would be to use the details and construct cross-sectional views of the tank at three-inch intervals, determine the area of each cross section, and finally calculate the volume by summing the products of each area multiplied by three inches.

The cross-sectional areas were determined and found to be 144, 146, 150, 152, 149, 145, 144, 142, 140, and 138 square inches. The total sum of each of these areas multiplied by three equals 4,350 cubic inches. When this figure was divided by 231 cubic inches per gallon, the volume of the tank was found to be 18.8 gallons.

(staggers) are formed by right angles to pass through these features. An offset cutting-plane line A-A is added to the top view and the material behind the cutting plane is viewed in section A-A, *Figure 6-14*. The front view is changed into an offset section, similar to a full-sectional view. The actual bends of the cutting-plane lines are omitted in the offset section, *Figure 6-15*. With the use of a sectional view, another view often may be omitted. In this example, the right-side view could have been omitted as it adds nothing to the drawing and takes extra time to draw.

Half Section

In a *half section*, the object is cut only halfway through and a quarter section is removed. See the given problem, *Figure 6-16*, showing two views of an object. A cutting plane is added to the front view,



FIGURE 6-14 *Pictorial view of the offset section.*



FIGURE 6-15 *Bends omitted from section view.*



FIGURE 6-16 *Given: Regular two views of an object.*

with only one arrowhead to indicate the viewing direction. Also, a quarter section is removed and, in this example, the right side is sectioned accordingly, *Figure 6-17*. A pictorial view of this half section is illustrated in *Figure 6-18*. The visible half of the



FIGURE 6-17 *Half section.*



FIGURE 6-18 *Pictorial view of the half section.*

object that is not removed shows the exterior of the object, and the removed half shows the interior of the object. The half of the object not sectioned can be drawn as it would normally be drawn, with the appropriate hidden lines.

Half sections are best used when the object is symmetrical, that is, the same shape and size on both sides of the cutting-plane line. A half-section view is capable of illustrating both the inside and the outside of an object in the same view. In this example, the top half of the right side illustrates the interior; the bottom half illustrates the exterior. A center line is used to separate the two halves of the half section (refer back to Figure 6-17). A solid line would indicate the presence of a real edge, which would be false information.

Broken-out Section

Sometimes, only a small area needs to be sectioned in order to make a particular feature or features easier to understand. In this case, a *broken-out section* is used, ***Figure 6-19.*** As drawn, the top section is somewhat confusing and could create a question. To clarify this



FIGURE 6-19 *Given: Regular two views of an object.*



FIGURE 6-20 *Pictorial view of the broken-out section.*

area, a portion is removed, ***Figure 6-20.*** The finished drawing would be drawn as illustrated in ***Figure 6-21.*** The broken line is put in freehand and is drawn as a visible thick line. The actual cutting-plane line is usually omitted.

Revolved Section (Rotated Section)

A *revolved section,* sometimes referred to as a *rotated section,* is used to illustrate the cross section of ribs, webs, bars, arms, spokes, or other similar features of



FIGURE 6-21 *Broken-out section.*



FIGURE 6-22 *Given: Regular two views of an object.*

an object. *Figure 6-22* is a two-view drawing of an arm. The cross-sectional shape of the center portion of the arm is not defined. In drafting, no feature should remain questionable, and a section through the center portion of the arm would provide the complete information.

A revolved section is made by assuming a cutting plane perpendicular to the axis of the feature of the object to be described, *Figure 6-23*. Note that the rotation point occurs at the cutting-plane location and, theoretically, will be rotated 90°. Rotate the imaginary cutting-plane line about the rotation point of



FIGURE 6-23 *Revolved section.*



FIGURE 6-24 *Pictorial view of revolved section.*

the object, *Figure 6-24*. Notice that dimension X is transferred from the top view to the sectional view of the feature—in this example, the front view. Dimension Y in the top view is also transferred to the front view. The section is now drawn in place. The finished drawing is illustrated in *Figure 6-25*. Note that the break lines in the front view are on each side of the sectional view and are put in freehand.



FIGURE 6-25 *Revolved section view.*

Industry Application

Betty Konrad was a CAD technician employed by a company that produced household appliances such as ovens, dishwashers, clothes washers, and dryers. The company planned to launch an advertising campaign to boost sales and expand their market base. They needed an effective means to communicate to the public just how their appliances worked.

Betty was assigned the task of organizing a group of two CAD technicians and two illustrators to prepare informational drawings to show how the appliances performed and what they were made of. To organize the team and to get them looking forward to working together, Betty called a meeting and tossed out several questions. "What do you think the users want to know about the appliances?" "What types of drawings would best show how they work and how they are assembled?" The group concluded that the most prevalent technical drawing showing the "insides" of appliances were pictorials with broken-out sections (Figure 6-20). Furthermore, the group felt that the users wanted to know how easy an appliance was to use and its capacity, such as what size turkey fit in an oven and how large loads could be in the washer and dryer.

Betty assigned two appliances to each CAD technician for the creation of isometric broken-out sections. The illustrators were to use this output to prepare colorful presentations. The illustrators would also include capacities.

As the team launched their efforts, Betty prepared a planning chart so each member would have a visual reminder of the team's schedule.

The revolved section is not used as much today as it was in past years. Revolved sections tend to be confusing, and they often create problems for the people who must interpret the drawings. Today, we are encouraged to use a removed section instead of a revolved or rotated section.

Removed Section

A *removed section* is very similar to a rotated section except that, as the name implies, it is drawn removed or away from the regular views, ***Figure 6-26.*** The removed section, as with the revolved section, is also used to illustrate the cross section of ribs, webs, bars, arms, spokes, or other similar features of an object.



FIGURE 6-26 *Removed section.*

A removed section is made by assuming that a cutting plane, perpendicular to the axis of the feature of the object, is added through the area that is to be sectioned. (Refer back to Figures 6-23 and 6-24.) Transfer dimensions X and Y to the removed views, exactly as was done in the rotated section. Height features, such as dimensions A and B, are transferred from the front view in this example.

Note that a removed section must identify the cutting-plane line from which it was taken. In the sectional view, do not draw features other than the actual section.

Removed sections are labeled section A-A, section B-B, and so forth, corresponding to the letters at the ends of the cutting-plane line. The sections are usually placed on the drawing in alphabetical order from left to right or from top to bottom, away from the regular views.

Sometimes a removed section is simply drawn on a center line that is extended from the object, ***Figure 6-27.*** A removed section can be drawn to an enlarged scale if necessary to illustrate and/or dimension a small feature. The scale of the removed section must be indicated directly below the sectional view, ***Figure 6-28.***

In the field of mechanical drafting, the removed section should be drawn on the same page as the



FIGURE 6-27 *Removed section view.*



FIGURE 6-28 *Enlarged removed section.*



FIGURE 6-29 *Auxiliary section.*



FIGURE 6-30 *Thinwall section.*



FIGURE 6-31 *Space between thinwall sections.*

regular views. If there is not room enough on the same page and the removed section is drawn on another page, a page number cross reference must be given as to where the removed section may be found. The page where the removed section is located must refer back to the page from which the section is taken. For example, section A-A on sheet 2 of 4.

Auxiliary Section

If a sectional view of an object is intended to illustrate the true size and shape of an object's boundary, the cutting-plane path must be perpendicular to the axis or surfaces of the object. An *auxiliary section* is projected in the same way as any normal auxiliary view, *Figure 6-29.*

Thinwall Section

Any very thin object that is drawn in section, such as sheet metal, a gasket, or a shim, should be filled-in solid black, as it is impossible to show the actual section lining. This is called a *thinwall section, Figure 6-30.* If several thin pieces that are filled-in solid black are touching one another, a small white space is left between the solid thinwall sections, *Figure 6-31.*

Assembly Section

When a sectional drawing is made up of two or more parts it is called an *assembly section, Figure 6-32.* An assembly section can be a full section (as it is in this example), an offset section, a half section, or a combination of the various kinds of sectional views. The assembly section shows how the various parts go together.

Each one of the section linings in Figure 6-32 is the accepted standard described in the beginning of the chapter. Nevertheless, sometimes you will be given drawings using lining symbols to represent



FIGURE 6-32 *Assembly section.*



FIGURE 6-33 *Symbols for section lining.*

different materials as illustrated in ***Figure 6-33.*** The symbols shown represent the more commonly used engineering metals and concrete. Symbols are also available for rubber, plastic, cork, insulation, slate, earth, rock, sand, and wood.

Each part in the assembly must be labeled with a name, part or plan number, and the quantity required for one complete assembly. If the assembly section does not have many parts, this information is added by a note alongside each part. If the assembly has many parts, and there is not enough room to prevent the drawing from appearing cluttered, each individual part may be identified by a number within a circle called a *balloon*. The balloon callout system is used in this example. A table must be added to the drawing, listing the name, part or plan number, quantity required for one complete assembly, and a cross reference to the corresponding balloon number. This is called a *parts list*. The exact form of the list varies from company to company. ***Figure 6-34*** is an example of a parts list used with the balloon system of callouts. Notice that entries are sometimes listed in reverse (bottom to top) order, as illustrated.

Occasionally drafters deviate from conventional standards for clarity, even though the deviation may violate a basic standard. The first part of this chapter covered conventional standards for sectioning; the latter part will focus on deviations for clarity.

Industry Application

CHANGING THE CONVENTION

The drafting team was dealing with a complex, irregularly shaped machine part. To adequately provide all of the information needed to manufacture the part, the team had to draw all six orthographic views. This did not completely solve the problem. "This part just has too many hidden lines," said the team leader. "I don't think I could make this part from these drawings. With all of the hidden lines, it's hard to determine what is required. Any suggestions?"

"Why don't we cut some sections?" asked one of the team members.

"I've been out of school too long," said the team leader. "Where would you cut them and how many?"

"As I see it," said the team member, "we need to cut a full section to show the right side, and another for the left side. Then we need an offset section from the direction of the front view and one broken-out section." Various team members began sketching as they talked. Soon the types and numbers of sections needed had been determined and the drafting team set to work revising the drawings. The final result was a set of drawings that gave manufacturing personnel the information they needed to make the part without difficulty.

CORRESPONDS TO BALLOON NUMBERS IN FIGURE 6-32

PART NO.	NO. REQD.	DESCRIPTION	MATERIAL	NOTES
6	1	DRIVE WASHER	1018 STEEL	
5	1	BUSHING	LEADED BRONZE	
4	1	CRANKSHAFT	AISI 1040 STEEL	
3	1	CRANKCASE	ALUMINUM ALLOY	
2	1	CONNECTING ROD	ALUMINUM ALLOY 7075T6	
1				(NO. NOT USED)

USUAL CALLOUT INFORMATION

FIGURE 6-34 *Examples of a parts list.*

Sections through Ribs or Webs

True projection of a sectioned view often produces incorrect impressions of the actual shape of the object. ***Figure 6-35*** has given a front view and a right-side view. Its pictorial view would look like ***Figure 6-36.*** A full section A-A would appear as it does in ***Figure 6-37.*** This is a true projection of section A-A, as the cutting-plane line passes through the rib.

However, such a sectional view gives an incorrect impression of the object's actual shape, and it is poor drawing practice. It misleads the viewer into thinking the object is actually shaped as it is shown in ***Figure 6-38.*** The conventional practice used to illustrate this section is to draw the section view as illustrated

GIVEN:



FIGURE 6-35 *Given: Two-view drawing of an object.*



FIGURE 6-36 *Pictorial view of an object.*



FIGURE 6-37 *True projection of an object.*



FIGURE 6-38 *True projection can be misleading.*



FIGURE 6-39 *Conventional practice—web or rib not sectioned.*

in ***Figure 6-39,*** which is not a true projection. Note that the web or rib is not section lined.

Some companies use another method to compensate for this problem. It is somewhat of a middle ground or a combination of true projection and correct representation, ***Figure 6-40.*** This is called alternate



FIGURE 6-40 *Alternate conventional practice.*



FIGURE 6-41 *Example of true projection.*



FIGURE 6-42 *Example of conventional practice.*



FIGURE 6-43 *Holes using true projection.*



FIGURE 6-44 *Holes using conventional practice (aligning of features).*

section lining. Section lining, over the rib or web section, is drawn by using every **other** section line, and the actual shape is indicated by hidden lines. However, most companies do not use alternate section lining.

Another example of a cutting plane passing through a rib or web is shown in ***Figure 6-41***. This example is a true projection, but it is poor drafting practice because it gives the impression that the center portion is a thick, solid mass. ***Figure 6-42*** is drawn incorrectly, but it does not give the false impression of the object's center portion.

This is the conventional practice used.

Holes, Ribs and Webs, Spokes and Keyways

Holes located around a bolt circle are sometimes not aligned with the cutting-plane line, ***Figure 6-43***. The cutting plane passes through only one hole. This is a true projection of the object, but poor drafting practice. In actual practice, the top hole is theoretically revolved to the cutting-plane line and projected to the sectional view, ***Figure 6-44***. This practice is called *aligning of features*.

Ribs and Webs

Ribs or webs sometimes do not align with the cutting-plane line, ***Figure 6-45***. The cutting plane passes through only one web and only one hole. This is a true projection of the object, but poor drafting practice. In actual practice, one of the webs is theoretically revolved up to the cutting-plane line and projected to



FIGURE 6-45 *Rib or web using true projection.*

the sectional view, *Figure 6-46*. Notice that the bottom hole is unaffected and is projected normally. This is another example of aligning of features.

Spokes and Keyways

Spokes and keyways and other important features sometimes do not align with the cutting-plane line, *Figure 6-47*. The cutting-plane line passes through only one spoke and misses the keyway completely. This also is a true projection of the object, but poor drafting practice. In conventional practice, spoke B is revolved to the cutting-plane line and projected to the sectional view, *Figure 6-48*. The keyway is also projected as illustrated. This is another example of aligning of features.



FIGURE 6-46 *Rib or web using conventional practice.*



FIGURE 6-47 *Spokes and keyway using true projection.*



FIGURE 6-48 *Spokes and keyway using conventional practice.*

Aligned Sections

Arms and other similar features are revolved to alignment in the cutting plane, as were spokes in the preceding section. This procedure is used if the cutting-plane line cannot align completely with the object, as illustrated in *Figure 6-49*.

The arm or feature is now revolved to the imaginary cutting plane and projected down to the sectional view, *Figure 6-50*. The actual cutting-plane line is bent and drawn through the arm or feature



FIGURE 6-49 *Two-view drawing.*



FIGURE 6-50 *Aligned section.*



FIGURE 6-51 *Parts not sectioned.*

and then revolved to a straight, aligned vertical position. Notice that section lining is **not** applied to the arm, and it is also omitted from the web area.

Fasteners and Shafts in Section

If a cutting plane passes lengthwise through any kind of fastener or shaft, the fastener or shaft is **not** sectioned, *Figure 6-51*. Section lining of a fastener or shaft would have no interior detail, thus it would serve no purpose and only add confusion to the drawing. The round head machine screw, the hex head cap screw with nut, and the rivet are not sectioned. The other objects in the figure such as fasteners, ball bearing rollers, and so forth, are also not sectioned.

If a cutting-plane line passes perpendicularly through the axis of a fastener or shaft, section lining is added to the fastener or shaft, *Figure 6-52*. The end view has section lining added as shown.

Intersections in Section

Where an intersection of a small or relatively unimportant feature is cut by a cutting-plane line, it is not drawn as a true projection, *Figure 6-53*. Because a true projection takes drafting time, it is preferred that it be disregarded and the feature drawn by using conventional practice, as shown in *Figure 6-54*. This procedure is much quicker and more easily understood.



FIGURE 6-53 *Intersection using true projection.*



FIGURE 6-52 *Shaft sectioned in end view only.*



FIGURE 6-54 *Intersection using conventional practice.*

Summary

- A sectional view is a view of the surfaces of an object that would be seen if an object could be cut open.
- A cutting-plane line indicates the path that an imaginary cutting plane follows to slide through an object.
- The direction of sight is shown by arrows on the cutting-plane line. It indicates the direction of sight for viewing the completed sectional view.
- Section lining shows where the object is sliced or cut by the cutting-plane line. It indicates the surface that is touched by the cutting plane.
- When an object is complicated and cut in more than one place, each cutting-plane line must be labeled starting with section A-A, B-B, C-C, and so on.
- The kinds of sections students can expect to draw are as follows: full, offset, half, broken-out, revolved, removed, auxiliary, thinwall, and assembly.
- A section cut through a rib or a web can result in a misleading representation if true projection is applied. Consequently, in conventional practice section lines are not drawn in the rib or web.
- When cutting sections through objects that have holes, ribs, webs, spokes, and/or keyways that are not obliqued, a cutting plane can pass through one feature and miss another. This problem is solved by revolving the missed feature over to the cutting plane. This same technique is used in creating obliqued sections of objects with arms or other features that do not line up with a cutting plane.
- If a cutting plane passes lengthwise through any type of fastener or shaft, the fastener or shaft is not section lined.

Review Questions

Answer the following questions either true or false.

1. True projection of a sectional view always produces the actual shape of the object.
2. Section lining should be parallel with the sides of the object to be section lined.
3. A revolved section is the same as a rotated section.
4. A removed section is very similar to a rotated section except that it is drawn away from the regular view.
5. Hidden lines are usually not used in a sectional view.
6. A removed section is sometimes drawn to larger scale to illustrate and/or dimension a small feature.
7. Half sections are best used when an object is **not** symmetrical.
8. Today, it is recommended to use the removed section rather than the revolved section.
9. If a cutting-plane line passes lengthwise through any kind of fastener or shaft, the fastener or shaft is not sectioned.
10. If a cutting-plane line passes perpendicularly through the axis of a fastener or shaft, the fastener or shaft is not sectioned.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** a list of types of sectional views?
   a. Full, half, offset
   b. Front, back, profile
   c. Broken-out, revolved, removed
   d. Thinwall, auxiliary, assembly
2. Which of the following is **not true** regarding alternate section lining?
   a. It is a combination of true projection and correct representation.
   b. Over the rib or web section, every other section line is drawn.
   c. The rib or web section is not lined.
   d. The actual shape is indicated by hidden lines.
3. What kind of section view illustrates both the exterior and interior of the object?
   a. Half section
   b. Full section
   c. Broken-out
   d. Revolved
4. Which of the following is **not** true regarding an assembly section?
   a. When a sectional drawing is made up or two or more parts, it is called an assembly section.
   b. A table, called a parts list, may be added to the drawing.
   c. Each part number may be identified by a number within a circle called a balloon.
   d. The assembly section is always represented using a full section view.
5. What must be done if a removed section needs to be placed on a page other than the page on which the cutting-plane line is placed?
   a. The page where the removed section is located must refer back to the page from which it was taken.

b. A page number cross-reference must be given to where the removed section may be found.
c. Both a and b
d. None of the above

6. What must be included for each part in an assembly section?
   a. Name of part
   b. Part number or plan number
   c. Quantity required to complete one assembly
   d. All of the above

Chapter 6 Problems

The following problems are intended to give the beginning drafter practice in using the various kinds of sectional views used in industry. As these are beginning problems, no dimensions will be used at this time.

Conventional Instructions

The steps to follow in laying out all problems in this chapter are:

STEP 1 Study the problem carefully.

STEP 2 Choose the view with the most detail as the front view.

STEP 3 Position the front view so there will be the least amount of hidden lines in the other views.

STEP 4 Make a sketch of all required views.

STEP 5 Determine what should be drawn in section, what type of section should be used, and where to place the cutting-plane line.

STEP 6 Center the required views within the work area with a 1″ (25 mm) space between views.

STEP 7 Use light projection lines. Do **not** erase them.

STEP 8 Lightly complete all views.

STEP 9 Check to see that all views are centered within the work area.

STEP 10 Check to see that there is a 1″ (25 mm) space between all views.

STEP 11 Carefully check all dimensions in all views.

STEP 12 Darken in all views by using correct line thickness.

STEP 13 Add a cutting-plane line and section lining as required.

STEP 14 Recheck all work and, if it is correct, neatly fill out the title block by using light guidelines and neat lettering.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order; then begin the project.

PROBLEM 6-1

Center three views within the work area and make the front view a full section.



PROBLEM 6-2

Center two views within the work area and make one view a full section. Use correct drafting practices for the ribs.



PROBLEM 6-3

Center two views within the work area and make one view a full section. Use correct drafting practices for the holes.



PROBLEM 6-4

Center the front view and top view within the work area. Make one view a full section.



PROBLEM 6-5

Center two views within the work area and make one view a full section. Use correct drafting practices for the arms, horizontal hole, and keyway.



PROBLEM 6-6

Center two views within the work area and make one view a full section. Use correct drafting practices for the keyway, ribs, and holes.



PROBLEM 6-7

Center three views within the work area and make one view an offset section. Be sure to include three major features.



PROBLEM 6-8

Center three views within the work area and make one view an offset section. Be sure to include three major features.



PROBLEM 6-9

Center three views within the work area and make one view an offset section. Be sure to include as many of the important features as possible.



PROBLEM 6-10

Center three views within the work area and make one view an offset section. Be sure to include as many of the important features as possible.



PROBLEM 6-11

Center two views within the work area and make one view an offset section. Be sure to include as many of the important features as possible.



PROBLEM 6-12

Center the front view and top view within the work area. Make one view a half section.



PROBLEM 6-13

Center two views within the work area and make one view a half section.



PROBLEM 6-14

Center the two views within the work area and make one view a half section.



PROBLEM 6-15

Center two views within the work area and make one view a half section.



PROBLEM 6-16

Center two views within the work area and make one view a full section.



PROBLEM 6-17

Center the required views within the work area and make one view a broken-out section to illustrate the complicated interior area.



PROBLEM 6-18

Center the required views within the work area and make one view a broken-out section as required.



PROBLEM 6-19

Center three views within the work area and add removed sections A-A and B-B.



PROBLEM 6-20

Center two views within the work area and add removed sections A-A, B-B, and C-C.



PROBLEM 6-21

Center the required views within the work area and add the removed section as required.



PROBLEM 6-22

Center the required views within the work area and add the removed section as required.



PROBLEM 6-23

Center the required views within the work area and add removed sections A-A and B-B.



PROBLEM 6-24

Center the required views within the work area and add removed section A-A.



PROBLEM 6-25

Center the four views within the work area. Make the top view section A-A and the right-side view section B-B.



PROBLEM 6-26

Center the required views within the work area, and add removed sections A-A and B-B.



PROBLEM 6-27

Center the required views within the work area and add removed sections A-A and B-B.



ALL UNMARKED RADII = R.06

PROBLEM 6-28

Center the front view, side view, and removed sections A-A, B-B, and C-C within the work area.



PROBLEM 6-29

Make a two-view assembly drawing of parts 1, 2, 3, and 4. Make one view a full-section assembly. Use correct section lining and all conventional drafting practices.







PROBLEM 6-30

Make a two-view assembly drawing of parts 1, 2, and 3. Make one view a full-section assembly. Use correct section lining and all conventional drafting practices.



PART NO. 1
3 – REQ'D



PART NO. 2



PART NO. 3

PROBLEM 6-31

Make a two-view assembly drawing of parts 1, 2, and 3. Make one view a full-section assembly. Use correct section lining and all conventional drafting practices.



PART NO.1



PART NO.2



PART NO.3

Problems 6-32 through 6-37

Center required views within the work area. Leave a 1" or 25 mm space between views. Make one view into a section view to fully illustrate the object. Use either a full, half, offset, broken-out, revolved, or removed section. Do not add dimensions.

PROBLEM 6-32



PROBLEM 6-33



PROBLEM 6-34



PROBLEM 6-35



PROBLEM 6-36



PROBLEM 6-37



PROBLEM 6-38

Refer to Problem 17-9 and use the full-section drawing for information on dimensions to determine the overall distance from the outside of part 1 on the left to the outside of part 1 on the right, along the center line of the pulley. Prepare a sketch with dimensions for your answer.

PROBLEM 6-39

Refer to Problem 18-52 (assembly) and prepare an assembly section (front-view orientation) of the vise. Indicate approximate dimensions only.

PROBLEM 6-40

Refer to Problem 18-50 and prepare a full-section view of the object.

PROBLEM 6-41

Refer to Problem 10-21 and prepare an offset section view (profile orientation) of the object through the center line. Include a threaded hole.

PROBLEM 6-42

Select an object having a non-uniform cross section like the scissor half shown and prepare removed section views to illustrate detail of the object. Suggested objects: hammer, pliers, bolt cutters, boat oar, snow ski, water ski, propeller (marine, airplane, contemporary wind machine, etc.), nozzle, handles, or spokes.



PROBLEM 6-43

Refer to Problem 10-12 and prepare an aligned section view of the object. Show the threaded holes and the keyway by using conventional practices.

PROBLEM 6-44

Refer to Problem 10-37 and prepare an aligned section view of the object.

PROBLEM 6-45

Refer to Problem 10-43. Prepare a conventional section view showing the ribs of the object.

PROBLEM 6-46

Refer to Problem 17-13 (top view). Prepare a section, drawn to scale.

PROBLEM 6-47

Refer to the drawings shown. Prepare an offset section C-C, full size, of the distributor cap. Dimensions are not required.



PROBLEM 6-48

Select one of the following common devices and prepare a section view(s) to best show inside details and how the device works for a nontechnical person. Simplify the details of the device for clarity. How-things-work books would be useful references. Indicate approximate sizes only.

- **a.** clock
- **b.** toaster
- **c.** internal-combustion-engine cylinder
- **d.** ski binding
- **e.** electric drill
- **f.** car window mechanism (manual or electrical)
- **g.** electric motor application in an average home, including an automobile

NOTE: The average home with an automobile has approximately 35 electric motors.

PROBLEM 6-49

Find material on threaded inserts (usually a threaded collar made of steel, inserted in softer material such as aluminum). Prepare a section drawing showing an application. Indicate approximate dimensions.

PROBLEM 6-50

Select an object from one of the locations or categories listed and prepare a multiview drawing of your redesign ideas for the object. Use section views to replace traditional views where appropriate. (Refer to Figure 6-15.)

a. classroom
b. lab
c. shop
d. garage
e. automobile
f. hobby
g. sports equipment

PROBLEM 6-51

Use the partially completed drawings shown and do the following.

a. Assume that the beam used has a depth of 152 mm and a flange width of 84 mm. Estimate dimensions of the parts that make up dimension X, and show in a freehand sketch dimension X and your assumptions.

b. Make additional estimates: (1) of the thickness of the plates for the trolley wheels, and (2) of the distances from the trolley wheels to the lower bolted connection and to the hole. Prepare an offset section through the trolley wheels, through the bolted connection, and through the hole.



TYPICAL APPLICATION OF THE TROLLEY, HOIST SUPPORT



HALF SCALE





PROBLEM 6-52

Design a lever-type door handle for handicapped individuals who have prosthetics for hands and cannot use knob-type door openers. Use removed sections to show the details of the lever arm. Indicate approximate dimensions.

PROBLEM 6-53

Design a desk for a personal computer, keyboard, printer with track-fed paper, a mouse with pad, and a monitor. Prepare a multiview drawing of the desk and show a cross-sectional view (profile view orientation) of the desk. A 26" knee standard is a typical standard for computer desks. Indicate approximate dimensions.

PROBLEM 6-54

Name or describe the type of sectioning used in the figures and problems listed.

Figure 10-105 (page 420), Figure 12-41 (page 501), Figure 13-14 (page 535), Figure 14-17 (page 583), Problem 17-9 (page 633), Figure 19-35 (page 725), Figure 20-13 (page 751), Figure 21-2 (page 789), and Figure 21-76 (page 838).

PROBLEM 6-55

Name or describe the type of sectioning used in the figures and problems listed.

Figure 10-127 (page 434), Figure 13-31 (page 540), Figure 16-30 (page 622), Problem 17-10 (page 634), Figure 20-3 (page 746), Figure 21-17 (page 800), Figure 21-69 (page 830), and Figure 21-77 (page 839).

PROBLEM 6-56

Name or describe the type of sectioning used in the figures and problems listed.

Problem 10-39 (page 457), Figure 12-5 (page 489), Figure 12-67 (page 511), Problem 12-25 (page 526), Figure 13-73 (page 564), Figure 17-17 (page 639), Problem 17-18 (page 640), Figure 20-8 (page 748), Figure 21-75 (page 837), and Figure 24-13 (page 949).

7

Auxiliary Views

CHAPTER OUTLINE

Auxiliary views defined • Secondary auxiliary views • Partial views • Auxiliary section • Half auxiliary views • Oblique surfaces, viewing planes, and auxiliary view enlargements • Summary • Review questions • Chapter 7 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Define the concept of an auxiliary view and list its advantages.
- Describe and use the reference plane method to draw an auxiliary view.
- Describe and use the folding line method to draw an auxiliary view.
- Draw round and curved surfaces in auxiliary views.
- Illustrate secondary auxiliary views.
- Illustrate partial auxiliary views.
- Draw enlarged auxiliary views.
- Describe the use of a viewing plane for auxiliary views.

KEY TERMS

Auxiliary section
Auxiliary view
Enlargement of the auxiliary view
Fold line
Front view auxiliary
Oblique surface
Partial auxiliary view
Primary auxiliary view
Secondary auxiliary view
Side view auxiliary
Top view auxiliary
True length
True size
Viewing plane

Auxiliary Views Defined

Many objects have inclined surfaces that are not always parallel to the regular planes of projection. For example, in *Figure 7-1*, the front view is correct as shown, but the top and right-side views do **not** correctly represent the inclined surface. To truly represent the inclined surface and to show its true shape, an auxiliary view must be drawn. An *auxiliary view* has a line of sight that is perpendicular to the inclined surface, as viewed looking directly at the inclined surface. Auxiliary views are always projected 90° from the inclined surface.

An auxiliary view serves three purposes:

- It illustrates the true size of a surface.
- It illustrates the true shape of a surface, including all true angles and/or arcs.
- It is used to project and complete other views.

An auxiliary view can be constructed from any of the regular views. An auxiliary view projected from the front view would appear as it does in Figure 7-1. This is referred to as a *front view auxiliary.* An auxiliary view projected from the top view would appear as it does in *Figure 7-2.* This is referred to as a *top view auxiliary.* An auxiliary view projected from the right-side view would appear as it does in *Figure 7-3.* This is referred to as a *side view auxiliary.* Note in each case that the auxiliary view is projected 90° from the inclined or slanted surface and is viewed from a line of sight 90° to the inclined or slanted surface, or as viewed looking directly down upon the inclined surface.



FIGURE 7-1 *Front view auxiliary view.*



FIGURE 7-2 *Top view auxiliary view.*



FIGURE 7-3 *Side view auxiliary view.*

Hidden Lines in an Auxiliary View

Hidden lines should be omitted in an auxiliary view, unless they are needed for clarity. This is the drafter's prerogative or decision.

How to Draw an Auxiliary View

GIVEN: The pictorial view of an object, *Figure 7-4.* Notice the inclined surface. Because the inclined surface is on the front view, this will be a front view auxiliary. The usual three views of an object (front view, top view, and right-side view) are shown in *Figure 7-5.*

STEP 1 Label all important points of the auxiliary view, as illustrated in *Figure 7-6A.*

STEP 2 Construct a reference line, which is also the edge view of a reference plane, in the right-side view. Always construct a reference line so that it is vertical and passes through as many points as possible. In this example, it passes through points a–d, *Figure 7-6B.*



FIGURE 7-4 *Drawing an auxiliary view.*



FIGURE 7-5 *Given: Three views of an object.*

STEP 3 Draw light projection lines 90° from the inclined surface and construct a reference line parallel to the inclined surface at any convenient distance, as shown in ***Figure 7-6C***. Label all important points established thus far. Notice points a and d are **on** the reference line.

STEP 4 In the right-side view, measure the distance each point is **from** the reference line. Project these distances back to the inclined surface of the front view and up to 90° from the inclined surface to the reference line above. Transfer each distance, and lightly label each point as illustrated in ***Figure 7-6D***.



FIGURE 7-6 *(A) Step 1; (B) Step 2; (C) Step 3; (D) Step 4; (E) Step 5 (finished drawing).*



FIGURE 7-7 *Draw only the inclined surface in the auxiliary view.*

STEP 5 Recheck all work. Be sure:

- The projection is 90° from the inclined surface, in this example the front view.
- The reference line is parallel to the inclined surface of the front view.
- All distances have been transferred accurately.

If correct, carefully darken in and complete all views. The final finished drawing will appear as it does in *Figure 7-6E.* Notice that **only** the inclined surface is projected into the auxiliary view. Anything else would be foreshortened and, thus, not of true size or shape, and therefore of no use. Good drafting practice is to project **only** the surface of the inclined line, *Figure 7-7.*

How to Draw an Auxiliary View by Using a Fold Line

GIVEN: The pictorial view of an object, Figure 7-4, which is also shown in the usual three orthographic views, front, top, and side, Figure 7-5. Because the inclined surface is on the front view, we will use a front view auxiliary for this illustration.

STEP 1 Label all the important points of the auxiliary surface as shown in *Figure 7-8A.*

STEP 2 Construct and label *fold lines,* which also represent the lines of intersection of adjacent orthographic projection planes, *Figure 7-8B.* (Refer to Figure 5-7.)

STEP 3 Draw light projection lines 90° from the inclined surface, and locate points a, b, c, and d in the auxiliary view from the fold line F/A, *Figure 7-8C.* These distances are identical to the distances from a, b, c, and d to the fold line F/S and fold line F/T. Lightly connect a, b, c, and d bordering the inclined surface.



FIGURE 7-8 *(A) Step 1; (B) Step 2.*

STEP 4 Recheck all work to ensure the following:

- That the projection lines are 90° from the inclined surface, which appears as an edge in the front view.
- That the fold line F/A is parallel to the inclined surface in the front view.
- That all distances have been transferred accurately.

Carefully darken in and complete the auxiliary view. The finished drawing will appear as it does in *Figure 7-8D.* Figure 7-8D shows the good drafting practice of projecting only the auxiliary surface, the surface of interest.



(C)

STEP 3



(D)

STEP 4 (FINISHED DRAWING)

FIGURE 7-8 *(Continued) (C) Step 3; (D) Step 4 (finished drawing).*

How to Project a Round Surface from an Inclined or Slanted Surface

GIVEN: The usual three views of an object, front view, right-side view, and unfinished top view, are shown in *Figure 7-9*. (The usual 45° projection angle line will be omitted, as a slightly newer projection method will be used to complete the top view.) Refer also to the pictorial drawing of this object, *Figure 7-10*.

STEP 1 Divide the rounded view into equal spaces. In this example, using a 30° triangle, the right-side view is rounded and divided into 12 equal parts, *Figure 7-11A*. Letter each point clockwise, as shown in the figure.

STEP 2 Construct a vertical reference line in the right-side view so it passes through the center, in this example, through points a and g. (Always place the reference line through the center of any symmetrical object.) Construct a reference line in the top view that runs through the center, as illustrated in *Figure 7-11B*.

STEP 3 Draw light projection lines from the 12 points in the right-side view to the inclined edge in the front view. Project these same 12 points directly up to the top view from the inclined edge in the front view. Notice points a and g are on the reference line, *Figure 7-11C*.

STEP 4 In the right-side view, measure the distance each point is from the reference line. Transfer each of these distances from the right-side view reference line to the top view reference line. Label each point lightly as each is found, *Figure 7-11D*.



FIGURE 7-9 *Projecting a round surface from an inclined surface.*



FIGURE 7-10 *Pictorial view of an object.*



FIGURE 7-11 *(A) Step 1; (B) Step 2; (C) Step 3.*





FIGURE 7-11 *(Continued) (D) Step 4; (E) Step 5.*

STEP 5 Lightly connect all points and, if correct, darken in all views. This completes the top view, *Figure 7-11E.* Always darken in the compass and irregular curve layout work first. This completes the top view.

How to Draw an Auxiliary View of a Round Surface

STEP 6 Draw light projection lines 90° from the inclined surface of the front view. Construct the reference line parallel to the inclined surface at any convenient distance. Label the points that are on the reference line; in this example, a and g, *Figure 7-11F.*

STEP 7 Draw light projection lines from the 12 points in the right-side view to the inclined edge in the front view (Step 3). Project these same 12 points directly up to the auxiliary view from the inclined edge in the front view. Again, notice points a and g are on the reference line, *Figure 7-11G.* In the right-side view, measure the distance each point is from the reference line. Transfer each of these distances from the right-side view reference line to the auxiliary view reference line. Label each point lightly as each is found.







FIGURE 7-11 *(Continued) (F) Step 6; (G) Step 7; (H) Step 8 (finished drawing).*

STEP 8 Lightly connect all points and, if correct, darken in the auxiliary view. This completes the auxiliary view, *Figure 7-11H.* Notice that only the inclined surface has been projected into the auxiliary view.



FIGURE 7-12 *Plotting an irregular curved surface.*

How to Plot an Irregular Curved Surface

GIVEN: The usual three views: front view (incomplete), top view, and the right-side view, *Figure 7-12*. This is an example of a top view auxiliary.

STEP 1 Add various points at random along the curved surface. Even spaces are not necessary, but try to choose points that pick up high and low points along the line, *Figure 7-13*. Always label the points in a clockwise direction.

STEP 2 From the right-side view, project these points up to the 45° projection line and over to the top view. Where these points intersect with the inclined surface, project directly down into the front view. Project these same points from the right-side view to the front view. Where the points intersect is where the point actually is. Lightly locate and connect all lines and complete the front view, *Figure 7-13B*.

STEP 3 Establish a reference line in the right-side view. Construct this reference line so it passes through as many points as possible; in this example, points a and j, *Figure 7-13C*.



FIGURE 7-13 *(A) Step 1; (B) Step 2; (C) Step 3.*





FIGURE 7-13 *(Continued) (D) Step 4; (E) Step 5 (finished drawing).*

STEP 4 Add projection lines at 90° from the inclined surface. Add a reference line parallel to the inclined surface. Notice that points a and j again fall on the reference line, *Figure 7-13D.*

STEP 5 Project all points from the right-side view up and over to the inclined surface of the top view. Where the points intersect with the inclined surface, project 90° from the inclined surface. Transfer all distances from the reference line in the right-side view to the reference line in the auxiliary view. Lightly connect all points and, if correct, darken in all views, *Figure 7-13E.*

Secondary Auxiliary Views

Up to this point, primary auxiliary views have been dealt with. A *primary auxiliary view* can be projected from any of the regular views, as has been illustrated thus far.



FIGURE 7-14 *Secondary auxiliary view.*

Sometimes, a primary auxiliary view is not enough to fully illustrate an object; a secondary auxiliary view is needed. A *secondary auxiliary view* is projected directly from the auxiliary view. Many times, the auxiliary view and/or some of the other views cannot be fully completed until the secondary view has been completed first, *Figure 7-14.*

Partial Views

The use of a *partial auxiliary view* makes it possible to eliminate one or more of the regular views that, in turn, saves drafting time and cost. *Figure 7-15* is an example of a front view, top view, right-side view, and auxiliary view. Note the auxiliary view is always drawn partial; only the inclined surface is drawn on the auxiliary view. By using a partial top and right-side view in conjunction with the particular auxiliary view, the drawing can be simplified without detracting from its clarity; in fact, in most cases, these partial views make the drawing easier to read, *Figure 7-16.*



FIGURE 7-15 *Given: Regular three views and partial auxiliary view.*

Industry Application

"We've got to cut costs in this department," said Anna Valdez, CAD supervisor for Montgomery Engineering Company (MEC). MEC was undergoing a company-wide effort to cut costs, increase productivity, improve quality, and enhance competitiveness. The CAD department was feeling the pressure because MEC's latest contract consisted of more than 50 separate machine parts, all oddly shaped and complex. Valdez had called a departmental meeting to brainstorm ways to reduce drafting time on this contract. "We can save a lot of time by using partial auxiliary views where appropriate and by eliminating regular views when we do," suggested John Compton, a senior CAD technician. Compton laid a stack of drawings on the table and pointed out several places where full auxiliary views had been drawn when partials would have sufficed. "Not only could we be using partials," said Compton, pointing to the drawings for emphasis, "but the partial auxiliary views would eliminate the need for regular views in some cases."

"Good point, John," said Valdez. "Just this one suggestion would reduce drafting time by at least 30 percent. What other suggestions are there?"

"Look at these objects," said Tram Ly. "They are symmetrical. Why do we waste time drawing full auxiliary views when half views would be sufficient?"

"A good question," said Valdez. "Is anyone opposed to using half auxiliary views on symmetrical parts?" Hearing no comments, Valdez said, "Good. Let's do it." By the time the meeting finally ended, MEC's drafting department had identified several solid suggestions for reducing drafting time and cutting costs.



FIGURE 7-16 *Partial view and partial auxiliary views.*



FIGURE 7-17 *Auxiliary section views.*

Auxiliary Section

An *auxiliary section*, as its name implies, is an auxiliary view in section. An auxiliary section is drawn exactly as is any removed sectional view, and it is projected in exactly the same way as any auxiliary view, ***Figure 7-17***. All the usual auxiliary view rules apply, and generally only the surface cut by the cutting-plane line is drawn.

Half Auxiliary Views

If an auxiliary view is symmetrical, and space is limited, it is permitted to draw only half of the auxiliary view, ***Figure 7-18***. Use of the half auxiliary view saves some time, but it should be used only as a last resort, as it could be confusing to those interpreting the drawing. Always draw the **near** half, as shown in the figure.

Oblique Surfaces, Viewing Planes, and Auxiliary View Enlargements

Oblique surfaces were described in Chapter 5 (Figure 5-27) as not being perpendicular to any one of the three principal projection planes. The Letter A Billboard in ***Figure 7-19A*** qualifies as an oblique



FIGURE 7-18 *Half auxiliary view.*

surface. It is used in this discussion to illustrate three auxiliary views: finding an auxiliary view from an oblique surface, using a *viewing plane* to establish an auxiliary view, and enlarging an auxiliary view to show more information.

Finding the true size of an oblique surface requires the descriptive geometry procedure for finding a plane in true size. As the descriptive geometry technique (Figure 8-17) is thoroughly discussed in the next chapter, only a brief summary will be offered here. Any line in *true length* in the oblique surface may be used. Line b_1-b_2 in the Letter A Billboard shown in Figure 7-19A is used to illustrate the technique. Construct fold line T/F parallel to b_1-b_2 in the **front** view so b_1-b_2 will be in true length in the **top** view. Make fold line T/A_1 perpendicular to the direction of line b_1-b_2 in the top view so b_1-b_2 will appear as a point in the A_1 view and the oblique surface will appear as an edge. Draw fold line A_1/A_2 parallel to the edge view of the oblique surface so that the oblique surface will appear in *true size* in the A_2 view. (Note that line b_1-b_2 will appear in true length.)

To illustrate the use of an auxiliary viewing plane, align viewing plane V-V in ***Figure 7-19B*** parallel to the edge view of the Letter A Billboard. View V-V will then appear in true size. Auxiliary view V-V could be placed at other locations on the drawing if more room is needed.

A two-to-one *enlargement of the auxiliary view* V-V is shown in Figure 7-19B. Construct enlargements when more detail is needed.

An additional type of enlargement drawing for better visualization is illustrated in Chapter 3, Figure 3-3, and in a number of drawings in Chapter 21, "Drafting Applications: Pipe, Structural, Architectural, Civil Engineering, and GIS." The example in Figure 3-3 is typical. Refer to the isolated drawing labeled **Detail B**.



FIGURE 7-19 *(A) Oblique surface auxiliary view: fold line method; (B) viewing plane and enlarged auxiliary view.*

Also notice the full-section drawing of the compression housing. The partial drawing in the detail is an enlargement of the portion within the small circle located where the flange joins the tubular portion. The letter B appears in the circumference of the small circle.

Summary

- An auxiliary view is a view with its line of sight perpendicular to an inclined surface of an object. An auxiliary view serves three purposes: (1) it illustrates the true size of a surface, (2) it illustrates the true shape of a surface, and (3) it can project and complete other views.
- A secondary auxiliary view is one that is projected from a primary auxiliary view to more fully illustrate an object.
- A partial auxiliary view is used to save drafting time and costs by eliminating one or more regular views.
- An auxiliary section is an auxiliary view in sections. It is drawn in the same way as a removed section.
- A half auxiliary view can be used when an auxiliary view is symmetrical. When this is used, the near half is drawn.

Review Questions

Answer the following questions either true or false.

1. A partial auxiliary view makes it possible to eliminate one or more of the regular views.
2. Hidden lines in an auxiliary view should be omitted unless they are needed for clarity.
3. A primary auxiliary view is always projected from the front view.
4. A reference line should be drawn horizontally and pass through as many points as possible.
5. Use of the half auxiliary view is very common because it saves time.
6. When laying out a drawing with an auxiliary view, always choose the view with the most detail as the front view.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** a purpose that an auxiliary view serves?
   a. To avoid having to create a removed sectional view
   b. To illustrate the true size of a surface
   c. To illustrate the true shape of a surface
   d. To project and complete other views
2. Which of the following is **not** a major kind of auxiliary view?
   a. Front view
   b. Top view
   c. Side view
   d. Bottom view
3. When we draw an auxiliary view, projection lines must be drawn at what angle from the inclined surface?
   a. 60°
   b. 45°
   c. 90°
   d. None of the above
4. Which of the following is **not** true regarding a secondary auxiliary view?
   a. It is projected directly from the auxiliary view.
   b. Many times the secondary auxiliary view is completed first.
   c. A secondary auxiliary view is always created.
   d. None of the above.
5. Which of the following is **not** true regarding an auxiliary sectional view?
   a. It is an auxiliary view in sections.
   b. It is drawn exactly as is any removed sectional view.
   c. Generally, only the surface cut by the cutting-plane line is drawn.
   d. Not all of the auxiliary view rules apply.

Chapter 7 Problems

The following problems are intended to give the beginning drafter practice in sketching and laying out multiviews with an auxiliary view.

Conventional Instructions

The steps to follow in laying out any drawing with an auxiliary view are:

STEP 1 Study the problem carefully.

STEP 2 Choose the view with the most detail as the front view.

STEP 3 Position the front view so there will be the least number of hidden lines in the other views.

STEP 4 Determine from which view to project the auxiliary view.

STEP 5 Make a sketch of all views, including the auxiliary view.

STEP 6 Center the required views within the work area with approximately 1″ (25 mm) of space between the views. Adjust the regular views to accommodate the auxiliary view.

STEP 7 Use light projection lines. Do **not** erase them.

STEP 8 Lightly complete all views.

STEP 9 Check to see that all views are centered within the work area.

STEP 10 Carefully check all dimensions in all views.

STEP 11 Darken in all views by using correct line thickness.

STEP 12 Recheck all work and, if it is correct, neatly fill out the title block by using light guidelines and neat lettering.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order; then begin the project.

Problems 7-1 through 7-4

Draw the front view, top view, right-side view, and auxiliary view. Complete all views using the listed steps.

PROBLEM 7-1



PROBLEM 7-2



PROBLEM 7-3



PROBLEM 7-4



PROBLEMS 7-5 AND 7-6

Draw the front view, top view, right-side view, and *two* auxiliary views to illustrate the true size and shape of the slanted surfaces. Complete all views by using the listed steps.

PROBLEM 7-5



PROBLEM 7-6



Problems 7-7 through 7-13

Draw the front view, top view, right-side view, and auxiliary view. Complete all views by using the listed steps.

PROBLEM 7-7



PROBLEM 7-8



PROBLEM 7-9



PROBLEM 7-10



PROBLEM 7-11



PROBLEM 7-12



PROBLEM 7-13



PROBLEM 7-14

Draw the front view, top view, right-side view, and *two* auxiliary views to illustrate the true size and shape of all surfaces. Complete all views by using the listed steps.



Problems 7-15 through 7-22

Draw the required views to fully illustrate each object. Complete all views by using the listed steps.

PROBLEM 7-15



PROBLEM 7-16



PROBLEM 7-17



PROBLEM 7-18



PROBLEM 7-19



PROBLEM 7-20



PROBLEM 7-21



PROBLEM 7-22



Problems 7-23 through 7-29

Make a finished drawing of selected problems as assigned by the instructor. Draw the given front and right-side views, add the top view with hidden lines if required, and add an auxiliary view. If assigned, design your own right-side view consistent with the given front view and add a complete auxiliary view. Do not *add dimensions.*

PROBLEM 7-23



PROBLEM 7-24



PROBLEM 7-25



PROBLEM 7-26



PROBLEM 7-27



PROBLEM 7-28



PROBLEM 7-29



Problems 7-30 through 7-37

PROBLEM 7-30

Draw the given views and add the required auxiliary view. Present the views within the work area so all views have a neat, centered appearance. Do *not* add dimensions.



PROBLEM 7-31



PROBLEM 7-32



PROBLEM 7-33



PROBLEM 7-34



PROBLEM 7-35



PROBLEM 7-36



PROBLEM 7-37



PROBLEM 7-38

The partially completed building, in outline form, is to have the name of your city painted on one side of the roof, in letters to be read by individuals in aircraft as high as 5,000′ above the roof sign. A rule of thumb for good readability is that the letters on a sign, in a classroom, in an auditorium, or on a roof, should be as high as approximately 1/250 of the distance the viewer is from the sign. Use an auxiliary view of the roof to lay out your city's name. Then specify the length of the building to suit your sign. Refer to Figure 3-4 for example fonts.





PROBLEM 7-39

The 750 mm outside diameter flange for the special 45° elbow shown is to have M24 × 3.0, in through holes on a 650 mm bolt circle. The recommended distance between fasteners (for strength and to provide space for wrenches) is 2.5–3.0 times the diameter of the fastener. Decide on the best, even number of bolts for the 650 mm bolt circle on this flange. Show your answer in an auxiliary view of the flange with the bolt holes.



PROBLEM 7-40

Panels A, B, and C, in the control station shown, satisfy anthropometric requirements. They are 30" from the operator's head at location O, and the edge of the desk is 10" from the operator. Panel B needs to be replaced with a new panel that has the five new instruments shown, located in a reasonable arrangement in the panel. Prepare an auxiliary view of panel B and locate the five instruments, using your own judgment for the arrangement. Note approximate dimensions to their locations. Suggestion: Construct the auxiliary view of B, which will show the panel in true size. Cut out five rectangles of paper to represent the five instruments, and make trial arrangements of them on your auxiliary view. Select the best arrangement, in your opinion. Mark their locations and give approximate dimensions to their locations.



PROBLEM 7-41

The hopper shown needs a vibrator attached to the left side to shake down material to the conveyor below. Without the vibrator, some materials tend to hang up. Prepare an auxiliary view of the left side of the hopper to determine the approximate dimensions to locate a mounting plate that already has threaded holes, shown. (The plate is to be welded to the hopper.) The center of the plate should be approximately 1.9 m above the floor level so maintenance personnel can reach the vibrator. Also, locate the plate to either side of center so the maintenance person won't have to reach over the conveyor.



8

Descriptive Geometry

CHAPTER OUTLINE

Descriptive geometry projection • Steps used in descriptive geometry projection • Notations • Fold lines • Bearings, slope, and grade • Applied descriptive geometry • Topographic topics • Vectors • Summary • Review questions • Chapter 8 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the reasons for using the descriptive geometry method of projection.
- List the steps used to solve descriptive geometry problems.
- Demonstrate proficiency in the use of systems of notations.
- Define the term *fold line.*
- Demonstrate proficiency at using fold lines.
- Demonstrate proficiency in determining the position of a line in space by using its bearing, slope, and grade.
- Demonstrate proficiency in plotting the boundaries of real estate.
- Demonstrate proficiency in applying the concepts of cut and fill.
- Demonstrate proficiency in applying the concepts of strike and dip.
- Demonstrate proficiency in the use of vectors.

KEY TERMS

Azimuth bearing
Batter
Bearing
Bevel
Clockwise
Contour interval
Contour line
Cuts and fills
Dip
Equilibrant
Fold line
Grade
Graphical method
Heading
Line
Lowercase end points
Lowercase letters
North/south deviation
Notations
Parallelogram law
Piercing point
Pitch
Scalars
Slope
Strike
Top view
True length
True slope
Trusses
Two-force member
Unlimited plane
Uppercase letters
Vector
Viewing plane

Descriptive Geometry Projection

Primary auxiliary views are views that have been projected perpendicular from an inclined surface and viewed looking directly at that surface. As studied in Chapter 7, the auxiliary view shows the true size and true shape of the inclined surface and is sometimes used to complete other views. If a surface is oblique (that is, slanting in more than one direction and not 90° from one of the other views), the true shape and true size of the successive surface is based on auxiliary views.

Using the descriptive geometry method of projection not only gives true size and shape, but it also can be used to find intersections, true distances of lines in space, true angles between surfaces, and exact piercing points. Descriptive geometry graphically shows the solution to problems dealing with points, lines, and planes, and their relationship in space. In order to be able to apply descriptive geometry to various drafting problems, the drafter must know and understand the various basic steps involved. This chapter explains these basic steps. The basic theories covered in this chapter are:

- Projecting a line into other views
- Projecting points into other views
- Determining the true length of a line
- Determining the point view of a line
- Finding the true distance between a line and a point in space
- Determining the true distance between two lines in space
- Projecting a plane surface in space
- Developing an edge view of a plane surface in space
- Determining the true distance between a plane surface and a point in space
- Determining the true angle between plane surfaces in space

Steps Used in Descriptive Geometry Projection

All problems, regardless of their complexity, use the same procedures or steps. These steps ultimately must be done in the same order each time, although some intermediate steps may be selected or are optional. Like climbing a flight of stairs, each step must be executed, and only experience can give one the ability to perform multiple steps simultaneously. An example of the sequential steps needed in descriptive geometry problems is as follows: In order to find an edge view of a plane (flat surface), we must locate a true-length line in that plane (Step 1); a point view of the true-length line must be projected, which yields an edge view of the plane (Step 2); see ***Figure 8-1***. By projective means, it would be impossible to find the edge view of an oblique surface from normal views without performing Steps 1 and 2.



FIGURE 8-1 *Steps used to solve descriptive geometric problems.*

Notations

As we progress through sequential steps it is important to keep track of all views and points in space. (Recall that a straight line is composed of two spatially located end points.) To do this, we should use a system of *notations* or labeling. Each view and each point should be labeled to provide an accurate identity of each at all times. For purposes of this text, the following notations are used in this chapter.

Each point in space is called out in *lowercase letters.*

EXAMPLE:

a, b, c, d

Each *line* in space is identified by the two *lowercase end points.*

EXAMPLE:

Line a-b

Each line in space is assumed to end at the indicated end points, unless it is specified as an extended line (continues without end).

EXAMPLE:

Line p-q and Extended Line j-k

Each plane in space, such as a triangle, is called out in lowercase letters.

EXAMPLE:

Triangle abc

Each plane in space is assumed to be limited (stops at the indicated boundaries) unless otherwise defined as an *unlimited plane* (limitless extension beyond the indicated boundaries).

EXAMPLE:

Plane defg and Unlimited Plane mno

Each *viewing plane* is called out in *uppercase letters.*

EXAMPLE:

F = Frontal viewing plane (a principal plane).

T = Top (horizontal) viewing plane (a principal plane).

R = Right-side (profile) viewing plane (principal plane).

L = Left-side (profile) viewing plane (principal plane).

A(digit) = an auxiliary viewing plane, with the number of successive projections from a principal viewing plane.

B(digit) = same as A(digit), but using a different series of successive projections.

A combination of lowercase and uppercase letters is used to fully describe each point in space and the view in which it is located.

EXAMPLE:

aF would be a location as seen in the frontal viewing plane.

aT-bT would be line a-b location as seen in the top (horizontal) viewing plane.

aR-bR-cR would be plane a-b-c as seen in the right-side (profile) viewing plane.

Fold Lines

A fold line is represented by a thin black line, similar to a phantom line. It indicates a 90° intersection of two viewing planes. Each fold line must be labeled using uppercase letters, *Figure 8-2.* In this example, the fold line is placed between the front view and the top view. This placement eliminates the usual 45° projection line, *Figure 8-3.* It is important to add these notations in order to keep track of exactly which viewing plane is being executed.

FIGURE 8-2 *Fold line.*



FIGURE 8-3 *Regular multiview drawing using 45° projection line.*

How to Project a Line into Other Views

Fold lines are placed between successive orthographic views and labeled with uppercase letters, *Figure 8-4.* Any appropriate spacing is permissible, but the distance from the image to the frontal viewing plane fold line must be equal at both the top and right-side views. The spatial positioning of a line a-b (surrounded by an imaginary transparent box) is shown in *Figure 8-5.* Point a is closer to the frontal viewing plane than is point b, but it is farther below the top (horizontal) viewing plane. Represented on a normal layout drawing, it would be illustrated and labeled as shown in *Figure 8-6.*

The customary 45° projection line is not used in descriptive geometry projection. All points are projected along light projection lines drawn at 90° to the fold lines. All measurements are taken along these light projection lines and measured from the fold line to the point in space, *Figure 8-7.*



FIGURE 8-4 *Regular multiview drawing using fold lines instead of 45° projection line.*



FIGURE 8-5 *Spatial positioning of line a-b.*



FIGURE 8-6 *Line a-b in all three regular views.*



FIGURE 8-7 *Skip a view when transferring distances.*

An important rule to remember is to always skip a view between all measurements. In Figure 8-7, notice in the right-side view that dimension X (distance from F/R fold line to point aR) is projected into and through the front view and up to the top view and transferred into the top view. (Distance from F/T fold line to point aT.) The front view was skipped.

Again, referring to the right-side view of Figure 8-7, dimension Y (distance from F/R fold line to point bR) is transferred into the top view (distance from F/T fold line to point bT), and the front view was skipped. In each of the instances, the distance is measured as the perpendicular distance from the fold line to the point.

EXAMPLE:

To project a top view of a line from a given front and right-side view.

GIVEN: Line a-b in the front view and line a-b in the right-side view, ***Figure 8-8.*** Extend projection lines into the top view from the end points in the front view, aF and bF. Find the distances X and Y from the line end points in the right-side view aR and bR to the frontal viewing plane at fold line F/R and transfer them into the top view. Label all points and fold lines in all views. Be sure that all projections are made at 90° from the relevant fold lines, ***Figure 8-9.***

How to Locate a Point in Space (Right View)

A point in space is projected and measured in exactly the same way as a line in space, except that the point is a line with a single end point, ***Figure 8-10A.***



FIGURE 8-8 *Locating line a-b in top view.*



FIGURE 8-9 *Line a-b in the top view using the fold line.*



FIGURE 8-10 *(A) Locating a point in space (right view); (B) Step 1.*

EXAMPLE:

To project the right-side view of a point from a given top and front view.

GIVEN: Point a in the front view and top view (Figure 8-10A). Project point aF from the front view into the right-side view. Point aR must lie on this projection line. Find X, which is the distance from fold line F/T to aT in the top view and project it into and through the front view, *Figure 8-10B.* Project it over into the right-side view. Transfer distance X to find point a. Be sure to always label all points and fold lines in all views.

How to Find the True Length of a Line

Any line that is parallel to a fold line will appear in its true length in the next successive view adjoining that fold line.

To find the true length of any line:

STEP 1 Draw a fold line parallel to the line of which the true length is required. This can be done at any convenient distance, such as approximately 1/2″.

STEP 2 Label the fold line A for auxiliary view.

STEP 3 Extend projection lines from the end points of the line being projected into the auxiliary view. These must always be at 90° to the fold line.

STEP 4 Transfer the end point distances from the fold line in the second preceding view from the one being drawn, to locate the corresponding end points in the view being drawn.

EXAMPLE:

Refer to ***Figure 8-11A.***

GIVEN: Line a-b in the front view, side view, and top view. The problem is to find the true length of line a-b. A true length can be projected from any of the three principal views by placing a fold line parallel to the line in any view. The right-side view is selected in this example.

STEP 1 Draw a fold line parallel to line a-b, and label it as shown in *Figure 8-11B.* Extend light projection lines at 90° to the fold line from points a and b into the auxiliary view.

STEP 2 Determine distances X and Y from the front view to the near-fold line and transfer them into the auxiliary view, as shown in *Figure 8-11C.* Label all points and fold lines. The result will be the true length of line a-b.

Use these steps to find the true length of any line.

How to Construct a Point View of a Line

To construct a point view of a line:

STEP 1 Find the true length of the line.

STEP 2 Draw a fold line perpendicular to the true-length line at any convenient distance from either end of the true-length line.

STEP 3 Label the fold line A-B (B indicates a secondary auxiliary view).

STEP 4 Extend a light projection line from the true-length line into the secondary auxiliary view.

STEP 5 Transfer the distance of the line end points into the secondary auxiliary view (B) from the corresponding points in the second preceding view.



FIGURE 8-11 *(A) Finding the true length of a line; (B) Step 1; (C) Step 2.*



FIGURE 8-12 *(A) Constructing a point view of a line; (B) Step 1; (C) Step 2.*

EXAMPLE:

Refer to ***Figure 8-12A.***

GIVEN: Line a-b in the front view, side view, and auxiliary view. The true length is located in the auxiliary viewing plane (A), which is projected from the front view. (The true length could have been projected from any of the given views.)

STEP 1 At any convenient distance from either end, draw a fold line A/B perpendicular to the true length of line a-b. This will establish a viewing plane that is perpendicular to the direction of the line's path. Extend a projection line aligned with the true-length line into this new secondary auxiliary view. The projection lines from both points a and b appear to align in this common projection line. Therefore, both points a and b must be located on this projection line in the secondary auxiliary view. In ***Figure 8-12B,*** the fold line A/B was added to the left of the true-length line a-b.

STEP 2 The front view is the second preceding view to the secondary auxiliary view being constructed. Therefore, distance X in the front view from the fold line A/F to line a/b is transferred to the secondary auxiliary view from the fold line A/B, ***Figure 8-12C.*** As points a and b in the front view are both at the same distance from the fold line A/F, and they both lie on the same projection line in the secondary auxiliary view, they

will appear to coincide at the same location. This provides evidence that the end view of the line has been achieved.

How to Find the True Distance Between a Line and a Point in Space

The true distance between a line and a point in space will be evident in a view that shows the end point of the line and that point, simultaneously.

STEP 1 Project an auxiliary view (viewing plane A) to find the true length of the line, and project the point into the same view.

STEP 2 Project a secondary auxiliary view (B) to find the point view of the line, and project the point into the same view.

STEP 3 The observable distance between the end view of the line and the point will be the actual distance between them. The location in the line that is nearest to the point is on the path that is perpendicular to the line from the point, but this is not discernible in the secondary auxiliary view.

EXAMPLE:

Refer to ***Figure 8-13A.***

GIVEN: Line a-b and point c in the front view and right-side view.

STEP 1 Project the true length of line a-b by placing a fold line parallel to a given view of the line, and project point c into the auxiliary view. Recall that point locations are transferred from the second preceding view. Label all fold lines and all points, ***Figure 8-13B.***

STEP 2 Draw a fold line perpendicular to the true length of line a-b and label the fold line. Project line a-b into the secondary auxiliary view (B) to find the point view of line a-b. Project point c along into the second auxiliary view (B). The actual distance between the point view of line a-b/B and point cB is evident, ***Figure 8-13C.***

The location in the line a-b that is nearest to point c lies on a path that is perpendicular to line ab and passes through c. Any path that is perpendicular to a line will appear perpendicular in a view where the line is true length. Therefore, the path can be drawn in the preceding view to locate point p on the line. Point p can be projected to its correct location on the original views of line a-b.



FIGURE 8-13 *(A) Finding the true distance between a line and a point in space; (B) Step 1; (C) Step 2.*

How to Find the True Distance Between Two Parallel Lines

If two lines are actually parallel, they will appear parallel in all views. A view is needed to show the end view of both lines simultaneously, where the real distance between them will be apparent.

STEP 1 Find the true length of each of the two lines. Projecting a view that will provide the true length of a line will automatically provide the true length of any other parallel line that is projected into the same view.

STEP 2 Find the point view of each of the two lines. Projecting a view that will provide the end view of a line will automatically provide the end view of any other parallel line that is projected into the same view.

STEP 3 The true distance between the parallel lines is the straight-line path between their end points. There is no single location within the length of the lines where this occurs, as each location in a line has a corresponding closest point location on the other line, each on the path connecting them and perpendicular to their respective lines.

EXAMPLE:

Refer to ***Figure 8-14A.***

GIVEN: The parallel lines a-b and c-d, in a front view, right-side view, and a top view.

STEP 1 Find the true lengths of line a-b and line c-d in auxiliary view A. The two parallel lines will also be parallel in the auxiliary, if they are actually parallel, *Figure 8-14B.*

STEP 2 Draw a fold line perpendicular to the true-length lines, a-b and c-d. Project the lines into the secondary auxiliary view (B) to find the point view of the two lines a-b and c-d. Measure the true distance between the point views of lines a-b/B and c-d/B, *Figure 8-14C.*

How to Find the True Distance Between Two Nonparallel (or Skewed) Lines

If two lines are not parallel, they will appear nonparallel in at least one view. It is wise to first check two nonparallel (or skewed) lines to determine if they actually intersect, which would make the distance between them zero. This can be verified by projecting the apparent point of intersection of a view to the adjoining view. If the apparent points of intersection align, then the lines actually intersect.

To determine the true distance between two nonparallel lines:

STEP 1 Project the true length of either one of the two lines, and project the other line into that auxiliary view (A).

STEP 2 Find the point view of the true-length line, and project the other line into that secondary auxiliary view (B).

STEP 3 Measure the true distance between the point view line at a location that is perpendicular to the other line.

EXAMPLE:

Refer to ***Figure 8-15A.***

GIVEN: Nonparallel lines a-b and c-d in a front view and right-side view.



FIGURE 8-14 *(A) Finding the true distance between two parallel lines; (B) Step 1; (C) Step 2.*

STEP 1 Project the true length of line a-b in an auxiliary view (A), and project line c-d along into that auxiliary view, *Figure 8-15B.* Notice that c-d is not the true length.

STEP 2 Project the point view of line a-b into the secondary view (B) and project line c-d into this view. Measure the true



FIGURE 8-15 *(A) Finding the true distance between two nonparallel (or skewed) lines; (B) Step 1; (C) Step 2.*

distance between the point view of line a-b/B, perpendicular from line c-d/B, *Figure 8-15C.*

How to Project a Plane into Another View

A limited plane is located by points in space joined by straight lines. In order to transfer a plane, find at least three points in the plane and project each point into the next view.

EXAMPLE:

Refer to *Figure 8-16A.*

GIVEN: Triangular plane abc shown in the top view and front view.

STEP 1 In the top view, find the distance from the fold line to points aT, bT, and cT, *Figure 8-16B.*



FIGURE 8-16 *(A) Projecting a plane into another view; (B) Step 1; (C) Step 2.*

STEP 2 Project these points from the front view into the right-side view, and transfer the corresponding distances from the top view points to the top view fold line into the right-side view, *Figure 8-16C.* Construct straight lines between points a, b, and c. This transfers the plane surface.

How to Construct an Edge View of a Plane Surface

If the end view of a line that is in a plane is shown, then the edge view of that plane is shown also. Recall that to find the end view of a line, a true length must be found first. When the boundaries of a plane are provided, projecting a view to find the true length of a selected boundary is a simple procedure. It is necessary only to locate a fold line parallel to the boundary to ensure its true length in the next projected view.

A shorter method of securing a true-length line in a plane is also used, if a true-length line is not

present already. A line may be added on the plane in any view, arranged to be parallel to an adjoining fold line, and to have its terminations at the plane boundaries. Projecting the added-line terminations to the corresponding boundaries in the adjoining view relocates the added line in that view. Moreover, it will be a true-length line, as it was made to be parallel to the fold line in the preceding view.

Whichever method is used to find a true-length line in the plane, all point locations within the plane should be projected to the view where the true-length line exists, if not there already. A fold line perpendicular to the true-length line will provide a direction for projecting the edge view of the plane. Projecting all the points in the plane will provide evidence of this, as they will align into a single, straight path.

EXAMPLE:

Refer to *Figure 8-17A.*

GIVEN: Plane surface abc in the top view and front view.

STEP 1 Construct a line parallel to fold line F/R and through one or more points, if possible. In this example, the line passes through point c. Label this newly constructed line cF/xF, *Figure 8-17B.*

STEP 2 Construct the true length of line cF/xF in the next view, *Figure 8-17C.*

STEP 3 Construct the point view of the true-length line cR/xR. Project the remaining points of the plane surface into this view. Also, label all points and fold lines. If done correctly, the result should be a straight line that passes through the point view. This straight line is the edge view of the plane, *Figure 8-17D.*

STEP 4 Construct a fold line A/B parallel to plane abc (shown as an edge in view A) and construct the plane surface abc in view B. Plane surface abc is now seen in true size, in view B, *Figure 8-17E,* because plane abc was seen as an edge in the adjacent view A.



FIGURE 8-17 *(A) Constructing an edge view of a plane surface; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4.*

How to Find the True Distance Between a Plane Surface and a Point in Space

Finding the true distance between a given point and a plane in space requires a view that shows the edge view of the plane and the point in the same view. The distance from the point to the plane is the path that is perpendicular to the plane and passing through the point.

STEP 1 Add a line on the plane parallel to a fold line, if a true-length line is not already available in the plane.

STEP 2 Project the added line to an adjoining view, where it will be seen in true length.

STEP 3 Project a point view of the added true-length line.

STEP 4 Project the points of the plane into this view. The result should be a straight line that passes through the added line end view, which is the edge view. Project the point in space into this view. Measure the perpendicular distance from the plane's edge view to the point in space. This is the true distance between the plane surface and the point in space.

EXAMPLE:

Refer to ***Figure 8-18A.***

GIVEN: Triangular plane abc and point X in the front view and right-side view.



FIGURE 8-18 *(A) Finding the true distance between a plane surface and a point in space; (B) Step 1; (C) Step 2; (D) Step 3.*

STEP 1 Construct a line parallel to the fold line F/R and through one or more points. Point c is a convenient line termination. Label this newly constructed line cR/zR, *Figure 8-18B.*

STEP 2 Construct the true length of line cR/zR in the front view, and label the line cF/zF, *Figure 8-18C.* Bring point X into this view, also. Label all points and fold lines.

STEP 3 Project the end view of the true-length line cF/zF in the auxiliary view, *Figure 8-18D.* Project the points of the plane surface into this view, and also point X, projecting 90° from the fold line. Label all points and fold lines. Measure the perpendicular distance from the edge view to the point in space. This is the true distance between the plane surface and the point X in space.

How to Find the True Angle Between Two Planes (Dihedral Angle)

The edge of intersection between two planes is a line that is common to both planes. The end view of that line will provide the edge view of both planes simultaneously, and the angle between them will be evident.

To find the true angle between two surfaces:

STEP 1 Construct the true length of the intersection between the two surfaces, and project all other points of both planes into that auxiliary view.

STEP 2 Project the end view of the true-length edge of intersection line and project the points of both planes into this secondary auxiliary view. Label all points and fold lines. Measure the true angle between the two surfaces.

EXAMPLE:

Refer to *Figure 8-19A.*

GIVEN: Plane abc and plane abd that intersect one edge, a-b, in the front view, side view, and top view.

STEP 1 Project the true length of the edge of intersection a-b, and project all other points into this auxiliary view (A), *Figure 8-19B.*

STEP 2 Project the point view of the true length of the edge of intersection a-b and project all other points into this secondary auxiliary view (B), *Figure 8-19C.* Measure the true angle between two surfaces.



FIGURE 8-19 *(A) Finding the angle between two surfaces; (B) Step 1; (C) Step 2.*

How to Determine the Visibility of Lines

To determine which line of an apparent intersection of two lines is closer to the viewer, the following steps are used.

STEP 1 From the exact crossover point of the lines, project to an adjoining view.

STEP 2 In the adjoining view, determine which of the lines is closest to the fold line between the views, on the projection line from the first view (or the first line that the projection line encounters on its path from the first view).

STEP 3 Whichever line is closest to the fold line at that point only is the line that is in front of the other line in the first view.

EXAMPLE:

Refer to ***Figure 8-20A.***

GIVEN: Lines a-b and c-d in the front view and top view.

STEP 1 At the exact crossover of lines a-b and c-d in the top view, project down through the fold line to the corresponding lines in the front view. At this exact point along the lines, line c-d is closer to the fold line and line a-b is farther away from the fold line; thus, in the top view, line c-d is in front of line a-b, *Figure 8-20B.*

STEP 2 See *Figure 8-20C.* At the exact crossover of lines a-b and c-d in the front view, project up through the fold line to the corresponding lines in the top view. At this exact point along the lines, line a-b is closer to the fold line and line c-d is farther away from the fold line; thus, in the front view, line a-b is in front of line c-d.

STEP 3 The result is drawn to illustrate this crossover, *Figure 8-20D.*



FIGURE 8-20 *(A) Determining the visibility of lines; (B) Step 1; (C) Step 2; (D) Step 3.*



FIGURE 8-21 *Determining the piercing point by inspection.*

How to Determine the Piercing Point by Inspection

The *piercing point* is the exact location of the intersection of a surface and a line. The exact piercing point is determined from the view where the surface appears as an edge view. In *Figure 8-21A*, the top view illustrates the edge view of the surface. The piercing point is established in the top view and projected down into the front view, *Figure 8-21B*. In *Figure 8-22A*, the front view illustrates the edge view of the surface. The piercing point is established in the front view and projected up into the top view, *Figure 8-22B*.

How to Determine the Piercing Point by Construction

To determine the exact piercing point by construction:

STEP 1 Construct a true length of a line on the plane surface.

STEP 2 Project a point view of the true-length line and an edge view of the plane surface. The edge view of the plane lies in the path of the line in this view, indicating the piercing point location.



FIGURE 8-22 *Determining the piercing point by inspection.*

STEP 3 Transfer the piercing point back into the other views.

STEP 4 Determine the visibility of lines to find which part of the line is visible from the viewing direction. Use the fold line to determine visibility, if necessary.

EXAMPLE:

Refer to ***Figure 8-23A.***

GIVEN: Plane surface abc and line x-y, in the top view and front view.

STEP 1 In the front view of plane abc, construct a line parallel to fold line bF-dF and find its true length in the top view, *Figure 8-23B.*

STEP 2 Project an auxiliary view to find the point view of the true-length line from the top view and the edge view of the plane. The line intersection with the edge view of the plane indicates the piercing point location, *Figure 8-23C.*



FIGURE 8-23 *(A) Determining the piercing point by construction; (B) Step 1.*



FIGURE 8-23 *(Continued) (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5.*

STEP 3 Project the piercing point back into other views, *Figure 8-23D.*

STEP 4 In each view that the piercing point is being projected to, the portion of the line that is visible can be determined by checking its preceding view, *Figure 8-23E.*

Notice in the auxiliary view that line x-y is closer to the fold line from the piercing point to point yA than is the edge view of the plane surface from the piercing point to point cA. Therefore, in the top view, line x-y is seen only from the piercing point to yT.

STEP 5 By viewing back into the top view, determine the visibility of lines of the plane surface and line x-y in the front view, *Figure 8-23F.* Notice in the top view that line x-y is closer to the fold line from the piercing point to point yT than is the edge view of the plane surface cT/bT; therefore, in the front view, line x-y is seen only from the piercing point to yF.

When the edge view does not appear in the regular views, it must be constructed using the preceding steps, *Figure 8-24A.* Once the edge view is constructed, the piercing point can easily be seen. The piercing point is now projected down into the front view and up into the top view, *Figure 8-24B.*

How to Determine the Piercing Point by Line Projection

An alternate method of determining the piercing point simply locates the path of a cutting plane that passes through the line, leaving a "scar" on the surface of the given plane. Since the line lies in the cutting plane, an intersection of the line and the scar on the given plane locates the piercing point. The end points of the scar are found by aligning the cutting plane with the given line in one view, where it crosses the boundary of the given plane in two places. Projecting the cutting plane intersection to the corresponding boundaries of the given plane in the next view locates the scar end points in that view, and it provides a view of the scar that the given line can cross at the piercing point.



FIGURE 8-24 *Determining the piercing point by construction.*



FIGURE 8-25 *Determining piercing points by line projection (skewed surface).*

EXAMPLE:

*See **Figure 8-25A.***

GIVEN: Skewed surface abc and a line.

STEP 1 In the top view, lightly draw the piercing line and determine points x and y where they cross the boundary of plane abc. The piercing point is located somewhere between these points.

STEP 2 Project points x and y down into the front view to the corresponding edges of the plane abc, *Figure 8-25B*. Where line x-y crosses the given line is the exact piercing point.

STEP 3 Project the piercing point to the top view, *Figure 8-25C*. The visibility of the piercing line is determined by inspection.

Figure 8-26A illustrates a cylinder pierced by a line. Lightly draw the piercing line in the top view and find point x. Project point x down into the front view, *Figure 8-26B*, to find piercing point x. Because the piercing line exits the skewed surface, piercing point y is found on the edge view of the front view, *Figure 8-26C*. Project piercing point y up into the top view. Visibility of the piercing line is determined by inspection.

If the object is a cone, line segments must be located and drawn from the base of the cone up to the vertex of the cone.

GIVEN: A cone with a piercing line, *Figure 8-27A*.

Lightly draw the piercing line in the top view and find points x and y, *Figure 8-27B*. Project points x and y down to the base of the cone. Project light line segments from points x and y on the base up to the



FIGURE 8-26 *Determining piercing points by line projection (cylinder).*



FIGURE 8-27 *Determining piercing points by line projection (cone).*

vertex of the cone. Where these lines cross the piercing line is the location of the two piercing points. Visibility of the piercing line is determined by inspection, *Figure 8-27C.*

If the object is spherical, an imaginary flat surface on the sphere must be established along the piercing line.

GIVEN: A sphere with a piercing line, *Figure 8-28A.*

Lightly draw the piercing line in the top view. Where the piercing line intersects with the sphere is the location of the imaginary flat surface, *Figure 8-28B.* This also establishes the diameter of the flat surface.



FIGURE 8-28 *Determining piercing points by line projection (sphere).*

Transfer the imaginary flat surface to the front view. Where the piercing line intersects the imaginary flat surface are the exact piercing point locations. Once the piercing point locations are found they are projected up into the top view, *Figure 8-28C*. The visibility of the piercing line is determined by inspection.

How to Find the Intersection of Two Planes by Line Projection

The intersection of two planes can be determined by generating an edge view of one of the planes. Another method, somewhat simpler, is the line-projection method.

GIVEN: Two plane surfaces, *Figure 8-29A*.

In the top view, locate points x and y on edge ab of one of the planes. Project points x and y down into the front view as illustrated in *Figure 8-29B* and draw a light line from x-y in the front view. The piercing point is where line x-y crosses the edge ab. Project points from edge ac of the same plane. Project these points down into the front view. Draw a line connecting these points; where they cross edge ac is the exact piercing point. Complete the views as illustrated in *Figure 8-29C*.

How to Find the Intersection of a Cylinder and a Plane Surface by Line Projection

The intersection of a cylinder and a plane surface can also be determined by generating an edge view of the plane surface. Another method is the line-projection method.

GIVEN: A cylinder and a plane surface, *Figure 8-30A*.

Divide the circle into equal parts; in this example, 12 equal parts. Extend these lines out to the edges of the plane surface, *Figure 8-30B*. The example illustrated uses points 1 o'clock and 7 o'clock to find



FIGURE 8-29 *Determining the intersection of two planes.*



FIGURE 8-30 *Determining the intersection of a cylinder and a plane surface.*

points x and y on the edge of the plane surface. Project points x and y down into the front view. Draw a line from x-y in the front view. Points 1 o'clock and 7 o'clock are located somewhere on this line. To find their exact locations, project points 1 and 7 from the top view to the line in the front view. Continue around the various points to locate each of the 12 points. Complete the drawing as shown in *Figure 8-30C*.

How to Find the Intersection of a Sphere and a Plane Surface

GIVEN: A sphere and a plane, *Figure 8-31A*.

Construct an edge view of the plane, *Figure 8-31B*. Divide the sphere into even spaces as illustrated. Think of each evenly spaced line as an imaginary sliced-off portion of the sphere. Draw each imaginary slice in the top view, and where the projection from the corresponding point on the edge view crosses is the piercing point. Complete the top view as illustrated. Once these points have been found in the top view, the line-projection method is used to transfer them to the front view, *Figure 8-31C*.

How to Find the Intersection of Two Prisms (Method 1)

GIVEN: The top, front, and right-side views of two intersecting prisms, *Figure 8-32*.

Label the various points as illustrated. Project each point to the 45° projection and into the next view, and where they intersect is the location of each point,



FIGURE 8-32 *Finding the intersection of two prisms (method 1).*

as illustrated. The only point in question is point x; using the three views, it can be easily found.

How to Find the Intersection of Two Prisms (Method 2)

With only two views, there is a problem locating point X in the front view. Refer to *Figure 8-33*. In the top view, extend line c′-x where it crosses line segment a-a′. Project point y down into the front view to line a-a′. Draw a line from c′ to y to locate point x in the front view.

Bearings, Slope, and Grade

In some fields of drafting the exact position of a line in space is described by its *bearing* and *slope* or by its bearing and *grade*.



FIGURE 8-31 *Determining the intersection of a sphere and a plane surface.*



FIGURE 8-33 *Finding the intersection of two prisms (method 2).*

Bearing of a Line

The bearing or *heading* of a line is the direction of that line as it is drawn in the *top view* of a drawing on a map. Using a map of a given area on the earth's surface, a view looking directly down would be an example of how a bearing of a line is used.

There are two methods used to call off a bearing. It is called off by either its *north/south deviation* or by its *azimuth bearing*.

North/South Deviation

A bearing of a line is measured in degrees with respect to the north or the south. It is customary to consider the north as being located from the top of the page and the south as being located from the bottom of the page, unless otherwise noted, ***Figure 8-34***. Bearings are called off in angles less than 90° and are always given from the north or south, heading toward either the east or west, ***Figure 8-35***. In this example a line, 1-2, is projected 45° from the north and toward the west. It has a bearing of, and is called off as, N 45° W. A line, 1-2, is projected 30° from the south toward the east, ***Figure 8-36***. It has a bearing of, and is called off as, S 30° E. It is important to know where the point of origin or the beginning of the line is, and in which direction the line is heading, ***Figure 8-37***. Line 2-2′ could be called off as either N 45° W or as S 45° E, depending on its point of origin. If the line is projected from point 1 to point 2, the bearing would be N 45° W; if from 1′ to point 2′, the bearing would be S 45° E.



FIGURE 8-34 *North, south, east, west headings; north is usually located at the top of the page.*

Azimuth Bearing

In using the azimuth bearing method, the total angle is used, going *clockwise* from the north. A given line, 1-2, is drawn at 45° from the north and heading toward the west, ***Figure 8-38***. Using the azimuth method and



FIGURE 8-35 *A line with a heading of N 45° W; headings are always drawn in the top view.*



FIGURE 8-36 *A line with a heading of S 30° E.*



FIGURE 8-37 *This line could be either N 45° W or S 45° W, depending upon the starting point and the direction in which it is projected.*



FIGURE 8-38 *Azimuth bearing is indicated from the north clockwise to the line.*

measuring clockwise from the north, it has a bearing of 315°, (90° plus 90° plus 90° plus 45°). It is usually understood that the north bearing is the starting point, thus the N is usually omitted in verbally describing the bearing; on the drawing, however, it is best to use the N or North so as to avoid any confusion. Note that bearing is sometimes noted as heading.

Slope Angle

Using the slope angle is a way to describe the inclination of a line. The slope of a line is the angle, in degrees, that the line makes with a horizontal (level) plane, *Figure 8-39*. The line is heading from point 1 toward point 2, and it is rising; therefore, it is a plus (+) slope angle.

Note that the *true slope* of a line can be seen only in the view that has a horizon (level) line and in which it is drawn as a *true length*, *Figure 8-40*. In this example,



FIGURE 8-39 *Slope angle is the angle in degrees from the horizon.*



FIGURE 8-40 *True slope angle of a line can be seen only in a view that has a horizon line. It is noted in degrees.*

the true length can be found from the front view and/or from the top view. However, projecting from the front view will **not** give a horizon (level) line—it is found only by projecting from the top view.

Grade Percent

Another way to describe the inclination of a line in relation to the horizon is by the ratio of the vertical rise (R) to the horizontal (H). It is expressed in percent and calculated by the simple formula:

$$\text{PERCENT OF GRADE} = \frac{\text{UNITS OF VERTICAL RISE (R)}}{\text{UNITS OF HORIZON (H)}} \times 100$$

Figure 8-41 illustrates a simple 45° angle line with 100 horizontal units and 100 vertical units. 100 divided by 100 times 100 equals a 100% grade. If the



$$\text{GRADE} = \frac{R}{H} \times 100$$

$$\text{GRADE} = \frac{100}{100} \times 100$$

$$\text{GRADE} = 1 \times 100$$

$$\text{GRADE} = 100\%$$

FIGURE 8-41 *Grade percent is the inclination of a line in relation to the horizon, noted in percent.*



$$\text{GRADE} = \frac{R}{H} \times 100$$

$$\text{GRADE} = \frac{85}{148} \times 100$$

$$\text{GRADE} = .57 \times 100$$

$$\text{GRADE} = 57\ \%$$

FIGURE 8-42 *Example of a line with a grade of 57%.*

angle were 30°, the grade would be 57%, ***Figure 8-42.*** The most common method of measuring the horizontal and vertical units is with an engineer's scale using multiples of 10. Percent of grade is another way to express the slope of a line, but, as in laying out grade percents, **the view that has both the true horizon and true length must be used.** Refer back to Figure 8-40.

Other Ways to Call Off the Slope of a Line

Various fields of drafting use slightly different methods to call off the specified inclination of lines. Each method is similar to that of calling off percent of slope and/or percent of grade in that each expresses the relationship of the line to the horizontal (level) plane. Three common methods are pitch, bevel, and batter.

FIGURE 8-43 *Pitch is the slope of a roof and is a ratio of vertical rise for every 12″ or 12′ of horizontal span.*

PITCH

Pitch is usually used in the architectural field of drafting and is used to call off the slope of a roof. It is expressed as the ratio of vertical rise to 12″ or 12′ of horizontal span, ***Figure 8-43.*** In each horizontal 12″ the roof rises 6″.

BEVEL

In structural engineering, where steel members are used in the construction of the building, the slope of a member is called off by the *bevel* of the beam, ***Figure 8-44.*** It is very similar to that of the pitch used in architectural drafting.

BATTER

In the field of civil engineering the slope of the grade (earth) is used and is referred to as *batter.* It is called off as illustrated by ***Figure 8-45.*** This means that for each unit of rise (R), there are four horizontal (H) units.

Angles Between Bearings or Headings

If you know the bearings of two lines, the angle between the lines can be determined, ***Figure 8-46.*** Given are lines 1-2 and 1-3, as illustrated. Both these



FIGURE 8-44 *Bevel is used in structural engineering to indicate the slope of a structural member.*



FIGURE 8-45 *Batter is used in the civil engineering field to indicate the slope of a grade.*



FIGURE 8-46 *Angle between two headings in one quadrant (90°).*



FIGURE 8-47 *How to calculate the angle between headings in one quadrant.*

lines fall within one 90° quadrant; therefore, to find the angle between the lines, subtract one bearing from the other, ***Figure 8-47***. Fifteen degrees is subtracted from 80°, and the true angle between the bearings is 65°.

If the bearings fall within two or more quadrants, the actual angles in each quadrant must be added or subtracted, as illustrated in ***Figures 8-48, 8-49, 8-50,*** and ***8-51***.

How to Construct a Line with a Specified Bearing, Slope Angle, and Length

The bearing is always drawn in the top view, and the true length can be drawn if the line is to be exactly horizontal. Any line with an incline up (+) or down



FIGURE 8-48 *Angle between two headings in three quadrants.*



FIGURE 8-49 *How to calculate the angle between headings in three quadrants.*



FIGURE 8-50 *Angle between two headings in four quadrants.*



FIGURE 8-51 *How to calculate the angle between headings in four quadrants.*

(–) from the horizon **must** be laid out using the following steps:

GIVEN: The starting point aT and aF of a line with a bearing of N 60° E, with a slope angle of +15°, and 230.0′ long, *Figure 8-52A*.

Because the line is **not** horizontal and has a slope angle of plus (+) 15°, the true length must be constructed before the heading length can be drawn in the top view.

STEP 1 In the top view, draw a line starting from aT, at 60° from the north and toward the east, *Figure 8-52B*. Temporarily draw the line longer than the 230.0′ required.

STEP 2 Find the true length of the line by adding a fold line, T/A, parallel to the bearing line aT. Project point a into the auxiliary view to find aA, *Figure 8-52C*, and refer to dimension X. Don't forget to skip a view.



FIGURE 8-52 *(A) Constructing a line with a specified bearing, slope angle, and length; (B) Step 1; (C) Step 2; (D) Step 3.*

From point aA in the auxiliary view, draw a light horizon line parallel to the fold line T/A. From point aA, construct a 15° angle toward the fold line as shown.

NOTE: Draw the line toward the fold line for a rise (+) and away from the fold line for a drop (–) in elevation. Along this line measure the true length, 230.0′, to establish point bA. Project bA back into the top view to find point bT. Remember, this line is ***not*** *the true length in the top view.*

STEP 3 Project point bT down into the front view to find point bF. Use the Y dimension to find point bF, but do not forget to skip a view, *Figure 8-52D.* Construct line aF/bF. Note that the line rises from a to b in the front view, which indicates a plus (+) rise.

The true bearing is found in the top view and the true length is found in the auxiliary view. Remember, true length must be found before the other views can be completed.

How to Construct a Line with a Specified Bearing, Percent of Grade, and Length

Approximately the same steps are used in constructing a line with a specified bearing, percent of grade, and length as was used in constructing a line with a specified bearing, slope angle, and length. The bearing is always drawn in the top view, and the true length of the line can be drawn if the line is to be **exactly** horizontal. Any line with an incline up (+) or down (–) from the horizon **must** be laid out using the following steps:

GIVEN: The starting point aT and aF of a line with a bearing of N 45° W, with a grade of (–) 40%, and 190.0 feet long, *Figure 8-53A.* Because the line is **not** horizontal and has a grade of minus (–) 40%, the true length must be constructed before the bearing length can be drawn in the top view.

STEP 1 In the top view, draw a line starting from aT, at 45° from the north and toward the west, *Figure 8-53B.* Temporarily draw the line actually longer than the 190.0′ required.

STEP 2 Find the true length of the line by adding a fold line, T/A, parallel to the bearing line aT. Project point a into the auxiliary view to find aA, *Figure 8-53C,* and refer to dimension X. Don't forget to skip a view.

From point aA in the auxiliary view, draw a light horizon line parallel to the fold line T/A. From point aA, and along the horizon line, measure 100 units. From this point, turn 90° away from the fold line and measure 40 units, and put a point there. Construct a line from aA to this new point and extend it out to the 190.0′ true length to find point bA.

NOTE: Construct the triangle toward the fold line for a rise (+) and away from the fold line for a drop (–) in elevation. Project bA back into the top view to find point bT. Remember, this line is not the true length in the top view.

STEP 3 Project point bT down into the front view to find point bF. Use the Y dimension to find point bF, but do not forget to skip a view, *Figure 8-53D.* Construct the line aF/bF. Note that the line falls from a to b in the front view, which indicates a minus (–) drop. The true bearing is found in the top view and the true length is found in the auxiliary view. Remember, true length must be found before the other views can be completed.

Applied Descriptive Geometry

The topics in the remainder of this chapter are essentially applications of the descriptive geometry basics already presented. Some of the topics are contours and topographic maps, vectors, forces in trusses, and revolution.

Topographic Topics

Surveys

Compass directions with distances describe real estate boundaries in cities and counties for commercial and domestic property owners. The descriptions usually include references to governmental surveys, such as being located in a government lot, section, township, and range and they have specific coordinates so a surveyor can locate the property and stake out the area. Architects and builders have drafters prepare scaled drawings of the areas for planning the locations of buildings and houses.

How to Plot the Boundary of Real Estate

EXAMPLE:

GIVEN: Compass bearings with distances in feet, outlining a real estate lot, shown in a rough sketch with north in the traditional direction toward the top of the sheet, *Figure 8-54A.*



FIGURE 8-53 *(A) Constructing a line with a specified bearing, percent of grade, and length; (B) Step 1; (C) Step 2; (D) Step 3.*

STEP 1 Lay out the boundary to scale starting with the S17° W 59′, then the S31° W 47′, and next the S54°30′ E 170′ while utilizing the drawing area efficiently: for example, the direction north may not be toward the top of the sheet, *Figure 8-54B*. Note that the 71°30′ angle shown is an internal angle, and that the sum of all the internal angles equals (number of sides N – 2) × 180°. For the layout shown, (N – 2) × 180° = (5 – 2) × 180° = 540°. The 85°30′ angle is called a deflection angle; this is the smallest angle the surveyor must turn the transit to align with the next side. The sum of all the deflection angles must equal 360° for a complete traverse around the property.

STEP 2 Complete the boundary with N26°25′104″ next and N54°30′ W 176′ last. The last segment should close on the starting point, *Figure 8-54C*.

For excavation and landscaping planning, an architect may ask a drafter to draw in contour lines. This is the topic of the next section.

Contour Lines

A *contour line* on a plot or map is a line at a constant elevation on the surface of the earth, above sea level,



(A)



(B)



(C)

FIGURE 8-54 *(A) Compass bearings and distances: Real estate lot; (B) Step 1; (C) Step 2.*

Figure 8-55A. A *contour interval* is the difference in elevation between neighboring contour lines. It is the same value for any one drawing. For example, 50′ is the interval in Figure 8-55A due to mountainous terrain. Intervals of 10′ are common; architectural plots may have only 1′ intervals on relatively level terrain for houses or buildings.

Usually, every fifth contour line is heavier and its elevation indicated. Lines close together represent steep terrain.

Profiles

Imagine a vertical plane cutting through a contoured map and being able to see the cross section at the cut.

The cross section would show a profile of the terrain in an elevation view, as illustrated in *Figure 8-55B* for a straight path from point A to point B. The fold line is added as a reminder that all topographic maps are T views, and elevations, of course, occur in views projected off a T view.



(A)

FIGURE 8-55 *(A) Contour map.*



(B)

FIGURE 8-55 *(Continued) (B) profile.*

Cuts and Fills

Highways passing through hilly terrain require that the earth of some hills be excavated and the earth used to fill in valleys—*cuts and fills, Figure 8-56.* The volume of the earth to be cut and filled needs to be determined prior to having an army of construction workers and their equipment arrive at the job site, for efficient use of labor and equipment. The volume of the cut determines how much fill can be completed. Volumes of cuts and fills are determined from boundary maps.

How to Determine the Boundaries of Cuts and Fills from Topographic Maps with Contour Lines

EXAMPLE:

GIVEN: A portion of a topographic map with contours and the proposed location of a 60′ wide, level road, at an elevation of 500′, *Figure 8-57A.* The fold line T/F is perpendicular to the direction of the road, and the F view shows elevation planes at 10′



FIGURE 8-56 *Cuts and fills.*

intervals; the topographic map and the elevations are drawn to the same scale.

STEP 1 Construct cutting planes at 45° to the horizontal in the elevation view F, to each side of



(A)

FIGURE 8-57 *(A) Proposed road.*



FIGURE 8-57 *(Continued) (B) Step 1; (C) Step 2.*

the proposed 60′ wide road, ***Figure 8-57B.*** Where the cutting planes intersect the elevation planes, mark the corresponding intersections on the map. Connect the intersections, freehand, to show the boundaries of the excavation cut, Figure 8-57B.

STEP 2 In a similar manner construct cutting planes at 45° to represent the proposed earth fill, and mark the boundaries as before, ***Figure 8-57C.*** Note that the angles of cuts and fills vary—for example, a commonly used fill has a slope of 1.5 horizontal to 1.0 vertical.

How to Determine the Volumes of Cuts and Fills (Graphical, Mechanical, and Electronic)

EXAMPLE:

GIVEN: The cut and fill boundaries from the preceding example shown in a simplified T view, ***Figure 8-58A.***

STEP 1 Start at the 500′ elevation. Divide the cut and the fill with vertical planes at 25′ intervals called stations (STA), ***Figure 8-58B.*** Estimate the elevations of the points where the vertical planes at each station intersect the boundaries by reading the contour lines.

STEP 2 Construct scaled drawings of the profiles at the stations, and determine the area of each profile by using a graphical method for calculating geometric areas, ***Figure 8-58C.*** Tabulate the results.

Three methods used to calculate geometric areas of cross sections are graphical, mechanical, and electronic. The three are applied to a variety of problems, such as cuts and fills, cross sections of ship and boat hulls, and cross sections of layers of odd shapes for volume calculations.

A *graphical method* for approximating areas was used in Figure 8-58C. The method is to divide the area into convenient





	STA	ft²
CUTS	5 + 00	10,412
	4 + 00	7,442
	3 + 00	5,316
	2 + 00	3,502
	1 + 00	900
	0	0
FILLS	1 + 00	2,070
	2 + 00	4,620
	3 + 00	6,900

(C)





FIGURE 8-58 *(A) Cut and fill boundaries; (B) Step 1; (C) Step 2 (graphical method); (D) Mechanical method; (E) Electronic method.*

shapes, such as trapezoids and triangles, to scale appropriate lengths, and to calculate the areas.

A mechanical method utilizes a planimeter shown in the conceptual sketch, ***Figure 8-58D***. Pole arm OA is confined to swivel about point O. Point P is a pointer the operator uses to trace the complete boundary, drawn to scale, causing an indicating wheel to rotate and slide. The wheel's final position gives a reading of the area traversed.

An electronic method employs a computer and a digitizer (looks like a computer mouse). A cross-haired window at the bottom of the digitizer is positioned at small increments of distances around the boundary

of an area, *Figure 8-58E*. At each increment along the boundary, a key on the digitizer is clicked. This causes X-Y coordinates to be stored in a computer. Finally, the computer uses the coordinates to calculate the digitized area.

STEP 3 Calculate the amount of earth to excavate (cut) between two stations (STA) by averaging the areas at the stations and multiplying by the 25′ distance between the stations. For example, the area STA 2 + 00 of the cut = 3,502 square feet; the area at STA 3 + 00 of the cut = 5,316 square feet; the volume between STAs 2 and 3 of the cut is (3,502 + 5,316)/2 × (25) = 110,225 cubic feet. The volume in cubic yards (called yards in construction) is 110,225/27 = 4,082. Use this calculation procedure to determine the volume of earth between STAs 0 + 00 and 5 + 00 of the cut, Figure 8-58B. Get 20,709 yards available for fills. The fill requirement (using the same calculation procedure) for the volume between STAs 0 + 00 and 3 + 00 FILLS is only 9,390 yards. The remaining earth from the cut would be used to fill to additional stations.

Strike and Dip

Strike and dip are terms used in mining to describe three attributes of ore veins, *Figure 8-59*. *Strike* is a compass direction of a horizontal line lying in the plane of an ore vein. *Dip* is the downward angle of the vein with respect to a horizontal plane at the site of the ore vein. Dip also includes the general compass direction of the downward slope.

The vein in Figure 8-59 would be described as N64°30′ E, 35° NW, that is, the compass direction of the strike and the 35° dip downward toward the NW.



FIGURE 8-59 *Strike and dip attributes.*

How to Determine the Strike and Dip of a Vein of Ore (or Stratum of Rock)

EXAMPLE:

GIVEN: The depths of three core-holes, a, b, and c, sunk over a discovered ore vein, *Figure 8-60A*.

STEP 1 Lay out the points a, b, and c in a T view to scale, Figure 8-60A. Since the points, which are at different depths, do not fall in a straight line, they describe a triangular plane lying in the vein, *Figure 8-60B*.

STEP 2 Find plane abc as an edge in view A by using fold line T/A, *Figure 8-60C*, and the technique described in Figures 8-17A through 8-17D in this chapter.



FIGURE 8-60 *(A) Core holes for vein location; (B) Step 1.*





FIGURE 8-60 *(Continued) (C) Step 2; (D) Step 3.*

STEP 3 In view A measure the dip angle, and in the T view measure the strike bearing, *Figure 8-60D*. Note the general direction of the dip to complete the attributes of the ore vein—N76° W, 52° NE.

How to Determine the Strike and Dip of a Vein Given Two Lines in the Plane of the Vein and Intersecting

EXAMPLE:

GIVEN: Two apparent dip directions (not strikes) and angles of the dips as follows: N61° W, 40° and N22° E, 25° both originating from the same point p, a bore-hole, *Figure 8-61A*.

STEP 1 Construct view A using fold line T/A parallel to DIP1 to obtain the true view of the dip. Construct view B using T/B parallel to DIP2 to obtain its true view, *Figure 8-61B*. From points pA and pB lay out the same distance, X, downward. Label the marks d1A and d2B, respectively.

STEP 2 Project the points d1A and d2B into the T view and note that the line d1T-d2T is horizontal and, therefore, the strike of the ore vein, *Figure 8-61C*.

STEP 3 Project the triangle (p-d1-d2)T into a view C using fold line T/C perpendicular to the strike line, and measure the true dip angle, *Figure 8-61D*. The true strike and dip are N52° E, 43° NW.





FIGURE 8-61 *(A) Given: Dip directions and angles; (B) Step 1.*



FIGURE 8-61 *(Continued) (C) Step 2; (D) Step 3.*

Vectors

A *vector* as defined in engineering, technology, and mathematics must have both magnitude and direction. The vector shown in *Figure 8-62*, drawn to scale and having an arrowhead at one end, could represent any one of the following: displacement (length and direction); force (pounds and direction); velocity (distance per unit of time and direction); or acceleration (distance per unit of time squared and direction). As a comparison, direction only is a characteristic of the omnipresent straight line with an arrowhead at one end. A straight line with arrowheads at both ends in dimensioning indicates magnitude. These are not vectors, but they efficiently convey information in technical material, such as compass bearings, cursor positions, callouts, identifying features, and of course dimensions on orthographic drawings, *Figure 8-63*. Magnitudes without directions are called *scalars*, such as temperature and pressure.

Vector equivalents of physical systems are simplifications used in engineering so that the vectors can be manipulated efficiently in mathematical formulas. For example, bulky objects or portions of a bridge deck are assumed to be loads concentrated at a point. Internal loads, although acting over an area, are assumed to be point loads acting at the centroid of the area. All parts of an object traveling at the same velocity are represented by one velocity vector acting at the center of mass of the object *Figure 8-64*. Always keep in mind that these simplifications do not change the physical situation, and that point loadings are only approximate. Thus, graphical solutions employing these simplifications are as accurate as mathematical solutions. A number of the vector manipulations that can be done graphically are discussed in this chapter, for two main reasons—to demonstrate the efficacy of graphics and to emphasize that when you can visualize what is going on, you will have a better understanding of the analysis and the answer.

Vectors will be labeled with capital letters, e.g., F(AB) is a force F in the direction of, or in, member AB. An applied load would be W or F. A velocity vector would be V.



FIGURE 8-62 *Vector.*



FIGURE 8-63 *Non-vectors.*



FIGURE 8-64 *Vectors used in engineering simplifications.*

Vector Systems

Six possibilities exist for analyses using vectors: coplanar (concurrent, parallel, and nonparallel) and noncoplanar (concurrent, parallel, and nonparallel). Coplanar-concurrent and noncoplanar-concurrent are the categories to be emphasized in this chapter.

Coplanar-Concurrent Force Systems—The Parallelogram Law: Two Vectors

The *parallelogram law* basically states that two vectors, not parallel, drawn to scale, having the same units, and acting at the same point can be added or subtracted as shown in ***Figure 8-65A***. Use vector A plus vector B to construct a parallelogram. The diagonal of the parallelogram vector (A + B) is called the resultant R, which is equivalent to the effect of the two vectors, ***Figure 8-65B***. Vector A minus vector B can also be used to construct a parallelogram. The resultant vector (A–B) is the diagonal, ***Figure 8-65C***.

If the vectors being added or subtracted are force vectors, the equal and opposite reaction to the resultant is defined as the *equilibrant*. The reaction must be present to satisfy a basic law of mechanics, which is



FIGURE 8-65 *(A) Coplanar concurrent vectors; (B) adding vectors: parallelogram law; (C) subtracting vectors: parallelogram law.*

that the sum of the forces acting on an object that is in equilibrium must add up to zero in any one direction, that is, $\Sigma F = 0$. A force may be defined as the action of one body on another, and it tends to change the state of rest or motion of the body acted on.

A vector force, acting on a body can be considered to be moved along its line of action without changing its effect on the body.

EXAMPLE:

Refer to *Figure 8-66A.*

GIVEN: Force vectors P and Q acting on body B. Also, S and T acting on W.

STEP 1 Move vectors P and Q along their respective lines of action until they meet and are tail to tail, *Figure 8-66B.* Also, move S and T.

STEP 2 The resultant R of vectors P and Q shows the combined effect of P and Q on body B, *Figure 8-66C.* Also, the resultant U of vectors S and T shows the effect on body W.

How to Add More than Two Coplanar-Concurrent Vectors

Two graphical methods can be used to add more than two coplanar-concurrent vectors. One requires adding any two vectors first, and then using the resultant to add to the third, etc. The second involves adding vectors "tail to head," in any order, to obtain a resultant.

EXAMPLE: METHOD 1

Refer to *Figure 8-67A.*

GIVEN: Vectors A, B, and C acting at point P.

STEP 1 Add vectors A and B using the parallelogram law to obtain resultant R1, *Figure 8-67B.*

STEP 2 Add vectors R1 and vector C using the parallelogram law to obtain resultant R2, *Figure 8-67C.* R2 is the resultant of the three vectors and would have the same effect as A, B, and C acting together at point P.

EXAMPLE: METHOD 2

Refer to *Figure 8-68A.*

GIVEN: Vectors A, B, and C acting at point P.

STEP 1 Move vector B parallel to its given position so that the tail of B is at the head of vector A, *Figure 8-68B.*

STEP 2 Locate vector C in a similar manner so that the tail of C is at the head of vector B, *Figure 8-68C.*

STEP 3 A vector from point P to the head of vector C is the resultant of the three vectors, that is, the resultant would have the same effect on point P as vectors A, B, and C, *Figure 8-68D.*



FIGURE 8-66 *(A) Vector line of action; (B) Step 1; (C) Step 2.*



FIGURE 8-67 *(A) Three coplanar concurrent vectors (method 1); (B) Step 1; (C) Step 2.*



FIGURE 8-68 *Four coplanar concurrent vectors (method 2).*

Resolution of Vectors

A given vector can be resolved into two coplanar vector components that act along two axes that intersect at the tail of the given vector.

How to Resolve a Vector onto Perpendicular Axes

EXAMPLE 1:

Refer to ***Figure 8-69A.***

GIVEN: Vector A and axes X and Y intersecting at O.

STEP 1 From the tip of vector A construct lines parallel to the two axes so that the lines intersect the axes X and Y at X(1) and Y(1), *Figure 8-69B.*

STEP 2 The two vector components that replace vector A are OX(1) and OY(1) with arrowheads at X(1) and Y(1), respectively, *Figure 8-69C.*



FIGURE 8-69 *(A) Resolution on perpendicular axes; (B) Step 1; (C) Step 2.*

EXAMPLE 2:

A three-dimensional mechanism problem in dynamics, but simplified to a statics problem at the instant shown. A further simplification presents the components as straight lines. The simplified mechanism and the velocity vector are drawn to scale. Refer to *Figure 8-70A.*

GIVEN: Arm R confined to rotate about point A. Slider S pinned to C of crank BC. Crank BC confined to rotate about point B, 360°. (The apparent interference of arm R with



FIGURE 8-70 *(A) Quick-return mechanism; (B) Steps 1 and 2.*

crank BC doesn't occur in the three-dimensional mechanism.) Slider C is free to slide along arm R.

Slider C at the instant shown has a velocity V(C) m/sec = ω(BC) radians/sec × BC m. The direction of the velocity of slider S at the instant shown is perpendicular to the crank BC because slider C is attached to point C.

TO FIND: The angular velocity ω(ARM)

STEP 1 Resolve vector V(C), drawn to scale, into two components, one parallel to arm R and one perpendicular, V(perpendicular), to arm R, *Figure 8-70B.*

STEP 2 Divide V(perpendicular) m/sec by L m to obtain ω(arm R) radians/sec. (Note that radians/sec = 2 × π × RPS. RPS = revolutions per second).

How to Resolve a Vector onto Two Axes not Perpendicular

EXAMPLE:

GIVEN: Vector V originating at o and axes m and n intersecting at o, *Figure 8-71A.*



FIGURE 8-71 *(A) Resolving a vector onto two axes not perpendicular; (B) Step 1; (C) Step 2.*

STEP 1 From the tip of vector V construct lines parallel to the two axes so that they intersect axes m and n at M(1) and N(1), *Figure 8-71B.*

STEP 2 The two components that replace vector V are OM(1) and ON(1) with arrowheads at M(1) and N(1), respectively, *Figure 8-71C.*

Two-Force Members

Two-force members have forces at each end, equal in magnitude, in the opposite direction, and collinear. Therefore, they are in equilibrium. The weight of the member is considered to be negligible due to the usually much greater effect of the forces applied. See *Figure 8-72.*



FIGURE 8-72 *Two-force members.*

How to Determine the Forces in the Members of a Pinned Joint

EXAMPLE:

GIVEN: A space diagram showing weight W supported by a frame in equilibrium, made up of two-force members AB and BC, drawn to scale, and pinned to a wall, *Figure 8-73A*.

STEP 1 Isolate pinned joint B by "cutting" the members AB and BC and redrawing the joint, parallel to the original drawing. An engineering expedient is to represent members of a frame (or truss) as straight lines. The lines of action of the internal forces F(AB) and F(BC) intersect at joint B. Their directions must be tentatively assumed by inspection. The direction of force F(AB) must keep the joint away from the wall. Force F(BC) keeps the joint from dropping. See *Figure 8-73B*.

STEP 2 Construct a vector force diagram of the forces at joint B. First, lay out the applied force W, from a point O, vertically downward, to scale. The two remaining forces F(AB) and F(BC) must add—tail to head—to W and end at the starting point O because joint B is in equilibrium. To determine the magnitudes of F(AB) and F(BC), construct a light line through the head of vector W parallel to the direction F(AB) and a light line through the tail of vector W parallel to the direction of F(BC), *Figure 8-73C*. Where the two lines intersect determines the magnitudes of F(AB) and F(BC). The tail-to-head method of adding vectors determines their directions. The assumed directions are confirmed in the vector force diagram.

Note that only two unknown magnitudes of forces can be determined in these coplanar joint analyses. Their directions are determined in the space diagram.



FIGURE 8-73 *(A) Determining forces of a pinned joint; (B) Step 1; (C) Step 2.*

Trusses

Trusses are frames that are usually two-dimensional and are made of structural shapes, such as angles, tubes, rounds, and channels. They are assembled in triangular patterns for rigidity. The members are considered to be two-force members, and the joints are assumed to be pinned even though welded, bolted, or riveted. Observe some features of the truss shown in *Figure 8-74A* and the simplified drawing of the truss in *Figure 8-74B*. Both are drawn to scale.



FIGURE 8-74 *(A) Example truss; (B) Simplified drawing of truss.*

Trusses seldom stand alone. They are used in pairs or in multiples. For example, some highway bridges and railroad bridges employ pairs. Multiples are used to support roofs, *Figure 8-75A*. In a coplanar analysis, each truss is assigned its share of the roadbed loading or the roof loads at the appropriate joints of the trusses, *Figure 8-75B*.



FIGURE 8-75 *(A) Truss applications; (B) truss drawings for analyses.*

How to Determine the Forces in the Members of a Truss

EXAMPLE 1(A): METHOD OF JOINTS

GIVEN: Line drawing to scale of a symmetrical truss with one applied load and two equal reactions, *Figure 8-76A*.

STEP 1 Select a joint in the truss with only two unknowns. A and C meet this criterion. Use joint A and isolate it in a space diagram, *Figure 8-76B*. Assume the direction of F(AD) by inspection to "go into" the joint, that is, to be a compressive force. Assume F(AB) "goes away from" the joint and is thus a tensile force. Next, lay out a force diagram to scale, starting with the known force of 2500 N. Follow the procedure described in Step 2 of the preceding discussion, Figure 8-73C, where the light lines indicate the lines of action of the two unknown forces. Their intersection point determines the magnitudes. Scale the magnitudes and put arrowheads on the vectors so that the vectors add head to tail back to the tail of the 2500 N force, the starting point. Finally, make a small freehand sketch of the truss and circle the known members, AD and AB.

STEP 2 Joints B or D have only two unknowns. Select either one and isolate it in an equilibrium sketch. Use joint B, *Figure 8-76C*. Construct a force diagram starting with known information, the 5,000 N applied load, and the 7,500 N tensile force in AB. Construct the light lines for the forces in members BD and BC. Scale their magnitudes and add arrowheads so the forces add head to tail back to the tail of the 5,000 N force. On a new freehand sketch, circle the known members, AD, AB, BD, and BC.

STEP 3 The remaining member DC is known due to the symmetry of the truss, F(CD) = F(AD), and is a compressive force. If the truss or the loading were not symmetrical, joint C would be isolated and a force diagram prepared as shown, *Figure 8-76D*.

STEP 4 Prepare a summary of the forces on a sketch of the truss or in a table, *Figure 8-76E*.



(A)





(B)





(C)







(D)

MEMBER	FORCE	T OR C
AB	7,500 N	T
BC	7,500 N	T
AD	7,900 N	C
DC	7,900 N	C
BD	5,000 N	T

(E)

FIGURE 8-76 *(A) Example 1 (a) method of joints; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4.*

EXAMPLE 1(B): METHOD: MAXWELL DIAGRAM WITH BOW'S NOTATION

GIVEN: The same truss used for the method of joints, but to be labeled with Bow's notation scheme, *Figure 8-77A*. Label the triangular spaces within the truss with numbers or letters. Create enclosed spaces between the applied forces and reaction forces by drawing a light envelope line surrounding the truss and passing through each applied force and reaction. Label each "space" with a letter.

STEP 1 Construct a force diagram from reading the external spaces in the envelope in a clockwise direction, *Figure 8-77B*. Use a convenient scale to keep the force diagram on the drawing sheet and to use the space efficiently. Read spaces a to b for the left reaction, 2,500 N. Then read spaces b to c for 2,500 N. Finally, read c to a for the 5,000 N force, which brings the force diagram back to the starting point. Thus, the truss is in equilibrium.

STEP 2 Select any joint with only two unknown members and read spaces clockwise around the joint, *Figure 8-77C*. Construct lines



FIGURE 8-77 *(A) Example 1 (b) Maxwell diagram with Bow's notation; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4.*

parallel to the two members crossed. For example, start at joint A and go a to b, b to 1, and 1 to a. Point 1 is located where the construction lines cross.

STEP 3 Select the next joint with only two unknown members, joint B or D. Around B go a to 1, 1 to 2, 2 to c, and c to a, *Figure 8-77D*. The two light lines for 1 to 2 and 2 to c locate point 2. To finish the force diagram for the truss, go around joint C or joint D. Choose joint C and go b to c, c to 2, and 2 to b.

STEP 4 Prepare a summary of the forces on a sketch of the truss, *Figure 8-77E*. Go clockwise around each joint of the truss to determine tensile and compressive forces. For example, reading clockwise around joint A, 1 to a in the force diagram goes in a direction away from A. Therefore, AB is in tension, and the magnitude is scaled to be 7,500 N. Going b to 1 goes into joint A, thus producing a compressive force of 7,900 N. In a similar clockwise pattern, determine the type and magnitude of the force for each member.

The next example focuses on a more complicated truss with asymmetrical loading.

EXAMPLE 2(A): METHOD OF JOINTS

GIVEN: A freehand sketch and a scaled line drawing of a symmetrical roof truss, but with asymmetrical loading due to anticipated wind and snow conditions, *Figure 8-78A*. The reactions at A and D were determined



FIGURE 8-78 *(A) Example 2 (a) method of joints 5,000 N A 11,279 N 26.1°.*



(B)



(C)





(D)





(E)



(F)

MEMBER	FORCE N	T OR C
AB	12900	T
BC	8400	T
CD	18500	T
DE	21400	C
EF	21400	C
FG	17900	C
GA	20700	C
BG	4300	C
BF	4400	T
CF	10200	T
CE	10000	C

(G)

FIGURE 8-78 *(Continued) (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5; (G) Step 6.*

analytically using the fundamental equations of statics, $\Sigma F = 0$ and $\Sigma M = 0$. At joint A, the small freehand sketch shows a typical symbol for a pinned support, that is, it provides support vertically and horizontally. The symbol at the right end indicates support in one direction only, normal to the surface of support.

STEP 1 Start at a joint with only two unknowns, A or D. Isolate joint A, *Figure 8-78B,* and construct a force diagram to find F(AB) and F(AG). (Use the technique discussed with respect to Figure 8-73C.) Then, to keep a handy record, circle the known members AB and AG in a miniature sketch of the truss. Circle additional known members as they are found.

STEP 2 Isolate joint G, the next joint with only two unknowns, *Figure 8-78C.* Construct a force diagram starting with known forces F(AG) and the 5,000 N applied force. Find F(GF) and F(GB) and circle those members in a miniature sketch.

STEP 3 Isolate joint B next, *Figure 8-78D,* and construct a force diagram starting with F(AB), then F(GB) to find F(BF) and F(BC). Note that the light line for F(BC) coincides with F(AB) because of the arbitrary clockwise selection of forces around joint B. However, any order of taking the forces around a joint can be used for the method of joints; the final magnitudes and directions would be identical. Circle the known members, in a miniature sketch.

STEP 4 Isolate joint F, *Figure 8-78E.* Construct a force diagram by using any order of forces. A clockwise order was used for the figure; starting with known F(FB), then F(FG) followed by the 7,000 N applied force to determine F(FE) and F(FC). Add these to a miniature sketch.

Determine F(CE) by inspection to be 10,000 N. A force acting normal to a joint that has members at 90° to each other can only transmit force to the truss member along the same line as the force. Circle this member in the sketch.

STEP 5 Isolate the last joint D, *Figure 8-78F,* to determine F(DC) and F(DE). Observe that force F(DE) should equal F(EF) due to the 90° angles between member DE and CE, and between DE and the 10,000 N force. Circle the last two members to complete the analysis.

STEP 6 Prepare a table of the forces in the truss members, *Figure 8-78G.*

EXAMPLE 2(B): METHOD: MAXWELL DIAGRAM WITH BOW'S NOTATION

GIVEN: The same symmetrical truss, drawn to scale, with asymmetrical loads, used in the preceding method of joints example, *Figure 8-79A.* Label the triangular spaces within the truss with numbers. Draw a light line envelope surrounding the truss and passing through each applied force and reaction. Label these spaces with letters.

STEP 1 Start a force diagram (to a scale to keep the diagram on the drawing sheet) by reading the external spaces in a clockwise direction, a to b, b to c, c to d, d to e, and e to a. Plot each applied force and reaction, *Figure 8-79B.*

Either clockwise or counterclockwise will work, but once a pattern is started it must be used throughout the complete problem both for the Maxwell diagram and for determining whether a member is in tension or compression.

STEP 2 Start at a joint with only two unknowns, A or D. At joint D, go clockwise a to 1, 1 to e, and e to a to locate point 1, *Figure 8-79C.*

STEP 3 Now joint E has only two unknowns, so continue d to e, e to 1, 1 to 2, and 2 to d to locate point 2, *Figure 8-79D.*

STEP 4 For joint C go a-3-2-1-a to locate point 3, *Figure 8-79E.*

STEP 5 Joint F has only two unknowns, so go d-2-3- 4-c-d to locate point 4, *Figure 8-79F.*

STEP 6 Around point B go a-5-4-3-a to locate point 5, *Figure 8-79G.*

STEP 7 For the last joint, A, go a-b-5-a, *Figure 8-79H.* The closing line in direction 5-b should intersect point b on the Maxwell diagram for a correct solution.

STEP 8 Prepare a table of the forces in each member; scale the diagram for magnitudes and use the clockwise pattern to determine whether the force goes into the joint



MEMBER	FORCE N	T OR C
AB	12,900	T
BC	8,400	T
CD	18,500	T
DE	21,400	C
EF	21,400	C
FG	17,900	C
GA	20,700	C
BG	4,300	C
BF	4,400	T
CF	10,200	T
CE	10,000	C

FIGURE 8-79 *(A) Example 2 (b) Maxwell diagram with Bow's notation; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5; (G) Step 6; (H) Step 7; (I) Step 8.*

(compression) or goes away (tension), ***Figure 8-79I.*** For example, around joint C for member CF, 3-2 goes away from the joint; thus, CF is in tension. Scale the magnitude to be 10,000 N. Around joint F, 2–3 goes away from the joint F as expected because CF is a tension member.

Noncoplanar-Concurrent Force Systems

How to Determine the Forces in the Members of a Noncoplanar-Concurrent Force System

A noncoplanar-concurrent force system could be described as a "tripod" with a force or forces applied at the apex of the tripod, that is, three two-force members, usually rigid, meeting at a point and supporting a load, ***Figure 8-80.*** Only three unknown forces may be present in order to solve for their magnitudes using basic statics; again the governing equation is $\Sigma F = 0$. Furthermore, the vectors, representing the forces in the three members, plus the applied load(s) must add tail to head starting at the apex and ending at the apex because the system is in equilibrium, Figure 8-80.

Graphical solutions of three-member, noncoplanar-concurrent force systems incorporate two fundamental descriptive geometry techniques; one, finding the piercing point of a line in a plane and two, finding the true length of a line. In a space diagram, the



FIGURE 8-80 *Noncoplanar-concurrent force systems.*

direction line of a force vector of one member pierces the plane made by the other two vectors. In a force diagram the true lengths of the three vectors representing the forces in the members are found. The space diagram and the force diagram are drawn to scale and are usually superimposed for convenience.

EXAMPLE 1:

GIVEN: A track beam for a hoist, attached to a wall, held up by two wire ropes, and supporting a load at the end as illustrated in the simplified line drawing, *Figure 8-81A*. The line drawing of the beam and wire ropes is drawn to scale. The applied load of 40,000 N is drawn to scale.

STEP 1 Draw a direction line, originating at the tip of the applied load vector, and parallel to any one of the three members, *Figure 8-81B*. Find the piercing point made by this line in the plane made by the other two members.

Select this first direction line for convenience in arriving at a solution. For example, the plane made by (b-o)T and (c-o)T in view T shows as an edge in view F. Having the edge view expedites finding a piercing point. Therefore, construct a line parallel to the third member (a-o)F, starting the line at the tip of vector F, and note where the line pierces the (b-o-c)F plane, which actually extends beyond the apparent boundaries of (b-o-c)F. (Keep in mind that

Industry Application

Du Vo Minh could remember really disliking descriptive geometry during his years as a student. Projecting lines into other views, determining the true length of a line, identifying the true angle between surfaces, and constructing force diagrams were not what Minh had thought drafting would be about. He wanted to design expensive mansions and unique commercial buildings. He wanted to draw the plans for majestic skyscrapers and towering parking decks. Minh's teacher had reassured him at the time that he would probably do all of these things after graduation, and that he would do them even better if he understood the proper application of descriptive geometry. At the time, the instructor's advice had been a bitter pill to swallow, but Minh had taken it and learned descriptive geometry.

Now, six years later, Minh silently thanks the instructor for insisting that he learn force diagrams and all of the other applications of descriptive geometry. The company he worked for, Commercial Construction, Inc. (CCI), had been awarded a contract to renovate the historic district of downtown Williamsboro, Tennessee, a prestigious multi-million dollar contract. But things were not going well, or at least they hadn't been.

CCI was using trusses in the renovation of several colonial-style buildings, and the trusses were failing.

Several had twisted under only partial loading, and truss members had actually snapped on one. The engineers who had designed the trusses were stumped; they couldn't find the problem. That's where Minh became a hero and earned a promotion.

Using the descriptive geometry concepts he had learned in school, Minh developed a force diagram for the trusses in question. He also created a member table showing the forces for each vector in the diagram.

By examining Minh's diagram and table, CCI's engineers were able to see clearly what they had missed mathematically.

The trusses were quickly redesigned, and CCI's construction crews resumed work. Du Vo Minh was promoted to senior drafter and assigned to the design team responsible for roof trusses.

a willingness to "go beyond arbitrary boundaries" is a step toward being a creative individual.)

STEP 2 Find F(BO) and F(CO) now that F(AO) has been established. The force vectors parallel to members OB and OC, and lying in the plane of BOC extended, must add tail to head to F(AO) and end at the origin of the force vector F, *Figure 8-81C*.

STEP 3 Determine the magnitudes of the three unknown forces and prepare a summary sketch, *Figure 8-81D*. Use the principle of revolution (to be discussed in the next section of this chapter) to determine the magnitudes. The sketch of isolated joint O with directions of the three forces found in the force diagram indicate whether each member is in tension or compression. Of course, cables supporting a load must be in tension.

EXAMPLE 2:

GIVEN: A tripod on a sloping terrain supporting a 12,000 N load, *Figure 8-82A*. The tripod and the applied load are drawn to scale.

STEP 1 Select a plane made by two of the members, to expedite the solution, and construct a view showing this plane as an edge, *Figure 8-82B*. Use members (a-o)F and (c-o)F to establish the plane using auxiliary line (a-x)F, and project the plane (a-o-c)T into view A. Use the technique shown in Figure 8-17, discussed earlier in this chapter, for finding an edge view of a plane surface.

STEP 2 Find the piercing point in plane (a-o-c)A of the vector representing the force in member (o-b)A by constructing a direction line in view A, originating at the tip of the 12,000 N force and parallel to member (o-b)A. Label the piercing point pA and



FIGURE 8-81 *(A) Determining the forces of a noncoplanar-concurrent force system—example 1; (B) Step 1; (C) Step 2; (D) Step 3.*

show F(OB), ***Figure 8-82C***. Project a line from point pA into view T and locate pT by noting where extended line (o-b)T crosses the projected line from pA in view A.

STEP 3 In the T view, construct a line from the piercing point pT, parallel to (o-a)T, until it intersects (o-c)T. This establishes F(OA) and F(OC), ***Figure 8-82D***. Project the point of intersection of F(OA) with (o-c)T into



FIGURE 8-82 *(A) Determining the forces of a noncoplanar-concurrent force system—example 2; (B) Step 1; (C) Step 2; (D) Step 3.*

view A and indicate both vectors F(OA) and F(OC) in view A.

STEP 4 Determine the magnitudes of the three unknowns—F(OB), F(OA), and F(OC), and list them in a table, ***Figure 8-82E***. All three unknown forces could be determined by the true-length-of-a-line method. For example, F(OA) and F(OC) could be determined in an auxiliary view B by making a fold line A/B parallel to the edge view of plane (a-o-c)A. Then F(OA) and F(OC) would be in true size in view B. A different method, however, will be used for the three unknowns—the technique of revolution.



MEMBER	FORCE	T OR C
OA	4,400 N	C
OB	7,000 N	C
OC	6,800 N	C

FIGURE 8-82 *(Continued) (E) Step 4.*

For clarity, the technique of revolution will be shown for determining one force only, force F(OB). Revolution will be discussed in the next section.

COMMENT: An alternative method of finding the piercing point described in Step 2 would be to employ the line projection method, Figure 8-25, discussed earlier in this chapter. The method is shown in views F and T, Figure 8-83.

Revolution

The revolution technique in graphics saves time and space. The technique can be used to solve many true-length and true-angle problems while requiring fewer views.

Consider the basic attributes of the technique by observing the straight member, a-b, rigidly attached to an axis m-n (which can rotate 360°), shown in the T and F views, *Figure 8-84A*. The true length of member a-b is seen twice in the F view as the axis makes one revolution, *Figure 8-84B*. The end bT of member a-b traces a circular path in the T view, and bF traces a straight line in the F view. The circle made by bT is in true size in the T view, and bF's path shows as an edge parallel to the fold line T/F in the F view.

The revolution technique works only if the axis, whether real or imaginary, shows as a point in one view and in true length in any adjacent view.

How to Determine the True Length of a Line

EXAMPLE:

GIVEN: The T and F views from Figure 8-11A are redrawn here, *Figure 8-85A*. In the T view, assume that an axis (m-n)T goes through bT; but it only shows as a point, mT, nT. Then, in the F view, axis mF-nF shows in true length.

STEP 1 In the T view, rotate member (a-b)T about axis mT,nT until (a-b)T is parallel to the fold line T/F, *Figure 8-85B*. Next, in the F



FIGURE 8-83 *Piercing point by line projection method.*

view, move point aF parallel to the fold line T/F until it lines up with the projection line from aT's new position in the T view. Redraw (a-b)F in the revolved position where it is now in true length.

COMMENT: Revolution techniques also save time in laying out developments, Chapter 9.

How to Determine the True Angle a Line Makes with a Plane

EXAMPLE 1:

GIVEN: Plane (a-b-c-d)T in true size and line (k-j)T piercing the plane at point pT, in the T view, *Figure 8-86A*. In the F view, the line (k-j)F pierces plane (a-b-c-d)F, which shows as an edge.

STEP 1 Construct an auxiliary axis m-n that shows as point mT,nT in the T view and goes through piercing point pT, *Figure 8-86B*. Construct the axis (m-n)F as a true-length line in the F view, perpendicular to the T/F fold line.



FIGURE 8-84 *(A) Revolution attributes; (B) True length by revolution.*

STEP 2 Rotate line (k-j)T about the axis, in the direction of the smallest angle, until line (k-j)T is parallel to the fold line T/F, *Figure 8-86C*. Construct projection lines from the new positions of kT and jT into the F view. Then locate the new positions of kF and jF by moving them parallel to the fold line T/F. The point kF moves to the left to the projection line from kT, and point jF moves to the right to the projection from jT. Draw (k-j)F in its revolved position and observe that it is now in true length. Measure the true angle between the line (k-j)F and the plane (a-b-c-d)F.



FIGURE 8-85 *(A) Determining the true length of a line—example 1; (B) Step 1.*



FIGURE 8-86 *(A) Determining the true angle; (B) Step 1; (C) Step 2.*

In summary, the true angle a line makes with a plane must be seen in a view where the plane shows as an edge and the line is in true length.

EXAMPLE 2:

GIVEN: Views F, T and A from Figure 8-23F and redrawn here, ***Figure 8-87A.***

This example shows that with only one more view, view B, the true angle between the piercing line (x-y)A and the plane (a-b-c)A can be found easily using revolution.

Construct a fold line A/B parallel to the edge view of plane (a-b-c)A shown in the A view, ***Figure 8-87B.***

Project the plane and the piercing line into the B view. The plane (a-b-c)B will be in true size, but the line (x-y)B is not.

Therefore, in view A, construct a true-length axis (m-n)A going through the piercing point and perpendicular to plane (a-b-c)A. The axis will show as a point (m-n)B in view B, at the piercing point. Rotate the line (x-y)B about the axis in view B until the line is parallel to the fold line A/B. Then in view A, move point xA parallel to fold line A/B to coincide with the new position of xB in view B. In view A, draw the line (x-y)A in its rotated position, where it now shows in true length. In view A measure the true angle between the line (x-y)A and the edge view of plane (a-b-c)A.



FIGURE 8-87 *(A) Determining the true angle—example 2 (refer to Figure 8-23F); (B) true angle.*



FIGURE 8-88 *(A) Vertical wind turbine; (B) Step 1.*

How to Determine Clearances Using Revolution

EXAMPLE:

GIVEN: The top and front views of a proposed installation of a vertical wind turbine and turbine blade details, *Figure 8-88A*.

Requirement:

Determine the vertical distance to raise anchor B so cable (o-b)F will clear any portion of the turbine blades by at least .3 meter. Cables (o-a)F and (o-c)F are assumed to meet this requirement, but they should be checked.

STEP 1 Rotate (o-b)T in the T view until it is parallel to the fold line T/F, *Figure 8-88B*. Note that the vertical axis of the turbine qualifies as the axis of revolution because it is in true length in the F view and shows as a point in the adjacent view, view T. Move point bF to the right in the F view as shown. Then, lay out the true size of the turbine blade in the F view.

Construct a straight line from oF, representing (o-b)F, which clears the turbine blade by at least .3 meter. Find the intersection point of this straight line (o-b)F with a vertical line directly above anchor B.

The vertical distance down from the intersection point to the original elevation of anchor B is the required distance to raise anchor B.

Summary

- Descriptive geometry shows graphically the solution to problems involving points, lines, and planes and their relationship in space.
- Basic theories of descriptive geometry include the following: projecting a line into other views; projecting points into other views; determining the true length of a line; determining the point view of a line; finding the true distance between a point and a line, a plane or two lines in space; projecting a plane surface in space; developing an edge view of a plane surface in space; and determining the true angle between plane surfaces in space.

- The bearing or heading of a line is the direction of the line as it is drawn on a map in top view. There are two methods used for calling out a bearing: north/south deviation and azimuth bearing.
- The slope of a line is the angle, in degrees, that the line makes with a horizontal plane.
- The grade percent of a line describes the inclination of the line in relation to the horizon by the ratio of the vertical rise to the horizontal.
- The pitch of a line or surface describes the slope of a roof and is expressed as the ratio of vertical rise to 12″ or 12′ in horizontal span.
- A contour line on a plot or map is a line at a constant elevation of the earth, above sea level. Contour interval is the difference in elevation between neighboring contour lines.
- Strike is a compass direction of a horizontal line lying in the plane of an ore vein. Dip is the downward angle of the vein with respect to a horizontal plane at the site of the ore vein.
- A vector is a graphic representation of force, displacement, velocity, or acceleration. A vector has both direction and magnitude.

Review Questions

Answer the following questions either true or false.

1. Descriptive geometry is used by drafters, designers, and engineers because it graphically shows the solutions to problems dealing with points, lines and planes, and their relationship in space.
2. Notations are like footnotes.
3. Notations are important because they are used to keep track of all views and points in space.
4. The point view of a line describes the inclination of a line in relation to the horizon.
5. In order to find an edge view of a plane, a true-length line must be located in that plane.
6. A fold line is represented by a thin black line and must be labeled using lowercase letters.
7. The first step to determining the visibility of two intersecting lines (which of the two lines is closer) is to project the exact crossover point of the lines to an adjoining view.
8. The bearing and grade, or bearing and slope, refers to the exact position of a fold line.
9. A contour line on a plot or a map is a line at a constant elevation on the surface of the earth, above sea level.
10. The significance of contour lines being close together on a map is steep terrain.
11. The term cuts and fills refers to earth being excavated for highways.
12. A vector is a directed line segment which, in computer graphics, is defined by its two end points.
13. Trusses are usually used in pairs or in multiples.
14. A truss is a frame that is usually three-dimensional and made of structural shapes.
15. Space diagrams and force diagrams are used in truss analysis to determine the forces in the members of a truss.
16. Methods of assembling truss joints include welding, riveting, and bolting.
17. When projecting a plane into another view, you must first find at least four points in the plane and project each point into the next view.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** an acceptable method for determining the intersection of two planes?
   a. By inspection
   b. By generating an edge view of the plane surface
   c. By using the line projection method
   d. Both b and c
2. Which of the following is **not** a step involved in determining the true distance between two parallel lines in space?
   a. Find the true length of each of the two lines.
   b. Find the point view of each of the two lines.
   c. Project a point view of the added true-length line.
   d. The true distance between the parallel lines is the straight-line path between their end points.
3. Which of the following is **not** a step involved in determining the true distance between two non-parallel (or skewed) lines in space?
   a. Project the true length of either one of the two lines, and project the other line into that auxiliary view (A).
   b. Find the point view of the true-length line, and project the other line into that secondary auxiliary view (B).
   c. Measure the true distance between the point view line at a location that is perpendicular to the other line.
   d. Project the same points from the front view into the right-side view.
4. A point is called out in a given view by:
   a. Lowercase letters
   b. Uppercase letters

c. Either upper- or lowercase letters
d. All of the above

5. Which of the following is an important rule to remember when projecting from one view to another?
   a. Always project the top view of a line from a given front.
   b. The customary 45° projection line is used.
   c. The fold line is always placed between the front V and the top V.
   d. Always skip a view between all measurements.

6. Which of the following is **not** one of the basic steps involved in finding the true length of any straight line?
   a. Draw a fold line parallel to the line for which the true length is required and label it A for auxiliary.
   b. Extend projection lines from the end points of the line being projected into the auxiliary view.
   c. Projection lines must always be parallel to the fold line.
   d. Transfer the end point distances from the fold line in the second preceding view from the one being drawn to locate the corresponding end points in the view being drawn.

7. Which of the following is **not** one of the basic steps used to find the point view of a line as projected from its true length?
   a. Find the true length of the line.
   b. Draw a fold line perpendicular to the true-length line at any convenient distance from either end of the true-length line and label it A-B.
   c. Extend a light projection line from the true-length line into the secondary auxiliary view.
   d. Measure the true distance between the point view line at a location perpendicular to the other line.

8. Which of the following is a use of vectors in engineering and technology?
   a. Displacement
   b. Force
   c. Velocity
   d. All of the above

9. Which of the following is **not** part of the parallelogram law?
   a. Two vectors
   b. Not parallel, drawn to scale
   c. Parallel, drawn to scale
   d. Having the same units, and acting at the same point can be added or subtracted using a specific formula

10. Which of the following is the correct formula for determining the percent of grade?
    a. Units of horizon ÷ units of vertical rise × 100
    b. Units of vertical rise ÷ units of horizon × 100
    c. Units of horizon × units of vertical rise ÷ 100

11. A piercing point is:
    a. The exact location of an intersection of two lines
    b. The exact location of an intersection of two surfaces
    c. The exact location of an intersection of a plane and a surface line
    d. None of the above

12. Given the bearing, slope, and length of a line, which of the following is **not** true when constructing the line in a drawing?
    a. The bearing is always drawn in the top view.
    b. The true length can be drawn if the line is to be exactly horizontal.
    c. Any line with an incline up (+) or down (–) from the horizon must be laid out using specific steps.
    d. If the line is horizontal, the true length must be constructed before the heading length can be drawn in the top view.

13. Which of the following is **not** true regarding trusses?
    a. Trusses are seldom used in multiples.
    b. Trusses seldom stand alone.
    c. Trusses are frames that are usually two-dimensional.
    d. Joints are assumed to be pinned, although they can be welded, bolted, or riveted.

Chapter 8 Problems

The following problems are intended to give the beginning drafter practice in using the various principles of descriptive geometry. Problems 1 through 13 deal with each of the various principles used to solve actual design problems. Problems 14 through 32 apply these principles to develop required views of various objects.

Conventional Instructions

The steps to follow in laying out problems 1 through 13 and 23 through 32 are:

1. On an 8½ × 11″ sheet of paper with a sharp 4-H lead, locate all lines, points, and fold lines per the given dimensions.
2. Complete the problem per the given instructions. Project in the direction of the large arrow.

The steps to follow in laying out problems 14 through 27 are:

STEP 1 Study the problem carefully.

STEP 2 Using the given front view, make a sketch of all required views.

STEP 3 Center the required views within the work area with a 1″ (25 mm) space.

STEP 4 Use light projection lines. Do **not** erase them.

STEP 5 Lightly complete all views.

STEP 6 Check to see that all views are centered within the work area.

STEP 7 Check that there is a 1″ (25 mm) space between all views.

STEP 8 Carefully check all dimensions in all views.

STEP 9 Darken in all views using correct line thickness.

STEP 10 Recheck all work, and, if correct, neatly fill out the title block using light guidelines and neat lettering.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project, and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

PROBLEM 8-1

Locate line a-b and fold lines per the given dimensions. Locate line a-b in the right-side view. Label all points in all views.



PROBLEM 8-2

Locate line a-b and fold lines per the given dimensions. Locate line a-b in the top view. Locate point c on line a-b in all views. Label all points in all views.



PROBLEM 8-3

Locate line a-b and fold lines per the given dimensions. Locate line a-b in the right view. Find the true length of line a-b, projecting from the right side. Label all points in all views.



PROBLEM 8-4

Locate the line a-b and fold lines per the given dimensions. Locate line a-b in the top view. Find the point view of line a-b, projecting from the top view. Label all points in all views.



PROBLEM 8-5

Locate line a-b, point c, and fold lines per the given dimensions. Find the true distance from line a-b to point c. Project from the right view. Label all points in all views.



PROBLEM 8-6

Locate parallel lines a-b and c-d and fold lines per the given dimensions. Find the true distance between lines a-b and c-d. Project from the front view. Label all points in all views.



PROBLEM 8-7

Locate lines a-b and c-d and fold lines per the given dimensions. Find the true distance between lines a-b and c-d. Project from the top view. Label all points in all views.



PROBLEM 8-8

Locate points a, b, and c and fold lines per the given dimensions. Connect points a, b, and c to form a plane. Project plane abc into the top view. Label all points in all views.



PROBLEM 8-9

Locate points a, b, c, and d, point x, and fold lines per the given dimensions. Connect points a, b, c, and d to form a plane. Project plane abcd into the right view; locate point x in all views. Label all points in all views.



PROBLEM 8-10

Locate points a, b, c, and fold lines per the given dimensions. Connect points a, b, and c to form a plane. Draw a line from point cF, parallel to fold line F-R; label this line cF-xF. Find the edge view of plane surface abc. Project from the right view. Label all points in all views.



PROBLEM 8-11

Locate points a, b, and c and fold lines per the given dimensions. Connect points a, b, and c to form a plane. Draw a line from point bF, parallel to fold line F-T; label this line bF-xF. Find the edge view of the plane abc and project from the front view. Label all points in all views.



PROBLEM 8-12

Locate points a, b, and c, point x, and fold lines per the given dimensions. Connect points a, b, and c to form a plane. Find the true distance between plane surface abc and point x. Project from the front view. Label all points in all views.



PROBLEM 8-13

Locate points a, b, c, and d and fold lines per the given dimensions. Connect points a, b, c, and d to form a folded object. Find the true angle between the plane surfaces as viewed directly along the fold, a-b. Project from the right view. Label all points in all views.



Problems 8-14 through 8-22

Draw the front view, top view, right view, and auxiliary view per the listed steps.

PROBLEM 8-14



PROBLEM 8-15



PROBLEM 8-16



PROBLEM 8-17



PROBLEM 8-18



PROBLEM 8-19



PROBLEM 8-20



PROBLEM 8-21



PROBLEM 8-22



PROBLEM 8-23

Draw the front view, top view, right view, and required auxiliary views per the listed steps. Find the true angle at abc, as viewed along the fold.



PROBLEMS 8-24 AND 8-25

Draw the front view, top view, right view, and auxiliary view per the listed steps.

PROBLEM 8-24



PROBLEM 8-25



PROBLEMS 8-26 AND 8-27

Draw the front view, top view, right view, and required auxiliary views per the listed steps. Find the true angle between the various surfaces as viewed along the fold.

PROBLEM 8-26



PROBLEM 8-27



PROBLEM 8-28

Complete the front view using the line-projection method. Draw the correct visibility of all lines in the front view.



PROBLEM 8-29

Complete the top and front views using the line-projection method. Draw the correct visibility of all lines by inspection.



PROBLEM 8-30

Complete the front view by inspection and projection. Draw the correct visibility of all lines.



PROBLEM 8-31

Complete the front view using the line-projection method. Draw the correct visibility of all lines.



PROBLEM 8-32

Complete the top and front views using the line-projection method. Do not use the right-side view for solving the problem. Draw the correct visibility of all lines.



Problems 8-33 through 8-42

Lightly lay out and draw the two views and the fold line on an A-size sheet of vellum using the given dimensions. Complete all views using correct line thickness—add all hidden lines.

PROBLEM 8-33



PROBLEM 8-34



PROBLEM 8-35



PROBLEM 8-36



PROBLEM 8-37



PROBLEM 8-38



PROBLEM 8-39



PROBLEM 8-40



PROBLEM 8-41



PROBLEM 8-42



PROBLEM 8-43

Calculate the angles using the given bearings for A through F. Show all math work.



PROBLEM 8-44

On a B-size paper, draw the *top view* and *front view* of a straight roadway (a-b) 280.0 feet long, with an azimuth bearing of N 288°, and a grade of –20%. Use a 1″ = 50.0′ scale. Show all light construction work.

GIVEN: Location of fold line F/T and location of point aT and aF.



PROBLEM 8-45

On a B-size paper, lay out the *top view* and *front view* of a radio tower. Use a 1″ = 50.0′ scale. Show all light construction work. Answer the following questions:

1. What is the grade percent for the guide wire a/b?
2. What is the slope angle of the guide wire?
3. What is the true length of the wire?

GIVEN: Location of the radio tower, guide wires, and fold line F/T.



PROBLEM 8-46

On a B-size paper, draw an existing conveyor belt system with the given specifications (see specifications in box). The conveyor belt system is to be redesigned to go from point a directly to point d. Use a 1″ = 50.0′ scale. Show all light construction work. Answer the following questions:

1. What is the new redesigned bearing from points a to d?
2. What is the new redesigned true length?
3. What is the new grade percent?
4. How much shorter is the new design than the old design?

GIVEN: Location of grade, starting point a, and fold line F/T.

BELT	BEARING	TRUE LG.	GRADE %
a – b	N 30° W	180.0'	40%
b – c	N 80° W	140.0'	30%
c – d	S 45° W	145.0'	15%

ANSWER			
a – d			



PROBLEM 8-47

On a B-size paper, construct two tunnels, a and b. Tunnel a starts at point a and has a bearing of N 70° W. It is 240.0 feet long and has a plus slope angle of 34°. Tunnel b starts at point b and has a bearing of N 60° E. It is 200.0 feet long and has a plus slope angle of 19°. Use a 1″ = 50′ scale. Show all light construction work. Project from the front view. Answer the following questions:

1. Do the tunnels ever intersect?
2. If not, how far apart are they?

GIVEN: Locations of tunnel entrances a and b and fold line F/T.



PROBLEM 8-48

On a B-size paper, construct two mining shafts into a mountain from two different directions and elevations. Both are cut straight into the mountain at different percents of grades. One shaft starts at point a and the other starts at point b. Shaft a has a bearing of S 60° W, with a grade of + 35%, and is 165.0 feet long. Shaft b has a bearing of S 45° E, with a grade of + 40%, and is 176.0 feet long. Use a 1″ = 50.0′ scale. Show all light construction work. Answer the following questions:

1. Do the shafts intersect?
2. What is the true distance from the entrance of shaft a to the entrance of shaft b?
3. What is the bearing and percent of grade from the two entrances?

GIVEN: Locations of the shaft entrances a and b, fold line F/T, and mountain.



PROBLEM 8-49

A 40′ wide, level road, at elevation 150′, is to be run through a hilly terrain as shown on the contour map. Trace the map and use the accompanying scale to determine cut and fill boundaries for a slope of 1:1 for both the cuts and the fills.



PROBLEM 8-50

Vehicle A is traveling due North at 150 kph (90 mph); vehicle B, due West at 110 kph (66 mph). Vehicle B is 40 kilometers North and 40 kilometers East of vehicle A at the instant shown. What is the shortest distance between the vehicles A and B when they pass each other? An example velocity vector diagram illustrates the consequences of A and B going at the same speed. What should vehicle B's speed be so that the shortest distance between A and B is 15 kilometers when they pass each other?



PROBLEM 8-51

An ore outcropping is shown on the topographic contour map. Points A and B are on the upper surface (called the hanging wall) of the vein. A vertical bore hole at point C indicates that the hanging wall is at 877' elevation. The core hole extended at C indicates that the bottom surface of the ore vein (footwall) is at 841' elevation. For the information given for the locations of points A, B, and C and the vein surfaces, determine the following:

1. The strike and dip of the ore vein.
2. The true thickness of the ore vein.



	FROM 0		ELEV
A	435 E	610 N	980'
B	815 E	370 N	940'
C	605 E	195 N	955'

PROBLEM 8-52

The simplified drawing of the four-bar linkage shown (three links and the rigid support) has link A-B rotate 360° around pinned connection A. Link A-B's motion causes link C-D to oscillate about pinned connection D. At the instant shown, a velocity analysis has link C-D rotating CCW at 18.3 radians per second. Note that the velocity of point B of link A-B is V(B) = ω(AB) × (0.03 m) = 1.8 m per second. The component of V(B), which is coincident with member B-C, causes link B-C to move to the left with a velocity of V(BC) = 1.2 m per second as found graphically. Next, a component of V(BC) perpendicular to C-D causes C-D to rotate CCW about point D with an angular velocity of ω(CD) = (1.19)/0.065 = 18.3 radians per second. Determine the following:

1. The instantaneous angular velocities of ω(CD) when A-B is at 90°, 180°, and 270°.
2. At what values of θ will C-D have an angular velocity of zero? Why?



FOUR-BAR LINKAGE

PROBLEM 8-53

The cam and cam follower shown represent a camshaft cam and valve follower in an internal combustion engine. The cam rotates at a constant rate of 2,000 rpm, which is 209 radians per second (2000/60 = 33.33 RPS; and 33.33 × 2 × π = 209 radians per second). The cam has rotated 225° at the instant shown and is transferring a velocity of 120 inches per second to the follower as determined by a graphical analysis. The velocity of the point in contact T at this instant is V(T) = ω(cam) × 0.98 inch = (209 radians per second) × (0.98′) = 205″ per second. Then the resolution of the 205″/sec gives 120″/sec to the follower, and the other component indicates a sliding velocity parallel to the bottom surface of the valve. Hence, good lubrication is required.

Lay out the cam from the dimensions given and graphically determine the velocity of the valve throughout one revolution, starting at θ = 0°. Record the results in a graph of V(follower) versus angle of rotation θ. Suggestions: (1) From θ = 180° to 360° determine V(follower) at 15° intervals. (2) Lay out the cam on one sheet of drawing paper and use an overlay sheet of drawing paper for the intervals.



PROBLEM 8-54

The laser beam a-b shines on the metal door shown. As the door swings open, the laser beam traces a path on the door's surface. Determine the path for the door opening 150° and show the path in view F.



PROBLEM 8-55

A basic toggle mechanism is used to generate a large force from a smaller force for punching holes in metal. For the position shown in the simplified mechanism, what force is generated at punch A, vertically downward? When the 40,000 N force is at B2, what force at A is generated vertically downward?



PROBLEM 8-56

For the coplanar-concurrent system shown, determine the forces in members AB and BC using the method of joints.



PROBLEM 8-57

Use the method of Maxwell diagram with Bow's notation to determine the forces in each member of the truss shown. Tabulate the magnitudes and whether the members are in tension or compression.



PROBLEM 8-58

Redraw the tripod and the 1,500 lb applied force starting at the lower left-hand area of a drawing sheet. Determine the force in each member by the method shown in this chapter, and use revolution to finally determine the magnitude of each force. *Suggestion:* Use members o-b and o-c to form a plane.



PROBLEM 8-59

From the given information, lay out the four noncoplanar-concurrent force vectors and add them tail to head in any order (the order can differ in each view also) to determine the equivalent resultant of the four forces. Then, find the magnitude of the resultant by revolution. Also, determine the bearing and percent slope of the resultant. The coordinates of the four forces originating from point o are:

a. (10,5,5)
b. (4,–13,–10)
c. (–8,–8,8)
d. (–15,5,–10)



PROBLEM 8-60

A ham radio operator needs to know the lengths of three guy wires for his antenna installation and where to locate guy wire o-c. At the lower left corner of a sheet of drawing paper, construct a layout of the given roof information and solve the ham's guy wire problem using rotation. Guy wire o-c is to clear corner f of the chimney by one foot. Show all work and tabulate the answers. aT



PROBLEM 8-61

A tension spring a-b constrains a 30″ wide door. The spring shown in simplified schematic form has a spring constant of 5 lb/in., i.e., 5 lb will stretch the spring 1″. The door shown in the closed position pivots about a hinge located at point c. At the position shown, the spring has an initial tension of 6 lb. What will be the total tension in the spring when the door is opened 90°? Solve the problem using revolution.



PROBLEM 8-62

The simplified drawing shows a personnel lift, powered by a hydraulic cylinder, DC. At different angles θ the force F(DC) required by the cylinder is calculated by dividing the moment due to the 1,000 lb load (1,000 lb load × the shortest distance to the line of action of the 1,000 lb load from point A), by the shortest distance to the line of action of the cylinder's force F(DC). The shortest distances are called moment arms. Redraw the positions of the lift as specified in the table, locate the cylinder, measure moment arms, and do the calculations to finish the table.



	ANGLE	1,000 lb MOMENT	CYLINDER MOMENT	FORCE IN CYL.
$\Sigma M_A = 0$	0°	22,000 ft-lb = 3.1 x F(CYL)		7,097 lb
	15°			
	30°			
	40°	17,500 ft-lb = 2.3 x F(CYL)		7,609 lb
	50°			

NOTE:
- ARMS AE AND BF ARE ALWAYS PARALLEL
- A, B, C, D & E ARE PINNED JOINTS
- CHANGE IN LENGTH CD AS LIFT RISES IS STROKE OF CYLINDER
- A MOMENT ABOUT A POINT, DUE TO A FORCE, EQUALS THE PRODUCT, OF THE FORCE TIMES THE SHORTEST DISTANCE TO THAT POINT FROM THE LINE OF ACTION OF THE FORCE

$\Sigma M_A = 0$ AT 0° (1,000)(22.0) = (3.1)(FORCE IN CYLINDER) ft-lb
AT 40° (1,000)(17.5) = (2.3)(FORCE IN CYLINDER) ft-lb

PROBLEM 8-63

A floating golf-course green, supported by a concrete float, is moved by changing the lengths of four wire ropes powered by winches inside the float. From the position shown, the green is moved 130 yards west and 20 yards north. Use revolution to determine the change in length of each cable, A, B, C, and D. Tabulate the changes. (Ask your golfing friends if they could hit the green at the new position.)



9

Patterns and Developments

KEY TERMS

Bend allowance charts
Developed length
Development
Development surface
Double-curved surface
Flat-plane surface
Parallel line development
Parallel station lines
Plane surface
Radial line development
Seams
Single-curved surface
Stretchout line
Thickness gage
Triangulation
Triangulation development
True distance
True length
Warped surface
Weight gage

CHAPTER OUTLINE

Developments • Parallel line development • Radial line development • Triangulation development • True-length diagrams • Notches • Bends • Summary • Review questions • Chapter 9 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Define the term *development* and list the major kinds of developments.
- Demonstrate proficiency in making parallel line developments.
- Demonstrate proficiency in making radial line developments.
- Demonstrate proficiency in the application of triangulation developments.
- Demonstrate proficiency in constructing a true-length diagram.
- Explain when and how the two major types of notches are used.
- Demonstrate proficiency in performing bend calculations.

Developments

A *development* is the pattern or template of a shape that is laid out in a single flat plane in preparation for the bending or folding of a material to a required shape. Surface developments are used in many different industries. Some examples of objects requiring developments are cereal boxes, toolboxes, funnels, air-conditioning ducts, and simple mailboxes.

Three major kinds of surface developments are parallel line developments, radial line developments, and triangulation developments. *Parallel line developments* are used for objects having parallel fold lines. *Radial line developments* are those whose fold lines radiate from one point, ***Figure 9-1***. *Triangulation development* is the development process of breaking up an object into a series of triangular plane surfaces, ***Figure 9-2***. Each kind of development is explained here in full.

Surfaces

A *development surface* is the exterior and/or interior of the sheet material used to form an object. The various kinds of surfaces include plane surface, single-curved surface, and double-curved surface.

If any two points anywhere on a surface are connected to form a straight line, and that line rests upon the surface, it is a *plane surface*. If all points on a surface



FIGURE 9-1 *Parallel line development and radial line development.*



FIGURE 9-2 *Triangulation development.*

can be interconnected to form straight lines without exception, it is a *flat-plane surface*. The top of a drawing board is an example of a flat-plane surface. A flat-plane surface can have three or more straight edges. Objects such as a cube or a pyramid are bounded by plane surfaces. If a surface can be unrolled to form a plane, it is a *single-curved surface*. A cylinder or a cone is an example of a single-curved surface.

A surface that cannot be developed because it is neither a plane surface nor a curved surface is a *warped surface*. An automobile fender is an example of a warped surface. This kind of surface is usually stamped or pressed into shape. An object fully formed by curved lines with no straight lines is a *double-curved surface*. A sphere is an example of a double-curved surface. This type of surface cannot be developed exactly by using flat patterns; only an approximate development can be made.

Laps and Seams

Extra material must be provided for laps and *seams*. Many kinds of seams are available, ***Figure 9-3***. When making a choice, the drafter must take into account the thickness of the metal so that crowding of the metal at the joints is not a problem. Allowance must be made for the gluing, soldering, riveting, or welding processes for joints. The method of fastening joints together varies with the material and, accordingly, the elimination of rough or sharp edges. Tabs for the drawing problems at the end of this chapter should be designed to support the joining surfaces, ***Figure 9-4***.

Design Practices

The drafter should lay out developments according to the dimensions of stock materials for economy and the best use of materials and labor. The stock material area required to cut a pattern should be kept to the smallest



FIGURE 9-3 *Many types of seams are available.*



FIGURE 9-4 *Tabs should support the joining surfaces.*

convenient size. It is good practice to put the seam at the shortest joint and to attach tops and bottoms along the longest possible seam or bend to reduce the length requiring soldering, riveting, or welding. It is assumed that the inside surface of the final object is the side that the pattern defines. (The important dimension sizes are usually the inside surfaces.) Fold or bend locations in the material are shown on the pattern with thin, solid lines and are locations that are also assumed to occur on the inside surface of the final object.

Thickness of Material

The actual thickness of sheet metal is specified by gage numbers. Each gage number indicates a particular thickness of material. ***Figure 9-5*** lists the gage number and gage sizes for sheet and plate steel. These are nominal thicknesses, subject to permissible tolerances. Today, there is considerable confusion when using the gage numbering system.

In 1893, Congress established the United States Standard Gage, and it was primarily a *weight gage* rather than a *thickness gage*. It was derived from the weight of wrought iron. At that time, the weight of wrought iron was calculated at 480 pounds per cubic foot; thus, a plate 12″ square and 1″ thick weighed 40 pounds. A No. 3 U.S. gage represents a wrought iron plate weighing 10 pounds per square foot. Therefore, if a weight per square foot 1″ thick is 40 pounds, the plate thickness for a No. 3 gage equals $10 \div 40 = 0.25$″, which is the original thickness equivalent for a No. 3 U.S. gage. Since this and all other gage numbers were based on the weight of wrought iron, they are not correct for steel. To add to the confusion, there is considerable variation in the gage thickness for different kinds of material. For example, a gage used for such nonferrous materials as brass and copper is sometimes also used to specify a thickness for steel or vice versa.

Today, to help eliminate the problems, the decimal or metric system of indicating gage size is now replacing the older gage size numbering system.

Parallel Line Development

In parallel line developments all fold lines are parallel. (Refer back to Figure 9-1.)

A three-view drawing of a simple two-inch cube is shown in ***Figure 9-6***. A cube is a specific kind of prism.

SHEET METAL						
GAGE	ALUMINUM		BRASS		STEEL	
	THICKNESS	WT./SQ. FT.	THICKNESS	WT./SQ. FT.	THICKNESS	WT./SQ. FT.
8	.1285	1.812	.1285	5.662	.1644	6.875
9	.1144	1.613	.1144	5.041	.1494	6.250
10	.1019	1.440	.1019	4.490	.1345	5.625
11	.0907	1.300	.0907	3.997	.1196	5.000
12	.0808	1.160	.0808	3.560	.1046	4.375
13	.0720	1.020	.0720	3.173	.0897	3.750
14	.0641	.907	.0641	2.825	.0747	3.125
15	.0571	.805	.0571	2.516	.0673	2.812
16	.0508	.720	.0508	2.238	.0598	2.500
17	.0453	.639	.0453	1.996	.0538	2.250
18	.0403	.580	.0403	1.776	.0478	2.000
19	.0359	.506	.0359	1.582	.0418	1.750
20	.0320	.461	.0320	1.410	.0359	1.500
21	.0285	.402	.0285	1.256	.0329	1.375
22	.0253	.364	.0253	1.119	.0299	1.250
23	.0226	.318	.0226	.996	.0269	1.125
24	.0201	.289	.0201	.886	.0239	1.000
25	.0179	.252	.0179	.789	.0209	.875
26	.0159	.224	.0159	.700	.0179	.750
27	.0142	.200	.0142	.626	.0164	.688
28	.0126	.178	.0126	.555	.0149	.625
29	.0113	.159	.0113	.498	.0135	.562
30	.0100	.141	.0100	.441	.0120	.500
31	.0089	.126	.0089	.392	.0105	.438
32	.0080	.112	.0080	.353	.0097	.406
33	.0071	.100	.0071	.313	.0090	.375
34	.0063	.089	.0063	.278	.0082	.344
35	.0056	.079	.0056	.247	.0075	.312
36	.0050	.071	.0050	.220	.0067	.281
37	.0045	.063	.0045	.198	.0064	.266
38	.0040	.056	.0040	.176	.0060	.250
39	.0035	.050	.0035	.154	–	–
40	.0031	.044	.0031	.137	–	–

FIGURE 9-5 *Thickness of material.*



FIGURE 9-6 *Simple multiview drawing of a cube.*

Notice that all the fold lines that form the lateral surfaces of a prism are parallel, ***Figure 9-7A***. If the cube were to be unfolded, it would appear as it does in ***Figures 9-7B, 9-7C,*** and ***9-7D***. The finished development is shown in ***Figure 9-7E***.

Notice that the cube was developed or laid out from a baseline, sometimes referred to as the *stretchout line*. Fold lines are always oriented 90° from the baseline, as illustrated. If the pattern were to be cut from a flat sheet of material, tabs would be needed to fasten the cube together. Tabs must be positioned so as to make each meet with an untabbed edge, ***Figure 9-7F***. Notice that there are seven tabs and seven blank edges. Each tab folds to meet a particular blank edge.



FIGURE 9-7 *(A) All fold lines are parallel; (B) Cube as it unfolds; (C) cube as it unfolds further; (D) cube flattened out; (E) cube in the finished development; (F) cube flattened out with tabs added.*

How to Develop a Truncated Prism Using Parallel Line Development

GIVEN: A prism with a front view, top view, and auxiliary view, *Figure 9-8A.*

STEP 1 Locate the baseline, which must always be 90° from the parallel fold lines. Label each fold line clockwise in alphabetical or numerical order. Always start with the shortest fold line, *Figure 9-8B.* Either fold line a-a′ or b-b′ would be eligible, and a-a′ is selected. Notice that the starting fold line is also the finishing fold line, and each is labeled at the same location. The finishing fold line is a-a′. All real (or true) lengths of the fold lines are seen in the front view, and the real distances between their locations are seen in the top view.

STEP 2 On a separate sheet of paper, construct a pattern baseline, allowing enough space for the complete development, top and bottom surfaces, and the required tabs. At the left end of the baseline, draw a line perpendicular to the baseline. This is the first fold line and is also a seam edge. Transfer the true length from fold line a-a′ (as measured from the three-view drawing in Figure 9-8A). Label this line a-a′ also, as illustrated in *Figure 9-8C.*

STEP 3 From the top view of Figure 9-8A, obtain the true distance from the first fold line location at a-a′ to the second fold line location at b-b′. On the pattern baseline, transfer this distance, measuring from the first fold line a-a′, and draw the next fold line parallel to the first fold line. Label it b-b′, *Figure 9-8D.*

STEP 4 Repeat the first three steps, alternating true fold line lengths and true distances between fold lines until all the true lengths and true distances are transferred. Each of the true lengths a-a′ through e-e′ are transferred from the front view, and the true distances between them are found from the top view of Figure 9-8A. Connect the points as illustrated in *Figure 9-8E.*

STEP 5 The edge selected for attachment of the top surface should be made to keep the rectangle size from which the whole pattern is cut as small as possible. Line a′b′ would be the best, except an acute angle cutout c′b′a′ is difficult to make. The fold line a′d′ is next best, as shown. From Figure 9-8A, transfer the true size and shape of the top surface (auxiliary view) and the bottom surface, *Figure 9-8F.*

STEP 6 Add tabs enough to fasten the edges. The locations should be selected so as not to enlarge the material area needed for the pattern cutout, *Figure 9-8G.* Check to verify that the number of tabs equals the number of blank edges in the same manner as is illustrated in Figure 9-7F. This completes the parallel line development of the object in Figure 9-8A.



FIGURE 9-8 *(A) Development of a truncated prism using parallel line development; (B) Step 1.*



FIGURE 9-8 *(Continued) (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5; (G) Step 6 (completed development of the prism).*

How to Develop a Truncated Cylinder Using Parallel Line Development

GIVEN: A cylinder with a front view, top view, and auxiliary view, *Figure 9-9A*. In developing a cylinder, the same procedure is used as when developing a prism. Because the cylinder has a rounded surface, line segments called station lines must be assumed or chosen on the lateral surface. This is explained in Step 1.

STEP 1 Locate a baseline that must always be 90° from the fold lines, sometimes referred to as *parallel station lines*. The bottom corner of the lateral surface is selected as a convenient location because it already exists. In the view where the cylinder appears as a diameter (the top view in this example), divide the diameter into equal divisions, *Figure 9-9B*. This example uses 12 equal divisions, but any number of appropriate equal divisions would do. These divisions locate fold line positions, which are used only for construction and layout purposes. Starting with the shortest fold line, consecutively label each division—in this example, a through 1. Note that a-a′ marks the beginning and ending of the same line, which meets from opposite directions. The true "distances" between station lines can be approximated in this top view. Project each point into the next (front) view in order to find the true "lengths" of the fold lines. It should be re-emphasized that the fold lines must be 90° from the baseline.

STEP 2 On a separate sheet of paper, construct a pattern baseline allowing enough space for the complete development, both ends, and the required tabs. At the left end of the pattern baseline draw a line perpendicular to the baseline. This is the first fold line location a-a′. Transfer the true length a-a′ from



FIGURE 9-9 *(A) Development of a truncated cylinder using parallel line development; (B) Step 1; (C) Step 2; (D) Steps 3 and 4; (E) Step 5 (completed development of the cylinder).*

the front view of Figure 9-9B. Label this line as illustrated in ***Figure 9-9C.***

STEP 3 Two methods are used for finding the distances between station lines. Method A is an approximate method that assumes the cylinder to be a prism, whereas Method B is mathematically correct.

METHOD A: From the top view of Figure 9-9B, obtain the direct chordal distance from the first station line a-a′ to the second

fold line b-b′. On the pattern baseline, draw the second fold line parallel to the first station line a-a′ at the chordal distance found from the top view, and label it b-b′, *Figure 9-9D*. Repeat these steps, alternating chordal lengths and true distances until all station lines have been located and drawn. Note that the last fold line length a-a′ is a duplicate of the first.

METHOD B: The required length to form the cylinder's circumference can be calculated using the following formula: circumference = cylinder diameter × π. (π = 3.1416, approximately.) The baseline is extended to this length and divided into the same number of divisions as was done at Step 1 in the top view of the cylinder, Figure 9-9B. The division can best be performed as a construction exercise, rather than mathematically. Refer back to Chapter 4, "Geometric Construction." Each of the 13 division locations (from 12 spaces) is the correct location of the required station lines and can be successively labeled.

STEP 4 Add the true size and shape of the bottom surface (bottom view), and the top surface (auxiliary view). The attachment locations of these surfaces are particularly difficult, as the mathematical point of tangency is not easily isolated on the pattern. The top surface location is chosen to allow the widest access of cutting to this point. The bottom surface can be added to any of the fold lines. In order to locate the top surface, the distance X from center to point 0 is transferred from Figure 9-9B to the development, and projected 90° as illustrated in Figure 9-9D.

STEP 5 Add the tabs necessary for edge attachments. In cylinders, a notched tab must be used in order to accommodate crowding by surface curvature. A tab must also be added at fold line a-a′ in order to attach edge a-a′ to the other edge a-a′; the top (auxiliary) and bottom fold to meet the notched tabs, *Figure 9-9E.*

Regardless of the shape, whether it be a cylinder or a prism, parallel line developments follow, essentially the same procedure. *Figure 9-10* shows a prism



FIGURE 9-10 *Creating a new baseline.*



FIGURE 9-11 *Using station lines instead of fold lines.*

truncated at both ends, which necessitates creating a new baseline other than a part edge to ensure that all fold lines (instead of station lines) are at 90° to the baseline. *Figure 9-11* is a cylindrical prism, truncated at each end, which requires the selection of station lines instead of using existing fold lines. *Figure 9-12* shows a series of truncated cylinders, similar in construction to the preceding views, whose patterns are used to form an elbow.



FIGURE 9-12 *Series of patterns used to form an elbow.*

Radial Line Development

Radial line development is different from parallel line development in that all fold lines or line segments radiate from one point. (Review Figure 9-1.) As in all patterns, true lengths and true distances must be used in laying out the developments.

How to Develop a Truncated Pyramid Using Radial Line Development

GIVEN: A two-view drawing and an auxiliary view of a pyramid with the top cut off at an angle (truncated), *Figure 9-13A*. Label points clockwise starting with the shortest fold line. In this example, either a-1 or b-2



FIGURE 9-13 *(A) Development of a pyramid using radial line development; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4 (completed development of a pyramid).*

could be used. Line a-1 is selected, but the fold line location a-1 is also the meeting corner of edges a-1 and a-1. True distances between the end points of the fold lines are evident in the top view. For example, a-b, b-c, c-d, and d-a are true lengths.

STEP 1 To find the true length of the fold lines, they must be rotated to a position that is parallel to the frontal viewing plane, ***Figure 9-13B***. In the top view, point a is rotated as shown and projected into the front view. This revolved line from a′ to 0 is its true length. Similarly, point c in the top view is rotated and projected into the front view, giving the true length of c′-0. The same procedure is used to find the true lengths 3′-0 and 1′-0. To construct a development of this object, continue with the following steps.

STEP 2 Using the true length from 0 to a (a′-0), swing the arc as shown in ***Figure 9-13C***. On this arc, mark off as chord lengths the true distances between the fold line end points a to b, b to c, c to d, and d to e, as transferred from the top view of Figure 9-13B. Label all points as shown. Connect the fold lines a to 0, b to 0, c to 0, d to 0, and a to 0.

STEP 3 Using the true lengths found in Figure 9-13B, locate points 1, 2, 3, 4, and 1 on the respective fold lines 0-a, 0-b, 0-c, 0-d, and 0-a. Note that 0-1 is the same length as both 0-2 and 0-1, and 0-3 is the same length as 0-4. Add the auxiliary and bottom views, transferring them directly from the original drawing 9-13A, ***Figure 9-13D***.

STEP 4 Add the required tabs as illustrated in ***Figure 9-13E***. Check to be sure the number of tabs equals the number of blank edges. In this example, there are seven tabs and seven blank spaces.

How to Develop a Truncated Cone Using Radial Line Development

As with cylindrical parallel line developments, station lines are line segments that must be positioned on the lateral surface in order to draw a development.

GIVEN: A two-view drawing of a round cone, with the top cut off at an angle (truncated), and having no fold lines, ***Figure 9-14A***. It is necessary to first complete the given views and to draw a true view of the inclined flat surface. To project the flat surface to the top view, the front view is sliced at points A through G. These seven slices are projected into the top view and appear as circles, correspondingly labeled A through G. The points of intersection of the edge view with each slice is projected into the top view. To construct the auxiliary view, project from the seven point intersections perpendicular from the edge view of the flat surface to any convenient distance for the auxiliary view. Draw and use the center line as a reference line, and transfer all point-to-center line distances from the top view to the auxiliary view; refer to reference distances X.

STEP 1 To construct a development of this object, station lines need to be established, and their true lengths and true distances must be determined. In the top view of ***Figure 9-14B***, divide the base circle into 12 equal parts, and label each point. In this example, numbers 1 through 12 are arbitrarily used, positioned as illustrated. The station line 0-3 must have two identities because two edges will meet at this point. The true distances between station lines are located between their end points on the cone base, seen in the top view. Project the 12 points down into the base of the front view. These are the end points of the station lines in the front view. Draw a line from each of these end points up to point 0.

STEP 2 There are two methods of drawing the pattern outline. Each begins with swinging an arc whose radius is the true length of the lateral distance from the apex to the base, or length 0-3 or 0-9. The compass radius can be set to this distance on Figure 9-14B. This distance can also be derived mathematically if the diameter of the base of the cone is known and the altitude (perpendicular distance from base to apex) is known. The formula is:

RADIUS = THE SQUARE ROOT OF [(½ CONE BASE DIAMETER)^2 + (ALTITUDE)^2]

After swinging this arc, choose Method A, which approximates the cone as a pyramid, or Method B, which is mathematically correct.

METHOD A: In the top view of Figure 9-14B, the direct chordal distance between any two station line end points, say 5 and 6 (they are all equal), is an approximation of the arc

length between them. On the 0-3 radius just drawn, strike off this chordal distance between station line end points repeatedly to equal the same number of spaces on the arc as the top view of the cone was divided into in Step 1, and ending at point 3, ***Figure 9-14C.*** Connect the station line end points from point 0 to each of these arc intersections, and proceed to Step 3.

METHOD B: The central angle of the pattern is determined by a pattern arc length needed to equal the circumference of the base of the cone. The ratio of the central angle (A°) to a full circle 360° is the same as the circumference of the base of the cone is to the full circumference generated by the pattern's radius.

$$\frac{A^\circ}{360^\circ} = \frac{\text{CIRCUMFERENCE OF BASE OF CONE}}{\text{CIRCUMFERENCE OF PATTERN}}$$

$$\frac{A^\circ}{360^\circ} = \frac{\pi \times \text{CONE DIAMETER AT BASE}}{\pi \times \text{PATTERN DIAMETER}}$$

$$\frac{A^\circ}{360^\circ} = \frac{\text{CONE BASE DIAMETER}}{2 \times \text{PATTERN RADIUS}}$$

$$A^\circ = \frac{180 \times \text{CONE BASE DIAMETER}}{\text{PATTERN RADIUS (A' – 0)}}$$



(A)



(B)



(C)



(D)



(E)

FIGURE 9-14 *(A) Development of a truncated cone using radial line development; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4 (completed development of a cone).*

After the central pattern radius A° is found, the angle between successive station lines (a°) is found by dividing the same number of conic divisions done in Step 1 into A°. The chordal lengths (D) of these divisions are found by using the formula:

$$D = 2 \times \text{PATTERN RADIUS} \times [\text{SIN } (\tfrac{1}{2} A°)]$$

This chordal distance can then be struck off on the pattern radius to form the same number of spaces as the conic divisions in Step 1, and labeled accordingly. See Figure 9-14C. Connect these station line end points from point 0 to each of the intersections, and proceed to Step 3.

STEP 3 To draw the edge of the intersection that the cone's lateral surface makes with the upper flat surface, true lengths from the apex to this edge at each station line must be determined. Only 3′-0 and 9′-0 are visible as true lengths in the front view of Figure 9-14B. To find the other true lengths, each segment must be rotated to a position parallel to the frontal viewing plane; in this example, on line 3-0. Project the intersection of each station line at the truncated surface edge to line 3-0 on the cone profile in the front view (on line 3-0).

Starting with the shortest line segments of the cone, swing true lengths arc 0-3′ on the corresponding pattern station lines, as illustrated in *Figure 9-14D*. Swing the apex-to-edge true length found for each station point at the corresponding station line on the pattern. Repeat for all 13 stations, 3 through 12 and back to 3. Label each point as illustrated.

Draw light line segments between each of the station line intersection positions found on the corresponding pattern station lines. This completes the true contour of the top edge, Figure 9-14D.

STEP 4 Add the top, bottom, and split tabs, as illustrated in *Figure 9-14E*.

Triangulation Development

Triangulation is the third major method used to lay out a surface development. *Triangulation* is a method of dividing a surface into a number of triangles and then transferring each triangle's true size and shape to the development. (Review Figure 9-2.) As with parallel line and radial line developments, *true lengths* and *true distances* must be used exclusively in pattern constructions.

True-Length Diagrams

Before any layouts can be started, true lengths and true distances of the object's boundary edges must be determined. A true-length diagram is usually used to develop true lengths and true distances of these edges. A true-length diagram is often a quicker way to obtain the needed projections than descriptive geometry methods.

How to Develop a Transitional Piece Using Triangulation Development

GIVEN: *Figure 9-15A* describes a transitional piece using a top view, front view, and isometric view. Each of the object's corners is labeled as illustrated. Note that the true distances A to B, B to C, C to D, D to A, 1 to 2, 2 to 3, 3 to 4, and 4 to 1 can be measured directly from the top view. As drawn, the lengths A-1, B-1, B-2, C-2, C-3, D-3, D-4, and A-4 are not shown in their true lengths. A true-length diagram must be used to find these.

STEP 1 A true-length diagram is a combination of two views. In this example, it is a combination of the top view and the front view, *Figure 9-15B*. The height between points A and 1 is shown projected from the front view to the true-length diagram. The distance X between corresponding line end points A and 1 is found in the top view and transferred to the true-length diagram. The illustrated diagonal line, drawn in the true-length diagram, is the true length of A-1. As all the heights and top view distances between end points are the same for each of the lateral edges, then A-1 is also the same length as B-1, B-2, C-2, C-3, D-3, D-4, and A-4. These true lengths are needed to lay out the development.

STEP 2 Starting from line A-1 and using true lengths and true distances, reconstruct each triangle representing a surface of the object, as illustrated in *Figure 9-15C*. (Review Chapter 3 for aid in transferring a triangle.) Notice in this example that all true distances are transferred from the top view, and all true distances are transferred from the true-length diagram. A tab is



FIGURE 9-15 *(A) Development of a transitional piece using triangulation development; (B) Step 1 (true-length diagram); (C) Step 2.*

added to join A-1 to A′-1′. This completes the transitional piece development as drawn in Figure 9-15A.

How to Develop a Transitional Piece with a Round End Using Triangular Development

A transitional piece that is square or rectangular at one end and round at the other is laid out using a procedure very similar to the one outlined previously. The only difference is that station lines must be positioned on the lateral surface of the round-to-corner transitions. *Figure 9-16A* illustrates a two-view transitional piece with a round top end and a rectangular bottom end. In this example, the top end is divided into 12 equal spaces. Each point is numbered clockwise as illustrated. The bottom four corners making up the bottom rectangle are labeled A through D, *Figure 9-16B*. The true distances from A-B, B-C, C-D, and D-A′ are found in the top view. Station lines W, X, Y, and Z are not true lengths, but the true lengths must be determined with a true-length diagram. Note that in the true-length diagram, the true length of line W, from A′ to 0, is also the same lengths for B-6, C-6, and D-12. Lines X, Y, and Z are also used four times at corresponding locations. Segment the object into triangles and develop the pattern by using true lengths and true distances to reconstruct each adjoining segment, *Figure 9-16C*.



FIGURE 9-16 *(A) Development of a transitional piece with a round end using triangulation; (B) true-length diagram; (C) completed development of a transitional piece with a round end.*

How to Develop a Transitional Piece with No Fold Lines Using Triangular Development

Figure 9-17A shows a transitional piece with no evident fold lines or line segments. It is developed in the same manner as any other triangulation development.

STEP 1 Divide the top and bottom surfaces into equal spaces as illustrated in *Figure 9-17B*. In this example, the top edge is divided into 12 equal spaces, 0 through 12. The bottom edge is divided into the same number of equal spaces and lettered A through L to A.

STEP 2 Connect points 12 to A, 1 to B, 2 to C, and consecutively to points L to 11 with solid lines, as illustrated in *Figure 9-17C*. Dashed lines are added to segment the object into various triangles.

STEP 3 True distances from 1 to 2, 2 to 3, 3 to 4, and so on through 11 to 12, and the true distances from A to B, B to C through to L to A′ are found in the top view, Figure-9-17C. The other fold lines connecting the top and bottom are not true lengths and, therefore, true-length diagrams must be made, one for the solid lines and the



FIGURE 9-17 *(A) Development of a transitional piece with no fold lines; (B) Step 1; (C) Step 2; (D) Step 3 (true-length diagram); (E) completed development of a transitional piece.*

Industry Application

Andrews Sheet Metal Fabrication (ASMF) is a successful family business that to date has supported three generations of the Andrews family. ASMF has been in business for more than 60 years. In the old days, all of the key management and technical positions were held by family members who learned their respective trades from grandfathers, fathers, older brothers, and uncles. But in recent years, ASMF's reputation for quality has resulted in rapid expansion. The company must now look outside the family for designers, drafters, and leading technicians.

This is causing a problem. John Andrews, the current CEO of ASMF, explains the situation as follows: "When we started looking outside of the family to fill technical positions—particularly design and drafting positions—we simply could not find anyone qualified. We received plenty of applications from people who had excellent mechanical drafting skills relating to precision metal parts, but most had never heard of sheet metal fabrication. No one knew how to perform bend calculations. Out of frustration, we started calling technical schools and community colleges as far away as 100 miles. Finally, after two weeks of telephone calls we came across a small technical college in a town 75 miles to the south that sounded promising. In fact, it sounded too good to be true.

"Fully expecting to be disappointed, I visited the college and examined the curriculum. To my great surprise, I could have hired any of the school's advanced students. They all knew patterns, developments, and bend calculations. I gave projects that included parallel line development, radial line development, triangulation development, and true-length diagrams. I talked with several students who actually pointed out errors in a set of hand calculations I had brought with me.

"I hired two students on the spot, and worked out an agreement to notify the head of the college's drafting program every time a position became available. We plan to have a long-term relationship with this college. In fact, I'm going to establish the ASMF scholarship for the sheet metal trades to encourage drafting students to study our field. Our new relationship with the college is a win-win-win partnership. ASMF wins, the college wins, and the students win."

other for the dashed lines, ***Figure 9-17D.*** The development is laid out by constructing connecting triangles using the lengths of each leg of each triangle, ***Figure 9-17E.***

Notches

Some developments require notches. Two major types of notches are usually used: a sharp V or a rounded V, ***Figure 9-18.*** The sharp V is used only if a minimal force is tending to part the material. The sharp point of the V will tear or crack under stress. The rounded V is used where parts would be under greater stress. The radius of the vertex of the rounded V should be at least twice the thickness of the metal used, and larger if possible.



FIGURE 9-18 *Notches.*

Bends

When sheet metal is bent to form a corner, rib, or design, the outer surface stretches and the inner surface compresses. The length of material needed by each bend must be calculated and added to the straight, unbent portions of the pattern. The material needed by each bend is the length of the neutral axis within the material, where neither compression nor stretching occurs. This is calculated either by using formulas or various charts available for this purpose.

Bend allowance charts are included in Appendix A and are much faster to use than a formula. Two basic kinds of charts are used to calculate bend allowance, in both the English and metric systems. One type is

used for 90° bends; the other for bends from 1° through 180°. The total length of a pattern is called the *developed length.* To determine the developed length, the stretched-out flat pattern must include all straight sides, plus the calculated bend allowances.

How to Find All Straight Sides of a 90° Bend

Figure 9-19A shows a simple 90° bend with an inside radius of .25, a sheet metal thickness of .125, and legs of 2.0 and 3.0. (The English system inch is used in this example.) Bend radii are always measured from the surface closest to the bend radius center.

STEP 1 Locate the tangent points at the ends of the straight sides.

STEP 2 Add the thickness of the sheet metal to the bend radius .25 (.125 + .25 = .375).

STEP 3 Subtract the sum of the sheet metal thickness .125 and the radius .25 from the 3.00 overall length of the object (3.00 – .375 = 2.625).

STEP 4 Subtract the sum of the sheet metal thickness .125 and the bend radius .25 from the 2.00 overall height of the object (2.00 – .375 = 1.625).

STEP 5 Add the two straight sides together (2.625 + 1.625 = 4.250). This is the total length of the straight sides of this object, *Figure 9-19B.*

How to Find the Bend Allowance of a 90° Bend

Review Figure 9-19A.

STEP 1 Note the metal thickness, in this example .125, and the inside radius, in this example .25.

STEP 2 Refer to the bend allowance chart in inches for 90° bends in Appendix A.

STEP 3 The left-hand column gives various metal thicknesses. Go down the left-hand column until the required size or the closest size is found. In this example it is .125.

STEP 4 Along the top of the chart is listed various inside radii; go across the top of the chart to the required size or the closest radius, in this example .25.

STEP 5 From the .125 number in the left-hand column, project across to the right; from the .25 number along the top of the chart, project down to where the two columns intersect. Given is the bend allowance for material .125 thick with a .25 radius. In this example the bend allowance is .480, *Figure 9-19C.*



FIGURE 9-19 *(A) Bend allowance of 90° bend; (B) total of straight lengths; (C) total length including straight lengths and bend allowance.*

STEP 6 The stretched-out dimension is found by adding the straight sides to the bend allowance; in this example, 4.250 + .480 = 4.730 (see Figure 9-19C).

How to Find the Total Straight-Side Length Adjoining a Bend Other than 90°

Figure 9-20A shows a simple 30° bend with an inside radius of 6.35 and a sheet metal thickness of 3.175 (the metric system is used in this example).



FIGURE 9-20 *(A) Bend allowance of a bend other than 90°—total of straight lengths; (B) total length of bend allowance; (C) total length including straight lengths and bend allowance.*

STEP 1 Locate the tangent points at the ends of the straight sides.

STEP 2 Determine the length of the straight sides and add them together (64.0 + 50.0 = 114.0). This is the total length of the straight sides of this object.

How to Find the Bend Allowance of Other Than a 90° Bend

Review Figure 9-20A.

STEP 1 Note the metal thickness, in this example 3.175, and the inside radius, in this case R6.35.

STEP 2 Refer to the bend allowance chart in millimeters for 1° bends in Appendix A.

STEP 3 The left-hand column gives various metal thicknesses. Go down the left-hand column until the required size or the closest size is found. In this example it is 3.175.

STEP 4 Along the top of the chart is listed various inside radii. Go across the top of the chart to the required size or closest radius, in this example 6.35.

STEP 5 From the 3.175 number in the left-hand column, project across to the right; from the 6.35 number along the top of the chart, project down to where the two columns intersect. Given is the factor used to calculate the bend allowance. In this example, .1356.

STEP 6 Multiply this factor times the actual degrees in the bend, from a straight 180° line, *Figure 9-20B*. This is the bend allowance (.1356 × 30° = 4.068).

STEP 7 Add the straight-side lengths to the bend allowance to get the total developed length: 114.0 + 4.068 = 118.068, *Figure 9-20C*.

NOTE: A 30° bend dimension as illustrated in Figure 9-21A is actually 150° (180° − 30° = 150°), Figure 9-21B. The total bend must be calculated from a straight piece that is actually 180° before bending.

Summary

- A development is the pattern or template of a shape that is laid out in a single flat plane in preparation for bending or folding into a required shape. The three types of developments are parallel, radial line, and triangulation.
- In parallel line development, all fold lines are parallel, and the object is laid out from a baseline known as the stretch line.
- In radial line development, all fold lines and line segments radiate from one point. True lengths and



(A)



(B)

FIGURE 9-21 *(A) Total bend must be calculated from straight line dimension—given is 30°; (B) as dimensioned, 30° is actually a 150° bend from a straight line.*

true distances must be used in laying out the developments.

- Triangulation is a method of dividing a surface into a number of triangles and then transferring each triangle's true size and shape to the development.
- When a development must be notched, two major types are used: sharp V and rounded V. Parts that will be subjected to greater levels of stress use the rounded V.
- When bending a sheet metal to form a corner, rib, or design, the outer surface stretches and the inner surface compresses. The length of material needed by each bend must be calculated and added to the straight, unbent portions of the pattern.

Review Questions

Answer the following questions either true or false.

1. A transitional piece is usually stamped or pressed into a particular shape.
2. A gage number represents the weight per square foot of a particular material.
3. The importance of developing the pattern or template with the inside surface up is that important dimension sizes and fold or bend locations are assumed to occur on the inside surface of the final object.
4. Tabs are used to fasten items together.
5. Bend allowance refers to the practice of calculating the length of material needed by each bend.
6. A true-length diagram often provides needed projections more quickly than descriptive geometry methods.
7. If a transitional piece does not have fold lines, it is developed in the same manner as any other triangulation development.
8. An automobile fender is an example of a single-curved surface.

Answer the following questions by selecting the best answer.

1. Which kind of development would be used to develop a pattern?
   a. Parallel line development
   b. Truncated line development
   c. Radial line development
   d. Triangulation line development
2. What are the two major kinds of notches used in a development?
   a. Sharp U or rounded U
   b. Sharp V or rounded U
   c. Rounded U or rounded V
   d. Rounded V or sharp V
3. In parallel line development, at which angle to the baseline must the fold lines be projected?
   a. 45° c. 90°
   b. 60° d. 180°
4. The gage system of calling out the thickness of a material is being phased out because:
   a. It is out of date.
   b. It causes considerable confusion.
   c. It is inaccurate.
   d. None of the above.
5. Which of the following elements **must** be located or laid out before a development can actually be started?
   a. True lengths c. Station lines
   b. True distances d. Both a and b

Chapter 9 Problems

The following problems are intended to give the beginning drafter practice in sketching, laying out auxiliary views if required, and drawing the stretched-out development of various objects. These problems will use one or more of the three standard methods of development: parallel line developments, radial line developments, and triangulation developments. The student will also practice calculating developed lengths by using various charts to determine full length before bending.

Conventional Instructions

The steps to follow in laying out any object that is to be developed are:

STEP 1 Study the problem carefully.

STEP 2 Determine which method or methods of development will be used (parallel line/radial line/triangulation).

STEP 3 On a scrap sheet of paper, draw to scale the number of views required to lay out **all** true lengths and true distances. Add the end view and auxiliary views, in scale, if necessary. Draw with a **sharp** 4-H lead, and work as accurately as possible.

STEP 4 Label each point, if necessary, in order to keep track of progress.

STEP 5 Check all lengths and auxiliary views if included.

STEP 6 Starting from a baseline, lightly lay out the development. Use true lengths and true distances for all measurements. (Be sure to start the seam at the shortest fold line possible.)

STEP 7 Label each point, if necessary, in order to keep track of progress.

STEP 8 Use phantom lines to represent all fold lines.

STEP 9 Add tabs as required, and check to see that there are enough but without duplications.

STEP 10 Recheck all true lengths and true distances.

STEP 11 Darken in all lines.

CAD Instructions

Student who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order; then begin the project.

Problems 9-1 through 9-18

Using the parallel line development method, develop each object starting from the given seam. Label each point clockwise; add ends and/or auxiliary views as necessary to develop a complete object. Add tabs .125 (3) × 45° to suit. Use phantom lines for all fold lines.

Extra assignment(s): *Cut out the developments and glue or tape them together to prove their accuracy.*

PROBLEM 9-1



PROBLEM 9-2



PROBLEM 9-3



PROBLEM 9-4



PROBLEM 9-5



PROBLEM 9-6



PROBLEM 9-7



PROBLEM 9-8



PROBLEM 9-9



PROBLEM 9-10



PROBLEM 9-11



PROBLEM 9-12



PROBLEM 9-13



PROBLEM 9-14



PROBLEM 9-15



PROBLEM 9-16



PROBLEM 9-17



PROBLEM 9-18



Problems 9-19 through 9-23

Using the parallel line development method, develop each object starting from the given seams. Add .125 (3) × 45° tabs as required to hold parts together. Design parts so there are as many identical parts as possible. Use phantom lines for all fold lines.

Extra assignment(s): *Cut out the developments and glue or tape them together to prove their accuracy.*

PROBLEM 9-19



PROBLEM 9-20



PROBLEM 9-21



PROBLEM 9-22



PROBLEM 9-23



Problems 9-24 through 9-26

Develop the objects by using the given dimensions. Using bend allowance charts, design layouts to include material for bends.

Extra assignment(s): *Cut out the developments and glue or tape them together to prove their accuracy.*

PROBLEM 9-24



PROBLEM 9-25



PROBLEM 9-26



Problems 9-27 through 9-30

Carefully lay out a full-size multiview drawing of the object; include all intersection lines. Make a full-size development of the object. Add tabs .125 (3) × 45° as required to hold parts together.

Extra assignment(s): *Cut out the developments and glue or tape them together to prove their accuracy.*

PROBLEM 9-27



PROBLEM 9-28



PROBLEM 9-29



PROBLEM 9-30



Problems 9-31 through 9-42

Using the radial line development method, develop each object starting from the given seam. Label each point clockwise; add ends and/or auxiliary views as necessary to develop a complete object. Add tabs .125 (3) × 45° to suit. Use phantom lines for all fold lines.

Extra assignment(s): *Cut out the developments and glue or tape them together to prove their accuracy.*

PROBLEM 9-31



PROBLEM 9-32



PROBLEM 9-33



PROBLEM 9-34



PROBLEM 9-35



PROBLEM 9-36



PROBLEM 9-37



PROBLEM 9-38



PROBLEM 9-39



PROBLEM 9-40



PROBLEM 9-41



PROBLEM 9-42



Problems 9-43 through 9-46

Using the triangulation development method, develop each object starting from the given seam. Label each point clockwise: add tabs .125 (3) × 45° to suit. Use phantom lines for all fold lines.

Extra assignment(s): *Cut out the developments and glue or tape them together to prove their accuracy.*

PROBLEM 9-43



PROBLEM 9-44



PROBLEM 9-45



PROBLEM 9-46



Problems 9-47 through 9-49

Using development charts, calculate the true developed length of each object. Round the answer to the nearest three places. Recheck all calculations.

PROBLEM 9-47



PROBLEM 9-48



PROBLEM 9-49



Problems 9-50 through 9-54

Using the parallel line, the radial line, or the triangulation development method, develop each object. Be sure to leave a seam and to add all required tabs to suit as required. Use phantom lines for all fold lines.

Extra assignment(s): *Cut out the developments and glue or tape them together to prove their accuracy.*

PROBLEM 9-50



PROBLEM 9-51



PROBLEM 9-52



PROBLEM 9-53



PROBLEM 9-54



10

Dimensioning and Notation

KEY TERMS

Allowance
Arrowhead
Attributes
Chamfer
Clearance fit
Decimal-inch dimensioning
Detail notes
Dimensioning
Dimension line
Extension line
Fractional dimensioning
General notes
Interference fit
Knurl
Leader line
Least material condition (LMC)
Manufacturing part family
Maximum material condition (MMC)
Metric dimensioning
Nominal dimension
Notation
Opitz system
Part family
Tolerance
Transition fit
Verification
Written notes

CHAPTER OUTLINE

Dimensioning systems • Dimension components • Laying out dimensions • Steps in dimensioning • Specific dimensioning techniques • Summary of dimensioning rules • Notation • Rules for applying notes on drawings • Group technology • Summary • Review questions • Chapter 10 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the three main dimensioning systems used in the United States: metric, decimal-inch, and fractional dimensioning.
- Demonstrate proficiency in properly using the following dimension components: extrusion lines, dimension lines, leader lines, and arrowheads.
- Demonstrate the steps used in laying out dimensions for an object.
- Demonstrate proper application of the dimensioning techniques for the following: dimensioning symbols, dimensioning chords, arcs, angles, radii, curved surfaces, offsets, irregular curves, contours, multiple radii, normal objects by offset, spheres, round holes, making simple hole callouts, applying drill size tolerances, dimensioning hole locations for single and multiple holes, and locating holes about a bolt center.
- Demonstrate proficiency at applying the following dimensioning techniques: locating holes on center

(continued)

(CHAPTER OBJECTIVES continued)

lines and concentric arcs, multiple holes along the same center line, repetitive features, callouts for tapered holes, callouts for countersunk holes, callouts for counterbored holes, dimensioning a cylinder and a square, double dimensioning, reference dimensioning, dimensioning slots and rounded ends, not-to-scale dimensions, nominal dimensions, dimensioning external chambers, internal chambers, necks, undercuts, knurls and keyways, staggered dimensions, and dimensioning flat tapers, round tapers, threads, pads, bosses, sheet metal bends, sectional views, pyramids, and cones.

- Demonstrate proficiency at applying the following dimensioning techniques: dimensioning concentric and nonconcentric shafts, rectangular coordinate dimensioning, dimensioning holes on a bolt center diameter, finish marks, X-Y-Z coordinates, tabular dimensioning, tabular drawing, tolerancing, shaft limits, hole limits, allowance, clearance, interference fit, transition fit, size limits, design size, maximum and minimum sizes, location limits, design location, maximum and minimum location, calculating fits, matching parts, and standard fits.
- Demonstrate proficiency in the proper application of notation.
- Explain the concept of group technology as it relates to design and drafting.

One of the most fundamental drafting tasks is to meet the requirements of the engineering definition of the part while providing for the most economical production process and interchangeability considerations. All of this is accomplished by the use of proper dimensions and notation on drawings. *Dimensioning* is the process whereby size and location data for the subject of a technical drawing are provided. *Notation* is the process whereby needed information not covered by dimensions is placed on a technical drawing.

It is critical that drafters, designers, and engineers be proficient in standard dimensioning practices. The most widely accepted dimensioning standard is American Society of Mechanical Engineers document Y14.5M-1994 (ASME Y14.5M-1994R). Similar standards are produced by the International Standards Organization (ISO). However, unless otherwise specified, ASME Y14.5M-1994 is the standard used for guiding dimensioning practices.

Modern dimensioning practices described in ASME Y14.5M-1994 apply in most instances in which interchangeability of parts is a major consideration. The concept dictates that parts produced from a drawing at one manufacturing site should be interchangeable with those produced at another manufacturing site. Automotive parts are an excellent example of production for interchangeability. Some parts are manufactured in America, some in Europe, and some in Japan, but they must all fit together in one car during assembly. Although interchangeability is not a factor with all parts that are produced, the drafter should still use the basic dimensioning principles of ASME Y14.5M-1994. This is particularly important when the parts will be produced using such ever-increasing automated, semi-automated, or integrated processes as numerical control, computer-aided manufacturing (CAM), or computer-integrated manufacturing (CIM).

Dimensioning Systems

Three dimensioning systems are used on technical drawings in the United States: metric dimensioning, decimal-inch dimensioning, and fractional dimensioning. Certain rules of practice with which drafters should be familiar pertain to each of these dimensioning systems.

Metric Dimensioning

The standard metric unit of measurement for use on technical drawings is the millimeter (.001 meter) or .039 inch. ***Figure 10-1*** is a chart of various metric units of measurement of less than a meter that shows where the millimeter fits in.

When using *metric dimensioning*, several general rules should be observed. When a dimension is less than 1 millimeter, a zero must be placed to the left of the decimal point, ***Figure 10-2A***. When a metric dimension is a whole number, neither the zero nor the decimal is required, ***Figure 10-2B***. When a metric dimension consists of a whole number and a decimal portion of another millimeter, it is written as follows: whole number first, decimal point second, and finally, the decimal part of the number. The decimal part of the number is not followed by a zero in metric dimensioning, ***Figure 10-2C***. Individual digits in metric dimensions are not separated by commas or spaces, ***Figure 10-3***. Drawings prepared with metric

UNIT	MULTIPLE OF A METER
METER	1.0
DECIMETER	0.1
CENTIMETER	0.01
MILLIMETER	0.001

FIGURE 10-1 *Metric linear measurements.*



FIGURE 10-2 *Metric dimensioning.*



FIGURE 10-3 *No commas in metric dimensions.*

dimensions are identified with the word "metric" contained in a small rectangle below the part.

Decimal-Inch Dimensioning

Decimal-inch dimensioning is frequently used in the dimensioning of technical drawings. It is a much less cumbersome system for mechanical drawings than is the fractional system, and it is still used more than the metric system. When using the decimal-inch dimensioning system, several rules should be observed. If a dimension is less than one inch, only a decimal point and the numbers of the decimal fraction are required. A zero is not required preceding the decimal point, *Figure 10-4A*. The number of places beyond the decimal point that a decimal-inch dimension is carried is determined by the specified



FIGURE 10-4 *Decimal-inch dimensioning.*

tolerance for the part in question, *Figure 10-4B*. In this figure, a tolerance of .002 (±.001), three places to the right of the decimal, is specified. Consequently, the dimension of 1.637 is carried out three places to the right of the decimal.

There are no specified sizes for decimal points, but they should be made dark enough and large enough to be seen and to reproduce through any normal reproduction process (diazo, photocopy, or microfilm).

Fractional Dimensioning

Fractional dimensioning is not frequently used on mechanical technical drawings. Its primary use is on architectural and structural engineering drawings. However, since it is occasionally still used on mechanical drawings, drafters should be familiar with this system. When you are using fractional dimensions on mechanical drawings, several rules should be observed. The line separating the numerator and denominator of a fraction should be a horizontal line, not an inclined line, *Figure 10-5*. Full-inch dimensions should be a minimum of one-eighth inch in height. The combined height of the numerator, denominator, and horizontal line of a fraction should be one-quarter inch, *Figure 10-6*, for A-, B-, and C-size drawings, and

FIGURE 10-5 *Horizontal line is the correct method.*



FIGURE 10-6 *Proportions for fractions.*

a minimum of five-sixteenths inch for D-, E-, and F-sizes. Also, be sure to leave a visible gap between the numerator, denominator, and horizontal line of the fraction.

Orienting Dimensions

Regardless of whether you are dimensioning in the metric, decimal-inch, or fractional dimensioning system, there are two subsystems for orienting dimensions. These orientation subsystems are known as the aligned system and the unidirectional system. The aligned dimensioning system is illustrated in *Figure 10-7*. In this system the dimensions are aligned with the dimension line so that they can be read either from the bottom of the drawing sheet or from the right-hand side. Notice in Figure 10-7 the area that has been marked off to be avoided if possible. Dimensions written in this area are difficult to read from either the bottom or the right-hand side of the drawing sheet and, therefore, should be avoided. The unidirectional dimensioning system is illustrated in *Figure 10-8*. In this system all dimensions are written so that they can be read from the bottom of the drawing sheet. This means that the guidelines used in entering the dimensions should always be parallel with the bottom of the page.



FIGURE 10-7 *Aligned dimensioning system.*



FIGURE 10-8 *Unidirectional dimensioning system.*

Dimension Components

Several components are common to all dimensioning systems. These include extension lines, dimension lines, arrowheads, leader lines, and the actual numbers or dimensions. Drafters and engineers should be knowledgeable in the proper use of these components.

Extension Lines

An *extension line* is a thin, solid line that extends from the object in question or from some feature of the object. Several rules should be observed when placing extension lines on technical drawings. There should be a small but visible gap (approximately .06″) between the object or object feature and the beginning of an extension line, *Figure 10-9A*. Extension lines should extend uniformly beyond dimension lines for a distance of approximately one-eighth inch, *Figure 10-9B*. Extension lines that originate on the object, such as center lines, may cross visible lines with no gap required, *Figure 10-10*. *Figure 10-11* is a fully dimensioned mechanical drawing that summarizes the basic rules drafters and engineers should remember about the spacing of extension lines, dimension lines, and dimensions. Notice in this figure that when center lines



FIGURE 10-9 *Drawing extension lines.*



FIGURE 10-10 *Center lines as extension lines.*



REQUIRED DIMENSIONS BETWEEN VIEWS	SUGGESTED DISTANCE BETWEEN VIEWS	
1	1.25	30
2	1.62	39
3	2.00	48
4	2.38	57
5	2.75	66
6 MAX.	3.12	75

FIGURE 10-11 *Spacing for extension lines, dimension lines, and dimensions.*

become extension lines there is no gap required as they cross object lines. Notice also that leader lines are not broken when they cross object lines. Note the visible gap (approximately .06″) between the object itself and the beginning of extension lines. Note the .12″ or approximately one-eighth″ overhang of the extension line beyond dimension lines. Suggested spacing of dimension lines and distances between views are summarized in the chart in Figure 10-11.

Dimension Lines

A *dimension line* is a thin, solid line used to indicate graphically the linear distance being dimensioned. Dimension lines are normally broken for placement of the dimension, ***Figure 10-12A***. If a horizontal dimension line is not broken, the dimension is placed above the dimension line with guidelines parallel to it, ***Figure 10-12B***. ***Figure 10-13*** illustrates the proper



FIGURE 10-12 *Placement of dimensions.*



FIGURE 10-13 *Placement of dimensions when space is limited.*

methods to be used for locating dimensions when space is limited on a drawing. *Notice from this illustration that one dimension can be written and then leaders can be used to point to where the dimension applies.* A dimension may be written within the extension lines with dimension lines extending inward rather than outward. Dimension lines may be bent at a 90° angle, and extension lines, when necessary, can be drawn at an oblique angle. Double arrowheads can be used on a dimension line when a long or short break line has been used.

When dimensioning multiple features of an object, dimensions should be aligned uniformly rather than staggered or randomly scattered about the object, ***Figure 10-14***. ***Figure 10-15*** illustrates another rule for the proper placement of dimensions. When dimensioning several views of the same object, always place the dimensions between the views, and always include the overall size, width, height, and depth of the object.

Dimension lines are drawn parallel to the direction of measurement. Sufficient distance between the object and the dimension lines, and between successive dimension lines, is important so that cramped and crowded dimensions do not result. First dimension lines should be at least .38 inch from the object, ***Figure 10-16A***. Successive dimension lines should be at least .25 inch apart. If using metric dimensions, the first dimension lines should be at least 10 mm away from the object. Successive lines should have at least 6 mm between them, ***Figure 10-16B***. ***Figure 10-17*** illustrates the methods to be used when successive dimensions are called for in close areas. Notice how the dimension lines and corresponding dimensions are offset, and notice also the gap left in the extension lines to accommodate crossover of dimension lines.

When the shape of an object requires a series of parallel lines, the breaks and dimensions should be slightly staggered to make it easier to read the dimensions, ***Figure 10-18***. ***Figure 10-19*** illustrates the proper



FIGURE 10-14 *Proper placement of dimensions when dimensioning multiple features.*



FIGURE 10-15 *Dimensioning between views.*



FIGURE 10-16 *Successive dimension lines.*



FIGURE 10-17 *Successive dimension lines in close areas.*



FIGURE 10-18 *Staggering dimensions.*



RULES:
ALWAYS PLACE SHORTEST DIMENSIONS CLOSEST TO THE OBJECT
ALWAYS KEEP DIMENSIONS OUTSIDE AND AWAY FROM THE OBJECT

FIGURE 10-19 *Stacking dimension lines.*



FIGURE 10-21 *Angle of a leader line.*



FIGURE 10-22 *Lettering and leaders.*

way of stacking a successive group of dimension lines. Drafters and engineers should always place the shortest dimensions closest to the objects, and always keep dimensions outside and away from the object, as illustrated in Figure 10-19.

Leader Lines

A *leader line* is a thin line that begins horizontally, breaks at an angle, and terminates in an arrowhead, or, on occasion, a dot, ***Figure 10-20.*** Leaders that terminate at an edge or at some other specific point on a drawing should have an arrowhead. Leaders that terminate inside an object on a flat surface should end in a dot. The preferred angle of a leader line is from a minimum of 30° to a maximum of 60°, ***Figure 10-21.*** The horizontal portion of a leader should be from .125 inch to .25 inch in length, Figure 10-21. To avoid confusion, leader lines should not be drawn parallel to extension lines or dimension lines. When placing a dimension and/or note at the end of a leader line, it is easier to letter from the leader than into the leader, ***Figure 10-22.***

When using a leader line to direct a dimension to its appropriate feature on a drawing, one dimension for each leader is the preferred method, ***Figure 10-23.*** More than one leader line extending from the same dimension can create a confusing situation that is difficult to interpret. Leader lines pointing to the center of a circle should be directed toward but not extended into the circle center, ***Figure 10-24. Figure 10-25*** illustrates the proper use of leader lines in a variety of dimensioning situations.



FIGURE 10-20 *Leader lines.*



FIGURE 10-23 *One dimension per leader line is preferred.*



FIGURE 10-24 *Leader lines point at the center of a circle.*



FIGURE 10-25 *Proper use of leader lines.*

Arrowheads

An *arrowhead* is the most commonly used termination symbol for dimension and leader lines. Arrowheads should be approximately three times as long as they are wide. They should be large enough to be seen but small enough that they do not detract from the appearance of the drawing. A commonly accepted length for arrowheads is .12 inch. Arrowheads may be slightly larger or smaller than this, but, regardless of their size, they should be uniform throughout a drawing, ***Figure 10-26.*** Although the same standard applies to drawings prepared on a CAD system, arrowheads do not have to be filled in on drawings prepared using automated processes. Some CAD systems fill in arrowheads and some do not. Both open and filled-in



FIGURE 10-26 *Proper size and shape of arrowheads.*



FIGURE 10-27 *Drawing arrowheads.*

arrowheads have been considered acceptable since the advent of CAD.

Figure 10-27 illustrates the three steps used in drawing arrowheads.

Laying Out Dimensions

Figure 10-28 illustrates the four steps in laying out dimensions for an object. First, place light layout lines on the drawing sheet. Second, draw in light guidelines for the dimensions. Third, darken your extension lines, dimension lines, and dimensions. Fourth, add arrowheads.

Steps in Dimensioning

There are two basic steps in dimensioning objects, regardless of the type of object.



FIGURE 10-28 *Laying out dimensions.*



FIGURE 10-29 *Size and location dimensions.*

STEP 1 Apply the size dimensions. These are dimensions that indicate the overall size of the object and the various features that make up the object.

STEP 2 Apply the locational dimensions. Locational dimensions are dimensions that locate various features of an object from some specified datum or surface. *Figure 10-29* gives examples of size and location dimensions.

In order to properly dimension an object, drafters and engineers must be able to mentally break the object down into component parts and sub-elements. *Figure 10-30* illustrates graphically how this is done. On the left side of the figure is a two-dimensional representation of the object containing a top and front view. On the right side of the figure is a three-dimensional geometric breakdown of the object. This three-dimensional breakdown shows the drafter and engineer what geometric shapes must be sized using dimensions and which must be located using dimensions.



FIGURE 10-30 *Geometric breakdown of an object.*

Specific Dimensioning Techniques

All of the information on dimensioning so far has been of a general nature. The following sections deal with techniques used for applying dimensions to specific situations that are recurrent in drafting. With a thorough knowledge of the general information presented earlier, and the specific information presented in these sections, drafters and engineers will be able to dimension any situation confronted on technical drawings.

Dimensioning Symbols

There are a number of symbols used in different dimensioning situations with which drafters and engineers should be familiar. These symbols are summarized in *Figure 10-31*. Review these symbols carefully and commit them and their uses to memory before proceeding.

Dimensioning Chords, Arcs, and Angles

Chords, arcs, and angles are dimensioned in a similar manner. When dimensioning a chord, the dimension line should be perpendicular and the extension lines parallel to the chord. When dimensioning an arc, the dimension line runs concurrent with the arc curve, but the extension lines are either vertical or horizontal. An arc symbol is placed above the dimension. When dimensioning an angle, the extension lines extend from the sides forming the angle, and the dimension line forms an arc. These methods are illustrated in

CR	CONTROLLED RADIUS
R	RADIUS
Ø	DIAMETER
2X	NUMBER OF TIMES–PLACES
↧	DEEP OR DEPTH
∨	COUNTERSINK
⌴	COUNTERBORE OR SPOTFACE
□	SQUARE
( )	REFERENCE DIMENSION
.25	NOT TO SCALE DIMENSION
◺	SLOPE
▷	CONICAL TAPER
⌒	ARC LENGTH
SR	SPHERICAL RADIUS
SØ	SPHERICAL DIAMETER
[X]	BASIC DIMENSION
⟨ST⟩	STATISTICAL TOLERANCE

FIGURE 10-31 *Dimensioning symbols.*



FIGURE 10-32 *Dimensioning chords, arcs, and angles.*



FIGURE 10-33 *Dimensioning angles.*



FIGURE 10-34 *Dimensioning angles.*

Figure 10-32. *Figures 10-33* and *10-34* contain additional information relative to dimensioning angles.

Figure 10-33 shows that angles are normally written in degrees, minutes, and seconds. The symbols used to depict degrees, minutes, and seconds are also shown in this figure. Angular measurements may also be stated in decimal form. This is particularly advantageous when they must be entered into an electronic digital calculator. The key to converting angular measurements to decimal form is in knowing that each degree contains 60 minutes, and each minute contains 60 seconds. Therefore, converting a measurement stated in degrees, minutes, and seconds into decimal form is a two-step process. Consider the example of the angular measurement 2 degrees, 15 minutes, and 30 seconds. This measurement would be converted to decimal form as follows:

STEP 1 The seconds are converted to decimal form by dividing by 60. Thirty seconds divided by 60 equals .50. The 15 minutes are added to this so that the minutes are expressed in decimal form or 15.50.

STEP 2 The minutes stated in decimal form are converted to decimal degrees by dividing by 60. The number 15.50 divided by 60 equals .25833. The 2 degrees are added to this number to have the measurement stated in decimal form or 2.2583 degrees.

Figure 10-34 illustrates how angles can be dimensioned for size and location. The size dimension gives the overall size of the angular cut. However, it does not locate the angular cut in the object. This is done by using a locational dimension off of the center line of the object. *Figure 10-35* shows how normal linear dimensions can be used for effecting the proper angle. When this method is used in the example on the left, all surfaces are dimensioned except the angular surface. When this method is used the angular surface is defined by default. In the method on the right, three linear dimensions and one angular dimension define the angular surface.

Dimensioning a Radius

Dimension lines used to specify a radius have one arrowhead, normally at the arc end. An arrowhead should not be used at the center of the arc. Where space permits, the arrowhead should be placed between the arc and the arc center with the arrowhead touching the arc. If space permits, the dimension is



FIGURE 10-35 *Using normal linear dimensions for effecting the proper angle.*



FIGURE 10-36 *Dimensioning a radius.*

placed between the arc center and the arrowhead. If space is not available, the dimension may be placed outside the arc by extending the dimension line into a leader. The arc center of a radius is denoted with a small cross. *Figure 10-36* illustrates the preferred method for dimensioning a radius.

Dimensioning a Foreshortening Radius

On occasion the center of an arc radius will fall outside the drawing or will be so far removed from the drawing as to interfere with other views. When this is the case, the radius dimension line should be foreshortened and the radius center located using coordinate dimensions. This is done by relocating the arc center and placing a zig-zag in the radius dimension line, as shown in *Figure 10-37*. When this method is used it is important that the arc center actually lay upon the real center line of the arc.

Dimensioning Curved Surfaces

Curved surfaces containing two or more arcs are dimensioned by showing the radii of all arcs and locating the arc centers using coordinate dimensions. Other radii may be located using their points of tangency. This method is illustrated in *Figure 10-38*.

Dimensioning Offsets

Offsets are dimensioned from the points of intersection of the tangents along one side of the object, *Figure 10-39*. The distance from one end of the offset to



FIGURE 10-37 *Dimensioning a foreshortening radius.*



FIGURE 10-38 *Dimensioning curved surfaces.*



FIGURE 10-39 *Dimensioning offsets.*

the intersection is specified with a coordinate dimension. The distance from the other end to the offset is also specified with a coordinate dimension, as shown in Figure 10-39.

Dimensioning Irregular Curves

You have already seen in Figure 10-38 how to dimension curved surfaces using arc centers, radius dimensions, and tangent points. Irregular curves may also be dimensioned using coordinate dimensions from a specified datum. When this is the case, the coordinate dimensions extend from a common base line to specified points along the curve, *Figure 10-40.*

Dimensioning Contours not Defined as Arcs

Contours not defined as arcs can be dimensioned by indicating X–Y coordinates at points along the surface of the contour. Each of these points, sometimes referred to as stations, is numbered. The X and Y coordinates for each station are tabulated and placed in table form under the drawing, *Figure 10-41.*

Dimensioning Multiple Radii

When dimensioning an object that requires several radii, arcs should be dimensioned showing the radius in a view that gives the true shape of the curve. The dimension lines for a radius should be drawn as a radial line at an angle, rather than horizontally or vertically. Only one arrowhead is used. The R precedes the dimensional value when dimensioning in decimal-inch or the metric system. This method is illustrated in *Figures 10-42, 10-43,* and *10-44.* Notice in Figure 10-44 that where a radius is dimensioned in a view that does not show the true radius, a note should be used to indicate what the true radius is.



FIGURE 10-40 *Dimensioning irregular curves.*



STATION	1	2	3	4	5
X	1.12	2.12	3.00	3.62	4.00
Y	1.75	1.50	1.12	.75	.31

FIGURE 10-41 *Dimensioning contours not defined as arcs.*



FIGURE 10-42 *Dimensioning multiple radii.*



FIGURE 10-43 *Dimensioning multiple radii.*

FIGURE 10-44 *Dimensioning multiple radii.*



FIGURE 10-45 *Dimensioning by offset (round object).*

Dimensioning by Offset (Round Objects)

Another way to dimension a round object is the offset method. In this method, dimension lines are used as extension lines. Dimension lines are distributed across the object perpendicular to the center line of the object and spaced using coordinate dimensions, *Figure 10-45.*

Dimensioning by Offset (Flat Objects)

Flat objects may also be dimensioned using the offset method. Again, dimension lines on the object become extension lines. Dimension lines are spaced across the object perpendicular to the center line of the datum and extended to become extension lines for the coordinate dimensions that space them, *Figure 10-46.*

Dimensioning Spheres

Figure 10-47 illustrates the proper method for dimensioning spheres. When the diameter method is used, a leader points to the center of the sphere, and the diameter note is preceded with a capital S to indicate that it is a spherical diameter. When the radius method is used, a dimension extends from the arc center to the arc and is extended on with a leader, and the note is preceded by a capital SR to indicate a spherical radius.

Dimensioning Round Holes

Round holes are dimensioned in the view in which they appear as circles, *Figure 10-48.* Holes may be dimensioned using a leader that points toward the center of the hole in which the note gives the diameter, or extension lines may be drawn from the circle with a dimension that also indicates the diameter. Larger circles are dimensioned with a dimension line drawn across the circle through its center at an angle with the diameter dimension shown. Except for very large holes, the arrowhead and the dimensional value are placed outside the hole. It is important when dimensioning holes to call off the diameter, not the radius.



FIGURE 10-46 *Dimensioning by offset (flat object).*



FIGURE 10-47 *Dimensioning spheres.*



FIGURE 10-48 *Dimensioning round holes.*



FIGURE 10-49 *Simple hole callouts.*

Simple Hole Callouts

Drafters and engineers need to know how to apply simple callouts to both through-holes and blind-holes. A through-hole is one that passes all the way through the object. A blind-hole is one that cuts into but does not pass through the object. Both types of holes, and the callout used for each, are illustrated in *Figure 10-49*. Machine holes are generally drilled to make the rough hole and then reamed to refine the hole. Figure 10-49 shows the difference between a drill and a ream. No hole is only reamed. A hole must be drilled before it can be reamed.

A through-hole callout has a leader line extending toward the center of the hole in the view in which the hole appears as a circle. The note attached to the leader gives the diameter of the hole and the word "thru" to indicate that the hole passes through an object. Blind-hole callouts are similar to through-hole callouts, except that the depth symbol is followed by the actual depth of the hole.

Drill Size Tolerancing

Holes are not drilled to the exact size specified on a drawing. This is because there are several factors that mitigate against a perfectly sized hole. The accuracy of the drill, the tolerance level of the machine, and the qualifications of the machinist all have an impact on the actual size of a hole once it's drilled. It is accepted in manufacturing that no hole, even with the added accuracy provided by computer-aided manufacturing, is going to be drilled exactly the size specified. Therefore, drafters and engineers need to know how much variation to expect in a hole so that they can decide what limits to give the hole and whether the actual drilled hole will give the fit required in a given situation.

Drill size tolerance charts have been developed to assist drafters and engineers in determining the expected upper and lower limits of a drilled hole. Such charts are contained in Appendix A as Table 16. Turn to this table and you will notice that the standard drill size is given a number/letter, a fractional designation, a decimal designation, and a metric designation. To the right-hand side of the table the tolerance for each drill size is given in decimals. The left-hand column is the plus tolerance, and the right-hand column is the minus. To use this table, apply the following steps:

1. Find the letter or number of the drill in question on the left-hand side of the table.
2. Find the corresponding size for the drill in decimal form.
3. Find the plus tolerance for that size drill and add it to the decimal drill size. This will give you the upper limit for the hole size.
4. Find the minus tolerance for that drill size and subtract it from the decimal drill size. This will give you the lower limit for the hole.
5. Write the upper and lower limits with the smaller number on top separated from the larger number by a horizontal line. For example, an H-size drill has a decimal diameter of 0.2660. To find the upper limits for a hole using this drill size, add the plus tolerance of 0.0064 to this decimal drill size to get 0.2724 as the upper limit for the hole. To find the lower limit, subtract the minus tolerance of .002 from the decimal drill size to get a lower limit of 0.2640.

Dimensioning Hole Locations

In addition to dimensioning the size of a hole, drafters and engineers must also dimension the locations of holes. *Figure 10-50* illustrates the proper methods for dimensioning the location of a hole. The preferred method is to dimension the location of the hole in the view where the hole appears as a circle. It is common practice to dimension from a reference side of the object to the center line of the hole. One should never dimension to a hidden line, however. If it is necessary to show one of the locational dimensions in a hidden view, convert the view into a sectional view.

Dimensioning Hole Locations (More than One Hole)

Figure 10-51 illustrates the proper method of dimensioning the locations of more than one hole within an object. When there is more than one hole in an object,



FIGURE 10-50 *Dimensioning hole locations.*



FIGURE 10-51 *Dimensioning hole locations (more than one hole).*

what is important is the relationship of the holes to each other. Because of this, the dimensions applied show the distance horizontally and vertically between the center lines of the holes.

Locating Holes About a Bolt Center

A common dimensioning situation is to have holes spaced about a bolt center. When this is the case the holes may be dimensioned using coordinate dimensions or angular dimensions, *Figure 10-52*. For the greatest accuracy, coordinate dimensions can be given from the center line of the bolt's center as well



FIGURE 10-52 *Locating holes about a bolt center.*

as center-to-center dimensions of the holes. This method is illustrated in the top half of Figure 10-52. Notice that the diameter of the bolt center is specified as a reference dimension. Reference dimensions are given only for informational purposes. They are not intended to be measured or to be used in dictating manufacturing operations. Another method that can be used for locating holes about a bolt center is illustrated in the bottom half of Figure 10-52.

With this method the diameter of the bolt circle is shown and a note specifying the number of holes, their diameters, and the indication "equally spaced" is given. If the holes are unequally spaced, the same method can be used except that the note "equally spaced" is dropped and an angular measurement with reference to one of the center lines is indicated.

Locating Holes on Center Lines and Concentric Arcs

When locating holes on common center lines, the center lines become base lines from which coordinate measurements can be made, as illustrated in the top half of *Figure 10-53*. All three holes in the object in this figure share the same horizontal center line. Consequently, the only dimensions required are dimensions from center to center of the circles. This is accomplished by providing a coordinate dimension from the center of a large circle to the center of one of the smaller circles, and the overall coordinate dimension between the centers of the two small circles, as illustrated. When centers are located on concentric



FIGURE 10-53 *Locating holes on center lines and concentric arcs.*



FIGURE 10-54 *Dimensioning multiple holes.*

arcs, the polar system of dimensioning can be used, as illustrated in the bottom half of Figure 10-53. When this is the case, the radial distances from the point of concurrency and the angular measurements between the holes are used to locate the centers of the holes. The distance from the point of concurrency to the center of each hole is indicated by the radius, as shown.

Dimensioning Multiple Holes Along the Same Center Line

Figure 10-54 shows the proper method used for dimensioning multiple holes along the same center line. The method shown at the top of Figure 10-54 is known as "chain dimensioning." The center line of the first hole is dimensioned from a reference base line, which is normally one side of the object. Then each successive center line is dimensioned from the immediate preceding center line. A problem with this type of dimensioning is that if one of the features in the chain is improperly located, all successive features will be improperly located. As a result, another method of dimensioning multiple holes or features is often used in place of chain dimensioning. This dimensioning concept is known as "datum," or "base line" dimensioning. As is shown in Figure 10-54B, each successive center line is dimensioned from a base line or datum. In this way any one of the multiple features can be improperly located by the machinist without affecting the others. When this happens, the error can sometimes be corrected.

Another method that can be used for dimensioning multiple features within an object is illustrated at the bottom of Figure 10-54. With this method the center line of the first feature is dimensioned from a given datum, usually the edge of the object. Remaining features are dimensioned using a note that indicates the number of spaces at a given distance. This method does not have the disadvantage of needing an accurate placement of the first feature in order for each successive feature to be accurately located.

Dimensioning Repetitive Features

Figure 10-55 illustrates the proper methods for dimensioning an object that contains repetitive features. Repetitive features may be located on a drawing using a note that specifies the number of times a given dimension is repeated, and giving one particular dimension and the total length as a reference. When dealing with repetitive features it is necessary to use both size and locational dimensions. Note the dimensions that have been given in Figure 10-55. Some are size dimensions and some are location dimensions.

Callouts for Tapered Holes

Occasionally the design of a manufactured part will require a tapered hole. *Figure 10-56* illustrates the proper method for annotating a tapered hole and



FIGURE 10-55 *Dimensioning repetitive features.*



FIGURE 10-56 *Callouts for tapered holes.*

shows an example of a 4° tapered bit. Callouts for tapered holes are similar to those for regular holes except that the note must also contain the taper symbol and the degree and the length of taper. The callout for the tapered hole in Figure 10-56 means that the subject hole has a .50 diameter at the top. It is drilled through and tapered at 4° for the full length of the hole.

Callouts for Countersunk Holes

Countersinking is a machining process to form a conical head so that a fastener can fit flush with the top of a part. The callout for a countersunk hole should contain the diameter of the countersink hole, which is the maximum diameter on the surface, and the angle of the countersink. The proper method for calling out a countersunk hole is illustrated in ***Figure 10-57***. First a .50 diameter hole is drilled through the part. Then, using a countersink bit, the top of the hole is countersunk at 82° until the head of the countersink has a diameter of 1.12.

Callouts for Counterbored Holes

On occasion a hole in a part is counterbored to allow the head of a bolt or another type fastener to be recessed. The bottom of a counterbore is flat rather than angled as in a countersink. The callout for a counterbored hole shows the diameter of the drilled hole, the counterbore symbol, the diameter of the counterbore itself, and the depth of the counterbore. When a hole is to be counterbored, the hole itself is drilled first and then the counterbore is applied using a special counterbore bit, as shown in ***Figure 10-58***.

Callouts for Spotfaces

A spotface is a machining process used to finish the surface around the top of a hole so that a bolt or



FIGURE 10-57 *Callouts for countersunk holes.*



FIGURE 10-58 *Callouts for counterbored holes.*



FIGURE 10-59 *Callouts for spotfaces.*

other type of threaded fastener can feed properly. A spotface resembles a very shallow counterbore. The callout for a spotface contains the diameter of the actual hole, and the diameter of the spotface. The counterbore symbol is also used for a spotface. The depth of a spotface is not normally shown. When a hole is to be spotfaced, the hole itself is drilled first and then the spotface is applied with a special spotface bit, as illustrated in *Figure 10-59*.

Dimensioning a Cylinder

Figure 10-60 shows the proper way to dimension a cylinder. Notice from this figure that two methods can be used. In the first method the longitudinal view and the end view of the cylinder are given. When this method is used, the length of the cylinder is shown and the diameter dimension is applied between the longitudinal view and the end view. In the second method, the end view is left off. Consequently, the diameter dimension is applied to the longitudinal view. When dimensioning a cylinder, always specify the diameter rather than the radius.



FIGURE 10-60 *Dimensioning a cylinder.*



FIGURE 10-61 *Dimensioning a square.*

Dimensioning a Square

Figure 10-61 illustrates the proper method for dimensioning an object that is square in cross section. No center line on the object indicates that the object is square rather than round in cross section. This type of object requires a length dimension on the longitudinal view and a height dimension placed between the longitudinal view and the end view, and preceded by the square symbol.

Double Dimensioning

Figure 10-62 illustrates the concept of double dimensioning. This is sometimes referred to as "superfluous" dimensioning. Drafters and engineers should avoid double dimensioning. It is redundant and can lead to confusion.

Reference Dimensioning

Figure 10-63 illustrates the concept of reference dimensioning. In the object shown, the .62 dimension in parentheses is a reference dimension. Reference dimensions are not required. They are occasionally given for information purposes only. The old method used the letters REF following the dimension to indicate a reference dimension. The newer and accepted method is to place reference dimensions in parentheses. *Figures 10-64* and *10-65* further illustrate the concept of reference dimensions.



FIGURE 10-62 *Double dimensioning.*



FIGURE 10-63 *Reference dimensioning.*



FIGURE 10-64 *Reference dimensions.*



FIGURE 10-65 *Reference dimensions.*

In Figure 10-64, the second .25 dimension in the front view of the object is a double dimension; it is superfluous. In Figure 10-65, the problem has been solved by placing the second dimension in parentheses, thereby making it a reference dimension. The drafter or engineer had two options in this case for solving the problem: omit the dimension altogether or make it a reference dimension.

Dimensioning Internal Slots

Internal slots represent a common manufacturing situation. Drafters and engineers approach internal slots as two partial holes separated by a space. There is a variety of methods for dimensioning internal



FIGURE 10-66 *Dimensioning internal slots.*

slots. The preferred methods are illustrated in *Figure 10-66*. Notice from these examples that when the width of the slot is dimensioned, there is no need to indicate the size of the radius. To do so would be double dimensioning. All of the methods shown in Figure 10-66 are acceptable methods and can be substituted for each other based on the needs of the individual drawing and local preferences.

Figures 10-67 and *10-68* are examples of how to dimension internal slots for two other manufacturing situations. Note in Figure 10-67 that the distance from the concurrent center point to the center line of the



FIGURE 10-67 *Dimensioning internal slots.*



FIGURE 10-68 *Dimensioning internal slots.*

slot is indicated with a radius dimension. In addition, the angle formed by the extension of the two-hole center lines to their intersection at the converging point must also be dimensioned as an angle. Figure 10-68 illustrates the proper method for dimensioning an internal slot when one of the holes is larger than the other. If a width dimension is provided, a radius value is not provided. If a width dimension is not provided, the radius dimension must be.

Dimensioning Rounded Ends

Figure 10-69 illustrates the proper method for dimensioning the three most common situations involving external rounded ends. Parts with fully rounded ends



FIGURE 10-69 *Dimensioning external rounded ends.*

should be dimensioned with an overall dimension and the radius should be indicated but not dimensioned, as indicated at the top of Figure 10-69. Figures with partially rounded ends, such as the example in the middle of Figure 10-69, require a radius specification. For parts with rounded ends and holes, overall dimensions can be given as reference dimensions, as shown in the bottom example of Figure 10-69.

Dimensioning and Hidden Lines

There is only one rule for dimensioning and hidden lines:

Do not Dimension to Hidden Lines

Figure 10-70 illustrates what drafters and engineers can do when faced with a situation where it is necessary to dimension hidden lines. When this is the case, and it cannot be avoided in any other way, convert the hidden-line view to a sectional view so that you are dimensioning to a solid line.

Not to Scale (NTS) Dimensions

On occasion it is necessary to enter a dimension not to scale. When this is the case, the not-to-scale dimension should be underlined with a solid straight line, as illustrated in *Figure 10-71*. The old method used a wavy line under the dimension. This is no longer an acceptable practice.

Nominal Dimensions

A *nominal dimension* is one that represents a general classification size given to a part or product. It may not, and usually does not, express the actual size of the object dimensioned. There is usually a small amount of difference between the actual size of a part and the nominal size, as illustrated in *Figure 10-72*.



FIGURE 10-70 *Do not dimension to hidden lines.*



FIGURE 10-71 *Not to scale (NTS) dimensions.*



FIGURE 10-72 *Nominal dimensions.*

Dimensioning External Chamfers

A *chamfer* is a beveled edge normally applied to cylindrical parts and a variety of different types of fasteners. Chamfers are used to eliminate rough edges that might break off or impede the assembly of parts. *Figure 10-73* illustrates three accepted procedures for dimensioning external chamfers. The illustration at the top shows how to dimension a chamfer using a leader and note. This is frequently done when the chamfer is a 45° chamfer. The middle illustration shows how to dimension larger chamfers at angles other than 45°. Notice that the length of the chamfer



FIGURE 10-73 *Dimensioning external chamfers.*

is dimensioned, as is the angle of the chamfer. The bottom illustration shows how to dimension a 45° chamfer that is very small. The dimension is called out and followed by the term "MAX." This tells the machinist that a 45° chamfer is to be applied but its length is to be no more than .010.

Dimensioning Internal Chamfers

Figure 10-74 illustrates two accepted methods for dimensioning internal chamfers. The example on the left illustrates how to call out a 45° chamfer. The example on the right illustrates how to call out a chamfer other than 45°. Notice that when the chamfer is other than 45° the dimension of the top of the hole after the chamfer has been applied must be given, as must the angle of the chamfer.

Staggered Dimensions

Figure 10-75 illustrates the proper method for applying staggered dimensions. A succession of parallel dimensions can become confusing and difficult to read. As a result, the accepted practice is to stagger the series of parallel dimensions as shown in the bottom half of Figure 10-75. Staggered dimensions are usually easier to read than aligned parallel dimensions.

Dimensioning Necks and Undercuts

Necks and undercuts are recessed cuts into cylindrical parts. They are generally used where cylinders or other geometric shapes come together. *Figure 10-76* illustrates the proper method for dimensioning necks and undercuts. Notice from the three examples on the left side of Figure 10-76 that necks and undercuts may be dimensioned using a leader and accompanying note. The three examples on the right side of Figure 10-76 show that necks and undercuts may also be dimensioned using a combination of notes, angular dimensions, and size dimensions.



FIGURE 10-74 *Dimensioning external chamfers.*



FIGURE 10-75 *Staggered dimensions.*



FIGURE 10-76 *Dimensioning necks and undercuts.*

Head Fits for Undercuts and Chamfers

Figure 10-77 illustrates the proper method for showing head fits for parts with undercuts and shoulders. With an undercut, the head fits flush with the surface. With a shoulder, the head will only fit flush with the surface if the surface has been chamfered.

Dimensioning Knurls

Knurls are diamond-shaped or parallel patterns cut into cylindrical surfaces to improve gripping, to improve the bonding between parts for permanent press



FIGURE 10-77 *Head fits for undercuts and chamfers.*



FIGURE 10-78 *Dimensioning knurls.*

fits, and, sometimes, for decoration. The accepted method for dimensioning both parallel and diamond-shaped knurls is illustrated in ***Figure 10-78***. Notice in this figure that when knurls are fully dimensioned on a drawing, there is no need to actually show them. The callouts for a knurl should include the type, pitch, and diameter. The initials DP in the knurl callouts stand for diametrical pitch. The most commonly used diametrical pitches for knurling are 64 DP, 96 DP, 128 DP, and 160 DP. In addition to the knurling callout, the length of the knurl and the diameter of the cylinder that will receive the knurls must be shown.

Dimensioning Keyways

Figure 10-79 illustrates the preferred methods for dimensioning both exterior and interior keyways. Notice that both size and location dimensions are required to completely dimension a keyway. The size dimension gives the overall width of the keyway, and the location dimension locates the keyway on the object in question from a specified datum such as the center line of the object. With an exterior keyway, the depth is shown using a dimension that runs from the bottom of the keyway to the bottom of the part in question and parallel to the center line or axis of the shaft. With an interior keyway, the depth of the keyway is specified using a dimension that runs from the top of the keyway to the bottom of the hole and parallel to the center line of the hole. ***Figure 10-80*** illustrates the preferred method for dimensioning a woodruff keyway. A woodruff keyway requires both size and location dimensions. The size dimensions specify the width and depth of the keyway. The location dimension from a specified datum such as a center line locates the keyway in the part as shown in Figure 10-80. In addition, the location of the center of the keyway from one end of the shaft must also be shown. The diameter of the shaft and the woodruff cutter must also be dimensioned, as shown in Figure 10-80.



FIGURE 10-79 *Dimensioning keyways.*



FIGURE 10-80 *Dimensioning a woodruff keyway.*



FIGURE 10-81 *Dimensioning flat tapers.*

Dimensioning Flat Tapers

Figure 10-81 illustrates the preferred method for dimensioning flat tapers. The method on the left uses 2-size dimensions and a leader with a taper symbol attached. In addition, the taper ratio must be shown. The 5:1 taper ratio called out for the part on the left means that the part tapers one unit in the vertical direction for every five units traveled in the horizontal. The example on the right illustrates another acceptable method for dimensioning flat tapers. In this method, 3-size dimensions provide all of the information needed to manufacture the part with the proper taper.

Dimensioning Round Tapers

Figure 10-82 illustrates two acceptable methods for dimensioning round tapers. Round tapers can be dimensioned by providing the following dimensional data: (a) the diameter or width at both ends of the taper; (b) the length of the tapered feature; and (c) the rate of taper. The example on the right shows the diameter at both ends of the taper. The example on the left shows the length of the tapered feature and is in the taper ratio of 10:1, meaning that the part is tapered 1 unit for every 10 units parallel to the horizontal center line of the shaft.



FIGURE 10-82 *Dimensioning round tapers.*



FIGURE 10-83 *Dimensioning threads.*

Dimensioning Threads

Figure 10-83 shows the preferred methods for dimensioning threaded fasteners. Notice that it is not necessary to attempt to draw an actual representation of the thread. Rather, the schematic approach shown in the middle and bottom examples is preferred. The threads themselves are called out in a thread note attached to a leader. In addition, the nominal diameter of the shaft being threaded and the longitudinal distance of the threading must also be dimensioned, as shown in Figure 10-83. A chamfer callout should be shown with the leader line to indicate how the end of the threaded fastener is to be chamfered.

Dimensioning a Pad and a Boss

Figure 10-84 illustrates the preferred method for dimensioning a pad and a boss. A boss is a round projection from a part. A pad is a projection of any shape other than round. Notice from Figure 10-84 that the



FIGURE 10-84 *Dimensioning a pad and a boss.*



FIGURE 10-85 *Dimensioning sheet metal bends.*

boss requires a diameter dimension, a dimension showing how far the boss projects out from the part, and a radius indicator. The pad requires 2-size dimensions: one for length and one for width. It also requires a projection dimension and a radius indicator.

Dimensioning Sheet Metal Bends

Figure 10-85 illustrates the different methods for dimensioning sheet metal bends. When dimensioning a sheet metal object, allowances must be made for the bends. The intersection of the surfaces adjacent to a bend is called the "mold line." This is the line that is used for dimensioning purposes. Notice in Figure 10-85 that each bend has an inside mold line and an outside mold line. Dimensions begin at the intersection of the outside mold line, as shown.

Dimensioning Sectional Views

Figure 10-86 illustrates the rule for dimensioning sectional views. The dimension should, whenever possible, be placed outside the object. Placing dimensions inside an object causes them to conflict with the section lines. When there is no other way to apply a dimension than to place it inside a sectioned area, remove enough of the section lining to permit the dimension to be



FIGURE 10-86 *Dimensioning sectional views.*



FIGURE 10-87 *Dimensioning a pyramid.*

easily read and the dimension lines to be easily seen, as shown in the right-hand example in Figure 10-86.

Dimensioning Pyramids

Figure 10-87 illustrates the acceptable method for dimensioning a pyramid. A pyramid is dimensioned by showing the height in the front view and the dimensions of the base and the center of the vertex in the top view. If the pyramid base is square, it is only necessary to show the base dimension on one side of the base in the top view and to indicate that the base is square by using the appropriate symbol.

Dimensioning a Cone

Figure 10-88 illustrates the preferred methods for dimensioning a cone. A cone is dimensioned by showing its altitude in the view where the cone appears as a triangle and showing the diameter of the base between the top view and front view. The frustum of a cone is dimensioned by giving the diameter between the top and front view, and both heights in the front view where the cone would appear as a triangle. The example on the right-hand side of Figure 10-88 illustrates how to dimension a cone that is cut off at an angle. The diameter of the cone's base is shown between the



FIGURE 10-88 *Dimensioning a cone.*

top and front views. The height of the cone before it is cut and the height of the cone at the center line of the cone after the cut are shown in the front view where the cone would appear as a triangle. The angle of the cut also is dimensioned in this view.

Dimensioning Concentric and Nonconcentric Shafts

Figure 10-89 illustrates the various methods that can be used for dimensioning concentric and nonconcentric shafts and cylinders. The example at the top uses the chain dimensioning concept. The example in the center uses the datum or baseline dimensioning concept. The example at the bottom uses the datum dimensioning concept combined with a reference dimension.

Rectangular Coordinate Dimensioning

Figure 10-90 illustrates the proper methods for applying rectangular coordinate dimensioning. Rectangular coordinate dimensioning is a system that locates features of the drawing relative to each other, individually or as a group, from a datum or series of datums. Round holes and other similar features are located by dimensioning distances to their center points. Linear dimensions in the rectangular coordinate dimension system specify distances from two or three mutually perpendicular planes which are used as datums. Coordinate dimensions should clearly indicate what features of the part being dimensioned establish these datums.

Dimensioning Holes on a Bolt Center Diameter

Figure 10-91 illustrates the proper methods used in dimensioning holes on a bolt center diameter. In the example on the left, the diameter of the bolt's circle is



FIGURE 10-89 *Dimensioning concentric and nonconcentric shafts.*



FIGURE 10-90 *Rectangular coordinate dimensioning.*

given and one angle is shown to indicate the number of degrees between the center lines of the six circles. This is sufficient information for the machinist to properly drill the holes. In the example on the right, a note is used to accomplish the same thing. Notice that the note specifies the number and size of the holes. It explains that the holes are drilled through the object and equally spaced on a bolt center. Either of these



FIGURE 10-91 *Dimensioning holes on a bolt center diameter.*



FIGURE 10-92 *Dimensioning holes around a center.*

methods may be used for dimensioning holes around a center. *Figure 10-92* shows two other methods that are used for dimensioning holes around a center. These methods are used when the holes around the bolt center are not equally spaced. The example on the left gives a dimension for the bolt center, a note containing the number of holes and their size, and angles turned from a reference center line for locating the center lines of the other three holes. The example on the right substitutes linear dimensions for angular dimensions.

Finish Marks

Figure 10-93 illustrates three different systems for applying finish marks to drawings. The traditional system and the general system have been replaced by the new system. However, engineers should be familiar with all three systems so that they are prepared to interpret finish marks applied to drawings produced in years past. Note the sizes specified when applying finish marks. A finish mark in the new system, which



FIGURE 10-93 *Finish marks.*

is the type of finish mark that should be used on all drawings now, resembles a mechanically produced check mark that forms a 60° "v." Finish marks are used for specifying the type of surface finish to be applied to any machined surface. Finish marks should always appear where the surface in question appears as an edge view. Finish marks are not used when dimensioning notes are given for such machining processes as drilling and boring, as they would be redundant. Finish marks are also omitted when the part in question is made of machined stock. When all surfaces on a part are finished, a note stating "Finish all over" or the letters FAO may be substituted.

Surface imperfections of a part are usually so small that they may be barely visible to the human eye. Consequently, they are measured in micro-inches. *Figure 10-94* illustrates the concept of the micro-inch.

Figure 10-95 illustrates the proper method for applying micro-inch callouts to finish marks. Notice that micro-inch callouts are not used with the traditional finish mark system.



FIGURE 10-94 *Micro-inches.*



FIGURE 10-95 *Micro-inch callouts.*

Figure 10-96 illustrates the rule for applying finish marks to drawings. Note that finish marks are to be repeated in every view where the surface in question appears as an edge. Table 46 in Appendix A shows the surface roughness textures obtainable by common production methods. Engineers should be familiar with the information in this table. The various manufacturing processes are listed along the left side of the table. The typical applications are listed along the bottom of the table, and the corresponding roughness height rating for each process/application is listed horizontally in a bar-graph format. *Figure 10-97* is a table of typical surface roughness height applications.



FIGURE 10-96 *Applying finish marks to drawings.*

Micro-inch ratings are listed in the left-most column of the table. The corresponding micrometer ratings are listed in the next column. Applications are then

MICROMETERS AA RATING	MICROINCHES AA RATING	APPLICATION
25.2	1000	Rough, low-grade surface resulting from sand casting, torch or saw cutting, chipping, or rough forging. Machine operations are not required because appearance is not objectionable. This surface, rarely specified, is suitable for unmachined clearance areas on rough construction items.
12.5	500	Rough, low-grade surface resulting from heavy cuts and coarse feeds in milling, turning, shaping, boring, and rough filing, disc grinding, and snagging. It is suitable for clearance areas on machinery, jigs, and fixtures. Sand casting or rough forging produces this surface.
6.3	250	Coarse production surfaces, for unimportant clearance and cleanup operations, resulting from coarse surface grind, rough file, disc grind, rapid feeds in turning, milling, shaping, drilling, boring, grinding, etc., where tool marks are not objectionable. The natural surfaces of forgings, permanent mold castings, extrusions, and rolled surfaces also produce this roughness. It can be produced economically and is used on parts where stress requirements, appearance, and conditions of operations and design permit.
3.2	125	The roughest surface recommended for parts subject to loads, vibration, and high stress. It is also permitted for bearing surfaces when motion is slow and loads light or infrequent. It is a medium commercial machine finish produced by relatively high speeds and fine feeds taking light cuts with sharp tools. It may be economically produced on lathes, milling machines, shapers, grinders, etc., or on permanent mold castings, die castings, extrusion, and rolled surfaces.
1.6	63	A good machine finish produced under controlled conditions using relatively high speeds and fine feeds to take light cuts with sharp cutters. It may be specified for close fits and used for all stressed parts, except fast rotating shafts, axles, and parts subject to severe vibration or extreme tension. It is satisfactory for bearing surfaces when motion is slow and loads light or infrequent. It may also be obtained on extrusions, rolled surfaces, die castings, and permanent mold castings when rigidly controlled.
0.8	32	A high-grade machine finish requiring close control when produced by lathes, shapers, milling machines, etc., but relatively easy to produce by centerless, cylindrical, or surface grinders. Also, extruding, rolling, or die casting may produce a comparable surface when rigidly controlled.This surface may be specified in parts where stress concentration is present. It is used for bearings when motion is not continuous and loads are light. When finer finishes are specified, production costs rise rapidly; therefore, such finishes must be analyzed carefully.
0.4	16	A high-quality surface produced by fine cylindrical grinding, emery buffing, coarse honing, or lapping, it is specified where smoothness is of primary importance, such as rapidly rotating shaft bearings, heavily loaded bearing, and extreme tension members.
0.2	8	A fine surface produced by honing, lapping, or buffing. It is specified where packings and rings must slide across the direction of the surface grain, maintaining or withstanding pressures, or for interior honed surfaces of hydraulic cylinders. It may also be required in precision gauges and instrument work, or sensitive value surfaces, or on rapidly rotating shafts and on bearings where lubrication is not dependable.
0.1	4	A costly refined surface produced by honing, lapping, and buffing. It is specified only when the design requirements make it mandatory. It is required in instrument work, gauge work, and where packing and rings must slide across the direction of surface grain such as on chrome-plated piston rods, etc, where lubrication is not dependable.
0.05 0.025	2 1	Costly refined surfaces produced only by the finest of modern honing, lapping, buffing, and superfinishing equipment. These surfaces may have a satin or highly polished appearance depending on the finishing operation and material. These surfaces are specified only when design requirements make it mandatory. They are specified on fine or sensitive instrument parts or other laboratory items, and certain gauge surfaces, such as precision gauge blocks.

FIGURE 10-97 *Typical surface roughness height applications.*



FIGURE 10-98 *X-Y-Z coordinates.*

explained horizontally beside each rating. Engineering students should familiarize themselves with these ratings and their corresponding applications.

X-Y-Z Coordinates

Figure 10-98 illustrates the concept of X-Y-Z coordinates. In order to be able to fully understand the various dimensioning systems, one must understand the concept of X-Y-Z coordinates. This is particularly true in the case of tabular dimensioning. Note from this illustration that X coordinates move from an origin in a horizontal direction, Y coordinates move from an origin in a vertical direction, and Z coordinates move from an origin in a direction indicating depth.

Tabular Dimensioning

Figure 10-99 illustrates the concept of tabular dimensioning. Tabular dimensioning is a system in which size and location dimensions are given in a table rather than on the drawing itself. Notice that the only dimensions applied to the drawing itself are the overall length, width, and depth dimensions. Each hole is given an alphanumeric designation. Holes with the same letter designation have the same diameter. Holes with the same letter designation but a different numerical suffix have the same diameter but a different depth. The holes are located in the part using X, Y, and Z coordinates from the specified base lines. In certain cases such as the one illustrated in Figure 10-99, tabular dimensioning is a more convenient, less confusing approach.

Tabular Drawing

When parts have similar features but different dimensions, the dimensions can be given in tabular form to decrease the amount of drawing that must be



HOLE	ϕ	X	Y	Z	NOTE
A1	.25	.30	1.75	THRU	–
A2		1.38	1.06	.38	–
B1	.18	.30	.94	THRU	–
B2		3.25	1.75	THRU	–
B3		3.25	1.50	THRU	–
C1	.38	.88	1.68	.38	–
C2		.88	.62	.25	–
C3		1.12	.38	.38	–
D1	.08	2.12	1.81	THRU	–
D2		3.00	.62	.38	–
D3		3.62	.62	.38	–

FIGURE 10-99 *Tabular dimensioning.*

done. With a tabular drawing, one drawing of the part is made with all appropriate dimension lines applied. However, instead of dimension notations, numerical notations are substituted. Then a table of dimensions is prepared showing the part numbers for all of the parts that the drawing applies to and the dimensions for each letter notation, *Figure 10-100.*

Tolerancing

Even the best machinist operating the most accurate machine tool is not able to produce a part as precisely



A85254-3	4.50	1.62	ϕ.38	3/8-16 UNC-2A	1.50
A85254-2	4.88	2.50	ϕ.38	3/8-16 UNC-2A	2.00
A85254-1	2.50	1.50	ϕ.25	1/4-20 UNC-2A	.88
PART NUMBER	A	B	C	D	E

REGULAR DRAWING NUMBER

PLAN NO 85254

FIGURE 10-100 *Tabular drawing.*

and accurately as specified on a drawing. For this reason it is necessary to apply tolerances when dimensioning parts. A *tolerance* is the total amount of variation permitted from the design size of a part. A basic rule of thumb when applying tolerances is to make them as large as possible and still be able to produce a usable part. Tolerances may be expressed as limits, as shown in ***Figures 10-101*** and ***10-102*** or as the design size followed by the tolerance (12.382 ± 0.003). The design size of a part is also known as the nominal size. This is the dimension from which the limits are calculated. To calculate the upper limit of a toleranced dimension, add the allowable tolerance to the nominal size. To calculate the lower limits for such dimensions, subtract the allowable tolerance from the nominal size, Figures 10-101 and 10-102. There are several definitions with which drafters and engineers should be familiar before applying tolerances on drawings. The most important of these are:

ACTUAL SIZE
Also called the produced size, this is the actual size of the part after it is produced.

ALLOWANCE
The amount of room between two main parts, usually considered the tightest possible fit between the two parts, is called the *allowance*.



FIGURE 10-101 *Shaft limits.*



FIGURE 10-102 *Hole limits.*

BILATERAL TOLERANCE
A bilateral tolerance is one in which variation from the nominal dimension is allowed in both the plus and the minus directions (.500 ±.002).

DATUM
A theoretically perfect surface, plane, axis, center plane, or point from which dimensions for related features are established.

LEAST MATERIAL CONDITION (LMC)
The condition which exists when the least material is available for the features being dimensioned. *Least material condition (LMC)* is the lower limit for an external feature and the upper limit for an internal feature.

LIMITS
The largest and smallest possible size in which a part may be produced and still be usable. The limits are calculated by applying the specified tolerance to the nominal dimension.

MAXIMUM MATERIAL CONDITION (MMC)
The condition of a part in which the most material is present. *Maximum material condition (MMC)* is the upper limit for an external feature and the lower limit for an internal feature.

NOMINAL DIMENSION
This is the dimension from which the limits are calculated. By applying the specified tolerance to the nominal dimension one can calculate the upper and lower limits.

TOLERANCE
The total permissible variation in size for a part. The tolerance is the difference between the upper and lower limits for a part.

UNILATERAL TOLERANCE
A tolerance that may vary in only one direction; either in the plus or minus direction but not both:

$$.500^{+.000}_{-.002} \qquad .250^{+.002}_{-.000}$$

In addition to these tolerance-related definitions, drafters and engineers should also be familiar with the types of fits that are used with mating parts. The following definitions relate specifically to fits between mating parts.

FIT
Fit refers to the amount of tightness or looseness between mating parts. There are three types of fits: clearance, interference, and transition.

CLEARANCE FIT

A clearance fit is one in which there is space remaining after mating parts have been assembled.

INTERFERENCE FIT

The type of fit that occurs when there is a negative allowance, or in other words, when the shaft is larger than the collar with which it must mate.

TRANSITION FIT

The type of fit in which there may be either a clearance or an interference fit after mating parts have been assembled. This occurs when the smallest shaft size within the allowable tolerance will fit within the largest hole size, resulting in a clearance fit, and when the largest shaft size within the allowable tolerance will interfere with the smallest hole within an allowable tolerance, creating an interference fit.

Shaft Limits

Figure 10-101 illustrates the concept of shaft limits. In this figure the shaft has a nominal dimension of .500. The tolerance specified is ±.010. To determine the upper limit for the shaft, the tolerance of .010 is added to the nominal dimension of .500, resulting in an upper limit of .510. To determine the lower limit of the shaft, the tolerance of .010 is subtracted from the nominal dimension of .500, resulting in a lower limit of .490.

Hole Limits

Figure 10-102 illustrates the concept of hole limits. The hole through the part shown has a nominal diameter of .525. The specified tolerance is ±.010. To determine the upper limit for the hole, the tolerance of .010 is added to the nominal dimension of .525, resulting in an upper limit of .535. The lower limit is determined by subtracting the tolerance of .010 from the nominal dimension of .525, resulting in a lower limit of .515.

Allowance

Figure 10-103 illustrates the concept of allowance or the tightest fit between mating parts. Part 1 is a shaft that, when assembled, will mate with Part 2. To determine the allowance between Part 1 and Part 2, the maximum material condition of the shaft (the largest allowable size) is subtracted from the maximum material condition of the hole (the smallest size hole). The maximum material condition of the shaft is .510. The maximum material condition of the hole is .515. Therefore, the allowance between Part 1 and Part 2 is .005.



FIGURE 10-103 *Allowance.*



FIGURE 10-104 *Clearance.*

Clearance Fit

Figure 10-104 illustrates the concept of *clearance fit*. The shaft, Part 1, is to mate with the collar, Part 2, during assembly. To determine the clearance between Part 1 and Part 2, the least material condition of the shaft is subtracted from the least material condition of the hole. The least material condition of the shaft is .490. The least material condition of the hole is .535. Therefore, the clearance between Part 1 and Part 2 is .045.

Interference Fit

Figure 10-105 illustrates the concept of *interference fit*. The smallest shaft in this example is larger than the largest corresponding hole. To determine the amount



FIGURE 10-105 *Interference fit.*

of interference, you can calculate the allowance and the clearance. The allowance, in the case of an interference fit, represents the maximum amount of interference. The clearance, in an interference fit, represents the smallest amount of interference. You can see from the calculations in Figure 10-105 that the maximum amount of interference during assembly will be .007, or the allowance. The minimum amount of interference will be .004, or the clearance.

Transition Fit

Figure 10-106 illustrates the concept of *transition fit*. In this example there can be both a clearance fit and an interference fit. The largest shaft in this example would interfere with the smallest hole. However, the smallest shaft will fit through the largest hole. This condition is illustrated in the calculations.

Size Limits

Figure 10-107 illustrates the concept of size limits. The cylindrical part shown in this figure will be usable if produced at any size between the upper and lower length limits, and at any diameter between the upper and lower diameter limits, inclusive. Applying size limits such as those illustrated in Figure 10-107 cuts down on waste, requires less time to produce the part, and, therefore, cuts the cost of production and the corresponding costs of the part.



FIGURE 10-106 *Transition fit.*



FIGURE 10-107 *Size limits.*



FIGURE 10-108 *Design size.*

Design Size

Figure 10-108 illustrates the concept of design size. Design size is another way of stating nominal size. The design size represents the ideal the drafter or engineer is seeking. Ideally, the produced size will match the design size. However, since this is not practical, tolerances are normally applied.

Maximum and Minimum Sizes

Figure 10-109 illustrates the concept of maximum and minimum sizes. These are the sizes between which the actual length and diameter of the produced part must fall. After all machining processes have been completed, the inspection department will check the part. If the actual produced size falls within the established maximum and minimum sizes (inclusive), the part will be passed as usable. If it is smaller in any dimension than the minimum size, the part will be scrapped as waste. If it is larger in any dimension than the maximum size, it might be salvaged through additional machining.

Location Limits

Just as limits are applied to size dimensions, they are also applied to location dimensions, and for the same reasons. Machinists cannot locate features on a part precisely to the design dimension. Consequently, limits must be applied to location dimensions.

Figure 10-110 illustrates how limits are applied to location dimensions. The part shown in Figure 10-110 will be accepted if the central line of the hole falls within the limits shown.



FIGURE 10-109 *Maximum and minimum sizes.*



FIGURE 10-110 *Location limits.*



FIGURE 10-111 *Design location.*

Design Location

Figure 10-111 illustrates the concept of design location. The design location is the location the drafter or engineer actually wants. It is the theoretically ideal location of the feature. The dimensions shown on this figure are the design dimensions, sometimes referred to as nominal dimensions. The specified tolerance is applied to these nominal dimensions to determine the upper and lower limits for locating the feature.

Maximum and Minimum Locations

Figure 10-112 illustrates the concept of maximum and minimum locations. By applying the specified tolerance to the nominal dimensions, the maximum and minimum locations of the center line of the feature in this figure can be determined. The tolerances applied to the nominal dimension give the machinist latitude in both the X and Y directions. This establishes a square tolerance zone within which the actual center point must fall. So long as the center of the feature



FIGURE 10-112 *Maximum and minimum locations.*



RULE:
ALL TOLERANCES SHOULD BE GIVEN AS LARGE AS POSSIBLE WITHOUT INTERFERING WITH THE FUNCTION OF THE PART IN ORDER TO KEEP COST DOWN — CLOSE DIMENSIONS ARE EXPENSIVE

FIGURE 10-113 *Calculating fits.*

falls anywhere within the prescribed tolerance zone, the parts will be accepted as usable.

Calculating Fits

Figure 10-113 illustrates the mathematics involved in calculating fits. Take special note of the rule that states "All dimensions should be given as large as possible without interfering with the function of the part in order to keep costs down—close dimensions are expensive." The tighter the fit, the more difficult the part is to manufacture. The more difficult the part is to manufacture, the more it costs to manufacture. Therefore, an engineer and a drafter should never assign a tighter fit than is absolutely necessary for the part to properly function.

Matching Parts

Figure 10-114 illustrates the concept of matching parts. During assembly, Part A must fit over Part B. You can see from this drawing that the hole in Part A



FIGURE 10-114 *Matching parts.*

must be large enough to accommodate the size and location tolerances of the pins in Part B. The parts must be able to fit if the holes in Part A are bored and located on the low side of the tolerance and the pins in Part B are made and located on the high side of the tolerance. Obviously, determining the dimensions to be used for matching parts takes a good deal of careful planning. It is critical that features on mating parts be located from the same datum as shown in this figure. Some additional factors to consider when planning the dimensions for matching parts are:

1. The length of time the parts are to be engaged
2. The speed at which mating parts will move after assembly
3. The load of the parts after assembly
4. The type of lubrication used if lubrication is necessary
5. The average temperature at which parts will operate
6. The level of humidity during operation
7. The materials of which parts are made
8. The required functional lifespan of the part
9. The capabilities of machine tools and the people that operate them in the manufacturing plant
10. Overall costs of the part

Standard Fits

Figure 10-115 shows the different types of standard fits. The American National Standards Institute document governing fits is ANSI B4.1-1967, R1994. This standard covers the five types of fits listed in Figure 10-115. Each of these fits is explained in this section.

RUNNING OR SLIDING CLEARANCE FITS (RC)

Running or sliding fits are used to provide a similar running or sliding performance, with an allowance for suitable lubrication, for all sizes within the specified range. *Figure 10-116* is a table of American National Standard Running and Sliding Fits (ANSI B4.1-1967, R1994). From this table you can see that there are nine classes of running and sliding fits: Classes RC1, RC2, RC3, RC4, RC5, RC6, RC7, RC8, and RC9.

STANDARD FITS	
RC	RUNNING AND SLIDING FITS
LC	CLEARANCE LOCATIONAL FITS
LT	TRANSITION LOCATIONAL FITS
LN	INTERFERENCE LOCATIONAL FITS
FN	FORCE AND SHRINK FITS

FIGURE 10-115 *Standard fits.*

Class RC1 is used with close sliding fits for accurately locating parts that must fit together without any play. Class RC2 is used for sliding fits where accurate location is important, but where greater maximum clearance that is provided by class RC1 fits is necessary. Parts manufactured to this fit do not run freely, but they do move and turn easily. Class RC3 is used for precision running fits. This class ensures the closest possible fit that can be expected to run freely. This fit is used for precision work that will operate at slow speeds under light pressures, but it is not suitable where significant temperature differences are likely to occur.

Class RC4 is used for close running fits on accurate machinery with medium surface speeds and pressure when accurate location and very little play is desired. Classes RC5 and RC6 are used for medium running fits on accurate machinery with higher running speeds and/or heavier pressures. Class RC7 is used for free running fits where accuracy is less important and/or where significant temperature variations are likely. Classes RC8 and RC9 are used for loose running fits when large tolerances are necessary, together with an allowance on the external parts.

CLEARANCE LOCATIONAL FITS (LC)

Clearance locational fits are used with parts that are stationary but must be able to be freely assembled or disassembled. *Figure 10-117* is a table of American National Standard Clearance Locational Fits from ANSI 4.1-1967, R1994.

TRANSITION LOCATIONAL FITS (LT)

Transition locational fits fall on a continuum between clearance and interference fits, and are used in applications where locational accuracy is important but a small amount of clearance or interference is allowable. *Figure 10-118* (page 407) is a table of American National Standard Transition Locational Fits from ANSI B4.1-1967, R1994.

INTERFERENCE LOCATIONAL FITS (LN)

Interference locational fits are used when locational accuracy is very important and for parts requiring rigidity and alignment but no special requirements for bore pressure. Interference locational fits are not used for parts that are designed to transmit frictional loads to other parts through the tightness of the fits. These types of applications are covered by force fits. *Figure 10-119* (page 408) is a table of American National Standard Interference Locational Fits from ANSI B4.1-1967, R1994.

Nominal Size Range, Inches Over To	Class RC 1			Class RC 2			Class RC 3			Class RC 4		
	Clearance*	Standard Tolerance Limits Hole H5	Shaft g4	Clearance*	Standard Tolerance Limits Hole H6	Shaft g5	Clearance*	Standard Tolerance Limits Hole H7	Shaft f6	Clearance*	Standard Tolerance Limits Hole H8	Shaft f7
	Values shown below are in thousandths of an inch											
0–0.12	0.1 0.45	+0.2 0	−0.1 −0.25	0.1 0.55	+0.25 0	−0.1 −0.3	0.3 0.95	+0.4 0	−0.3 −0.55	0.3 1.3	+0.6 0	−0.3 −0.7
0.12–0.24	0.15 0.5	+0.2 0	−0.15 −0.3	0.15 0.65	+0.3 0	−0.15 −0.35	0.4 1.12	+0.5 0	−0.4 −0.7	0.4 1.6	+0.7 0	−0.4 −0.9
0.24–0.40	0.2 0.6	+0.25 0	−0.2 −0.35	0.2 0.85	+0.4 0	−0.2 −0.45	0.5 1.5	+0.6 0	−0.5 −0.9	0.5 2.0	+0.9 0	−0.5 −1.1
0.40–0.71	0.25 0.75	+0.3 0	−0.25 −0.45	0.25 0.95	+0.4 0	−0.25 −0.55	0.6 1.7	+0.7 0	−0.6 −1.0	0.6 2.3	+1.0 0	−0.6 −1.3
0.71–1.19	0.3 0.95	+0.4 0	−0.3 −0.55	0.3 1.2	+0.5 0	−0.3 −0.7	0.8 2.1	+0.8 0	−0.8 −1.3	0.8 2.8	+1.2 0	−0.8 −1.6
1.19–1.97	0.4 1.1	+0.4 0	−0.4 −0.7	0.4 1.4	+0.6 0	−0.4 −0.8	1.0 2.6	+1.0 0	−1.0 −1.6	1.0 3.6	+1.6 0	−1.0 −2.0
1.97–3.15	0.4 1.2	+0.5 0	−0.4 −0.7	0.4 1.6	+0.7 0	−0.4 −0.9	1.2 3.1	+1.2 0	−1.2 −1.9	1.2 4.2	+1.8 0	−1.2 −2.4
3.15–4.73	0.5 1.5	+0.6 0	−0.5 −0.9	0.5 2.0	+0.9 0	−0.5 −1.1	1.4 3.7	+1.4 0	−1.4 −2.3	1.4 5.0	+2.2 0	−1.4 −2.8
4.73–7.09	0.6 1.8	+0.7 0	−0.6 −1.1	0.6 2.3	+1.0 0	−0.6 −1.3	1.6 4.2	+1.6 0	−1.6 −2.6	1.6 5.7	+2.5 0	−1.6 −3.2
7.09–9.85	0.6 2.0	+0.8 0	−0.6 −1.2	0.6 2.6	+1.2 0	−0.6 −1.4	2.0 5.0	+1.8 0	−2.0 −3.2	2.0 6.6	+2.8 0	−2.0 −3.8
9.85–12.41	0.8 2.3	+0.9 0	−0.8 −1.4	0.8 2.9	+1.2 0	−0.8 −1.7	2.5 5.7	+2.0 0	−2.5 −3.7	2.5 7.5	+3.0 0	−2.5 −4.5
12.41–15.75	1.0 2.7	+1.0 0	−1.0 −1.7	1.0 3.4	+1.4 0	−1.0 −2.0	3.0 6.6	+2.2 0	−3.0 −4.4	3.0 8.7	+3.5 0	−3.0 −5.2
15.75–19.69	1.2 3.0	+1.0 0	−1.2 −2.0	1.2 3.8	+1.6 0	−1.2 −2.2	4.0 8.1	+2.5 0	−4.0 −5.6	4.0 10.5	+4.0 0	−4.0 −6.5

See footnotes at end of table.

Nominal Size Range, Inches Over To	Class RC 5			Class RC 6			Class RC 7			Class RC 8			Class RC 9		
	Clearance*	Standard Tolerance Limits Hole H8	Shaft e7	Clearance*	Standard Tolerance Limits Hole H9	Shaft e8	Clearance*	Standard Tolerance Limits Hole H9	Shaft d8	Clearance*	Standard Tolerance Limits Hole H10	Shaft c9	Clearance*	Standard Tolerance Limits Hole H11	Shaft
	Values shown below are in thousandths of an inch														
0–0.12	0.6 1.6	+0.6 0	−0.6 −1.0	0.6 2.2	+1.0 0	−0.6 −1.2	1.0 2.6	+1.0 0	−1.0 −1.6	2.5 5.1	+1.6 0	−2.5 −3.5	4.0 8.1	+2.5 0	−4.0 −5.6
0.12–0.24	0.8 2.0	+0.7 0	−0.8 −1.3	0.8 2.7	+1.2 0	−0.8 −1.5	1.2 3.1	+1.2 0	−1.2 −1.9	2.8 5.8	+1.8 0	−2.8 −4.0	4.5 9.0	+3.0 0	−4.5 −6.0
0.24–0.40	1.0 2.5	+0.9 0	−1.0 −1.6	1.0 3.3	+1.4 0	−1.0 −1.9	1.6 3.9	+1.4 0	−1.6 −2.5	3.0 6.6	+2.2 0	−3.0 −4.4	5.0 10.7	+3.5 0	−5.0 −7.2
0.40–0.71	1.2 2.9	+1.0 0	−1.2 −1.9	1.2 3.8	+1.6 0	−1.2 −2.2	2.0 4.6	+1.6 0	−2.0 −3.0	3.5 7.9	+2.8 0	−3.5 −5.1	6.0 12.8	+4.0 0	−6.0 −8.8
0.71–1.19	1.6 3.6	+1.2 0	−1.6 −2.4	1.6 4.8	+2.0 0	−1.6 −2.8	2.5 5.7	+2.0 0	−2.5 −3.7	4.5 10.0	+3.5 0	−4.5 −6.5	7.0 15.5	+5.0 0	−7.0 −10.5
1.19–1.97	2.0 4.6	+1.6 0	−2.0 −3.0	2.0 6.1	+2.5 0	−2.0 −3.6	3.0 7.1	+2.5 0	−3.0 −4.6	5.0 11.5	+4.0 0	−5.0 −7.5	8.0 18.0	+6.0 0	−8.0 −12.0
1.97–3.15	2.5 5.5	+1.8 0	−2.5 −3.7	2.5 7.3	+3.0 0	−2.5 −4.3	4.0 8.8	+3.0 0	−4.0 −5.8	6.0 13.5	+4.5 0	−6.0 −9.0	9.0 20.5	+7.0 0	−9.0 −13.5
3.15–4.73	3.0 6.6	+2.2 0	−3.0 −4.4	3.0 8.7	+3.5 0	−3.0 −5.2	5.0 10.7	+3.5 0	−5.0 −7.2	7.0 15.5	+5.0 0	−7.0 −10.5	10.0 24.0	+9.0 0	−10.0 −15.0
4.73–7.09	3.5 7.6	+2.5 0	−3.5 −5.1	3.5 10.0	+4.0 0	−3.5 −6.0	6.0 12.5	+4.0 0	−6.0 −8.5	8.0 18.0	+6.0 0	−8.0 −12.0	12.0 28.0	+10.0 0	−12.0 −18.0
7.09–9.85	4.0 8.6	+2.8 0	−4.0 −5.8	4.0 11.3	+4.5 0	−4.0 −6.8	7.0 14.3	+4.5 0	−7.0 −9.8	10.0 21.5	+7.0 0	−10.0 −14.5	15.0 34.0	+12.0 0	−15.0 −22.0
9.85–12.41	5.0 10.0	+3.0 0	−5.0 −7.0	5.0 13.0	+5.0 0	−5.0 −8.0	8.0 16.0	+5.0 0	−8.0 −11.0	12.0 25.0	+8.0 0	−12.0 −17.0	18.0 38.0	+12.0 0	−18.0 −26.0
12.41–15.75	6.0 11.7	+3.5 0	−6.0 −8.2	6.0 15.5	+6.0 0	−6.0 −9.5	10.0 19.5	+6.0 0	−10.0 −13.5	14.0 29.0	+9.0 0	−14.0 −20.0	22.0 45.0	+14.0 0	−22.0 −31.0
15.75–19.69	8.0 14.5	+4.0 0	−8.0 −10.5	8.0 18.0	+6.0 0	−8.0 −12.0	12.0 22.0	+6.0 0	−12.0 −16.0	16.0 32.0	+10.0 0	−16.0 −22.0	25.0 51.0	+16.0 0	−25.0 −35.0

All data above heavy lines are in accord with ABC agreements. Symbols H5, g4, etc. are hole and shaft designations in ABC system. Limits for sizes above 19.69 inches are also given in the ANSI Standard.

* Pairs of values shown represent minimum and maximum amounts of clearance resulting from application of standard tolerance limits.

FIGURE 10-116 *ANSI standard running and sliding fits. (Courtesy ASME)*

Nominal Size Range, Inches	Class LC 1			Class LC 2			Class LC 3			Class LC 4			Class LC 5		
		Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits	
Over To	Clearance*	Hole H6	Shaft h5	Clearance*	Hole H7	Shaft h6	Clearance*	Hole H8	Shaft h7	Clearance*	Hole H10	Shaft h9	Clearance*	Hole H7	Shaft g6
	Values shown below are in thousandths of an inch														
0–0.12	0 0.45	+0.25 0	0 −0.2	0 0.65	+0.4 0	0 −0.25	0 1	+0.6 0	0 −0.4	0 2.6	+1.6 0	0 −1.0	0.1 0.75	+0.4 0	−0.1 −0.35
0.12–0.24	0 0.5	+0.3 0	0 −0.2	0 0.8	+0.5 0	0 −0.3	0 1.2	+0.7 0	0 −0.5	0 3.0	+1.8 0	0 −1.2	0.15 0.95	+0.5 0	−0.15 −0.45
0.24–0.40	0 0.65	+0.4 0	0 −0.25	0 1.0	+0.6 0	0 −0.4	0 1.5	+0.9 0	0 −0.6	0 3.6	+2.2 0	0 −1.4	0.2 1.2	+0.6 0	−0.2 −0.6
0.40–0.71	0 0.7	+0.4 0	0 −0.3	0 1.1	+0.7 0	0 −0.4	0 1.7	+1.0 0	0 −0.7	0 4.4	+2.8 0	0 −1.6	0.25 1.35	+0.7 0	−0.25 −0.65
0.71–1.19	0 0.9	+0.5 0	0 −0.4	0 1.3	+0.8 0	0 −0.5	0 2	+1.2 0	0 −0.8	0 5.5	+3.5 0	0 −2.0	0.3 1.6	+0.8 0	−0.3 −0.8
1.19–1.97	0 1.0	+0.6 0	0 −0.4	0 1.6	+1.0 0	0 −0.6	0 2.6	+1.6 0	0 −1	0 6.5	+4.0 0	0 −2.5	0.4 2.0	+1.0 0	−0.4 −1.0
1.97–3.15	0 1.2	+0.7 0	0 −0.5	0 1.9	+1.2 0	0 −0.7	0 3	+1.8 0	0 −1.2	0 7.5	+4.5 0	0 −3	0.4 2.3	+1.2 0	−0.4 −1.1
3.15–4.73	0 1.5	+0.9 0	0 −0.6	0 2.3	+1.4 0	0 −0.9	0 3.6	+2.2 0	0 −1.4	0 8.5	+5.0 0	0 −3.5	0.5 2.8	+1.4 0	−0.5 −1.4
4.73–7.09	0 1.7	+1.0 0	0 −0.7	0 2.6	+1.6 0	0 −1.0	0 4.1	+2.5 0	0 −1.6	0 10.0	+6.0 0	0 −4	0.6 3.2	+1.6 0	−0.6 −1.6
7.09–9.85	0 2.0	+1.2 0	0 −0.8	0 3.0	+1.8 0	0 −1.2	0 4.6	+2.8 0	0 −1.8	0 11.5	+7.0 0	0 −4.5	0.6 3.6	+1.8 0	−0.6 −1.8
9.85–12.41	0 2.1	+1.2 0	0 −0.9	0 3.2	+2.0 0	0 −1.2	0 5	+3.0 0	0 −2.0	0 13.0	+8.0 0	0 −5	0.7 3.9	+2.0 0	−0.7 −1.9
12.41–15.75	0 2.4	+1.4 0	0 −1.0	0 3.6	+2.2 0	0 −1.4	0 5.7	+3.5 0	0 −2.2	0 15.0	+9.0 0	0 −6	0.7 4.3	+2.2 0	−0.7 −2.1
15.75–19.69	0 2.6	+1.6 0	0 −1.0	0 4.1	+2.5 0	0 −1.6	0 6.5	+4 0	0 −2.5	0 16.0	+10.0 0	0 −6	0.8 4.9	+2.5 0	−0.8 −2.4

See footnotes at end of table.

Nominal Size Range, Inches	Class LC 6			Class LC 7			Class LC 8			Class LC 9			Class LC 10			Class LC 11		
		Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits	
Over To	Clearance*	Hole H9	Shaft f8	Clearance*	Hole H10	Shaft e9	Clearance*	Hole H10	Shaft d9	Clearance*	Hole H11	Shaft c10	Clearance*	Hole H12	Shaft	Clearance*	Hole H13	Shaft
	Values shown below are in thousandths of an inch																	
0–0.12	0.3 1.9	+1.0 0	−0.3 −0.9	0.6 3.2	+1.6 0	−0.6 −1.6	1.0 2.0	+1.6 0	−1.0 −2.0	2.5 6.6	+2.5 0	−2.5 −4.1	4 12	+4 0	−4 −8	5 17	+6 0	−5 −11
0.12–0.24	0.4 2.3	+1.2 0	−0.4 −1.1	0.8 3.8	+1.8 0	−0.8 −2.0	1.2 4.2	+1.8 0	−1.2 −2.4	2.8 7.6	+3.0 0	−2.8 −4.6	4.5 14.5	+5 0	−4.5 −9.5	6 20	+7 0	−6 −13
0.24–0.40	0.5 2.8	+1.4 0	−0.5 −1.4	1.0 4.6	+2.2 0	−1.0 −2.4	1.6 5.2	+2.2 0	−1.6 −3.0	3.0 8.7	+3.5 0	−3.0 −5.2	5 17	+6 0	−5 −11	7 25	+9 0	−7 −16
0.40–0.71	0.6 3.2	+1.6 0	−0.6 −1.6	1.2 5.6	+2.8 0	−1.2 −2.8	2.0 6.4	+2.8 0	−2.0 −3.6	3.5 10.3	+4.0 0	−3.5 −6.3	6 20	+7 0	−6 −13	8 28	+10 0	−8 −18
0.71–1.19	0.8 4.0	+2.0 0	−0.8 −2.0	1.6 7.1	+3.5 0	−1.6 −3.6	2.5 8.0	+3.5 0	−2.5 −4.5	4.5 13.0	+5.0 0	−4.5 −8.0	7 23	+8 0	−7 −15	10 34	+12 0	−10 −22
1.19–1.97	1.0 5.1	+2.5 0	−1.0 −2.6	2.0 8.5	+4.0 0	−2.0 −4.5	3.0 9.5	+4.0 0	−3.0 −5.5	5.0 15.0	+6 0	−5.0 −9.0	8 28	+10 0	−8 −18	12 44	+16 0	−12 −28
1.97–3.15	1.2 6.0	+3.0 0	−1.0 −3.0	2.5 10.0	+4.5 0	−2.5 −5.5	4.0 11.5	+4.5 0	−4.0 −7.0	6.0 17.5	+7 0	−6.0 −10.5	10 34	+12 0	−10 −22	14 50	+18 0	−14 −32
3.15–4.73	1.4 7.1	+3.5 0	−1.4 −3.6	3.0 11.5	+5.0 0	−3.0 −6.5	5.0 13.5	+5.0 0	−5.0 −8.5	7 21	+9 0	−7 −12	11 39	+14 0	−11 −25	16 60	+22 0	−16 −38
4.73–7.09	1.6 8.1	+4.0 0	−1.6 −4.1	3.5 13.5	+6.0 0	−3.5 −7.5	6 16	+6 0	−6 −10	8 24	+10 0	−8 −14	12 44	+16 0	−12 −28	18 68	+25 0	−18 −43
7.09–9.85	2.0 9.3	+4.5 0	−2.0 −4.8	4.0 15.5	+7.0 0	−4.0 −8.5	7 18.5	+7 0	−7 −11.5	10 29	+12 0	−10 −17	16 52	+18 0	−16 −34	22 78	+28 0	−22 −50
9.85–12.41	2.2 10.2	+5.0 0	−2.2 −5.2	4.5 17.5	+8.0 0	−4.5 −9.5	7 20	+8 0	−7 −12	12 32	+12 0	−12 −20	20 60	+20 0	−20 −40	28 88	+30 0	−28 −58
12.41–15.75	2.5 12.0	+6.0 0	−2.5 −6.0	5.0 20.0	+9.0 0	−5 −11	8 23	+9 0	−8 −14	14 37	+14 0	−14 −23	22 66	+22 0	−22 −44	30 100	+35 0	−30 −65
15.75–19.69	2.8 12.8	+6.0 0	−2.8 −6.8	5.0 21.0	+10.0 0	−5 −11	9 25	+10 0	−9 −15	16 42	+16 0	−16 −26	25 75	+25 0	−25 −50	35 115	+40 0	−35 −75

All data above heavy lines are in accordance with American-British-Canadian (ABC) agreements. Symbols H6, H7, s6, etc. are hole and shaft designations in ABC system. Limits for sizes above 19.69 inches are not covered by ABC agreements but are given in the ANSI Standard.

* Pairs of values shown represent minimum and maximum amounts of interference resulting from application of standard tolerance limits.

FIGURE 10-117 *ANSI standard clearance locational fits. (Courtesy ASME)*

Nominal Size Range, Inches Over To	Class LT 1			Class LT 2			Class LT 3			Class LT 4			Class LT 5			Class LT 6		
		Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits	
	Fit*	Hole H7	Shaft js6	Fit*	Hole H8	Shaft js7	Fit*	Hole H7	Shaft k6	Fit*	Hole H8	Shaft k7	Fit*	Hole H7	Shaft n6	Fit*	Hole H7	Shaft n7
	Values shown below are in thousandths of an inch																	
0–0.12	−0.12 +0.52	+0.4 0	+0.12 −0.12	−0.2 +0.8	+0.6 0	+0.2 −0.2							−0.5 +0.15	+0.4 0	+0.5 +0.25	−0.65 +0.15	+0.4 0	+0.65 +0.25
0.12–0.24	−0.15 +0.65	+0.5 0	+0.15 −0.15	−0.25 +0.95	+0.7 0	+0.25 −0.25							−0.6 +0.2	+0.5 0	+0.6 +0.3	−0.8 +0.2	+0.5 0	+0.8 +0.3
0.24–0.40	−0.2 +0.8	+0.6 0	+0.2 −0.2	−0.3 +1.2	+0.9 0	+0.3 −0.3	−0.5 +0.5	+0.6 0	+0.5 +0.1	−0.7 +0.8	+0.9 0	+0.7 +0.1	−0.8 +0.2	+0.6 0	+0.8 +0.4	−1.0 +0.2	+0.6 0	+1.0 +0.4
0.40–0.71	−0.2 +0.9	+0.7 0	+0.2 −0.2	−0.35 +1.35	+1.0 0	+0.35 −0.35	−0.5 +0.6	+0.7 0	+0.5 +0.1	−0.8 +0.9	+1.0 0	+0.8 +0.1	−0.9 +0.2	+0.7 0	+0.9 +0.5	−1.2 +0.2	+0.7 0	+1.2 +0.5
0.71–1.19	−0.25 +1.05	+0.8 0	+0.25 −0.25	−0.4 +1.6	+1.2 0	+0.4 −0.4	−0.6 +0.7	+0.8 0	+0.6 +0.1	−0.9 +1.1	+1.2 0	+0.9 +0.1	−1.1 +0.2	+0.8 0	+1.1 +0.6	−1.4 +0.2	+0.8 0	+1.4 +0.6
1.19–1.97	−0.3 +1.3	+1.0 0	+0.3 −0.3	−0.5 +2.1	+1.6 0	+0.5 −0.5	−0.7 +0.9	+1.0 0	+0.7 +0.1	−1.1 +1.5	+1.6 0	+1.1 +0.1	−1.3 +0.3	+1.0 0	+1.3 +0.7	−1.7 +0.3	+1.0 0	+1.7 +0.7
1.97–3.15	−0.3 +1.5	+1.2 0	+0.3 −0.3	−0.6 +2.4	+1.8 0	+0.6 −0.6	−0.8 +1.1	+1.2 0	+0.8 +0.1	−1.3 +1.7	+1.8 0	+1.3 +0.1	−1.5 +0.4	+1.2 0	+1.5 +0.8	−2.0 +0.4	+1.2 0	+2.0 +0.8
3.15–4.73	−0.4 +1.8	+1.4 0	+0.4 −0.4	−0.7 +2.9	+2.2 0	+0.7 −0.7	−1.0 +1.3	+1.4 0	+1.0 +0.1	−1.5 +2.1	+2.2 0	+1.5 +0.1	−1.9 +0.4	+1.4 0	+1.9 +1.0	−2.4 +0.4	+1.4 0	+2.4 +1.0
4.73–7.09	−0.5 +2.1	+1.6 0	+0.5 −0.5	−0.8 +3.3	+2.5 0	+0.8 −0.8	−1.1 +1.5	+1.6 0	+1.1 +0.1	−1.7 +2.4	+2.5 0	+1.7 +0.1	−2.2 +0.4	+1.6 0	+2.2 +1.2	−2.8 +0.4	+1.6 0	+2.8 +1.2
7.09–9.85	−0.6 +2.4	+1.8 0	+0.6 −0.6	−0.9 +3.7	+2.8 0	+0.9 −0.9	−1.4 +1.6	+1.8 0	+1.4 +0.2	−2.0 +2.6	+2.8 0	+2.0 +0.2	−2.6 +0.4	+1.8 0	+2.6 +1.4	−3.2 +0.4	+1.8 0	+3.2 +1.4
9.85–12.41	−0.6 +2.6	+2.0 0	+0.6 −0.6	−1.0 +4.0	+3.0 0	+1.0 −1.0	−1.4 +1.8	+2.0 0	+1.4 +0.2	−2.2 +2.8	+3.0 0	+2.2 +0.2	−2.6 +0.6	+2.0 0	+2.6 +1.4	−3.4 +0.6	+2.0 0	+3.4 +1.4
12.41–15.75	−0.7 +2.9	+2.2 0	+0.7 −0.7	−1.0 +4.5	+3.5 0	+1.0 −1.0	−1.6 +2.0	+2.2 0	+1.6 +0.2	−2.4 +3.3	+3.5 0	+2.4 +0.2	−3.0 +0.6	+2.2 0	+3.0 +1.6	−3.8 +0.6	+2.2 0	+3.8 +1.6
15.75–19.69	−0.8 +3.3	+2.5 0	+0.8 −0.8	−1.2 +5.2	+4.0 0	+1.2 −1.2	−1.8 +2.3	+2.5 0	+1.8 +0.2	−2.7 +3.8	+4.0 0	+2.7 +0.2	−3.4 +0.7	+2.5 0	+3.4 +1.8	−4.3 +0.7	+2.5 0	+4.3 +1.8

All data above heavy lines are in accord with ABC agreements. Symbols H7, js6, etc. are hole and shaft designations in ABC system.
* Pairs of values shown represent maximum amount of interference (−) and maximum amount of clearance (+) resulting from application of standard tolerance limits.

FIGURE 10-118 *ANSI Standard Transition Locational Fits. (Courtesy ASME)*

FORCE AND SHRINK FITS (FN)

Force or shrink fits are a special type of interference fit used when maintenance of constant bore pressure for all sizes within the specified range is important. The amount of interference varies with the diameter, and the difference between minimum and maximum values is small to ensure maintenance of the resulting pressures within reasonable limits. *Figure 10-120* is a table of American National Standard Force and Shrink Fits from ANSI B4.1-1967, R1994.

Using Fit Tables

Figures 10-116 through 10-120 are fit tables taken from ANSI B4.1-1967, R1994. It is important for engineers and drafters to know how to use tables such as these. Look at Figure 10-116. The nine classes explained earlier are arranged across the top of the table. Under each class column there are three other columns: one giving the clearance, one giving the standard tolerance limits for the hole, and one giving the standard tolerance limits for the shaft. On the extreme left-hand side of the chart the nominal size range in inches is given. To use this table, as well as the others contained in this chapter, select the appropriate class across the top of the table and locate the nominal size at the extreme left-hand side of the table. Moving across the row that contains the appropriate nominal size range to the class column you have selected, you will find the tolerance limits you need. These tolerance limits are added to or subtracted from the basic size to obtain maximum and minimum sizes of mating parts. Each tolerance is preceded by either a plus or a minus to indicate whether it is added to or subtracted from the basic size. Values must be changed to inches before adding and subtracting.

EXAMPLE:

Using fit tables:

Values are limits in thousandths of an inch.

Basic size: .0156

Nominal size range: .0–0.12

Limits of clearance: 0.1 = 000.1 = .0001

0.45 = 000.45 = .00045

Standard limits: (Move decimal three places to the left to obtain values in inches.)

Tolerance limits given in body of table are added or subtracted to basic size (as indicated by + or − sign) to obtain maximum and minimum sizes of mating parts.

Nominal Size Range, Inches		Class LN 1			Class LN 2			Class LN 3		
		Limits of Interference	Standard Limits		Limits of Interference	Standard Limits		Limits of Interference	Standard Limits	
			Hole H6	Shaft n5		Hole H7	Shaft p6		Hole H7	Shaft r6
Over	To	Values shown below are given in thousandths of an inch								
0	0.12	0 0.45	+0.25 0	+0.45 +0.25	0 0.65	+0.4 0	+0.65 +0.4	0.1 0.75	+0.4 0	+0.75 +0.5
0.12	0.24	0 0.5	+0.3 0	+0.5 +0.3	0 0.8	+0.5 0	+0.8 +0.5	0.1 0.9	+0.5 0	+0.9 +0.6
0.24	0.40	0 0.65	+0.4 0	+0.65 +0.4	0 1.0	+0.6 0	+1.0 +0.6	0.2 1.2	+0.6 0	+1.2 +0.8
0.40	0.71	0 0.8	+0.4 0	+0.8 +0.4	0 1.1	+0.7 0	+1.1 +0.7	0.3 1.4	+0.7 0	+1.4 +1.0
0.71	1.19	0 1.0	+0.5 0	+1.0 +0.5	0 1.3	+0.8 0	+1.3 +0.8	0.4 1.7	+0.8 0	+1.7 +1.2
1.19	1.97	0 1.1	+0.6 0	+1.1 +0.6	0 1.6	+1.0 0	+1.6 +1.0	0.4 2.0	+1.0 0	+2.0 +1.4
1.97	3.15	0.1 1.3	+0.7 0	+1.3 +0.8	0.2 2.1	+1.2 0	+2.1 +1.4	0.4 2.3	+1.2 0	+2.3 +1.6
3.15	4.73	0.1 1.6	+0.9 0	+1.6 +1.0	0.2 2.5	+1.4 0	+2.5 +1.6	0.6 2.9	+1.4 0	+2.9 +2.0
4.73	7.09	0.2 1.9	+1.0 0	+1.9 +1.2	0.2 2.8	+1.6 0	+2.8 +1.8	0.9 3.5	+1.6 0	+3.5 +2.5
7.09	9.85	0.2 2.2	+1.2 0	+2.2 +1.4	0.2 3.2	+1.8 0	+3.2 +2.0	1.2 4.2	+1.8 0	+4.2 +3.0
9.85	12.41	0.2 2.3	+1.2 0	+2.3 +1.4	0.2 3.4	+2.0 0	+3.4 +2.2	1.5 4.7	+2.0 0	+4.7 +3.5
12.41	15.75	0.2 2.6	+1.4 0	+2.6 +1.6	0.3 3.9	+2.2 0	+3.9 +2.5	2.3 5.9	+2.2 0	+5.9 +4.5
15.75	19.69	0.2 2.8	+1.6 0	+2.8 +1.8	0.3 4.4	+2.5 0	+4.4 +2.8	2.5 6.6	+2.5 0	+6.6 +5.0

All data in this table are in accordance with American-British-Canadian (ABC) agreements.
Limits for sizes above 19.69 inches are not covered by ABC agreements but are given in the ANSI Standard.
Symbols H7, p6, etc. are hole and shaft designations in ABC system.
* Pairs of values shown represent minimum and maximum amounts of interference resulting from application of standard tolerance limits.

FIGURE 10-119 *ANSI Standard Interference Locational Fits. (Courtesy ASME)*

Hole: +0.2 = .000.2 = +.0002
−0 = −0

Shaft: −0.1 = −.000.1 = −.0001
−0.25 = −.000.25 = −.00035

Calculating for tolerance dimensions:

Hole: .0156 basic hole size
+.0002 standard limits in thousands
.0158 upper limit for hole

.0156 basic hole size
−0 standard limits in thousands
.0156 lower limit for hole

Shaft: .0156 basic hole size
−.0001 standard limits for shaft
.0155 upper limit for shaft

.0156 basic hole size
−.00025 standard limit for shaft
.01535 lower limit for shaft

Nominal Size Range, Inches Over	To	Class FN 1			Class FN 2			Class FN 3			Class FN 4			Class FN 5		
			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits	
		Interference*	Hole H6	Shaft	Interference*	Hole H7	Shaft s6	Interference*	Hole H7	Shaft t6	Interference*	Hole H7	Shaft u6	Interference*	Hole H8	Shaft x7
		Values shown below are in thousandths of an inch														
0	0.12	0.05 0.5	+0.25 0	+0.5 +0.3	0.2 0.85	+0.4 0	+0.85 +0.6				0.3 0.95	+0.4 0	+0.95 +0.7	0.3 1.3	+0.6 0	+1.3 +0.9
0.12	0.24	0.1 0.6	+0.3 0	+0.6 +0.4	0.2 1.0	+0.5 0	+1.0 +0.7				0.4 1.2	+0.5 0	+1.2 +0.9	0.5 1.7	+0.7 0	+1.7 +1.2
0.24	0.40	0.1 0.75	+0.4 0	+0.75 +0.5	0.4 1.4	+0.6 0	+1.4 +1.0				0.6 1.6	+0.6 0	+1.6 +1.2	0.5 2.0	+0.9 0	+2.0 +1.4
0.40	0.56	0.1 0.8	+0.4 0	+0.8 +0.5	0.5 1.6	+0.7 0	+1.6 +1.2				0.7 1.8	+0.7 0	+1.8 +1.4	0.6 2.3	+1.0 0	+2.3 +1.6
0.56	0.71	0.2 0.9	+0.4 0	+0.9 +0.6	0.5 1.6	+0.7 0	+1.6 +1.2				0.7 1.8	+0.7 0	+1.8 +1.4	0.8 2.5	+1.0 0	+2.5 +1.8
0.71	0.95	0.2 1.1	+0.5 0	+1.1 +0.7	0.6 1.9	+0.8 0	+1.9 +1.4				0.8 2.1	+0.8 0	+2.1 +1.6	1.0 3.0	+1.2 0	+3.0 +2.2
0.95	1.19	0.3 1.2	+0.5 0	+1.2 +0.8	0.6 1.9	+0.8 0	+1.9 +1.4	0.8 2.1	+0.8 0	+2.1 +1.6	1.0 2.3	+0.8 0	+2.3 +1.8	1.3 3.3	+1.2 0	+3.3 +2.5
1.19	1.58	0.3 1.3	+0.6 0	+1.3 +0.9	0.8 2.4	+1.0 0	+2.4 +1.8	1.0 2.6	+1.0 0	+2.6 +2.0	1.5 3.1	+1.0 0	+3.1 +2.5	1.4 4.0	+1.6 0	+4.0 +3.0
1.58	1.97	0.4 1.4	+0.6 0	+1.4 +1.0	0.8 2.4	+1.0 0	+2.4 +1.8	1.2 2.8	+1.0 0	+2.8 +2.2	1.8 3.4	+1.0 0	+3.4 +2.8	2.4 5.0	+1.6 0	+5.0 +4.0
1.97	2.56	0.6 1.8	+0.7 0	+1.8 +1.3	0.8 2.7	+1.2 0	+2.7 +2.0	1.3 3.2	+1.2 0	+3.2 +2.5	2.3 4.2	+1.2 0	+4.2 +3.5	3.2 6.2	+1.8 0	+6.2 +5.0
2.56	3.15	0.7 1.9	+0.7 0	+1.9 +1.4	1.0 2.9	+1.2 0	+2.9 +2.2	1.8 3.7	+1.2 0	+3.7 +3.0	2.8 4.7	+1.2 0	+4.7 +4.0	4.2 7.2	+1.8 0	+7.2 +6.0
3.15	3.94	0.9 2.4	+0.9 0	+2.4 +1.8	1.4 3.7	+1.4 0	+3.7 +2.8	2.1 4.4	+1.4 0	+4.4 +3.5	3.6 5.9	+1.4 0	+5.9 +5.0	4.8 8.4	+2.2 0	+8.4 +7.0
3.94	4.73	1.1 2.6	+0.9 0	+2.6 +2.0	1.6 3.9	+1.4 0	+3.9 +3.0	2.6 4.9	+1.4 0	+4.9 +4.0	4.6 6.9	+1.4 0	+6.9 +6.0	5.8 9.4	+2.2 0	+9.4 +8.0

See footnotes at end of table.

Nominal Size Range, Inches Over	To	Class FN 1			Class FN 2			Class FN 3			Class FN 4			Class FN 5		
			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits	
		Interference*	Hole H6	Shaft	Interference*	Hole H7	Shaft s6	Interference*	Hole H7	Shaft t6	Interference*	Hole H7	Shaft u6	Interference*	Hole H8	Shaft x7
		Values shown below are in thousandths of an inch														
4.73	5.52	1.2 2.9	+1.0 0	+2.9 +2.2	1.9 4.5	+1.6 0	+4.5 +3.5	3.4 6.0	+1.6 0	+6.0 +5.0	5.4 8.0	+1.6 0	+8.0 +7.0	7.5 11.6	+2.5 0	+11.6 +10.0
5.52	6.30	1.5 3.2	+1.0 0	+3.2 +2.5	2.4 5.0	+1.6 0	+5.0 +4.0	3.4 6.0	+1.6 0	+6.0 +5.0	5.4 8.0	+1.6 0	+8.0 +7.0	9.5 13.6	+2.5 0	+13.6 +12.0
6.30	7.09	1.8 3.5	+1.0 0	+3.5 +2.8	2.9 5.5	+1.6 0	+5.5 +4.5	4.4 7.0	+1.6 0	+7.0 +6.0	6.4 9.0	+1.6 0	+9.0 +8.0	9.5 13.6	+2.5 0	+13.6 +12.0
7.09	7.88	1.8 3.8	+1.2 0	+3.8 +3.0	3.2 6.2	+1.8 0	+6.2 +5.0	5.2 8.2	+1.8 0	+8.2 +7.0	7.2 10.2	+1.8 0	+10.2 +9.0	11.2 15.8	+2.8 0	+15.8 +14.0
7.88	8.86	2.3 4.3	+1.2 0	+4.3 +3.5	3.2 6.2	+1.8 0	+6.2 +5.0	5.2 8.2	+1.8 0	+8.2 +7.0	8.2 11.2	+1.8 0	+11.2 +10.0	13.2 17.8	+2.8 0	+17.8 +16.0
8.86	9.85	2.3 4.3	+1.2 0	+4.3 +3.5	4.2 7.2	+1.8 0	+7.2 +6.0	6.2 9.2	+1.8 0	+9.2 +8.0	10.2 13.2	+1.8 0	+13.2 +12.0	13.2 17.8	+2.8 0	+17.8 +16.0
9.85	11.03	2.8 4.9	+1.2 0	+4.9 +4.0	4.0 7.2	+2.0 0	+7.2 +6.0	7.0 10.2	+2.0 0	+10.2 +9.0	10.0 13.2	+2.0 0	+13.2 +12.0	15.0 20.0	+3.0 0	+20.0 +18.0
11.03	12.41	2.8 4.9	+1.2 0	+4.9 +4.0	5.0 8.2	+2.0 0	+8.2 +7.0	7.0 10.2	+2.0 0	+10.2 +9.0	12.0 15.2	+2.0 0	+15.2 +14.0	17.0 22.0	+3.0 0	+22.0 +20.0
12.41	13.98	3.1 5.5	+1.4 0	+5.5 +4.5	5.8 9.4	+2.2 0	+9.4 +8.0	7.8 11.4	+2.2 0	+11.4 +10.0	13.8 17.4	+2.2 0	+17.4 +16.0	18.5 24.2	+3.5 0	+24.2 +22.0
13.98	15.75	3.6 6.1	+1.4 0	+6.1 +5.0	5.8 9.4	+2.2 0	+9.4 +8.0	9.8 13.4	+2.2 0	+13.4 +12.0	15.8 19.4	+2.2 0	+19.4 +18.0	21.5 27.2	+3.5 0	+27.2 +25.0
15.75	17.72	4.4 7.0	+1.6 0	+7.0 +6.0	6.5 10.6	+2.5 0	+10.6 +9.0	9.5 13.6	+2.5 0	+13.6 +12.0	17.5 21.6	+2.5 0	+21.6 +20.0	24.0 30.5	+4.0 0	+30.5 +28.0
17.72	19.69	4.4 7.0	+1.6 0	+7.0 +6.0	7.5 11.6	+2.5 0	+11.6 +10.0	11.5 15.6	+2.5 0	+15.6 +14.0	19.5 23.6	+2.5 0	+23.6 +22.0	26.0 32.5	+4.0 0	+32.5 +30.0

All data above heavy lines are in accordance with American-British-Canadian (ABC) agreements. Symbols H6, H7, s6, etc. are hole and shaft designations in ABC system. Limits for sizes above 19.69 inches are not covered by ABC agreements but are given in the ANSI standard.

* Pairs of values shown represent minimum and maximum amounts of interference resulting from application of standard tolerance limits.

FIGURE 10-120 *ANSI Standard Force and Shrink Fits. (Courtesy ASME)*

Tolerance dimensions for basic size of .0156:

Hole: .01580 Shaft: .01550
.01560 .01535

To check calculations:

Subtract: .01580 upper limit of hole
−.01535 lower limit of shaft
.00045 limit of clearance
.01560 lower limit of hole
−.01550 upper limit of shaft
.0001 limit of clearance

Limit of Clearance:

.0001 = .1 from chart

.00045 = .45 from chart

Manufacturing Precision

Figure 10-121 is a table showing the levels of tolerances engineers and drafters can expect from various common manufacturing processes. It is important for engineers and drafters to know what to expect from the manufacturing processes that will be used in converting their design into an actual working part. It will serve no purpose to specify a tolerance greater than that which can be expected of a given manufacturing process.

Summary of Dimensioning Rules

This section summarizes most of the dimensioning rules with which engineers and drafters should be familiar. This section can be used as a checklist for ensuring that drawings you do throughout this book are properly dimensioned. Use this summary as a checklist until you are so familiar with these rules that the checklist is no longer necessary.

1. Give all dimensions necessary to accurately communicate the design to manufacturing personnel, but only those dimensions necessary.
2. Apply dimensions in such a way that they cannot be misinterpreted.
3. Show dimensions between surfaces or points that have a functional relationship.



FIGURE 10-121 *Manufacturing precision.* (From Machinery's Handbook, 24th edition, © 1992 by Industrial Press Inc. Used with permission)

4. Do not dimension to or from rough surfaces. Always attempt to dimension from a finished surface.
5. Give complete dimensions, so that manufacturing personnel do not have to interrupt their work to calculate or otherwise determine a dimension they need.
6. Apply dimensions in the views where the shape of the part is shown most accurately.
7. Apply dimensions in those views where the part being dimensioned appears true size and true shape.
8. Do not dimension to hidden lines. If it becomes necessary to dimension to hidden lines, change the view to a sectional view.
9. Attempt to place dimensions that apply to two adjacent views between the views.
10. Avoid crossing extension lines with dimension lines.
11. Clearly dimension and annotate all features. Never expect manufacturing personnel to assume anything.
12. Do not apply a complete chain of detail dimensions. Omit the last one or indicate that the last dimension in the chain is a reference dimension.
13. Avoid placing dimensions on the part itself.
14. Always place dimension lines uniformly throughout the drawing.
15. Never use a line that constitutes a portion of the drawing of a part as a dimension line.
16. Avoid crossing dimension lines wherever possible.
17. Extension lines that cross other extension lines or object lines should not be broken.
18. A center line may be used as an extension line.
19. Center lines should not extend from view to view.
20. Leader lines should point to the center of a hole or circular feature.
21. Leader lines should be straight and broken at precise angles. They should never curve.
22. Leader lines should begin approximately at the center of a note height and extend either from the beginning or end of the note.
23. If it becomes necessary to letter within a section-lined area, erase enough of the section lines to leave a clear space so that the dimension can be easily read.
24. Fraction bars should be horizontal rather than angled.
25. The numerator and denominator of a fraction should not touch the horizontal fraction bar.
26. Finish marks should be applied on views in which the surface appears as an edge.
27. Finish marks are not necessary on parts made from rolled stock.
28. If a part is finished all over, finish marks are not used. Substitute the letters FAO or apply a note that says "Finish All Over."
29. Dimension a cylinder by showing the diameter and length on the rectangular view or by showing the diameter as a diagonal dimension in the circular view.
30. Always specify drill sizes in decimals.
31. A metric or decimal-inch diameter dimension should be preceded by the diameter symbol.
32. A metric or decimal-inch radius dimension should be preceded by a capital R.
33. Dimensions that are not to scale should be underlined with a straight line.
34. Decimal dimensioning is preferred for mechanical and manufacturing-related drawings.

Notation

A good drawing may be defined as one that contains all of the information required by the various design and manufacturing people who will use it in producing the subject part. Most of this information can be conveyed graphically, using standard dimensioning practices. However, it is not uncommon to encounter a situation in which all of the needed information cannot be communicated graphically. In these cases, notes are used to communicate or clarify the designer's intent.

Notes are brief, carefully worded statements placed on drawings to convey information not covered or not adequately explained using graphics, *Figure 10-122*. Notes should be clearly worded so as to allow only one correct interpretation.

There are no ANSI standards specifically governing the use of notes on technical drawings. However, several rules of a general nature should be observed. These rules apply to both general notes and the more specific detail notes.

Rules for Applying Notes on Drawings

Notes may be lettered freehand, entered using a keyboard in a computer-aided drafting (CAD) system, or added through any one of several mechanical lettering



FIGURE 10-122 *Notes on drawings improve communication.*

processes. Sample notes are included on the drawings in *Figures 10-123* and *10-124*. In any case, regardless of how they are put on the drawing, notes should be oriented horizontally on the drafting sheet, *Figure 10-125*. General notes should be located directly above the title block, *Figure 10-126* (page 415). When using manual processes to apply general notes such as those in Figure 10-126, the first note is placed directly above the title block, the second is placed on top of it, and so on up the line. This allows notes to be added as needed without renumbering. However, when using a CAD system, this is not necessary since one of the advantages of CAD is that notes can be renumbered and rearranged automatically. Detail notes should be located as close as possible to the detail they are describing and connected to it by a leader line, *Figure 10-127* (page 416).

Notes should be applied to drawings after all graphics have been completed. This prevents notes and graphics from overlapping and minimizes other technique problems such as smudging the worksheet and frequent erasing of notes as changes are required on a drawing.

Two basic types of notes are used on technical drawings: general notes and detail notes. They serve different purposes and, therefore, must be examined separately.



FIGURE 10-123 *Sample note lettered mechanically.*

General Notes

General notes are broad items of information that have a job- or project-wide application rather than relating to just one single element of a project or a part. They are usually placed immediately above the title block on the drawing sheet and numbered sequentially.

Information placed in general notes includes such characteristics of a product as finish specifications; standard sizes of fillets, rounds, and radii; heat treatment specifications; cleaning instructions; general tolerancing data; hardness testing instructions; and stamping specifications. *Figures 10-128* (page 417) and *10-129* (page 418) are examples of drawings containing general notes.

Detail Notes

Detail notes are specific notes that pertain to one particular element or characteristic of a part. They are placed as near as possible to the characteristic to which they apply and are connected using a leader line, *Figure 10-130* (page 419).

Detail notes should not be placed on views, *Figure 10-131* (page 419). The only exception to this rule is in cases where a great deal of open space exists on a view, but very little around it,



FIGURE 10-124 *Notes lettered on a CAD system.* (Courtesy Interactive Computer Systems Inc.)



FIGURE 10-125 *Notes are placed horizontally.*

Figure 10-132 (page 419). Notes should never be superimposed over other data such as dimensions, lines, or symbols, *Figure 10-133* (page 419).

Common sense is the best rule to follow in applying detail notes. Since detail notes are used to more completely communicate or to clarify intent, they should be placed as close as possible to the element to which they pertain and in such a way as to be easily read.

Writing Notes

The written word lends itself to interpretations that may vary. Thus, *written notes* used on drawings must convey the exact intent of the designer. Consequently, drafters must be especially careful in the preparation of notes.

The first step is to place in a legend all abbreviations used in the notes, *Figure 10-134* (page 419). This ensures that all readers of the notes interpret the abbreviations consistently and correctly.

Another technique that will limit misinterpretation of notes is punctuation or indentation. Notes containing more than one sentence should be properly punctuated so that readers know where one sentence leaves off and the next one begins, *Figure 10-135* (page 419). Indentation is used when the length of a note requires more than one line. The second line is indented so that readers know it is part of the first line, *Figure 10-136* (page 419).

Another technique is particularly useful for beginning drafters. It is called *verification*. Notes to be placed on drawings are first jotted down, legibly, on a print of the drawing. Another drafter, preferably one with experience, is then asked to read the notes to ensure that they are not open to multiple interpretations.

Note Specifications

A number of specifications should be observed when writing notes. The most widely accepted lettering style for notes is uppercase (all capital) block Gothic letters in a vertical format. Some companies accept uppercase block Gothic lettering in an inclined or slanted format. The proper lettering height is one-quarter inch for titles such as GENERAL NOTES, and one-eighth″ to three-sixteenths″ for actual notes, *Figure 10-137* (page 419).

Spacing between successive lines of the same note should be approximately one-sixteenth″. Spacing between separate notes should be approximately one-eighth″, *Figure 10-138* (page 419).

There are no hard and fast rules governing the length of a line of notation, but from four to six words per line is widely accepted, *Figure 10-139* (page 419). When a note string will contain more than six words, it should be divided into more than one line. The number of words in the multiple line note should be divided so as to balance the finished note. One long line followed by a drastically shorter line is bad form, *Figure 10-140* (page 420).

On occasion, the last word in a note string will have to be hyphenated. There are rules governing the dividing of words, according to syllables. If the proper point of division is not obvious from the makeup of the word, consult a dictionary. Do not hyphenate abbreviated words.

Sample Notes

The following is a list of sample notes of the types frequently used on technical drawings:

- All fillets and rounds R1/8
- 45° chamfer all edges
- Surfaces A & B parallel
- Stock .125 thick
- Heat treat
- All internal radii R.0625
- FAO
- Ream for 1/4 dowels
- All bends R5/32
- CBORE from bottom
- Identical bolts—both sides
- 3/32 × 1/16 oil groove
- 87 CSK 3/4 diameter—4 holes
- Rounds R.125 unless otherwise specified
- 4 holes equally spaced
- 1/32 × 45° chamfer
- #7 Drill .75 deep
- Machine steel—4 required
- Power brush all exterior surfaces
- Sandblast before painting



NOTES

1. ON NO.1 BUS 1200 AMP BKRS ARE 750 MVA, 58 KA & 3000 AMP BKRS ARE 1000 MVA, 77 KA. ON P.P. BUS BKR N1 IS 750 MVA, 58 KA & BKR PP2-2 IS 750 MVA, 77 KA. ON NO.2 BUS ALL BKRS ARE 750 MVA, 77 KA.
2. IF Q1 & APCO ARE PARALLEL 32X TRIPS N2 THROUGH TIMER 62 IN 1.8 SECS.
3. RELAYS 86 Q1, 86 Q2 & 86 B2 EACH ARE 2 RELAYS IN PARALLEL (2ND NOT SHOWN).
4. BKR N16 EXISTS (TO BE RELOCATED FROM N2 LOCATION). CONTRACTOR TO ADD SIN RELAY & TO FURNISH & INSTALL PLATES OVER CUTOUTS NOT USED. DISCONNECT EXISTING LIGHTING ARRESTORS.
5. CONTRACTOR TO ADD 1 C.T. & RECONNECT TO 87B CKT.
6. CONTRACTOR TO ADD AUX. C.T.'S (A.C.T.) - 2 IN N3, & 1 IN N2.
7. CONTRACTOR TO ADD NEUTRAL C.T. IN GEN.1.
8. CONTRACTOR TO ADD AUX. C.T. (A.C.T.) & 87GD RELAY IN N4.
9. 2000 AMP BKR SPARES ONLY THE 2000 AMP BKR ON P.P. BUS & ALL BKRS ON NO.2 BUS.
10. —×—×—×— WIRE TO BE DISCONNECTED.
    —ADD— WIRE TO BE ADDED.
11. CONTRACTOR TO ADD TO NO.1 SWBD. RUN VM, INC.VM. & BUS1 V.S. WITH VM.
12. CONTRACTOR TO RELOCATE LTC CONTROLS FROM APCO SUB.

NO.	DATE	REVISIONS	BY	APP.

DRAWN BY	DATE	SUBMITTED BY	DATE
CHECKED BY	DATE	APPROVED BY	DATE
SUPERVISED BY	DATE	APPROVED BY	DATE

THIS DRAWING BY
THE RUST ENGINEERING COMPANY
BIRMINGHAM ALABAMA

RELEASED FOR APPROVAL
ISSUE NO.
BY _____ DATE _____

RELEASED FOR CONSTRUCTION
BY _____ DATE _____

DRAWING TITLE
13.8 KV POWER DISTRIBUTION
NO.1 & NO.2 BUS
RELAY & METER SINGLE LINE

SCALE: NONE
FILE:
DRAWING NO.
REV. 0

CD0868

FIGURE 10-126 *General notes are located over the title block.* (Courtesy the Rust Engineering Co.)



FIGURE 10-127 *Detail notes using leader lines.* (Courtesy Fruehauf Division, Fruehauf Corp)



GENERAL PIPING NOTES

A. THESE GENERAL NOTES APPLY TO ALL P & I DIAGRAMS IN THIS AREA.

B. FOR PIPING LEGEND SEE DWG. 05-6-4400-E AND 05-6-4401-E.

C. ALL PIPING SYSTEMS SHALL BE IN ACCORDANCE WITH SPECIFICATION 1840/00 AND ALL ATTACHMENTS CONTAINED THERE IN.

D. INSULATION SHALL BE IN ACCORDANCE WITH SPECIFICATION 1841/01.

NO.	DATE	REVISIONS	BY	APP.

DRAWN BY A.D.D.	DATE 05/15/81	SUBMITTED BY	DATE
CHECKED BY	DATE	APPROVED BY	DATE
SUPERVISED BY	DATE	APPROVED BY	DATE

THIS DRAWING BY
THE RUST ENGINEERING COMPANY
BIRMINGHAM ALABAMA
CONTRACT 21-

RELEASED FOR APPROVAL
ISSUE NO.
BY DATE

RELEASED FOR CONSTRUCTION
BY DATE

DRAWING TITLE
G.L.S.C. EVAPORATORS & CONCENTRATORS
P & I DIAGRAM
EVAPORATOR CONCENTRATORS 1 & 2

SCALE: NO SCALE	DRAWING NO.	REV.
FILE:		0

FIGURE 10-128 *General notes on drawings.* (Courtesy The Rust Engineering Co.)



FIGURE 10-129 *General notes on drawings.* (Courtesy General Railway Signal Corp.)



FIGURE 10-130 *Detail note connected with a leader line.*



FIGURE 10-131 *Poor placement of a detail note.*



FIGURE 10-132 *Acceptable placement of a detail note when there is space.*



NOTE: *DO NOT DIMENSION TO HIDDEN LINES OR CENTER LINES OF HIDDEN LINES*

FIGURE 10-133 *Superimposing a note is poor practice.*

LEGEND

1. ASSY = ASSEMBLY
2. FAO = FINISH ALL OVER
3. MS = MACHINE STEEL
4. FAB = FABRICATE
5. CARB = CARBURIZE
6. DVTL = DOVETAIL
7. HT TR = HEAT TREAT
8. KST = KEYSEAT
9. TPR = TAPER
10. SF = SPOTFACED

FIGURE 10-134 *Abbreviations are explained in a legend.*

NOTE

POWER BRUSH ALL SURFACES. APPLY THREE COATS PAINT. STAMP PART WITH NUMBER 01929612.

FIGURE 10-135 *Proper punctuation of notes is important.*

NOTE

ALL DIMENSIONS AND CONDITIONS SHALL BE FIELD CHECKED AND VERIFIED BY PROPER TRADES

FIGURE 10-136 *Indenting for clarity.*

GENERAL NOTES ← LETTERS .25 HIGH

ALL FILLETS AND ROUNDS .125 DIA. ← LETTERS .125–.1875 HIGH
ALL SURFACES MUST BE FREE OF BURRS. ←

FIGURE 10-137 *Proper lettering height is important.*

NOTES

1. SPACING BETWEEN LINES OF THE SAME NOTE SHOULD BE .Ø625.
2. SPACING BETWEEN SEPARATE NOTES SHOULD BE .125Ø.

FIGURE 10-138 *Spacing of notes.*

NOTES

NOTES SHOULD BE LIMITED TO
4 TO 6 WORDS PER LINE

FOUR TO SIX WORDS

FIGURE 10-139 *Number of words per line limitations are important.*

NOTES

AVOID LONG LINE IN A NOTE FOLLOWED BY
ONE SHORT LINE

FIGURE 10-140 *Lines in notes should be approximately equal.*

Notice that these sample notes are very brief, concise, and to the point. Words such as "a," "an," "the," and "are" are used only sparingly. The notes are not always complete sentences in terms of proper grammar, but they are complete thoughts in terms of communication. Notice also the use of abbreviations such as FAO (finish all over), CBORE (counterbore), and CSK (countersink). Abbreviations can be used frequently to cut down on the length of notes and the time required to letter them. However, when used, abbreviations should always be placed in a legend to ensure consistency of interpretation.

Group Technology

Group technology is a manufacturing concept in which similar parts are grouped together in parts groups or families. Parts may be alike in two ways:

1. In their design characteristics
2. In the manufacturing processes required to produce them

By grouping similar parts into families, manufacturing personnel can improve efficiency. Such improvements are the result of advantages gained in such areas as setup time, standardization of processes, and scheduling.

Group technology can also improve the productivity of design personnel by decreasing the amount of work and time involved in designing a new part. Chances are a new part will be similar to an existing part in a given family. When this is the case, the new part can be developed by simply modifying the design of the existing part. Design modifications tend to require less time and work than new design. This is especially true in the age of CAD. The advantages of group technology are dealt with at greater length later in this chapter.

Historical Development

Ever since the Industrial Revolution, manufacturing and engineering personnel have been searching for ways to optimize manufacturing processes. There have been numerous developments over the years since the Industrial Revolution mechanized production. Mass production and interchangeability of parts in the 1800s were major steps forward in optimizing manufacturing.

However, even with mass production and assembly lines, most manufacturing is done in small batches ranging from one workpiece to two or three thousand. In fact, even today over 70 percent of manufacturing involves batches of less than three thousand workpieces. Historically, less has been done to optimize small-batch production than has been done for assembly line work.

There have been attempts to standardize a variety of design tasks and some working queuing and sequencing in manufacturing, but until recent years design and manufacturing in small-batch settings has been somewhat random.

The underlying problem that has historically prevented significant improvements to small-batch manufacturing is that any solution must apply broadly to general production processes and principles rather than to a specific product. This is a difficult problem because the various workpieces in a small batch can be so random and different.

When manufacturing entered the age of automation and computerization, such developments as scheduling software, sequencing software, and materials requirements planning (MRP) systems became available to improve the production of both small and large batches. Even these developments have not optimized the production of small batch manufacturing lots. The problem has become even more critical because, since the end of World War II, the trend has been toward smaller batches.

In recent years the problems of small-batch production have finally begun to receive the attention necessary to bring about improvements. A major step is the ongoing development of group technology.

Part Families

It has already been stated that parts may be similar in design (size and shape) and/or in the manufacturing processes used to produce them. A group of such parts is called a *part family*. It is possible for parts in the same family to be very similar in design yet radically different in the area of production requirements. The opposite may also be true.

Figure 10-141 contains examples of two parts from the same family. These parts were placed in the same family based on design characteristics. They have exactly the same shape and size. However, you will notice that they differ in the area of production processes.

Part 1, after it is drilled, will go to a painting station for two coats of primer. Its dimensions must be held to a tolerance of plus or minus .125 inch. Part 2, after it is drilled, will go to a finishing station for sanding and buffing. Its dimensions require more



FIGURE 10-141 *Two parts from the same family.*

restrictive tolerances of plus or minus .003 inch. The parts differ in material. The material for Part 1 is cold-rolled steel; Part 2 is aluminum.

Figure 10-141 contains examples of two parts from the same family. Although the design characteristics of these two parts are drastically different (i.e., different sizes and shapes), a close examination will reveal that they are similar in the area of production processes. Part 1 is made of stainless steel. Its dimensions must be held to a tolerance of plus or minus .002″, and three holes must be drilled through it. Part 2, in spite of the differences in its size and shape, has exactly the same manufacturing characteristics.

The parts shown in Figure 10-141, because of their similar design characteristics, were grouped in the same family. Such a family is referred to as a design part family. Those in ***Figure 10-142*** were grouped together because of similar manufacturing characteristics. Such a family is referred to as a *manufacturing part family.* The characteristics used in classifying parts are referred to as attributes.

By grouping parts into families, manufacturing personnel can cut down significantly on the amount of materials handled and movement wasted in producing them. This is because manufacturing machines can be correspondingly grouped into specialized work cells instead of the traditional arrangement of machines according to function (i.e., mills together, lathes together, drills together, etc.).

Each work can be specially configured to produce a given family of parts. When this is done, the number of setups, the amount of materials handling, the length of lead time, and the amount of in-process inventory are all reduced.



FIGURE 10-142 *Two parts from the same family.*

Grouping Parts into Families

Part grouping is not as simple a process as one might think. You already know the criteria used: design similarities and manufacturing similarities. But how does the actual grouping take place?

There are three methods that can be used for grouping parts into families, ***Figure 10-143.***

1. Sight inspection
2. Route sheet inspection
3. Parts classification and coding

All three methods require the expertise of experienced manufacturing personnel.

Sight inspection is the simplest, least sophisticated method. It involves looking at parts, photos of parts, or drawings of parts. Through such an examination, experienced personnel can identify similar characteristics and group the parts accordingly. This is the easiest approach, especially for grouping parts by design attributes, but it is also the least accurate of the three methods.

The second method involves inspecting the routing sheets used to route the parts through the various operations to be performed. This can be an effective way to group parts into manufacturing part families, provided the routing sheets are correct. If they are, this method is more accurate than the sign inspection approach. This method is sometimes referred to as the PFA or production flow analysis method.



FIGURE 10-143 *Methods of grouping parts into families.*



FIGURE 10-144 *Parts classification and coding groups.*

The most widely used method for grouping parts is the third method: parts classification and coding. This is also the most sophisticated, most difficult, and most time-consuming method. Parts classification and coding is complex enough to require a more in-depth treatment than the other two methods.

Parts Classification and Coding

Parts classification and coding is a method in which the various design and/or manufacturing characteristics of a part are identified, listed, and assigned a code number. Recall that these characteristics are referred to as *attributes*. This is a general approach used in classifying and coding parts. There are many different systems that have been developed for actually carrying out the process, none of which has emerged as the standard.

The many different classification and coding systems that have been developed all fall into one of three groups, ***Figure 10-144.***

1. Design attribute group
2. Manufacturing attribute group
3. Combined attribute group Students of CAD/CAM should be familiar with how systems are grouped.

DESIGN ATTRIBUTE GROUP

Classification and coding systems that use design attributes as the qualifying criteria fall into this group. Commonly used design attributes include dimensions, tolerances, shape, finish, and material.

MANUFACTURING ATTRIBUTE GROUP

Classification and coding systems that use manufacturing attributes as the qualifying criteria fall into this group. Commonly used manufacturing attributes include production processes, operational sequence, production time, tools required, fixtures required, and batch size.

COMBINED ATTRIBUTE GROUP

There are advantages in using design attributes and advantages in using manufacturing attributes. Systems that fall into the design attribute group are particularly advantageous if the goal is design retrieval. Those in the manufacturing group are better if the goal is any of a number of production-related functions. However, there is a need for systems that combine the best characteristics of both. Such systems are both design and manufacturing attributes.

SAMPLE PARTS CLASSIFICATION AND CODING SYSTEM

Some companies develop their own parts classification and coding systems. But this can be an expensive and time-consuming approach. The more widely used approach is to purchase a commercially prepared system. There are several such systems available. However, the most widely used of these is the Opitz system. It is a good example of a parts classification and coding system and how one works.

Opitz System

Classification and coding systems use alphanumeric symbols to represent the various attributes of a part. One of the many classification and coding systems is the Opitz system. This system uses characters in 13 places to code the attributes of parts, and hence, to classify them. These digit places are represented as follows:

12345 6789 ABCD

The first five digits (12345) code the major design attributes of a part. The next four digits (6789) are for coding manufacturing-related attributes and are called the supplementary code. The letters (ABCD) code the production operation and sequence.

The alphanumeric characters shown represent places. For example, the actual numeral used in each place can be 0–9. The numeral used in the 1 place indicates the length-to-diameter ratio of the part. The numeral used in the 2 place indicates the external shape of the part. The numeral used in the 3 place indicates the internal shape of the part. The numeral used in the 4 place indicates the type of surface machining. The numeral used in the 5 place indicates gear teeth and auxiliary holes. With such a system, a part might be coded as follows:

20801

The 2 means that the part has a certain length-to-diameter ratio. The first 0 means the part has no external shape elements. The 8 means the part has an internal thread. The second 0 means no surface machining is required. The 1 means the part is axial, not on pitch.

Figure 10-145 is a chart that shows the basic overall structure of the Opitz system for parts classification and coding. *Figure 10-146* is a chart used for assigning an Opitz code to rotational parts. *Figure 10-147* is a drawing of an actual part that has been assigned an Opitz code of 15400. This code was arrived at as follows:

STEP 1 The total length of the part is divided by the overall diameter:

$$\frac{1.75(L)}{1.25(D)} = 1.40$$

Since 1.40 is greater than .5 but less than 3, the first digit in the code is 1.

STEP 2 An overall description of the external shape of the part would read ". . . a rotational part that is stepped on both ends with one stepped end threaded." Consequently, the most appropriate second digit in the code is 5.

STEP 3 A description of the internal shape of the part would read ". . . a through hole." Consequently, the third digit in the code is 4.

STEP 4 Upon examination, it can be seen that no surface machining is required. Therefore, the fourth digit in the code is 0.

STEP 5 It can also be seen that no auxiliary holes or gear teeth are required. Therefore, the fifth digit in the code is also 0.



FIGURE 10-145 *Basic structure of the Opitz system.*

	PART CLASS	MAIN SHAPE EXTERNAL	ROTATIONAL MACHINING INTERNAL	PLANE SURFACE MACHINING	ADDITIONAL HOLES AND TEETH
	L/D<0.5	Smooth, no shape elements	No hole, no breakthrough	No surface machining	No auxiliary hole
1	0.5<L/D<3	Stepped to one end or smooth: No shape elements	Smooth or stepped to one end: No shape elements	Surface plane and/or curved in one direction, external	Axial, not on pitch circle diameter
2	L/D≤3	Stepped to one end or smooth: Thread	Smooth or stepped to one end: Thread	External plane surface related by graduation around a circle	Axial on pitch circle diameter
3	—	Stepped to one end or smooth: Functional groove	Smooth or stepped to one end: Functional groove	External groove and/or slot	Radial, not on pitch circle diameter
4	—	Stepped to both ends: No shape elements	Stepped to both ends: No shape elements	External spline (polygon)	Axial and/or radial and/or other direction
5	—	Stepped to both ends: Thread	Stepped to both ends: Thread	External plane surface and/or slot, external spline	Axial and/or radial on PCD and/or other directions
6	—	Stepped to both ends: Functional groove	Stepped to both ends: Functional groove	Internal plane surface and/or slot	Spur gear teeth
7	—	Functional cone	Functional cone	Internal spline (polygon)	Bevel gear teeth
8	—	Operating thread	Operating thread	Internal and external polygon, groove and/or slot	Other gear teeth
	First Digit	Second Digit	Third Digit	Fourth Digit	Fifth Digit

Rotational ↕ Non-Rotational

No gear teeth

With gear teeth

FIGURE 10-146 *Assigning a code using the Opitz system.*



FIGURE 10-147 *Sample part that can be coded using the Opitz system.*

Advantages and Disadvantages of Group Technology

There are several advantages that can be realized through the application of group technology. These advantages include:

1. Improved design
2. Enhanced standardization
3. Reduced materials handling
4. Simplified production scheduling
5. Improved quality control

Improved Design

Group technology allows designers to use their time more efficiently and productively by decreasing the amount of new design work required each time a part is to be designed. When a new part is needed, its various attributes can be listed. Then, an existing part with as many of these attributes as possible can be identified and retrieved. The only new design required is that which relates to attributes of the new part not contained in the existing part. Because this characteristic of group technology tends to promote design standardization, additional design benefits accrue.

Enhanced Standardization

Parts are classified into groups according to their similarities. The more similarities, the better. Consequently, enhanced standardization is promoted by

Industry Application

GROUP TECHNOLOGY AND GLOBAL COMPETITION

"We need to adopt the group technology concept," said Juan Martinez. Martinez is the chief designer for Magna-Tech Manufacturing, a leading producer of metal components used in the manufacture of automobiles.

In recent years Magna-Tech's competition has become both global and fierce. In order to survive and prosper, the company needs to optimize the performance of every employee and every process from design and drafting to manufacturing.

As the design and drafting department's representative on the company's management team, Martinez is expected to propose strategies for cutting costs and improving productivity, and he is expected to propose strategies to help Magna-Tech become more competitive on a continual basis. The company's CEO has made it clear to all of his managers that he is looking for strategies that will give Magna-Tech a sustainable competitive advantage in the global marketplace. This is why Juan Martinez scheduled the current departmental meeting. He needs input from his design and drafting personnel.

"I want us to brainstorm this morning," said Martinez. "Before the next manager's meeting, I need a list of benefits our company can gain by adopting group technology." "The first benefit is that group technology will cut down on the amount of time needed to design a part," said Margaret Flagstone. "Right now we practically start over every time we have a new part we have already designed. With group technology we could place the new part in a part family. Once we know what family it fits in, much of the design is already done." "Excellent point," said Martinez. "I'll tell you what we might do. What if I write four or five benefits on the flip chart and see if you agree with them? Then when we have our top five benefits we can divide ourselves into five small groups and explore each benefit in depth. I'd like to have some concrete examples to offer at the manager's meeting." With that, Martinez began writing benefits on a flip chart.

group technology. As you have already seen, design factors account for part of the enhanced standardization. Setups and tooling also become more standardized because similar parts require similar setups and similar tooling.

Reduced Materials Handling

One of the major elements of group technology is the arrangement of machines into specialized work cells, each cell producing a given family of parts. Traditionally, machines are arranged by function (i.e., lathes together in one group, mills together in another, etc.). A functional arrangement causes excessive movement of parts from machine to machine and back. Specialized work cells reduce such movement to a minimum and, in turn, reduce materials handling.

Simplified Production Scheduling

With machines grouped into specialized work cells and arrangement of parts into families, there is less work center scheduling requiring less scheduling overall. Group technology involves less sophisticated scheduling.

Improved Quality Control

Quality control is improved through group technology because each work cell is responsible for a specific family of parts. This does two things, both of which tend to improve the quality of parts: (1) it promotes pride in the work among employees assigned to each work cell, and (2) it makes production errors and problems easier to trace to a specific source. In traditional manufacturing shops, each work center performs certain tasks, but no one center is responsible for an entire part. Such an approach does not promote quality control.

In spite of these advantages, there are several disadvantages associated with group technology. Transitioning from machines in a traditional shop into specialized work cells can cause a major disruption. Such disruptions translate quickly into monetary losses. As a consequence, some managers are reluctant to pursue group technology.

Another problem with group technology is that parts classification coding is a time-consuming, difficult, and expensive process, especially in the initial stages. This causes some managers to balk at the expense.

Summary

- The three dimensioning systems used on technical drawings in the United States are the metric, decimal-inch, and fractional. In all of these systems, dimensions are oriented to be read from the bottom or right-hand side of the drawing sheet.
- The components that are common to all dimensioning systems are extension lines, dimension lines, arrowheads, leader lines, and dimensions.
- The four steps in laying out dimensions are as follows: (1) place eight layout lines on the drawing sheet; (2) lightly draw in guidelines for the dimensions; (3) darken the extension lines and dimension lines and add dimensions; and (4) add arrowheads.
- Tolerancing-related concepts with which students should be familiar are actual size allowance, bilateral tolerance, datum, least material condition, limits, maximum material condition, nominal dimension, tolerance, unilateral tolerance, fit, clearance fit, interference fit, and transition fit.
- Not all information needed to convey a design can be given graphically. In such cases, notes are used to provide the additional information. Notes are brief, carefully worded statements placed on drawings to convey information not adequately explained graphically.
- Group technology is a manufacturing concept in which similar parts are grouped together in parts families. Such parts may be alike in two ways: (1) in their design characteristics and (2) in the manufacturing processes required to produce them. Advantages of group technology include improved design, enhanced standardization, reduced materials handling, simplified production scheduling, and improved quality control.

Review Questions

Answer the following questions either true or false.

1. The most frequently used dimensioning standard is fractional dimensioning.
2. The proper way to indicate on a drawing that a dimension is NTS is to put a wavy line under the dimension.
3. An extension line should extend beyond the dimension line approximately 1/8″.
4. The key word to remember when making arrowheads, regardless of the size, is "uniform."
5. Unidirectional dimensioning is aligning all dimensions with the dimension line.
6. Notes are brief, carefully worded statements placed on drawings to convey information not covered in the graphic.
7. Notes should be oriented on a drafting sheet horizontally.
8. The term *verification* as it relates to notes is printing a list of your notes and asking an experienced drafter to ensure that they are not open to multiple interpretations.
9. Group technology is a concept by which similar parts are grouped together in part groups or families.
10. Attributes are characteristics used to group parts.
11. General notes are specific and pertain to a particular element or characteristic of a part.
12. The proper height for lettering note titles is 1/4″.
13. Parts are grouped into families by their design characteristics or the manufacturing process required to produce them.

Answer the following questions by selecting the best answer.

1. Of the dimensioning systems used, which one is most frequently used on mechanical technical drawings?
   a. Metric dimensioning
   b. Decimal-inch dimensioning
   c. Fractional dimensioning
   d. Proportional dimensioning
2. Which is the correct rule when labeling for a metric dimension that is less than one millimeter?
   a. A decimal is not required
   b. Neither a zero nor a decimal is required
   c. Place a zero to the right of the decimal
   d. None of the above
3. Which is the correct way to show the line separating the numerator and denominator of a fraction?
   a. /
   b. —
   c. \
   d. All of the above
4. Which is not a component of all dimensioning systems?
   a. Arrowheads
   b. Extension lines
   c. Leader lines
   d. Orientation lines
5. The recommended length/width ratio of arrowheads is that they are:
   a. Twice as long as they are wide.
   b. Three times as long as they are wide.
   c. Twice as wide as they are long.
   d. Three times as wide as they are long.

6. Which is the proper location for general notes?
   a. In the lower left-hand corner
   b. In the upper left-hand corner
   c. Above the title block
   d. Below the title block

7. Which of the following is not true regarding notation?
   a. The number of words in a multiple-line note should be divided to balance the finished note.
   b. Four to six words per line is widely accepted.
   c. There are hard and fast rules regarding notation.
   d. Hyphenation, by syllables, is accepted.

8. Which of the following is **not** a method for grouping parts into families?
   a. Size and shape
   b. Sight inspection
   c. Route sheet inspection
   d. Parts classification and coding

9. Which of the following is **not** a commonly applied design attribute?
   a. Dimensions
   b. Weight
   c. Tolerances
   d. Shape

10. Which of the following is **not** a commonly applied manufacturing attribute?
    a. Production processes
    b. Operation sequence
    c. Sight inspection
    d. Tools required

11. Which of the following is **not** an advantage of group technology?
    a. Improved design
    b. Reduced materials handling
    c. Easier parts classification coding
    d. Simplified production scheduling

Chapter 10 Problems

The following problems are intended to give beginning drafters and engineers practice in applying the various dimensioning techniques required on technical drawings in industry. Students should follow the general instructions that apply to all problems, and any additional instructions provided for special problems. All problems should be dimensioned in strict accordance with the rules set forth in this chapter.

General Instructions

1. Study each problem carefully.
2. Make a complete sketch of the problem, applying all dimensions on the sketch. Note on the sketch the proper spacing between views, between the object and first dimension lines, and between successive dimension lines.
3. Compare your fully dimensioned sketch against all applicable sections of this chapter and "The Summary of Dimensioning Rules."

NOTE: These instructions do not apply to Problems 10-47 through 10-50.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

Problems 10-1 through 10-24

1. Use the grid to determine all dimensions.
2. Redraw the views shown, and fully dimension your drawing.

PROBLEM 10-1

























PROBLEM 10-2



PROBLEM 10-3


Ⓐ


Ⓑ


Ⓒ


Ⓓ


Ⓔ


Ⓕ


Ⓖ


Ⓗ


Ⓘ


Ⓙ


Ⓚ


Ⓛ

PROBLEM 10-4



PROBLEM 10-5



PROBLEM 10-6



PROBLEM 10-7



PROBLEM 10-8



PROBLEM 10-9



PROBLEM 10-10



PROBLEM 10-11



PROBLEM 10-12



PROBLEM 10-13



PROBLEM 10-14



PROBLEM 10-15



PROBLEM 10-16



PROBLEM 10-17



PROBLEM 10-18



PROBLEM 10-19



PROBLEM 10-20



PROBLEM 10-21



PROBLEM 10-22



PROBLEM 10-23



PROBLEM 10-24



Problems 10-25 through 10-46

1. Convert the isometric drawings provided into orthographic drawings, showing as many views and/or sections as necessary to communicate the design.
2. Fully dimension your drawing.

PROBLEM 10-25



PROBLEM 10-26



PROBLEM 10-27



PROBLEM 10-28



ALL UNMARKED RADII = R.09

PROBLEM 10-29



PROBLEM 10-30



PROBLEM 10-31



PROBLEM 10-32



PROBLEM 10-33



PROBLEM 10-34



PROBLEM 10-35



PROBLEM 10-36



PROBLEM 10-37



Problems

PROBLEM 10-38



NOTE: CYLINDER IS CENTERED ON THE BASE

PROBLEM 10-39



PROBLEM 10-40



ALL UNMARKED RADII = R.06

PROBLEM 10-41



PROBLEM 10-42



PROBLEM 10-43



PROBLEM 10-44



PROBLEM 10-45



PROBLEM 10-46



PROBLEM 10-47

Convert Problem 10-47 into a tabular drawing.



PROBLEM 10-48

Convert Problem 10-48 into a standard coordinate dimensioning system drawing.



MATERIAL: STEEL .12 THICK

HOLE	SIZE
A	.500
B	.218/.220
C	.188
D	.320
E	.375/.380
F	.510/.512
G	2.562/2.565
H	.120
I	.750/.752

PROBLEM 10-49

Convert Problem 10-49 into a tabular drawing.



PROBLEM 10-50

Draw parts AO608-5 and AO608-8 full size.



A0608-8	4.12	3.12	3.50	.50	3.00	.75	1.50	2.00	2	.50
A0608-7	3.38	1.75	2.50	.62	2.50	.50	–	–	–	–
A0608-6	3.50	1.50	2.50	.44	1.50	.50	1.00	.38	–	–
A0608-5	4.10	1.12	2.62	.25	1.25	.38	.75	.50	6	38
A0608-4	5.25	3.12	4.00	.75	2.25	1.00	2.12	.75	8	.62
A0608-3	3.25	1.50	2.38	.44	1.50	.50	1.00	.38	–	–
A0608-2	4.00	3.00	3.50	.62	1.00	.75	1.50	.62	3	.50
A0608-1	3.38	1.75	2.50	.50	2.00	.62	1.12	.25	4	.31
PART NO.	A	B	C	D	E	F	G	H	I	J

PROBLEMS 10-51 AND 10-52

Carefully fill in all blank lines.

PROBLEM 10-51



1 _____ NOMINAL SIZE
2 _____ MMC OF HOLE
3 _____ MMC OF SHAFT
4 _____ ALLOWANCE
5 _____ CLEARANCE
6 _____ NOMINAL SIZE
7 _____ MMC OF HOLE
8 _____ MMC OF SHAFT
9 _____ ALLOWANCE
10 _____ CLEARANCE



11 _____ NOMINAL SIZE
12 _____ MMC OF SLOT
13 _____ MMC OF KEY
14 _____ ALLOWANCE
15 _____ CLEARANCE
16 _____ NOMINAL SIZE
17 _____ MMC OF SLOT
18 _____ MMC OF KEY
19 _____ ALLOWANCE
20 _____ CLEARANCE

PROBLEM 10-52

PROB		NOM SIZE	BASIC SIZE	DIMENSION OF HOLE	DIMENSION OF SHAFT	HOLE TOLERANCE	SHAFT TOLERANCE	ALLOWANCE	CLEARANCE
INCH	1			.625 / .630	—		.005	+.002	
	2	1.25		—	—	.001	.002	+.001	
	3			.312 / .314	.316 / .314				
	4	.75		—	—	.003	.002	+.001	
	5			.812 / .813	.815 / .814				
METRIC	6			22.2 / 22.3	22.5 / 22.4				
	7	20		—	—	0.4	0.3	+0.2	
	8			9.6 / 9.4	9.8 / 9.4				
	9	30		—	—	0.2	0.4	+0.2	
	10			15.6 / 15.4	—		0.6	+0.4	

PROBLEM 10-53

Refer to the mounting guide drawing, No. 392450, and answer the following questions:

1. What is dimension A?
2. What tolerance is expected for two-place dimensions?
3. What are the dimension limits (maximum and minimum) of dimension B?
4. What size tap hole is specified for the 5/8 threaded hole?
5. What thread series is indicated for the 5/8 threaded hole?
6. When was the drawing last revised?
7. What are the dimension limits (maximum and minimum) of dimension C?
8. What is the maximum dimension of F?
9. For one assembly of the mounting guide, two stud bolts that are supposed to go through the two holes D are found to be spaced too far apart. The two stud bolts have a center-to-center distance of 1.625″ and are .373″ in diameter. The .422″ D holes are 1.563″ apart. One remedy for this type of problem is to enlarge the mating holes. Therefore, what is the minimum diameter for the two holes D that would permit the assembly?



11

Solid/3D Modeling: Computational Design and Analysis

CHAPTER OUTLINE

Factors in using visualization • Understanding data • Modeling techniques • Types of visualization images • Methods of representing variables • Relationships • Engineering visualization applications • Case studies • Summary • Review questions

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the advantages and disadvantages of using visualization.
- Describe the most widely used three-dimensional imaging techniques.
- Explain the various methods used to represent variables.
- Explain the various categories of engineering visualization.

KEY TERMS

Boolean operators
Computational fluid dynamics (CFD)
Finite-element analysis (FEA)
Finite-element model (FEM)
Gouraud
Holography
Modeling
Parametric solid modeling
Phong
Photorealism
Radiosity
Ray tracing
Rendering
Solid modeling
Texture mapping
Thermal analysis
Virtual reality
Visualization

Visualization is the pictorial representation of data for the purpose of a more clear and concise communication of information, ***Figure 11-1.*** The computer has made it possible to create pictorial representations of data that were virtually impossible with previous graphics techniques. The purpose of this chapter is to define and describe existing and emerging techniques for creating and analyzing data by means of computer-generated visualization. The old saying that a picture is worth a thousand words has never been more true. Today, however, the saying is more appropriately stated as: "A picture is worth 786,432 (1,024 × 768) pixels."

Visualization falls roughly into two categories. In some cases, visualization is used as an interactive design tool. An example of this is in mechanical CAD, where a clear image makes the design process easier. In other cases, visualization is used to represent complex data in a way that makes it easier to understand.

One example of representing complex data is in analyzing satellite telemetry, such as that sent by the Voyager and Explorer space missions. ***Figure 11-2*** illustrates a composite of true-color and filtered images of Jupiter that have been extracted from an animation of the planet rotating on its axis. These images represent digital data transmitted by the Voyager satellites used to render a three-dimensional model that was then animated to rotate on the planet's axis. The ability to view side-by-side animations of the real and filtered images greatly improved research on cloud composition compared with the previous method of viewing individual static images of small portions of the planet.

Increasingly complex engineering problems generate corresponding increases in the amount of information produced. The improvements in products



FIGURE 11-2 *Jupiter: True-color and spectral classification image.* (Courtesy Planetary Arts and Sciences)

made possible by more accurate data justify the large amounts of data to be utilized. In many cases the amount of data to be analyzed is so great that it is almost impossible to comprehend it in numerical form. The extremely large amount of data is one of the major reasons for utilizing visualization techniques. Stacks of printouts consisting of numerical data are frequently impossible to comprehend without the benefit of visualization.

Factors in Using Visualization

Several factors are leading to the increased use of visualization techniques and output:

- More complex engineering problems are generating increasingly large amounts of information.
- Increased computational speed makes it possible to perform visualization tasks on workstations and

FIGURE 11-1 *Harrier jet.* (Courtesy NASA)

personal computers instead of being limited to supercomputers.

- Increasing performance/price ratio makes visualization hardware and software affordable for more people and companies.
- Improved user interfaces make the operation of systems and the production of visualization output easier to perform. Rather than being so complex and unique that only a specialist can use a system to create visualization output, it has become increasingly easier for greater numbers of people to productively utilize visualization technology and techniques.

Even with tremendous improvements in performance and ease of use, major barriers to the adoption of visualization techniques still exist. Among the more critical factors are the following:

- In some cases, the complexity of visualization techniques and technology continue to make it difficult to learn and use. This is less true than it has been in the past, but it still takes substantial effort and training to produce high-quality visualization output.
- Visualization generally involves three-dimensional data. This represents a major increase in complexity from two-dimensional data and requires a solid understanding of three-dimensional information.
- An unlimited number of ways to represent any given data set presents complex choices. The decision of how to represent the data is subjective. Frequently, no standard rules exist to govern selection.

Understanding Data

Throughout this chapter, you will see a number of examples of powerful visualization techniques, from mechanical CAD to NASA satellite data, to digitized biomedical data. In all cases, these examples use underlying 3D data. The difference among them is how the 3D data is obtained. In some cases, the 3D data is the product of complex calculations and is generated to represent something that would not be visible otherwise. In other cases, the data is the direct result of a designer creating a 3D model. The same data used for visualization can be used to create the tools to make a product.

Modeling Techniques

Modeling is the term used to describe the process of creating data that represents a real-world engineering problem. The term is used rather pervasively in a number of disciplines, so you should be comfortable with it. In art, the process of creating a sculpture is called modeling. In market research, the process of building data that represents how a demographic group responds is called modeling. And in CAD, the process of creating a 2D or 3D data set that represents a real object or system is likewise called modeling. In the case of 3D CAD, the process used to create the model limits the visualization techniques that can be used to represent it. The most primitive modeling technique is 3D wireframe. In this method, the geometry of 3D surfaces is represented, but the actual topology of those surfaces is not applied. (You can think of geometry as the edges and topology as the skins.) ***Figures 11-3A*** and ***11-3B*** show a cube-like shape, represented both with and without topology. Without topology, there is no way to know which side the hole through the middle goes through.



(A)



(B)

FIGURE 11-3 *(A) Ambiguous wireframe cube shape; (B) non-ambiguous shaded cube shape.* (Courtesy The Yares Organization)

Several years back, 3D wireframe modeling was more accepted because it required less in the way of software, hardware, and training. Today, CAD software and computers are powerful enough that there is no justification for using 3D wireframe modeling. The next logical step from 3D wireframe is surface modeling. In this method, skins are applied to the edges of surfaces. This modeling method has been popular for many years in the aerospace and automotive industries, as it can represent complex objects with great precision. It has a further advantage over 3D wireframe in that, because the surface topology is known, the computer can calculate which lines or edges will be obscured in any particular view. This is known as a hidden-line calculation, *Figure 11-4*. It is actually a computationally intense process (particularly with complex or wavy surfaces), but the result is a pleasing image.

Surface modeling, *Figure 11-5*, is powerful, but it creates problems during the editing process. Changes made to one surface propagate to others—it's rather like the problems a tailor faces when fitting a sleeve onto a suit. From a designer's standpoint, building a surface model can be tedious, and there are no guarantees that all the surfaces in a model will fit together correctly when it is done. A surface model can be very accurate, but it takes great care on the part of the designer to ensure this.

Solid Modeling

A solid model, *Figures 11-6* and *11-7*, is simply a surface model where the computer system has kept track of the surface topology, made sure that all the seams between surfaces match, and made sure that the entire model is closed. Sometimes, designers talk about a solid model "holding water." This means there are no gaps at the seams and no openings between surfaces. This makes solid models quite accurate.

There are a number of processes for creating solid models, but the end result is always the same—a topologically closed solid model. From a visualization



FIGURE 11-4 *Wireframe with hidden lines removed.* (Courtesy Matra Datavision Inc.)

FIGURE 11-6 *Solid.* (Courtesy Matra Datavision Inc.)



FIGURE 11-5 *Surface model made by EUCLID CAD/CAM.* (Courtesy Matra Datavision Inc.)



FIGURE 11-7 *Sectioned solid.* (Courtesy Matra Datavision Inc.)

standpoint, there is usually little difference between a surface model and a solid model. From a creation standpoint, solid models are simpler to create and require more computer horsepower. Fortunately, this last point isn't the problem it used to be.

Surface and solid models can be represented as 3D wireframe, with or without hidden lines removed. They can also be represented in a shaded form, where each surface is assigned a shading color. Depending on a computer's graphics power, it may be possible to create shaded views as fast or faster than hidden-line views. Some moderately priced graphics subsystems are able to manipulate shaded views in real time.

As computers increase in speed and capability, design methodology will change. The use of 3D technology, particularly solid modeling, is becoming more and more prevalent. A number of powerful yet easy-to-use solid modeling programs are available, and this has made a noticeable change in the acceptance of solid modeling for mainstream design tasks.

Solid models are formed by joining various geometric shapes such as cones, prisms, pyramids, boxes, wedges, and cylinders. It is as if the computer mathematically "welds" the shapes together to form the solid model. Examine the solid models in Figures 11-6 and 11-7 closely and identify as many geometric shapes as you can. The computer uses *Boolean operators* to join the various shapes that make up the solid model. The most commonly used Boolean operators are:

- Union (also called *addition*)
- Difference (also called *subtraction*)
- Intersection

Figure 11-8 illustrates how these Boolean operators work. In Figure 11-8A, solid X has been added to (union) solid Y to form a new solid. This new solid has a volume equal to the combined volume of solids X and Y before the union. In Figure 11-8B, solid X has been subtracted (difference) from the new solid formed in Figure 11-8A. Notice that the volume where solids X and Y overlapped has been removed from solid Y. That volume appears in Figure 11-8C as the intersection of solids X and Y. The volume of the solid in Figure 11-8C is equal to the overlap between solids X and Y.

A more advanced form of solid modeling is *parametric solid modeling*. With this advanced form of the concept, the model's geometry is controlled by design parameters—hence the name parametric solid modeling—and curved paths are controlled mathematically rather than using coordinates. The benefit of parametric solid modeling is that as changes in the design are made, the model and corresponding drawings are updated automatically. This aspect of parametric solid modeling can shorten the design-prototyping-manufacturing process significantly.

Parametric Solid Modeling

Parametric modeling uses various *parameters*—hence the name—to define a model of an object such as a machine part, sub-assembly, or assembly. Commonly used parameters are dimensions. One of the major benefits of parametric modeling is that at any time the parameters that define the model are changed, the model is updated automatically in accordance with the change. This is critical because in the design process, an ongoing problem has always been that a change—even a seemingly minor change—to a part, sub-assembly, or assembly can cause other corresponding changes. Making sure that these corresponding changes are made and that they do not undermine the design is always a challenge. With parametric modeling this problem is solved. In addition to using dimensions, other parameters may also be used to define an object. These other parameters include material density, formulas that describe swept features, and imported data.



FIGURE 11-8 *Boolean operators in solid modeling.*

In addition to parameters, parametric modeling can use *constraints*. Constraints consist of required relationships between features of an object, or individual features that must be maintained or the design is undermined. For example, two features in an object might have to remain parallel no matter what else is changed about the design. In such a case, parallelism would be considered a constraint. Perpendicularity is another example of a potential constraint. Roundness, flatness, straightness, circularity, concentricity, and symmetry are others.

Types of Visualization Images

Still Images

Single-frame, still images remain one of the most prevalent types of images used for visualization. The exploded view of a fully shaded lifting block assembly in *Figure 11-9* presents a clear means of communicating product details. The ability to separate product components demonstrates an additional benefit of 3D modeling. This same 3D database may be used to generate multiple views of the product by simply designating an alternate viewing location.

There are many types of still images. We've already spoken of wireframe and hidden-line images. Shaded images can be created with various algorithms to obtain differing levels of realism. The simplest shading method is flat shading, where any curved surfaces on a model are broken up into facets (a process called *tessellation*), and each surface is assigned a color based on its angle with respect to the viewer. This gives the model a decidedly chunky and faceted look. Flat shading is fairly rare these days, as the computation power required to generate a better image is negligible. The more common method is *Gouraud* shading, which improves on flat shading by interpolating the colors between adjacent facets. This gives rather a nice, smooth look—in fact, Gouraud shading is often called smooth shading. Most quality graphics boards in modern personal computers can Gouraud-shade images in real time. For very complex images, there are special 3D graphics boards that are optimized for displaying shaded images.

The next step up in shaded image quality is *Phong* shading, which adds specular reflection. This is a mirrorlike glint that makes objects look shiny. Phong shading is possible on higher-end graphics systems, and it is useful for simulations that must be very lifelike.

Beyond simple shading, there are a number of methods that can be used to enhance an image. It is possible, when assigning shading colors to a model, to specify a transparency. This makes it possible to view internal details of parts. The lifting block in ***Figure 11-10*** illustrates how transparency can be used to clearly show the internal detail of assembled products.

Photorealism is the term used to describe images that are created in such a fashion that they might fool the viewer into thinking that they are photographs. In general, photorealistic images include multiple light sources, shadow casting, transparency, reflections, and refractions. As a rule, they also include *texture mapping*, where patterns (such as images of wood, stone, or fabric) are applied to object's surfaces. ***Figure 11-11*** shows a typical photorealistic image. Photorealistic images are also often called rendered images, with the process of creating them being called *rendering*.



FIGURE 11-9 *Lifting block: Exploded assembly.* (Courtesy IBM © 1992 by IBM Corporation. All rights reserved.)

FIGURE 11-10 *Lifting block: Transparent.* (Courtesy IBM © 1992 by IBM Corporation. All rights reserved.)



FIGURE 11-11 *Typical photorealistic image.*

As a rule, every improvement in image quality with photorealistic images comes at the cost of substantial preparation work and processing time. Accurate shadow casting and reflection/refraction calculation require a rendering process called *ray tracing,* which literally involves tracing the rays of light from the eye of the viewer through the scene. Diffuse light calculations (involving, for example, the wash of light off a wall, or through a stained glass window) require a rendering process called *radiosity.* ***Figure 11-12*** shows an image created using both ray tracing and radiosity. Note the realistic and accurate lighting.

Animation

Animation provides a means of representing time-dependent variables and active visualization of objects or events. Products consisting of moving parts and active functions often cannot be clearly represented by still images. Animation is becoming increasingly useful for a variety of innovative applications. In addition to playing a programmed animation, you can now move through 3D models interactively. Advancements in visualization technology will continue to increase the reality with which 3D models can be viewed and toured electronically.

Figure 11-13 shows a still frame from an animation depicting the motion of parts within an assembly. This animation incorporates photorealistic rendering and was created from parts modeled in a solid modeling CAD program.

The NASA Ames Research Center utilizes animation for a variety of design and analysis purposes. One project utilizing animation involves the flowfield about a delta wing equipped with thrust-reverser jets. Powered-lift flight in close vicinity to the ground can have serious implications for aircraft functionality. The three images in ***Figure 11-14*** have been extracted from an animated sequence to show the progression of the jet and the formation of a ground vortex. Particle traces are colored by time at release. Although the three images give a general understanding of the flowfield, they do not communicate the continuous and real-time progression of a live video.

Stereo Images

Stereo images are a special type of 3D model imaging. Stereo images consist of pairs of images that replicate views according to what the left and right eyes see. Since there is a slightly different angle of view between left and right eyes, it is necessary to create two images with slightly different views of an object. These matched sets of images must be viewed in a manner that limits the left eye to the left-view image

FIGURE 11-12 *An image created using both ray tracing and radiosity.*

FIGURE 11-13 *A still frame from an animation depicting the motion of parts within an assembly.*



FIGURE 11-14 *Delta wing animation series (three views).* (Courtesy NASA)

and the right eye to the right-view image. The benefit of stereo images is their ability to re-create a view conveying depth similar to what would be seen in our true 3D world.

Holography

Holography produces images that simulate the effect of seeing the three-dimensionality of an object from multiple viewpoints. Holographic images have become fairly common for a variety of applications. Perhaps the most prevalent application has been the use of holographic images on credit cards. In the past, holographic images have been limited to physical objects that could be photographed in a manner that permits compositing multiple images into a holographic image.

It is now possible to produce holographic images from computer-generated 3D models. In their most basic form, these images are static images on sheet material. One advancement over a static image is the combination of computer and holographic technology to create holographic images in 3D space.

The complexity and computational requirements involved in generating a holographic image in this manner are extremely demanding. For this reason, the model is initially viewed as a wireframe and then rendered as a surfaced model when the desired viewpoint is established. As computational speeds increase, it will be possible to generate increasingly realistic images. Increased size and the addition of color now exist for computer-generated holograms. Faster computational speeds will also improve the capability to interact with the model in real time.

Virtual Reality

Virtual reality is a technology designed to simulate either a physical or hypothetical environment. While the emphasis in this chapter is on visualization, it is important to note that virtual reality is intended to involve all the natural senses. Virtual reality systems can incorporate stimuli for all the five basic senses, but most commonly they deal only with sight and sound.

Virtual reality has a wealth of applications. It can create an environment that permits a sense of how a particular engineering design may feel or function. By being able to experience such an environment, the researcher can test and analyze alternative designs before investing in physical prototypes. Where multiple senses are important to a design project, virtual reality provides a more complete and realistic simulation.

Virtual reality also has great potential for hypothetical and hazardous environments. These environments don't exist, are too dangerous for humans to enter physically, or may be beyond the reach of humans. The virtual reality system illustrated in ***Figure 11-15*** is designed to provide the user with a simulated experience of walking on the planet Mars. The view the operator sees is replicated on the computer screen in order that observers may see what the operator is seeing. The operator is equipped with sensors that signal locational and relationship data to the simulation. All of these components work together to make it possible for the operator to interact with the computational world in a manner that simulates being in the real environment.

In the last few years, the VRML (Virtual Reality Modeling Language) standard has become popular. Strictly speaking, it is not a virtual reality language. It is a language to model static scenes, which users can

FIGURE 11-15 *Virtual reality.* (Courtesy NASA)



FIGURE 11-16 *With VMRI, users can interactively navigate around models, but they cannot move individual parts.*



FIGURE 11-17 *Hypersonic vehicle.* (Courtesy NASA)

navigate through using whatever input and output devices they choose. It doesn't provide for object interaction or motion within a scene. Still, it is an effective tool for interactively viewing complex models. It doesn't provide for motion within a scene, but it does allow a user to navigate around a static 3D model, *Figure 11-16.*

Methods of Representing Variables

Engineering projects involve a large variety of variables. Visualization may be called upon to represent either single or multiple variables in a given visualization image. Numerous means of representing product characteristics and data are available. The methods of representing variables may be used either individually or in combination, depending on the project requirements.

Color

Color is one of the most common and useful means of representing data with visualization. It may be assigned to numerous types of variables including temperature, function, and pressure. *Figure 11-17* illustrates a hypersonic vehicle and related flight pressures. Pressures are shown for both the vehicle and a cross section of the shock layer. The color hues range from magenta to blue and represent highest to lowest pressures, respectively.

In addition to using ranges of color hue to represent a variable, color can be used more directly to make visual representations of 3D models easier to understand. Look back through this chapter and you'll see many images that, if reproduced in black and white, would be much less clear.

Shape

Shape may be used to indicate both visible and invisible variables. This can be anything from pressure levels to molecular bonding forces. An object may in reality be physically deformed or may be represented as deformed to emphasize force. Images may also represent forces that are not visible to the human eye.

The perspective view in *Figure 11-18* represents the convective thermal field computed for a cross section (two-dimensional) of the thermal printhead geometry in an inkjet printing system. The model incorporates composite material structures, convective flow of the ink, and selective heating levels from the thermal device. The problem cross section is outlined in the



FIGURE 11-18 *Convective thermal field.* (Courtesy Xerox Corporation)

lower area. The temperature field is mapped into the third (vertical) dimension. This image also uses color and is mapped so that blue-yellow-red corresponds to a range of low- to high-temperature values. In this case the surface plot clearly emphasizes the jump discontinuities in temperature gradient, where crossing material interfaces with differing conductivities.

Symbols

Numerous types of symbols have been developed to represent variable characteristics. Some symbols have become standards and have very logical applications. Arrows are one example of a symbol with standard applications. They may be used to clearly indicate vectors and direction.

The types of symbols available for visualization and their possible combinations are infinite. Common types of variable symbols include points, lines, (+) and (–) symbols, and 2D and 3D polygons and shapes. The challenge of visualization is to develop the clearest and most intuitive representations possible to convey the information being described. A number of symbols are illustrated in examples throughout this chapter.

Relationships

A variety of relationships exist between variable symbols that may be visually represented to assist with engineering visualization. Similar to the infinite types of variable symbols, there are numerous ways of representing relationships. The three most common types are:

- **Direction:** The visualization of the aircraft hull illustrated in ***Figure 11-19*** utilizes arrows to indicate load distributions. The arrows indicate directional load forces on the hull.
- **Size:** The same arrows used to indicate directional load forces in Figure 11-19 also provide an indication of the amount of load forces on the hull at specific locations. This is achieved by varying the length of the arrows so that longer arrows indicate greater amounts of load force.
- **Density:** Another common method of representing a variable is to determine the density of symbols. In this case the arrows could all be the same length but more closely packed where greater load forces exist.

The decision of how to best represent variables is very subjective. The person responsible for visually representing the data being viewed must select the method of representation based on experience. The more knowledge a designer has about the alternative visualization techniques available, the better that person will be able to communicate necessary information.



FIGURE 11-19 *Boeing aircraft vectors: Direction and size.* (Courtesy Boeing)

Motion

Many engineering applications involve movement. Movement may be either moving parts or various types of flowing matter. The use of animation to represent moving entities has become increasingly practical in terms of both cost and production. Motion is vitally important to a vast number of engineering visualization applications. Aerodynamics is a prime example of an application that must include an understanding of moving matter, specifically air. The ability to portray airflow has dramatically improved the means of evaluating and optimizing the aerodynamics of aircraft. As an example, the image of the YAV-8B Harrier jet in Figure 11-1 may be viewed as an animation with the airflow progressing through simulated paths.

Engineering Visualization Applications

Engineering visualization involves numerous types of design and research information. Each of these types of information requires unique and specific means of representation in order to most clearly and concisely convey selected information. The following examples represent major types of engineering visualization.

Design

The biggest application of engineering visualization is in design—whether of microchips or mile-long bridges. In the past, visualization was often seen as a marketing tool, primarily because the cost and difficulty involved couldn't be justified otherwise. As computers have become more powerful, visualization has become integrated into the design process. With this integration, it is possible not only to improve a product's time to market, but also to optimize the product's cost and performance.

Finite-Element Analysis

Finite-element analysis (FEA) is a vital means of analyzing the structural response of objects. In this method, a model of a part is broken up into a finite number of polygonal elements, called a mesh. If the elements of the mesh are small enough, a structural analysis of this *finite-element model (FEM)* corresponds rather closely with the real-world response of the part. The golf club in ***Figure 11-20*** has been created as a finite-element model. In this example the model is being analyzed to determine the structural and impact characteristics of the golf club.

Stress is a factor in engineering designs of all types. While mechanical engineers spend quite some time understanding stress, you can simply envision it as the internal forces in an object that result from an external load. It may be concentrated in a small area or distributed over a large span. A localized concentration of stress is called a stress riser and can lead to part failure. In designs where failure due to stress is a concern, FEA helps the designer reach an optimal solution much faster than building prototypes or models would. ***Figure 11-21*** shows the results of a finite-element analysis, where the colors represent the stress in individual sections.



FIGURE 11-20 *Finite-element analysis model.* (Courtesy Karsten Manufacturing Corporation/Ping Golf Clubs)

FIGURE 11-21 *Results of a finite-element analysis on a wheel section.* (Courtesy The Yares Organization)

In the past, FEA was the domain of stress specialists—typically PhDs in mechanical engineering. Recently, FEA programs have become easy enough to use so that experienced designers can use them to get a quick readout on whether a part is likely to meet spec. Naturally, critical parts are still referred to the stress specialists. No sane person would want to fly in a plane in which the critical parts were not analyzed by an expert.

Thermal Analysis

Thermal analysis is a means of evaluating the thermal characteristics of a part or a product. Thermal analysis is vital to numerous types of design applications. A clear understanding of a product's thermal characteristics can improve both efficiency and longevity. It may, in fact, prevent product failure.

Thermal analysis may be used for applications where thermal characteristics are the only design variable. It may also be used for design projects where heat or cold is just one of many variables, and where each of the multiple variables has a direct impact on related variables. The heat may be flowing through a conduit or around the exterior of an object. Other products may be solid objects involving critical thermal transfer through a specific material or materials.

One very common application for thermal analysis is the design of heat ducts. These same principles apply to a variety of similar types of heating and cooling systems. The cross-sectional shape and internal volume of a duct significantly impact thermal transfer characteristics.

Thermal analysis systems employ visualization techniques that produce color-coded images, clearly illustrating temperature distributions. These simulations permit quick and easy evaluation of alternative conduit designs.

The two heat duct designs illustrated in ***Figures 11-22*** and ***11-23*** depict two design configurations. The thermal color coding shows distinctly different thermal characteristics. Depending on the desired thermal characteristics, one design may provide significantly better results.

Computational Fluid Dynamics

Computational fluid dynamics (CFD) is another means of using computers to simulate physical events mathematically. This involves the study of fluids and their characteristics under a variety of conditions. Fluids include both gases and liquids. Computer programs and algorithms have evolved to a level that make them highly accurate for predicting fluid flow characteristics for mechanical and electrical products, architectural structures, medicine, and the automotive and aerospace industries.

CFD plays a vital role in the aerospace industry. The design of airplanes depends upon CFD to produce efficient planes that also perform optimally. ***Figure 11-24*** illustrates the use of CFD to determine airflow over an F-16A aircraft. The particle traces illustrate the simulated flowfield about the F-16A. The colors are used to indicate height in relation to the wing. The red color is closest to the horizontal center plane of the wing, and red is highest above the plane. While it may not eliminate the need for testing a physical prototype in a wind tunnel, it significantly reduces the number of physical prototypes that must be built and tested.

The image of the space shuttle in ***Figure 11-25*** illustrates how computational and physical prototypes may be compared. The left half of the shuttle image is the result of a CFD simulation representing surface pressures with color. The right half of the image illustrates the corresponding surface pressures obtained with a physical model in a wind tunnel. The simulation approximates the physical results with sufficient accuracy to justify the use of CFD for design purposes.

In addition to the aerospace industry, there are growing numbers of other industries discovering innovative applications for CFD visualization. Applications include sports equipment, architecture, automobiles, and even consumer products, where CFD can help designers improve internal airflow and cooling.

FIGURE 11-22 *Heat duct: Thermal analysis.* (Courtesy Colorado State University, Department of Industrial Sciences)

FIGURE 11-23 *Heat duct: Thermal analysis.* (Courtesy Colorado State University, Department of Industrial Sciences)



FIGURE 11-24 *F-16A aircraft.* (Courtesy NASA)



FIGURE 11-25 *Shuttle: Simulated/physical.* (Courtesy NASA)

Medical science is developing numerous innovative applications using CFD. One such application is in the design of artificial hearts. This requires an understanding of liquid fluid flows and involves several variables. The heart illustrated in ***Figure 11-26*** is being studied to determine vorticity. Excessive vorticity may result in high shear regions within the heart. This is critical since high shear may damage blood cells as they travel through the heart. In this example, vorticity magnitude is represented by colors, with blue being low magnitude and white being high magnitude. The green cubes represent blood cell locations that have reached a specified threshold of vorticity.

Pre-Assembly Analysis

On complex products, assembly is never simply a matter of bolting together a bunch of parts. In aircraft, for example, physically fitting systems and their components into an aircraft is a monumental task. Not only must the systems fit into limited space, they are also constrained by aerodynamic considerations for the shape of the aircraft. Visualization techniques make it possible to locate potential system interferences during the design stage and eliminate costly revisions. Boeing has been at the forefront of applying visualization technology to reduce prototyping costs.

Space allocation in the area beneath the flight deck is a complex task involving several groups within Boeing. Computer technology and visualization provide a common database that can be used interactively by multiple groups to resolve problems in the early stages of design. This concurrent engineering procedure saves a tremendous amount of time and resources. Equally as important, it results in optimum solutions to design criteria.

Figure 11-27 illustrates an interference in the cargo compartment located beneath the passenger compartment. The interference occurs where the left end of the cream-colored channel meets the green mounting bracket. The channel serves as a mounting device for a light fixture used to illuminate the cargo compartment.

Configuration management software developed by Boeing is used to manage and "assemble" individual 3D solid-modeled parts into a digital mockup, which can be used instead of a physical prototype. In this

FIGURE 11-26 *Artificial heart.* (Courtesy NASA)



FIGURE 11-27 *Boeing structural: Interference.* (Courtesy Boeing)

FIGURE 11-28 *Boeing structural: Clearance.* (Courtesy Boeing)

case, the interference was corrected by replacing the original channel with a shorter channel. The correctly fitted channel is illustrated in ***Figure 11-28***. By detecting the interference early in the design process, it was possible to eliminate the interference before spending money on tooling.

Kinematic Simulations

Kinematics is an excellent application for visualization and simulation. Linkages and mechanisms are present in numerous products that we use daily. Computers are ideal for solving the mathematical calculations necessary. Once the calculations have been performed, images may be generated that clearly illustrate resulting designs. Technology exists that makes it easy to computationally build kinematic systems. Once a system has been built, it may easily be animated and tested for performance. ***Figure 11-29*** illustrates three stages of an animated sequence representing a linkage system and relevant system characteristics.

Automotive Crash Simulations

The automotive industry is using visualization in computational simulations to better understand structural damage resulting from crashes. This crash information is vital to improving the safety of vehicles. In the past, such information was available only from physically crashing real vehicles. ***Figure 11-30*** illustrates computer-simulated crash results. These three images have been extracted from an animation sequence that permits the study of progressive stages of crash impact. The ability to interactively study computational crashes permits a better understanding of the crash results. This information may then be used to optimize designs first with simulations. This reduces the need for crash testing real vehicles.



FIGURE 11-29 *Kinematic sequence.* (Courtesy Knowledge Revolution)



FIGURE 11-30 *Vehicle crash testing: Real and simulated.* (Courtesy Altair Engineering with CRAY XMS Supercomputer)

Case Studies

Engineering visualization is one aspect of product design. In reality there are multiple phases that occur between product conception and the final product. The following two examples illustrate how visualization is utilized to improve products, their production, and their cost effectiveness. These two examples also consist of several types of visualization images and considerations that need to be addressed.

Biomechanical Visualization Example

Biomechanical technology is incorporating ever-increasing use of engineering and visualization techniques to improve the quality and capabilities of work in this field. The following example describes work being done with hip and knee implant replacement techniques. In addition to demonstrating benefits of modern technology, it exemplifies very real benefits on a personal level. Prior to the use of this technology, a typical hip replacement had a life expectancy of four to five years. With the increased information and accuracy of visualization and related technologies, the life expectancy of the replacement has increased to 10 years and continues to improve. In simple terms, it reduces return surgery to one-half the previous frequency.

There are several steps involved in producing implant prosthetics. The first step in the process involves obtaining three-dimensional data, which can be used to create a 3D FEM of the problem area. This information is typically obtained by techniques such as magnetic resonance imaging (MRI). The 3D FEM may be used for a variety of design and analysis purposes.

The hip implant illustrated in ***Figure 11-31*** is being optimized relative to stresses in the region of the bone near the implant interface. The FEM on the right is the initial prosthetic design and the FEM on the left is the optimized prosthetic design. The material selected for this particular implant was titanium. Implant material selection is critical to hip replacement functionality. This type of surgery involves several critical factors, including bone material stress and growth characteristics. Understanding stress and growth characteristics has proven to be one of the major advancements related to increased prosthetic implant life expectancy.



FIGURE 11-31 *Hip implant: Optimal/initial.* (Courtesy NASA and Case Western Reserve University)

Orthopedic knee implants involve techniques similar to hip implants. Since a knee is subjected to both symmetrical and asymmetrical loading, it is necessary to evaluate the effects of both types of loading. ***Figure 11-32*** illustrates equivalent stress distributions in the cortical bone at three points in the design evolution for symmetric loads. ***Figure 11-33*** illustrates similar stress distributions for asymmetrical loads.

The knee implant in this case involves multiple materials in order to optimize functionality and longevity. ***Figure 11-34*** illustrates idealized morphology



FIGURE 11-32 *Knee implant: Symmetrical loads.* (Courtesy NASA and Case Western Reserve University)

FIGURE 11-33 *Knee implant: Asymmetrical loads* (Courtesy NASA and Case Western Reserve University)



FIGURE 11-34 *Knee implant: Composite materials.* (Courtesy NASA and Case Western Reserve University)

FIGURE 11-35 *Knee implant: Components.* (Courtesy NASA and Case Western Reserve University)

and material regions for a typical adult male tibia with an implant. Once the 3D FEM has been optimized for fit and functionality, it must next be produced. It is here that the relationship between design and production becomes evident. Typical knee implant components are illustrated in ***Figure 11-35.*** The production of implant components is now possible with automated machining equipment. The same 3D model that was used for design purposes may be used to generate codes to control machining operations. The automated machining equipment may then produce the prosthetic implant.

Product Design Example

Product design techniques are changing dramatically. Competition is demanding faster design cycles and improved design solutions. The following example describes how Xerox utilizes computer technology for product design. In addition to visualization techniques, methods of conducting real-time interactive design with variable controls on the computer screen are discussed. The goal is improved product quality and design time.

The use of physical prototypes is both time consuming and expensive. One means of significantly improving design solutions and time requirements is to perform initial design using computational prototypes. This permits ease of testing design alternatives and promotes investigating more designs than traditional physical prototyping methods. Testing more designs provides increased information from which to select the optimum design solution.

Xerographic printing and copying is pervasive throughout the world. The process of xerography is a very complex process demanding exacting standards. The design of xerography systems is accordingly complicated and presents an important case for the need

FIGURE 11-36 *Xerox interactive display.* (Courtesy Xerox Corporation)



FIGURE 11-37 *Xerox laser exposure of photoreceptor.* (Courtesy Xerox Corporation)

to develop computational prototyping techniques. It is equally important that researchers and designers are provided fully integrated computer systems with highly functional interactive user interfaces.

One critical aspect of the xerography process is to understand the effects of laser exposure on the photoreceptor. ***Figure 11-36*** is a screen-captured image from the designer's workstation. It represents an interactive session for analyzing the xerography imaging process. The upper window shows a cross section of the photoreceptor with space charge densities color mapped as blue-yellow-red to indicate zero, moderate, and high levels, respectively. The lower-right window shows the evolution of the surface voltage on the photoreceptor. As the image discharges subsequent to the laser illumination, the photo-generated charge from the bottom moves upward to lower the surface voltage. Development of the image is voltage sensitive.

The designer's screen illustrates built-in capabilities permitting interactive changing of variables. On the left are four dials that can be used to change photoreceptor velocity, dielectric constants, backplate voltage, and wire voltage. These dials let the designer computationally test varying levels and combinations of critical variables.

Further clarification of the effects of the laser exposure on the photoreceptor are illustrated in ***Figure 11-37***. This model graphically shows the scattering and attenuation of plane waves representing the laser illumination as it moves through the photoreceptor. In this instance, intensity is color mapped so that blue, yellow, and red indicate zero, moderate, and high levels of intensity, respectively. The resulting model indicates that light is a wavelike phenomenon. The plane waves are incident on the left and become compressed and wrapped around the toner particles on the surface of the photoreceptor. It may be noted that the plane waves are similar to water waves as they flow around poles placed in water.

Summary

- Visualization is the pictorial representation of data for the purpose of a more clear and concise communication of information.
- The increased use of visualization can be attributed to the increasing complexity of engineering problems, the improved capabilities of computers, relative affordability of computer hardware and software, and the relative ease of learning to create visualization output.
- Three-dimensional modeling techniques include wireframe, surface modeling, and solid modeling.
- Parametric solid modeling uses parameters of various kinds to define a model of an object. It also can use constraints such as parallelism that must be maintained as the model is revised.
- Types of visualization images include still images, transparency, photorealism, animation, stereo images, holography, and virtual reality.
- Variables in engineering projects may be represented using color, shape, symbols, size, density, and motion.
- Engineering visualization categories include design, finite-element analysis, thermal analysis, computational fluid dynamics, kinematic simulation, and automotive crash simulations.

Industry Application

The design team for Thompson Engineering International (TEI) had been debating the issue of visualization for over a week. All members of the team agreed that TEI's current 2D CAD capabilities were inadequate. The new space station project, the company's largest and most complex project ever, would be a particular challenge. The parts TEI will design for the joint U.S./European space station must be perfect; there is no room for error. This is why the topic of visualization is now being debated so intensely.

Several members of the team argue for a minimalist approach, combining 2D, 3D wireframe, and surface modeling where necessary. They argue that it will require less computing power and a shorter learning curve for design and drafting personnel. Plus, they won't have to throw away the investment they've made in their existing systems. Other members of the team favor moving completely to solid modeling; they counter the arguments of the wireframe advocates, claiming that approach won't yield sufficient information. In their words, "A wireframe image just is not descriptive enough to do us any good."

"Solid modeling," claims its advocates, "provides the most accurate, most comprehensive information possible, and the image is realistic." They add that "Revisions are particularly easy with solid modeling." The supporters of the minimalist approach counter by saying "We can't do solid modeling without an expensive hardware upgrade and it will take our team six months to develop modeling skills. This space-station project doesn't have a six-month learning curve built into it." This type of debate happens frequently in engineering companies. Join the debate. What is your opinion?

Review Questions

Answer the following questions either true or false.

1. Visualization is the pictorial representation of data for the purpose of a more clear and concise communication of information.
2. Visualization is beneficial because it allows extremely large amounts of data to be seen and therefore comprehended.
3. Computer technology and visualization have made it possible to resolve problems that were previously too complex to solve.
4. The wireframe method of modeling is the most time-consuming computationally.
5. A disadvantage of solid modeling is that it is not accurate.
6. Only high-dollar problems, such as those faced by NASA, justify the effort involved in visualization.
7. A disadvantage of visualization is that the hardware and software are not affordable for most people and companies.
8. Normal personal computers are capable of displaying and manipulating shaded images in real time.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** one of the basic methods of engineering modeling?
   a. wireframe
   b. surface
   c. photorealism
   d. solid modeling
2. Which of the following is **not** a type of visualization image?
   a. animation
   b. stereo images
   c. transparency
   d. intrinsic
3. Which of the following is the appropriate type of visualization image to represent an item in a physical or hypothetical environment?
   a. virtual reality
   b. holography
   c. photorealism
   d. animation
4. Which of the following is **not** a method for representing visualization variables?
   a. color
   b. motion
   c. symbols
   d. thermal analysis

5. Which of the following is **not** one of the five engineering visualization categories?
   a. holography
   b. finite-element analysis
   c. thermal analysis
   d. computational fluid dynamics
6. An example of an application using computational fluid dynamics is:
   a. the design of artificial turf
   b. the design of artificial intelligence
   c. the design of artificial knees
   d. the design of artificial hearts
7. Which of the following is **not** a factor in using visualization?
   a. More complex engineering problems are generating increasingly large amounts of information.
   b. Increased computational speed makes it possible to perform visualization tasks on workstations and personal computers instead of being limited to supercomputers.
   c. The decision of how to represent the data is subjective.
   d. Improved user interfaces make the operation of systems and the production of visualization output easier to perform.
8. Which of the following is **not** true regarding stress analysis?
   a. Stress is a critical factor in engineering designs of all types.
   b. Trained designers may be able to do basic stress analyses, but critical analyses should be left for specialists.
   c. Prior to being analyzed for stress, a model of a part must be broken up into a finite number of polygonal elements.
   d. Stress risers are desirable to assure that parts will not fail.
9. Which of the following is **not** a constraint that might be used in solid modeling?
   a. parallelism
   b. flatness
   c. visualization
   d. symmetry

SECTION 3

Design Drafting Applications

12 Geometric Dimensioning and Tolerancing

13 Fasteners

14 Springs

15 Cams

16 Gears

17 Assembly and Detail Drawings for Design

18 Pictorial Drawings

Career Profile

MARY TRAHAN

Mary started her career with drafting classes in high school and went on to a technical college, where she trained further on the subject. Coming out of the program, she joined the Consolidated Waterworks District 1 in Terrebonne Parish, Louisiana, as a drafter. At that time, her drawings were done with pen and paper. Things have changed a lot in 22 years!

Doing things on paper meant that when they had to replace valves or when a main line broke, they would have to redraft the map to account for the change. Thankfully, in the 1980s, the Waterworks started digitizing the maps, tracing aerial photographs electronically into computer-aided design (CAD) software. It was a big step up, but the program was not great for mapping. The roads, landmarks, and water mains are not merely straight lines, at which CAD programs are best. Often, the curves did not match. And technical specifications (like the depth at which a pipe is buried) had to be kept in a separate database.

By the 1990s, the Waterworks began working with other utilities, such as gas and electric, in order to fund and create a parish geographic information system (GIS). It became a functional way to view each other's information on intelligent maps. With the North American Datum coordinates, the maps can more closely approximate the spherical shape of the earth (versus the flatness of CAD). GIS also combined sophisticated graphics with the spatial integrity of tabular data. That means that Trahan can see if a specific pipe has had several leaks in the past few years, making it easier to prevent major problems before they happen. It also helps with safeguards: If there is a chemical leak at the plant, drafters can draw a polygon in the program and get customers' information for that area to notify them.

On a daily basis, Trahan is responsible for maintaining all the water-related changes on the map, whether they are water lines or fire hydrants. For instance, in the case of a new subdivision, she will go out after it is completed to make a final inspection and to ensure that main lines and valves operate as designed and comply with her system. Once she and the board approve the job, the engineer will submit digital copies (usually in AutoCAD), and Trahan will transfer those changes into the system map. Most of the drawings are flat, from a perspective above, but the benefit of the software is that she can also do other views. A profile, looking from the top of the earth into the depths, is especially necessary for new construction, so engineers can ensure that all utilities cross within proper distances. Trahan's insertions will make it easier for these other utilities to know where they can (and cannot) run lines.

12

Geometric Dimensioning and Tolerancing

CHAPTER OUTLINE

Summary of geometric dimensioning and tolerancing terms • Geometric dimensioning and tolerancing defined • Modifiers • Feature control symbol • True position • Circularity (roundness) • Cylindricity • Angularity • Parallelism • Perpendicularity • Profile • Runout • Concentricity • Summary • Review questions • Chapter 12 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Describe what is meant by the term *general tolerancing.*
- Define the concept *geometric dimensioning and tolerancing.*
- Explain the purpose of a modifier.
- Distinguish between the concepts *maximum material condition (MMC)* and *regardless of feature size (RFS).*
- Explain the concept *least material condition (LMC).*
- Describe what is meant by *projected tolerance zone.*
- Make a sketch that illustrates the concept of datums.
- Demonstrate how to establish datums.
- Apply feature control symbols when dimensioning objects.
- Explain the concept of *true position.*

KEY TERMS

All around symbol
Angularity
Basic dimension
Between symbol
Bilateral tolerance
Circularity
Cylindricity
Datum
Datum feature
Datum feature simulator
Datum feature symbol
Datum plane
Datum reference frame
Datum surface
Datum target symbol
Feature control symbol
Flatness
Free state variation
General tolerancing
Geometric dimensioning and tolerancing
Least material condition (LMC)
Limit dimensioning
Maximum material condition (MMC)
Modifiers
Parallelism
Perpendicularity
Positional tolerancing
Profile
Profile of a line
Profile of a surface
Projected tolerance zone
Regardless of feature size (RFS)
Rule #1
Runout
Size tolerance
Statistical tolerancing symbol
Straightness
Tangent plane
Tolerancing
True position
Unilateral tolerance
Virtual condition

Summary of Geometric Dimensioning and Tolerancing Terms

Actual Local Size. The value of any individual distance at any cross section of a feature.

Actual Mating Size. The dimensional value of the actual mating envelope.

Actual Size. Actual measured size of a feature.

Allowance. The difference between the larger shaft size limit and the smallest hole size limit.

Angularity. Tolerancing of a feature at a specified angle other than 90° from a referenced datum.

Basic Dimension. A theoretically "perfect" dimension similar to a reference or nominal dimension. It is used to identify the exact location, size, shape, or orientation of a feature. Associated tolerances are applied by notes, feature control frame, or other methods, excluding tolerance within title blocks.

Bilateral Tolerances. Tolerances that are applied to a nominal dimension in the positive and negative directions.

Bonus Tolerance. The permitted allowable increase in tolerance as the feature departs from the material condition identified within the feature control frame.

Circular Runout. A tolerance that identifies an infinite number of single circular elements measured at cross sections on a feature when the feature is rotated 360° for each cross section.

Circularity. A tolerance that controls the circular cross section of round features that is independent of other features. The tolerance zone boundary is formed by two concentric perfect circles.

Clearance Fit. A condition between mating parts in which the internal part is always smaller than the external parts it fits into.

Coaxiality. The condition of two or more features having coincident axes.

Compound Datum Features. Two datum features used to establish a datum or axis plane.

Concentricity. A tolerance in which the axis of a feature must be coaxial to a specified datum regardless of the datum's and the feature's size. The lack of concentricity is eccentricity.

Cylindricity. A tolerance that simultaneously controls a surface of revolution for straightness, parallelism, and circularity of a feature, and is independent of any other features on a part. The tolerance zone boundary is composed of two concentric perfect cylinders.

Datum. Reference points, lines, planes, cylinders, and axes that are assumed to be exact. They are established from datum features.

Datum Axis. The axis of a referenced datum feature such as a hole or shaft.

Datum Feature. A feature that is used to establish a datum.

Datum Feature of Size. A feature that has size, such as a shaft, that is used to establish a datum.

Datum Identification Symbol. A special rectangular box that contains the datum reference letter and a dash on either side of the letter. It is used to identify datum features.

Datum: Feature Simulator. A surface of adequately precise form (such as a surface plate, a gage surface, or a mandrel) contacting the datum feature(s) and used to establish the simulated datum(s).

Datum: Reference. Entering a datum reference letter in a compartment of the feature control frame following the tolerance value.

Datum: Reference Frame. Three mutually perpendicular planes that establish a coordinate system. It is created by datum references in a feature control frame or by a note.

Datum: Simulated. A point, axis, or plane established by processing or inspection equipment, such as the following: simulator, surface plate, a gage surface, or a mandrel.

Datum Simulation. The use of a tool contacting a datum feature used to simulate a true geometric counterpart of the feature.

Datum Simulator. A tool used to contact a datum feature.

Datum Target. Specified points, lines, or areas on a feature used to establish datums.

Datum Target Area. A specified area on a part that is contacted to establish a datum.

Datum Target Line. A line on a surface that is contacted to establish a datum.

Datum Target Point. A specified point on a surface used to establish a datum.

Datum Target Symbol. A circle divided horizontally into halves containing a letter and number to identify datum targets.

Envelope, Actual Mating. The term is defined according to the type of features as follows:

(a) *For an External Feature.* A similar perfect feature counterpart of smallest size that can be circumscribed about the features so that it just contacts the surface at the highest points. For example, a smallest cylinder of perfect

form or two parallel planes of perfect form at minimum separation that just contact(s) the highest points of the surface(s).

For features controlled by orientation or positional tolerances, the actual mating envelope is orientated relative to the appropriate datum(s), for example, perpendicular to a primary datum plane.

(b) *For an Internal Feature.* A similar perfect feature counterpart of largest size that can be inscribed within the feature so that it just contacts the surface at the highest points. For example, a largest cylinder of perfect form or two parallel planes of perfect form at maximum separation that just contact(s) the highest points of the surface(s).

For features controlled by orientation or positional tolerance, the actual mating envelope is oriented relative to the appropriate datum(s).

Feature. A component of a part such as a hole, slot, surface, pin, tab, or boss.

Feature of Size. One cylindrical or spherical surface, or a set of two opposed elements or opposed parallel surfaces, associated with a size dimension.

Feature, Axis of. A straight line that coincides with the axis of the true geometric counterpart of the specified feature.

Feature, Center Plane of. A plane that coincides with the center plane of the true geometric counterpart of the specified feature.

Feature, Derived Median Line of. An imperfect line (abstract) that passes through the center points of all cross sections of the feature. These cross sections are normal to the axis of the actual mating envelope. The cross section center points are determined as per ANSI B89.3.1.

Feature, Derived Median Plane of. An imperfect plane (abstract) that passes through the center points of all line segments bounded by the feature. These line segments are normal to the actual mating envelope.

Fit. A term used to describe the range of assembly that results from tolerances on two mating parts.

Flatness. A tolerance that controls the amount of variation from the perfect plane on a feature independent of any other features on the part.

Form Tolerance. A tolerance that specifies the allowable variation of a feature from its perfect form.

Free-State Variation. The condition of a part that permits its dimensional limits to vary after removal from manufacturing or inspection equipment.

Least Material Condition (LMC). A condition of a feature in which it contains the least amount of material relative to the associated tolerances. Examples are maximum hole diameter and minimum shaft diameter.

Limit Dimensions. A tolerancing method showing only the maximum and minimum dimensions that establish the limits of a part size or location.

Limits. The maximum and minimum allowable sizes of a feature.

Location Tolerance. A tolerance that specifies the allowable variation from the perfect location of a feature relative to datums or other features.

Maximum Material Condition (MMC). A condition in which the feature contains the maximum amount of material relative to the associated tolerances. Examples are maximum shaft diameter and minimum hole diameter.

Modifier. The application of MMC or LMC to alter the normally implied interpretation of a tolerance specification.

Parallelism. A tolerance that controls the orientation of interdependent surfaces and axes that must be of equal distance from a datum plane or axis.

Perpendicularity. A tolerance that controls surfaces and axes that must be at right angles with a referenced datum.

Position Tolerance. A tolerance that controls the position of a feature relative to the true position specified for the features, as related to a datum or datums.

Primary Datum. The first datum reference in a feature control frame. It is normally elected because it is most important to the design criteria and function of the part.

Profile of a Line. A tolerance that controls the allowable variation of line element in only one direction on a surface along an elemental tolerance zone with regard to a basic profile.

Profile of a Surface. A tolerance that controls the allowable variation of a surface from a basic profile or configuration.

Profile Tolerance Zone. A tolerance zone that can control the form of an individual feature and provide for a composite control of form, orientation, and location.

Projected Tolerance Zone. A tolerance zone that applies to the location of an axis beyond the surface of the feature being controlled.

Reference Dimension. A non-tolerance zone or location dimension used for information purposes only that does not govern production or inspection operations.

Regardless of Feature Size (RFS). A condition of a tolerance in which the tolerance must be met regardless of the produced size of the feature.

Runout. The composite surface variation from the desired form of a part of revolution during full rotation of the part on a datum axis.

Secondary Datum. The second datum reference in a feature control frame. Established after the primary datum, it has less design influence and functionality.

Size, Virtual Condition. The actual value of the virtual condition boundary.

Straightness. A tolerance that controls the allowable variation of a surface or an axis from a theoretically perfect line.

Symmetry. A condition for which a feature (or features) is equally disposed or shaped about the center plane of a datum feature.

Tangent Plane. A theoretically exact plane derived from the true geometric counterpart of the specified feature surface by contacting the high points on the surface.

Tertiary Datum. The third datum reference in a feature control frame. Established after the secondary datum, it has the least amount of design influence or functionality.

Tolerance. The acceptable dimensional variation or allowance of a part.

Total Runout. A tolerance that provides for a composite control of all surface elements as the part is rotated 360° about a datum axis.

Transition Fit. A condition in which the prescribed limits of mating parts produce either a clearance or an interference when the parts are assembled.

True Geometric Counterpart. The theoretically perfect boundary (virtual condition or actual mating envelope) or best-fit (tangent) plane of a specified datum feature.

True Position. The theoretically exact location of a feature.

Unilateral Tolerance. A tolerance that allows variations in only one direction.

Virtual Condition. A constant boundary produced by the combined effects of the maximum material condition size and geometric tolerance. It represents the worst-case condition of assembly at MMC.

Zero Tolerance at MMC or LMC. A tolerancing method where no tolerance is shown in the feature control frame. The tolerance allowed is totally dependent on the size of the feature departure from MMC or LMC.

General Tolerancing

The Industrial Revolution created a need for mass production, assembling interchangeable parts on an assembly line to turn out great quantities of a given finished product. Interchangeability of parts was the key. If a particular product was composed of 100 parts, each part could be produced in quantity, checked for accuracy, stored, and used as necessary.

Since it was humanly and technologically impossible to have every individual part produced exactly alike (it still is), the concept of geometric and positional tolerancing was introduced. *Tolerancing* means setting acceptable limits of deviation. For example, if a mass-produced part is to be 4″ in length under ideal conditions, but is acceptable as long as it is not less than 3.99″ and not longer than 4.01″, there is a tolerance of plus or minus .01″, ***Figure 12-1.*** This type of tolerance is called a *size tolerance.*

There are three different types of size tolerances: unilateral and bilateral, shown in ***Figure 12-2,*** and



FIGURE 12-1 *Size tolerance.*



FIGURE 12-2 *Two types of tolerances.*

limit dimensioning. When a *unilateral tolerance* is applied to a dimension, the tolerance applies in one direction only (for example, the object may be larger but not smaller, or it may be smaller but not larger). When a *bilateral tolerance* is applied to a dimension, the tolerance applies in both directions, but not necessarily evenly distributed. In *limit dimensioning*, the high limit is placed above the low value. When placed in a single line, the low limit precedes the high limit and the two are separated by a dash.

Tolerancing size dimensions offers a number of advantages. It allows for acceptable error without compromises in design, cuts down on unacceptable parts, decreases manufacturing time, and makes the product less expensive to produce. However, it soon became apparent that in spite of advantages gained from size tolerances, tolerancing only the size of an object was not enough. Other characteristics of objects also needed to be toleranced, such as location of features, orientation, form, runout, and profile.

In order for parts to be acceptable, depending on their use, they need to be straight, round, cylindrical, flat, angular, and so forth. This concept is illustrated in *Figure 12-3*. The object depicted is a shaft that is to be manufactured to within plus or minus .01 of 1.00 inch in diameter. The finished product meets the size specifications but, since it is not straight, the part might be rejected.

The need to tolerance more than just the size of objects led to the development of a more precise system of tolerancing called geometric dimensioning and *positional tolerancing*. This new practice improved on conventional tolerancing significantly by allowing designers to tolerance size, form, orientation, profile, location, and runout, *Figure 12-4*. In turn, these are the characteristics that make it possible to achieve a high degree of interchangeability.



FIGURE 12-3 *Tolerance of form.*

FOR INDIVIDUAL FEATURES	FORM
FOR INDIVIDUAL OR RELATED FEATURES	PROFILE
FOR RELATED FEATURES	ORIENTATION LOCATION RUNOUT

FIGURE 12-4 *Types of tolerances.*

Geometric Dimensioning and Tolerancing Defined

Geometric dimensioning and tolerancing is a dimensioning practice that allows designers to set tolerance limits not just for the size of an object, but for all of the various critical characteristics of a part. In applying geometric dimensioning and tolerancing to a part, the designer must examine it in terms of its function and its relationship to mating parts.

Figure 12-5 is an example of a drawing of an object that has been geometrically dimensioned and toleranced. It is taken from the dimensioning standards as defined by the American National Standards Institute (ANSI), written by the American Society of Mechanical Engineers (ASME) or ASME Y14.5M—1994. This manual is a necessary reference for drafters and designers involved in geometric dimensioning and positional tolerancing.

The key to learning geometric dimensioning and positional tolerancing is to learn the various building blocks that make up the system, as well as how to properly apply them. *Figure 12-6* contains a chart of the building blocks of the geometric dimensioning and tolerancing system. In addition to the standard building blocks shown in the figure, several modifying symbols are used when applying geometric tolerancing, as discussed in detail in upcoming paragraphs.

Another concept that must be understood in order to effectively apply geometric tolerancing is the concept of datums. For skilled, experienced designers, the geometric building blocks, modifiers, and datums blend together as a single concept. However, for the purpose of learning, they are dealt with separately and undertaken step-by-step as individual concepts. They are presented now in the following order: modifiers, datums, and geometric building blocks.

ANSI's dimensioning standards manual (Y14.5 series) changes from time to time as standards are updated. For example, the Y14.5 manual became



FIGURE 12-5 *Geometrically dimensioned and toleranced drawing. (From ASME Y14.5M—1994).*

SYMBOL	CHARACTERISTIC	GEOMETRIC TOLERANCE
—	STRAIGHTNESS	FORM
▱	FLATNESS	
○	CIRCULARITY	
⌭	CYLINDRICITY	
⌒	PROFILE OF A LINE	PROFILE
⌓	PROFILE OF A SURFACE	
∠	ANGULARITY	ORIENTATION
⊥	PERPENDICULARITY	
//	PARALLELISM	
⌖	TRUE POSITION	LOCATION
◎	CONCENTRICITY	
⌯	SYMMETRY	
↗	CIRCULAR RUNOUT	RUNOUT
⌰	TOTAL RUNOUT	

* MAY BE FILLED IN

FIGURE 12-6 *Building blocks.*

Y14.5M in 1982 to accommodate metric dimensioning. Revised again in 1988, it became Y14.5M-R1988. In the latest edition, the standard takes on the name of the developing agency, the American Society of Mechanical Engineers (ASME). ASME Y14.5M—1994 is the latest edition in the ongoing revision process of the standard. This chapter helps students learn the basics of geometric dimensioning and positional tolerancing so they will be able to apply the latest standards set forth by ASME at any point in time and in accordance with any edition of the manual that is specified. Students should not use this chapter as a reference in place of the ASME standard. Always refer to the latest edition of the standard for specifics that go beyond the basics covered herein.

Modifiers

Modifiers are symbols that can be attached to the standard geometric building blocks to alter their application or interpretation. The proper use of modifiers is fundamental to effective geometric tolerancing. Various modifiers are often used: maximum material condition, least material condition, projected tolerance zone, free-state variation, tangent plane, all around, between symbol, and statistical tolerance, *Figure 12-7A*, *Figure 12-7B*, and *Figure 12-7C*.

Maximum Material Condition

Maximum material condition (MMC) is the condition of a characteristic when the most material exists. For example, MMC of the external feature in *Figure 12-8* is .77″. This is the MMC because it represents the condition where the most material exists on the part being manufactured. The MMC of the internal feature in the figure is .73″. This is the MMC because

Ⓜ	MAXIMUM MATERIAL CONDITION
Ⓛ	LEAST MATERIAL CONDITION
Ⓟ	PROJECTED TOLERANCE ZONE
Ⓕ	FREE STATE VARIATION
Ⓣ	TANGENT PLANE
	ALL AROUND
←→	BETWEEN SYMBOL
Ⓢ	STATISTICAL TOLERANCE

THE RFS SYMBOL Ⓢ CAN STILL BE USED BUT THE PREFERRED PRACTICE IS TO OMIT IT.

FIGURE 12-7A *Modifiers used when applying geometric tolerancing.*

the most material exists when the hole is produced at the smallest allowable size.

In using this concept, the designer must remember that the MMC of an internal feature is the smallest allowable size. The MMC of an external feature is the largest allowable size within specified tolerance limits inclusive. A rule of thumb to remember is that MMC means most material.

Regardless of Feature Size

Regardless of feature size (RFS) tells machinists that a tolerance of form or position or any characteristic



FIGURE 12-7B *Form and proportion of geometric tolerancing symbols.*



FIGURE 12-7C *Form and proportion of dimensioning symbols and letters.*



FIGURE 12-8 *MMC of an external and an internal feature.*

must be maintained regardless of the actual produced size of the object. Geometric tolerances are understood to apply regardless of feature size where the modifiers M or L are not used. It is permissible to show the RFS modifier; however, it is redundant and the preferred practice is to omit it. The RFS concept is illustrated in ***Figure 12-9.*** In the RFS example, the object is acceptable if produced in sizes from 1.002″ to .998″ inclusive. The form control is axis straightness to a tolerance of .002″ regardless of feature size. This means that the .002″ axis straightness tolerance must be adhered to, regardless of the produced size of the part.

Contrast this with the MMC example. In this case, the produced sizes are still 1.002″ to .998″. However, because of the MMC modifier, the .002″ axis straightness tolerance applies only at MMC or 1.002″.

If the produced size is smaller, the straightness tolerance can be increased proportionally. Of course,



FIGURE 12-9 *Regardless of feature size (RFS).*

this makes the MMC modifier more popular with machinists for several reasons: (1) it allows them greater room for error without actually increasing the tolerance, (2) it decreases the number of parts rejected, (3) it cuts down on unacceptable parts, (4) it decreases the number of inspections required, and (5) it allows the use of functional gaging. All of these advantages translate into substantial financial savings while, at the same time, making it possible to produce interchangeable parts at minimum expense.

Least Material Condition

Least material condition (LMC) is the opposite of MMC. It refers to the condition in which the least material exists. This concept is illustrated in ***Figure 12-10.***



FIGURE 12-10 *Least material condition (LMC).*

In the top example, the external feature of the part is acceptable if produced in sizes ranging from .98″ to 1.02″ inclusive. The least material exists at .98″. Consequently, .98″ is the LMC.

In the bottom example, the internal feature (hole) is acceptable if produced in sizes ranging from .98″ to 1.02″ inclusive. The least material exists at 1.02″. Consequently, 1.02 represents the LMC.

Projected Tolerance Zone

Projected tolerance zone is a modifier that allows a tolerance zone established by a locational tolerance to be extended a specified distance beyond a given surface. This concept is discussed further later in this chapter under the heading "True Position."

Free-State Variation

Free-state variation is the concept that some parts cannot be expected to be contained within a boundary of perfect form. Some parts may vary in form beyond the MMC size limits after forces applied during manufacture are removed. For example, a thin-walled part shape may vary in its free state due to stresses being released in the part. This variation may require that the part meet its tolerance requirements while in its free state.

Parts that are subject to free-state variation do not have to meet the Rule #1 requirement of perfect form at MMC. These parts are standard stock such as bars, sheets, tubes, extrusions, structural shapes, or other items produced to established industry or government standards. The appropriate standard would govern the limits of form variation allowed after manufacture.

The free-state symbol specifies the maximum allowable free-state variation. It is placed within a feature control frame, following the tolerance and any modifiers, ***Figure 12-11.***

Tangent Plane

The *tangent plane* concept uses a modifying symbol with an orientation tolerance to modify the intended control of the surface. When an orientation tolerance is applied to a surface, the primary control is equivalent to the symbology used. An example of

FIGURE 12-11 *Feature control frame with free-state symbol.*

the primary control of a parallel callout is parallelism. However, when applied, the specified symbol controls not only parallelism but other form variations such as concavity, convexity, waviness, flatness, and other imperfections as well.

If two such controlled surfaces are assembled, the abrupt variation in the surfaces can cause different mating effects and assembly conditions. There are several ways to control the effects of surface conditions when applying orientation tolerances. The obvious method is to refine the surface control with a form tolerance such as flatness. This is permissible because the orientation tolerance controls flatness to the extent of the specified tolerance value.

Another method is to modify the orientation tolerance to apply a tangent plane. When the modifier is applied, the orientation tolerance zone for a tangent plane is identical to any other orientation tolerance zones with one exception. The orientation tolerance no longer controls the form of the surface. The surface of the controlled feature must be within the specified limits of size, but it is not required to fall within the parallelism tolerance zone boundary. Only a plane tangent to the high points on the surface must be within the tolerance zone boundary. The symbol is placed within the feature control frame following the stated tolerance, *Figure 12-12.*

All Around Symbol

The *all around symbol* is the symbolic means of indicating that the specified tolerance applies all around the part. The normal tolerance zone of a geometric callout extends the length of the feature in question. If there is an abrupt change in surface condition, such as an offset, the tolerance zone would conclude at the beginning of the offset. Applying the all around symbol extends the tolerance zone all around the feature to include abrupt surface variations, *Figure 12-13.* This concept will be discussed further later in this chapter under the heading "Profile."

FIGURE 12-12 *Specifying a tangent plane.*



FIGURE 12-13 *All around symbol.*

Between Symbol

The *between symbol* is a symbolic means of indicating that the stated tolerance applies to a specified segment of a surface between designated points. The normal tolerance zone of a geometric callout extends the length of the feature in question. Application of this symbol can be used to limit the tolerance zone to a specified area. It can also be used to clarify the extent of the profile tolerance when it is not clearly visible due to surface variations. *Figure 12-14* illustrates the use of this symbol.

Statistical Tolerancing Symbol

The *statistical tolerancing symbol* is a symbolic means of indicating that the stated tolerance is based on statistical process control (SPC). The symbol can be applied in one of two ways. When the tolerance is a statistical size tolerance, the symbol is placed next to the size dimension as shown in *Figure 12-15.* When



FIGURE 12-14 *Between symbol.*

FIGURE 12-15 *Statistical tolerance symbol.*

FIGURE 12-16 *Symbol indicating the specified tolerance is a statistical geometric tolerance.*

the tolerance is a statistical geometric tolerance, the symbol is placed in the feature control frame as shown in *Figure 12-16.*

Datums

Datums are theoretically perfect points, lines, axes, surfaces, or planes used for referencing features of an object. They are established by the physical datum features that are identified on the drawing. Identification of datum features is done by using a *datum feature symbol.* This symbol consists of a capital letter enclosed in a square frame. A leader line extends from the frame to the selected feature. A triangle is attached to the end of the leader and is applied in the appropriate way to indicate a datum feature. The symbols should only be applied to physical features. They should not be attached to center lines, axes, center planes, or other theoretical entities. *Figure 12-17* shows two ways in which datum feature symbols are placed on drawings. The datum symbol is attached to an extension line of the feature outline, clearly separated from the dimension line when the datum feature is a surface or placed on the visible outline of a feature surface.

In *Figures 12-18A, 12-18B,* and *12-18C,* the datum feature symbol is placed on an extension of the dimension line of a feature of size when the datum is



FIGURE 12-17 *Datum feature symbols on a feature surface and an extension line.*

an axis or center plane. In *Figures 12-18D, 12-18E,* and *12-18F,* the datum is an axis. The symbol can be placed on the outline of a cylindrical surface or an extension line of the feature outline, separated from the size dimension. Figure 12-18F shows one arrow of the dimension line being replaced by the datum feature triangle when space is limited. If no feature control frame is used, the symbol is placed on a dimension leader line to the feature size dimension as seen by the example of Datum B in *Figure 12-19.* In *Figure 12-20* the symbol is attached to the feature control frame below (or above) when the feature(s) controlled is a datum center plane.

Establishing Datums

In establishing datums, designers must consider the function of the part, the manufacturing processes



FIGURE 12-18 *Placement of datum feature symbols on features of size.*



NOTE: UNTOLERANCED DIMENSIONS LOCATING TRUE POSITION ARE BASIC

FIGURE 12-19 *Datum reference on dimension leader line.*



FIGURE 12-20 *Placement of datum feature symbol in conjunction with a feature control frame.*

that will be used in producing the part, how the part will be inspected, and the part's relationship to other parts after assembly. Designers and drafters must also understand the difference between a datum, datum feature, datum feature simulator, datum surface, datum plane, and a datum feature of size.

A datum is theoretical in nature and is located by the physical datum features identified on the drawing. A datum is considered to be the true geometric counterpart of the feature. It is the origin from which measurements are made, or that provides geometrical references to which other features are established.

A *datum feature* is the physical feature on a part used to establish a datum, ***Figure 12-21.*** It is identified on a drawing by use of a datum feature symbol, ***Figure 12-22.***

A *datum feature simulator* is a surface, the form of which is of such precise accuracy (such as a surface plate, a gage surface, or a mandrel) that it is used to simulate the datum. The datum feature simulator contacts the datum feature(s) and simulates the theoretical datum. Simulation is necessary because measurements cannot be made from the theoretical true geometric counterpart. It is therefore necessary to use high-quality geometric features to simulate datums. Although the features are not perfect, they are of such a quality that they can be used for that purpose. ***Figures 12-23*** and ***12-24*** illustrate this concept with respect to a surface and a feature of size.

A *datum surface* (feature) is the inexact surface of the object used to establish a datum plane. A *datum plane* is a theoretically perfect plane from which measurements are made. Since inaccuracies and variations in the surface condition of the datum surface make it impractical to take measurements from, then a theoretically perfect plane must be established from which measurements are made. To establish this datum plane, the high points of the datum surface are brought into contact with, in this case, a surface plate, which simulates the datum plane. This concept is illustrated in Figure 12-21.



FIGURE 12-21 *Datum feature, simulated datum, and theoretical datum plane.*



FIGURE 12-22 *Datum feature symbol.*

Notice the irregularities on the datum surface. The high points on the datum surface actually establish the datum plane, which, in this case, is the top of the manufacturing equipment. All measurements referenced to DATUM A are measured from the theoretically perfect datum plane. High point contact is used for establishing datums when the entire surface in question will be a machined surface.

A datum feature of size is established by associating the datum feature symbol with the size dimension of the selected feature size. When identified, the theoretical datum is the axis, center line, or center plane of the true geometric counterpart. It is simulated by the processing equipment (such as a chuck, vise, or centering device). The datum feature simulator establishes the datum axis, center line, or center plane from which measurements can be referenced. This concept is illustrated in Figures 12-23 and 12-24.

Datum Targets

On rougher, more irregular surfaces, such as those associated with castings, specified points, lines, or area contacts are used for establishing datums. Datum targets designate specific points, lines, or areas of contact on a part that are used in establishing a datum. They are used when it is not always practical to identify an entire surface as a datum feature.

A *datum target symbol* is used to identify datum targets. It consists of a circle divided in half with a



FIGURE 12-23 *Primary external datum diameter with datum feature simulator.*



FIGURE 12-24 *Primary internal datum diameter with datum feature simulator.*

horizontal line. The lower portion contains the datum identifying letter followed by a datum target number. The numbers are sequential, starting with one for each datum. The letter and number establish a target label to identify planes or axes as datums. The upper half of the symbol is normally empty except when one uses a diameter symbol followed by a value to identify the shape and size of the target area, *Figure 12-25*. *Figure 12-26* shows a part using the datum's target areas to establish a datum plane.

Dimensions used to locate targets may be *basic dimensions* or toleranced dimensions. A basic dimension is a theoretically perfect dimension, much like a nominal or design dimension. The dimension is identified by enclosing the value in a rectangular box as shown in *Figure 12-27*. Tolerances placed in general notes or within the title block do not apply to basic



FIGURE 12-25 *Datum target symbol.*





FIGURE 12-26 *Primary datum plane established by three datum target areas.*



FIGURE 12-27 *Basic dimension symbol.*

dimensions. In ***Figure 12-28,*** the datum targets are located using basic dimensions. Points are located relative to one another and dimensioned to show the relationship between targets.

When specific datum target points are used for establishing datums, a minimum of three points, not in a straight line, are required for the primary datum, a minimum of two for the secondary, and a minimum of one for the tertiary, Figure 12-28. In Figure 12-28, primary datum plane A is the top of the object, and it is established by points A1, A2, and A3. Secondary datum plane B is the front of the object, and tertiary datum plane C is the right side. The datum feature symbol is placed on a drawing in the view where the surface in question appears as an edge.

Notice also that the secondary datum must be perpendicular to the first, and the tertiary datum must be perpendicular to both the primary and secondary datums. These three mutually perpendicular datum planes establish what is called the datum reference frame. The *datum reference frame* is a hypothetical, three-dimensional frame that establishes the three axes of an X, Y, and Z coordinate system into which the object being produced fits and from which measurements can be made. ***Figure 12-29*** shows an object located within a datum reference frame. For features that have sides (for example, rectangular and square objects), it takes three datums to establish a datum reference frame.

For cylindrical features, a complete reference frame is established with two datum references. ***Figure 12-30*** shows an object within a reference frame.



FIGURE 12-28 *Dimensioning datum targets.*



FIGURE 12-29 *Datum reference frame.*



(A)



(B)

FIGURE 12-30 *Part with cylindrical datum feature.*

Datum D is the primary datum feature and is used to establish datum plane K. Notice that datum feature E is established by two theoretical planes intersecting at right angles on the datum axis. The datum axis becomes the origin of measurements to locate other features on the object. Datum feature E uses the second and third planes to locate the datum axis. The reference frame is thus established using two datums.

Figure 12-31 is an example of a "basic dimension." A basic dimension is a theoretically perfect dimension, much like a nominal or design dimension, that is used to locate or specify the size of a feature. Basic dimensions are enclosed in rectangular boxes, as shown in Figure 12-31.



FIGURE 12-31 *Basic dimensions.*



FIGURE 12-32 *Order of elements in a feature control symbol.*

Feature Control Symbol

The *feature control symbol* is a rectangular box in which all data referring to the subject feature control are placed, including the symbol, datum references, the feature control tolerance, and modifiers. These various feature control elements are separated by vertical lines. (Figure 12-5 contains a drawing showing how feature control symbols are actually composed.)

The order of the data contained in a feature control frame is important. The first element is the feature control symbol. Next is the zone descriptor, such as a diameter symbol where applicable. Then, there is the feature control tolerance, modifiers when used, and datum references listed in order from left to right, *Figure 12-32.*

Figures 12-33 through *12-37* illustrate how feature control symbols are developed for a variety of design situations. Figure 12-33 is a feature control symbol that specifies a .005 tolerance for flatness and no datum reference. Figure 12-34 specifies a tolerance of .005 for the true position of a feature relative to Datum A. Figures 12-35 and 12-36 show the proper methods for constructing feature control symbols with two and three datum references, respectively. Figure 12-37 illustrates a feature control symbol with a modifier and a controlled datum added.

True Position

True position is the theoretically exact location of the center line of a product feature such as a hole. The tolerance zone created by a position tolerance is an imaginary cylinder, the diameter of which is equal to the stated position tolerance. The dimensions used to locate a feature that is to have a position tolerance must be basic dimensions.



FIGURE 12-33 *Feature control symbol with no datum reference.*



FIGURE 12-34 *Feature control symbol with one datum reference.*



FIGURE 12-35 *Feature control symbol with two datum references.*



FIGURE 12-36 *Feature control symbol with three datum references.*



FIGURE 12-37 *Feature control symbol with a modifier.*

Figure 12-38 contains an example of a part with two holes drilled through it. The holes have a position tolerance relative to three datums: A, B, and C. The holes are located by basic dimensions. The feature control frame states that the positions of the center



FIGURE 12-38 *True position.*



FIGURE 12-39 *Cylindrical tolerance zone.*

lines of the holes must fall within cylindrical tolerance zones having diameters of .030″ at MMC relative to DATUMS A, B, and C. The modifier indicates that the .030″ tolerance applies only at MMC. As the holes are produced larger than MMC, the diameter of the tolerance zones can be increased correspondingly.

Figure 12-39 illustrates the concept of the cylindrical tolerance zone from Figure 12-38. The feature control frame is repeated showing a .030″ diameter tolerance zone. The broken-out section of the object from Figure 12-38 provides the interpretation. The cylindrical tolerance zone is shown in phantom lines. The center line of the hole is acceptable as long as it falls anywhere within the hypothetical cylinder.

Using the Projected Tolerance Zone Modifier

ASME recommends the use of the projected tolerance zone concept when the variation in perpendiculars of threaded or press-fit holes could cause fasteners, such as screws, studs, or pins, to interfere with mating parts.

The attitude of a threaded fastener is controlled by the inclination of the threaded hole into which it will assemble. There are instances where the inclination can be such that the fastener interferes with the mating feature. One method of overcoming this problem is to use a projected tolerance zone. When projected, the tolerance zone's intended outcome is to decrease the inclination of the fastener passing through the mating part. It is often thought that the tolerance zone extends through the feature being controlled to a point beyond the part equal to the projection, but this is not the case. Instead, the controlled feature has no internal tolerance; the zone is totally outside of the feature being controlled. The height of the zone is equal to the value specified within the feature control frame. *Figure 12-40* illustrates this concept.

The projected tolerance zone symbol is a capital P enclosed by a circle. It is placed within the feature control frame following the tolerance value or modifier where applicable. The projection height is placed after the projected tolerance zone symbol, as illustrated in Figure 12-40. When a projected tolerance zone modifier is used, the surface from which the tolerance is projected is identified as a datum and the length of the projected tolerance zone is specified. In cases where it is not clear from which surface the projection extends, such as a through hole, a heavy chain line is used with a dimension applied to it, as illustrated in *Figure 12-41*. The resultant tolerance zone lies totally outside the feature being controlled.



FIGURE 12-40 *Specified projected tolerance zone.*



FIGURE 12-41 *Projected tolerance zone using chain line.*

Flatness

Flatness is a feature control of a surface that requires all elements of the surface to lie within two hypothetical parallel planes. When flatness is the feature control, a datum reference is neither required nor proper.

Flatness is applied by means of a leader pointing to the surface or by an extension line of the surface. It cannot be attached to the size dimension. The modifiers M or L cannot be used with flatness because it is a surface control only. The flatness tolerance is not additive and must be less than the tolerance of size of the part unless the appropriate note is added exempting it from Rule #1 requirements.

Figure 12-42 shows how flatness is called out in a drawing and the effect such a callout has on the produced part. The surface indicated must be flat within a tolerance zone of .010, as shown in Figure 12-42.

Flatness is specified when size tolerances alone are not sufficient to control the form and quality of the surface and when a surface must be flat enough to provide a stable base or a smooth interface with a mating part.

Flatness is inspected for a full indicator movement (FIM) using a dial indicator. FIM is the newer term that has replaced the older "total indicator movement" or TIR. FIM means that the swing of the indicator needle from one extreme to the other cannot exceed the amount of the specified tolerance. The dial indicator is set to run parallel to a surface table that is a theoretically perfect surface. The dial indicator is mounted on a stand or height gage. The machined surface is run



FIGURE 12-42 *Flatness.*

under it, allowing the dial indicator to detect irregularities that fall outside of the tolerance zone.

Straightness

A *straightness* tolerance can be used to control surface elements, an axis, or a center plane. When used to control single elements for a flat surface, it is applied in the view where the element to be controlled is a straight line. When applied, it controls line elements in only one direction. It differs from flatness in that flatness covers an entire surface rather than just single elements on a surface. A straightness tolerance yields a tolerance zone of a specified width, within which all points on the line in question must lie. Straightness is generally applied to longitudinal elements.

Another difference between straightness and flatness concerns the application of the feature control frame. The method in which the feature control frame is applied, determines the intended control. If the feature control frame is attached to an extension line of the surface or attached to a leader pointing to the surface, the intended control is to the surface, *Figure 12-43A*. However, if the feature control frame is attached to a dimension line or adjacent to a dimension, the intended control is an axis or center plane, *Figure 12-43B*. Drastically different results are realized based on the application method.

Straightness of a Flat Surface

Figure 12-44 shows how a straightness tolerance is applied on a drawing to the elements of a flat surface. The straightness tolerance applies only to the top surface. The bottom surface straightness error is controlled by the limits of size. In this case, the straightness tolerance is used as a refinement for the top surface only. The feature control frame states that any longitudinal element for the referenced surface, in the direction indicated, must lie between two parallel straight lines that are .002″ apart.

Straightness of a Cylindrical Surface

Straightness applied to the surface of a cylindrical feature is shown in *Figure 12-45*. It is similar to that



FIGURE 12-43 *Dimensioning and tolerancing.*



FIGURE 12-44 *Straightness of a flat surface.*



FIGURE 12-45 *Straightness of surface elements.*



FIGURE 12-46 *Straightness interpreted.*

of a flat surface, with one exception. Since the surface is round, opposing surface line elements must also be considered when verifying straightness. The full straightness tolerance may not be available for these elements due to conditions such as wasting or barreling of the surface. Additionally, the straightness tolerance is not additive to the size tolerance and must be contained within the limits of size. This means that if the part is made at MMC, no straightness tolerance is available because any variation in surface straightness would cause the part to exceed the MMC boundary of size. ***Figure 12-46*** illustrates the relationship between a straightness tolerance and a size tolerance of a part. Remember, each element of the surface must stay within the specified straightness tolerance zone and within the size tolerance envelope. Straightness is affected by running the single-line elements of a surface under a dial indicator for a full indicator movement (FIM).

Figures 12-47 through 12-52 further illustrate the concept of straightness. ***Figure 12-47*** shows a part with a size tolerance, but no feature control tolerance. In this example, the form of the feature is controlled by the size tolerance. The difference between maximum and minimum limits defines the maximum form variation that is allowed. ASME Y14.5M outlines the requirements of form control for individual features controlled only with a size dimension. This requirement is known as *Rule #1*. According to the standard, Rule #1 states: "Where only a tolerance size is specified, the limits of size of an individual feature define the extent to which variations in its geometric form, as well as size, are allowed." This means that the size limits of a part determine the maximum and minimum limits (boundaries) for that part. The MMC limit establishes a boundary limit of perfect form. If a



MANUFACTURED SIZE	.504	.503	.502	.501	.500
OUT-OF-STRAIGHTNESS	.000	.001	.002	.003	.004

FIGURE 12-47 *Object with no feature control symbol (Rule #1 applies).*



MANUFACTURED SIZE	.504	.503	.502	.501	.500
OUT-OF-STRAIGHTNESS	.000	.001	.002	.002	.002

FIGURE 12-48 *Straightness at RFS.*

part is at MMC, it must have perfect form. No variation in form is allowed. As the part varies in size toward LMC, the form of the part is allowed to vary equal to the variation in size from MMC. When the part is made at LMC, the form variation is equal to the difference between the MMC and LMC sizes as illustrated in Figure 12-47.

Figure 12-48 is the same part with a straightness tolerance of .002 regardless of feature size tolerance. The implied regardless of feature size tolerance limits the amount the surface can be out of straightness to a maximum of .002 regardless of the produced size of the part. However, because the straightness control is on a cylindrical surface, the .002 tolerance might not be available as the part approaches MMC. The drawing at the top of the figure illustrates how the part would be drawn. The five illustrations below the part as drawn illustrate the actual shape of the object with each corresponding produced size and the available tolerance.

Straightness of an Axis or Center Plane

To locate the axis of a part, the size of the part must be known. To locate the center plane of two parallel features, the distance between the features must be known. These are two examples of what is known as features of size. Logically, then, to control the axis of a part the feature control frame must be applied to the size dimension of that part, or to control the center plane of a rectangular part it must be applied to the size dimension, Figure 12-43B. When straightness is applied to control the axis of the feature, the tolerance zone is cylindrical and extends the full length of the controlled feature. Straightness applied to control the center plane of a noncylindrical feature is shown in *Figure 12-49*. It is similar to that of straightness of a cylindrical feature, except that the tolerance zone is a width and no diameter symbol is used within the feature control frame.

Straightness applied to the axis or center plane of a feature creates a boundary condition known as *virtual condition*. Virtual condition in ASME Y14.5 is defined as follows: "A constant boundary generated by the collective effects of a size feature's specified MMC or LMC and the geometric tolerance for that material condition." This means that you are allowed to add the straightness tolerance to the MMC size for



FIGURE 12-49 *Straightness.*

a shaft and subtract the straightness tolerance from the MMC size for a hole. The resultant boundary represents the extreme form variation allowed for the part. Although this boundary is theoretical, it represents the size boundary of mating features. Unlike straightness of a surface control, a straightness control of an axis or center plane allows for the availability of straightness tolerance even when the part is made at MMC. Axis or center plane control of a feature becomes more desirable because of the increased availability of tolerance and better control of mating features.

Figure 12-50 is the same part as in the previous examples with a straightness tolerance of .002 at maximum material condition applied. The use of the MMC modifier is limited to tolerances controlling the axis or center plane of features. It specifies the tolerance allowed when the part is produced at MMC. The drawing at the top of the figure illustrates how the part would be drawn. The five illustrations below the part as drawn illustrate the actual shape of the object with each corresponding produced size. A virtual condition boundary of .506 is created. When the part is at .504, the .506 virtual condition boundary allows for straightness of .002 at MMC. Since the .002 straightness tolerance applies at maximum material condition, the amount that the part can be out of straightness increases correspondingly as the



MANUFACTURED SIZE	.504	.503	.502	.501	.500
OUT-OF-STRAIGHTNESS	.002	.003	.004	.005	.006

FIGURE 12-50 *Straightness of an axis at MMC.*



MANUFACTURED SIZE	.504	.503	.502	.501	.500
OUT-OF-STRAIGHTNESS	.006	.005	.004	.003	.002

FIGURE 12-51 *Straightness of an axis at LMC.*

produced size decreases. The table at the bottom of Figure 12-50 summarizes the manufactured sizes and the corresponding amounts that the part can be out of straightness for each size.

Figure 12-51 is an example of the same part with a .002 straightness tolerance at least material condition (LMC). It specifies the tolerance allowed when the part is produced at LMC. This results in the opposite effect of what occurred in Figure 12-49. Notice that the .002 straightness tolerance applies at the least material condition. As the actual produced size increases, the amount of out of straightness allowed increases correspondingly.

Figure 12-52 illustrates the same part from a .002 straightness tolerance and a regardless of feature size tolerance. Notice in this example that the .002 straightness tolerance applies regardless of the actual produced size of the part.

Circularity (Roundness)

Circularity, sometimes referred to as roundness, is a feature control for a surface of revolution (cylinder, sphere, cone, and so forth). It specifies that all points of a surface must be equidistant from the center line or axis of the object in question. The tolerance zone



MANUFACTURED SIZE	.504	.503	.502	.501	.500
OUT-OF-STRAIGHTNESS	.002	.002	.002	.002	.002

FIGURE 12-52 *Straightness of an axis at RFS.*

for circularity is formed by two concentric and coplanar circles between which all points on the surface of revolution must lie.

Figures 12-53 and *12-54* illustrate how circularity is called out on a drawing and provides an interpretation of what the circularity tolerance actually means. At any selected cross section of the part, all points on the surface must fall within the zone created by the two concentric circles. At any point where circularity is measured, it must fall within the size tolerance. Notice that a circularity tolerance cannot specify a datum reference.

Circularity establishes elemental single-line tolerance zones that may be located anywhere along a surface. The tolerance zones are taken at any cross section of the feature. Therefore, the object may be spherical, cylindrical, tapered, or even hourglass shaped so long as the cross section for inspection is taken at 90° to the nominal axis of the object. A circularity tolerance is inspected using a dial indicator and making readings relative to the axis of the feature. In measuring a circularity tolerance, the full indicator movement (FIM) of the dial indicator should not be any larger than the size tolerance, and there should be several measurements made at different points along the surface of the diameter. All measurements taken must fall within the circularity tolerance.



MEANS EACH CIRCULAR ELEMENT OF THE SURFACE IN A PLANE PERPENDICULAR TO AN AXIS MUST LIE BETWEEN TWO CONCENTRIC CIRCLES, ONE HAVING A RADIUS .007 LARGER THAN THE OTHER. EACH CIRCULAR ELEMENT OF THE SURFACE MUST BE WITHIN THE SPECIFIED LIMITS OF SIZE.

FIGURE 12-53 *Circularity for a cylinder or cone.*



EACH CIRCULAR ELEMENT OF THE SURFACE IN A PLANE PASSING THROUGH A COMMON CENTER MUST LIE BETWEEN TWO CONCENTRIC CIRCLES, ONE HAVING A RADIUS 0.25 LARGER THAN THE OTHER. EACH CIRCULAR ELEMENT OF THE SURFACE MUST BE WITHIN THE SPECIFIED LIMITS OF SIZE.

FIGURE 12-54 *Circularity for a sphere.*

Cylindricity

Cylindricity is a feature control in which all elements of a surface of revolution form a cylinder. It gives the effect of circularity extended the entire length of the object, rather than just a specified cross section. The tolerance zone is formed by two hypothetical concentric cylinders.

Figure 12-55 illustrates how cylindricity is called out on a drawing. Notice that a cylindricity tolerance does not require a datum reference.



FIGURE 12-55 *Specifying cylindricity.*

Figure 12-55 also provides an illustration of what the cylindricity tolerance actually means. Two hypothetical concentric cylinders form the tolerance zone. The outside cylinder is established by the outer limits of the object at its produced size within specified size limits. The inner cylinder is smaller (on radius) by a distance equal to the cylindricity tolerance.

Cylindricity requires that all elements on the surface fall within the size tolerance and the tolerance established by the feature control.

A cylindricity tolerance must be less than the size tolerance, and it is not additive to the maximum material condition of the feature. Cylindricity is inspected using a dial indicator and making readings relative to the axis of the feature. In measuring cylindricity tolerance, the full indicator movement (FIM) of the dial indicator should not be any larger than the size tolerance. The part is rotated as the indicator is moved simultaneously along the surface of the diameter. At no point can the full indicator movement exceed the tolerance specified.

Angularity

Angularity is a feature control in which a given surface, axis, or center plane must form a specified angle other than 90° with a datum. Consequently, an angularity tolerance requires one or more datum references. The tolerance zone formed by an angularity callout consists of two hypothetical parallel planes that form the specified angle with the datum. All points on the angular surface or along the angular axis must lie between these parallel planes.



FIGURE 12-56 *Specifying angularity for a surface.*

Angularity of a Surface

Figure 12-56 illustrates how an angularity tolerance on a surface is called out on a drawing. Notice that the specified angle is basic. This is required when applying an angularity tolerance. Figure 12-56 also provides an interpretation of what the angularity tolerance actually means. The surface must lie between two parallel planes of .02 apart that are inclined at a 30° basic angle to datum plane A.

Angularity also controls the flatness of the surface to the same extent that it controls the angular orientation. When it is required that the flatness of the feature be less than the orientation, a flatness callout can be used as a refinement of the orientation callout. When using flatness as a refinement, the tolerance is less than the orientation tolerance. The feature control frame is normally placed on an extension line below the orientation control, *Figure 12-57.*

Angularity of an Axis or Center Plane

An angularity callout can also be used to control the axis or center plane of a feature. This is done by placing the feature control frame with the size dimension



FIGURE 12-57 *Angularity with flatness refinement.*



FIGURE 12-58 *Angularity for an axis (cylindrical tolerance zone).*

in an appropriate manner as seen in *Figure 12-58.* The tolerance zone for an axis control can be cylindrical in shape or two parallel planes. When the diameter symbol is used within the feature control frame, the tolerance zone is cylindrical. When no diameter is used, the tolerance zone shape is two parallel planes, *Figure 12-59.*



FIGURE 12-59 *Angularity for an axis (two parallel planes).* (From ASME Y14.5M–1994)

Parallelism

Parallelism is a feature control that specifies that all points on a given surface, axis, line, or center plane must be equidistant from a datum. Consequently, a parallelism tolerance requires one or more datum references. A parallelism tolerance zone is formed by two hypothetical parallel planes that are parallel to a specified datum. They are spaced apart at a distance equal to the parallelism tolerance.

Parallelism of a Surface

Figure 12-60 illustrates how a parallelism is called out on a drawing and provides an interpretation of what the parallelism tolerance actually means. Notice that all elements of the toleranced surface must fall within the size limits.



FIGURE 12-60 *Parallelism for a surface to datum plane.*

Notice in Figure 12-60 that the .006 parallelism tolerance is called out relative to Datum A. You must specify a datum when calling out a parallelism tolerance. Parallelism should be specified when features such as surfaces, axes, and planes are required to lie in a common orientation. Parallelism is inspected by placing the part on an inspection table and running a dial indicator a full indicator movement across the surface of the part.

Parallelism also controls the flatness of the surface to the same extent that it controls parallel orientation. When it is required that the flatness of the feature be less than the orientation, a flatness callout can be used as a refinement of the orientation callout. When using flatness as a refinement, the tolerance is less than the orientation tolerance. The feature control frame is normally placed on an extension line below the orientation control, *Figure 12-61.*



FIGURE 12-61 *Parallelism with flatness refinement.*

Parallelism of an Axis or Center Plane

Parallelism can be used to control the orientation of an axis to a datum plane, an axis to an axis, or the center plane of noncylindrical parts. When applied to control the axis or center plane, the feature control frame must be placed with the size dimension in the appropriate fashion. When used to control an axis to a datum plane, the tolerance zone shape is two parallel planes separated by the amount of the stated tolerance. The tolerance control is only applicable relative to the specified datum surface, *Figure 12-62.* Virtual condition exists for the controlled feature, which allows for the availability of additional tolerance. The



FIGURE 12-62 *Parallelism for an axis to datum plane.*



REGARDLESS OF FEATURE SIZE, THE FEATURE AXIS MUST LIE WITHIN A .010 DIAMETER CYLINDRICAL ZONE PARALLEL TO DATUM AXIS A. THE FEATURE AXIS MUST BE WITHIN THE SPECIFIED TOLERANCE OF LOCATION.

FIGURE 12-63 *Parallelism for an axis to datum axis.*

M and L modifiers can be used because we are controlling a feature of size.

When used to control an axis to a datum axis, the tolerance zone shape is cylindrical and the diameter is equal to the amount of the stated tolerance. The tolerance control is three-dimensional, allowing the axis to float relative to the orientation of the datum, *Figure 12-63*. Virtual condition exists for the controlled feature, which allows for the availability of additional tolerance. The M and L modifiers can be used because we are controlling a feature of size.

When used to control a center plane to a datum plane or a center plane to a center plane, the tolerance zone is similar to that of an axis to a surface or an axis to a datum axis. However, the tolerance zone shape is never cylindrical. The shape is two parallel planes separated by the amount of the stated tolerance. Virtual condition exists for the controlled feature, which allows for the availability of additional tolerance. The M and L modifiers can be used because we are controlling a feature of size.

Perpendicularity

Perpendicularity is a feature control that specifies that all elements of a surface, axis, center plane, or line form a 90° angle with a datum. Consequently, a perpendicularity tolerance requires a datum reference. A perpendicularity tolerance is formed by two hypothetical parallel planes that are at 90° to a specified datum. They are spaced apart at a distance equal to the perpendicularity tolerance.

Perpendicularity of a Surface

Figure 12-64 illustrates how a perpendicularity tolerance is called out on a drawing and provides an interpretation of what the perpendicularity tolerance actually means. The elements of the toleranced surface must fall within the size limits and between two hypothetical parallel planes that are a distance apart equal to the perpendicularity tolerance.

The perpendicularity of a part such as the one shown in Figure 12-64 could be inspected by clamping the part to an inspection angle. The datum surface should rest against the inspection angle. Then a dial indicator should be passed over the entire surface for a full indicator movement to determine if the perpendicularity tolerance has been complied with.



THE SURFACE MUST LIE BETWEEN TWO PARALLEL PLANES .010 APART THAT ARE PERPENDICULAR TO DATUM PLANE F. THE SURFACE MUST BE WITHIN THE SPECIFIED LIMITS OF SIZE.

FIGURE 12-64 *Perpendicularity for a surface to a datum plane.*



FIGURE 12-65 *Perpendicularity with flatness refinement.*

Perpendicularity also controls the flatness of the surface to the same extent that it controls orientation. When it is required that the flatness of the feature be less than the orientation, a flatness callout can be used as a refinement of the orientation callout. When using flatness as a refinement, the tolerance is less than the orientation tolerance. The feature control frame is normally placed on an extension line below the orientation control, *Figure 12-65.*

Perpendicularity of an Axis or Center Plane

Perpendicularity can be used to control the orientation of an axis to a datum plane, an axis to an axis, or the center plane of noncylindrical parts. When applied to control the axis or center plane, the feature control frame must be placed with the size dimension in the appropriate fashion. When used to control an axis to a datum plane, the tolerance zone shape is cylindrical, and its diameter equals the amount of the stated tolerance. The tolerance control is three-dimensional, allowing the axis to be at any orientation relative to the specified datum surface, *Figure 12-66.* Virtual condition exists for the controlled feature, which allows for the availability of additional tolerance. The M and L modifiers can be used because we are controlling a feature of size.

When used to control an axis to a datum axis, the tolerance zone shape is two parallel planes that are separated by a distance equal to the amount of the stated tolerance. The tolerance control is only applicable relative to the orientation of the datum, *Figure 12-67.* Virtual condition exists for the controlled feature, which allows for the availability of additional tolerance. The M and L modifiers can be used because we are controlling a feature of size.

When used to control a center plane to a datum plane or a center plane to a center plane, the tolerance similarity to that of an axis to a surface or an



FIGURE 12-66 *Perpendicularity for an axis to a datum plane.*



FIGURE 12-67 *Perpendicularity for an axis to a datum axis.*

axis to a datum axis. However, the tolerance zone shape is never cylindrical. The shape is two parallel planes separated by the amount of the stated tolerance. Virtual condition exists for the controlled feature, which allows for the availability of additional tolerance. The M and L modifiers can be used because we are controlling a feature of size.

Profile

Profile is a feature control that specifies the amount of allowable variance of a surface or line elements on a surface. There are three different variations of the profile tolerance: unilateral (inside), unilateral (outside), and bilateral (unequal distribution), ***Figure 12-68.*** A profile tolerance is normally used for controlling arcs,



FIGURE 12-68 *Application of profile of a surface.*



FIGURE 12-69 *Profile of a line with size control.*

curves, and other unusual profiles not covered by the other feature controls. It is a valuable feature control for use on objects that are so irregular that other feature controls do not easily apply.

When applying a profile tolerance, the symbol used indicates whether the designer intends profile of a line or profile of a surface, ***Figures 12-69*** and ***12-70*** (pages 513–514). *Profile of a line* establishes a tolerance for a given single element of a surface. *Profile of a surface* applies to the entire surface. The difference between profile of a line and profile of a surface is similar to the difference between circularity and cylindricity.

When using a profile tolerance, drafters and designers should remember to use phantom lines to indicate whether the tolerance is applied unilaterally up or unilaterally down. A bilateral profile tolerance requires no phantom lines. An ALL AROUND symbol should also be placed on the leader line of the feature control frame to specify whether the tolerance applies ALL AROUND or between specific points on the object, ***Figure 12-71.***

Figure 12-72 provides an interpretation of what the BETWEEN A & B profile tolerance in Figure 12-71 actually means. The rounded top surface, and only the top surface, of the object must fall within the specified tolerance zone. ***Figure 12-73*** provides an interpretation of what the ALL AROUND profile tolerance in Figure 12-71 actually means. The entire surface of the object, all around the object, must fall within the specified tolerance zone.

Profile tolerances may be inspected using a dial indicator. However, because the tolerance zone must be measured at right angles to the basic true profile and perpendicular to the datum, the dial indicator must be set up to move and read in both directions. Other methods of inspecting profile tolerances are becoming more popular, however. Optical comparators are becoming widely used for inspecting profile tolerances. An optical comparator magnifies the silhouette of the part and projects it onto a screen where it is compared to a calibrated grid or template so that the profile and size tolerances may be inspected visually.



FIGURE 12-70 *Profile of a surface.*



FIGURE 12-71 *Profile "ALL AROUND."*

FIGURE 12-72 *Interpretation of "BETWEEN A & B."*



FIGURE 12-73 *Interpretation of "ALL AROUND."*

Runout

Runout is a feature control that limits the amount of deviation from perfect form allowed on surfaces or rotation through one full rotation of the object about its axis. Revolution of the object is around a datum axis. Consequently, a runout tolerance does require a datum reference.

Runout is most frequently used on objects consisting of a series of concentric cylinders and other shapes of revolution that have circular cross sections, usually, the types of objects manufactured on lathes, *Figures 12-74* and *12-75*.

Notice in Figures 12-74 and 12-75 that there are two types of runout: circular runout and total runout. The circular runout tolerance applies at any



FIGURE 12-74 *Specifying circular runout relative to a datum diameter.*



FIGURE 12-75 *Specifying total runout relative to a datum diameter.*

single-line element through which a section passes. The total runout tolerance applies along an entire surface, as illustrated in Figure 12-75. Runout is most frequently used when the actual produced size of the feature is not as important as the form, and the quality of the feature must be related to some other feature. Circular runout is inspected using a dial indicator along a single fixed position so that errors are read only along a single line. Total runout requires that the dial indicator move in both directions along the entire surface being toleranced.

Concentricity

It is not uncommon in manufacturing to have a part made up of several subparts all sharing the same center line or axis. Such a part is illustrated in *Figure 12-76.* In such a part it is critical that the center line for each subsequent subpart be concentric with the center lines



FIGURE 12-76 *Part with concentric subparts.*

of the other subparts. When this is the case, a concentricity tolerance is applied. A concentricity tolerance locates the axis of a feature relative to the axis of a datum. A concentricity tolerance deals only with the center line relationship. It does not affect the size, form, or surface quality of the part. Concentricity deals only with axial relationships. It is applied only on a regardless-of-feature-size basis. Regardless of how large or small the various subparts of an overall part are, only their axes are required to be concentric. A



FIGURE 12-77 *Concentricity tolerancing.*

concentricity tolerance creates a cylindrical tolerance zone in which all center-lines for each successive subpart of an overall part must fall. This concept is illustrated in ***Figure 12-77.*** A concentricity tolerance is inspected by a full indicator movement of a dial indicator.

Symmetry

Parts that are symmetrically disposed about the center plane of a datum feature are common in manufacturing settings. If it is necessary that a feature be located symmetrically with regard to the center plane of a datum feature, a symmetry tolerance may be applied, ***Figure 12-78.*** The part in Figure 12-78 is symmetrical about a center plane. To ensure that the part is located symmetrically with respect to the center plane, a .030 symmetry tolerance is applied. This creates a .030 tolerance zone within which the center plane in question must fall, as illustrated in the bottom portion of Figure 12-78.

Positioning

Position tolerancing is used to locate features of parts that are to be assembled and mated. Position is symbolized by a circle overlaid by a large plus sign or cross. This symbol is followed by the tolerance, a modifier when appropriate, and a reference datum, ***Figure 12-79.*** ***Figures 12-80*** and ***12-81*** illustrate the difference between conventional and position dimensioning. The tolerance dimensions shown in Figure 12-80 create a square tolerance zone. This means that the zone within which the center line being located by the dimensions must fall takes the shape of a square. As you can see in Figure 12-81, the tolerancing zone is round when position dimensioning is used. The effect of this on manufacturing is that the round tolerancing zone with position dimensioning increases the size of the tolerance zone by 57%, ***Figure 12-82.*** This means that for the same tolerance the machinist has 57% more room for error without producing an out-of-tolerance part.

When using position dimensioning, the tolerance is assumed to apply regardless of the feature size unless modified otherwise. ***Figure 12-83*** illustrates the effect of modifying a position tolerance with a maximum material condition modifier. In this example, a hole is to be drilled through a plate. The maximum diameter is .254 and the minimum diameter is .250. Therefore, the maximum material condition of the part occurs when the hole is drilled to a diameter of .250. Notice from this example that as the hole increases, the positional tolerance increases. At maximum material condition (.250 diameter), the tolerance zone has a diameter of



FIGURE 12-78 *Symmetry tolerancing.*

FIGURE 12-79 *Position symbology.*



FIGURE 12-80 *Conventional dimensioning.*



FIGURE 12-81 *Position dimensioning.*



FIGURE 12-82 *Comparison of tolerance zones.*



FIGURE 12-83 *Positioning at MMC.*

.042. At least material condition (.254 diameter), the tolerance zone increases to .046 diameter. The tolerance zone diameter increases correspondingly as the hole size increases.

Review of Datums

Fundamental to an understanding of geometric dimensioning and tolerancing is an understanding of datums. Since many engineering and drafting students find the concept of datums difficult to understand, this section will review the concept in depth. It is important to understand datums because they represent the starting point for referencing dimensions to various features on parts and for making calculations relative to those dimensions. Datums are usually physical components. However, they can also be invisible lines, planes, axes, or points that are located by calculations or as they relate to other features. Features such as diameters, widths, holes, and slots are frequently specified as datum features.

Datums are classified as primary, secondary, or tertiary, *Figure 12-84*. Three points are required to establish a primary datum. Two points are required to establish a secondary datum. One point is required to establish a tertiary datum, *Figure 12-85*. Each point used to establish a datum is called off by a datum target symbol, *Figure 12-86*. The letter designation in the datum target symbol is the datum identifier. For example, the letter A in *Figure 12-87* is the datum designator for Datum A. The number 2 in *Figure 12-88* is the point designator for Point 2. Therefore, the complete designation of A2 means Datum A-Point 2.

Figure 12-89 illustrates how the points that establish datums should be dimensioned on a drawing. In this illustration, the three points that establish Datum A are dimensioned in the top view and labeled using the datum target symbol. The two points that establish Datum B are dimensioned in the front view. The one point that establishes Datum C is dimensioned in the right-side view. *Figure 12-90*



FIGURE 12-84 *Datums.*



FIGURE 12-85 *Establishing datums.*



FIGURE 12-86 *Datum target symbol.*



FIGURE 12-87 *Datum designation.*



FIGURE 12-88 *Point designator.*



FIGURE 12-89 *Dimensioning datum points.*



FIGURE 12-90 *Datum plane versus datum surface.*



FIGURE 12-91 *Reconciling the datum surface to the datum plane.*

illustrates the concept of datum plane and datum surface. The theoretically perfect plane is represented by the top of the machine table. The less perfect actual datum surface is the bottom surface of the part. *Figure 12-91* shows how the differences between the perfect datum plane and the actual datum surface are reconciled. The three points protruding from the machine table correspond with the three points that establish Datum A. Once this difference has been reconciled, inspections of the part can be carried out.

Summary

- General tolerancing involves setting acceptable limits of deviation for manufactured parts.
- Geometric dimensioning and tolerancing involves setting tolerance limits for all characteristics of a part.
- Modifiers are symbols that can be attached to the standard geometric building blocks to alter their application or interpretation.
- MMC is when the most material exists in the part. RFS means that a tolerance of form or position or any characteristic must be maintained regardless of the actual produced size of the object.
- Projected tolerance zone is a modifier that allows a tolerance zone established by a locational tolerance to be extended a specified distance beyond a given surface.
- Datums are theoretically perfect points, lines, axes, surfaces, or planes used for referencing features of an object.
- True position is the theoretically exact location of the center line of a product feature such as a hole.

Review Questions

Answer the following questions either true or false.

1. Tolerancing means setting acceptable limits of deviation.
2. The three types of size tolerances are unilateral, location, and runout.
3. The need to tolerance more than just the size of an object led to the development of geometric dimensioning and tolerancing.
4. Geometric dimensioning specifies the allowable variation of a feature from perfect form.
5. The term *regardless of feature size* is a modifier that tells machinists that a tolerance of form or position or any characteristic must be maintained, regardless of the actual produced size of the object.
6. Datums are components of a part such as a hole, slot, surface, or boss.
7. A datum is established on a cast surface by a "flag" or symbol.

Answer the following questions by selecting the best answer.

1. Which of the following is the identification for the ASME standard on dimensioning?
   a. ASME Y14.5 M—1994
   b. ASME Y24.5 M—1992
   c. ASME Y34.5 M—1990
   d. ASME Y44.5 M—1988
2. Which of the following has the incorrect symbol?
   a. flatness ▱
   b. circularity ○
   c. straightness —
   d. true position ♦
3. Which of the following has the incorrect symbol?
   a. perpendicularity =
   b. straightness —
   c. parallelism //
   d. angularity ∠
4. Which of the following is **not** true regarding *flatness?*
   a. It differs from straightness.
   b. The term *flatness* is interchangeable with the term *straightness.*
   c. When flatness is the feature control, a datum reference is neither required nor proper.
   d. Flatness is specified when size tolerances alone are not sufficient to control the form and quality of the surface.

5. The term *least material condition* means:
   a. the opposite of MMC
   b. a condition of a feature in which it contains the least amount of material
   c. the theoretically exact location of a feature
   d. both a and b
6. Which of the following is not true regarding feature control symbols?
   a. The order of data in a feature control frame is important.
   b. The first element is the feature control symbol.
   c. Various feature control elements are separated by //.
   d. Datum references are listed in order from left to right.
7. Which of the following feature controls must have a datum reference?
   a. flatness b. straightness c. cylindricity
   d. parallelism

Chapter 12 Problems

The following problems are intended to give beginning drafters practice in applying the principles of geometric dimensioning and tolerancing.

Conventional Instructions

The steps to follow in completing the problems are as follows:

STEP 1 Study the problem carefully.

STEP 2 Make a checklist of tasks you will need to complete.

STEP 3 Center the required view or views in the work area.

STEP 4 Include all dimensions according to ASME Y14.5M—1994.

STEP 5 Recheck all work. If it's correct, neatly fill out the title block using light guidelines and freehand lettering.

NOTE: These problems do not follow current drafting standards. You are to use the information shown here to develop properly drawn, dimensioned, and toleranced drawings.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project, and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

PROBLEM 12-1

Apply tolerances so that this part is straight to within .004 at MMC.



PROBLEM 12-2

Apply tolerances so that the top surface of this part is flat to within .001 and the two sides of the slot are parallel to each other within .002 RFS.



PROBLEM 12-3

Apply tolerances so that the smaller diameter has a cylindricity tolerance of .005 and the smaller diameter is concentric to the larger diameter to within .002. The shoulder must be perpendicular to the axis of the part to within .002.



PROBLEM 12-4

Apply tolerances to locate the holes using position and basic dimensions relative to datums A-B-C.



PROBLEM 12-5

Apply angularity, true position, and parallelism tolerances of .001 to this part. Select the appropriate datums. The parallelism tolerances should be applied to the sides of the slot.



PROBLEM 12-6

Apply tolerances so that the outside diameter of the part is round to within .004 and the ends are parallel to within .001 at maximum material condition.



PROBLEM 12-7

Apply a line profile tolerance to the top of the part between points X and Y of .004. Apply position tolerances to the holes of .021, and parallelism tolerances of .001 to the two finished sides.



PROBLEM 12-8

Use the bottom of the part as Datum A and the right side of the part as Datum B. Apply surface profile tolerances of .001 to the top of the part between points X and Y.



PROBLEM 12-9

Select datums and apply tolerances in such a way as to ensure that the slot is symmetrical to within .002 with the .625 diameter hole, and the bottom surface is parallel to the top surface to within .004.



PROBLEM 12-10

Apply tolerances to this part so that the tapered end has a total runout of .002.



PROBLEM 12-11

Apply tolerances to this part so that diameters X and Z have a total runout of .02 relative to Datum A (the large diameter of the part) and line runout of .004 to the two tapered surfaces.



PROBLEM 12-12

Select datums and apply a positional tolerance of .001 at MMC to the holes, and a perpendicularity tolerance of .003 to the vertical leg of the angle.



Problems 12-13 through 12-30

For each of the remaining geometric dimensioning and tolerancing problems, examine the problem closely with an eye to the purpose that will be served by the part. Then select datums, tolerances, and feature controls as appropriate, and apply them properly to the parts. In this way you will begin to develop the skills required of a mechanical designer. Do not overdesign. Remember, the closer the tolerances, and the more feature control applied, the more expensive the part. Try to use the rule of thumb that says: "Apply only as many feature controls and tolerances as absolutely necessary to ensure that the part will properly serve its purpose after assembly."

PROBLEM 12-13



PROBLEM 12-14



PROBLEM 12-15



PROBLEM 12-16



PROBLEM 12-17



PROBLEM 12-18



PROBLEM 12-19



PROBLEM 12-20



PROBLEM 12-21



PROBLEM 12-22



PROBLEM 12-23



PROBLEM 12-24



PROBLEM 12-25



ALL UNMARKED RADII = R.06

PROBLEM 12-26



PROBLEM 12-27



PROBLEM 12-28



PROBLEM 12-29



ALL UNMARKED RADII = R.2

PROBLEM 12-30



PROBLEM 12-31

This problem deals with feature control symbols. In items 1–19, explain what each symbol means. In items 20–30, draw the required symbols.

MEANS



1) _____
2) _____
3) _____
4) _____
5) _____
6) _____
7) _____

SYMBOL	MEANS	SYMBOL	MEANS
8) Ⓜ		14) ○	
9) ⌐A⌐		15) ⌓	
10) ( )		16) ⌖	
11) R		17) Ⓢ	
12) ⌵		18) ⌀	
13) ∨		19) ⌓	

	SYMBOL
20) ANGULARITY	
21) POSITION	
22) FLATNESS	
23) PROFILE OF A SURFACE	
24) PERPENDICULARITY	
25) CIRCULAR RUNOUT	
26) STRAIGHTNESS	
27) TOTAL RUNOUT	
28) PROFILE OF A LINE	
29) CYLINDRICITY	
30) CIRCULARITY	

13

Fasteners

KEY TERMS

Angle of thread
Axis
Beveled rings
Blind hole
Bolt
Bowed rings
Butt joint
Cap screws
Crest
Depth of thread
Expanded diameter
External rings
External thread
Form
Full threads
Grooved fasteners
Grooved studs
Internal rings
Internal thread
Key
Keyseat
Lap joint
Lead
Machine screw
Major diameter
Minor diameter
Multiple thread
Permanent fasteners
Pitch
Pitch diameter
Retaining rings
Rivets
Root
Screw
Self-locking rings
Series of thread
Set screw
Single thread
Spring pin
Stud
Temporary fasteners
Thread relief
Through hole

CHAPTER OUTLINE

Classifications of fasteners • Threads • Screw thread forms • Tap and die • Threads per inch (TPI) • Pitch • Single and multiple threads • Right-hand and left-hand threads • Thread relief (undercut) • Screw, bolt, and stud • Rivets • Keys and keyseats • Grooved fasteners • Spring pins • Fastening systems • Retaining rings • Summary • Review questions • Chapter 13 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the classifications of fasteners.
- Explain the four uses of threads.
- List the various screw thread forms.
- Distinguish between the tap and die processes.
- Demonstrate two methods for measuring threads per inch.
- Define the term *pitch.*
- Distinguish between single and multiple threads.
- Demonstrate how to distinguish between right- and left-hand threads.
- Demonstrate the various methods of thread representation.
- Explain the concept of *thread relief.*
- Distinguish among the following: screw, bolt, and stud.
- Demonstrate the proper methods for drawing screws, bolts, and studs.
- Define the term *rivet.*

(continued)

(CHAPTER OBJECTIVES continued)

- Explain the concept of keys and keyseats.
- Explain how grooved fasteners are used.
- Describe the uses of spring pins.
- Explain the concept of fastening systems.
- Describe how retaining rings are used.

Classifications of Fasteners

As a new product is developed, determining how to fasten it together is a major consideration. The product must be assembled quickly, using standard, easily available, low-cost fasteners. Some products are designed to be taken apart easily—others are designed to be permanently assembled. Many considerations are required as to what kind, type, and material of fastener is to be used. Sometimes the stress load upon a joint must be considered. There are two major classifications of fasteners: permanent and temporary. *Permanent fasteners* are used when parts will not be disassembled. *Temporary fasteners* are used when the parts will be disassembled at some future time.

Permanent fastening methods include welding, brazing, stapling, nailing, gluing, and riveting. Temporary fasteners include screws, bolts, keys, and pins.

Many temporary fasteners include threads in their design. In early days, there was no such thing as standardization. Nuts and bolts from one company would not fit nuts and bolts from another company. In 1841, Sir Joseph Whitworth worked toward some kind of standardization throughout England. His efforts were finally accepted, and England came up with a standard thread form called Whitworth Threads.

In 1864, the United States tried to develop a standardization of its own but, because it would not interchange with the English Whitworth Threads, it was not adopted at that time. It was not until 1935 that the United States adopted the American Standard Thread. It was actually the same 60° V-thread form proposed back in 1864. Still, there was no standardization between countries. This created many problems, but nothing was done until World War II forced the issue of interchangeability on the Western Allies. As a result of problems experienced by the Allies, in 1948 the United States, Canada, and Great Britain developed the Unified Screw Thread. It was a compromise between the newer American Standard Thread and the old Whitworth Threads.

Today, with the changeover to the metric system, new standards are being developed. The International Organization for Standardization (ISO) was formed to develop a single international system using metric screw threads. This new ISO standard will be united with the American National Standards Institute (ANSI) standards. At the present time, we are in a transitional period, and a combination of both systems is still being used.

Threads

Threads are used for four different applications:

1. to fasten parts together, such as a nut and a bolt.
2. for fine adjustment between parts in relation to each other, such as the fine adjusting screw on a surveyor's transit.
3. for fine measurement, such as a micrometer.
4. to transmit motion or power, such as an automatic screw threading attachment on a lathe or a house jack.

There are many types and sizes of fasteners, each designed for a particular function. Permanently fastening parts together by welding or brazing is discussed in Chapter 19. Although screw threads have other important uses, such as adjusting parts and measuring and transmitting power, only their use as fasteners and only the most-used kinds of fasteners are discussed in this chapter.

Thread Terms

Refer to ***Figure 13-1*** for the following terms.

- *External thread*—Threads located on the outside of a part, such as those on a bolt.
- *Internal thread*—Threads located on the inside of a part, such as those on a nut.
- *Axis*—A longitudinal center line of the thread.
- *Major diameter*—The largest diameter of a screw thread, both external and internal.
- *Minor diameter*—The smallest diameter of a screw thread, both external and internal.
- *Pitch diameter*—The diameter of an imaginary diameter centrally located between the major diameter and the minor diameter.
- *Pitch*—The distance from a point on a screw thread to a corresponding point on the next thread, as measured parallel to the axis.
- *Root*—The bottom point joining the sides of a thread.
- *Crest*—The top point joining the sides of a thread.
- *Depth of thread*—The distance between the crest and the root of the thread, as measured at a right angle to the axis.
- *Angle of thread*—The included angle between the sides of the thread.
- *Series of thread*—A standard number of threads per inch (TPI) for each standard diameter.



FIGURE 13-1 *Thread terms.*

Screw Thread Forms

The *form* of a screw thread is actually its profile shape. There are many kinds of screw thread forms. Seven major kinds are discussed next.

Unified National Thread Form

The Unified National thread form has been the standard thread used in the United States, Canada, and the United Kingdom since 1948, *Figure 13-2A*. This thread form is used mostly for fasteners and adjustments.

ISO Metric Thread Form

The ISO metric thread form is the new standard to be used throughout the world. Its form or profile is very similar to that of the Unified National thread, except that the thread depth is slightly less, *Figure 13-2B*. This thread form is used mostly for fasteners and adjustments.

Square Thread Form

The square thread's profile is exactly as its name implies, that is, square. The faces of the teeth are at right angles to the axis and, theoretically, this is the best thread to transmit power, *Figure 13-2C*. Because this thread is difficult to manufacture, it is being replaced by the Acme thread.



FIGURE 13-2A *Unified National thread form (UN).*



FIGURE 13-2B *ISO metric thread form.*



FIGURE 13-2C *Square thread form.*

Acme Thread Form

The Acme thread is a slight modification of the square thread. It is easier to manufacture and is actually stronger than the square thread, *Figure 13-2D*. It, too, is used to transmit power.

Worm Thread Form

The worm thread is similar to the Acme thread, and it is used primarily to transmit power, *Figure 13-2E*.



FIGURE 13-2D *Acme thread form.*



FIGURE 13-2E *Worm thread form.*



FIGURE 13-2F *Knuckle thread form.*

Knuckle Thread Form

The knuckle thread is usually rolled from sheet metal and is used, slightly modified, in electric light bulbs, electric light sockets, and sometimes for bottle tops. The knuckle thread is sometimes cast, *Figure 13-2F.*

Buttress Thread Form

The buttress thread has certain advantages in applications involving exceptionally high stress along its axis in one direction only. Examples of applications



FIGURE 13-2G *Buttress thread form.*



FIGURE 13-3 *Tap and die.*

are the breech assemblies of large guns, airplane propeller hubs, and columns for hydraulic presses, *Figure 13-2G.*

Tap and Die

Various methods are used to produce inside and outside threads. The simplest method uses thread-cutting tools called taps and dies. The tap cuts internal threads; the die cuts external threads, *Figure 13-3.* In making an internal threaded hole, a tap-drilled hole must be drilled first. This hole is approximately the same diameter as the minor diameter of the threads.

Notice how the tap is tapered at the end; this taper allows the tap to start into the tap-drilled hole. This tapered area contains only partial threads.

Threads per Inch (TPI)

One method of measuring threads per inch (TPI) is to place a standard scale on the crests of the threads, parallel to the axis, and count the number of full threads within one inch of the scale, *Figure 13-4.* If only part of an inch of stock is threaded, count the number of full threads in one-half inch and multiply by two to determine TPI.

A simpler, more accurate method of determining threads per inch is to use a screw thread gage, *Figure 13-5.* By trial and error, the various fingers or



FIGURE 13-4 *Use of a scale to calculate threads per inch (TPI).*



FIGURE 13-5 *Use of a screw pitch gage.*



FIGURE 13-6 *Reading screw pitch gage.* (Courtesy the L.S. Starrett Co.)

leaves of the gage are placed over the threads until one is found that fits exactly into all the threads. Threads per inch are then read directly on each leaf of the gage, ***Figure 13-6.***

Pitch

The pitch of any thread, regardless of its thread form or profile, is the distance from one point on a thread to the corresponding point on the adjacent thread as measured parallel to its axis, ***Figure 13-7.*** Pitch is found by dividing the TPI into one inch.

In this example, a coarse thread pitch, there are 10 threads in one measured inch; 10 TPI divided into one inch equals a pitch of 10. In a fine thread of the same diameter there are 20 threads in one measured inch; 20 TPI divided into one inch equals a pitch of 20, ***Figure 13-8.***



FIGURE 13-7 *Coarse thread pitch.*



FIGURE 13-8 *Fine thread pitch.*

For metric threads, the pitch is specified in millimeters. Pitch for a metric thread is included in its call-off designation. For example: M10 × 1.5. The 1.5 indicates the pitch; therefore, it does not as a rule have to be calculated.

Single and Multiple Threads

A *single thread* is composed of one continuous ridge. The lead of a single thread is equal to the pitch. *Lead* is the distance a screw thread advances axially in one full turn. Most threads are single threads.

Multiple threads are made up of two or more continuous ridges following side-by-side. The lead of a double thread is equal to twice the pitch. The lead of a triple thread is equal to three times the pitch, ***Figure 13-9.***

Multiple threads are used when speed or travel distance is an important design factor. A good example of a double or triple thread is found in an inexpensive ballpoint pen. Take a ballpoint pen apart and study the end of the external threads. There will probably be two or three ridges starting at the end of the threads. Notice how fast the parts screw together. The speed, not power, is the characteristic of multiple threads.

Right-Hand and Left-Hand Threads

Threads can be either right-handed or left-handed. To distinguish between a right-hand and a left-hand thread, use this simple trick. A right-hand thread winding tends to lean toward the left. If the thread leans toward the left, the right-hand thumb points in



FIGURE 13-9 *Single and multiple threads.*



FIGURE 13-10 *Right-hand and left-hand threads.*

the same direction. If the thread leans to the right, *Figure 13-10*, the left-hand thumb leans in that direction indicating that it is a left-hand thread.

Thread Representation

The top illustration of *Figure 13-11* shows a normal view of an external thread. To draw a thread exactly as it will actually look takes too much drafting time. To help speed up the drawing of threads, one of two



FIGURE 13-11 *Thread representation.*



FIGURE 13-12 *How to draw threads using the schematic system.*

basic systems is used, and each is described and illustrated. The schematic system of representing threads was developed approximately in 1940, and it is still used somewhat today. The simplified system of representing threads was developed 15 years later, and it is actually quicker and in greater use today.

How to Draw Threads Using the Schematic System

STEP 1 Refer to *Figure 13-12*. Lightly draw the major diameter, and locate the approximate length of full threads.



FIGURE 13-13 *How to draw threads using the simplified system.*

STEP 2 Lightly locate the minor diameter and draw the 45° chamfered ends as illustrated. Draw lines to represent the crest of the threads spaced approximately equal to the pitch.

STEP 3 Draw slightly thicker lines centered between the crest lines to the minor diameter. These lines represent the root of the threads.

STEP 4 Check all work and darken in. Notice the crest lines are **thin** black lines and the root lines are **thick** black lines.

How to Draw Threads Using the Simplified System

STEP 1 Refer to *Figure 13-13.* Lightly draw the major diameter and locate the approximate length of full threads.

STEP 2 Locate the minor diameter and draw the 45° chamfered ends as illustrated. Draw dash lines along the minor diameter. This represents the root of the threads.

STEP 3 Check all work and darken in. The dash lines are thin black lines.

Standard External Thread Representation

The most recent standard to illustrate external threads using either the schematic or simplified system is illustrated in *Figure 13-14.* Note how section views are illustrated using schematic and simplified systems.



FIGURE 13-14 *Standard external thread representation.*

Standard Internal Thread Representation

There are two major kinds of interior holes: through holes and blind holes. A *through hole,* as its name implies, goes completely through an object. A *blind hole* is a hole that does **not** go completely through an object. In the manufacture of a blind hole, a tap drill must be drilled into the part first, *Figure 13-15.* To illustrate a tap drill, use the 30°–60° triangle. This is **not** the actual angle of a drill point, but it is close enough for illustration. The tap is now turned into the tap drill hole. Because of the taper on the tap, *full threads* do not extend to the bottom of the hole (refer back to Figure 13-3). The drafter illustrates the tap drill and the full threaded section as shown to the right in Figure 13-15.

Using the schematic system to represent a through hole is illustrated in *Figure 13-16.* A blind hole and a section view are drawn as illustrated in *Figure 13-17.*

Using the simplified system to represent a through hole is illustrated in *Figure 13-18.* A blind hole and a section view are drawn as illustrated in *Figure 13-19.*

Thread Relief (Undercut)

On exterior threads, it is impossible to make perfectly uniform threads up to a shoulder; thus, the threads tend to run out, as illustrated in *Figure 13-20.* Where mating parts must be held tightly against the shoulder, the last one or two threads must be removed or **relieved.** This is usually done no farther than to the



FIGURE 13-15 *Standard internal thread representation.*



FIGURE 13-16 *Standard internal thread representation for a through hole (schematic system).*



FIGURE 13-17 *Standard internal thread representation for a blind hole (schematic system).*

depth of the threads so as not to weaken the fastener. The simplified system of thread representation is illustrated at the bottom of Figure 13-20.

Full interior threads cannot be manufactured to the end of a blind hole. One way to eliminate this problem is to call off a thread relief or undercut, as illustrated in *Figure 13-21.* The bottom illustration is as it would be drawn by the drafter.

Screw, Bolt, and Stud

Figure 13-22 illustrates and describes a screw, a bolt, and a stud. A *screw* is a threaded fastener that does not use a nut and is screwed directly into a part.

A *bolt* is a threaded fastener that passes directly through parts to hold them together and uses a nut to tighten or hold the parts together.

A *stud* is a fastener that is a steel rod with threads at both ends. It is screwed into a blind hole and holds other parts together by a nut on its free end. In general practice, a stud has either fine threads at one end and coarse threads at the other, or Class 3-fit threads at one end and Class 2-fit threads at the other end. Class of fit is fully explained later in this chapter under "Classes of Fit."



FIGURE 13-18 *Standard internal thread representation for a through hole (simplified system).*



FIGURE 13-19 *Standard internal thread representation for a blind hole (simplified system).*

The minimum full thread length for a screw or a stud is:

In steel: equal to diameter.

In cast iron, brass, bronze: equal to 1.5 times the diameter.

In aluminum, zinc, plastic: equal to 2 times the diameter.

The clearance hole for holes up to .375 (9) diameter is approximately .03 oversize; for larger holes, .06 oversize.

Machine Screws

Machine screw sizes run from .021 (.3) to .750 (20) in diameter. There are eight standard head forms. Four



FIGURE 13-20 *External thread relief (undercut).*



FIGURE 13-21 *Internal thread relief (undercut).*

major kinds are illustrated in ***Figure 13-23.*** *Machine screws* are used for screwing into thin materials. Most machine screws are threaded within a thread or two to the head. Although these are screws, machine screws sometimes incorporate a hex-head nut to fasten parts together.

The length of a machine screw is measured from the bottom of the head to the end of the screw (refer again to Figure 13-23).

Cap Screws

Cap screw sizes run from .250 (6) and up. There are five standard head forms, ***Figure 13-24.*** A *cap screw* is usually used as a true screw, and it passes through a clearance hole in one part and screws into another part.



FIGURE 13-22 *Screw, bolt, and stud.*



FIGURE 13-23 *Machine screws.*



FIGURE 13-24 *Cap screws.*

How to Draw a Machine Screw or Cap Screw

The exact dimensions of machine screws and cap screws are given in Appendix A but, in actual practice, they are seldom used for drawing purposes. *Figures 13-25* and *13-26* show the various sizes as they are proportioned in regard to the diameter of the fastener. Various fastener templates are now available to further speed up drafting time.

Set Screws

A *set screw* is used to prevent motion between mating parts, such as the hub of a pulley on a shaft. The set



FIGURE 13-25 *Approximate sizes for machine screws or cap screws.*



FIGURE 13-26 *Approximate sizes for machine screws or cap screws.*

screw is screwed into and through one part so that it applies pressure against another part, thus preventing motion. Set screws are usually manufactured of steel, and they are hardened to make them stronger than the average fastener.

Set screws have various kinds of heads and many kinds of points. *Figure 13-27* illustrates a few of the more common kinds of set screws. Set screws are manufactured in many standard lengths of very small increments, so almost any required length is probably "standard." Exact sizes and lengths can be found in Appendix A. As with machine screws and cap screws, in actual practice, the drawing of set screws is done using their proportions in relationship to their diameters.



FIGURE 13-27 *Approximate sizes for set screws and set screw points.*

How to Draw Square- and Hex-Head Bolts

Exact dimensions for square- and hex-head bolts are given in Appendix A, but in actual practice, they are drawn using the proportions as given in *Figures 13-28* and *13-29*. Notice that the heads are shown in the profile so three surfaces are seen in the front view. In the event a square- or hex-head bolt must be illustrated 90°, the proportions as illustrated in *Figure 13-30* are used.



FIGURE 13-28 *Approximate sizes for a square-head bolt.*



FIGURE 13-29 *Approximate sizes for a hex-head bolt.*



FIGURE 13-30 *Side view of hex- and square-head bolts.*

Nuts, Bolts, and Other Fasteners in Section

If the cutting plane passes through the axis of any fastener, the fastener is **not** sectioned. It is treated exactly as a shaft and drawn exactly as it is viewed. Refer to *Figure 13-31*. The illustration at the left is drawn correctly. The figure at the right is drawn incorrectly (notice how difficult it is to understand, especially the nut).



FIGURE 13-31 *Fasteners in section.*

Thread Call-Offs

Although not all companies use the same call-offs for various fasteners, it is important that all drafters within one company use the same method. One method used to call off fasteners is illustrated in *Figure 13-32*. Regardless of which system is used, the first line contains the fastener's general identification,



FIGURE 13-32 *Thread call-off.*

FIGURE 13-33 *Kinds of screw heads.*

type of head, and classification. The second line contains all the exact detailed information. All threads are assumed to be right hand (R.H.), unless otherwise noted. If a thread is to be left hand (L.H.), it is noted at the end of the second line.

Various Kinds of Heads

Many different kinds of screw heads are used today. *Figure 13-33* illustrates a few of the standard heads.

Rivets

Rivets are permanent fasteners, usually used to hold sheet metal together. Most rivets are made of wrought iron or soft steel and, for aircraft and space missiles, copper, aluminum, alloy, or other exotic metals.

Riveted joints are classified by applications, such as pressure vessels, structural, and machine members. For data concerning joints for pressure vessels refer to such sources as ASME boiler codes. For data concerning larger field structural rivets, such as bridges, buildings, and ships, see ANSI standards or a *Machinery's Handbook*. This chapter covers information for small-size rivets for machine-member riveted joints used for lighter mass-produced applications.

Two kinds of basic rivet joints are the lap joint and the butt joint, *Figure 13-34*. In the *lap joint*, the parts overlap each other and are held together by one or more rows of rivets. In the *butt joint*, the parts are butted and are held together by a cover plate or butt strap that is riveted to both parts.



FIGURE 13-34 *Two basic rivet joints (lap joint and butt joint).*

Factors to consider are type of joint, pitch of rivets, type and diameter of rivet, rivet material, and size of clearance holes, *Figure 13-35*. The diameter of a rivet is calculated from the thickness of metal and commonly ranges between

$$d = 1.2\ \sqrt{t} \text{ AND } d = 1.4\ \sqrt{t}$$

where d is the diameter and t is the thickness of the plate.

Size and Type of Hole

Rivet holes must be punched, punched and then reamed, or drilled. As a general rule, holes are usually made .06 (1.5 mm) larger in diameter than the nominal rivet diameter.

Rivet Symbols

Rivets applied in mass-produced applications are represented in *Figure 13-36A*, illustrating the kind of rivet, to which side it is applied, if it is to be countersunk, and so forth.

Kinds of Rivets

There are many different kinds of small-size rivets. The five major kinds are truss head, button head, pan head, countersunk head, and flat head. The countersunk-head rivet is not as strong as the other kinds of rivets; therefore, more rivets must be used to gain strength equal to the other types.

Drawing of Rivets

American standard small solid rivets are shown in their approximate standard proportions in Figure 13-36A. These sizes are close enough to be used for drawing the rivet if necessary. For exact sizes, data must be obtained from other sources.



FIGURE 13-35 *Factors to consider in rivet joints.*



(A)



(B)

FIGURE 13-36 *(A) Approximate sizes for standard small rivets; (B) Illustrated rivet code.*

End Points

The end of a standard rivet is usually cut off straight. If a point is required, a standard size point is illustrated at the lower end of a countersunk head (refer back to Figure 13-36A).

The drafter must indicate what kind of rivet is to be used, and on which side the head is to be positioned. To illustrate this, the drafter uses a code such as that illustrated in *Figure 13-36B*.

Keys and Keyseats

Key

A *key* is a demountable part that provides a positive means of transferring torque between a shaft and a hub.

Keys are used to prevent slippage and to transmit torque between a shaft and a hub. There are many kinds of keys. The five major kinds used in industry today are illustrated in *Figure 13-37:* square key, flat key, gib head key, Pratt & Whitney key, and Woodruff key. Where a lot of torque is present, a double key and keyseat are often used. In extreme conditions, a spline is machined into the shaft and into the hub. For spline information, refer to a *Machinery's Handbook*.



FIGURE 13-37 *Keys and keyseats.*

Keyseat

A *keyseat* is an auxiliary-located rectangular groove machined into the shaft and/or hub to receive the key.

Classes of Fit

There are three classifications of fit:

CLASS 1 A side surface clearance fit obtained by using bar stock key and keyseat tolerances. This is a relatively free fit.

CLASS 2 A possible side surface interference or side surface clearance fit obtained by using bar stock key and keyseat tolerances. This is a relatively tight fit.

CLASS 3 A side surface interference fit obtained by interference fit tolerances. This is a very tight fit and has not been generally standardized.

Key Sizes

For a general rule, the key width is about one-fourth the nominal diameter of the shaft. For exact recommended key sizes, refer to Appendix A or a *Machinery's Handbook*.

Dimensioning Keyseats

Methods of dimensioning a stock key are shown in *Figure 13-38*.

For dimensioning a Woodruff keyseat, the key number must be included, ***Figure 13-39***. Refer to the key size in Appendix A to obtain the exact sizes. To dimension a Pratt & Whitney keyseat, see ***Figure 13-40***.



FIGURE 13-38 *Dimensioning keyseats.*

Industry Application

A FASTENER PROBLEM

The problem the design team at Reynolds Tool and Die Company faced at the beginning of the Anderson project had been fasteners. Specifically, the team had to decide how to anchor several springs that are critical components in a family of fixtures to be designed and manufactured for Anderson Aviation Company.

Using a small bolt was discussed and dismissed as being impractical because there would be a blind hole in the fixture. Without a through hole, a bolt could not be used. Various types of screws were discussed. One line of thought was that the head of the screw would anchor the end loop of the tension spring. In addition, a screw would work with a blind hole. The only negative brought up in the discussion of using a screw was the need for threads in the blind hole. The threading process would increase the cost of each fixture by 12%, a cost that had not been anticipated when the design team originally estimated the cost of the Anderson project.

The Reynolds design team was almost resigned to the 12% loss on the project when one member suggested using a grooved pin. After researching the recommendation, the team decided to use a Type G Number 2 pin 3/8" in diameter. Such a pin has locking grooves on one end to fit into the blind hole and an angular groove at the other end to hold the end loop of a tension spring.

The decision to use a grooved pin turned out to be serendipitous. Not only did the groove perform as needed, it also decreased the anticipated cost of assembling the fixtures by 9%. Consequently, Reynolds Tool and Die Company earned more than anticipated on the Anderson project.



FIGURE 13-39 *Woodruff keyseat.*



FIGURE 13-40 *Pratt & Whitney keyseat.*

Grooved Fasteners

Many types of fasteners are used in industry, each with its own application. Threaded fasteners, such as nuts and bolts, are used to hold parts in tension. *Grooved fasteners* are used to solve metal-to-metal pinning needs with shear application, ***Figure 13-41.***

Grooved fasteners have great holding power and are resistant to shock, vibration, and fatigue. They are available in a wide range of types, sizes, and materials. A grooved fastener often has a better appearance than most other methods of fastening. This can be important to the overall design, if the fastener is visible.

Grooved fasteners have three parallel grooves, equally spaced, impressed longitudinally on their exterior surface. To make these grooves, a grooving tool is pressed **below** the surface to displace a carefully determined amount of material. Nothing is removed. The metal is displaced to each side, forming a raised portion or flute extending along each side of the groove, ***Figure 13-42.*** The crest of the flute constitutes the *expanded diameter* (Dx). The expanded diameter (Dx) is a few thousandths larger than the nominal diameter (D) of the stock.

Grooved fasteners can be custom manufactured in order to meet most any application. For example, a custom-grooved pin can be made with a cross-drilled hole, a groove for a snap ring, or a threaded hole in one end. The groove length can also be varied and placed anywhere along the length of the pin.



FIGURE 13-41 *Grooved fastener.*



FIGURE 13-42 *Enlarged sectional view of one of the grooves before inserting fastener.*



FIGURE 13-43 *The same view after insertion. A powerful radial thrust is obtained.*

Installation

The grooved fastener is forced into a drilled hole slightly larger than the nominal or specified diameter of the pin, *Figure 13-43*. The crest or flutes are forced back into the grooves when the fastener is driven into the hole. The resiliency of the metal forced back into the grooves creates powerful radial forces against the hole wall.

In many cases, grooved fasteners are lower in cost than knurled pins, taper pins, pins with cotter pins, rivets, set screws, keys, or other methods used to fasten metal-to-metal parts together. The installation cost of grooved pins is invariably lower because of the required hole tolerances, and no special guides are required at assembly.

Material

Standard grooved fasteners are made of cold-drawn, low-carbon steel. The physical properties of this material are more than enough for ordinary applications. Alloy steel, hard brass, silicon bronze, stainless steel, and other exotic metals may also be specially ordered. These special materials are usually heat treated for optimum physical qualities.

Finish

Standard grooved fasteners have a finish of zinc electroplate, deposited approximately .00015 inch deep. Chromate, brass, cadmium, and black oxide can also be specially ordered.

Standard Types

Study the various types of grooved fasteners and the related technical data in ***Figures 13-44, 13-45, 13-46, 13-47*** (page 530), and ***13-48*** (page 530). Note the various types of fasteners, how each functions, and what each replaces. For example, Type A is used in place of taper pins, rivets, set screws, and keys.

Standard Sizes

Refer to the standard size charts in ***Figures 13-49*** (page 531), ***13-50*** (page 532), ***13-51*** (page 533), and ***13-52*** (page 534). Across the top of each chart are the nominal sizes from 1/16″ diameter to 1/2″ diameter. At the left side of each chart are listed the standard lengths from 1/4″ long to 4 1/2″ long. Various other technical information can be derived from the charts. For drilling procedure, hole tolerances, application data, and high-alloy pin applications, see ***Figures 13-53*** (page 535), ***13-54*** (page 535), ***13-55*** (page 536).

Grooved Studs

Grooved studs are widely used for fastening light metal or plastic parts to heavier members or assemblies, ***Figures 13-56*** (page 536) and ***13-57*** (page 537). They replace screws, rivets, preened pins, and many other types of fasteners. The grooves function as any grooved fastener.

Spring Pins

Another type of fastener is the *spring pin*, ***Figure 13-58*** (page 537). Spring pins are manufactured by cold-forming strip metal in a progressive roll-forming operation. After forming, the pins are broken off and deburred to eliminate any sharp edges. They are then heat treated to a R/C 46/53. This develops spring qualities or resiliency in the metal.

In the free state, the pins are larger in diameter than the hole into which they are to be inserted. The pins compress themselves as they are driven into the hole, thus exerting radial forces around the entire circumference of the hole.

TYPE A

The Type A DRIV-LOK pin has three **full-length tapered** grooves. This popular type is used in applications requiring excellent locking effect and ease of assembly. It is widely used in place of taper pins, rivets, set screws and keys. Typical applications include keying sprockets, gears, collars, knobs, handles, levers and wheels to shafts.



Locking Collar to Shaft



Lever and Shaft Assembly

TYPE A3



Type A3 pins have three **full-length parallel** grooves with a short pilot end to ensure easy starting. They are recommended for applications requiring maximum locking effect where severe vibration and/or shock loading are present.



Keying Gear to Shaft



Locking Gear to Shaft

TYPE U



Type U has three **parallel** grooves extending the **full length** of the pin. A short pilot at each end permits hopper or automatic feeding. Identical ends speed manual insertion as operator need not examine pin to determine proper end to start. Full-length parallel grooves provide maximum locking effect. Typical applications include keying gears, collars, knobs, handles, etc. to shafts.



Attaching Knob to Shaft



Pinning "V" Pulley to Shaft

FIGURE 13-44 *Typical applications for grooved pin types A, A3, and U.*



Type B pins have three **tapered** grooves extending **one-half** the length of the pin. This type is widely used as a hinge or pivot pin. Driven or pressed into a straight drilled hole, the grooved portion locks in one part, while the ungrooved portion will remain free. Also excellent for dowel and locating applications.

The Type C Pin has three **parallel** grooves extending **one-quarter** its overall length. It is ideally suited for linkage or pivot applications, especially where a relatively short locking section and longer free length are required. Widely used in certain types of hinge applications. The long lead permits easy insertion.



Roller Pins



Control Valve Hinge Assembly



Hinge Pins



Linkage or Hinge Pin

FIGURE 13-45 *Typical applications for grooved pin types B and C.*

Type D has three **reverse** taper grooves extending **one-half** the length of the pin. Recommended for use in blind holes as a stop pin, roller pivot, dowel, or for certain hinge or linkage applications. Reverse taper grooves permit easy insertion in blind holes.



Type E has three **parallel half-length** grooves located equidistant from each end. Widely used as T handle on valves and tools. Also used as a cross pin, cotter pin, pivot pin, etc. where center locking is required.



Roller End Pins



Linkage Pin



Stop Pins



T Handle for Valve

FIGURE 13-46 *Typical applications for grooved pin types D and E.*

TYPE G

Typical applications

Type G has three **parallel half-length** grooves including pilot. It is a very versatile pin, suitable for use in both blind and through holes as a spring anchor pin. The annular groove opposite the locking end is used to anchor the end loop of a tension spring. If snap or retainer rings are to be used, special section annular grooves can be machined to order.



Spring Anchor Pin Used in Through Hole



Spring Anchor in Blind Hole

FIGURE 13-47 *Typical application for grooved pin type G.*

1	Straight pin with annular grooves at each end designed to accommodate snap or retainer rings. Available 3/16" through 3/4" diameters.	
2	Pin with locking grooves on one end and annular groove on other end. Often used for roller or collar retention. Available 3/16" through 3/4" diameters.	
3	Straight pin with both ends chamfered. Available 1/16" through 3/4" diameters.	
4	Grooved spring anchor pin with annular grooves at both ends. Available 3/32" through 3/4" diameters.	
5	Special pin with grooves extending one-third length of pin. Groove length and position can be varied to suit specific applications. Available 1/16" through 3/4" diameters.	
6	Special straight pin with both ends chamfered and cross-drilled for cross pin or cotter. Available 1/4" through 3/4" diameters.	

FIGURE 13-48 *Special pins.*

Spring pins are made from a high-carbon steel—1074, stainless steel, either 420 heat treated or 300 series cold worked. Some spring pins are also made from brass or beryllium copper. Spring pins meet the demand of many industrial applications. ***Figures 13-59*** (page 537) and ***13-60*** (page 538) list some suggested applications.

Fastening Systems

Fastening systems play a critical role in most product design. They often do more than position and secure components. In many cases, fastening systems have a direct effect upon the product's durability, reliability, size, and weight. They affect the speed with which the product may be assembled and disassembled, both during manufacturing and later in field service. Fastening systems also affect cost, not only for the fasteners, but also for the machining and assembly operations they require.

Unless a drafter has had a great deal of experience in using different fastening devices and techniques, it is often difficult to choose a fastener that combines optimum function with maximum economy. A fastening system that is best for one product may not be desirable for another.

(Text continues on page 539)



STANDARD SIZES

Nominal diameter and recommended drill sizes	1/16	5/64	3/32	7/64	1/8	5/32	3/16	7/32	1/4	5/16	3/8	7/16	1/2
Dec. Equivalents	.0625	.0781	.0938	.1094	.1250	.1563	.1875	.2188	.2500	.3125	.3750	.4375	.5000
Crown Height, In.	.0065	.0087	.0091	.0110	.0130	.0170	.0180	.0220	.0260	.0340	.0390	.0470	.0520
Radius, In. ±.010	5/64	3/32	1/8	9/64	5/32	3/16	1/4	9/32	5/16	3/8	15/32	17/32	5/8
Pilot Length, In. (Ref.)	1/32	1/32	1/32	1/32	1/32	1/16	1/16	1/16	1/16	3/32	3/32	3/32	3/32
Chamfer Length, In. (Type U Only)	1/64	1/64	1/64	1/64	1/64	1/32	1/32	1/32	1/32	3/64	3/64	3/64	3/64
"Dx" EXPANDED DIAMETER—CAN BE DETERMINED ACCURATELY ONLY WITH RING GAGES													
LENGTH OF PIN IN INCHES													
1/4 (.250)	.068	.084	.101	.117	.134								
3/8 (.375)	.068	.084	.101	.117	.134	.166	.198						
1/2 (.500)	.068	.084	.101	.117	.134	.166	.198	.230	.263				
5/8 (.625)	.068	.084	.101	.117	.134	.166	.198	.230	.263	.329			
3/4 (.750)	.068	.084	.101	.116	.134	.166	.198	.230	.263	.329	.394		
7/8 (.875)	.068	.084	.101	.116	.133	.165	.198	.230	.263	.329	.394	.459	
1 (1.000)	.068	.084	.101	.115	.133	.165	.198	.230	.263	.329	.394	.459	.525
1 1/4 (1.250)			.101	.115	.132	.164	.197	.230	.263	.329	.394	.459	.525
1 1/2 (1.500)					.132	.164	.197	.229	.262	.329	.394	.459	.525
1 3/4 (1.750)						.163	.197	.229	.262	.328	.393	.459	.525
2 (2.000)						.163	.196	.229	.262	.328	.393	.458	.525
2 1/4 (2.250)							.196	.229	.262	.328	.393	.458	.524
2 1/2 (2.500)								.228	.261	.327	.393	.458	.524
2 3/4 (2.750)								.228	.261	.327	.393	.458	.524
3 (3.000)								.227	.260	.327	.392	.457	.523
3 1/4 (3.250)									.260	.326	.392	.457	.523
3 1/2 (3.500)										.326	.391	.456	.522
3 3/4 (3.750)											.391	.456	.522
4 (4.000)											.390	.455	.521
4 1/4 (4.250)											.390	.455	.521
4 1/2 (4.500)												.454	.520

Nom. Diam. (D)	Exp. Diam. (Dx) reduced by
1/16	.002
5/64	.002
3/32	.002
7/64	.002
1/8	.002
5/32	.002
3/16	.003
7/32	.003
1/4	.003
5/16	.004
3/8	.005
7/16	.006
1/2	.006

TOLERANCES:

On Nominal Diameter "D"
+.000—.001 up to 7/64" diameter
+.000—.002 7/64" and above

On Expanded Diameter "Dx"
±.001 up to 7/64" diameter
±.002 7/64" and above
On over-all Length "L"
±.010 for all diameters

For stainless steels and other special materials, the expanded diameters shown in above table are reduced by amounts shown at left.

Note: Intermediate pin lengths, pin diameters up to 3/4", groove lengths, and groove positions to order as specials. When ordering, specify type, diameter, length, and special finishes.

FIGURE 13-49 *Standard size chart of grooved pin types A, A3, and U.*



STANDARD SIZES

Nominal diameter and recommended drill sizes	1/16	5/64	3/32	7/64	1/8	5/32	3/16	7/32	1/4	5/16	3/8	7/16	1/2
Dec. Equivalents	.0625	.0781	.0938	.1094	.1250	.1563	.1875	.2188	.2500	.3125	.3750	.4375	.5000
Crown Height, In.	.0065	.0087	.0091	.0110	.0130	.0170	.0180	.0220	.0260	.0340	.0390	.0470	.0520
Radius, In. ± .010	5/64	3/32	1/8	9/64	5/32	3/16	1/4	9/32	5/16	3/8	15/32	17/32	5/8

"Dx" EXPANDED DIAMETER—CAN BE DETERMINED ACCURATELY ONLY WITH RING GAGES

LENGTH OF PIN IN INCHES

1/4 (.250)	.068	.084	.101	.117	.134								
3/8 (.375)	.068	.084	.101	.117	.134	.166	.198						
1/2 (.500)	.068	.084	.101	.117	.134	.166	.198	.230	.263				
5/8 (.625)	.068	.084	.101	.117	.134	.166	.198	.230	.263	.329			
3/4 (.750)	.068	.084	.101	.117	.134	.166	.198	.230	.263	.329	.394		
7/8 (.875)	.068	.084	.101	.117	.134	.166	.198	.230	.263	.329	.394	.459	
1 (1.000)	.068	.084	.101	.117	.134	.166	.198	.230	.263	.329	.394	.459	.525
1 1/4 (1.250)			.101	.117	.134	.166	.198	.230	.263	.329	.394	.459	.525
1 1/2 (1.500)					.134	.166	.198	.230	.263	.329	.394	.459	.525
1 3/4 (1.750)						.165	.198	.230	.263	.329	.394	.459	.525
2 (2.000)						.165	.198	.230	.263	.329	.394	.459	.525
2 1/4 (2.250)							.197	.230	.263	.329	.394	.459	.525
2 1/2 (2.500)								.230	.263	.329	.394	.459	.525
2 3/4 (2.750)								.229	.262	.329	.394	.459	.525
3 (3.000)								.229	.262	.329	.394	.459	.525
3 1/4 (3.250)									.262	.328	.393	.459	.525
3 1/2 (3.500)										.328	.393	.459	.525
3 3/4 (3.750)											.393	.458	.525
4 (4.000)											.393	.458	.525
4 1/4 (4.250)											.393	.458	.524
4 1/2 (4.500)												.458	.524

Nom. Diam. (D)	Exp. Diam. (Dx) reduced by
1/16	.002
5/64	.002
3/32	.002
7/64	.002
1/8	.002
5/32	.002
3/16	.003
7/32	.003
1/4	.003
5/16	.004
3/8	.005
7/16	.006
1/2	.006

TOLERANCES:

On Nominal Diameter "D"
+.000–.001 up to 7/64" diameter
+.000–.002 7/64" and above

On Expanded Diameter "Dx"
± .001 up to 7/64" diameter
± .002 7/64" and above
On over-all Length "L"
± .010 for all diameters

For stainless steels and other special materials, the expanded diameters shown in above table are reduced by amounts shown at left.

Note: Intermediate pin lengths, pin diameters up to 3/4", groove lengths, and groove positions to order as specials. When ordering, specify type, diameter, length, and special finishes.

FIGURE 13-50 *Standard size chart of grooved pin types B and C.*

TYPE D



TYPE E



STANDARD SIZES

Nominal diameter and recommended drill sizes	1/16	5/64	3/32	7/64	1/8	5/32	3/16	7/32	1/4	5/16	3/8	7/16	1/2
Dec. Equivalents	.0625	.0781	.0938	.1094	.1250	.1563	.1875	.2188	.2500	.3125	.3750	.4375	.5000
Crown Height, In.	.0065	.0087	.0091	.0110	.0130	.0170	.0180	.0220	.0260	.0340	.0390	.0470	.0520
Radius, In. ± .010	5/64	3/32	1/8	9/64	5/32	3/16	1/4	9/32	5/16	3/8	15/32	17/32	5/8

"Dx" EXPANDED DIAMETER—CAN BE DETERMINED ACCURATELY ONLY WITH RING GAGES

LENGTH OF PIN IN INCHES

1/4	(.250)	.068	.084	.101	.117	.134								
3/8	(.375)	.068	.084	.101	.117	.134	.166	.198						
1/2	(.500)	.068	.084	.101	.117	.134	.166	.198	.230	.263				
5/8	(.625)	.068	.084	.101	.117	.134	.166	.198	.230	.263	.329			
3/4	(.750)	.068	.084	.101	.117	.134	.166	.198	.230	.263	.329	.394		
7/8	(.875)	.068	.084	.101	.117	.134	.166	.198	.230	.263	.329	.394	.459	
1	(1.000)	.068	.084	.101	.117	.134	.166	.198	.230	.263	.329	.394	.459	.525
1 1/4	(1.250)			.101	.117	.134	.166	.198	.230	.263	.329	.394	.459	.525
1 1/2	(1.500)					.134	.166	.198	.230	.263	.329	.394	.459	.525
1 3/4	(1.750)						.165	.198	.230	.263	.329	.394	.459	.525
2	(2.000)						.165	.198	.230	.263	.329	.394	.459	.525
2 1/4	(2.250)							.197	.230	.263	.329	.394	.459	.525
2 1/2	(2.500)								.230	.263	.329	.394	.459	.525
2 3/4	(2.750)								.229	.262	.329	.394	.459	.525
3	(3.000)									.229	.262	.329	.394	.459	.525
3 1/4	(3.250)									.262	.328	.393	.459	.525
3 1/2	(3.500)										.328	.393	.459	.525
3 3/4	(3.750)											.393	.458	.525
4	(4.000)											.393	.458	.525
4 1/4	(4.250)											.393	.458	.524
4 1/2	(4.500)												.458	.524

Nom. Diam. (D)	Exp. Diam. (Dx) reduced by
1/16	.002
5/64	.002
3/32	.002
7/64	.002
1/8	.002
5/32	.002
3/16	.003
7/32	.003
1/4	.003
5/16	.004
3/8	.005
7/16	.006
1/2	.006

TOLERANCES:

On Nominal Diameter "D"
+.000—.001 up to 7/64" diameter
+.000—.002 7/64" and above

On Expanded Diameter "Dx"
± .001 up to 7/64" diameter
± .002 7/64" and above
On over-all Length "L"
± .010 for all diameters

For stainless steels and other special materials, the expanded diameters shown in above table are reduced by amounts shown at left.

Note: Intermediate pin lengths, pin diameters up to 1/4", groove lengths, and groove positions to order as specials. When ordering, specify type, diameter, length, and special finishes.

FIGURE 13-51 *Standard size chart of grooved pin types D and E.*

TYPE G (combined former F and G)



STANDARD SIZES

Nominal diameter and recommended drill sizes	3/32	7/64	1/8	5/32	3/16	7/32	1/4	5/16	3/8	7/16	1/2
Dec. Equivalents	.0938	.1094	.1250	.1563	.1875	.2188	.2500	.3125	.3750	.4375	.5000
Crown Height, In.	.0091	.0110	.0130	.0170	.0180	.0220	.0260	.0340	.0390	.0470	.0520
Radius, In., ±0.010	1/8	9/64	5/32	3/16	1/4	9/32	5/16	3/8	15/32	17/32	5/8
Pilot Length, In. (Ref.)	1/32	1/32	1/32	1/16	1/16	1/16	1/16	3/32	3/32	3/32	3/32
M Neck Radius (Ref.)	1/64	1/64	1/32	1/32	1/32	3/64	3/64	1/16	1/16	3/32	3/32
G Neck Width (Ref.)	1/32	1/32	1/16	1/16	1/16	3/32	3/32	1/8	1/8	3/16	3/16
Shoulder Width +.010—.000	1/32	1/32	1/32	3/64	3/64	1/16	1/16	3/32	1/8	1/8	1/8
K Neck Diameter ±.005	.062	.078	.083	.104	.125	.146	.167	.209	.250	.293	.312
"Dx" EXPANDED DIAMETER—CAN BE DETERMINED ACCURATELY ONLY WITH RING GAGES											
LENGTH OF PIN IN INCHES											
3/8 (.375)	.101	.117	.134	.166	.198						
1/2 (.500)	.101	.117	.134	.166	.198	.230	.263				
5/8 (.625)	.101	.117	.134	.166	.198	.230	.263	.329			
3/4 (.750)	.101	.117	.134	.166	.198	.230	.263	.329	.394		
7/8 (.875)	.101	.117	.134	.166	.198	.230	.263	.329	.394	.459	
1 (1.000)	.101	.117	.134	.166	.198	.230	.263	.329	.394	.459	.525
1 1/4 (1.250)	.101	.117	.134	.166	.198	.230	.263	.329	.394	.459	.525
1 1/2 (1.500)			.134	.166	.198	.230	.263	.329	.394	.459	.525
1 3/4 (1.750)				.165	.198	.230	.263	.329	.394	.459	.525
2 (2.000)				.165	.198	.230	.263	.329	.394	.459	.525
2 1/4 (2.250)					.197	.230	.263	.329	.394	.459	.525
2 1/2 (2.500)						.230	.263	.329	.394	.459	.525
2 3/4 (2.750)						.229	.262	.329	.394	.459	.525
3 (3.000)								.329	.394	.459	.525
3 1/4 (3.250)								.328	.393	.459	.525
3 1/2 (3.500)								.328	.393	.459	.525
3 3/4 (3.750)									.393	.458	.525
4 (4.000)									.393	.458	.525
4 1/4 (4.250)									.393	.458	.524
4 1/2 (4.500)										.458	.524

Nom. Diam. (D)	Exp. Diam. (Dx) reduced by
3/32	.002
7/64	.002
1/8	.002
5/32	.002
3/16	.003
7/32	.003
1/4	.003
5/16	.004
3/8	.005
7/16	.006
1/2	.006

TOLERANCES:

On Nominal Diameter "D"
+.000—.001 up to 7/64" diameter
+.000—.002 7/64" and above

On Expanded Diameter "Dx"
±.001 up to 7/64" diameter
±.002 7/64" and above

On over-all Length "L"
±.010 for all diameters

For stainless steels and other special materials, the expanded diameters shown in above table are reduced by amounts shown at left.

Note: Intermediate pin lengths, pin diameters up to 3/4", groove lengths, and groove positions to order as specials. When ordering, specify type, diameter, length, and special finishes.

FIGURE 13-52 *Standard size chart of grooved pin type G.*

Pin Diameter	Decimal Equivalent	Recommended Drill Size	Hole Tolerances ADD To Nominal Diameter
1/16"	.0625	1/16"	.002"
5/64	.0781	5/64	.002"
3/32	.0938	3/32	.003"
7/64	.1094	7/64	.003"
1/8	.1250	1/8	.003"
5/32	.1563	5/32	.003"
3/16	.1875	3/16	.004"
7/32	.2188	7/32	.004"
1/4	.2500	1/4	.004"
5/16	.3125	5/16	.005"
3/8	.3750	3/8	.005"
7/16	.4375	7/16	.006"
1/2	.5000	1/2	.006"

Tolerances for drilled holes shown in table are based on depth-to-diameter ratio of approximately 5 to 1. Higher ratios may cause these figures to be exceeded, but in no case should they be exceeded by more than 10%. Specifications for holes having a depth-to-diameter ratio of 1 to 1 or less should be held extremely close; 60% of figures shown in table is recommended.

Undersized drills should never be used to produce holes for Driv-Lok Pins. This malpractice results from the false assumption that the pins will "hold better." Instead, they bend, damage the hole wall, crack castings, and peel their expanded flutes, thus reducing their retaining characteristics and preventing their release.

Holes made in hardened steel or cast iron are recommended to have a slight chamfer at the entrance. This eliminates shearing of the flutes as the pins are forced in.

Care should be exercised in all drilling for Driv-Lok Pins. Drills used should be new or properly ground with the aid of an approved grinding fixture. The drilling machine spindle must be in good condition and operated at correct speeds and feeds for the metal being drilled, and suitable coolant is always recommended. Drill jigs with accurate bushings always facilitate good drilling practice.

FIGURE 13-53 *Drilling procedure and hole tolerance.*

RECOMMENDED PIN DIAMETER FOR VARIOUS SHAFT SIZES AND TORQUE TRANSMITTED BY PIN IN DOUBLE SHEAR

Shaft Size	Pin Diameter	Torque Inch Lbs.	H.P. at 100 R.P.M.	Shaft Size	Pin Diameter	Torque Inch Lbs.	H.P. at 100 R.P.M.
3/16	1/16	4.6	.007	7/8	1/4	347	.555
7/32	5/64	8.4	.013	15/16	5/16	580	.927
1/4	3/32	13.7	.022	1	5/16	618	.990
5/16	7/64	23.6	.038	1 1/16	5/16	657	1.05
3/8	1/8	37.2	.060	1 1/8	3/8	1010	1.61
7/16	5/32	67.6	.108	1 3/16	3/8	1065	1.70
1/2	5/32	77.2	.124	1 1/4	3/8	1120	1.79
9/16	3/16	125.0	.200	1 5/16	7/16	1590	2.55
5/8	3/16	139.0	.222	1 3/8	7/16	1670	2.67
11/16	7/32	207.0	.332	1 7/16	7/16	1740	2.79
3/4	1/4	297.0	.476	1 1/2	1/2	2380	3.81
13/16	1/4	322	.516				

This table is a guide in selecting the proper size Driv-Lok Grooved Pin to use in keying machine members to shafts of given sizes and for specific load requirements. Torque and horsepower ratings are based on pins made of cold finished, low carbon steel and a safety factor of 8 is assumed.

MINIMUM SINGLE SHEAR VALUES (LBS.) OF DRIV-LOK PINS OF VARIOUS MATERIALS

	MATERIAL				
DRIV-LOK PIN DIAM.	Cold Finished 1213 Steel	Shear-Proof® ALLOY STEEL R.C. 40 - 48	Brass	Silicon Bronze	Heat Treated Stainless Steel
1/16	200	363	124	186	308
5/64	312	562	192	288	478
3/32	442	798	272	408	680
7/64	605	1091	372	558	933
1/8	800	1443	492	738	1230
5/32	1240	2236	764	1145	1910
3/16	1790	3220	1100	1650	2750
7/32	2430	4386	1495	2240	3740
1/4	3190	5753	1960	2940	4910
5/16	4970	8974	3060	4580	7650
3/8	5810	12960	4420	6630	11050
7/16	7910	17580	6010	9010	15000
1/2	10300	23020	7850	11800	19640

FIGURE 13-54 *Grooved pin application/engineering data.*



MATERIAL HANDLING EQUIPMENT—The Type E pin provides positive locking with a half-length groove in the center of the pin. Extreme shear is exerted in this application, yet the Shear-Proof pin is used with complete safety for both men and materials. Type E is a special pin.



HEAVY-DUTY GEAR AND SHAFT ASSEMBLY—Type A Shear-Proof pin as specified for this application to give maximum locking power over the entire pin and gear hub area. The Type A pin, with grooves the full length of the pin, is the standard stock pin which meets most applications.



AUTOMATIC TRANSMISSION IN AUTOMOBILES—Special Type C was selected as a shaft in this transmission servo to replace a cross-drilled shaft with a cross pin for holding shaft in position. This eliminated a costly drilling operation and the cross pin.



UNIVERSAL JOINTS IN HAND TOOLS—Special Type E pin with center groove eliminates costly staking and grinding operations and improves product appearance. This pin is easily installed, fits flush, and permits plating before assembly.



EYE BOLT HINGE PIN — Type C pin, with quarter-length grooves, provides maximum ease of assembly. There is no interference until three-fourths of the pin is in position. The high safety factor inherent in Shear-Proof pins makes them practical and efficient for such constant-shear applications. Type C is a special pin.



HIGH-PRESSURE PISTON AND ROD ASSEMBLY—Type B pin was used here because the half-length grooves simplified the job of starting the pin into the hole. Ease of assembly was matched with sufficient locking power even when subjected to continuous, strong reciprocating forces. Type B is a special pin.

FIGURE 13-55 *High alloy shear-proof pins.*



STANDARD SIZES and SPECIFICATIONS

Stud Number	Nominal Shank Diameter	Recommended Drill Size	Head Dia. Max.	Head Dia. Min.	Head Height Max.	Head Height Min.
0	.067	51	.130	.120	.050	.040
2	.086	44	.162	.146	.070	.059
4	.104	37	.211	.193	.086	.075
6	.120	31	.260	.240	.103	.091
7	.136	29	.309	.287	.119	.107
8	.144	27	.309	.287	.119	.107
10	.161	20	.359	.334	136	.124
12	.196	9	.408	.382	152	.140
14	221	2	.457	.429	.169	156
16	250	¼"	472	.443	.174	.161

Maximum Expansion—Standard Lengths

Stud No.	⅛"	3/16"	¼"	5/16"	⅜"	½"
0	.074	.074	.074			
2	096	.096	.095			
4		.115	113	.113		
6			132	.130	.130	
7				.147	.147	.144
8					.155	.153
10					.173	.171
12						.206
14						.234
16						.263

TOLERANCES
On length ± .010
On Exp. Diameter + .002
On Nominal Diameter + .000 −.002

Note: The expanded diameter can be determined accurately only with ring gages.

TYPICAL APPLICATIONS

Fastening knobs handles, etc.



Attaching nameplates, instruction panels



Widely used for fastening brackets



Fastening spring assemblies or control arms

FIGURE 13-56 *Standard studs.*

1.	Flathead special stud with one-third length groove at lead end. Groove length can be varied.	
2.	Flathead special grooved stud with shoulder. Often hardened to provide wear surface in shoulder area.	
3.	Flathead grooved stud.	
4.	Round head reverse taper groove stud.	
5.	Stud with conical head and parallel grooves.	
6.	Round head stud with parallel grooves of special length.	
7.	Countersunk head grooved stud.	
8.	T head cotter used extensively in chain industry in place of cotter pins.	



FIGURE 13-57 *Special studs.*



FIGURE 13-58 *Spring pin.*



FIGURE 13-59 *Spring pin application.*



STANDARD SIZES

A			B	C		WALL THICKNESS	RECOMMENDED HOLE SIZE		MINIMUM DOUBLE SHEAR STRENGTH POUNDS
Nominal	Minimum $\frac{1}{3}(D_1+D_2+D_3)$	Maximum (Go Ring Gage)	Max.	Min.	Max.		Min.	Max.	Carbon Steel and Stainless Steel
.062	.066	.069	.059	.007	.028	.012	.062	.065	425
.078	.083	.086	.075	.008	.032	.018	.078	.081	650
.094	.099	.103	.091	.008	.038	.022	.094	.097	1,000
.125	.131	.135	.122	.008	.044	.028	.125	.129	2,100
.156	.162	.167	.151	.010	.048	.032	.156	.160	3,000
.187	.194	.199	.182	.011	.055	.040	.187	.192	4,400
.219	.226	.232	.214	.011	.065	.048	.219	.224	5,700
.250	.258	.264	.245	.012	.065	.048	.250	.256	7,700
.312	.321	.328	.306	.014	.080	.062	.312	.318	11,500
.375	.385	.392	.368	.016	.095	.077	.375	.382	17,600
.437	.448	.456	.430	.017	.095	.077	.437	.445	20,000
.500	.513	.521	.485	.025	.110	.094	.500	.510	25,800

All dimensions listed on this page are in accordance with National Standards. Wall thicknesses within the Spring Pin industry are standard.

SPRING PIN WEIGHT PER 1000 PIECES

Material—Steel • Nominal Diameter

LENGTH	.062	.078	.094	.125	.156	.187
0.187	.10	0.18				
0.250	.15	0.22	0.33			
0.312	.19	0.28	0.41			
0.375	.23	0.34	0.50	0.89		
0.437	.27	0.40	0.58	1.00	1.50	
0.500	.30	0.46	0.66	1.20	1.70	2.50
0.562	.34	0.51	0.75	1.30	1.90	2.90
0.625	.38	0.57	0.83	1.50	2.10	3.20
0.687	.42	0.63	0.92	1.60	2.40	3.50
0.750	.46	0.69	1.00	1.80	2.60	3.80
0.812	.49	0.74	1.10	1.90	2.80	4.10
0.875	.53	0.80	1.20	2.10	3.00	4.50
0.937	.57	0.86	1.30	2.20	3.20	4.80
1.000	.61	0.92	1.40	2.40	3.40	5.10
1.125		1.00	1.50	2.70	3.80	5.70
1.250		1.20	1.70	3.00	4.30	6.40
1.375		1.30	1.80	3.30	4.70	7.00
1.500		1.40	2.00	3.60	5.10	7.60
1.625				3.90	5.50	8.30
1.750				4.20	6.00	8.90
1.875				4.50	6.40	9.60
2.000				4.70	6.80	10.0
2.250					7.80	12.0
2.500					8.60	13.0

LENGTH	.219	.250	.312	.375	.437	.500
0.562	4.00					
0.625	4.50	5.30				
0.687	4.90	5.90				
0.750	5.30	6.30	9.90	15.0		
0.812	5.80	6.90	11.0			
0.875	6.20	7.40	12.0			
0.937	6.70	8.00	12.0			
1.000	7.00	8.50	13.0	20.0	24.0	
1.125	7.90	9.50	14.0			
1.250	8.80	11.0	16.0	24.0	30.0	41.0
1.375	9.70	12.0	18.0			
1.500	11.0	13.0	19.0	29.0	36.0	49.0
1.625	12.0	14.0	21.0			
1.750	12.0	15.0	22.0	34.0	42.0	57.0
1.875	13.0	16.0	24.0			
2.000	14.0	17.0	25.0	38.0	48.0	65.0
2.250	16.0	19.0	29.0	43.0	54.0	73.0
2.500	18.0	21.0	32.0	48.0	60.0	81.0
2.750	19.0	23.0	35.0	53.0	66.0	89.0
3.000	21.0	25.0	38.0	58.0	72.0	97.0
3.250		28.0	41.0	62.0	77.0	105.0
3.500		31.0	44.0	67.0	83.0	114.0
3.750			48.0	72.0	89.0	122.0
4.000			51.0	77.0	95.0	130.0

FIGURE 13-60 *Spring pin data.*

Retaining Rings

Retaining rings are precision-engineered fasteners. They provide removable shoulders for positioning or limiting the movement of parts in an assembly, *Figure 13-61*. Applications range from miniaturized electronic systems to massive earth-moving equipment. Retaining rings are used in automobiles, business machines, and complex components for guided missiles. They are found in such commonplace items as doorknobs and in sophisticated underwater seismic cable connectors.

Typical ring applications are shown in *Figures 13-62* through *13-66*. From these figures, the drafter may examine the design of various types of rings, determine their purpose and function, and decide how they may be used to the best advantage.

Most retaining rings are made of materials that have good spring properties. This permits the rings to be deformed elastically to a substantial degree, yet still spring back to their original shape during assembly and disassembly. This allows most rings to function in one of two ways: (1) they may be sprung into a groove or other recess in a part, or (2) they may be seated on a part in a deformed condition so that they grip the part by frictional means. In either case, the rings form a fixed shoulder against which other components may be abutted and prevented from moving.

Unlike wire-formed rings, which have a uniform section height, stamped rings have a tapered radial width. The width decreases symmetrically from the center section to the free ends. The tapered section permits the rings to remain circular after they have been compressed for insertion into a bore or expanded for assembly over a shaft. Most rings are designed to be seated in grooves. This constant circularity assures maximum contact surface with the bottom of the groove. It is also an important factor in achieving high static and dynamic thrust load capacities.



FIGURE 13-61 *Retaining rings.* (Courtesy Koh-I-Noor Rapidograph)



FIGURE 13-62 *Ring application in a precision differential.* (Courtesy Koh-I-Noor Rapidograph)



FIGURE 13-63 *Ring application in a cylindrical lockset.* (Courtesy Koh-I-Noor Rapidograph)



FIGURE 13-64 *Ring application in an electromagnetic clutch brake.* (Courtesy Koh-I-Noor Rapidograph)



FIGURE 13-65 *Ring application in a road grader.*
(Courtesy Koh-I-Noor Rapidograph)

Types of Retaining Rings

A great number of fastening requirements are involved in product design. This factor has led to the development of many different types of retaining rings. Standard rings are shown in ***Figure 13-67.***

Limited space prevents describing in detail all the different ring types available. In general, however, retaining rings can be grouped into two major categories.

Internal rings for axial assembly are compressed for insertion into a bore or housing. They generally have a large gap and holes in the lugs, located at the free ends, for pliers which are used to grasp the rings securely during installation and removal, ***Figure 13-68.***

External rings for axial assembly are expanded with pliers, ***Figure 13-69,*** so they may be slipped over the end of a shaft, stud, or similar part. They have a small gap, and the lug position is reversed from that of the internal ring. Radially assembled external rings do not have holes for pliers. Instead, the rings have a large gap and are pushed into the shaft directly in the plane of the groove with a special application tool, ***Figure 13-70.***



FIGURE 13-66 *Ring application in strip chart recorder.*
(Courtesy Koh-I-Noor Rapidograph)



FIGURE 13-67 *Standard retaining rings series.*
(Courtesy Koh-I-Noor Rapidograph)

FIGURE 13-68 *Internal ring pliers.* (Courtesy Koh-I-Noor Rapidograph)



FIGURE 13-69 *External ring pliers.* (Courtesy Koh-I-Noor Rapidograph)

FIGURE 13-70 *Applicator and dispenser for retaining rings.* (Courtesy Koh-I-Noor Rapidograph)

In addition to the tools shown here, retaining rings can be installed with automatic equipment. This equipment can be designed for specific, high-speed, automatic assembly lines. Retaining ring grooves serve two purposes: (1) they ensure precise seating of the ring in the assembly, and (2) they permit the ring to withstand heavy thrust loads. The grooves must be located accurately and precut in the housing or shaft before the rings are assembled. Shaft grooves often can be made at no additional cost during the cut-off and chamfering operations.

Self-locking rings do not require any grooves because they exert a frictional hold against axial displacement. They are used mainly as positioning and locking devices where the ring will be subjected only to moderate or light loading.

Bowed rings differ from conventional types in that they are bowed around an axis perpendicular to the diameter bisecting the gap. The bowed construction permits the rings to function as springs as well as fasteners. This provides resilient end play take-up in the assembly.

Beveled rings have a 15° bevel on the groove-engaging edge. They are installed in grooves having a comparable bevel on the load-bearing wall. When the ring is seated in the groove, it acts as a wedge against the retained part. Sometimes play develops between the ring and retained part because of accumulated tolerances or wear in the assembly. If play develops, the spring action of the ring causes the fastener to seat more deeply in its groove and move in an axial direction, automatically taking up the end play. (Because self-locking rings can be seated at any point on a shaft or in a bore, they too can be used to compensate for tolerances and eliminate end play.)

Materials and Finishes

As indicated previously, retaining rings are made of materials having good spring properties. Some also have high tensile and yield strengths. They must also have adequate ratio or ultimate tensile strength to elasticity. This permits the required deformation

without too much permanent set. A ratio of 1:100 is satisfactory for most rings having the tapered-section design.

Standard material for most rings is carbon spring steel (SAE 1060-1090). For special applications, rings are also available in stainless steel (PH 15-7 Mo), beryllium copper (Alloy #25), and aluminum (Alclad 7075-T6). Rings are normally phosphate coated. Cadmium, zinc, and other platings and finishes are used for assemblies where extra corrosion resistance is needed or where the rings must withstand other unusual environmental conditions.

Selection of the ring material and finish for a specific product design should be based upon the operating conditions under which the ring must function. These may include temperature, the presence of corrosive elements, thrust loads, and other factors.

Selection Considerations

Selecting the best ring for a product load capacity is a critical factor in some product designs. There are other factors the drafter should consider, however, before selecting specific ring types for a given product.

- Will there be adequate clearance to assemble the ring with pliers or other tools?
- Must the ring take up accumulated tolerances, either resiliently or rigidly?
- Is it possible to machine a ring groove on the shaft or inside a bore?
- Should the ring be adjustable to several positions on a shaft?

Making the Choice

After considering all these conditions, the drafter may find that more than one ring type is suitable. How, then, can the drafter make the best choice?

The most important design criterion is the ability of the ring to do the fastening job required. Before a final selection of ring type is made, the drafter should consider savings that may be possible in various parts of the assembly. These include:

- The cost of installing the ring.
- Whether or not a groove is required.
- If the ring can be installed **permanently** or if it may have to be removed for field service.

A self-locking ring, for example, eliminates the need for the ring grooves. If the ring will be subjected to only moderate loading, this may be ideal for the assembly. But most self-locking rings must be destroyed for removal. If field service is anticipated, another style of ring should be adopted.

The ideal ring is the one that will function adequately and provide the most economical means of fastening. Retaining rings are designed primarily as shoulders for positioning and retaining machine components on shafts and in housings and bores. Different rings have been developed and manufactured to meet specific fastening needs and problems.

To ensure correct selection of the proper type for any individual application, rings have been grouped according to their basic function. The selector guides, *Figures 13-71* and *13-72*, provide a visual index to all standard types.

Figures 13-73 and *13-74* (pages 546 through 549) are from the latest *Truarc Technical Manual*. Figure 13-73 is a sample of an internal series (N5000); Figure 13-74 is from an external series (5100).

EXAMPLE (REFER TO FIGURE 13-73):

A shaft of 1.000 (24.4) diameter would use a No. N5000-100.

- Free diameter = $1.111 \pm \begin{matrix} .015 \\ .010 \end{matrix}$
- Thickness = .042 ± .002
- Lug size = .155 ± .005
- Plier hole diameter = .062

The required groove must be:

- Diameter = 1.066 ± .003 (.004 TIR)
- Width = $.046 \pm \begin{matrix} .003 \\ .000 \end{matrix}$

EXAMPLE (REFER TO FIGURE 13-74):

A shaft of 4.000 (101.6) diameter would use a No. 5100-400.

- Free diameter = $3.700 \pm \begin{matrix} .020 \\ .030 \end{matrix}$
- Thickness = .109 ± .003
- Lug size = .352 ± .005
- Plier hole size = $.125 \pm \begin{matrix} .015 \\ .002 \end{matrix}$

The required groove must be:

- Diameter = 3.792 ± .006 (.006 TIR)
- Width = $.120 \pm \begin{matrix} .005 \\ .000 \end{matrix}$

(Text continues on page 550)

DESIGN FEATURES

RING TYPES FOR AXIAL ASSEMBLY

Series N5000, 5100: Tapered section assures constant circularity and groove pressure. Secure against heavy thrust loads and high rotational speeds.

Series 5008, 5108: Lugs inverted to abut groove bottom. Rings form high circular shoulder, concentric with bore or shaft. Good for parts having large corner radii or chamfers.

Series 5160: Heavy-duty ring resists high thrust, impact loads. Eliminates spacer washers in bearing assemblies.

Series 5560: New miniature, high-strength ring. Forms tamper-proof shoulder on small diameter shafts subject to heavy thrust loads.

Series 5590: Permanent-shoulder ring for small diameter shafts. When compressed into groove, notches deform to close gaps, reducing both I.D. and O.D.

RING TYPES FOR RADIAL ASSEMBLY

Series 5103: Forms narrow, uniformly concentric shoulder. Excellent for assemblies where clearance is limited.

Series 5133: Provides large shoulder on small diameter shafts. Installed in deep groove for added thrust capacity.

Series 5144: Reinforced to provide five times greater gripping strength, 50% higher rpm limits than conventional E-rings. Secure against rotation.

Series 5107: Two-part ring balanced to withstand high rpm's, heavy thrust loads, relative rotation between parts.

Series 5304: New high-strength ring for large bearing surface. Can be installed quickly with pliers or mallet, removed with ordinary screw driver.

Series T5304: Thinner model of 5304. Can be seated in same width grooves as E-rings, has more gripping power. Good for cast or molded grooves.

RING TYPES FOR TAKING UP END-PLAY

Series N5001, 5101: Bowed cylindrically to accommodate large tolerances, provide resilient end-play take-up.

Series N5002, 5102: Rings beveled 15° on groove-engaging edge for use in groove with similar bevel. Wedge action provides rigid end-play take-up.

Series 5131: Provides large shoulder on small diameter shafts. Bowed for resilient end-play take-up.

Series 5139: Bowed ring designed for use as shoulder against rotating parts. Prongs lock against shaft, prevent ring from being forced from groove.

SELF-LOCKING-TYPE RINGS (No groove required)

Series 5115: Push-on-type fastener for ungrooved shafts and studs. Has arched rim for extra strength, long prongs for wide shaft tolerances.

Series 5105, 5005: Flat rim, shorter prongs, smaller O.D. than 5115. For flat contact surface, better clearance.

Series 5555: Secure against axial displacement from either direction. No groove needed. Adjustable, reusable.

Series 5305: Dished body, three heavy prongs lock on shaft under spring tension. Withstands heavy thrust loads.

Series 5300: Free-spinning nut. Dished body flattens under torque, eliminating need for separate lock washers.

INTERNAL	BASIC **N5000** For housings and bores. Size Range: .250—10.0 in. / 6.4—254.0 mm.	EXTERNAL	BOWED **5101** For shafts and pins. Size Range: .188—1.750 in. / 4.8—44.4 mm.	EXTERNAL	REINFORCED **5115** For shafts and pins. Size Range: .094—1.0 in. / •	EXTERNAL	TRIANGULAR NUT **5300** For threaded parts. Size Range: 6-32 and 8-32 / 10-24 and 10-32 / 1/4-20 and 1/4-28
INTERNAL	BOWED **N5001** For housings and bores. Size Range: .250—1.750 in. / 6.4—44.4 mm.	EXTERNAL	BEVELED **5102** For shafts and pins. Size Range: 1.0—10.0 in. / 25.4—254.0 mm.	EXTERNAL	BOWED E-RING **5131** For shafts and pins. Size Range: .110—1.375 in. / 2.8—34.9 mm.	EXTERNAL	KLIPRING **5304** **T-5304** For shafts and pins. Size Range: .156—1.000 in. / 4.0—25.4 mm.
INTERNAL	BEVELED **N5002** For housings and bores. Size Range: 1.0—10.0 in. / 25.4—254.0 mm.	EXTERNAL	CRESCENT® **5103** For shafts and pins. Size Range: .125—2.0 in. / 3.2—50.8 mm.	EXTERNAL	E-RING **5133** For shafts and pins. Size Range: .040—1.375 in. / 1.0—34.9 mm.	EXTERNAL	TRIANGULAR **5305** For shafts and pins. Size Range: .062—.438 in. / •
INTERNAL	CIRCULAR **5005** For housings and bores. Size Range: .312—2.0 in. / •	EXTERNAL	CIRCULAR **5105** For shafts and pins. Size Range: .094—1.0 in. / •	EXTERNAL	PRONG-LOCK® **5139** For shafts and pins. Size Range: .092—.438 in. / •	EXTERNAL	GRIPRING® **5555** For shafts and pins. Size Range: .079—.750 in. / 2.0—19.0 mm.
INTERNAL	INVERTED **5008** For housings and bores. Size Range: .750—4.0 in. / 19.0—101.6 mm.	EXTERNAL	INTERLOCKING **5107** For shafts and pins. Size Range: .469—3.375 in. / 11.9—85.7 mm.	EXTERNAL	REINFORCED E-RING **5144** For shafts and pins. Size Range: .094—.562 in. / 2.4—14.3 mm.	EXTERNAL	HIGH-STRENGTH **5560** For shafts and pins. Size Range: .101—.328 in. / •
EXTERNAL	BASIC **5100** For shafts and pins. Size Range: .125—10.0 in. / 3.2—254.0 mm.	EXTERNAL	INVERTED **5108** For shafts and pins. Size Range: .500—4.0 in. / 12.7—101.6 mm.	EXTERNAL	HEAVY-DUTY **5160** For shafts and pins. Size Range: .394—2.0 in. / 10.0—50.8 mm.	EXTERNAL	PERMANENT SHOULDER **5590** For shafts and pins. Size Range: .250—.750 / 6.4—19.0 mm.

FIGURE 13-71 *Selector guide: Standard ring series.* (Courtesy Koh-I-Noor Rapidograph)

The symbols listed below are used in the data charts for various ring types. Ring, groove, and retained part dimensions are in inches; allowable thrust loads are in pounds.

SYMBOL		DEFINITION	RING SERIES WHERE APPLICABLE
A		Minimum gap width: internal ring installed in groove	N5000, N5001, N5002, 5008
B		Lug height	N5000, N5001, N5002, 5100, 5101, 5102, 5160, 5555
b		Ring height	5139, 5555, 5305, 5300, 5304
C		Clearance diameter	5139, 5590
C_1		Clearance diameter: ring sprung into housing or over shaft, prior to installation in groove	N5000, N5001, N5002, 5008, 5100, 5101, 5102, 5108, 5160, 5555, 5560, 5590
C_2		Clearance diameter: ring installed in groove	N5000, N5001, N5002, 5008, 5100, 5101, 5102, 5103, 5107, 5108, 5131, 5133, 5144, 5160, 5560

SYMBOL		DEFINITION	RING SERIES WHERE APPLICABLE
$Ch_{max.}$		Maximum allowable chamfer height of retained part	N5000, N5001, N5002, 5008, 5100, 5101, 5102, 5103, 5107, 5108, 5131, 5133, 5144, 5160, 5555, 5560
D		Free diameter	N5000, N5001, N5002, 5008, 5100, 5101, 5102, 5103, 5107, 5108, 5131, 5133, 5144, 5160, 5304, 5555, 5560, 5590
d		Nominal groove depth	ALL RINGS USED IN GROOVES
E		Large section height	N5000, N5001, N5002, 5008, 5100, 5101, 5102, 5103, 5107, 5108, 5160, 5560
e REF.		Distance from center of ring to outer edge (Reference)	5139
G		Groove diameter	ALL RINGS USED IN GROOVES
H		Bow height	5139
h		Ring height	5115

FIGURE 13-72 *Definition symbols.* (Courtesy Koh-I-Noor Rapidograph)

SYMBOL		DEFINITION	RING SERIES WHERE APPLICABLE
J		Small section height	N5000, N5001, N5002, 5008, 5100, 5101, 5102, 5108, 5160, 5560
K		Maximum gaging diameter: ring installed in groove	5100, 5101, 5102, 5108, 5160, 5560
k		Overall ring width	5305, 5300
L M		L: Location of outer groove wall from plane of reference M: Width of retained part	N5001, N5002, 5101, 5102, 5131, 5139
P		Pliers hole diameter	N5000, N5001, N5002, 5008, 5100, 5101, 5102, 5108, 5160, 5555
p		Gap width	5139
P_r P'_r P_g	Allowable thrust load for ring (lbs.) Allowable assembly load with maximum corner radius or chamfer Allowable thrust load for groove (lbs.)		ALL RINGS USED IN GROOVES
R		Radius of groove bottom	ALL RINGS USED IN GROOVES
$R_{max.}$		Maximum allowable corner radius of retained part	N5000, N5001, N5002, 5008, 5100, 5101, 5102, 5103, 5107, 5108, 5131, 5133, 5144, 5160, 5555, 5560

SYMBOL		DEFINITION	RING SERIES WHERE APPLICABLE
S		Shaft or housing diameter	ALL RINGS
t		Ring thickness	ALL RINGS
U		Ring thickness at beveled edge	N5002, 5102
V		Overall bow height	N5001, 5101, 5131
W		Groove width	ALL RINGS USED IN GROOVES
X		Distance from outer groove wall to face of retained part	N5001, 5101, 5131, 5139
Y		Free outside diameter	5103, 5133, 5144, 5131, 5304
Z		Edge margin	ALL RINGS USED IN GROOVES
Z_1		Minimum distance from face of retained part to end of shaft or housing	5115, 5005, 5105, 5305

FIGURE 13-72 *(Continued)*



HOUSING DIA.			MIL-R-21248 MS 16625 INTERNAL SERIES N5000	TRUARC RING DIMENSIONS (Thickness t applies only to unplated rings. For plated and stainless steel (Type H) rings, add .002" to the listed maximum thickness. Maximum ring thickness will be at least .0002" less than the listed minimum groove width (W).)					GROOVE DIMENSIONS (T.I.R. (total indicator reading) is the maximum allowable deviation of concentricity between groove and housing.)					APPLICATION DATA			
				FREE DIA.		THICKNESS			DIAMETER		WIDTH			CLEARANCE DIAMETER		ALLOW. THRUST LOAD (lbs.) Sharp corner abutment	
Dec. equiv. inch	Approx. fract. equiv. inch	Approx. mm.						Approx. weight per 1000 pieces					Nominal groove depth	When sprung into housing S	When sprung into groove G	RINGS (Standard material) Safety factor = 4	GROOVES (Cold rolled steel bores and housings) Safety factor = 2
S	S	S	size—no.	D	tol.	t	tol.	lbs.	G	tol.	W	tol.	d	C_1	C_2	P_r	P_g
.250	1/4	6.4	N5000-25	.280		.015		.08	.268	±.001 .0015 T.I.R.	.018	+.002 −.000	.009	.115	.133	420	190
.312	5/16	7.9	N5000-31	.346		.015		.11	.330		.018		.009	.173	.191	530	240
.375	3/8	9.5	N5000-37	.415		.025		.25	.397	±.002	.029		.011	.204	.226	1050	350
.438	7/16	11.1	N5000-43	.482		.025		.37	.461	.002	.029		.012	.23	.254	1220	440
.453	29/64	11.5	N5000-45	.498		.025		.43	.477	T.I.R.	.029		.012	.25	.274	1280	460
.500	1/2	12.7	N5000-50	.548	+.010 −.005	.035		.70	.530		.039		.015	.26	.29	1980	510
.512	—	13.0	N5000-51	.560		.035		.77	.542	±.002 .004 T.I.R.	.039		.015	.27	.30	2030	520
.562	9/16	14.3	N5000-56	.620		.035		.86	.596		.039		.017	.275	.305	2220	710
.625	5/8	15.9	N5000-62	.694		.035		1.0	.665		.039		.020	.34	.38	2470	1050
.688	11/16	17.5	N5000-68	.763		.035		1.2	.732		.039	+.003 −.000	.022	.40	.44	2700	1280
.750	3/4	19.0	N5000-75	.831		.035		1.3	.796		.039		.023	.45	.49	3000	1460
.777	—	19.7	N5000-77	.859		.042		1.7	.825		.046		.024	.475	.52	4550	1580
.812	13/16	20.6	N5000-81	.901	+.015 −.010	.042		1.9	.862		.046		.025	.49	.54	4800	1710
.866	—	22.0	N5000-86	.961		.042		2.0	.920		.046		.027	.54	.59	5100	1980
.875	7/8	22.2	N5000-87	.971		.042		2.1	.931	±.003 .004 T.I.R.	.046		.028	.545	.60	5150	2080
.901	—	22.9	N5000-90	1.000		.042	±.002	2.2	.959		.046		.029	.565	.62	5350	2200
.938	15/16	23.8	N5000-93	1.041		.042		2.4	1.000		.046		.031	.61	.67	5600	2450
1.000	1	25.4	N5000-100	1.111		.042		2.7	1.066		.046		.033	.665	.73	5950	2800
1.023	—	26.0	N5000-102	1.136		.042		2.8	1.091		.046		.034	.69	.755	6050	3000
1.062	1 1/16	27.0	N5000-106	1.180		.050		3.7	1.130		.056		.034	.685	.75	7450	3050
1.125	1 1/8	28.6	N5000-112	1.249		.050		4.0	1.197		.056		.036	.745	.815	7900	3400
1.181	—	30.0	N5000-118	1.319		.050		4.3	1.255		.056		.037	.79	.86	8400	3700
1.188	1 3/16	30.2	N5000-118	1.319		.050		4.3	1.262		.056		.037	.80	.87	8400	3700
1.250	1 1/4	31.7	N5000-125	1.388		.050		4.8	1.330		.056		.040	.875	.955	8800	4250
1.259	—	32.0	N5000-125	1.388	+.025 −.020	.050		4.8	1.339		.056		.040	.885	.965	8800	4250
1.312	1 5/16	33.3	N5000-131	1.456		.050		5.0	1.396	±.004 .005 T.I.R.	.056		.042	.93	1.01	9300	4700
1.375	1 3/8	34.9	N5000-137	1.526		.050		5.1	1.461		.056		.043	.99	1.07	9700	5050
1.378	—	35.0	N5000-137	1.526		.050		5.1	1.464		.056	+.004 −.000	.043	.99	1.07	9700	5050
1.438	1 7/16	36.5	N5000-143	1.596		.050		5.8	1.528		.056		.045	1.06	1.15	10200	5500
1.456	—	37.0	N5000-145	1.616		.050		6.4	1.548		.056		.046	1.08	1.17	10300	5700
1.500	1 1/2	38.1	N5000-150	1.660		.050		6.5	1.594		.056		.047	1.12	1.21	10550	6000
1.562	1 9/16	39.7	N5000-156	1.734		.062		8.9	1.658		.068		.048	1.14	1.23	13700	6350
1.575	—	40.0	N5000-156	1.734	+.035 −.025	.062		8.9	1.671	±.005 .005 T.I.R.	.068		.048	1.15	1.24	13700	6350
1.625	1 5/8	41.3	N5000-162	1.804		.062	±.003	10.0	1.725		.068		.050	1.15	1.25	14200	6900
1.653	—	42.0	N5000-165	1.835		.062		10.4	1.755		.068		.051	1.17	1.27	14500	7200
1.688	1 11/16	42.9	N5000-168	1.874		.062		10.8	1.792		.068		.052	1.21	1.31	14800	7450

FIGURE 13-73 *Internal series N5000.* (Courtesy Koh-I-Noor Rapidograph)

FIG. 1: MAXIMUM ALLOWABLE CORNER RADIUS ($R_{max.}$) AND CHAMFER ($Ch_{max.}$)



FIG. 2: ENLARGED DETAIL OF GROOVE PROFILE AND EDGE MARGIN (Z)



MAXIMUM BOTTOM RADII	
Ring Size	R
-25 thru -100	.005
-102 thru -1000	.010

FIG. 3: SUPPLEMENTARY RING DIMENSIONS



FIG. 4: MINIMUM GAP WIDTH (Ring installed in groove)



SUPPLEMENTARY APPLICATION DATA					SUPPLEMENTARY RING DIMENSIONS								
INTERNAL SERIES **N5000**	Maximum allowable corner radii and chamfers of retained parts (Fig. 1)		Allow. assembly load with $R_{max.}$ or $Ch_{max.}$	Edge margin (Fig. 2)	LUG		LARGE SECTION		SMALL SECTION		HOLE DIAMETER		MIN. GAP WIDTH (Fig. 4) Ring installed in groove
size—no.	R_{max}	$Ch_{max.}$	P'_r (lbs.)	Z	B	tol.	E	tol.	J	tol.	P	tol.	A
N5000-25	.011	.0085	190	.027	.065		.025		.015		.031		.047
N5000-31	.016	.013	190	.027	.066		.033	±.002	.018	±.002	.031		.055
N5000-37	.023	.018	530	.033	.082		.040		.028		.041		.063
N5000-43	.027	.021	530	.036	.098	±.003	.049	±.003	.029	±.003	.041		.063
N5000-45	.027	.021	530	.036	.098		.050		.030		.047		.071
N5000-50	.027	.021	1100	.045	.114		.053		.035		.047		.090
N5000-51	.027	.021	1100	.045	.114		.053		.035		.047		.092
N5000-56	.027	.021	1100	.051	.132		.053		.035		.047		.095
N5000-62	.027	.021	1100	.060	.132		.060	±.004	.035	±.004	.062		.104
N5000-68	.027	.021	1100	.066	.132		.063		.036		.062	+.010 −.002	.118
N5000-75	.032	.025	1100	.069	.142		.070		.040		.062		.143
N5000-77	.035	.028	1650	.072	.146		.074		.044		.062		.145
N5000-81	.035	.028	1650	.075	.155		.077		.044		.062		.153
N5000-86	.035	.028	1650	.081	.155		.081		.045		.062		.172
N5000-87	.035	.028	1650	.084	.155		.084	±.005	.045	±.005	.062		.179
N5000-90	.038	.030	1650	.087	.155		.087		.047		.062		.188
N5000-93	.038	.030	1650	.093	.155		.091		.050		.062		.200
N5000-100	.042	.034	1650	.099	.155		.104		.052		.062		.212
N5000-102	.042	.034	1650	.102	.155		.106		.054		.062		.220
N5000-106	.044	.035	2400	.102	.180		.110		.055		.078		.213
N5000-112	.047	.036	2400	.108	.180	±.005	.116		.057		.078		.232
(S=1.181) N5000-118	.047	.036	2400	.111	.180		.120		.058		.078		.226
(S=1.188) N5000-118	.047	.036	2400	.111	.180		.120		.058		.078		.245
(S=1.250) N5000-125	.048	.038	2400	.120	.180		.124		.062		.078		.265
(S=1.259) N5000-125	.048	.038	2400	.120	.180		.124	±.006	.062	±.006	.078		.290
N5000-131	.048	.038	2400	.126	.180		.130		.062		.078		.284
(S=1.375) N5000-137	.048	.038	2400	.129	.180		.130		.063		.078	+.015	.297
(S=1.378) N5000-137	.048	.038	2400	.129	.180		.130		.063		.078	−.002	.305
N5000-143	.048	.038	2400	.135	.180		.133		.065		.078		.313
N5000-145	.048	.038	2400	.138	.180		.133		.065		.078		.320
N5000-150	.048	.038	2400	.141	.180		.133		.066		.078		.340
(S=1.562) N5000-156	.064	.050	3900	.144	.202		.157		.078		.078		.338
(S=1.575) N5000-156	.064	.050	3900	.144	.202		.157		.078		.078		.374
N5000-162	.064	.050	3900	.150	.227		.164	±.007	.082	±.007	.078		.339
N5000-165	.064	.050	3900	.153	.227		.167		.083		.078		.348
N5000-168	.064	.050	3900	.156	.227		.170		.085		.078		.357

FIGURE 13-73 *(Continued)*

• Sizes -206 thru -1000 are available in banded or tape-wrapped Rol-Pak cartridges.



SHAFT DIAMETER			MIL-R-21248 MS 16624	TRUARC RING DIMENSIONS					GROOVE DIMENSIONS					APPLICATION DATA			
				Thickness t applies only to unplated rings. For plated and stainless steel (Type H) rings, add .002" to the listed maximum thickness. Maximum ring thickness will be at least .0002" less than the listed minimum groove width (W).					T.I.R. (total indicator reading) is the maximum allowable deviation of concentricity between groove and shaft.					CLEARANCE DIAMETER		ALLOW. THRUST LOAD (lbs.) Sharp Corner Abutment	
Dec. equiv. inch	Approx fract. equiv. inch	Approx mm	EXTERNAL SERIES 5100	FREE DIA.		THICKNESS		Approx weight per 1000 pieces	DIAMETER		WIDTH		Nominal groove depth	When sprung over shaft S	When sprung into groove G	RINGS (standard material) Safety factor = 4	GROOVES (Cold Rolled steel shafts) Safety factor = 2
S	S	S	size — no.	D	tol.	t	tol.	lbs.	G	tol.	W	tol.	d	C_1	C_2	P_r	P_g
3.438	3 7/16	87.3	5100-343	3.179		.093		66.0	3.257		.103		.090	4.14	3.96	37700	21900
3.500	3 1/2	88.9	5100-350	3.237		.109		72.0	3.316		.120		.092	4.25	4.07	44900	22800
3.543	—	90.0	5100-354	3.277	+.020 −.030	109		73.0	3.357	±.006	120		093	4.29	4.11	45500	23300
3.625	3 5/8	92.1	5100-362	3.352		.109	±.003	76.0	3.435	.006	120	+ 005	095	4.37	4.18	46600	24300
3.688	3 11/16	93.7	5100-368	3.410		.109		80.0	3.493	T.I.R.	120	− 000	097	4.43	4.24	47300	25300
3.750	3 3/4	95.2	5100-375	3.468		.109		83.0	3.552		.120		099	4.50	4.31	48100	26200
3.875	3 7/8	98.4	5100-387	3.584		.109		88.0	3.673		.120		.101	4.60	4.40	49700	27700
3.938	3 15/16	100.0	5100-393	3.642		.109		95.0	3.734		.120		.102	4.70	4.50	50600	28400
4.000	4	101.6	5100-400	3.700		.109		101.0	3.792		.120		104	4.78	4.58	51400	29400
4.250	4 1/4	108.0	5100-425	3.989		.109		112.0	4.065		.120		092	5.09	4.91	54600	27600
4.375	4 3/8	111.1	5100-437	4.106		.109		115.0	4.190		.120		092	5.22	5.04	56200	28400
4.500	4 1/2	114.3	5100-450	4.223		.109		101.0	4.310		.120		.095	5.37	5.18	57800	30200
4.750	4 3/4	120.6	5100-475	4.458		.109		113.0	4.550		.120		100	5.67	5.47	61000	33600
5.000	5	127.0	5100-500	4.692		.109		149.0	4.790		.120		105	5.96	5.75	64200	37100
5.250	5 1/4	133.3	5100-525	4.927		.125		190.0	5.030		139		.110	6.27	6.05	77300	40800
5.500	5 1/2	139.7	5100-550	5.162	+.020 −.040	.125	±.004	202.5	5.265	±.007 .006 T.I.R.	.139	+.006 −.000	117	6.57	6.34	81000	45500
5.750	5 3/4	146.0	5100-575	5.396		.125		220.0	5.505		.139		122	6.86	6.62	84700	49600
6.000	6	152.4	5100-600	5.631		.125		210.0	5.745		.139		.127	7.16	6.91	88300	53800
6.250	6 1/4	158.7	5100-625	5.866		.156		282.0	5.985		.174		132	7.46	7.20	114800	58300
6.500	6 1/2	165.1	5100-650	6.100	+.020 −.050	.156		330.0	6.225		.174		.137	7.87	7.60	119400	62900
6.750	6 3/4	171.4	5100-675	6.335		.156		356.0	6.465		.174		142	8.06	7.78	124000	67700
7.000	7	177.8	5100-700	6.570		.156		388.0	6.705		.174		147	8.36	8.07	128600	72700
7.250	7 1/4	184.2	5100-725	6.775		.187	±.005	510	6.942		.209		154	8.70	8.39	159700	78900
7.500	7 1/2	190.5	5100-750	7.009		.187		534	7.180		.209		160	8.96	8.64	165200	84800
7.750	7 3/4	196.9	5100-775	7.243		.187		545	7.420		209		165	9.20	8.87	170700	90450
8.000	8	203.2	5100-800	7.478		.187		640	7.660		.209		.170	9.60	9.26	176200	98100
8.250	8 1/4	209.6	5100-825	7.712		.187		665	7.900	± 008 .006 T.I.R.	.209	+.008 −.000	.175	9.85	9.50	181700	102100
8.500	8 1/2	215.9	5100-850	7.947	+ .050	.187		692	8.140		.209		.180	10.10	9.74	187200	108100
8.750	8 3/4	222.3	5100-875	8.181	− .130	.187		712	8.380		.209		185	10.40	10.00	192700	114450
9.000	9	228.6	5100-900	8.415		.187		737	8.620		.209		.190	10.60	10.22	198200	120800
9.250	9 1/4	234.9	5100-925	8.650		.187		760	8.860		.209		195	10.85	10.50	203700	128225
9.500	9 1/2	241.3	5100-950	8.885		.187		785	9.100		.209		.200	11.10	10.70	209200	134200
9.750	9 3/4	247.6	5100-975	9.120		.187		845	9.338		.209		206	11.35	10.95	214700	142000
10.000	10	254.0	5100-1000	9.355		.187		910	9.575		.209		.212	11.60	11.20	220200	149800

FIGURE 13-74 *External series 5100.* (Courtesy Koh-I-Noor Rapidograph)

FIG. 1: MAXIMUM ALLOWABLE CORNER RADIUS ($R_{max.}$) AND CHAMFER ($Ch_{max.}$)



FIG. 2: ENLARGED DETAIL OF GROOVE PROFILE AND EDGE MARGIN (Z)

MAXIMUM BOTTOM RADII	
Ring size	R
-12 thru -23	Sharp corners
-25 thru -35	.003
-37 thru -100	.005
-102 thru -200	.010

FIG. 3: SUPPLEMENTARY RING DIMENSIONS



FIG. 4: MAXIMUM GAGING DIAMETER (Ring installed in groove)



FIG. 5: LUG DESIGN Sizes -12 thru -23



SUPPLEMENTARY APPLICATION DATA						SUPPLEMENTARY RING DIMENSIONS (Fig. 3)								
EXTERNAL SERIES 5100	Maximum allowable corner radii and chamfers of retained parts (Fig. 1)		Allow. assembly load with $R_{max.}$ or $Ch_{max.}$	Edge margin (Fig. 2)	Calculated RPM limits (Std. ring mat'l.) Apply req'd. safety factor	LUG		LARGE SECTION		SMALL SECTION		HOLE DIAMETER		MAX. GAGING DIA. Ring installed in groove (Fig. 4)
size — no.	$R_{max.}$	$Ch_{max.}$	P'_r (lbs.)	Z		B	tol.	E	tol.	J	tol.	P	tol.	K
5100-343	.129	.077	7350	.270	5900	.308	±.005	.292	±.008	.148	±.008	.125	+.015 −.002	3.712
5100-350	.122	.073	10500	.276	5900	.328		.285		.148		.125		3.764
5100-354	.123	.074	10500	.279	5800	.328		.288		.149		.125		3.809
5100-362	.127	.076	10500	.285	5700	.328		.296		.153		.125		3.898
5100-368	1295	.078	10500	.291	5600	.330		.302		.156		.125		3.966
5100-375	133	.080	10500	.297	5500	.332		.310		.160		125		4.037
5100-387	137	.082	10500	.303	5100	.330		.318		.163		.125		4.169
5100-393	137	.082	10500	.306	5200	.342		.318		.163		.125		4.230
5100-400	135	.081	10500	.312	5000	.352		.318		.163		.125		4.288
5100-425	146	.088	10500	.276	4800	.395		.318		.176		.125		4.558
5100-437	.146	.088	10500	.276	4700	.395	±.008	.318	±.010	.181	±.010	.125		4.683
5100-450	.102	.061	10500	.285	4500	.404		.285		.128		.125		4.730
5100-475	.115	.069	10500	.300	4200	.429		.303		.136		.125		4.996
5100-500	.165	.099	10500	.315	4000	.450		.360		194		.156		5.346
5100-525	.169	.101	13500	.330	3900	.472		.372		.211		.156		5.605
5100-550	175	.105	13500	.351	3700	.497		.390		.209		.156		5.867
5100-575	.184	.110	13500	.366	3500	.518		.408		.220		.156		6.134
5100-600	.143	.086	13500	.381	3400	.540		.381		.171		.156		6.302
5100-625	.148	.089	21000	.396	3100	.561		.396		.176		.156		6.568
5100-650	.191	.114	21000	.411	3000	.586		.438		.236		.156		6.905
5100-675	200	.120	21000	.426	3000	.608	±.012	.456	±.015	.246	±.015	.187	+.020 −.005	7.172
5100-700	208	.125	21000	.441	2900	.629		.474		.256		.187		7.439
5100-725	214	128	30000	.460	2800	.660		.490		.267		.187		7.700
5100-750	220	132	30000	480	2700	676		.507		.277		.187		7.963
5100-775	227	136	30000	495	2600	660		.523		.285		.187		8.228
5100-800	235	141	30000	.510	2500	.735		.540		294		.187		8.493
5100-825	242	146	30000	.525	2400	.735		.556		304		.187		8.758
5100-850	250	.150	30000	.540	2300	.735		.573		.314		.187		9.023
5100-875	258	.155	30000	.555	2200	.735		.591		.322		.187		9.280
5100-900	267	.160	30000	.570	2200	.735		.609		.333		.187		9.557
5100-925	274	.164	30000	.585	2100	.735		625		341		.187		9.830
5100-950	281	.168	30000	.600	2100	.735		.642		.350		187		10.086
5100-975	287	.172	30000	.618	2000	735		.658		.358		.187		10.340
5100-1000	294	.176	30000	.636	2000	.735		.675		.367		.187		10.610

FIGURE 13-74 *(Continued)*

Summary

- Threads are used for four applications: (1) to fasten parts together, (2) for fine adjustments between parts, (3) for fine measurements, and (4) to transmit motion or power.
- Screw thread forms include the unified national, ISO, metric, square, acme worm, knuckle, and buttress.
- Inside and outside threads are produced using taps and dies. Taps are used to cut internal threads; dies are used to cut external threads.
- Pitch is the distance from one point on a thread to the corresponding point on the adjacent thread as measured parallel to its axis.
- A single thread is composed of one continuous ridge. Lead is the distance a screw thread advances axially in one full turn. Multiple threads are made up of two or more continuous ridges side-by-side.
- A right-hand thread rotates in a clockwise direction. A left-hand thread rotates in a counterclockwise direction.
- Threads may be represented graphically in the following ways: schematic or simplified.
- A screw is a threaded fastener that does not use a nut and is screwed directly into a part. A bolt is a threaded fastener that passes directly through parts to hold them together and uses a nut. A stud is a fastener that is a steel rod with threads at both ends.
- Rivets are permanent fasteners, usually used to hold sheet metal together.
- A key is a demountable part that provides a positive means of transferring torque between a shaft and a hub.
- Grooved fasteners are used to solve metal-to-metal pinning needs with shear application.
- Spring pins are manufactured by cold-forming strip metal in a progressive roll-forming operation. They are slightly larger in diameter than the hole into which they are inserted.
- Retaining rings are precision-engineered fasteners that provide removable shoulders for positioning or limiting movement in an assembly.

Review Questions

Answer the following questions either true or false.

1. Two other uses for threads besides fastening things together are adjusting parts and measuring and transmitting power.
2. If you have a 1/4 – 20 UNC threaded screw and rotate it 10 full turns, the end will travel 1/2″.
3. A 5115 series retaining ring would be recommended to provide resilient end play take-up.
4. The free diameter of an external 5100-775 retaining ring is 7.243.
5. The depth of a thread is figured by measuring the distance between the crest and the root of the thread, as measured at a right angle to the axis.

Answer the following questions by selecting the best answer.

1. What #5100 series retaining ring would be recommended for a shaft diameter of 203.2 mm?
   a. 5100-343
   b. 5100-437
   c. 5100-675
   d. 5100-800
2. What is **not** a factor to be considered before selecting any type of retaining ring, other than load capacity?
   a. lug size
   b. adequate clearance
   c. the cost of installing the ring
   d. whether or not a groove is required
3. What does 5.8 – 11 UNC – 2A × 21.2 LG mean?
   a. 5.8″ long, right-hand thread, average fit
   b. 5.8″ nominal size, 11 TPI, Unified National Series- Coarse, average fit, external thread, 21.2″ long
   c. 5.8″ diameter, 11″ long, coarse series
   d. 11 fit, coarse × 21.2″ long × 5.8″ diameter

4. What is the recommended hole size for a .312″ (8) diameter spring pin?
   a. Min .312, Max .318
   b. Min .321, Max .328
   c. Min .322, Max .325
   d. Min .315, Max .318

5. A screw that is 3″ long, 3.8″ in diameter, 15 threads per inch, unified coarse, right-hand threads, average fit, and rounded-head style cap screw is called out by:
   a. 3.8 × 15 UNC – RDH Cap Screw × 3.0 LG
   b. RDH Cap Screw – 15 UNC 3.8 × 3.0 LG
   c. 3.8 – 15 UNC – 2A × 3.0 LG RDH
   d. 3″ Long Round Head Cap Screw (3.8″ diameter, coarse)

6. The housing diameter for an internal series N5000- 25 ring is:
   a. .688
   b. .453
   c. .250
   d. .875

7. Which phrase is **not** true of a series 5115 self-locking ring?
   a. is used for flat contact surfaces
   b. withstands heavy thrust loads
   c. should not be used with ungrooved shafts
   d. has arched rim for extra strength

Chapter 13 Problems

The following problems are intended to give the beginning drafter practice using various size charts of fastener and, by using these charts, practice in laying out and drawing the many fasteners used.

Conventional Instructions

The steps to follow in laying out fasteners are:

STEP 1 Study all required specifications.

STEP 2 Using the appropriate size chart for size dimension, lightly lay out fastener in place.

STEP 3 Check each dimension.

STEP 4 Darken in the fastener, starting with diameters and arcs first to correct line thickness. Use simplified thread representation.

STEP 5 Neatly add all required call-off specifications, using the latest drafting standard.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

PROBLEM 13-1

On an A-size, 81.2 × 11 sheet of paper, lay out the center lines per the given dimensions.

Calculate standard thread lengths.

Draw the following fasteners on the center lines as illustrated.

A. Flathead cap screw—3.8 – 16 UNC – 2A × 2.0 lg.
B. Roundhead cap screw—1/2 – 13 UNC – 2A × 2.25 lg.
C. Fillister-head cap screw—5.8 – 11 UNC – 2A × 2.5 lg.
D. Oval-head cap screw—3.8–24 UNF – 2A × 1.75 lg.
E. Hex-head cap screw with hex nut—1 – 8 UNC – 2A × 2.5 lg.
F. Socket-head cap screw—1.2 – 20 UNF – 2A × 2.0 lg.
G. Cotter pin—3.8 dia. × 3.5 lg.



PROBLEM 13-2

On an A-size, 81.2 × 11 sheet of paper, lay out the center lines per the given dimensions.

Calculate standard thread lengths.

Draw the following fasteners on the center lines as illustrated.

A. Hex-head bolt—13.8 – UNC × 3.0 lg.
B. Lock washer (for a 7.8 dia. cap screw).
C. Square nut—1 – 12 UNF 2B.
D. Square-head cap screw—3.4 – 10 UNC × 3.0 lg.



PROBLEM 13-3

On an A-size, 81.2 × 11 sheet of paper, lay out the center lines per the given dimensions.

A. Calculate the required size of square key needed for a 2.25 ID collar. Draw collar and keyway, and dimension per drafting standards.

B. Calculate the required size of square key needed for the matching shaft of the collar. Draw the end view of the shaft and dimension per drafting standards.

C. Calculate the **minimum** length hex-head cap screw, 3.4 – 10 UNC – 2A required to safely secure part X to part Y (material: aluminum).

Illustrate and call off the required pilot drill size and recommended depth into part Y.

Illustrate and call off the required size and depth of **full** threads for the hexhead cap screw.

Illustrate and call off the diameter for clearance hole in part X.

D. Draw a square-head set screw with a full dog point, 5.8 – 18 UNF × 3.0 lg.



PROBLEM 13-4

On an A-size, 81.2 × 11 sheet of paper, lay out the center lines, part X, and part Y per the given dimensions.

Calculate the standard thread lengths.

Draw the following fasteners on the center lines as illustrated.

Give **all** specific hole call-off information for each fastener in the space above each as illustrated. Include clearance hole sizes, counterbore specifications, countersink specifications, spotface specifications, required tap drill size and depth for 75% thread, and tap size and required depth per the latest drafting standards.

A. Socket-head cap screw—7.8 – 9 UNC × 1.75 lg (calculate counterbore information).

B. Oval-head cap screw—3.4 – 10 UNC × 2.5 lg (calculate countersink information).

C. Hex-head cap screw—1 – 12 UNF × 2.5 lg (calculate spotface information).

D. Fillister-head cap screw with plain washer and hex-head nut—4 – 16 UNF × length to suit. (Calculate clearance hole required.)



PROBLEM 13-5

Given: an illustration of an old design (Figure 13-5A) that uses a washer and cotter pin to hold the .3543 diameter shaft in place. Using this design, it was necessary to locate and drill a hole for the cotter pin. The new design incorporated the use of one retaining ring to achieve the same function at a much lower cost. Choose the correct type and size retaining ring and fill in the required dimensions at A, B, and C (see Figure 13-6A). Neatly letter all retaining ring data below the dimensioned shaft as illustrated.





PROBLEM 13-6

Given: an illustration of an old design (Figure 13-5B) that uses a cover plate with 4 holes for 4 washers and 4 round-head machine screws to hold the shaft in place. Using this design required drilling 4 blind tap-drill holes that had to be tapped for the 4 round-head screws. The new design incorporated the use of one retaining ring to achieve the same function at a much lower cost. Choose the correct type and size retaining ring and fill in the required dimensions at A, B, and C (see Figure 13-6B). Neatly print all retaining ring data below the dimensioned collar as illustrated.



DATA:

RETAINING RING NUMBER _____
FREE DIAMETER _____
THICKNESS _____
LUG SIZE _____
LARGE SECTION _____
SMALL SECTION _____
PLIER HOLE SIZE _____
MAX. GAGING DIA. WHEN INSTALLED _____



DATA:

RETAINING RING NUMBER _____
FREE DIAMETER _____
THICKNESS _____
LUG SIZE _____
LARGE SECTION _____
SMALL SECTION _____
PLIER HOLE SIZE _____
MIN. GAGING DIA. WHEN INSTALLED _____

14

Springs

KEY TERMS

Active coils
Coil (turn)
Compression spring
Direction of winding
Extension spring
Flat spring
Free length
Helical spring
Inside diameter
Loaded length
Mean diameter
Outside diameter
Solid length
Spring
Torsion spring
Wire size

CHAPTER OUTLINE

Spring classification • Helical springs • Flat springs • Terminology of springs • Required spring data • Other spring design layout • Standard drafting practices • Section view of a spring • Isometric views of a spring • Summary • Review questions • Chapter 14 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the classifications of springs.
- Describe the three different kinds of helical springs and their functions.
- Define the function of flat springs.
- Define the various terms associated with springs and their design.
- List the spring data that should accompany spring drawings.
- Demonstrate proficiency in drawing the various types of springs.
- Demonstrate proficiency in applying standard drafting practices when drawing springs.
- Demonstrate proficiency in drawing sectional views of springs.
- Demonstrate proficiency in drawing isometric views of springs.

A *spring* is a mechanical device that is used to store and apply mechanical energy. A spring can be designed and manufactured to apply a pushing action, a pulling action, a torque or twisting action, or a simple power action.

Product manufacturers usually use standard-size springs that are purchased from companies that specialize in making springs. These springs are usually mass produced and are, therefore, relatively inexpensive. Occasionally, however, a special spring must be designed to perform a special function. To be able to design special-function springs, the drafter or designer must know the many terms associated with springs and how to design and construct special springs.

Spring Classification

A spring is generally classified as either a helical spring or a flat spring. *Helical springs* are usually cylindrical or conical; the *flat springs*, as their name implies, are usually flat.

Helical Springs

Three types of helical springs are compression springs, extension springs, and torsion springs, ***Figures 14-1A, 14-1B, and 14-1C.***



FIGURE 14-1A *Types of helical springs (1) compression spring, (2) extension spring, (3) torsion spring.*

FIGURE 14-1B *Varieties of compression and extension springs.* (Courtesy AMETEK Inc., Hunter Spring Division)



FIGURE 14-1C *Varieties of torsion springs.* (Courtesy AMETEK Inc., Hunter Spring Division)

Compression Spring

A *compression spring* offers resistance to a compressive force or applies a pushing action. In its free state, the coils of the compression spring do not touch. The types of ends of a compression spring are illustrated and described as follows:

Plain open-end—Figure 14-2A. The plain open-end spring is very unstable, has only point contact, and has ends that are not perpendicular to the axis of the spring.

Plain closed-end—Figure 14-2B. The plain closed-end spring is a little more stable and provides a round, parallel surface contact perpendicular to the axis of the spring.

Ground open-end—Figure 14-2C. The ground open-end spring is much more stable and provides a flat surface contact perpendicular to the axis of the springs.

Ground closed-end—Figure 14-2D. The ground closed-end spring is the most stable, and the best design. This design provides a large, flat surface contact perpendicular to the axis of the spring.

A good example of a compression spring is the kind that is used in the front end of an automobile.

Extension Spring

An *extension spring* offers resistance to a pulling force. In its free state, the coils of the extension spring are usually either touching or very close. The ends of an extension spring are usually a hook or loop, *Figure 14-3.* Illustrated are a few of the many kinds of ends that are used. The loop or hook can be over the center or at the side. Each end is designed for a specific application or assembly. Regardless of the shape of the loop or hook, the overall length of an extension spring is measured from the inside of the loops or hook. A good example of an extension spring is the kind that is used to counterbalance a garage door.



FIGURE 14-2A *Plain open-end compression spring.*



FIGURE 14-2B *Plain closed-end compression spring.*



FIGURE 14-2C *Ground open-end compression spring.*



FIGURE 14-2D *Ground closed-end compression spring.*



FIGURE 14-3 *Ends of extension spring.*



FIGURE 14-4 *Torsion spring.*

Torsion Spring

A *torsion spring* offers resistance to a torque or twisting action. In its free state, the coils of a torsion spring are usually either touching or very close. The ends of a torsion spring are usually specially designed to fit a particular mechanical device, ***Figure 14-4.*** A good example of a torsion spring is the kind that is used to return a doorknob to its original position.

Flat Springs

The other classification or type of spring is the flat spring. The flat spring is made of spring steel and is designed to perform a special function. Flat springs are not standard and must be designed and manufactured to fit each particular need. The flat spring is considered a power spring, and it resists a pressure. A good example of a flat spring is the kind that is used for a door latch on a cabinet, ***Figure 14-5,*** or a leaf spring as used in a truck, ***Figure 14-6.*** A flat spiral spring used to power a windup clock or toy is another example, ***Figure 14-7.***

Terminology of Springs

It is important to know and fully understand the various terms associated with springs and their design, ***Figure 14-8.***



FIGURE 14-5 *Flat spring.*



FIGURE 14-6 *Leaf spring.*



FIGURE 14-7 *Special spring.*



FIGURE 14-8 *Spring terminology.*

Free Length

Free length is the overall length of the spring when it is in its free state of unloaded condition. Free length of a compression spring is measured from the extreme ends of the spring. In an extension spring, the free length is measured inside the loops or hooks.

Solid Length

Solid length of a compression spring is the overall length of the spring when all coils are compressed together so they touch. This can be mathematically calculated. If the wire diameter is .500, the overall solid length is 3.25.

Outside Diameter

Outside diameter (OD) is the outside diameter of the spring (2 × wire size **plus** inside diameter).

Wire Size

Wire size is the diameter of the wire used to make up the spring.

Inside Diameter

Inside diameter (ID) is the inside diameter of the spring (2 × wire size **minus** outside diameter).

Active Coils

Active coils in a compression spring are usually the total coils minus the two end coils. In a compression spring, the coil at each end is considered nonfunctional. In an extension spring, active coils include **all** coils.

Loaded Length

Loaded length is the overall length of the spring with a special given or designed load applied to it.

Mean Diameter

Mean diameter is the theoretical diameter of the spring measured to the center of the wire diameter. This theoretical diameter is used by the drafter to lay out and draw a spring. To mathematically calculate the mean diameter, subtract the wire diameter from the outside diameter.

Coil

Coil or *turn* is one full turn or 360° of the wire about the center axis, *Figure 14-9*.

Direction of Winding

Direction of winding is the direction in which the spring is wound. It can be wound right hand or left hand, *Figure 14-10*. The thumbs of your hands point toward the direction in which the coil windings are leaning. If the coil windings slant to the right, as the example to the left illustrates, it agrees with the direction of your left-hand thumb; thus, a left-hand winding. If the coil windings slant to the left as the example to the right illustrates, it agrees with the direction of your right-hand thumb; thus, a right-hand winding. If the coil winding direction is not called off on the drawing, it will be manufactured with right-hand winding.



FIGURE 14-9 *Coils or turns.*



FIGURE 14-10 *Direction of winding.*

Required Spring Data

Each drawing must include complete dimensions and specific data. Besides the regular dimensions, that is, outside diameter (OD) and/or inside diameter (ID), wire size, free length, and solid length (compression spring), the following data should be called off at the lower right side of the work area:

- Material
- Number of coils (including active and inactive coils)
- Direction of winding (if not noted, it is assumed to be right hand)
- Torque data (if torsion spring)
- Finish
- Heat treatment specification
- Any other required data

How to Draw a Compression Spring

GIVEN: Plain open ends, 1.50 outside diameter, .25 diameter wire size, 4.00 free length, oil-tempered spring steel wire, 8 total coils (6 active coils), left-hand winding, heat treatment: heat to relieve coiling stresses, finish: black paint. Make a rough sketch of the spring using the given specifications, *Figure 14-11A*. A rough sketch is extremely important in developing a new spring design.

STEP 1 Measure and construct two vertical lines the required overall length (front view). Divide the space between the two vertical lines into 17 equal spaces (front view) 2 × total coils plus 1; in this example, 2 × 8 + 1 = 17, *Figure 14-11B*. Measure and construct the mean diameter. To calculate the mean



FIGURE 14-11 *(A) How to draw a compression spring with plain open ends; (B) Step 1; (C) Step 2.*

diameter, subtract the wire diameter from the outside diameter (end view).

STEP 2 Determine the direction of windings; refer to the sketch and lightly construct the wire diameter accordingly (front view). The wire diameters are constructed on the mean diameter. Lightly draw the outside diameter and inside diameter (end view), *Figure 14-11C.*

STEP 3 Lightly construct the near side of the spring. Add short, light tangent points, *Figure 14-11D.*

STEP 4 Lightly construct the rear side of the spring. Add ends of spring; in this example, plain open ends. Check all work against given requirements, *Figure 14-11E.*

STEP 5 Recheck all work. Darken in spring using the latest drafting standards. Add end of spring, right end, dimensions, and all required spring data, *Figure 14-11F.*



FIGURE 14-11 *(Continued) (D) Step 3; (E) Step 4; (F) Step 5.*

NOTICE: Outside diameter, wire size, free length, and solid length are given as regular dimensions. The material, number of coils, direction of winding, heat treatment specifications, and finish requirements are listed below and to the right as a note. In this example, the outside diameter is the controlling dimension; that is, the outside dimension is more important than the inside dimension. Inside and outside dimensions should not both be added to the same drawing.

How to Draw a Compression Spring (Plain Closed Ends)

GIVEN: Plain closed ends, 20 mm inside diameter, 5 mm diameter wire size, 100 mm free length,

material: hard drawn steel spring wire, 5 active coils (total 7 coils), left-hand winding, heat treatment: heat to relieve coiling stresses, finish: zinc plate. Make a rough sketch of the spring using the given specifications, *Figure 14-12A.*

STEP 1 Measure and construct two vertical lines the required overall length (front view). Draw a line **inside** the two vertical lines equal to half the wire diameter from each end. Divide the space between the two vertical lines into 13 equal spaces (front view) 2 × total coils minus 1; in this example, 2 × 7 − 1 = 13, *Figure 14-12B.* Measure and construct the mean diameter. To calculate the mean diameter, add the wire diameter to the inside diameter (end view).

STEP 2 Determine the direction of winding; refer to the sketch and lightly construct the wire diameter accordingly (front view). Lightly draw the outside diameter and inside diameter (end view), *Figure 14-12C.*

STEP 3 Lightly construct the near side of the spring. Add short tangent points, *Figure 14-12D.*

STEP 4 Lightly construct the rear side of the spring. Add ends of springs. In this example, plan closed ends. Check all work against given requirements, *Figure 14-12E.*

STEP 5 Recheck all work. Darken in spring using the latest drafting standards. Add all required dimensions and spring data, *Figure 14-12F.*



(A)



(B)



(C)



(D)



(E)



(F)

FIGURE 14-12 *(A) How to draw a compression spring with plain closed ends; (B) Step 1; (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5.*

How to Draw a Compression Spring (Ground Closed Ends)

(The following illustrations are for a ground closed-end compression spring. The same steps can be used for a ground open-end compression spring.)

GIVEN: Ground closed ends, 1.125 outside diameter, .188 diameter wire size, 3.00 free length, material: hard drawn steel spring wire, 7 total coils (5 active coils), right-hand winding, heat treatment: heat to relieve coiling stresses, finish: zinc plate. Make a rough sketch of the spring using the given specifications, *Figure 14-13A.*

STEP 1 Measure and construct two vertical lines the required free length (front view). Divide the space between the two vertical lines into 13 equal spaces (front view), 2 × total coils minus 1; in this example, 2 × 7 − 1 = 13, *Figure 14-13B.* Measure and construct the mean diameter. To calculate the mean diameter, subtract the wire diameter from the outside diameter (end view).

STEP 2 Determine the direction of winding; refer to the sketch and lightly construct the wire diameter accordingly (front view). Lightly draw the outside diameter and inside diameter (end view), *Figure 14-13C.*

STEP 3 Lightly construct the rear side of the spring. Add short tangent points, *Figure 14-13D.*



(A)



(B)

FIGURE 14-13 *(A) How to draw a compression spring with ground closed ends; (B) Step 1.*



(C)



(D)



(E)



(F)

FIGURE 14-13 *(Continued) (C) Step 2; (D) Step 3; (E) Step 4; (F) Step 5.*

STEP 4 Lightly construct the rear side of the spring. Add ends of spring; in this example, ground closed end. Check all work against given requirements, *Figure 14-13E.*

STEP 5 Recheck all work. Darken in spring using the latest drafting standards. Add all required dimensions and spring data, *Figure 14-13F.*

How to Draw an Extension Spring

GIVEN: Full loop, over center each end 1.625 outside diameter, .188 diameter wire size, 4.750 approximate free length, material: hard drawn spring steel wire, heat treatment: heat to relieve coiling stresses, finish: black paint, windings as tight as possible. Make a rough sketch of the spring using the given specifications, *Figure 14-14A.*

STEP 1 Draw the outside diameter, inside diameter, and mean diameter (end view). Lightly draw the required free length. In the design of an extension spring, it is almost impossible to arrive at the **exact** free length. In designing an extension spring, it is best to design it slightly **shorter** than actually required. Construct the end loops with the **inside** diameter within the specified free length, *Figure 14-14B.* Note in this example the loops are the exact diameter as the spring itself.

STEP 2 Starting at the intersection of the mean diameter of the right end loop and the mean diameter of the spring, lower side, locate and draw the first lower wire diameter, *Figure 14-14C.* Project directly up to the mean diameter of the spring, upper side, and draw the first upper wire diameter **over** to the left, half a wire diameter as illustrated. Lay out, side-by-side, wire diameters touching, as illustrated; in this example, 10 ½ coils. Notice the coils must end on the mean diameter, left end. This may mean adjusting slightly the location of the left end loop. It is best to bring it in slightly, if necessary.

STEP 3 Locate points X and Y, as illustrated in *Figure 14-14D,* and adjust the drafting machine at this angle and lock on this angle. Draw the wire loops.

STEP 4 Lightly draw the loop in the right-side view. To calculate just what the loop will actually look like, number various points along the loop in the front view; in this example, point 1, starting point; point 2, up; point 3, over; and point 4, around. Project these points to the end view, as illustrated in *Figure 14-14E.*



FIGURE 14-14 *(A) How to draw an extension spring with full loop ends; (B) Step 1.*



FIGURE 14-14 *(Continued) (C) Step 2; (D) Step 3; (E) Step 4.*



FIGURE 14-14 *(Continued) (F) Step 5.*

STEP 5 Recheck all work. Darken in spring using the latest drafting standards. Add all required dimensions and spring data, *Figure 14-14F.*

Other Spring Design Layout

When drawing any specially designed spring for a particular function, one should make a rough sketch of it, including all required specifications. A torsion spring is developed in a manner very similar to an extension spring with its tight coils. Usually, the required torque pressure is included in the given spring data. The actual designed deflection of the torsion spring is illustrated by phantom lines, and the angle is noted.

Standard Drafting Practices

Some company standards specify that the drafter not draw the complete spring because of the time and cost involved. A shortcut method for drawing a spring is shown in *Figure 14-15.* At top is the conventional method of representing a compression spring; below it is the same spring drawn by the schematic drawing system.



FIGURE 14-15 *Schematic system of representing a compression spring*



FIGURE 14-16 *Incomplete coils with phantom lines.*

Another method of drawing a spring, especially a long spring, is illustrated in *Figure 14-16.* The uncompleted coils are illustrated by phantom lines. If the company does not have a standard method of drawing springs it is the drafter's decision as to which method of representation is used. In most cases, it is best to draw the object, in this case the spring, in such a way that there is no question whatsoever as to exactly what is required. Of course, regardless of which system is used, full dimensions and specification data must be included.

Section View of a Spring

If a cutting-plane line passes through the axis of a spring, the spring is drawn in one of two ways. A small spring is drawn with the back coils showing, as illustrated in *Figure 14-17A,* with the section lining of the coils filled in solid. A larger spring is drawn the same way, but uses standard section lining, *Figure 14-17B.* Notice that both illustrations are right-hand springs, but because the front half has been removed, only the rear half is seen, which appears as left hand.

Isometric Views of a Spring

A template, such as the one shown in *Figure 14-18,* makes it quick and simple to draw isometric views



FIGURE 14-17 *Section view of a spring.*

Industry Application

John Dugan had been the outstanding drafting student at Minot Technical Institute. His work as a student had won him a closet full of awards and much recognition. Consequently, nobody was surprised when Dugan secured a job in the drafting department of Minot Machine Tool Company, an excellent employer.

John Dugan's talent was apparent from the outset, and within weeks he was assigned to a team that took on the company's most difficult projects. His first assignment on the "A" team was to draw the plans for several different extension springs. Springs had been Dugan's specialty at Minot Tech. In the words of his professor, "Dugan can draw springs that look so realistic you can lift them off the page and use them."

Consequently, Dugan was taken aback when his team leader stopped him after he had completed only one of the five spring drawings he was assigned. "What in the world are you doing?" asked the team leader, clearly flabbergasted. Dugan, unsure of what was wrong and shocked by the first negative reaction he had ever had to his work, could only stammer, "What do you mean? I'm drawing the springs you assigned me." "I asked you to draw them, not make them," said the team leader. "We don't do pictorial spring drawings here. This is the drafting department, not the art department. We use schematic representation with all the critical data called out in the notes. It takes time to create pictorial representations of springs, and time is money." "Besides," said the team leader, "there is no need to give the machining department anything but a schematic and some notes. That is all they need to make the springs, and it is our job to give them that much information and nothing more. Every minute you spend creating these beautiful pictorials is time that could have been put to better use on another project." John Dugan had just learned a valuable lesson that eventually every drafter must learn.



This template makes it quick and simple to draw isometric views of all light, medium, or heavyweight open springs. Lightweight springs are slightly smaller than the dimension printed on the template because they are drawn with the two smallest cutouts in any set. The thick lower edge and pinpoint centers insure precise positioning to repeat each loop for any length spring.

FIGURE 14-18 *Isometric spring template.* (Courtesy Timely Products Co.)

of light, medium, or heavyweight open springs. Lightweight springs are slightly smaller than the dimension printed on the template because they are drawn with the two smallest cutouts in any set. The thick lower edge and pinpoint centers ensure precise positioning to repeat each loop for any length spring.

Summary

- Springs can be classified as helical or flat. There are three types of helical springs; compression, extension, and torsion.
- Key terms associated with spring design include the following: free length, solid length, outside diameter, wire size, inside diameter, active coils, loaded length, wear diameter, coil, and direction of winding.
- Required spring data include the following: material, number of coils, direction of winding, torque data, finish, and heat treatment specifications.
- Some companies specify the use of schematic representation of springs as a way to save time and money. Another time-saving method is to draw only those coils that are at each end of the spring and connect them with phantom lines.
- If a cutting-plane line passes through the axis of a spring, the spring may be drawn in one of two ways. A small spring is drawn with the section lines filled in. A larger spring uses standard section lining.

Review Questions

Answer the following questions either true or false.

1. It is incorrect to dimension both the inside diameter and the outside diameter of a spring on the same drawing.
2. The two general classifications of springs are helical and flat.
3. The solid length of a compression spring is the length of the spring stretched out straight.
4. Section lining is illustrated in a large spring where the cutting-plane line passes through the center axis of the spring by filling the coils in solid.
5. The free length of a spring means the overall length of a spring when it is in its free state or unloaded condition.

Answer the following questions by selecting the best answer.

1. If the coil winding direction is not called off on the drawing, it will be manufactured:
   a. Left-hand winding.
   b. Right-hand winding.
   c. The same as other springs in the drawing.
   d. None of the above
2. Which dimension should be given for the diameter of a spring on a drawing?
   a. inside
   b. outside
   c. radial
   d. both a and b
3. Other than the required dimensions, what spring data must be noted below and to the right?
   a. material
   b. number of coils
   c. direction of winding
   d. all of the above
4. Which of the following is **not** a type of helical spring?
   a. compression spring
   b. flat spring
   c. torsion spring
   d. extension spring
5. Which of the following is **not** a common use for a torsion spring?
   a. a doorknob
   b. a clock
   c. a truck
   d. a wind-up toy

Chapter 14 Problems

The following problems are intended to give the beginning drafter practice in drawing various kinds of springs with special required specifications.

Conventional Instructions

The steps to follow in laying out springs are:

STEP 1 Study all required specifications.

STEP 2 Make a rough sketch of the spring, incorporating **all** required specifications and required dimensions.

STEP 3 Calculate the size of the basic shape of the front and end views.

STEP 4 Center the two views within the work area with correct spacing for dimensions between views.

STEP 5 Starting with the end view, or the view that contains the diameter, lightly draw the spring adhering to all specific required specifications. Take care to show correct direction of winding, correct type of ends, and total count of windings.

STEP 6 Check to see that both views are centered within the work area.

STEP 7 Check all dimensions in both views.

STEP 8 Darken in both views, starting first with all diameters and arcs.

STEP 9 Neatly add all dimensioning as required to fully describe the object using the latest drafting standards.

STEP 10 Neatly add all required specifications under the two views. The drawing must include the following: Free length Wire size Total number of coils Type of ends Solid length Outside diameter Inside diameter Direction of windings Material (usually, hard drawn steel, spring wire) Required heat-treating process (usually, heat to relieve coiling stresses) Any other special requirements.

STEP 11 For torsion-type springs, illustrate working location and travel with phantom lines and dimension.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

Problems 14-1 through 14-7

Construct a 2-view drawing of each spring using the listed steps. Center the views on an A-size, 8 ½ × 11" sheet of paper with a 1" (25 mm) space between views. Use correct line thicknesses and all drafting standards. Add all required dimensions and specifications per the latest drafting standards.

PROBLEM 14-1

Compression-type spring Free length 7.00 Wire size .25 12 active coils (14 **total** coils). Plain open ends OD 2.00/ID 1.50 R.H. winding Calculate solid length



PROBLEM 14-2

Compression-type spring Free length 5.25 Wire size .375 4 active coils (6 **total** coils). Ground open ends OD 2.75/ID 2.00 L.H. winding Calculate solid length



PROBLEM 14-3

Compression-type spring Free length 6.25 Wire size .375 9 total coils (7 **active** coils). Plain closed ends OD 2.00/ID 1.25 L.H. winding Calculate solid length



PROBLEM 14-4

(Metric) Compression-type spring Free length 90 Wire size 12 4 total coils (2 **active** coils). Ground closed ends OD 96/ID 72 R.H. winding Calculate solid length



PROBLEM 14-5

Extension-type spring Full loop over center, both ends Approx. free length 7.0 Wire size .25 OD 2.0/ID 1.50 R.H. winding (This is **standard** for all extension springs.)



PROBLEM 14-6

(Metric) Extension-type spring Full loop over center (right end) Long hook over center (left end) Free length 150 Wire size 5 12 total coils 65 coil length OD 42/ID 32 Standard R.H. winding



PROBLEM 14-7

Torsion-type spring Free length 3.625 Wire size .25 13 total coils OD 2.0/ID 1.50 R.H. standard winding 90° maximum working flex (counterclockwise) Arm lengths 2.0 (as shown)



15

Cams

CHAPTER OUTLINE

Cam principle • Basic types of followers • Cam mechanism • Cam terms • Cam motion • Laying out the cam from the displacement diagram • Timing diagram • Dimensioning a cam • Summary • Review questions • Chapter 15 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the cam principle.
- Describe the four basic types of followers.
- Distinguish between the two major kinds of cams used in industry.
- Define the most important cam terms.
- Compare and contrast the four principal types of cam motion.
- Demonstrate proficiency at laying out a cam from a displacement diagram.
- Demonstrate proficiency in drawing various types of cams.
- Demonstrate proficiency in developing timing diagrams.
- Demonstrate proficiency in dimensioning cams.

KEY TERMS

Base circle
Baseline
Cam
Cylindrical
Displacement diagram
Dwell
Harmonic motion
Lowest position
Modified uniform velocity
Parallel
Perpendicular
Radial arm
Rotation
Time interval
Timing diagram
Uniform acceleration
Uniform velocity
Working circle

Cam Principle

A *cam* produces a simple means to obtain irregular or specified predictable, designed motion. These motions would be very difficult to obtain in any other way.

Figure 15-1 illustrates the basic principle and terms of a cam. In this example, a rotating shaft has an irregularly shaped disc attached to it. This disc is the cam. The follower, with a small roller attached to it, pushes against the cam. As the shaft is rotated, the roller follows the irregular surface of the cam, rising or falling according to the profile of the cam. The roller is held tightly against the cam either by gravity or a spring.

Figure 15-2 illustrates a simple cam in action. Notice how the rotation of the shaft converts into an up-and-down motion of the follower. A cam using a flat-faced follower is shown in *Figure 15-3*. This type of cam, for example, is used to raise and lower the valve in an automobile engine. A modified



FIGURE 15-1 *Basic cam principle and terms.*



FIGURE 15-2 *Simple cam in action.*



FIGURE 15-3 *Flat-faced follower.*



FIGURE 15-4 *Rocker arm follower with wheel.*

cam follower is used to change the rotary motion of shaft A into an up-and-down motion of the rocker arm, and then into a rocking motion of shaft B, *Figure 15-4*.

Basic Types of Followers

Speed of rotation and the actual load applied upon the lifter determine the type of follower to be used. There are various basic types of followers: roller, pointed, flat-faced, and spherical-faced, *Figure 15-5*.

Cam Mechanism

Two major kinds of cams are used in industry: radial arm design and cylindrical design. The *radial arm* design changes a rotary motion into either an up-and-down motion or a rocking action as discussed previously. In the *cylindrical* design, a shaft rotates exactly as it does in the radial design, but the action or direction of the follower differs greatly. In the radial arm design, the follower operates *perpendicular* to the camshaft. In the cylindrical design, the follower operates *parallel* to the camshaft. See *Figure 15-6* for



FIGURE 15-5 *Basic types of followers.*



FIGURE 15-6 *Cylindrical cam mechanism.*

a simplified example of a cylindrical design cam. Shaft A has an irregular groove cut into it. As the cam rotates, the follower traces along the groove. The follower is directly attached to a shaft that moves to the left and right. Notice this shaft does **not** rotate; the motion is parallel to the axis of the rotating camshaft.

Cams produce one of three kinds of motion: uniform velocity, harmonic, or uniform acceleration. Each is discussed in full later.

Cam Terms

Working Circle

The *working circle* is considered to be a distance equal to the distance from the center of the camshaft to the highest point on the cam, ***Figure 15-7.***

Displacement Diagram

The *displacement diagram* is a designed layout of the required motion of the cam. It is laid out on a grid, and its length represents one complete revolution of the cam. The length of the displacement diagram is usually drawn equal in length to the circumference of the working circle. This is not absolutely necessary, but it will give an in-scale idea of the cam's profile. The height of the displacement diagram is equal to the radius of a working circle, ***Figure 15-8.*** The bottom line of the displacement diagram is the *baseline.* All dimensions should be measured upward from the baseline. On the cam itself, think of the center of the cam as the baseline.

The length of the displacement diagram is divided into equal lines or grids, each of which represents



FIGURE 15-7 *Cam terms and working circle.*



FIGURE 15-8 *Displacement diagram (basic layout).*



FIGURE 15-9 *Displacement diagram with 30° increments.*

degrees around the cam. These divisions can be 30°, 15°, or even 10°. The finer the divisions, the more accurate is the final cam profile, ***Figure 15-9.***

Dwell

Dwell is the period of time during which the follower does not move. This is shown on the displacement diagram by a straight horizontal line throughout the dwell angle. On the cam, the dwell is drawn by a radius.

Time Interval

The *time interval* is the time it takes the cam to move the follower to the designed height.

Rotation

Rotation of the cam is either clockwise or counterclockwise. The actual cam profile is laid out opposite of the rotation.

Base Circle

The *base circle* is used to lay out an offset follower that is illustrated in detail later. The base circle is a circle with a radius equal to the distance from the center of the shaft to the center of the follower wheel at its *lowest position.* On an offset follower, the base circle replaces the working circle.

Cam Motion

Four major types of curves are usually employed. Special irregular curves other than the four major types can be designed to meet a specific movement, if necessary.

The four types are: uniform velocity, modified uniform velocity, harmonic motion, and uniform



FIGURE 15-10 *Uniform velocity cam.*

acceleration. For comparison, the following four examples use the same working circle, same shaft, and same rise.

Uniform Velocity

In this type of motion, the cam follower moves with a *uniform velocity;* that is, it rises and falls at a constant speed, but the start and stop are very abrupt and rough, ***Figure 15-10.***

Modified Uniform Velocity

Because of the abrupt and rough start and stop of the uniform velocity, it is modified slightly. *Modified uniform velocity* smoothes out the roughness slightly by adding a radius at the ends of the high and low points. This radius is equal to 1/3 the rise or fall, ***Figure 15-11.*** This radius smoothes out the start and stop somewhat and is good for slow speed.

Harmonic Motion

Harmonic motion is very smooth, but the speed is not uniform. Harmonic motion has a smooth start and stop and is good for fast speed.

To lay out a harmonic motion on the displacement diagram, draw a semicircle whose diameter is equal to the designed rise or fall. Divide the semicircle into equal divisions; in this example, 30°. Divide the overall horizontal distance of the rise or fall equally into increments of the same number as the semicircle; in this example, six equal divisions. Projection points on the semicircle are projected horizontally to the corresponding vertical lines. For example, the first point on the semicircle is projected to the first vertical line, the second point on the semicircle is projected to the second vertical line, and so forth. Connect the curve with an irregular curve. This completes the harmonic curve, ***Figure 15-12.***

Uniform Acceleration

Uniform acceleration is the smoothest motion of all cams, and its speed is constant throughout the cam travel. The uniform acceleration curve is actually a parabolic curve; the first half of the curve is exactly the reverse of the second half. This form is best for high speed.

To lay out a uniform acceleration motion on the displacement diagram, divide the designed rise or fall into 18 equal parts. To do this, place the edge of a scale with its "0" on the starting level of the rise or fall, and equally space 18 units of measure on the high or low elevation of the rise or fall, ***Figure 15-13.*** Mark off points 1, 4, 9, 4 (14), and 1 (17), and draw horizontal lines. Note that 14 is actually 4, and 17 is actually 1. Divide the overall horizontal distance of the rise or fall into 12 equal increments. From points 1, 4, 9, 4 (14), and 1 (17), project points to the corresponding vertical lines. For example, the first point is from point 1 on the division line to the first vertical line, and then from point 4 on the division line to the second vertical, and so forth. Connect the curve with an irregular curve. This completes the uniform acceleration curve.



FIGURE 15-11 *Modified uniform velocity cam.*



FIGURE 15-13 *Uniform acceleration cam.*



FIGURE 15-12 *Harmonic motion cam.*



FIGURE 15-14 *Combination of motions.*

Combination of Motions

The illustrations thus far have covered the four major types of cams: uniform velocity, modified uniform velocity, harmonic motion, and uniform acceleration. Any combinations of these can be designed for a particular function or requirement. *Figure 15-14* illustrates a displacement diagram with a 90° fall using a harmonic motion, followed by a 30° dwell. The cam then falls again 90° using a modified uniform velocity followed by a 30° dwell. The cam then rises using uniform acceleration motion followed by another 30° dwell.

Laying Out the Cam from the Displacement Diagram

Regardless of which type of motion is used, the layout process is exactly the same. The working circle is drawn equal to the height of the displacement diagram. The circle of the cam must be divided into the same number of equal divisions as the displacement diagram, *Figure 15-15A*. Label the increments on both the displacement diagram and the working circle of the cam; in this example, harmonic motion is illustrated.

Notice that the even increment on the cam layout is labeled opposite of the rotation of the cam. In this example, rotation is clockwise; therefore, the labeling of the radial lines should be counterclockwise. Transfer each distance from the displacement diagram to the corresponding radial line, *Figure 15-15B*. Using an irregular curve, complete the cam layout.

Offset Follower

The cam follower is usually in line with the same center line as the cam (see Figure 15-1). Occasionally, however, when position or space is a problem, the follower can be designed to be on another center line, or offset as illustrated in *Figure 15-16*. In order to lay out an offset follower, it is necessary to use slightly different steps than those used for a regular cam.



FIGURE 15-15 *(A) Displacement diagram example; (B) heights transferred from displacement diagram.*



FIGURE 15-16 *Associated cam terms.*

How to Draw a Cam with an Offset Follower

GIVEN: Cam data: harmonic motion cam, follower offset .625, base circle .88 radius, rise of 1.50, shaft diameter .375, direction of rotation counterclockwise.

Follower data: Follower width .250, roller .375 diameter.

STEP 1 Design and lay out a displacement diagram exactly as with any cam, *Figure 15-17A.*

STEP 2 From the center of the shaft of the cam, construct the offset circle. The offset circle has a radius equal to the required follower offset. From the same swing point, lay out the base circle. The radius of the base circle is equal to the distance from the center of the shaft to the center of the follower wheel at its **lowest** position, *Figure 15-17B.*

STEP 3 The point where it crosses a constructed vertical line from the center line of the follower is point A on the displacement diagram, *Figure 15-17C.* This represents the lowest position of the follower wheel. This vertical line is the measuring line and will be used to lay out the other points around the cam.

STEP 4 Divide the offset circle into the same equal divisions as used on the displacement diagram; in this example, 12 equal parts. Lightly and consecutively, letter or number the divisions on the offset circle. Start at the lowest point of the cam; in this example, point A. Letter or number in a direction opposite to that of the cam rotation. Note that point A is the exact location where the center line of the follower is tangent with the offset circle. Construct a layout projection line 90° from the tangent point of the circle, *Figure 15-17D.*

STEP 5 Transfer the distances from the displacement diagram to the measuring line, and lightly letter or number each point. With the compass point on the center of the shaft of the cam, swing these distances to the corresponding radial lines (refer back to Figure 15-17D). Lightly letter or number each point. Do not forget to *lay out the cam opposite to the direction of rotation.* These points represent the path of the center of the follower wheel. Lightly connect these points together, *Figure 15-17E.*



FIGURE 15-17 *(A) Step 1 (drawing a cam with an offset follower design layout); (B) Step 2; (C) Step 3.*

STEP 6 With the compass set at the radius for the roller, lightly draw the roller around the path of the follower. The inside, high points of these arcs represent the actual profile of the cam, *Figure 15-17F.*

STEP 7 Check all construction work. If correct, darken and complete the cam, *Figure 15-17G.*

How to Draw a Cam with a Flat-Faced Follower

GIVEN: Cam data: harmonic motion cam, base circle .75 radius, rise of 1.50, shaft diameter .375, direction of rotation clockwise.

Follower data: flat-faced follower, 1.25 diameter distance across the flat surface.



(D)



(E)



(F)



(G)

FIGURE 15-17 *(Continued) (D) Step 4; (E) Step 5; (F) Step 6; (G) Step 7.*

Design and lay out a displacement diagram exactly as with any cam. In this example, the displacement diagram in Figure 15-17A will be used.

STEP 1 Construct the base circle. The base circle is drawn with a radius equal to the distance from the center of the shaft to the face of the follower in its lowest position. Divide the base circle into the same equal divisions as used on the displacement diagram. Lightly and consecutively letter or number the divisions on the base circle, *Figure 15-18A.*

STEP 2 Locate point A, which represents the location of the flat-faced follower at its lowest point. Construct a measuring line starting from the base circle and transfer the distances from the displacement diagram to the measuring line. Letter or number each point, *Figure 15-18B.* Do not forget to lay out the cam *opposite to the direction of rotation.*

STEP 3 Swing these distances to the corresponding radial lines, *Figure 15-18C.*

STEP 4 From these distances, construct lines perpendicular from these radial lines at the point of intersection, *Figure 15-18D.*



(A)



(B)

FIGURE 15-18 *(A) Step 1 (drawing a cam with a flat-faced follower); (B) Step 2.*



(C)



(D)



(E)



(F)

FIGURE 15-18 *(Continued) (C) Step 3; (D) Step 4; (E) Step 5; (F) Step 6.*

STEP 5 Lightly construct the cam within these perpendicular lines, ***Figure 15-18E.***

STEP 6 Check all construction work. If correct, darken and complete the cam, ***Figure 15-18F.*** Notice the position of the flat-faced follower at the 0°, 90°, and 150° positions.

Timing Diagram

Many times, more than one cam is attached to the same shaft. In this case, each cam works independently but must function in relation to the other cams. In order to be able to visualize graphically and study the interaction of the cams on the same shaft, place the various displacement diagrams in a column with the starting points and ending points in line, as illustrated in ***Figure 15-19.*** This represents one full revolution and is referred to as a *timing diagram.* For example, at 240° it is easy to visualize the exact position of each cam roller.

Dimensioning a Cam

A cam must be fully dimensioned. The cam size dimensions are constructed radiating from the center of the shaft by both radii length and degrees from the starting point, as illustrated in ***Figure 15-20.*** Other important dimensions pertain to the shaft hole size and keyway size, and are dimensioned according to most recent drafting standards.

Try not to place dimensions on the cam itself; place them around the perimeter, if possible.



FIGURE 15-19 *Timing diagram.*

Industry Application

"This new job has several cams in it," said Marge McCrory. "Does anybody know how to draw cams?" When she got nothing but blank stares from the members of her drafting team, McCrory said, "All right then, we'll just have to learn." She distributed copies of several different diagrams among team members.

"This is what we start with. These are displacement diagrams. Don't ask me how just yet, but we use these to lay out the cams. There is one displacement diagram for each cam." Then McCrory told her team members to go to the company's Engineering Library and start researching cams. "I want to know what all of these terms on the diagrams mean, how we get a cam layout from a diagram, and how to completely detail a cam including dimensions," said McCrory.

When the team gathered in the Engineering Department conference room the next day, McCrory could tell immediately that their research had been successful. Her team looked confident and anxious to get started. "Who wants to demonstrate how to lay out a cam from one of these displacement diagrams?" When several hands went up simultaneously, McCrory called on Doug Fulton, the team's senior drafter.

Fulton went to the marker board and quickly sketched his displacement diagram. Then, under it, he sketched the layout for the corresponding cam. He began the cam layout by drawing a circle, which he labeled "working circle." The radius of the circle was equal to the height of the displacement diagram. He divided the circle into 30° segments to match the 30° increments on the displacement diagram. He then transferred each displacement distance from the diagram onto the radial lines of the working circle, beginning at the center of the circle and working outward along each respective radial line.

Within just a few minutes Fulton had laid out his cam. McCrory then asked another team member to use Fulton's diagram to illustrate cam terminology. Another team member put a transparency on an overhead projector to illustrate dimensioning techniques. McCrory was pleased with her team's work and told them so.

This case study from the workplace illustrates an important point. Students seldom graduate knowing everything they will need to know on the job. Even if they did, what must be known today will change tomorrow. Like Marge McCrory's team members, the modern drafting technician must be able to learn on the job.



FIGURE 15-20 *Dimensioning a cam.*

Summary

- A cam produces a simple means to obtain irregular or specified predictable, designed motion.
- Cam followers are of four types: roller, pointed, flat-face, and spherical-face.
- The two main types of cams are radial arm design and cylindrical design. Important cam-related terms are *working circle, displacement diagram, time interval, rotation,* and *base circle.*
- The four main types of cam motion are uniform velocity, modified uniform velocity, harmonic velocity, and uniform acceleration.
- By placing the displacement diagrams for different cams that are attached to the same shaft in a column, we can produce a timing diagram. A timing diagram allows you to visualize graphically the interaction of the cams.

Review Questions

Answer the following questions either true or false.

1. Speed of rotation and the actual load applied on the lifter determine the type of follower to be used.
2. The two major kinds of cams used in industry are radial arm and parallel.
3. A working circle is considered a distance equal to the distance from the center of the camshaft to the highest point on the cam.
4. A displacement diagram is a designed layout of the required motion of the cam.
5. Dwell is the period of time during which the follower moves.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** a type of motion produced by a cam?
   a. harmonic
   b. uniform acceleration
   c. uniform velocity
   d. harmonic displacement
2. Which of the following is **not** true regarding the design and layout of the cam displacement diagram?
   a. The bottom line of the displacement diagram is the baseline.
   b. All dimensions should be measured upward from the baseline.
   c. The length of the displacement diagram is usually drawn equal in length to the circumference of the working circle.
   d. A displacement diagram is a designed layout that measures the applied load.
3. Which of the following is **not** true regarding a timing diagram?
   a. It is used when more than one cam is attached to the same shaft.
   b. Each cam works independently.
   c. Each cam works dependently.
   d. Each cam must function in relation to the other cams.
4. Which of the following is **not** true regarding cam motion?
   a. With uniform velocity, there is a very rough stop and start.
   b. Harmonic motion is very smooth, but the speed is not uniform.
   c. Harmonic motion is very smooth, and the speed is uniform.
   d. Uniform acceleration is the smoothest motion.
5. Which of the following is **not** true regarding the length of the displacement diagram?
   a. The length of the displacement diagram represents one complete revolution of the cam.
   b. The length of the displacement diagram is usually drawn equal in length to the circumference of the working circle.
   c. The height of the displacement diagram is equal to the radius of the working circle.
   d. The height of the displacement diagram is equal to the circumference of the working circle.

Chapter 15 Problems

The following problems are intended to give the beginning drafter practice in designing and layout of cam displacement diagrams according to the required specifications to do a particular function. The cam displacement diagram will then be transferred to an actual cam profile layout. The drafter will practice laying out uniform velocity, harmonic motion, and uniform acceleration motions.

Conventional Instructions

The steps to follow in laying out cams are:

STEP 1 Study all required specifications.

STEP 2 Make a rough sketch of the cam displacement diagram, incorporating **all** required specifications and required dimensions.

STEP 3 Lightly lay out the displacement diagram. Space out horizontally as far as possible.

STEP 4 Break down the area into equal spaces that correspond to degrees around the cam. Label each line, indicating the degrees.

STEP 5 Following the required specifications, lightly develop the cam's travel on the displacement diagram. (Show all light layout work—do not erase.)

STEP 6 Check all work.

STEP 7 Darken in the displacement diagram.

STEP 8 To lay out the cam profile, locate the center of the cam.

STEP 9 Draw the shaft, hub, working circle, and key, if required, in place.

STEP 10 Divide the working circle into equal degrees as required.

STEP 11 Note direction of travel. Lightly letter the degrees around the working circle opposite of the direction of travel.

STEP 12 Locate the starting elevation and draw the cam follower from the starting point.

STEP 13 Lightly draw in the rest of the cam, following details as required.

STEP 14 Transfer all distances from the cam displacement diagram to the corresponding degree line around the cam layout.

STEP 15 Lightly connect all points using an irregular curve.

STEP 16 Check all work.

STEP 17 Darken in all work.

STEP 18 Neatly add all required specifications and dimensions to the drawing.

The drawing must include the following:
Shaft diameter
Hub size
Key or set screw size
Direction of rotation
Working circle size
All dimensions according to the most recent drafting standards. (For these problems, dimension only the front view.)

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

PROBLEMS 15-1A AND 15-1B

Construct a cam displacement diagram on an A-size, 8 ½ × 11″ sheet of paper per the dimensions given. Lay out a cam with the following specifications:

1. Working circle 5.0 dia.
2. Shaft dia. .75 counterclockwise
3. Hub dia. 1.25
4. Square key .18
5. Rotation:
6. Follower dia. 1.0
7. Start 1.0 from center

Required motion:

1. Rise 90°, modified uniform velocity 1.5
2. Dwell 60°
3. Fall 60°, modified uniform velocity .75
4. Dwell 30°
5. Fall 60°, modified uniform velocity .75
6. Dwell 60°

Construct the cam and follower on an A-size, 8½ × 11″ sheet of paper per the dimensions given, and transfer all dimensions from the displacement diagram to the cam layout.

Check all work and add all required dimensions and specifications according to the most recent drafting standards.

PROBLEM 15-1A



PROBLEM 15-1B



PROBLEMS 15-2A AND 15-2B

Construct a cam displacement diagram on an A-size, 8 ½ × 11″ sheet of paper per the dimensions given. Lay out a cam with the following specifications:

1. Working circle 5.0 dia.
2. Shaft dia. .75 clockwise
3. Hub dia. 1.25
4. Square key .18
5. Rotation:
6. Follower dia. 1.0
7. Start 1.0 from center

Required motion:

1. Rise 90°, harmonic motion 1.00
2. Dwell 30°
3. Rise 90°, harmonic motion .50
4. Dwell 30°
5. Fall 90°, harmonic motion 1.50
6. Dwell 30°

Construct the cam and follower on an A-size, 8½ × 11″ sheet of paper per the dimensions given, and transfer all dimensions from the displacement diagram to the cam layout.

Check all work and add all required dimensions and specifications according to the most recent drafting standards.

PROBLEM 15-2A



PROBLEM 15-2B



PROBLEMS 15-3A AND 15-3B

Construct a cam displacement diagram on an A-size, 8½ × 11″ sheet of paper per the dimensions given.

Lay out a cam with the following specifications:

1. Working circle 5.0
2. Shaft dia. .63
3. Hub dia. 1.0
4. Square key to suit
5. Rotation: clockwise
6. Follower dia. .75
7. Start 2.5 from center

Required motion:

1. Fall 180°, uniform acceleration 1.50
2. Dwell 45°
3. Rise 90°, uniform acceleration 1.50
4. Dwell 45°

Construct the cam and follower on an A-size, 8½ × 11″ sheet of paper per the dimensions given, and transfer all dimensions from the displacement diagram to the cam layout.

Check all work and add all required dimensions and specifications according to the most recent drafting standards.

PROBLEM 15-3A



PROBLEM 15-3B



PROBLEMS 15-4A AND 15-4B

Construct a cam displacement diagram on an A-size, 8½ × 11″ sheet of paper per the dimensions given. Lay out a cam with the following specifications (metric):

1. Working circle 245
2. Shaft dia. 28
3. Hub dia. 44
4. Square key to suit
5. Rotation: clockwise
6. Follower dia. 22
7. Start 32 from center

Required motion:

1. Rise 60°, harmonic motion 25
2. Dwell 15°
3. Rise 90°, harmonic motion 38
4. Dwell 15°
5. Fall 45°, harmonic motion 44
6. Dwell 15°
7. Rise 30°, harmonic motion 18
8. Dwell 15°
9. Fall to starting level 75°, harmonic motion 38

Construct the cam and follower on an A-size, 8½ × 11″ sheet of paper per the dimensions given, and transfer all dimensions from the displacement diagram to the cam layout.

Check all work and add all required dimensions and specifications according to the most recent drafting standards.

PROBLEM 15-4A



PROBLEM 15-4B



PROBLEMS 15-5A AND 15-5B

Construct a cam displacement diagram on an A-size, 8 ½ × 11″ sheet of paper per the dimensions given.

Lay out a cam with the following specifications:

1. Working circle 7.0
2. Shaft dia. .625
3. Hub dia. 1.0
4. Square key to suit
5. Rotation: counterclockwise
6. Follower dia. 1.0
7. Start 1.0 from center

Required motion:

1. Rise 120°, modified uniform velocity 2.5
2. Dwell 60°
3. Fall 30°, modified uniform velocity .75
4. Dwell 30°
5. Fall to starting level 90°, modified uniform velocity 1.75
6. Dwell 30°

Construct the cam and follower on an A-size, 8 ½ × 11″ sheet of paper per the dimensions given, and transfer all dimensions from the displacement diagram to the cam layout.

Check all work and add all required dimensions and specifications according to the most recent drafting standards.

PROBLEM 15-5A



PROBLEM 15-5B



PROBLEMS 15-6A AND 15-6B

Construct a cam displacement diagram on an A-size, 8 ½ × 11″ sheet of paper per the dimensions given.

Lay out a cam with the following specifications:

1. Working circle 7.75
2. Shaft dia. .56
3. Hub dia. .88
4. Square key to suit
5. Rotation: clockwise
6. Follower dia. .375
7. Start 1.625 from center

Required motion:

1. Fall 90°, uniform acceleration 3.0
2. Dwell 15°
3. Rise 60°, uniform acceleration 2.0
4. Dwell 105°
5. Rise 90°, uniform acceleration to starting level (1.0)

Construct the cam and follower on an A-size, 8 ½ × 11″ sheet of paper per the dimensions given, and transfer all dimensions from the displacement diagram to the cam layout.

Check all work and add all required dimensions and specifications according to the most recent drafting standards.

PROBLEM 15-6A



PROBLEM 15-6B



PROBLEMS 15-7A AND 15-7B

Construct a metric cam displacement diagram per the dimensions given.

Lay out a cam with the following specifications:

1. Rise/fall 56
2. Shaft dia. 16
3. Hub dia. 32
4. Square key to suit
5. Rotation: clockwise
6. Follower: flat-faced* (34 dia.)
7. Base circle 26 radius
8. Harmonic motion/one full turn

Construct the cam and flat-faced follower per the dimensions given.

Check all work and add required dimensions and specifications according to the most recent drafting standards and using the metric system.

*Design the flat-faced follower to suit.

PROBLEM 15-7A



PROBLEM 15-7B



PROBLEMS 15-8A AND 15-8B

Construct a cam displacement diagram per the dimensions given.

Lay out an offset cam with the following specifications:

1. Offset circle dia. 2.00
2. Shaft dia. .75
3. Hub dia. 1.25
4. Square key to suit
5. Rotation: clockwise
6. Follower dia. .75
7. Follower offset 1.00
8. Base circle 1.375 radius

Required motion:

1. Rise 75°, uniform acceleration 1.00
2. Dwell 10°
3. Rise 35°, harmonic motion .75
4. Dwell 5°
5. Fall 70°, modified uniform velocity 1.25
6. Dwell 15°
7. Rise 45°, harmonic motion .75
8. Dwell 15°
9. Fall 60°, uniform acceleration 1.26
10. Dwell 30° Construct the cam and offset follower per the dimensions given, and transfer all dimensions from the displacement diagram to the cam layout.

Check all work and add all required dimensions and specifications according to the most recent drafting standards.

PROBLEM 15-8A



PROBLEM 15-8B



16

Gears

CHAPTER OUTLINE

Kinds of gears • Gear ratio • The involute curve • Pitch diameter and basic terminology • Pitch diameter (D) • Diametral pitch (P) • Gear blank • Pressure angle, base circle, and center-to-center distance • Rack • Gear train • Required tooth-cutting data • Measurements required to use a gear tooth caliper • Bevel gear • Worm and worm gear • Materials • Design and layout of gears • Summary • Review questions • Chapter 16 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Identify different kinds of gears.
- Comment briefly on flexible drives such as chain- and belt.
- Discuss terms related to the profiles and kinematics of gears.
- Determine the gear ratio between two gears.
- Calculate train values of gear trains.
- Construct an involute curve on a base circle.
- Calculate the center distance between two gears in contact.
- Prepare working drawings of gears.

KEY TERMS

Addendum
Angle gear
Base circle
Bevel gear
Center-to-center distance
Chain and sprockets
Chordal addendum
Chordal thickness
Circular pitch
Clearance
Dedendum
Diametral pitch
Gear tooth caliper
Gear train
Helical gear
Herringbone gear
Involute curve
Miter gear
Outside diameter
Pinion gear
Pitch diameter
Rack gear
Ring gear
Root diameter
Spiral bevel gear
Spur gear
Train value
Whole depth
Working depth
Worm
Worm gear

Spur gears are the chief focus of this chapter; however, we plan to introduce you to various kinds of gears, gear nomenclature, technical drawing requirements for gears, the kinematics (study of motion without considering the forces) of gear trains, and related topics such as belt and chain drives. Brief consideration of forces on spur gear teeth is mentioned with respect to the pressure line between gears. Further inclusion of force topics appear in the problems at the end of the chapter.

Gear analysis and design is complex and beyond the scope of this text. For example, gear designers utilize equations that calculate stresses induced in gear teeth due to the forces transmitted and adverse operating conditions. Even more detailed analysis is required whenever wear on gear tooth surfaces is the determining design criterion.

Gears transfer rotary motion from one shaft to another shaft. Gears can change direction of rotation, speed up or slow down rotation, transmit rotational power (torque), and change rotary motion to straight-line motion. There are various kinds of gears, each with their own function, ***Figure 16-1.***



FIGURE 16-1 *Exploded assembly of gears in use.* (Courtesy The Maytag Company)

Drafters must be able to identify each kind of gear, know the various functions of each, and be able to prepare working drawings of the various gears using correct terminology.

Kinds of Gears

Gears are usually classified by the position or location of the shafts they connect. A spur gear, pinion gear, or helical gear is usually used to connect shafts that are parallel to each other. Intersecting shafts at 90° are usually connected by a beveled gear or angle gear. Shafts that are not parallel to each other and that do not intersect use a worm and worm gear. In order to connect rotary motion into a reciprocating or back-and-forth motion, a rack gear and pinion would be used. (Note that the rack gear and pinion are also known as a rack and pinion gear).

Spur Gear

The *spur gear* is the most commonly used gear, ***Figure 16-2.*** It is cylindrical in form, with teeth that are cut straight across the face of the gear. All teeth are parallel to the axis of the shaft. The spur gear is usually considered the driven gear.

Pinion Gear

The *pinion gear* is exactly like a spur gear but it is usually smaller and has fewer teeth, Figure 16-2. The pinion gear is normally considered the drive gear.

Rack Gear

The *rack gear* is a type of spur gear, but its teeth are in a straight line or flat instead of in a cylindrical form, ***Figure 16-3.*** The rack gear is used to transfer circular motion into straight-line motion.



FIGURE 16-2 *Spur gear (left), pinion gear (right.)* (Courtesy Boston Gear)



FIGURE 16-3 *Rack gear.* (Courtesy Boston Gear)

FIGURE 16-4 *Ring gear.* (Courtesy Boston Gear)

Ring Gear

The *ring gear* is similar to the spur, pinion, and rack gears, except that the teeth are internal, ***Figure 16-4.***

Bevel Gear

A bevel gear is another gear commonly used, ***Figure 16-5.*** A *bevel gear* is cone shaped in form with straight teeth that are on an angle to the axis of the shaft. Bevel gears are used to transmit power and motion between intersecting shafts that are at 90° to each other.

Angle Gear

The *angle gear* is similar to a bevel gear, except that the angles are at other than 90° to each other.

Miter Gear

The *miter gear* is exactly the same as a bevel gear, except that both mating gears have the same number of teeth. The shafts are at 90° to each other, ***Figure 16-6.***



FIGURE 16-5 *Bevel gear.* (Courtesy Boston Gear)

FIGURE 16-6 *Miter gear.* (Courtesy Boston Gear)

FIGURE 16-7 *Spiral bevel gear.* (Courtesy Boston Gear)

Spiral Bevel Ormiter Gears

Any bevel gears with curved teeth are called *spiral bevel gears,* ***Figure 16-7.***

Worm Gear

Worm gears are used to transmit power and motion at a 90° angle between nonintersecting shafts, ***Figure 16-8.*** They are normally used to reduce speed. The worm gear is round like a wheel. The *worm* is shaped like a

FIGURE 16-8 *Worm and worm gear.* (Courtesy Boston Gear)

screw, with threads (or teeth) wound around it. Because one full turn of the worm is required to advance the worm gear one tooth, a high-ratio speed reduction is achieved. The worm drives the larger worm gear.

Helical Gears

Helical gears operate on parallel shafts and transmit rotary motion in a manner identical to spur gears. The teeth have an involute shape but are not parallel to their rotational axis, ***Figure 16-9.*** Helical gear sets can transmit heavy loads at high speeds due to gradual engagement of the teeth and the smooth transfer of load from one tooth to another.

Herringbone Gears

Since helical gear teeth are cut at an angle to the axis of the gear, a force is generated along the axis. To compensate for this force, left-hand and right-hand teeth are combined, ***Figure 16-10.*** Large ships, for example, use *herringbone gears* in the drive train between the turbine and the propeller.

Chain and Sprockets

A *chain and sprockets* are used to transmit motion and power to shafts that are parallel to each other,



FIGURE 16-9 *Helical gears.*



FIGURE 16-10 *Herringbone gears.*



FIGURE 16-11 *Chain and sprockets.* (Courtesy Boston Gear)

Figure 16-11. Sprockets are similar to spur and pinion gears, for the teeth are cut straight across the face of the sprocket and are parallel to the shaft. There are many types of chains and sprockets but all use the same terms, formulas, ratios, and so forth.

Belt Drives

Belt drives, like the belts used on a typical automobile engine, are similar to chain-and-sprocket drives; however, slippage can occur between belts and pulleys. Belt drives are employed to start large masses such as ventilating fans so some slippage can occur if needed.

Gear Ratio

Friction wheels can be used to illustrate the basic kinetic relationship between a driver gear and a driven gear, ***Figure 16-12.*** Wheel A is on a shaft parallel to the shaft of wheel B and it drives wheel B through friction at the point of contact. If wheel A rotates clockwise, then wheel B will rotate counterclockwise. Furthermore, if the circumference of wheel B is two times the circumference of wheel A, wheel A must make two complete revolutions to cause wheel B to make one (assuming no slippage).



FIGURE 16-12 *Relationship of two wheels of different diameters.*

The train value (TV) of this drivetrain is calculated by the equation:

$$TV = \frac{\text{driver circumference}}{\text{driven circumference}} = 0.5$$

For example, if the rotational speed of A is 30 RPM (revolutions per minute) then the rotational speed of B is calculated as follows:

$$B(RPM) = TV \times A(RPM) = 0.5 \times 30 = 15 \text{ RPM}$$

Assume that the drivetrain now is made up of gear A (20 teeth) rotating at 30 RPM and driving gear B (40 teeth). The train value (TV) is calculated by:

$$TV = \frac{\text{Number of Teeth on Driver}}{\text{Number of Teeth on Driven}} = \frac{20}{40} = 0.5$$

Then the rotational speed of gear B = 0.5 × 30 = 15 RPM.

The Involute Curve

Spur gears use the involute curve as the profile of their gear teeth because of the involute's unique property of being able to transfer motion and forces in a uniform manner.

How to Construct an Involute Curve on a Base Circle

An *involute curve* may be considered to be the path traced by the end of a string as it is unwound from a circle called a *base circle.*

EXAMPLE:

GIVEN: Portion of a base circle m-n, which has a convenient radius of 3.2″ to fit on your paper, *Figure 16-13.*

STEP 1 Locate a point 6 to anchor a 3″ long theoretical string. Call the string 6-0 and label it 6, 5, 4, 3, 2, 1, and 0 at 0.5″ intervals, *Figure 16-13A.*

STEP 2 Beginning at point 1, construct a tangent to the 3.2″ curve (a base circle for the involute curve), lay out the distance 1-0 (0.5″) along the tangent from the point of tangency 1, and label it 1-0(1), *Figure 16-13B.*

STEP 3 At point 2, construct a tangent to the base circle and lay out a distance from the point of tangency 2 equal to two times the distance 1-0. Label it 2-0(2), *Figure 16-13C.*



FIGURE 16-13 *How to construct an involute curve on a base circle; (A) Step 1; (B) Step 2; (C) Step 3.*



(D)



(E)

FIGURE 16-13 *(Continued) (D) Step 4; (E) Step 5.*

STEP 4 From points 3, 4, 5, and 6 lay off in a similar manner distances along the tangents and label them 3-0(3), 4-0(4), 5-0(5), and 6-0(6), respectively, *Figure 16-13D.*

STEP 5 Finally connect the points 0(1)-0(6) with a French curve to produce the involute curve, *Figure 16-13E.*

Pitch Diameter and Basic Terminology

The drafter must know and understand all major terms associated with various kinds of gears used today in industry. Illustrated in *Figure 16-14* are the basic terms associated with most gears, regardless of type.



FIGURE 16-14 *Basic gear terminology.*

Pitch Diameter (D)

The *pitch diameters* (D) of two spur gears exist theoretically only when the two gears are in contact. When the point of contact between a tooth on gear A and a tooth on gear B falls on the line of centers between the two gears, then that point determines the radii of imaginary pitch circles of gear A and gear B, respectively, *Figure 16-15.*

Figure 16-16 illustrates additional terms that will help you to prepare working drawings of spur gears. Circular pitch (p) and the terms are explained in the paragraphs that follow.

Circular Pitch (P)

Circular pitch (p) is the distance between corresponding points of adjacent teeth measured on the circumference of the pitch diameter, Figure 16-16.

Diametral Pitch (P)

Diametral pitch (P) is a ratio equal to the number of teeth (N) per inch of pitch diameter (D). Follow the derivation that follows to better understand the term.

$(p) \times (N) =$ the circumference of the pitch circle

$(D) \times \pi =$ the circumference of the pitch circle

$$\text{so } (p) \times (N) = (D) \times \pi$$

$$\text{and } (p) \times \frac{(N)}{(D)} = \pi$$

$$\text{then } (p) \times (P) = \pi$$



FIGURE 16-15 *Pitch circles determined from point of contact on line of centers.*



FIGURE 16-16 *Major gear terms.*

EXAMPLE:

A gear with 48 teeth on a 3.0″ pitch diameter (D), would have a diametral pitch (P) of 16.

NOTE: All pairs of spur gears must have the same diametral pitch (P)!

Working Depth (HK)

The *working depth* is the distance that a tooth projects into the mating space. It is equal to gear addendum (a) plus pinion addendum (a).

Addendum (A)

The *addendum* is the radial distance from the pitch diameter to the top of the tooth. It is equal to 1/P.

Dedendum (B)

The *dedendum* is the radial distance from the pitch diameter to the bottom of the tooth. It is equal to 1.157/P, 1.250/P, or 1.350/P; 1.250/P is preferred for 20° teeth.

Clearance (C)

Clearance is the space between the working depth and the whole depth. It is equal to dedendum (b) minus addendum (a).

Whole Depth (HT)

The *whole depth* is the total depth of a tooth space. It is equal to the addendum (a), plus the dedendum (b), plus the clearance (c).

NOTE: All notations in parentheses ( ) correspond to those used in the most recent edition of Machinery's Handbook *so that they agree if a more detailed formula is required by the drafter.*

Outside Diameter (OD)

The *outside diameter* is the measurement over the extreme outer edge of teeth. It is equal to the pitch diameter, plus 2 times the addendum (a).

Root Diameter (DR)

The *root diameter* is the measurement over the extreme inner edges of teeth. It is equal to the pitch diameter minus 2 times the dedendum (b).

How to Draw a Spur Gear Tooth

Draw a spur gear tooth for the experience and for learning spur gear nomenclature. Later you will discover that working drawings of gears and gear sets seldom require drawing the tooth profile.

GIVEN: Spur gear specifications of D = 6.0″, P = 4, T = 24, and ϕ = pressure angle of 20°.

STEP 1 Construct an arc representing the basic circle, *Figure 16-17A*. The base circle radius = D cos ϕ/2 = 6.0 × cos 20°/2 = 2.819″.

STEP 2 At an arbitrary point B on the base circle, draw an involute curve one of several ways. Your choices are the basic method shown in Figure 16-13, the approximate method (D/8 = approximate involute curve), or the simplest method using a template, *Figure 16-18*. A fourth choice would be to use a CAD program. For this example use the approximate method, *Figure 16-17B*. Then D/8 = 6.0″/8 = 0.75″.

STEP 3 Draw an arc representing the pitch circle, D/2 = 6.0″/2 = 3.0″ and label point T where the pitch circle intersects the approximate involute curve, *Figure 16-17C*.



FIGURE 16-17 *How to draw a spur gear tooth; (A) Step 1.*





FIGURE 16-17 *(Continued) (B) Step 2; (C) Step 3.*

STEP 4 Locate the tooth width along the pitch circle, *Figure 16-17D*, and label the width T-S. The width T-S equals half the circular pitch p. The circular pitch p = π/P = π/4 = 0.785″. The tooth width then is 0.785″/2 = 0.392″. Construct an approximate involute curve from the base circle and going through point S.

STEP 5 Finish the tooth profile by constructing the addendum and dedendum circles plus two radial lines, *Figure 16-17E*. Add the addendum 1/P = 1/4 = 0.25″ to the pitch circle



(D)



(E)

FIGURE 16-17 *(Continued) (D) Step 4; (E) Step 5.*

arc, and subtract the dedendum 1.250/P = 0.312″ from the pitch circle arc. Finally, from where the base circle intersects the tooth profile, draw radial segments from the base circle to the dedendum arc. To provide a small amount of clearance, Figure 16-16, add small fillets.

Gear Template

A quick and efficient method of illustrating teeth is by using a gear template, *Figure 16-18* (shown at approximately half size). When using a gear template,



FIGURE 16-18 *Gear template—spur/rack/worm* (Courtesy Modern School Supply)

SPUR GEAR TEETH Comparison

	Inch 20° 24T P = 4	Metric 20° 24T P = 4
Pitch Diameter	6.0"	152.4 mm
Circular Pitch	π/P = 0.785"	19.95 mm
Base Circle Diameter	D cos 20° = 5.638"	143.2 mm
Module(MDL) = (length of pitch diameter per tooth)		pitch dia/24 = 152.4/24 = 6.35 mm
Addendum	1/P = 0.25"	MDL = 6.35 mm
Dedendum	1.157/P = 0.289" or 1.250/P = 0.312	1.157 x MDL = 7.35 mm 1.25 x MDL = 7.94 mm

FIGURE 16-19 *Comparison of metric and inch spur gears.*

the drafter must first calculate the diametral pitch (P). The numbers next to each tooth indicate the diametral pitch. The lower part of the template opening is used to draw spur gear teeth. The top portion of the opening is used to draw teeth of a rack or worm.

Metric Spur Gears

Metric spur gears and inch spur gears are essentially identical. For a comparison of an inch gear with a metric one, a gear with a 20° pressure angle, 24 teeth, and a diametral pitch of P = 4 is shown in *Figure 16-19.*

Gear Blank

Gears are usually cut from a gear blank. The gear blank must allow sufficient space for the gears and a method to attach the gear to the shaft. Illustrated in *Figure 16-20* is a common gear blank with an outside diameter and face width for the gears to be cut into, a hub, and a hole for the set screw to secure the gear blank to the shaft. A half-section is used to illustrate the gear blank in this example. Two complete sets of dimensions must be applied to the gear drawing; those relating to the gear blank, as illustrated, and



FIGURE 16-20 *Gear blank.*

those relating to the teeth. Gear dimensions do not hold tight tolerancing, but all gear tooth dimensions must hold very tight tolerancing.

Pressure Angle, Base Circle, and Center-to-Center Distance

The pressure angle determines the diameters of the base circles, which in turn determine the tooth forms. To illustrate this principle, the steps to prepare a drawing of two spur teeth in contact will be discussed.

How to Draw Two Spur Gear Teeth in Contact

GIVEN: A 20-tooth pinion gear to drive a 40-tooth gear, P = 5. The pressure angle ϕ is to be 20°.

STEP 1 Start the drawing by laying out the center-to-center distance, *Figure 16-21A*. The *center-to-center distance* equals the sum of the radius of the pinion plus the radius of the gear.

D (pinion) = N/P = 20/5 = 4″

R (pinion) = 4/2 = 2″

D (gear) = N/P = 40/5 = 8″

R (gear) = 8/2 = 4″

C-to-C = 2 + 4 = 6″

Label the juncture of the two radii, T. Construct a perpendicular to the line between centers at point T.



FIGURE 16-21 *How to draw two spur gear teeth in contact; (A) Step 1; (B) Step 2.*

STEP 2 Lay out the pressure line at 20° to the perpendicular at T assuming that the pinion is rotating clockwise and driving the gear, ***Figure 16-21B.*** Next construct perpendiculars from the pinion and gear centers to the pressure line.

STEP 3 Use the perpendiculars that represent the radii of the respective base circles to draw the base circles, ***Figure 16-21C.***

NOTE: The lengths of the radii of the base circles equal the radii of the pitch circles times cos 20°.

STEP 4 To save time, use the approximate method (D/8, Figure 16-17) to draw the tooth profiles from each base circle, the profiles to go through point T, ***Figure 16-21D.*** Finish the two teeth and note that the base of the tooth on the gear is wider than the base on the pinion.

STEP 5 Assume that the pinion rotates approximately one tooth width clockwise (p/2) and construct a new pinion tooth, ***Figure 16-21E.*** Draw a gear tooth in contact and observe that the two teeth are in contact on the pressure line. The true involute profile ensures that the teeth will always be in contact along the pressure line—hence the smooth transfer of rotation and power.



FIGURE 16-21 *(Continued) (C) Step 3; (D) Step 4.*



FIGURE 16-21 *(Continued) (E) Step 5.*

Rack

A rack is simply a gear with teeth formed on a flat surface, *Figure 16-22.* A rack changes rotary motion into reciprocating motion. All terms and formulas associated with spur and pinion gears apply to the rack. The sides of the teeth are straight, not involute as on a spur gear. The teeth are inclined at the same angle as the pressure angle of the mating pinion gear. Note that the circular pitch of the pinion gear is the same as the linear pitch of the rack. All dimensions for heights of depth, pitch, and addendum lines are calculated from a datum or reference line. The rack is usually manufactured out of rectangular stock but, occasionally, it is manufactured out of round stock to meet a specific design.

The required tooth-cutting data for a rack are:

- Pressure angle (same as mating pinion gear)
- Tooth thickness at pitch line (same as mating pinion gear)
- Whole depth (same as mating pinion gear)
- Maximum allowance pitch variation
- Accumulated pitch error max (over total length)



FIGURE 16-22 *Gear terminology for a rack.*

Gear Train

A *gear train* is two or more gears used to achieve a designed RPM. The ratio of the RPM of the last gear to the RPM of the first gear is called the *train value* of the gear train. Calculate the train value as follows:

$$\text{Train Value (TV)} = \frac{\text{product of number of teeth on driving gears}}{\text{product of number of teeth on driven gears}}$$

and

$$\text{RPM (last gear)} = \text{TV} \times \text{RPM first gear}$$

EXAMPLE:

Assume that a 150 RPM gear motor with a 15-tooth pinion drives a 40-tooth gear mounted on a conveyor driveshaft. The speed of the driveshaft would be:

$$\text{RPM (driveshaft)} = \frac{\text{15 teeth on driver}}{\text{40 teeth on driven}} \times \text{RPM (gear motor)}$$

$$\text{RPM (driveshaft)} = 0.375 \times 150 = 56.25 \text{ RPM}$$

Consider a more complicated gear train, *Figure 16-23A.*

- Shafts 1 and 2 are connected by pinion A and gear B
- Shafts 2 and 3 are connected by pinion C and gear D
- Shafts 3 and 4 are connected by pinion E and gear F
- Pinion A has 12 teeth
- Gear B has 45 teeth
- Pinion C has 20 teeth



FIGURE 16-23A *A more complicated gear train.*

- Gear D has 40 teeth
- Pinion E has 15 teeth
- Gear F has 60 teeth

PROBLEM:

For an input speed of 200 RPM at shaft 1, what is the output speed of shaft 4 in RPM?

$$\text{Train Value (TV)} = \frac{12 \times 20 \times 15}{45 \times 40 \times 60} = 0.033$$

Output speed shaft 4 = 0.033 × 200 = 6.67 RPM

Observe the use of arrows in Figure 16-23A to show the direction of gear rotation. Gear A is rotating clockwise; therefore, gear B is rotating counterclockwise.

Occasionally, gear trains are drawn with their centers on a horizontal line, *Figure 16-23B*. The upper view clarifies the relationships of the gears and the directions of rotation.

The equation for calculating the train value of a spur gear train applies to other gear trains such as bevel, worm, and helical, plus combinations of all of them.

Required Tooth-Cutting Data

Overall gear blank dimensions are shown on the detail drawing (as illustrated in Figure 16-20) and can hold loose tolerancing. The actual gear dimensions must hold tight tolerancing.

Twelve essential items of information must be calculated and listed on the gear detail drawing. This list is usually located at the lower right-hand side of the drawing, and generally consists of the data in *Figure 16-24*, but these items may vary slightly from



FIGURE 16-23B *Optional methods of drawing gear trains.*

company to company. The required material, heat-treating process, and other important information must also be included, usually in the title block.

In actual practice, the gear teeth are not drawn because it takes too much drawing time. A simplified method is used to illustrate the actual gear tooth, similar to that used to illustrate threads of a fastener, *Figure 16-25*. The outside diameter and the root diameter are illustrated by a thin phantom line. The pitch diameter is illustrated by a thin center line. Actual teeth are not drawn, except to illustrate some special feature in relationship to a tooth, a spline, a keyway, or a locating point. In this example, all dimensions in color are related to the gear blank only. All gear dimensions are called off in the cutting data box underneath.

Recent practice of spur gear design favors 20° and 25° pressure angles; however, 14.5° full depth and 20° stub (shorter addendum) are not recommended for new designs according to the *Machinery's Handbook, 25th Edition*.

Refer to the *Machinery's Handbook* for more extensive information on gearing and gearing standards, including ANSI B6.1-1968, R1974, and ANSI B6.7-1977.

Measurements Required to Use a Gear Tooth Caliper

A *gear tooth caliper*, *Figure 16-26*, is used to check and measure an individual gear tooth. Gear tooth calipers measure two parts of the tooth profile: the

REQUIRED CUTTING DATA			
ITEM	TO FIND:	HAVING	FORMULA
1	Number of teeth (N)	D & P	D x P
		DO & P	(DO x P) – 2
2	Diametral pitch (P)	p	$\frac{3.1416}{p}$
		D & N	$\frac{N}{D}$
		DO & N	$\frac{N+2}{DO}$
3	Pressure angle (ø)	–	20° STANDARD 14°-30' OLD STANDARD
4	Pitch diameter (D)	N & P	$\frac{N}{P}$
		N & DO	$\frac{N \times DO}{N+2}$
		DO & P	$DO - \frac{2}{P}$
5	Whole depth (ht)	a & b	a + b
		P	$\frac{2.157}{P}$
6	Outside diameter (OD)	N & P	$\frac{N+2}{P}$
		D & P	$D + \frac{2}{P}$
		D & N	$\frac{(N+2) \times D}{N}$
7	Addendum (a)	P	$\frac{1}{P}$
8	Working depth (hk)	a	2 x a
		P	$\frac{2}{P}$
9	Circular thickness (t)	P	$\frac{3.1416}{2 \times P}$
10	Chordal thickness	N, D & a	$\sin\left(\frac{90°}{N}\right) \times D$
11	Chordal addendum	N, D & a	$\left[1\text{-}\cos\left(\frac{90°}{N}\right)\right] \times \frac{D}{2} + a$
12	Dedendum (b)	P	$\frac{1.157}{P}$

FIGURE 16-24 *Required tooth-cutting data for spur and pinion gears.*



CUTTING DATA	
NUMBER OF TEETH	24
DIAMETRAL PITCH	4
PRESSURE ANGLE	20°
PITCH DIAMETER	6.000
WHOLE DEPTH	0.5393
OUTSIDE DIAMETER	6.500
ADDENDUM	.250
WORKING DEPTH	.500
CIRCULAR THICKNESS	.3925
CHORDAL THICKNESS	.2566
CHORDAL ADDENDUM	.3924
DEDENDUM	.289

FIGURE 16-25 *Example of a spur gear detail drawing.*



FIGURE 16-26 *Using a gear tooth caliper.* (Courtesy L. S. Starrett Co.)

chordal thickness and the chordal addendum, *Figure 16-27.* The center slide is set to the desired chordal addendum using the vertical vernier and scale. The tips of the two jaws are then used to measure the chordal thickness read on the horizontal vernier and scale.

Chordal Thickness

The *chordal thickness* is the length of the chord measured straight across at the pitch diameter. It is measured straight across the tooth, not along the pitch diameter as is the circular thickness.

$$\text{Chordal thickness} = \sin\left(\frac{90°}{N}\right) \times \text{Pitch dia.}$$

Chordal Addendum

The *chordal addendum* is the distance from the top of the tooth to the point at which the chordal thickness is measured.

$$\text{Chordal addendum} = \left[1 - \cos\left(\frac{90°}{N}\right)\right] \times \frac{\text{Pitch dia.}}{2} + \text{addendum}$$



FIGURE 16-27 *Measurements required to use a gear tooth caliper.*

Bevel Gear

Bevel gears transmit power and motion between intersecting shafts at right angles to each other. *Figure 16-28* illustrates the various terms associated with bevel gears. The required tooth-cutting data for bevel gears are similar to spur/pinion gears. These must be calculated and listed on the detail drawing. *Figure 16-29* shows the order in which the data and formulas should be listed on the drawing. Bevel gears must be designed and drawn in pairs to ensure a perfect fit.



FIGURE 16-28 *Gear terminology for bevel gears.*

REQUIRED CUTTING DATA				
ITEM	TO FIND:	HAVING	FORMULA SPUR	FORMULA PINION
1	Number of teeth (N)	–	AS REQ'D.	
2	Diametral pitch (P)	p	$\frac{3.1416}{p}$	
3	Pressure angle (ø)	–	20° STANDARD 14°-30′ OLD STANDARD	
4	Cone distance (A)	D & d	$\sin d \sqrt{\frac{D}{2}}$	
5	Pitch distance (D)	p	$\frac{N}{p}$	
6	Circular thickness (t)	p	$\frac{1.5708}{p}$	
7	Pitch angle (d)	N & d (of pinion)	90°–d(pinion)	$\tan d \frac{N \text{ pinion}}{N \text{ gear}}$
8	Root angle (γR)	d & δ	d – δ	
9	Addendum (a)	p	$\frac{1}{p}$	
10	Whole depth (ht)	p	$\frac{2.188}{p} + .002$	
11	Chordal thickness (C)	D & d	$\frac{1}{2}\left(\frac{D}{\cos d}\right)$	$1 - \cos\left(\frac{90°}{\frac{N}{\cos d}}\right) + a$
12	Chordal addendum (aC)	d	$\sin\left(\frac{90°}{\frac{N}{\cos d}}\right)$	
13	Dedendum (bC)	P	$\frac{2.188}{P} - a(\text{pinion})$	$\frac{2.188}{P} - a(\text{gear})$
14	Outside diameter (OD)	D, a & d	D + (2 x a) x cos d	
15	Face	A	1/3 A (max.)	
16	Circular pitch (p)	p & N	$\frac{3.1416 \times p}{N}$	
17	Ratio	N gear & N pinion	$\frac{N \text{ gear}}{N \text{ pinion}}$	
18	Back angle (γO)	–	SAME AS PITCH ANGLE	
19	Angle of shafts	–	90°	
20	Part number of mating gear	–	AS REQ'D.	
21	Dedendum angle δ	A & b	$\frac{b}{A} = \tan \delta$	

FIGURE 16-29 *Required tooth-cutting data for bevel gears.*

Worm and Worm Gear

The worm and worm gear are used to transmit power between nonintersecting shafts at right angles to each other. With the worm and worm gear, a large speed ratio is possible because one revolution of a



FIGURE 16-30 *Examples of worm and worm gear data.*

single-thread worm turns the worm gear only one tooth and one space.

The worm's thread is similar in form to a rack tooth. The worm gear is similar in form to a spur gear, except that the teeth are twisted slightly and curved to fit the curvature of the worm.

When drawing the worm and worm gear, an approximate representation is used, ***Figure 16-30.*** Cutting data for the worm and worm gear must be listed on the drawing in the lower-right side in the order illustrated in ***Figure 16-31*** for the worm gear, and in ***Figure 16-32*** for the worm.

NOTE: It is important that the mounting of a worm and gear set ensures that the central plane of the gear passes essentially through the axis of the worm. This may be accomplished by adjusting the gear axially at assembly by means of shims. When properly mounted and lubricated, worm gear sets will become more efficient after the initial breaking-in period.

Other information that must be included on a worm/worm gear detail drawing includes:

- Gear blank information
- Tooth-cutting data
- Reference to mating part

Materials

Gears are made of many materials, such as brass, cast iron, steel, and plastic, to mention but a few. Many bevel gears are forged, some are stamped

REQUIRED CUTTING DATA			
ITEM	**TO FIND:**	**HAVING**	**FORMULA**
1	Number of teeth (N)	–	AS REQ'D.
2	Pitch diameter (D)	N & p	$\frac{N \times p}{3.1416}$
3	Addendum (a)	p	p x .3181
		P	$\frac{1}{P}$
4	Whole depth (ht)	p	p x .6866
		P	$\frac{2.157}{P}$
5	Lead (L) Right-Left	p & N	p x N
6	Worm part no.	–	AS REQ'D.
7	Pressure angle ø	–	20° STANDARD 14°-30' OLD STANDARD
8	Outside diameter (OD)	Dt & Pa	Dt + .4775 x Pa
9	*Circular pitch (p)	P	$\frac{3.1416}{P}$
		L & N	$\frac{L}{N}$
10	Diametral pitch (P)	p	$\frac{3.1416}{p}$
11	Throat diameter (Dt)	D & Pa	D + .636 x Pa
12	Ratio of worm/ worm gear	N worm & N worm gear	$\frac{N \text{ worm gear}}{N \text{ gear}}$
13	Center-to-center distance between worm & worm gear	D worm & D worm gear	$\frac{D \text{ worm} + D \text{ worm gear}}{2}$

*Circular pitch (p) must be same as worm axial pitch (Pa)

FIGURE 16-31 *Required tooth-cutting data for a worm gear.*

REQUIRED CUTTING DATA			
ITEM	TO FIND:	HAVING	FORMULA
1	Number of teeth (N)	P	$\frac{3.1416}{P}$
2	Pitch diameter (D)	Pa	(2.4 x Pa) + 1.1
		DO & a	DO – (2 x a)
3	*Axial pitch (Pa)	–	Distance from a point on one tooth to same point on next tooth
4	Lead (L) Right or Left	p & N	p x N
5	Lead angle (La)	L & D	$\frac{L}{3.1416 \times D} = \tan La$
6	Pressure angle (ø)	–	20° STANDARD 14°-30' OLD STANDARD
7	Addendum (a)	p	p x .3183
		P	$\frac{1}{P}$
8	Whole depth (ht)	Pa	.686 x Pa
9	Chordal thickness	N, D & a	$\left[1 - \cos\left(\frac{90°}{N}\right)\right] \times \frac{D}{2} + a$
10	Chordal addendum	N, D & a	$\sin\left(\frac{90°}{N}\right) \times D$
11	Outside diameter (OD)	D & a	D + (2 x a)
12	Worm gear part no.	–	AS REQ'D.

*Axial pitch (Pa) must be same as worm gear circular pitch (p)

FIGURE 16-32 *Required tooth-cutting data for worm.*

from thin material, some are cast as a blank and machined, and others are die-cast to the exact size and shape.

Each application must be carefully analyzed. Metal gears have been used for years, but, if the load is not excessive, plastic gears have many advantages. Plastic runs quieter, has a self-lubricating effect, weighs much less, and costs much less. In addition, complicated multiple gears can be molded into a single piece, which further reduces costs.

Design and Layout of Gears

The initial design of gears starts with the nominal size of the pitch diameters. The required speed ratio, loading, space limitations, and center-to-center distances are also important factors to consider. Mating gears and pinions must have equal diametral pitch in order to correctly mesh; therefore, the diametral pitch should be one of the first considerations. A complete analysis and design of a gear or a complete gear chain are very complex, and far beyond the scope of this text. Most designers try to use standard gears from a company that specializes in gears, gear chains, and gear design. Most gear manufacturing companies can be of assistance in designing gears for special applications. These companies can usually manufacture gears at a lower price than if they were made in-house.

Further analysis, in-depth study, and design data can be found in the most recent edition of *Machinery's Handbook*.

Summary

- Gears are classified by the position or location of the shafts they connect. The most widely used types of gears are spur, pinion, rack, ring, bevel, angle, miter, worm, helical, and herringbone.
- Diametral pitch is a ratio equal to the number of teeth (N) per inch of pitch diameter (D). Circular pitch is the distance between corresponding points of adjacent teeth measured on the circumference of the pitch diameter.
- A gear blank is the material from which the gear is cut. The gear blank must allow sufficient space for the gears and a method to attach the gear to the shaft.
- A rack is a gear with teeth formed on a flat surface. A rack changes rotary motion into reciprocating motion.
- A gear train is two or more gears used to achieve a designed RPM.
- A tooth gear caliper is used to check and measure an individual gear tooth.
- Bevel gears transmit power and motion between intersecting shafts at right angles to each other.
- The worm and worm gear are used to transmit power between nonintersecting shafts at right angles to each other.
- Gears are made of many materials such as brass, cast iron, steel, and plastic. Gears may be machined, forged, stamped, or cast.

Review Questions

Answer the following questions either true or false.

1. The outside diameter of a spur gear having a pitch diameter of 1.500 and 48 teeth is 1.68.
2. The pitch diameter of a spur gear having 40 teeth and a diametral pitch of 20 is 19.68.
3. The circular pitch of a bevel pinion having a 16 diametral pitch and 20 teeth is 1.43.
4. A ratio of 2:1 between gear A and gear B means that gear B rotates two times every time gear A rotates once.

Industry Application

The want ad read in part as follows: *"Opening for entry-level mechanical drafting technician. Must have training in laying out and drawing gears."* It was the sentence about gears that gave Peter Walton a problem. He had been an excellent student of Florida Community College (FCC). His field of study was mechanical drafting, and he had graduated with honors. But gears? Walton didn't remember studying gears. His program at FCC had focused on tool design. Walton knew a great deal about jigs and fixtures, but next to nothing about gears.

But Walton needed a drafting job, and, at least for the time being, could not relocate. His mother was in poor health and his father had died when Walton was a young child. Consequently, he needed to stay at home and look after his mother. There weren't many drafting jobs available in Walton's little town of Long Bend, Florida. Since graduating from FCC he had been working at a convenience store. Walton had earned a degree in drafting, and he wanted to put it to work.

Knowing that he might not get another chance without relocating, Walton made up his mind. "I am going to get this job." Walton called and made an appointment for an interview. Regarding the gear issue, he told the company personnel manager, "I will bring several gear drawings that will verify my ability to lay out various types of gears." To himself he said, "I may not be an expert on gears now, but I will be when I interview for the job!" Walton had just one week to learn about gear design and to prepare several drawings. He didn't waste any time. Walton drove to FCC and met with his former drafting professor who quickly pulled several books off the shelf and showed him what he would have to learn. Walton began his crash course immediately.

He read about spurs, pinion, rack, ring, bevel, miters, and worm gears. He learned about gear ratio, pressure angle, and diametral pitch. He learned how to calculate the value of the gear train. Walton studied until his head hurt and his vision was blurry; then he studied some more. After three days he was ready to start drawing. After two days of drawing he had a comprehensive portfolio that included a spur gear, two bevel gears, and a worm gear.

Two days later the interview went well and Walton got the job. In fact, the company officials were so impressed with Walton's knowledge of gears that they increased the starting salary for the job!

5. The pitch diameter of a gear can be thought of as the outside diameter of the friction wheel.
6. The root diameter of a spur gear having a pitch diameter of 2.000 and 32 teeth is 1.75.

Answer the following questions by selecting the best answer.

1. Diametral pitch can be defined as:
   a. diameter of the gear blank divided by two
   b. a ratio equal to the number of teeth on a gear per inch of pitch diameter
   c. the chordal thickness divided by the pressure angle
   d. number of teeth divided by the dedendum
2. What is the dedendum of a spur gear having a pitch diameter of 3.000 and 48 teeth?
   a. 0.3857
   b. 0.2692
   c. 1.4617
   d. 0.3889
3. How many teeth are on a spur gear having a pitch diameter of 1.750, diametral pitch of 20, and outside diameter of 1.850?
   a. 3.24
   b. 37
   c. 16
   d. 35
4. What is the diametral pitch of a pinion gear having 75 teeth and 3.208 outside diameter? (Use the formula P = N/D)
   a. 19.68
   b. 23.38
   c. 24.83
   d. 23.21
5. When cutting the teeth for bevel gears, how does one compute diametral pitch (P)?
   a. .5 (2.188) + sin d
   b. 1 ÷ p
   c. 3.1416 × sin d
   d. 3.1416 ÷ p

6. When cutting the teeth for a worm gear, how does one compute the pitch diameter?
   a. D + (2 × a)
   b. .686 × Pa
   c. P × N
   d. OD – (2 × a)
7. A gear train can best be described as:
   a. a series of gears linked together.
   b. two or more gears used to achieve a designed RPM.
   c. a power transmission device for transferring motion.
   d. a series of gear pinions.
8. How does one compute the center-to-center distance between worm and worm gear?
   a. P × .3181
   b. D + .636 × Pa
   c. Nworm gear ÷ Dworm
   d. Dworm + Dworm gear 2

Chapter 16 Problems

The following problems are intended to give the beginning drafter practice in using the many formulas associated with gears and practice in laying out finished professional detail drawings of major kinds of gears.

Conventional Instructions

The steps to follow in laying out gears are:

STEP 1 Study the problem carefully.

STEP 2 Make a sketch if necessary.

STEP 3 Do all math required for each problem. Keep all math work for rechecking.

STEP 4 Center the required views within the work area.

STEP 5 Include all dimensioning according to the most recent drafting standards.

STEP 6 Add all required gear cutting specifications in the lower right side of the paper.

STEP 7 Recheck all work, and, if correct, neatly fill out the title block using light guidelines and neat lettering.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

PROBLEM 16-1

Use the following specifications to lay out a single-view drawing of a 2:1 ratio spur gear and pinion gear in mesh.

Spur gear:	Pinion gear:
88 teeth	hub diameter 1.625
pressure angle 20°	bore of 1.000 diameter
pitch diameter 5.500	pressure angle 20°
hub diameter 2.625	
bore of 2.000 diameter	

Use all standard drafting methods to illustrate the outside diameter, pitch diameter, and root diameter. Calculate and add the center-to-center distance between the shafts.

PROBLEM 16-2

Draw a spur gear having the following specifications: 56 teeth, pressure angle 20°, pitch diameter 3.500, hub diameter 1.00 gear blank with overall size (width) 1.00, face size .50, bore .5625; use a 1/8" set screw.

Complete two views using the half-section method of representing gears. Do not show the gear teeth; use the conventional method of illustrating teeth.

Dimension per all standard practices. Calculate and add all standard required cutting data to the lower-right side of the work area. Material S.A.E. #1320 cast steel. Heat treatment: carburize .015 – .020 deep.

PROBLEM 16-3

Complete a 2-view detail drawing of a pinion gear having the following specifications (calculate and add all standard cutting data): 30 teeth, pressure angle 20°, pitch diameter 6.000, hub diameter 2.000, heat treatment carburize .050 deep, gear blank with overall size (width) 3.500, face size 1.250, bore 1.000, material S.A.E. #4620 steel.

PROBLEM 16-4

Make a detail drawing, completely dimensioned, of a spur gear with the following specifications: diametral pitch 16, pressure angle 20°, pitch diameter 5.500, whole depth .1348, outside diameter 5.625, addendum .0625, working depth .125, circular thickness .098, chordal thickness .0633, chordal addendum .0985, whole depth .1348, and dedendum .0723, material cast brass.

Design a simple gear blank with a set screw to fasten the gear to a .75 dia. shaft.

PROBLEM 16-5

Design and draw a detailed drawing, completely dimensioned, of a pair of bevel gears having teeth of a 4.0 diametral pitch, the gear with 25 teeth, the pinion gear with 13 teeth, face width of 1.00, gear shaft 1.25 diameter, and pinion shaft .875 diameter. (Calculate for FN-2 fits with the shaft.)

Design the hub diameter to be approximately twice the shaft diameter. Backing for the gear 1.375 and for the pinion .75. Design and dimension the remaining portion to suit, using standard drafting practices. Add all cutting data to the lower-right side of the work area. Material: S.A.E. #3120 cast steel, heat treatment: carburize .015/.020 deep.

PROBLEM 16-6

Make a design layout of a worm and worm gear with the following specifications: shaft diameter 1.25, single-thread worm, lead .75, worm gear with 28 teeth. Add all dimensions and cutting data as required.

17

Assembly and Detail Drawings for Design

CHAPTER OUTLINE

Technical drawings and the engineering department • The engineering department • Systems company • Design section • Working drawings: detail and assembly • Title block • Numbering system • Drawing revisions: ECRs and ECOs • Application engineering • Quotation department • Mass production company • Design for manufacturability (DFM) • DFM guidelines • Design for assembly (DFA) • DFA guidelines • Personal technical file • Invention agreement • Patent drawings • Summary • Review questions • Chapter 17 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Discuss the use of sketches, layout drawings, detail drawings, subassembly drawings, and final assembly drawings.
- Summarize the contents of a parts lists or a bill of materials, including purchased parts.
- Prepare sketches, layout drawings, detail drawings, subassembly drawings, and final assembly drawings.
- Describe a typical engineering department and the functions of a design section, an application department, and a quotation department.
- Describe the design procedure used in industry and identify your own potential role in the procedure.
- Compare the similarities and differences between a proposal and a contract.

(continued)

KEY TERMS

Application engineering
Assembly drawing
Conceptual design
Contract
Design development layout drawings
Design procedure
Design section
Detail drawings
DFA (design for assembly) procedure
DFM (design for manufacturing) procedure
ECO (engineering change order)
ECR (engineering change request)
Invention agreement
Mass production company
Parts list
Patent drawings
Proposal
Purchased part
Quotation department
Scientific design
Selling price
Sketches
Subassembly drawing
Title block

(CHAPTER OBJECTIVES continued)

- Process ECRs and ECOs.
- Describe how a selling price is established for a product.
- Start your own technical file in a systematic manner.
- Explain DFM and DFA.
- Recognize invention agreements and patent drawings.

Technical Drawings and the Engineering Department

A representative engineering department and a flowchart showing lines of communication, ***Figure 17-1***, provide a framework for discussing technical drawings and related engineering practices. Technical drawings include sketches and layout, detail, and assembly drawings. Related engineering practices encompass the following: design procedure, parts lists, title blocks, engineering revisions, invention agreements, patents, personal technical files, designing for manufacturing and assembly, and quotation-proposals. In the problems at the end of the chapter you will have the opportunity to do basic designing using the procedures, drawings, and practices discussed. You will be able to utilize topics from preceding chapters, such as dimensioning, standards, fasteners, tolerances, and machine elements.

The Engineering Department

Engineering departments vary from company to company, but most of them have functions in common. An example engineering department in a medium-sized engineering company, Figure 17-1, has a variety of sections usually directed by a chief engineer. Our example has three sections: design, application, and quotation. The design section is responsible for new products and minor design improvements for existing products. The application engineering section handles special-order modifications to existing products of the company. For example, if our company manufactured commercial scales for weighing trucks, the application section would modify scales to meet specific customer requirements. The quotation department estimates costs of new or modified existing products and prepares quotations of selling prices to present to potential customers. In larger engineering companies, design and application sections may be divided into fields of engineering such as mechanical, civil, electrical,



FIGURE 17-1 *Chain of command in an engineering department.*

electronic, structural, materials, agricultural, petroleum, and so forth.

Directly under the chief engineer are the section heads, usually engineers or designers with extensive design-engineering experience plus an ability to lead teams of skilled personnel. The teams could consist of engineers, designers, drafters, detailers, checkers, technical writers, illustrators, and typists. Although most engineering departments have definite departmental structures, many companies move drafters, designers, and engineers back and forth among the various sections as needed. The moves help new personnel to learn the departmental structure and operation of their organization. Another exercise to gain an understanding of how an engineering organization functions is to follow paper documents along the chains of command as indicated in the flowchart, Figure 17-1.

Hence, for illustrative purposes in this chapter, two hypothetical engineering organizations are discussed. The first company produces one-of-a-kind systems to meet special needs of customers—in this case, a customer who produces electrical power. The second is a company that mass-produces a device used for positioning a small crosshair cursor or a pointer on a computer screen—the ubiquitous mouse.

Systems Company

Assume that a systems company has received a request for proposal (RFP) from a solid-waste handling company that needs to convert burnable waste into electrical power. The proposal is to be submitted to the solid-waste handling company in two months. The president of the systems company sends a memo to his chief engineer with directions to process the RFP. Consequently, the chief calls a meeting of the design, application, and quotation department heads. They decide that the design section will need to design a new furnace and one new conveyor for handling solid waste coming from a shredder. The application engineering group will need to modify several designs of existing conveyors. A steam turbine design and an electrical generator design will only require small changes. The quotation department has the task of preparing a proposal to be submitted to the waste-handling company before the two-month deadline. The proposal will include the selling price of the complete energy-generating system, the delivery dates, and descriptions of the system components. Then, if the waste-handling company accepts the proposal and signs it, the proposal becomes a binding contract on both companies.

Design Section

The *design section* will be discussed first to illustrate the uses of the drawings and the related engineering practices listed earlier, which include preparing assembly, detail, and layout drawings, following design procedures, making comprehensive parts lists, executing engineering revisions, handling invention agreements, keeping personal technical files, and preparing quotations. Application engineering will be discussed later.

Design Procedure

A design process or *design procedure* used by the design section acts as a general guideline for a team of designers, engineers, and drafters, ***Figure 17-2***. Their preliminary design tasks are to design a new conveyor and create a new furnace. Detailed information on these two system components needs to be developed so the quotation department can prepare cost estimates on them.

No one design process serves an individual designer, design team, or organization. Each individual, team, and organization develops a design process to suit



FIGURE 17-2 *Design procedure.*

their respective needs. (Similar-but-different design processes also are discussed in the Introduction and Chapters 1 and 24.)

The actual process of developing a new product from its established need (the RFP in this example) to its final production, consumes many hours and involves a variety of highly trained, skilled personnel. The flowchart in Figure 17-2 shows the overall process to production; however, in this preliminary RFP phase, the design team only goes through to the cost study stage to prepare information for quoting purposes. Later, if the proposal is accepted by the customer, the design section team would develop the conveyor and furnace through to the production stage.

Nevertheless, to continue describing the design procedure followed by the design section team for the new conveyor and new furnace, concept-study *sketches* would be done first. (Note that a market survey would not be required for this project because the RFP stated the need.) Sketches would be made of conveyor ideas for moving the waste from a shredder to the furnace, ***Figure 17-3***. Next, where and how to burn the waste in the furnace and where to utilize the hot gases to generate steam would be considered. During these studies, many ideas are presented, usually in sketches. Designers are encouraged to generate and sketch ideas without restraint; that is, without being influenced by existing designs, in order to arrive at a fresh and perhaps unique solution. The more ideas that are proposed in the time available, the greater the chances of developing the best solution to the problem. These brainstorming sessions are conducted in an atmosphere of "no criticism" so members will not feel inhibited. Analysis of the ideas is scheduled after the free-wheeling sessions.

The design section team employs two effective design approaches. In *conceptual design*, much use is made of known technical information from such sources as reference books, technical journals, handbooks, and manufacturers' catalogs. (Refer to Chapters 13, 21, and 24 for examples.) All members of the team should be aware of the latest technical information available. In *scientific design*, use is made of concepts from physics, mechanics, materials science, chemistry, and mathematics.

During the analysis phase the best ideas are identified and developed further in sketches. Suitable engineering materials are investigated. Loads on the structures are analyzed and energy balances (output versus input) are estimated.

Layout Drawings

The department head in the design section follows the team's progress and directs them to prepare *design development layout drawings* for a preliminary



FIGURE 17-3 *Sketch for conveyor ideas for conveying waste to the furnace.*



FIGURE 17-4 *Sketch of preferred conveyor for conveying waste to the furnace.*



FIGURE 17-5 *Layout drawing of preferred conveyor.*

design review. The team draws the best sketches to scale either by pencil or a computer. For example, ***Figure 17-4*** shows a sketch of a preferred drag-type conveyor for delivering burnable shredded waste to the furnace, and ***Figure 17-5*** shows portions of the preferred conveyor drawn to scale in a layout drawing. Note the informality of the design development layout drawing. Standard dimensioning practices are encouraged, but not required. Clear handwritten notes are acceptable. Drafters, designers, and engineers do layout drawings as needed. The layouts may not be completely dimensioned, but they have overall dimensions and important center lines located. Informal notes specify tolerances, materials, special manufacturing processes, and related pertinent information. Title blocks are optional.

During the design review, the layout drawings help the team to decide on the final designs to consider. The quotation department assists the team in preliminary cost analyses. Finally, the conveyor design and a new furnace concept that best meet the requirements are selected. Manufacturing personnel who also have participated in these discussions recommend appropriate manufacturing processes for the conveyor and furnace.

Assume now that the quotation department has received all the technical data and specifications they need from the design section and application engineering departments to prepare a cost estimate to satisfy the RFP. A proposal is written and presented to the waste-handling company just before the two-month deadline. In addition to the written proposal and several systems site–drawings, three types of illustrative material may be presented for better visualization of the system. An illustrator may prepare a watercolor perspective drawing of the whole system or a computer-generated 3D picture. A third type that might be presented is an architectural-type scale model made of cardboard and balsa wood of the whole system showing dumping sites, chutes, conveyors, the furnace and boiler, and the electricity-generating equipment.

The waste-handling company representatives may ask for further information and explanations, such as brief descriptions of system components and when specific components will be delivered, installed, and operating. Finally, after further comments and questions, the proposal is accepted and signed. It is now a binding, legal contract on both companies. ***Figure 17-6*** shows an example signature page from a proposal-contract form.



COMPANY

20—APPROVAL: There are no agreements or oral understandings outside of this proposal, which shall become a contract only when accepted by you, _____ _____, and approved in writing by a plant manager or an executive officer of Company.

Prepared and submitted to you for Company

by _____

Accepted this _____ day of _____

19___ for

_____

by _____

Title _____

Approved for Company at

_____

this _____ day of _____ 19 ____

by _____

Title _____

FIGURE 17-6 *Proposal-contract signature page.*

Working Drawings: Detail and Assembly

The systems company president notifies the chief engineer that the proposal is now a contract. The chief directs the designers and engineers to forward the design development layout drawings of the new conveyor and the furnace to drafters and detailers who use these drawings to create working drawings; that is, detail and assembly drawings for manufacturing. There are a number of different kinds of working drawings associated with the development and production of a product, so the drafter must be familiar with each kind, know the company standards, and be able to draw each kind. The major kinds of working drawings are:

- Assembly drawings
- Subassembly drawings
- Detail drawings
- Modified purchased drawings

Assembly Drawing

Any product that has more than one part must have an assembly drawing. The *assembly drawing* illustrates how a product is assembled when completed. The assembly drawing can have one, two, three, or more views as needed. Often, a full section view is used to show how the parts are assembled.

Assembly drawings usually are not dimensioned, except for general overall dimensions or to indicate the capabilities of the assembly. For example, a clamp assembly drawing might have a dimension to illustrate how wide it opens. (Refer to Problem 17-7.) Assembly drawings do not contain hidden lines unless they are absolutely necessary to illustrate some important feature that the reader might otherwise miss.

An assembly drawing must call off each part that is used to make up the assembly. Each part must be called off by its part number and title, and the total number required to make up one complete assembly. Companies most often use one of two methods to call off the parts. In Method A, each part has a leader line with the part number, title, and number required, ***Figure 17-7.*** In Method B, each part has a leader line with a balloon call-off number inside, ***Figure 17-8.*** This method uses a tabulation chart to list the part number, title, and number required.



FIGURE 17-7 *Assembly call-off (Method A).*



MUST INCLUDE: **DRAWING NUMBER**
TITLE
NUMBER REQUIRED PER ASSEMBLY

NO.	DRAWING NO.	ITEM	REQ'D
–	–	1/4-20 UNC	–
5	PURCH	LOCK NUT-HEX	2
–	–	1/4-20 UNC X 1 1/2 LG.	–
4	PURCH	SCREW-CAP HEX HD	2
3	A 661982	HOOK	2
2	A 661981	SCREW-CENTER	1
1	A 661983	YOKE	1

FIGURE 17-8 *Assembly call-off (Method B).*



FIGURE 17-9 *Subassembly drawing.*

Subassembly Drawing

A subassembly is composed of two or more parts permanently fastened together. A *subassembly drawing* is very similar to an assembly drawing. All standard practices associated with assembly drawings apply to subassembly drawings. That is, full section views, few overall dimensions, hidden lines only if necessary, and call-offs using either method one or two are employed.

Subassemblies sometimes require machining operations after assembly, *Figure 17-9*. For instance, a hole is to be drilled through the parts after assembly. Drilling each individual part and then aligning the holes at assembly would be much more difficult and costly. Thus, the required dimensions to drill the hole are added to the subassembly drawing.

There can be any number of subassemblies in the final assembly. For example, in an automobile, the engine is a subassembly, the alternator is a subassembly, the transmission is a subassembly, and so forth. These subassemblies, together with various single



FIGURE 17-10 *Detail drawing.*

parts, make up the final assembly of the automobile. Note that subassemblies are often purchased, stocked, and stored for later final assemblies.

Detail Drawings

Every manufactured part must have its own fully dimensioned *detail drawing*, with its own drawing number and title block, ***Figure 17-10.*** All information needed to manufacture the part is contained in the detail drawing, including as many views as needed to fully illustrate and dimension the parts.

The general practice in technical drawing is to draw only one part to one sheet of paper, regardless of how small the part is, because individual parts are often made on different machines or by different processes, and the bookkeeping plus costing is easier for one part per drawing.

Most companies use detail drawings as just described. However, some companies separate the detail drawings into various manufacturing processes, such as:

- Pattern detail drawings for castings
- Casting detail drawings
- Machining detail drawings
- Forging detail drawings
- Welding detail drawings
- Stamping detail drawings

Two observations regarding technical drawings are added here for your information.

1. Fold lines, construction lines, reference planes, and reference numbers and letters are almost never included on technical drawings. They may have been utilized to prepare views and sections, but they are omitted from the drawing.
2. A seldom-discussed drawing technique designed to clarify portions of drawings may be used effectively. Usually a small portion of a large drawing is removed, enlarged, and labeled, e.g., DETAIL A. Refer to figures in the latter portion of Chapter 21 for examples.

Purchased Parts

Most manufacturing companies cannot make such purchased items as electric motors, bearings, shafting, bolts, nuts, screws, and washers as cheaply as companies that specialize in making these items. Therefore, designers should specify these standard



FIGURE 17-11 *Detail drawing of modified purchased part.*

items whenever possible. *Purchased parts* are drawn in assembly drawings, usually in outline form, to show their function and relationship to the product. All specific information for a purchased part should be listed on the drawing or parts list, including size, material, special features, vendor part number, performance, and so forth. For example, specifications for a DC motor might read as follows: "12 volt DC motor, GE no. 776113 or equal."

Modified Purchased Parts

A purchased part that needs to be modified, however slightly, must have the modification fully described and dimensioned as with any detailed part, except that the purchased part size and description are listed in the title block under Material. ***Figure 17-11*** shows a standard fastener, M20 × 2.5-6g × 70 long hex-head machine screw, which is to have a tip specially turned and a 4 mm diameter hole drilled through the tip. The standard fastener is drawn with the modifications added and dimensioned. Then it would be called out as a standard metric fastener in the title block under Material. This directs the machinist to make the part from a standard fastener.

Title Block

Title blocks vary from company to company, although most companies follow the ANSI standard illustrated in Figure 17-10. The primary function of a *title block* is to provide information not normally given on the drawing, such as:

- Name and address of the company
- Drawing title
- Drawing or part number
- Scale of the drawing
- Name of the drafter and date completed
- Name of the checker and date checked
- Name of the person who approved the drawing and date
- Material the part is to be made of
- Tolerances/limits of dimensions
- Heat treatment requirements if not specified on the drawing
- Finish requirements if not specified on the drawing

Size of Lettering within the Title Block

- General information, .125 (3) freehand/.120 mechanical
- Drawing title, .250 (6) freehand/.240 mechanical
- Drawing number, .312 (8) freehand/.350 mechanical

Checking Drawings

The importance of absolute accuracy in engineering drawings cannot be stressed enough. The slightest error could cause large and unnecessary expenses. In some fields of engineering, such as in aircraft and space vehicles, an error could cause tremendous consequences—lost lives! Therefore, every precaution should be taken to avoid errors. In most engineering departments, checkers are employed to verify all dimensions and to see that standard materials and features (holes, threads, keyways, etc.) are used wherever possible. The checker's responsibility is to check the entire drawing and sign it before the drawing is finally approved (usually by a chief engineer) and released.

Conscientious drafters check their drawings before submitting them to the checkers to ensure accuracy and to save the checker's time. A partial checklist for drafters is as follows:

- Are all dimensions included?
- Are there unnecessary dimensions?

- Can the part be manufactured in the most economical way?
- Are dimensions and instructions clear and understandable?
- Will the part assemble with mating parts?
- Have all limits, tolerances, and allowances been properly analyzed for all moving parts?
- Have undesirable accumulations of tolerances been analyzed?
- Are all notes added?
- Are finish-texture symbols added?
- Are the material and treatment for each part specified?
- What is the drawing's general appearance? (legibility, neatness, arrangement of views)
- Does it follow all drawing and company standards?
- Is the title block complete? (title, part number, drafter's name, etc.)

Parts List

A *parts list* may contain the assembly drawing number, all subassembly drawing numbers, all detail drawing numbers, all purchased parts, material of each part, and the quantity of individual parts needed for one complete assembly.

A drafter usually prepares the parts list while following company guidelines. Some companies list the parts in order of size, some in the order of importance in the manufacturing process, and others in order of assembly. The assembly method is preferred due to the time savings later in the assembly area. An assembly method parts list is shown in ***Figure 17-12***, for a machine vise.

The parts are listed in the order used for assembling the machine vise. Note that the purchased parts do not have a drawing number; therefore, they are listed under the column titled Drawing No. as PURCH., indicating that these are standard parts to be purchased, not made, by the company. Additional typical purchases for most companies are motors, bearings, switches, gears, chains, belts, and controls. Complete specifications must be listed for purchased parts so that there is no question as to what must be purchased. The purchasing agent for the company may not have a technical background and therefore will rely on the parts list specifications for purchasing "buyouts." In this example, items numbered 7, 8, 17, 23, and 24 are purchased parts.

Some companies use a system of indents to list the parts, Figure 17-12. There are four indents,

INDENT 1 = ASSEMBLY DRAWING
INDENT 2 = SUBASSEMBLY DRAWINGS
INDENT 3 = DETAIL DRAWINGS
INDENT 4 = PURCHASED PARTS

MASTER PARTS LIST

NO	DRAWING NO.	DESCRIPTION	MATERIAL	QUAN
1	D77942	VISE ASSEMBLY-MACHINE	AS NOTED	1
2				
3	C77947	BASE-VISE	AS NOTED	1
4	B77952	BASE-LOWER	C.I.	1
5	A77951	BASE-UPPER	C.I.	1
6	A77946	SPACER-BASE	STEEL	1
7	PURCH.	BOLT 1/2-13 UNC-2.0 LG.	STEEL	1
8	PURCH.	NUT 1/2-13 UNC	STEEL	1
9				
10	C77955	JAW-SLIDING	STEEL	1
11				
12	A77954	SCREW-VISE	STEEL	1
13	A77953	ROD-HANDLE	STEEL	1
14	A77956	BALL-HANDLE	STEEL	2
15				
16	A77961	PLATE-JAW	STEEL	2
17	PURCH.	SCREW 1/4-20 UNC-1.0 LG.	STEEL	4
18				
19	A77962	COLLAR	STEEL	1
20				
21	A77841	KEY-SPECIAL VISE	STEEL	2
22				
23	PURCH.	BOLT 1/2-13 UNC-4.0 LG.	STEEL	4
24	PURCH.	NUT 1/2-13 UNC	STEEL	4

JAN ENGINEERING PETERBOROUGH, NH	Model No. 160	Parts Lister NELSON	Date 6 AUG 98
Title VISE ASSEMBLY-MACHINE		PAGE 1 OF 1 PAGES	Drawing No. A1198891

FIGURE 17-12 *Parts list.*

indicating the various kinds of drawings. The first indent indicates the main assembly drawing. The second indent indicates all subassembly drawings used to make up the assembly. The third indent indicates all detail drawings and modified purchase parts with drawing numbers to make up the assembly. The fourth indent indicates all purchased parts to make up the assembly.

Not all companies use this system, but using the indent system gives a quick indication of which parts are used to make up the various subassemblies. Note on the example list that item number 3 is indented one place, indicating a subassembly. Item numbers 4, 5, and 6 are detail drawings used to make up the subassembly item number 3. Item numbers 7 and 8 are purchased parts used to complete the subassembly item number 3.

For additional examples of parts lists or bills of materials, refer to Figures I-31, I-36, 21-35, 21-46, 24-16, and 24-17.

Numbering System

The numbering system for identifying and recording technical drawings varies from company to company. Although no standard system is used by all companies, most companies assign a sequential number for each drawing as it is finished. Some also add a prefix letter to indicate the drawing size. A drawing on a C-size sheet with an assigned number of 114937 would be indicated on the drawing by C–114937. The drawing number could be done in freehand, 0.312 (8) high, or mechanically lettered, 350 (9) high.

Drawing Revisions: ECRs and ECOs

After any technical drawing has been signed off (drawn, checked, and approved) and incorporated into the company's system, changes in the drawing are usually accomplished through *ECRs* and *ECOs*. Anyone having a suggestion or need to improve a part or assembly within the product, or an error to correct on the drawing, must bring it up in an *engineering change request (ECR)* procedure meeting, ***Figure 17-13,*** and request an *engineering change order (ECO)*. No change can be made in a drawing after it has been released (signed off) to manufacturing, even by the drafter or designer who drew it. All departments concerned must agree to the change, Figure 17-13. The ECR and ECO explain what change is to be made, what it was before, why the change is to be made, whether it affects other parts, and who suggested the change. When the engineering change request has been approved, the committee issues the engineering change order. The ECR and ECO list the departments in the company that will be directly affected by the change.

Beginning drafters, detailers, designers, or newly hired engineering graduates may "get their feet wet" in the company by being assigned the task of incorporating ECOs in the company's technical drawings. These assignments are made primarily to introduce the employees, new to the company, to technical documents that flow through the company and to how the company functions. Introducing new employees to the flow of technical documents illustrates an admonition of a commencement speaker who said to the graduates, "Get dirt under your fingernails so you'll know what's going on!"

Minor changes on original drawings may be just erasures or additions made directly on the original, whether on paper or in a computer. If a dimension is not noticeably affected by the change, the dimension is simply corrected and underlined with a heavy black line. This indicates that the dimension is correct, but slightly out of scale, ***Figure 17-14.***

If the change is extensive, the drawing must be redrawn. The original drawing is not destroyed: it is stamped OBSOLETE and includes the note "SUPERSEDED BY (the number of the corrected drawing)." The new drawing must have a note referring back to the superseded drawing. The change on the drawing must be clearly marked where the change was made, and it must clearly describe what was changed. Each company has its own standards to indicate this information. The most common method is to place a letter or number in a small balloon near a changed dimension or dimensions, or near the change made to the drawing. The letter or number must be listed in the revision block, ***Figure 17-15.*** The revision block, located either to the left of the title block or on the top right corner of the drawing sheet, shows the letter or number of the change, what



FIGURE 17-13 *Engineering change request order procedure.*



FIGURE 17-14 *Balloon change call-off.*



FIGURE 17-15 *Revision block.* (Courtesy Bishop Graphics Accupress)

was changed, the date of the change, and who made it. If the change is extensive, only the ECO number is listed. Anyone needing to know why the change was made can refer back to the ECO or the ECR.

Some companies add the last change letter to the drawing number, which, in effect, actually changes the part number. For example, part number C–65498 would become C–65498–A for the first change. Then, if changed again at a later date, it would become C–65498–B, and so on.

In certain cases, appropriate administrative changes may be made without an engineering change order. Such simple changes as misspelled words or incorrect references are non-engineering changes and probably would not affect other departments.

The next section in the system company's structure, application engineering, primarily processes existing designs.

Application Engineering

Preliminary activity in the *application engineering* section proceeds to the cost studies step in the design procedure, Figure 17-2, in a manner similar to the design section. The procedure acts as a guide for an application engineering team of engineers, designers, and drafters who consider designs of conveyors, steam turbines, and electrical generators the company has produced in the past. Also, the team considers concepts that already exist in industry. The team's primary task is to modify and incorporate these existing concepts to meet the design requirements for the waste-burning system. For example, a scale is modified to monitor the amount of waste being delivered. A platform over the scale must be modified to accommodate large trucks. After being weighed, the trucks would dump the waste into a chute going to a flight conveyor, a standard product of the company, which would carry the waste to a hopper where the waste would be stored until conveyed to a shredder. From the shredder the waste would be conveyed to the furnace on the new drag conveyor created in the design section, Figures 17-4 and 17-5. Drawings of a steam turbine would be reviewed in an ECR meeting where ECOs would be written to modify the existing specifications and drawings of the turbine. Drawings of an electrical generator system also would be modified from ECOs. Drafters and detailers would process the ECOs.

Several new designs are developed in application engineering, but they are minor and are based on the designer's previous experience. For example, sketches and a layout drawing to determine overall dimensions of the chute previously mentioned are shown in ***Figure 17-16.***

Finally, specifications and appropriate layout drawings are forwarded to the quotation department for their use in the cost study.

Quotation Department

During the design and development of the waste-burning furnace and during the processing of the conveyors, steam turbine, and electrical generator, the *quotation department* closely followed the design section's progress and the application engineering's activities. Thus an estimate of the selling price for the entire system was nearly completed for the RFP by the time design and application finished their respective tasks. The selling price is the major dollar figure submitted to the customer, but subtotals for component systems, such as the furnace, the steam turbine, and the generator may be included. The *selling price* is prepared by the quotation department in steps illustrated in ***Figure 17-17.*** Basic costs include labor and engineering materials. Basic labor (sometimes labeled direct labor) includes estimates of hours for engineering, drafting, manufacturing, assembling, and installing. Engineering materials include steel plates, structural steel shapes, fasteners, welding rods, switches, motors, controls, and so forth. Manufacturing expenses, such as depreciation of machines and maintenance, add to the basic costs to make up manufacturing costs. Sales salaries and expenses plus general overhead costs (electricity, water, office supplies, etc.) are added to manufacturing costs to arrive at the total cost to produce the energy system. Profit added to total cost establishes the selling price.

The selling price, specifications, delivery schedules, and the "boilerplate" make up the *proposal.* A typical boilerplate would be stored in a computer ready for use in any new proposal. It includes introductory comments and sections intended to promote the company to the prospective customer, such as descriptions of past systems designed and installed and summaries of the expertise of the personnel who would handle the job if the proposal were accepted. Another section of the boilerplate protects the company with legal statements referring to late delivery due to



FIGURE 17-16 *Sketches and layout drawing of chute.*



FIGURE 17-17 *Selling price components.*

strikes, acts of God (earthquakes, tornadoes, etc.), unavailability of materials, and so forth.

A cover letter with a bound copy of the proposal would be mailed to the prospective customer before the due date, or delivered in person if an oral presentation was arranged. Oral presentations give the recipient an opportunity to ask questions, suggest changes, and correct any misunderstandings. When the customer accepts the proposal and signs it, it becomes a binding legal *contract* on both parties. It also becomes a document that immediately generates continuing work for the design and application sections of the systems company.

This continuing work for the design section was discussed earlier. Working drawings were prepared, checked, signed, and sent to manufacturing. In a similar manner, application engineering would produce working drawings, have them checked, signed, and sent on to manufacturing.

Mass Production Company

A *mass production company* that produces large quantities of a product would have an engineering departmental structure similar to the systems company discussed earlier, Figure 17-1; however, the mass production company would have a somewhat different approach to producing a product, ***Figure 17-18.*** The company's design, application-engineering, quotation, and manufacturing departments would follow this design procedure for mass-producing one product while working together more closely than departments in the company that produced a one-of-a-kind system. To illustrate these different procedures, assume that the mass production company primarily produces mouse units, ***Figure 17-19,*** for use with a computer. Essentially, a mouse provides a quick way for computer operators to position a small crosshair cursor or a small pointer on a video screen by moving the mouse across a special desk pad. Then once the crosshair or pointer has been positioned, one key atop the mouse is clicked to initiate a basic computer operation.

Assume that the mass production company has received an order for two million mouse units and that each unit requires more functions than their standard mouse. The major challenge to the company is to design and mass-produce these units as efficiently as possible and still have a reliable product. The company's design efforts are focused on two important areas of mass production. The first, DFM (design for manufacturability) emphasizes design of the parts that make up a product. The second, DFA (design for assembly) concentrates on assembly of the parts that make up a product.



FIGURE 17-18 *DFM-DFA procedures.*



FIGURE 17-19 *Computer mouse.*

Design for Manufacturability (DFM)

The *DFM procedure* is an iterative loop and acts as a guide for a design team, Figure 17-18. The primary goals of the DFM team are to develop the new mouse design, for more efficient manufacturing, at the least cost, within a reasonable time, and to ensure its

function for a reasonable life. The team made up of engineers, designers, drafters, and manufacturing personnel pursue these goals as illustrated by the iterative path shown. Start with optimizing (design, function, and cost), then go on to simplifying (DFM guidelines), ensuring (function, life, materials), and back to optimizing. One factor not shown in Figure 17-18 is the time constraint for making decisions. This can affect the success of the DFM process. Decisions must be made at each step in the loop, based on information available at the time and the judgment of the team members.

DFM Guidelines

Guidelines for DFM evolved over a period of time, essentially due to an increasing need for collaboration on the design of products between a company's engineering department and manufacturing. To be competitive, companies needed to be more efficient and to produce better products. Some DFM guidelines from DFM literature are:

- Minimize the number of parts.
- Minimize part variations.
- Design parts to have more than one function or use.
- Design parts for ease of manufacturing.
- Use fasteners that handle easily and can be readily installed.
- Arrange the assembly of parts so they assemble in layer fashion.
- Avoid flexible parts.

Minimize Number of Parts

One approach is to combine two parts into one, thus eliminating fasteners. An obvious example is shown in *Figure 17-20.*

Minimize Part Variations

If fasteners are required, use all the same size to save storage space and sorting-and-assembly costs. Use standard off-the-shelf parts where possible.

Design Parts to be Multifunctional

For example, a leaf spring designed to exert a small force could also conduct an electrical current. A structural part could have ridges for guiding a second part into position. A spacer post could be used for a fastener, *Figure 17-21.* One shaft of a specific length and diameter could be used in a variety of products. One-size parts such as bearings, springs, or gears could be used in a variety of products in a company.



FIGURE 17-20 *Combining two parts into one.*



FIGURE 17-21 *Post used for spacer and fastener.*

Design Parts for Ease of Manufacturing

Precision cast gears or stamped gears need little or no machining or surface finishing. Basic materials with relatively expensive finishes, such as anodized aluminum, may ultimately save painting, polishing, and machining later in the manufacturing processes, thus keeping labor costs down.

Use Fasteners Easily Handled and Installed

Snap-in fasteners save assembly and screwdriver time, *Figure 17-22.*

Arrange Parts Assembly for Layering

Assembly of the mouse shown in *Figure 17-23* illustrates layering; that is, essentially, parts are stacked from the bottom up.

Avoid Flexible Parts

Use circuit boards instead of flexible, difficult-to-assemble wires for electrical circuits where possible.



FIGURE 17-22 *Snap-in fastener for circuit board.*



FIGURE 17-23 *Layering for mouse assembly.*

Of course, the mouse, Figure 17-19, needs one flexible connector for easy movement on a desk pad.

The next step in the loop, Figure 17-18, is to ensure function and life, and to select the best materials. Most mouse units utilize a printed circuit on a board with electronic components, to integrate the digital signals



FIGURE 17-24 *Slotted disks inside a mouse.*

generated by light passing through rotating slotted disks inside the mouse, ***Figure 17-24.*** The shafts of the two slotted disks are driven by a small ball, mostly inside the body of the mouse, as it rolls on a special desk pad in a direction determined by the computer user, who observes a crosshair or pointer on the video screen. Since the disks are mounted in "X" and "Y" orientations, the sum of their rotations (digital signals) is used to position the crosshair or pointer on the video screen. The body of the mouse and a number of the inside parts are made of molded plastic. Resistors, capacitors, optical components, and switches are purchased buyouts. Stainless steel shafts support the disks; bearing supports for the shafts are part of the plastic body, thus no lubrication is required. The keys for initiating basic operations are molded plastic with narrow portions acting as hinges. The only maintenance required for the mouse is to occasionally remove the ball (approximately 22 cm in diameter), wash it in soapy water, rinse, dry, and reinstall. The additional functions ordered by the customer for the new mouse design were incorporated by adding one key and one switch, and expanding the printed circuit. These additions, of course, required engineering change orders (ECOs) to modify the company's existing mouse design.

After the team was satisfied that their designs for manufacturing parts of the mouse were optimum, they concentrated their efforts on design of the parts for assembly (DFA).

Design for Assembly (DFA)

The *DFA procedure* is an iterative loop that occurs simultaneously with the DFM loop, Figure 17-18, but the emphasis is on assembly of parts vis-à-vis the

design and manufacturing of parts. The team has similar goals in the DFA loop—develop the best design of parts for assembly of the mouse, at the least cost, within a reasonable time, and ensure its function. They follow the DFA loop shown: first, consider which parts should be assembled automatically, and second, consider which parts need to be assembled manually.

DFA Guidelines

A partial list of DFA guidelines from DFA literature is as follows:

- Use pick-and-place robots for simple, routine placement of parts.
- Keep the number of parts to a minimum (DFM guideline, also).
- Use gravity and vibration for moving parts into assembly areas.
- Avoid parts that tangle (hang up on each other).
- Use tapers and chamfers to guide parts into position.
- Avoid time-consuming manual operations such as screwdriving, soldering, and riveting.

Use Robots for Simple Operations

Robots can be programmed to pick electronic components off a conveyor or from a feeder and place them accurately into a circuit board for the mouse. A mouse may require 25 to 50 electronic components, depending on the basic functions it is to perform.

Minimize the Number of Parts

Combine several components into one molded part, *Figure 17-25.*



FIGURE 17-25 *Combine several parts into one.*

Move and Orient Parts using Gravity and Vibration

Figure 17-26 shows one method of orientating spacers and steps to avoid tangling of lock washers and tangling of rivets.

Use Tapers and Chamfers for Positioning

An example of tapered fasteners and a receptacle with a tapered hole, both for ease of assembly, are shown in *Figure 17-27.*

Avoid Time-Consuming Operations

The snap locks in the body shown in Figure 17-22 allow for quick assembly and accurate positioning of the circuit board.

Finally, after the DFA team members agree on the best designs for manufacturability and the best designs for assembly for the new mouse, and the DFM team concludes its optimization efforts, costs for producing the new mouse are checked. If the cost



FIGURE 17-26 *Spacers handling and anti-tangling techniques.*

Industry Application

Mark and John are about the same age. They graduated from the same technical college at the same time and both went to work for the same company. Both were excellent students, and both have done well on the job. But Mark just beat John in an internal competition for a team leader position. As a result, Mark now earns more than John, has a new office, and is on the fast track for future promotions.

When the time came to select a new team leader, the difference between Mark and John could be stated in just three words: "design for manufacturability." Mark was a proponent of DFM who had proven he was adept at applying its principles. In fact, he always referred to the manufacturing personnel who would use his drawings as his customers. Mark was often seen on the shop floor talking with manufacturing personnel and observing their processes. Over and over Mark could be heard asking shop floor personnel the same questions: "What can I do to make our products easier to manufacture?" As a result, Mark had become a skilled practitioner of the art and science of design for manufacturability or DFM.

John, on the other hand, never visited the shop floor unless it was absolutely necessary. To him the shop floor was a dirty place best avoided. John's attitude can be seen in one of his favorite statements: "I am a designer, not a machinist. If I wanted to know about machining, I would have majored in shop." John's mistake was to view design and drafting as an island that stands by itself rather than as a part of a larger process that includes design, manufacturing, and all of the other activities necessary to convert an idea into a product that can succeed in the marketplace.

Mark's first decision as a new team leader was to include manufacturing personnel on his team. He wanted to eliminate the "us-against-them" mentality that can grow between design and manufacturing so that his team's designs would be not just functional but also manufacturable.



FIGURE 17-27 *Tapered fasteners and a tapered hole for ease of assembly.*

analysis results in further modifications, sketches and layout drawings may be prepared and ECOs may be issued. To continue the design procedure, the new mouse design is formally released. Designers and drafters prepare working drawings. Eventually, all the drawings are released to manufacturing supervisors who have anticipated the drawings because they had worked closely with the design teams during the development of the new mouse design.

As the new mouse goes into production, the personnel of the mass production company realize that even a small savings in cost resulting from following DFM and DFA guidelines is worthwhile when millions of units are involved. Moreover, the company finds that following the guidelines not only results in cost savings but also improves the design and function of products.

Personal Technical File

During the various design and development activities, each engineer, designer, detailer, checker, technical writer, and illustrator should develop and maintain a technical file to enhance his or her involvement in the company. The objective is to minimize the time spent locating technical information pertinent to their respective jobs. Usually a company manufactures products and performs engineering in specific areas of technology, so files can be concentrated in these areas for efficient retrieval of information. An efficient technical filing system uses an alphabetical-numerical scheme. For example, the first part of a filing scheme for a drafter-designer in a company specializing in conveyors would be an alphabetical listing of technical topics with numerical references. This file should be kept in a three-ringed binder or a computer

so that additional information can be added easily. Example entries would be:

Section A			
Aluminum Products	112	Channel Sections	134
ANSI Standards	410	Conveyors	500
Section B		Codes and Standards	410
Bar Stock	132	Controls	210
Beams	133	*Section D*	
Belt Conveyors	510	Drives	600
Belt Materials	122	*Section E*	
Bucket Elevators	530	Electrical Components	200
Section C		Controls	210
Castings	140	Switches	230
Chain Conveyors	520	And so on . . .	

The numerical part of the file, kept in a file cabinet, would contain tab-numbered dividers, numbered folders, and numbered materials in the folders. Example tabs, folders, and materials would be numbered as follows. (The letters in parentheses are for discussion purposes only: T = Tab number for a divider, F = Folder number, and M = Material labeled with a number.)

100 Engineering Materials	(T)
110 Metals	(F)
111 Ferrous Based	(M)
112 Aluminum	(M)
120 Nonmetals	(F)
121 Ceramics	(M)
122 Rubber (belts)	(M)
130 Structural Shapes	(F)
131 Angles	(M)
132 Bar Stock	(M)
133 Beams	(M)
134 Channels	(M)
200 Electrical Components	(T)
210 Controls	(F)
220 Motors	(F)
221 AC Motors	(M)
222 DC Motors	(M)
230 Switches	(F)
300 Materials Handling	(T)
310 Solid Waste	(F)
400 Codes and Standards	(T)
410 ANCI Standards	(F)
411 ANSI Y14.5M–1982	(M)
500 Conveyors	(T)
510 Belt	(F)
520 Chain	(F)
530 Bucket	(F)
600 Drives	(T)
610 Gear Box	(F)
620 Roller Chain and Sprockets	(F)
630 V-Belt and Pulleys	(F)
And so on . . .	

Start a technical file now, as a student, and expand it later, to suit your technical jobs in industry.

In addition to your personal file, when you are working in a design section, the section usually has an extensive vendor-catalog library and related references. There will most likely be a *Thomas Register* set (lists of vendors, their products, and addresses) and a set of ANSI (American National Standards Institute) standards related to your company's products. The vendor catalog collection would cover components such as the following:

- Bearings
- Belts
- Brakes
- Cams
- Clutches
- Controls
- Couplings
- Fasteners
- Gears
- Hydraulic power (liquid)
- Hydraulic power (pneumatic)
- Jigs and fixtures
- Keys and pins
- Lubricants
- Motors
- O-rings
- Piping lumber
- Plastics
- Programmable logic circuits
- Pulleys
- Pumps
- Reducers
- Retaining rings
- Roller chain
- Sprockets
- Structural steel and aluminum
- Shafts
- Switches
- Tools

Occasionally, a drafter, designer, or engineer may be required by an employer to keep a bound-page notebook for patent development. The pages are bound together, numbered, and each one signed by the individual inventor. Also, each page needs to be signed by at least two witnesses who understand the area of technology of the potential patent. Furthermore, the individual inventor may be required to sign an invention agreement.

Invention Agreement

Anyone who is creative and working for a company, such as a drafter, designer, or engineer, usually must sign an *invention agreement* form giving the company the right to any new invention designed while one is working for the company. The form specifies that the employee will not reveal any of the company's discoveries or projects. The invention agreement is binding on the employee from six months to two years after the employee leaves the company, so that employees will not invent something, quit, and patent the invention themselves.

A company is not obligated to, so it usually does not give extra pay for an invention developed by an employee. This is what the employee is paid to do.



FIGURE 17-28 *Patent drawing.* (Courtesy Timex Corp.)

However, companies recognize talent and will reward that talent with a promotion, stocks, bonds, or possibly a raise. Signing an employee/employer invention agreement is a normal request in any company. Of course, prospective employees should read the agreement carefully and understand it before signing. An applicant who refuses to sign the agreement may be asked to look elsewhere for employment.

Patent Drawings

All patent applications for a new idea or an invention must include a *patent drawing* to illustrate and explain its function. Patent drawings must be mechanically correct and must adhere to strict patent drawing regulations, ***Figure 17-28.*** For example, patent drawings are more pictorial and explanatory than regular detail or assembly drawings. Center lines, dimensions, and notes are omitted. All features and parts are identified by numbers that refer to written explanations and descriptions. Line shading is used to improve readability.

All patent drawings must be made so that they reproduce clearly, which essentially means that the drawings must be done in ink. Current requirements specify that India ink or its equivalent be used, and that the drawings be done on strong, white paper, 8½ × 13″ (21.6 × 33.1 cm) or 8½ × 14″ (21.6 × 35.6 cm). A precise "sight" area (20.3 × 29.8 cm) must be used for the drawing itself on the strong, white paper. (For further requirements, refer to 37 *CFR* Ch 1 7-1-91 edition.) The publication *A Guide for Patent Drawings* may be obtained from the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.

Summary

- A typical engineering department has three sections: design, application, and quotation. The design procedure used in industry and the basis for establishing the selling price of a system or product should be understood by design and drafting students.
- Technical drawing types used in industry include freehand sketches, layout drawings, detail drawings, and assembly drawings. Fold lines are seldom included on technical drawings in industry. Procedures for handling ECRs and ECOs on drawings should be understood by design and drafting students.
- Students should understand mass production and the role of DFM and DFA in the manufacturing process in a mass production company. Design for manufacturability (DFM) involves considering both function and production during the design process. Design for assembly (DFA) requires the consideration of both function and the assembly process.

Review Questions

Answer the following questions either true or false.

1. The application engineering section typically handles special-order modifications of existing products.

2. The only members of the design team should be designers and drafters.
3. Producing computer mouse units is an example of a one-of-a-kind system.
4. RFP stands for request for proposal.
5. In a layout drawing, a freehand sketch is redrawn to scale.
6. A design procedure acts as a general guideline for the design team.
7. Conceptual design is based on materials science, chemistry, and mathematics.
8. Any product that has more than two parts requires an assembly drawing.
9. A company uses purchased parts made by another company because it is cheaper.
10. The numbering system for identifying and recording technical drawings is standardized and used throughout the United States.

Answer the following questions by selecting the best answer.

1. The two types of illustrative material used by a systems company to help a customer visualize the overall system are:
   a. assembly and detail
   b. working and assembly
   c. perspective and scale model
   d. assembly and subassembly
2. Which of the following is **not** part of the information usually included in a title block?
   a. material the part is to be made of
   b. tolerances/limits of dimensions
   c. part or drawing number
   d. reference numbers of subassembly drawings
3. Which of the following is **not** true regarding checking drawings?
   a. Slight errors can cause large expenses.
   b. A good drafter thoroughly inspects his/her own drawings once completed.
   c. If the drafter does a thorough inspection of his/her own drawing, it is not necessary to send it to the checker.
   d. Every precaution should be taken to avoid errors.
4. Which of the following is **not** true regarding drawing revisions?
   a. A drawing can be modified once an ECR is signed and submitted.
   b. All departments concerned must agree to the change.
   c. A drafter can change his/her own drawing after it has been released and signed off.
   d. Minor changes to drawings could be simple erasures or additions made directly on the original.
5. Which of the following would be part of preparing a selling price?
   a. engineering materials
   b. basic labor (direct labor)
   c. profit
   d. all of the above
6. Which of the following is **not** part of a typical boiler plate?
   a. introductory comments
   b. descriptions of past systems designed/installed
   c. an invention agreement for signature
   d. a legal section
7. Which of the following is **not** a guideline from DFM literature?
   a. Minimize number of parts.
   b. Minimize multifunctional parts.
   c. Minimize part variation.
   d. Minimize number of flexible parts.
8. Which of the following is **not** true regarding a mass production company?
   a. Its approach to producing a product would be different than a one-of-a-kind system.
   b. Their internal departments would work together more closely than those in a one-of-a-kind system.
   c. Their internal departments would work together less closely than those in a one-of-a-kind system.
   d. None of the above.

Chapter 17 Problems

The major drawings that were illustrated and emphasized in this chapter included freehand sketches, layout, detail, and assembly drawings, the types of drawings used in industry to develop a product. Two completed sets of these drawings are included here for your information and guidance. Then, the problems for Chapter 17 follow.

EXAMPLE NUMBERS 17-1-1 THROUGH 17-1-6 (SUBASSEMBLY NOT REQUIRED)

Objective: Design a hold-down clamp that:

1. bolts through a 3.4" thick worktable and clamps materials 1" to 1½" thick.
2. stays in "open" (up) position when not clamping.



EX 17-1-1 *Freehand sketch of hold-down clamp.*



EX 17-1-2 *Layout drawing of hold-down clamp.*



EX 17-1-3 *Detail drawing of clamp bar.*



EX 17-1-4 *Detail drawing of spring sleeve.*



EX 17-1-5 *Assembly drawing of hold-down clamp.*

				.08" OD, FREE HT 1 1/4"
				.08" Ø5 COILS, PLAIN ENDS
	1		4	SPRING: HARD DRAWN SPRING STEEL WIRE RH
	1		3	SPRING SLEEVE DWG EX1-2
	1		2	CLAMP BAR DWG EX1-1
	1		1	HEX HEAD BOLT 1/2" DIA X 3 1/4" LG. HEX NUT
	QTY REQD	FSCM NO.	PART OR IDENTIFYING NO.	NOMENCLATURE OR DESCRIPTION / MATERIAL SPECIFICATION

PARTS LIST

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES ARE: FRACTIONS ± DECIMALS .XX ± .XXX ± ANGLES ±	CONTRACT NO		
MATERIAL	APPROVALS	DATE	ASSEMBLY HOLD DOWN CLAMP
	DRAWN		
FINISH	CHECKED		SIZE A / FSCM NO. / DWG. NO. EX1-3 / REV.
DO NOT SCALE DRAWING	ISSUED		SCALE / SHEET 2 OF 2

EX 17-1-6 *Parts list for hold-down clamp.*

EXAMPLE NUMBERS 17-2-1 THROUGH 17-2-8 (SUBASSEMBLY REQUIRED)

Objective: Design an articulated parallelogram, approximately 7″ long and 2″ wide, made of brass, which:

1. will maintain parallelism between two end members of the device and provide space in the end members for the customer's machining.
2. uses ball bearings at the pivot points and uses retaining rings for the pivot pins.

NOTE: Articulated parallelograms are used in pick-and-place robots and in goniometers (devices to measure angular displacements of knee joints).



EX 17-2-1 *Freehand sketch of articulated parallelogram.*



EX 17-2-2 *Layout drawing of articulated parallelogram.*



EX 17-2-3 *Subassembly detail drawing of linkage.*



EX 17-2-4 *Detail drawing of pivot pin.*



EX 17-2-5 *Detail drawing of end block.*



EX 17-2-6 *Assembly drawing of articulated parallelogram.*

	QTY REQD	FSCM NO.	PART OR IDENTIFYING NO.	NOMENCLATURE OR DESCRIPTION	MATERIAL SPECIFICATION
	8		4	RETAINING RING	PIC Z3-3
	4		3	PIVOT PIN	DWG EX2-2
	2		2	END BLOCK	DWG EX2-3
	2		1	LINKAGE	DWG EX2-1

PARTS LIST

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES
TOLERANCES ARE
FRACTIONS ± DECIMALS .XX ± .XXX ± ANGLES ±

MATERIAL

FINISH

DO NOT SCALE DRAWING

CONTRACT NO

APPROVALS	DATE
DRAWN	
CHECKED	
ISSUED	

ASSEMBLY
PARALLELOGRAM

SIZE A | FSCM NO. | DWG. NO. EX2-4 | REV.

SCALE | SHEET 2 OF 2

EX 17-2-7 *Parts list for articulated parallelogram.*



	QTY REQD	FSCM NO.	PART OR IDENTIFYING NO.	NOMENCLATURE OR DESCRIPTION	MATERIAL SPECIFICATION

PARTS LIST

UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES
TOLERANCES ARE
FRACTIONS ± DECIMALS .XX ± .XXX ± ANGLES ±

MATERIAL

FINISH

DO NOT SCALE DRAWING

CONTRACT NO

APPROVALS	DATE
DRAWN	
CHECKED	
ISSUED	

ASSEMBLY
PARALLELOGRAM

SIZE A | FSCM NO. | DWG. NO. EX2-4A | REV.

SCALE | SHEET 1 OF 1

EX 17-2-8 *Exploded assembly drawing of articulated parallelogram (an alternative type of assembly drawing).*

Unless otherwise directed, do the problems following the steps indicated using traditional technical drawing instruments or a CAD system as assigned.

Conventional Instructions

STEP 1 Prepare a freehand sketch(es) of the device or component to be designed or changed. Refer to Figure 17-4, Example 17-1-1, and Example 17-2-2 for example freehand sketches.

STEP 2 Prepare a layout drawing(s) of the freehand sketch(es) from Step 1. Refer to Figure 17-5, Example 17-2-1, and Example 17-2-2 for example layout drawings.

STEP 3 Prepare the necessary detail drawings of each component of the device, one component per drawing. Refer to Figure 17-10, Figure 17-11, Example 17-1-3, Example 17-1-4, Example 17-2-4, and Example 17-2-5 for examples. Include required fits and tolerances as required.

STEP 4 Prepare a subassembly drawing if needed. Refer to Figure 17-9 and Example 17-2-3 for example subassembly drawings.

STEP 5 Prepare the final assembly drawing with the appropriate parts list. Refer to Figure 17-7 for a Method A assembly drawing, and to Figure 17-8 for a Method B drawing. Also refer to Example 17-1-5, Example 17-1-6, Example 17-2-6, and Example 17-2-7 for final assembly drawings with parts lists on separate sheets. Example 17-2-8 is an example of an exploded assembly drawing.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

PROBLEM 17-1

Prepare a freehand sketch of a step stand, two levels, for general use in homes, institutions (libraries, schools, etc.), and business offices. Use black anodized aluminum sheet and structural angles. Use any combination of 1 × 1 × ⅛, 1½ × 1½ × ⅛, or 2 × 2 × ⅛ angles and assume bolted construction.

PROBLEM 17-2

The winch shown is to be used to pull boats up a ramp, and it needs a support base so it can be mounted on a horizontal wooden platform 1″ thick and about 4′ high.

a. Prepare a freehand sketch of the support base.

b. Prepare a layout drawing of your support base.



PROBLEM 17-3

Prepare a freehand sketch of a dolly approximately 2′ × 3′ using two fixed and two swivel casters. Fasteners should not project above the top surface. A convenient means to hand-carry the dolly should be provided.

Prepare layout, detail, and assembly drawings as assigned.



PROBLEM 17-4

The torque wrench shown in the freehand sketch needs to be developed further and sent on to be manufactured in the shop.

a. Prepare a layout drawing of the torque wrench.
b. Prepare detail drawings of the torque wrench.
c. Prepare an assembly drawing and parts list for the torque wrench.



PROBLEM 17-5

The clamp shown in the freehand sketch needs to be developed further and sent on to be manufactured in the shop.

a. Prepare a layout drawing of the clamp.
b. Prepare detail drawings of the clamp.
c. Prepare an assembly drawing and a parts list for the clamp.



PROBLEM 17-6

GIVEN: A layout drawing of adjustable dividers. Prepare detail and assembly drawings as assigned.



PROBLEM 17-7

GIVEN: A layout drawing of a wood shop clamp. Prepare detail and assembly drawings as assigned.



PROBLEM 17-8

Conceptual views of a toggle clamp are shown in the freehand sketches. When pivot B on the toggle clamp arm ABT passes below the line of centers between A and C, the pressure at P causes the elastic head to compress. Then B is "locked" in position and the object under the elastic head at P is clamped securely. A typical compression distance is approximately 1.5 mm. The adjustments at E accommodate different sizes of objects.

a. From the information given, prepare a layout drawing to establish the remaining dimensions of the components, the pivot point locations, and the bolt hole locations.

b. Prepare detail drawings of the components.

c. Prepare an assembly drawing and parts list for the toggle clamp.



PROBLEM 17-9

GIVEN: A layout drawing of a jack. Prepare detail and assembly drawings as assigned.



PROBLEM 17-10

GIVEN: A layout drawing of an adjustable compass. Prepare detail and assembly drawings as assigned.



PROBLEM 17-11

Limit switches, which are basically electrical on-off switches, limit the travel of machine parts, act as interlocks, and indicate positions of devices. For example, the machines in the photographs in Chapter 20 use limit switches to limit travel. Limit switches activated by open doors prevent an elevator from moving. Positions of remote devices in hostile environments, such as control rods in nuclear reactors, are indicated safely by limit switches. Rotating antennas can be stopped at preset positions by limit switches to keep wires from tangling.

Use information in the figure to do a layout drawing to determine the dimensions of an actuating shoe that would cause the limit switch to operate and stop the rotation of the antenna. Also, do a layout drawing of the support plate for the actuating shoe. Include a hub and set screw. Hub diameters may average approximately 2 times shaft diameters and are about 2 times shaft diameters long. The hub is to be welded to the support plate. Use low-carbon steel. (Refer to Table 47 in Appendix A.)



CONCEPTUAL SKETCH OF ANTENNA AND DRIVE



PROBLEM 17-12

An air-actuated cylinder is to be used to bend a specimen in a fatigue test apparatus.

The air cylinder and the specimen are shown in the partially completed layout drawing. You are to devise a means to support the cylinder and the specimen and to provide adjustments as indicated.

a. Complete the layout drawing with a design that provides the support and adjustments.

b. Prepare detail drawings of your design.

c. Prepare an assembly drawing with a parts list of your design. When you draw the cylinder in the assembly drawing, use phantom lines. Purchased parts such as motors, reducers, generators, and cylinders often are drawn with phantom lines.



PROBLEM 17-13

GIVEN: A layout drawing of an adjustable lifting clamp. Prepare detail and assembly drawings as assigned.



PROBLEM 17-14

GIVEN: A layout drawing of a lever-controlled valve. Prepare detail and assembly drawings as assigned.



PROBLEM 17-15

A hand-powered winch is shown in the isometric sketch. Using the information in the freehand sketches of the components of the winch, 17-15A through 17-15H:

a. Prepare detail drawings of each component. (Note that layout drawings are omitted in this exercise due to the completeness of the freehand sketches. Discrepancies, if any, will be found while doing the final assembly drawing.)

b. Prepare subassembly drawings of the drum 17-15B and the handle 17-15H.

c. Prepare a final assembly drawing with a parts list for the winch.





Drum Gear (A)



Cast Al Drum



Bushing for Drum 2 Reqd (B)

PROBLEM 17-15 (continued)



Drum Shaft
(C)



Pinion Gear
(D)



Pawl 5/16 Plate
(Refer to 4 for Gear.)
(E)



Pawl Shoulder Bolt
Steel
(F)





Cast Aluminum Base
6061 T6
(G)



Winch Handle



Aluminum Handle
6061-T6
(H)

PROBLEM 17-16

The corrosion bath shown is rocked back and forth by an arm that is coupled to a variable-speed drive mechanism. Corrosive liquid is sloshed over the test specimens. The equipment was originally built by a skilled mechanic from sketches that have been misplaced or destroyed. Detail and assembly drawings of this testing equipment are needed by another company to build their own bath. From the information given in the sketches, do the following:

a. Prepare a layout drawing of the bath equipment.
b. Prepare detail drawings of the components.
c. Prepare subassembly drawings of the shaft *A* supports and the container for the plastic bath.
d. Prepare an assembly drawing with a parts list for the bath equipment.







PROBLEM 17-17

Using detail drawings 17-17A through 17- 17O, prepare a 3-view assembly drawing and a parts list. Also, the following is a summary of the FITS specified for the various components. (Calculate these and show your work.)

(1) FN-1/1.062 Parts 1, 12
(2) FN-2/.688 Parts 1, 2
(3) LC-4/1.5 Parts 1, 11
(4) RC-5/.562 Parts 3, 4
(5) RC-5/.375 Parts 4, 5
(6) LC-2/.125 Parts 4, 8
(7) FN-2/.250 Parts 9, 14
(8) RC-6/.938 Parts 13, 14, 15



NO. 1 CRANKCASE
ALUMINUM ALLOY

(A)



NO. 2 BUSHING CRANKCASE
LEADED BRONZE

(B)



NO. 3 CRANKCASE SUBASSEMBLY
MAT'L AS NOTED

(C)

PROBLEM 17-17 (*continued*)



NO. 4 CRANKSHAFT
AISI 1040 STEEL

(D)



NO. 5 ROD-CONNECTING
ALUMINUM ALLOY 7075-T6

(E)



NO. 7 SPINNER
ALUMINUM ALLOY

(G)



NO. 6 DRIVE WASHER
AISI C1018 STEEL

(F)



NO. 8 PIN-DRIVE WASHER
1010 STEEL

(H)



NO. 9 PIN PISTON
1010 STEEL

(I)



NO. 10 SPACER-PISTON
BRASS

(J)

PROBLEM 17-17 (*continued*)



NO. 11 BACKPLATE
CAST ALUMINUM

(K)



NO. 12 FINS-CYLINDER
ALUMINUM ALLOY

(L)



NO. 14 PISTON
DUCTILE IRON

(N)



NO.13 SLEEVE-CYLINDER
DUCTILE IRON

(M)



NO. 15 HEAD CYLINDER
ALLUMINUM ALLOY

(O)

PROBLEM 17-18: REVERSE ENGINEERING

Reverse engineering basically involves:

1. "taking apart" a manufactured device and
2. analyzing each component of the device for design features, size, materials, function, manufacturing processes, and any other factors such as aesthetics, color, and surface finishes.

Valuable insights can be learned from the exercise of "working backwards" as compared to "working forward."

1. Select or be assigned one of the following to be "taken apart" and analyzed as described above:
   - **a.** component(s) from an electronic product such as a hand calculator, a printing calculator, a VCR, a TV, a light switch, or a timer (Note that electronic repair shops are excellent sources of discarded products.)
   - **b.** automotive devices
   - **c.** appliances
   - **d.** exercise and sports equipment
   - **e.** hardware stores
2. Prepare a freehand sketch of the component selected or assigned, and list the design features, size, material(s), function, and other properties.

PROBLEM 17-19

Assume that you are a designer-drafter employed by a large company that designs and produces yard tools for average homeowners. Your company has received a request for a bid on 100,000 wheelbarrows, of approximately a 5 cubic foot capacity. You are given a freehand sketch of a wheelbarrow to more accurately determine dimensions, sizes, and the buyout requirements (fasteners and the wheel).

Assume that the time constraints require that you must establish a selling price for the wheelbarrow because your company's quotation department must meet a major deadline on another project. An approximate method of quickly setting a selling price is to calculate a "price-per-pound" of existing wheelbarrows already on the market. Then multiply the weight of your wheelbarrow design times the price per pound for an approximate selling price.

You may need to visit a hardware store to obtain data or find an appropriate catalog. One of your colleagues said that his wheelbarrow was approximately $2 per pound.

Time is a constraint so:

- **a.** Prepare a layout drawing of the wheelbarrow and estimate its weight.
- **b.** Calculate a price per pound of existing wheelbarrows and establish an approximate selling price.
- **c.** Prepare an assembly drawing with a parts list for the wheelbarrow.



PROBLEM 17-20

Attribute listing is similar to reverse engineering, but not as comprehensive. (An explanation of the attribute listing technique is in Chapter 24. A relatively simple example of attribute documenting of a caster is shown in the drawing.) Problem 17-20 combines the attribute listing procedure with technical drawings.

Find a music stand (or an object assigned by your instructor) and do the following:

a. Measure the components of the stand, note the materials used, determine the manufacturing processes, list the function(s) of the stand, and comment on any other facets such as color, weight, and stability. Prepare freehand sketches of the components. Incorporate any design changes you deem appropriate.

b. Prepare layout drawings of your freehand sketches, especially if you recommend changes.

c. Prepare detail drawings of the components.

d. Prepare subassembly and assembly drawings as needed.



PROBLEM 17-21

The angle stop shown in the drawing is to be changed according to ECO Number C159, originated by GNC on Sept. 11, and justified because of a new model of anchor-bolt puller to be manufactured. The description of change on a typical ECO form indicates that the 210 mm dimension changes to 250 and the holes change from a diameter of 13 to 19. An ECO committee determined that the change was necessary and that the change would not affect performance, reliability, or safety. Each member of the committee signed off the ECO (see Figure 17-13). Make a machine copy of the drawing as it is shown. Make the changes. (Refer to Figure 17-14.) Record the changes in the revisions block (upper right-hand corner).



PROBLEM 17-22

An engineering change request (ECR) involving the articulated parallelogram in Example 17-2-1 (page 634) has evolved into an engineering change order (ECO). The device is to be modified as follows:

1. Replace the ball bearings in the linkages with bronze bushings.
2. Use aluminum 6061-T6 instead of brass for the linkages and the end blocks.
   - **a.** Prepare a layout drawing for the changes.
   - **b.** Prepare detail drawings of the new design.
   - **c.** Prepare an assembly drawing with a parts list for the new design.



PROBLEM 17-23

Use the five steps listed on page 639 to incorporate an ECO that requires that ball bearings replace the sliding bearings, Part #4.



PROBLEM 17-24

Follow the five steps listed on page 639 to develop the puller shown. For this problem, use the information from Figures 17-7 and 17-8 to prepare freehand sketches for each part. Assume an overall length of 9″ for the assembly of the yoke, the screw-center, and the hooks. Make the yoke and hooks of medium carbon steel, AISI 1045. (Refer to Table 47 in Appendix A.) Make the hooks at least ¼″ thick, and use ½″-20UNF threads or larger for the screw-center.



MUST INCLUDE: **DRAWING NUMBER**
TITLE
NUMBER REQUIRED PER ASSEMBLY

NO.	DRAWING NO.	ITEM	REQ'D
–	–	1/4-20 UNC	–
5	PURCH	LOCK NUT-HEX	2
–	–	1/4-20 UNC X 1 1/2 LG.	–
4	PURCH	SCREW-CAP HEX HD	2
3	A 661982	HOOK	2
2	A 661981	SCREW-CENTER	1
1	A 661983	YOKE	1

PROBLEM 17-25

The pressure transducer shown indicates pressure by the distortion of the piezoelectric crystal that generates a voltage proportional to the distortion. A digital voltmeter is used to read the voltage. Assembly of the transducer could be simplified if the tubular spacer were part of the hex-shaped fitting with the ½″-UNF threads. Prepare a freehand sketch of your idea to simplify the assembly, and follow the five steps listed on page 656 to develop the transducer. The crystal is a purchased item. Use stainless steel. (Refer to Table 47 in Appendix A.)



PROBLEM 17-26

Manufacturing and assembly of the adjustable roller support shown could be improved upon. Prepare a freehand sketch of your idea for improvement and then follow the five steps listed on page 639 to develop the adjustable roller support. Note that slotted holes are used frequently for adjustments.



PROBLEM 17-27

Start your own technical file by selecting manufacturing catalogs that list products in areas of your interests. Label the catalogs with "100" numbers like the listings in this chapter in the section on Technical Files. Select at least 10 catalogs as a beginning.

As a suggestion, visit one or more of the following locations where you would most likely find a library of catalogs to help start your list: your own drafting classroom, an engineering library, maintenance shops on your campus, or local manufacturing firms.

PROBLEM 17-28

Drawings for patents of mechanical devices must clearly depict the assembly and function of the devices. Peruse a collection of patents or patent gazettes and list the patents with comments on the different types of drawings used to communicate information. List at least 10 patents (patent number, date, and a brief description of the device). Suggestion: librarians cannot only help you find the patents but can help you find patents in your areas of technical interest.

18

Pictorial Drawings

KEY TERMS

Cabinet drawing
Cavalier drawing
Dimetric drawing
Exploded isometric drawing
General oblique drawing
Isometric assembly
Isometric drawing
Isometric projection
Nonisometric line
Oblique drawing
Offset measurement
Perspective drawing
Trimetric drawing

CHAPTER OUTLINE

Purpose of pictorial drawings • Oblique drawings • Isometric drawings • Axonometric: drawing and projection • Other oblique drawings • Perspective drawings • Summary • Review questions • Chapter 18 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the purpose of pictorial drawings.
- Demonstrate proficiency in developing oblique drawings, including cavalier and cabinet.
- Demonstrate proficiency in developing isometric drawings, including diametric and trimetric.
- Demonstrate proficiency in drawing circles, curves, and irregular shapes in isometric and on flat and inclined surfaces.
- Demonstrate proficiency in developing one-, two-, and three-point perspective drawings.

Purpose of Pictorial Drawings

Pictorial drawings facilitate the communication of technical information during all phases of the design process—from early sketching of product ideas for future uses, to talking through concepts with colleagues, and finally, to the more formal pictorial drawings (for selling products, maintenance manuals, catalogs, assembly instructions, etc.). This chapter begins with the three most common types of pictorial drawings used by drafters, designers, and engineers—oblique, isometric, and perspective. Sketching these three types was introduced in Chapter 3.

After the discussion of oblique, isometric, and perspective drawings, more complete discussions will follow on additional types of pictorial drawings and projections.

Oblique Drawings

Oblique drawing is the easiest of the three to draw. In oblique drawing, one surface of the object, usually the front view, is drawn exactly as it would appear in a multiview drawing. Circles are true circles, and rectangles parallel to the frontal plane are in true size, *Figure 18-1*. Circles are drawn with a compass or circle template, and rectangles have square corners.

Constructing Oblique Drawings

Oblique drawings use three axes: two at right angles (for example, X and Y in Figure 18-1) and one, the Z axis, usually at an angle of the convenient 30° or 45° standard triangle. Measurements are taken from the multiview drawing; X and Y dimensions match those in front views, and Z dimensions, depth, are laid off parallel to the third axis.



FIGURE 18-1 *Axes for oblique drawings.*



FIGURE 18-2 *Advantages of oblique.*

Cylinders, Angles, and Curves in Oblique Drawings

Figure 18-2 has further illustrations of the primary advantages of oblique drawings, especially starting with the front view. Cylinders are round, angles are in true size, and irregular curves are not distorted.

Isometric Drawings

Isometric drawings are the most used of the three common pictorials. They are easier to draw than perspective drawings and they illustrate objects almost as well as perspective drawings.

Isometric drawings use three axes, sometimes called principal edges, at 120° to each other, *Figure 18-3*.

How to Make an Isometric Drawing

GIVEN: A multiview drawing of an object, *Figure 18-4A*.

STEP 1 Locate the starting point and lightly draw the three principal edges at 120° using a 30°–60° triangle, *Figure 18-4B*.

STEP 2 Transfer the depth, height, and width directly from the multiview drawing, *Figure 18-4C*, to the three principal edges. Measure full size directly along each edge. Lightly construct an isometric, basic outline, or "box," of the object, Figure 18-4C.

STEP 3 Transfer true-size lengths, lengths parallel to the principal axes, from the various features of the object, *Figure 18-4D*.

STEP 4 Check all lines, correct if necessary, and darken in the object using correct line thickness, *Figure 18-4E*.



FIGURE 18-3 *Isometric principles.*





FIGURE 18-4 *(A) How to draw an isometric drawing; (B) Step 1.*



FIGURE 18-4 *(Continued) (C) Step 2; (D) Step 3; (E) Completed isometric view.*

How to Center an Isometric Object

Save time in locating isometric drawings in or near the center of a drawing space by following these steps.

GIVEN: A multiview of an object, *Figure 18-5A.*

STEP 1 Locate the center point of the work area and do the following: go North ½ H, go S60°W a distance of ½ D, and go S60° E, ½ W to establish a starting point, *Figure 18-5B.*



FIGURE 18-5 *(A) Centering an isometric view within the work area.*

STEP 2 From the starting point, draw the basic shape of the object, *Figure 18-5C*.

STEP 3 Construct the object within the basic shape, *Figure 18-5D*.



(B)



(C)



(D)

FIGURE 18-5 *(Continued) (B) Step 1; (C) Step 2; (D) Completed isometric view.*

Offset Measurements

Offset measurements are used to locate one feature in relationship to another. Measure offsets parallel or perpendicular to one of the three standard planes—frontal, top, or profile—from the multiview of the object being drawn, *Figure 18-6A*.

Develop the isometric drawing as before; first, the basic shape or "box" with dimensions W, D, and H, and then, the offset measurements A, B, and C parallel or perpendicular to the frontal, top, or profile planes, *Figure 18-6B*. Note lines that are truly parallel in the multiview drawing must be parallel in the isometric drawing.



(A)





(B)

FIGURE 18-6 *(A) Multiview projection; (B) Offset measurements.*

Nonisometric Lines

If a line is not parallel or perpendicular to any of the three principal edges in an isometric drawing, it is a *nonisometric line*. *Figure 18-7A* shows a multiview drawing of an object with a 30° inclined surface, labeled as shown with a, b, a′, and b′.

Construct the isometric drawing as before; "box" first, then the feature using the X and Y dimensions, and finally, heavy in the lines of the object, *Figure 18-7B*. Line a-b is not in the true length, and the 30° angle is distorted.

Box Construction for Irregular Objects

Some objects, *Figure 18-8A*, have lines that do not line up with the isometric axes, so use a box or basic shape to establish offset dimensions for drawing the object, *Figure 18-8B*.



FIGURE 18-7 *(A) Nonisometric lines; (B) Locating points.*

Next, draw an isometric box, *Figure 18-8C*. Locate key points of the object using offset measurements, *Figure 18-8D*. Finish the object, *Figure 18-8E*.



FIGURE 18-8 *(A) Box construction; (B) Basic shape; (C) Isometric basic shape; (D) Locating points of object.*



ISOMETRIC VIEW

(E)

FIGURE 18-8 *(Continued) (E) Isometric view completed.*

Hidden Lines

Hidden lines are not used in isometric drawings unless needed to show an important feature that otherwise would not be seen. Try to orient objects so hidden lines are not needed, not only in isometric drawings, but in all pictorials.

Isometric Curves

Construct isometric curves in isometric drawings using offsets or a grid. For a series of offset distances, use a number of evenly spaced lines, all parallel to one of the principal edges, ***Figure 18-9A***. Transfer these lines to the isometric layout and transfer each distance, respectively, to locate points on the curve, ***Figure 18-9B***. Give depth to the drawing by projecting D distances at 30°, which is parallel to an isometric axis, from each point on the curve. Use a French curve to connect the points.

For transferring a curve using a grid, choose a grid spacing that will give a sufficient number of points along the curve to give as much detail of the curve as needed, ***Figure 18-10A***.

Construct the basic shape of the object using the W, H, and D dimensions. Transfer the grid, ***Figure 18-10B***. Finally, transfer the irregular curve, square by square. Use a French curve to connect the points on the curve.

Irregularly Shaped Objects

Transfer and draw irregularly shaped objects by dividing the object into a series of convenient sections.



FIGURE 18-9A *Drawing an isometric curve (offset method).*



FIGURE 18-9B *Drawing an isometric curve (offset distances and depth).*



FIGURE 18-10A *Drawing an isometric curve (grid method).*



FIGURE 18-10B *Isometric grid layout.*

Draw each section as an isometric, *Figure 18-11A*. The two-view drawing of the boat has been simplified for this example. Divide the object into a series of sections, A through H. Use a logical baseline (in this case a center line). Locate and draw each section, *Figure 18-11B*. Connect all the sections and complete the boat, *Figure 18-11C*.

Isometric Circles and Arcs

Drawing isometric circles and arcs, without using templates, takes too much time for isometric drawing. Use an isometric ellipse template, *Figure 18-12*. The template has eight hash marks printed around the perimeter of each ellipse. Four indicate the



FIGURE 18-11 *(A) Irregularly shaped object; (B) Drawing each section; (C) Completed objects.*



FIGURE 18-12 *Isometric ellipse template.* (Courtesy Timely Products Co.)



FIGURE 18-13A *Basic shape of the circle.*



FIGURE 18-13B *Draw the ellipse within the basic shape.*



FIGURE 18-13C *Isometric ellipse template aligned on axis of circle 1 2 3 4.*

isometric center lines of the circle or arc. For example, an ellipse for a one-inch circle would be labeled number –1– and it would measure 1″ across the ellipse along the isometric center line. These same hash marks also indicate the four tangent points of the isometric circle with the isometric basic shape of the circle, *Figures 18-13A* and *18-13B*. The other four hash marks line up with the axes of the circle; two are coincident with the axis of the circle and are lined up across the narrow part of the ellipse, and two are perpendicular to the axis and are lined up across the longest part of the ellipse, *Figure 18-13C*. The longest distance, across the one-inch ellipse, actually measures more than one inch due to the way the basic shape is constructed for isometric drawing.

How to Use Isometric Ellipse Templates for Isometric Drawings

STEP 1 For the object given, *Figure 18-14A*, locate the center of the circle or arc to be drawn using offset measurements, and construct the basic shape for the circle so that the sides of the basic shape are parallel to the two appropriate principal edges.

STEP 2 Line up the 1″ ellipse template so that the isometric center line hash marks touch the tangent points 1, 2, 3, and 4 of the basic shape, *Figure 18-14B*. Trace the ellipse. If some doubt exists as to which hash marks to line up, refer to *Figure 18-15* for guidance.



FIGURE 18-14A *How to use an isometric ellipse template.*



FIGURE 18-14B *Line up hash marks on tangent points.*



FIGURE 18-15 *Isometric circles in various planes.*

How to Draw True Isometric Circles

Assume that a relatively accurate isometric drawing of a circle is required, but a template is not available for the size needed.

GIVEN: A regular circle in its basic shape, and the same circle as it would be drawn in an isometric drawing, in its basic shape, *Figure 18-16A*. In both drawings the tangent points are given "clock" numbers.

STEP 1 Use the circle in the basic shape, a square, with the tangent points 3, 6, 9, and 12. Use the remaining clock numbers and divide the circle into the rectangles shown, *Figure 18-16B*.

STEP 2 Draw the basic shape of the circle and use the offset method to locate points 1, 5, 7, and 11 using the X and Y dimensions, *Figure 18-16C*.



FIGURE 18-16 *(A) Regular circle and isometric circle; (B) Step 1; (C) Step 2; (D) Step 3; (E) Completed isometric circle.*



FIGURE 18-17 *How to draw an isometric arc (offset method).*

STEP 3 Locate points 2, 4, 8, and 10 in a similar manner, *Figure 18-16D.*

STEP 4 Connect the 12 points with a French curve and finish the isometric drawing of the circle, *Figure 18-16E.*

To draw an arc of a circle, use these steps and use the portion of the circle needed, *Figure 18-17.*

How to Draw Approximate Isometric Circles

Assume that an approximate isometric circle is needed in an isometric drawing, but a template is not available with the size required. The four-center method described in the following steps can be used.

GIVEN: A regular circle with a radius X, Figure 18-16A.

STEP 1 Draw the basic shape of the circle in the appropriate location in the drawing. Label the four tangent points 1, 2, 3, and 4, *Figure 18-18A.*

STEP 2 From each of the four tangent points, draw a line at 90° to the opposite sides of the basic shape, *Figure 18-18B.* These lines intersect at four locations called the swing points or centers. Label them A, B, C, and D, *Figure 18-18C.* A line can be used to check the location centers A and B.

STEP 3 Construct a radius at each of the four centers, A, B, C, and D as shown in *Figures 18-18D* and *18-18E.*

STEP 4 Darken in the completed isometric circle and center lines, *Figure 18-18F.*



FIGURE 18-18 *(A) Step 1 (how to draw an approximate isometric circle); (B) and (C) Step 2; (D) and (E) Step 3.*



FIGURE 18-18 *(Continued) (F) Completed isometric circle; (G) Drawing isometric arcs (four-center method).*

Construct arcs by using the four-center method and the radius X, discussed in these four steps, *Figure 18-18G.*

How to Draw an Ellipse on an Inclined Plane

GIVEN: A 2-view drawing of a cylinder cut at an angle, *Figure 18-19A.*

STEP 1 Divide the view of the cylinder, showing it as a circle, in 12 equally spaced arcs (1 through 12). Project the points into the view showing the base of the cylinder as an edge. Locate the true-length line segments from each point, Figure 18-19A.

STEP 2 Construct an isometric circle of the base and locate each of the 12 points using the offset technique, *Figure 18-19B.*

STEP 3 Project each true-length line segment up from the base and connect the end points to form the boundary of the elliptically shaped surface. Use a French curve.

Isometric Intersections

An isometric drawing can be constructed from a completed multiview drawing, showing an intersection(s), by following the steps outlined in this chapter. First, construct a basic shape, box, and then transfer a sufficient number of points from the multiview drawing, using the offset method, to complete the isometric drawing.



FIGURE 18-19 *(A) How to draw an ellipse on an inclined plane. Given: two views; (B) An isometric ellipse on an inclined plane.*

Isometric Dimensioning

Use the same dimensioning standards, rules, and methods discussed in Chapter 10 to dimension isometric drawings. Furthermore, use unidirectional dimensioning for clarity and ease of placing the dimensions, *Figure 18-20.* Note that extension lines and dimension lines are parallel to one of the three axes.



FIGURE 18-20 *Isometric dimensioning.*



FIGURE 18-21 *Isometric rounds and fillets.*

Isometric Rounds and Fillets

Rounds and fillets in isometric drawings can be shown three ways, *Figure 18-21A, B,* and *C.* Use whichever way, or combinations of ways, that best shows the fillets or rounds and where they are located.

Isometric Knurls, Screw Threads, and Spheres

Isometric knurls are usually drawn with straight lines, *Figure 18-22A* and *B.* Part A shows the location of a proposed knurl and how to indicate a chamfer. Part B shows the finished drawing.

Isometric threads are readily represented by a series of ellipses drawn along the center line of the fastener, parallel to each other, and approximating the thread spacing, *Figure 18-23.*



FIGURE 18-22 *Isometric knurl.*



FIGURE 18-23 *Isometric threads.*

Isometric spheres require three ellipses to be drawn, *Figure 18-24*—one along each axis, and one circumscribing the first two. If only a portion of a sphere is wanted, then the first two ellipses can be used to outline a half sphere, *Figure 18-25;* a quarter sphere, *Figure 18-26;* or a three-quarter sphere, *Figure 18-27.*

Based on the 2-view drawing in *Figure 18-28,* draw a flat surface in a sphere by following the implied steps in *Figure 18-29.*



FIGURE 18-24 *Isometric sphere.*



FIGURE 18-25 *Isometric half sphere.*



FIGURE 18-26 *Isometric quarter sphere.*



FIGURE 18-27 *Isometric three-quarter sphere.*



FIGURE 18-28 *Two-view drawing of sphere.*



FIGURE 18-29 *Flat surface on a sphere.*

Axonometric: Drawing and Projection

Drafters, designers, and engineers use the pictorial drawings—oblique, isometric, and perspective—discussed in the first part of this chapter because approximations of these drawings are easy to sketch, and relatively accurate drawings of these types are easy to construct. Additional pictorial drawings and several projections will be considered next.

Isometric Projection

Isometric projection causes dimensions along the three principal edges to be foreshortened to approximately 82% of their true length, ***Figure 18-30.*** Note that the



FIGURE 18-30 *Isometric projection.*

diagonal of the 1″ cube is seen as a point in the A view, the three edges 3-2, 3-4, and 3-7 equal 0.816″, and the angles between edges 3-2, 3-4, and 3-7 are all equal to 120°.

Isometric Assemblies

Isometric assembly drawings appear in two popular formats: exploded and assembled. *Exploded isometric drawings* show all the components of an assembly as individual isometric drawings, including fasteners; however, the components are aligned in space in the same way they are to be assembled. See Problem 18-52 for an exploded-assembly sketch.

Exploded-assembly instructional drawings usually accompany products that are to be assembled after the buyer purchases the product. Exploded-assembly drawings are used extensively in automotive maintenance manuals.

Assembled isometric assembly drawings show how a single product looks when assembled. For example, refer to the isometric drawing of a robot in Chapter 20. Other isometric assembly drawings may show a large number of individual components, for example, a CIM system (computer-integrated manufacturing) in Chapter 20, and a piping-system drawing in Chapter 21.

Dimetric Drawing

Dimetric drawing differs from isometric drawing in that only two angles are equal. ***Figure 18-31*** shows a number of orientations for drawing dimetric views; lines of an object that are parallel to the first two axes are drawn full size, lines parallel to the third are drawn to a different scale. Because two different scales are used, less distortion is apparent and an object looks more realistic. One disadvantage, however, is that circles are difficult to draw in dimetric views.



FIGURE 18-31 *Dimetric drawing.*



FIGURE 18-32 *Trimetric drawing.*

Trimetric Drawing

Trimetric drawing uses axes that are rotated so that each axis is drawn at a different angle, and each axis uses a different scale, ***Figure 18-32.*** Trimetric drawings can appear more realistic than any of the other types, but they are the most time consuming to draw, so they aren't used by drafters.

Other Oblique Drawings

Cavalier Drawing

Cavalier drawings have a receding axis drawn between 30° and 60° to the horizon, and the receding distances are drawn full size, ***Figures 18-33*** and ***18-34.***

Cabinet Drawing

Cabinet drawings have the same range of receding axes as cavalier drawings, but the receding distances are drawn to half size, ***Figure 18-35.***

General Oblique Drawing

General oblique drawing is similar to cabinet drawing except that the lines drawn along the direction of the receding distances may be at any scale between half and full, ***Figure 18-36.***



FIGURE 18-33 *Oblique drawing.*



FIGURE 18-34 *Cavalier drawing.*



FIGURE 18-36 *General oblique.*



FIGURE 18-35 *Cabinet drawing.*

Perspective Drawings

A *perspective drawing* is a three-dimensional drawing of an object or scene that shows visible lines almost as a person's eyes would perceive them from one particular viewing location. A perspective drawing is somewhat like a photograph, ***Figure 18-37***. The upper drawing shows the lines of a building from the outside; the lower one shows an inside view of a room. Both views are drawn in two-point perspective like several of the sketches in Chapter 3.

OUTSIDE VIEW IN TWO-POINT PERSPECTIVE



INSIDE VIEW IN TWO-POINT PERSPECTIVE

FIGURE 18-37 *Outside and inside perspective views.*



FIGURE 18-38 *Perspective terms.*

Perspective Drawing Terms

Learn the terms used in perspective drawing while studying the figures and procedures that follow.

Station Point (SP). The exact location from which the observer views the object, ***Figure 18-38.***

Ground Line (GL). The edge view of the surface upon which the object to be viewed rests, Figure 18-38.

Horizon (H). A line at the level of the viewer's eyes, Figure 18-38, and the line where the vanishing points are located.

Vanishing Point (VP). A point on the horizon line to which all other lines are projected, ***Figure 18-39.*** Six cubes, A through F, are used to show which sides of an object would be seen for various left and right positions of the cubes in perspective drawings. Note that if the dimension X shown is too great, a two-point perspective drawing would be needed.

Picture Plane (PP). Like the projection plane in multiview drawings. An imaginary plane perpendicular to the ground line, Figure 18-38.

Visible Rays (VR). Lines from the eyes of the viewer to each and every point on the object to be viewed. The visible rays intersecting the picture plane create the perspective drawing, Figure 18-38.

Measuring Line (M). Actually used as a vertical line, but it appears horizontal because of the way it is established. The line originates at the projection plane and is 90° to it. Referring ahead, Figures 18-40D, G, and H show the measuring line as a vertical line used to measure true heights.



FIGURE 18-39 *Vanishing point and horizon line.*

Presketching for Perspective Drawings

Make simple, quick sketches of an object to be drawn in two-point perspective to determine the best arrangement of the horizon, station point, ground line, and vanishing points, Figures 18-40A and B. Two of the multiviews are required for the two-point perspective (usually a top view and a front or side view).



FIGURE 18-40 *(A) How to draw a two-point perspective drawing; (B) Sketch of object in various positions; (C) Step 1; (D) Step 2.*

How to Draw a Two-Point Perspective

GIVEN: Multiview drawing *Figure 18-40A* and the sketches of the object in *Figure 18-40B*. Sketch C is selected as the best position to show the features of the object.

STEP 1 On the upper portion of a drawing sheet, draw the top view at any orientation, but attempt to match the best position from the sketches, *Figure 18-40C*. Locate the front edge of the object tangent to the picture plane.

STEP 2 From the front edge of the object, where it is tangent to the picture plane line, project the measuring line at 90° to the picture plane, *Figure 18-40D*. Locate the station point on the measuring line so the inclusive angle of view is 30° or less.

STEP 3 From the station point, construct lines parallel to the two edges of the top view, *Figure 18-40E*, and label their intersections with the picture plane, 1 and 2.

STEP 4 Draw the horizontal line at a convenient location, preferably below the station point to avoid a cluttered drawing, *Figure 18-40F*. From points 1 and 2 on the picture plane, project downward to the horizon line to locate the left and right vanishing points. Locate a ground line and draw a side or front view on the line as shown.

STEP 5 From the view selected for the ground line, in this example the right-side view, project the true height of the object to the measuring line, *Figure 18-40G*. From the true height, project lines to the left and right vanishing points, and then construct a perspective basic shape of the object. Note how the vertical boundaries of the basic shape are established by the top view.

STEP 6 Project the true heights of each feature from the right-side view to the measuring line and back toward the appropriate vanishing point, to a point where the same feature intersects the picture plane line, *Figure 18-40H*. Develop the various features of the object in light lines until satisfied that the drawing is correct.

STEP 7 Finally, darken the lines of the object, *Figure 18-40I*. Hidden lines are not usually drawn except to show an important feature that otherwise would not be seen.



(E)



(F)



(G)



(H)

(I)

FIGURE 18-40 *(Continued) (E) Step 3; (F) Step 4; (G) Step 5; (H) Step 6; (I) Step 7.*



FIGURE 18-41 *Kinds of perspective drawings.*

Perspective View

Types of Perspective Views

Three types of perspective views are shown in *Figure 18-41:* one-, two-, and three-point, respectively. Only two-point perspective is discussed in this chapter because it is the type most often used in industry.

Perspective Irregular Curves

Use a multiview drawing and a grid as was done for the isometric drawing. Then follow the steps in the previous example to construct a perspective drawing, *Figure 18-42.*

Perspective Circles and Arcs

Divide the circle (or arc) into equal segments, *Figure 18-43.* Follow the steps from the previous example to construct the perspective drawing.



FIGURE 18-42 *Perspective irregular curves.*

Industry Application

"Who remembers how to make isometric drawings?" asked Mark Malone—Chief Drafter for Pensacola Prestressed Concrete Company (PPCC). Malone had been asked by the foreman of PPCC's construction crew to develop pictorial drawings of several complicated connection joints for a bridge the company was building. The joints in question were so complicated that PPCC's construction crew was having trouble reading the plans. These joints had to be fitted together properly. The structural integrity of the bridge would depend on them.

Malone had agreed to provide pictorials without considering who would draw them. He could not remember the last time pictorial drawings had been called for. Prestressed concrete plans were almost always orthographic. In fact, he had not made a pictorial drawing himself since coming to PPCC 12 years ago. But he did remember being good at it as a drafting student at Pensacola Junior College.

That was when the idea came to him. "I'll ask the drafting class at PJC to take on this project." In the past he had given the class projects when PPCC's drafting team got overloaded and deadlines were fast approaching. The students had always done an excellent job, and they appreciated the real-world experience.

Two days later, Malone had several outstanding isometric joint details, PJC's drafting students had additional real-world experience, the construction crew had drawings they could read, and Malone had found two talented students he could hire in the near future.



FIGURE 18-43 *Perspective circles or arcs.*

Summary

- The most common types of pictorial drawings used by drafters, designers, and engineers are oblique, isometric, and perspective.
- Oblique drawings are the easiest type of pictorial drawing to make. The surface of the object is drawn exactly as it would appear in a multiview drawing.

  The depth axis is drawn at either 30° or 45°.
- Isometric drawings use three axes, sometimes called principal edges, at 120° to each other. They are the most frequently used pictorial drawings because they depict an object as well as a perspective drawing, but they are easier to make.
- A perspective drawing is a three-dimensional drawing of an object or scene that shows visible lines almost as a person's eye would perceive them from one particular viewing location. Key perspective concepts are the station point, ground line, horizon, vanishing point, picture plane, visible rays, and measuring line. There are one-, two-, and three-point perspective drawings.
- Dimetric drawings are similar to isometric except that only two angles are equal.
- Trimetric drawings are similar to isometric except that all three angles are different.
- A cavalier drawing is a type of oblique drawing in which depth is measured at full scale.
- A cabinet drawing is a type of oblique drawing in which depth is measured at half scale.
- General oblique drawings allow any appropriate scale to be used for the depth.

Review Questions

Answer the following questions either true or false.

1. The true isometric circle method is preferred over the four-center isometric circle method when time is an important factor.
2. An isometric drawing is dimensioned by using unidirectional dimensioning.
3. Trimetric drawings use axes that are rotated so that each axis is drawn at a different angle, and each axis uses a different scale.
4. Isometric, dimetric, and trimetric drawings are classified as perspective drawings.
5. Hidden lines are only used in pictorial drawings to show an important feature that otherwise would not be seen.
6. Isometric drawings use four axes sometimes called principal edges.
7. An isometric projection causes dimensions along the three principal edges to be foreshortened to approximately 87% of their true length.
8. Offset measurements are used to locate the center point of the work area.

Answer the following questions by selecting the best answer.

1. Which of the following is a type of pictorial drawing not frequently used in industry?
   a. cabinet
   b. trimetric
   c. isometric
   d. two-point perspective
2. Which of the following is the perspective view most used in industry?
   a. one-point
   b. two-point
   c. three-point
   d. four-point
3. Which type of pictorial drawing best illustrates the object as it would be viewed by the eye?
   a. oblique
   b. isometric
   c. perspective
   d. dimetric
4. Which of the following is the correct definition of a nonisometric line?
   a. a line that is not parallel to any of the three principal edges in an isometric drawing
   b. a line that is not perpendicular to any of the three principal edges in an isometric drawing
   c. a line that is not parallel or perpendicular to any of the three principal edges in an isometric drawing
   d. none of the above
5. Which of the following is **not** true regarding an oblique drawing?
   a. It is easier to draw than isometric or perspective drawings.
   b. Usually the front view is drawn exactly as it would appear in a multiview drawing.
   c. Oblique drawings use three axes.
   d. Oblique drawings are the most used of the three common pictorials.

Chapter 18 Problems

The following problems are intended to give the beginning drafter practice in laying out and developing isometric and perspective renderings of various objects.

Conventional Instructions

The steps to follow in laying out the drawings in this chapter are:

STEP 1 Study the problem carefully.

STEP 2 Position the object so it **best** illustrates the most features.

STEP 3 Make a pictorial sketch of the object.

STEP 4 Calculate the basic shape size.

STEP 5 Find the center of the work area.

STEP 6 Lightly center and lay out the basic shape within the work area.

STEP 7 Lightly develop the object within the basic shape.

STEP 8 Check to see that the completed object is centered within the work area.

STEP 9 Check all size dimensions, and check for accuracy of the object.

STEP 10 Darken in the object.

STEP 11 Recheck all work and, if correct, neatly fill out the title block using light guidelines and neat lettering.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

Problems 18-1 through 18-27

Construct an isometric drawing of the object in Problems 18-1 through 18-27. (Note that these problems have only straight lines.)

PROBLEM 18-1



PROBLEM 18-2

PROBLEM 18-3



PROBLEM 18-4



PROBLEM 18-5



PROBLEM 18-6



PROBLEM 18-7



PROBLEM 18-8



PROBLEM 18-9



PROBLEM 18-10



PROBLEM 18-11



PROBLEM 18-12



PROBLEM 18-13



PROBLEM 18-14



PROBLEM 18-15



PROBLEM 18-16



PROBLEM 18-17



PROBLEM 18-18



PROBLEM 18-19



PROBLEM 18-20



PROBLEM 18-21



PROBLEM 18-22



PROBLEM 18-23



METRIC

PROBLEM 18-24



PROBLEM 18-25



PROBLEM 18-26



PROBLEM 18-27



Problems 18-28 through 18-51

Construct an isometric drawing of the object in Problems 18-28 through 18-51. (Note that these problems have straight lines, arcs, and circles.)

PROBLEM 18-28



PROBLEM 18-29



PROBLEM 18-30



PROBLEM 18-31



PROBLEM 18-32



PROBLEM 18-33



METRIC

PROBLEM 18-34



PROBLEM 18-35



PROBLEM 18-36



PROBLEM 18-37



PROBLEM 18-38



PROBLEM 18-39



PROBLEM 18-40



PROBLEM 18-41



PROBLEM 18-42



PROBLEM 18-43



PROBLEM 18-44



PROBLEM 18-45



PROBLEM 18-46



PROBLEM 18-47



PROBLEM 18-48



PROBLEM 18-49



ALL UNMARKED RADII = R.09

PROBLEM 18-50



PROBLEM 18-51



PROBLEM 18-52 (A TO I)

Construct an exploded isometric drawing of the assembly of a vise, Problem 18-52A. The vise consists of seven different parts and various fasteners, Problems 18-52B through 18-52I. Illustrate the exploded view with the parts in relationship to its assembly. Space parts with an approximate 1″ (25 mm) space between parts. Center the completed view within the work area.



(A)

PROBLEM 18-52 (*continued*)



(B)



(C)

PROBLEM 18-52 (*continued*)



PART NO. 3
1 REQ'D.

(D)



PART NO. 4
1 REQ'D.

(E)



PART NO. 5
2 REQ'D.

(F)



(G)



(H)



TENTATIVE "BOX" ISOMETRIC DRAWINGS. REARRANGE THE DRAWINGS TO BEST SHOW THE ASSEMBLY OF THE VISE

(I)

PROBLEM 18-53

Using the given multiview drawing, develop a perspective drawing in the positions as illustrated by sketches A, B, C, D, E, and F.



SKETCHES



PROBLEM 18-54

Using the given multiview drawing, develop a perspective drawing in the positions as illustrated by sketches A and B.



SKETCHES



PROBLEM 18-55

Choose various objects from Problems 18-1 through 18-51, and develop them into a perspective drawing. Compare the isometric view with the isometric drawing.

PROBLEM 18-56

Prepare an isometric drawing of the object shown in Problem 6-26.

PROBLEM 18-57

Prepare an isometric drawing of the object shown in Problem 9-49.

PROBLEM 18-58

Prepare an oblique drawing of the object shown in Problem 10-13.

PROBLEM 18-59

Prepare an oblique drawing of the object shown in Problem 10-40.

PROBLEM 18-60

Redesign parts 2 and 3 of the vise in Problem 18-52. Propose a more positive means for connecting part 2 to part 3. Show the redesign in any combination of the following formats: multiview drawings, section drawings, isometric drawings, oblique drawings, perspective drawings.

PROBLEM 18-61

Select an assembled product (one that can be disassembled easily, or if necessary, destroyed during disassembly) and draw an exploded, approximate isometric drawing of the components. The objective is to show how the product works. Suggestions: household items, automotive components, office devices (pencil sharpener, file drawer mechanism), sports equipment, weight-training apparatus, laboratory equipment, classroom demonstrations.

PROBLEM 18-62

Design a means, made of simple parts, to raise water one meter from one irrigation canal to another for a third-world country. Employ animal power or a windmill-type apparatus. Prepare an exploded isometric of the components that make up the design.

PROBLEM 18-63

Design a wooden toy (but metal for axles, fasteners, etc.) to be made out of simple shapes; for example, a train engine made of blocks, cylinders, circles, cones, etc. Prepare an exploded isometric showing how the pieces are to go together and how they are to be joined.

SECTION 4

Related Technologies, Applications, and Processes

19 Welding

20 Modern Manufacturing: Materials, Processes, and Automation

21 Drafting Applications: Pipe, Structural, Architectural, Civil Engineering, and GIS

22 The Design Process

Career Profile

TERRY SCHULTZ

Terry Schultz came upon his career path late in life. At 40 years old, after many years managing restaurants, he was ready for a change. Remembering how much he enjoyed drafting classes in high school, Schultz went back to ITT to get a degree in drafting. After a few years working for others, he decided to go out on his own, with his still-growing small business, Spokane CAD Consultants.

Primarily a structural drafter, Schultz works directly with an engineer on most projects. The engineer will give him sketches, which Schultz looks over to see if there's anything obviously missing. (He recognizes that engineers are not drafters and vice versa, but both need to serve as each other's check and balance.) Sometimes he does his own sketch to see if he understands, before he lays a sketch out in CAD, paying particular attention to detail, scale, and ASME standards.

Often Schultz and the engineer will work with the architect and the architect's drawings. But they also must do their own. Here's the difference: A structural drafter—and the engineer he or she is working with—is most interested in weights, stress loads, and pressures. He or she is thinking, how will I support this building? What beams and supports are necessary? While an architectural drafter might be looking at the facings of a building, a structural drafter will look at the column supports inside. The drafter also must work with the welder—where two pieces of a support will be seamlessly joined, there will be welding. Right now, Schultz and the engineer are creating a basin for a wastewater treatment plant. For this project, Schultz has to make sure his drawing outlines a setup that supports 36,000 gallons of water and contains the appropriate piping underneath. In this project, iron is welded to channel; he must know that it is a Phillips weld, what the depth of it is, and what the standard symbol for that is.

The engineer who brought Schultz into this project is someone he has worked with a number of times before. While owning his own business often requires a lot of legwork, he is starting to make contacts who will call him for projects. It is a good sign for the continued expansion of his business; Schultz hopes that within the next few years, he will be managing contract drafters as well. Until then, he can see the day-to-day joy of what he is doing, especially when he gets to see something he drew turn into a sturdy and safe structure.

19

Welding

CHAPTER OUTLINE

Welding processes • Basic welding symbol • Size of weld • Length of weld • Placement of weld • Intermittent welds • Process reference • Contour symbol • Field welds • Welding joints • Types of welds • Multiple reference line • Spot weld • Projection weld • Seam weld • Welding template • Design of weldments • Summary • Review questions • Chapter 19 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- List the most widely used welding procedure.
- Demonstrate proficiency in the proper use of welding symbols.
- Demonstrate proficiency in the proper dimensioning of welds.
- Demonstrate proficiency in properly indicating weld placement.
- Demonstrate proficiency in properly indicating intermittent welds.
- Explain the proper use of the contour symbols as part of the welding symbol.
- Explain the proper use of the symbology for field welds.
- Describe the five basic types of welded joints.
- Describe the six major types of welds.

(continued)

KEY TERMS

Back weld
Backing weld
Basic welding symbol
Brazing
Chain intermittent weld
Double weld
Field weld
Fillet weld
Flange weld
Forge welding
Fusion weld
Fusion welding
Gas welding
Groove weld
Increment
Intermittent weld
Multiple reference lines
Multiweld
Pitch
Plug weld
Projection weld
Resistance welding
Root opening
Seam weld
Section lining
Slot weld
Spot welding
Staggered intermittent weld
Surface weld
Welding

(CHAPTER OBJECTIVES continued)

- Demonstrate proficiency in the proper use of multiple reference lines.
- Explain the concept of spot welding.
- Explain the differences between spot welds and projection welds.
- Explain the concept of the seam weld.
- Demonstrate proficiency in the use of welding templates.

Welding Processes

Pieces of metal can be fastened together with mechanical fasteners as was discussed in Chapter 13, "Fasteners." They can also be held together by soldering or brazing, and some are fastened together by an adhesive. A permanent way to join pieces of metal together is by *welding*.

One method used to weld parts together is to heat the edges of the pieces to be joined until they melt and join or fuse together. When the pieces cool, they become one homogeneous mass, permanently joined together. A filler rod is sometimes used to mix with the molten metal to make the joint stronger. When a lot of heat is used to melt and fuse the joint, the weld is called a *fusion weld*. Heat for this process can come from a torch, burning gases, or with a high electric current. Because of the extremely high temperatures involved in welding, the part or parts may be distorted; thus, all machining is usually done after welding.

Another kind of weld used in years past was the pressure weld. In this process, the parts to be welded together are heated to a plastic state, and forced together by pressure or by hammering. This was done by the local blacksmith. This old method was called *forge welding*. Today, faster and better methods are used.

Welding assemblies are usually built-up from stock forms, such as plate steel, square bars, tubing, angle iron and the like. These parts are cut to shape and welded together. The various welding processes are illustrated in ***Figure 19-1***.Welded assemblies are much less expensive and more satisfactory than the casting process, especially in a case where only one or only a few identical parts are required.

Welding is used on large structures that would be difficult or impossible to build in a manufacturing plant. Large structures such as building frames, bridges, and ships are welded into one large assembly.

Major welding methods classified by the American Welding Society include brazing, gas welding, arc welding, resistance welding, and fusion welding. *Brazing* is the process of joining metals together with a nonferrous filler rod. A temperature above 1,000°F, but just below the melting point, is used to join the parts. The most commonly used *gas welding* is oxy-acetylene welding. Resistance welding and fusion welding, the two major processes, are explained in this text. Detailed information regarding the other types of welding processes can be obtained by writing to the American Welding Society, P.O. Box 351040, Miami, Florida 33125.

Resistance welding is the process of passing an electric current through the exact location in which the parts are to be joined. This is usually done under pressure. The combination of the pressure and the heat generated by the electric current welds the parts together. This process is usually done on thin sheet metal parts.

Fusion welding is usually used for large parts. The fusion welding process uses many standard types of welds, ***Figure 19-2***. Each is explained in full.

The next few figures use the fillet welding symbol as an example, but the same method applies, regardless of which welding symbol is used.

Basic Welding Symbol

The *basic welding symbol* consists of a reference line, a leader line and arrow, and, if needed, a tail, ***Figure 19-3***. The tail is added for specific information or notes in regard to welding specifications, processes, or reference information. The reference line of the basic welding symbol is usually drawn horizontally. Any welding symbol placed on the upper side of the reference line indicates WELD OPPOSITE SIDE, ***Figure 19-4***. Any welding symbol placed on the lower side of the reference line indicates WELD ARROW SIDE, Figure 19-4. The direction of the leader line and arrow has no significance whatsoever to the reference line.

A fillet weld symbol, Figure 19-2, is added above or below the reference line with the left leg always drawn vertical, ***Figure 19-5***. A welding symbol placed above the reference line means to weld the OPPOSITE side, as illustrated in ***Figure 19-6***. A weld symbol placed below the reference line means to weld ARROW side, as illustrated in Figure 19-6. The positions as drawn and as welded are shown in ***Figures 19-7*** and ***19-8***. A weld symbol placed above and below the reference line means to weld both the OPPOSITE side and the ARROW side, as illustrated in ***Figure 19-9***.



FIGURE 19-1 *Master chart of welding processes.* (Courtesy American Welding Society)

Size of Weld

The weld must be fully dimensioned so that there is no question whatsoever as to its intended and designed size. The size of a weld refers to the length of the leg or side of the weld. The size is placed directly to the left of the welding symbol. The two legs are assumed to be equal in size unless otherwise dimensioned, *Figure 19-10.* If a double weld is needed, the size of each weld must be included as illustrated in *Figure 19-11.*

If the legs or sides of the weld are to be different, the dimensions of the sides must be indicated to the left of the welding symbol in parentheses, as reference-only dimensions, *Figure 19-12.* Because the symbol does not indicate which is the .50 leg and which is the .25 leg, the detail drawing must include the dimensions.



FIGURE 19-1 *(continued)*



FIGURE 19-2 *Fusion welding.*



FIGURE 19-3 *Basic welding symbol.*



FIGURE 19-4 *Any welding symbol placed on the upper side of the reference line indicates weld OPPOSITE side.*



FIGURE 19-5 *Left leg of welding symbol is always drawn vertical.*

FIGURE 19-6 *Welding symbol placed above the reference line means to weld OPPOSITE side. Welding symbol placed below the reference line means to weld ARROW side.*



FIGURE 19-7 *Position as drawn and as welded.*



FIGURE 19-8 *Position as drawn and as welded.*



FIGURE 19-9 *Welding symbol placed above and below the reference line means to weld both sides.*



FIGURE 19-10 *Dimension to the left of welding symbol indicates length of leg or side of weld.*



FIGURE 19-11 *Size of each weld is required.*



FIGURE 19-12 *Welds with legs or side of different sizes.*

Length of Weld

When a weld length is not specified, it is assumed to be continuous the full length, *Figure 19-13.* If a weld must be made to a special length, it must be indicated. This is done by a dimension directly to the right of the weld symbol, *Figure 19-14.*



FIGURE 19-13 *If weld is not specified, it is assumed to be continuous full length.*



FIGURE 19-15 *A small circle indicates weld continuously around an object.*



FIGURE 19-14 *Length of weld must be noted to the right of the welding symbol.*



FIGURE 19-16 *Section lining indicates location of weld.*

When a weld is to be made continuously all around an object, it is indicated on the welding symbol by adding a small circle between the reference line and the leader line, *Figure 19-15.*

Placement of Weld

When a weld is not continuous and is needed in only a few areas, *section lining* is used to indicate where the weld is to be placed, ***Figure 19-16.*** If a weld is to be placed in a few areas, this is indicated by the use of multiple leader lines and arrows, ***Figure 19-17.***

Intermittent Welds

Intermittent welds are a series of short welds. When this type of weld is needed, an extra dimension is added to the welding symbol, ***Figure 19-18.*** The usual size of the leg is noted to the left of the symbol, and the length of the weld is indicated to the right of the welding symbol followed by a dash line and the pitch of the intermittent welds, ***Figure 19-19.*** An



FIGURE 19-17 *Leader line and arrows indicate location of weld.*



FIGURE 19-18 *Intermittent welds are noted by dimensions to the right of the welding symbol.*



FIGURE 19-19 *Pitch is the center-to-center distance between welds.*

increment is the length of the weld; the *pitch* is the center-to-center distance between increments.

Chain Intermittent Weld

A *chain intermittent weld* is a weld in which each weld is applied directly opposite to each other on opposite sides of the joint, *Figure 19-20*. Note that the welding symbol is applied above and below the reference line and that they are in line with each other.



FIGURE 19-20 *Chain intermittent welds are applied directly opposite each other.*

Staggered Intermittent Weld

A *staggered intermittent weld* is similar to the chain intermittent weld except the welds are staggered directly opposite each other on opposite sides, *Figure 19-21*. Note the welding symbol is applied above and below the reference line staggered to each other.



FIGURE 19-21 *Staggered intermittent welds are placed staggered opposite each other.*

DESIGNATION OF WELDING AND ALLIED PROCESSES BY LETTERS

AAC	air carbon arc cutting
AAW	air acetylene welding
ABD	adhesive bonding
AB	arc brazing
AC	arc cutting
AHW	atomic hydrogen welding
AOC	oxygen arc cutting
AW	arc welding
B	brazing
BB	block brazing
BMAW	bare metal arc welding
CAC	carbon arc cutting
CAW	carbon arc welding
CAW-G	gas carbon arc welding
CAW-S	shielded carbon arc welding
CAW-T	twin carbon arc welding
CW	cold welding
DB	dip brazing
DFB	diffusion brazing
DFW	diffusion welding
DS	dip soldering
EASP	electric arc spraying
EBC	electron beam cutting
EBW	electron beam welding
ESW	electroslag welding
EXW	explosion welding
FB	furnace brazing
FCAW	flux cored arc welding
FCAW-EG	flux cored arc welding–electrogas
FLB	flow brazing
FLOW	flow welding
FLSP	flame spraying
FOC	chemical flux cutting
FOW	forge welding
FRW	friction welding
FS	furnace soldering
FW	flash welding

FIGURE 19-22 *Designation of welding and allied processes by letters (abbreviations).*

DESIGNATION OF WELDING AND ALLIED PROCESSES BY LETTERS

GMAC	gas metal arc cutting
GMAW	gas metal arc welding
GMAW-EG	gas metal arc welding–electrogas
GMAW-P	gas metal arc welding–pulsed arc
GMAW-S	gas metal arc welding–short circuiting arc
GTAC	gas tungsten arc cutting
GTAW	gas tungsten arc welding
GTAW-P	gas tungsten arc welding–pulsed arc
HFRW	high frequency resistance welding
HPW	hot pressure welding
IB	induction brazing
INS	iron soldering
IRB	infrared brazing
IRS	infrared soldering
IS	induction soldering
IW	induction welding
LBC	laser beam cutting
LBW	laser beam welding
LOC	oxygen lance cutting
MAC	metal arc cutting
OAW	oxyacetylene welding
OC	oxygen cutting
OFC	oxyfuel gas cutting
OFC-A	oxyacetylene cutting
OFC-H	oxyhydrogen cutting
OFC-N	oxynatural gas cutting
OFC-P	oxypropane cutting
OFW	oxyfuel gas welding
OHW	oxyhydrogen welding
PAC	plasma arc cutting
PAW	plasma arc welding
PEW	percussion welding
PGW	pressure gas welding
POC	metal powder cutting
PSP	plasma spraying
RB	resistance brazing
RPW	projection welding
RS	resistance soldering
RSEW	resistance seam welding
RSW	resistance spot welding
ROW	roll welding
RW	resistance welding
S	soldering
SAW	submerged arc welding
SAW-S	series submerged arc welding
SMAC	shielded metal arc cutting
SMAW	shielded metal arc welding
SSW	solid state welding
SW	stud arc welding
TB	torch brazing
TCAB	twin carbon arc brazing
TW	thermit welding
USW	ultrasonic welding
UW	upset welding

FIGURE 19-22 *(Continued) Designation of welding and allied processes by letters (abbreviations).*

Process Reference

There are many welding processes developed by the American Welding Society. Each process has a standard abbreviation designation, ***Figure 19-22.*** Letter designations are used to specify a method used to obtain a particular contour of a weld, ***Figure 19-23.*** These abbreviations are taken from the latest American Welding Society's standard #AWS-2.4-79,71.

The standard process abbreviations or letter designations are usually added to the tail of the basic welding symbol as required, ***Figure 19-24.*** Sometimes, they are called off in a note somewhere on the drawing, ***Figure 19-25.***

Contour Symbol

If a special finish must be made to a weld, a contour symbol must be added to the welding symbol. There are three kinds of contour symbols used: flush, convex, or concave, ***Figure 19-26.*** The contour symbol is added directly above or below the welding symbol. If

LETTER	METHOD
C	CHIPPING
G	GRINDING
H	HAMMERING
R	ROLLING
M	MACHINING

FIGURE 19-23 *Abbreviations of standard method used to obtain a particular contour.*



FIGURE 19-24 *Process abbreviations are placed in the tail of the basic welding symbol.*



FIGURE 19-25 *Sometimes a note is indicated somewhere on the drawing.*

FIGURE 19-26 *Contour symbol.*

FIGURE 19-27 *Contour symbol is added to the welding symbol.*



FIGURE 19-28 *Finish number specifies finish required.*

the welding symbol is above the reference line, the contour symbol is placed above the welding symbol. If the welding symbol is placed below the reference line, the contour symbol is placed below the welding symbol, *Figure 19-27*. The degree of finish is not usually included, but if a specific finish is desired, a finish number designation must be added, *Figure 19-28*.

Figure 19-29 represents that the finish weld must be concave and ground to a 125-microinch surface finish. *Figure 19-30* represents that the finish weld must be machined flat on the top surface to a surface finish of 125 microinches. The weld must be convex on the bottom surface with a hammered finish.





FIGURE 19-29 *Finish weld is to be concave and ground to a 125-microinch surface finish.*





FIGURE 19-30 *Finish weld is to be machined flat on top surface to 125 microinch and convex on the bottom surface with a hammered finish.*

Field Welds

Any weld not made in the factory—that is, it is to be made at a later date, perhaps at final assembly on-site—is called a *field weld*. Its symbol is added to the basic



FIGURE 19-31 *Field weld.*

weld symbol by a filled-in flag, located between the reference line and the leader line and drawn using a 30°–60° triangle, *Figure 19-31*.

Welding Joints

There are five basic kinds of welding joints and they are classified according to the position of the parts that are being joined, *Figures 19-32A* through *19-32E*. There are many types of welds used to weld these joints together. Considerations as to which type of weld to use are based on the particular application, thickness of material, required strength of the joint, and available welding equipment, among others.





FIGURE 19-32 *(A) Butt joint; (B) Corner joint.*







FIGURE 19-32 *(Continued) (C) T-joint; (D) Lap joint; (E) Edge joint.*

Types of Welds

There are six major types of welds (refer back to Figure 19-2): fillet, groove, back or backing, plug or slot, surface, and flange welds.

More than one type of weld may be applied to a single joint—usually for strength or appearance. For example, a groove V weld may be used on one side, and a backing weld on the other side, *Figure 19-33*. This is known as a *multiweld*.

The same type of weld may be used on opposite sides of a single joint. Such a joint is called a *double weld;* for example, double V, double U, or double J weld,



FIGURE 19-33 *Multiwelds (different type of welds).*



FIGURE 19-34 *Double welds (same type of welds).*

Figure 19-34. These too, are used for strength and/or appearance.

Fillet Welds

Up to this point, the *fillet weld* and its symbol have been used as an example. The other five major types of welding symbols used are very similar.

Groove Weld

Seven types of welds are considered to be *groove welds*: square, V, bevel groove, J, U, flare V, and flare bevel. Each type has its own welding symbol, *Figure 19-35.* In the bevel groove and J welds, only one part is actually chamfered or grooved. To do this, the leader line and arrow point toward the part that has the bevel groove or J groove, *Figure 19-36.* Note that the

GROOVE WELDS		
TYPE	SYMBOL	AS SEEN
SQUARE		
V		
BEVEL GROOVE		
U		
J		
FLARE V		
FLARE BEVEL		

FIGURE 19-35 *Groove welds.*



FIGURE 19-36 *Groove weld illustrations.*

welding symbol is placed above or below the reference line, as usual, to indicate on which side the chamfer or groove is located.

Size of Groove Weld. In the groove weld, the dimension refers to the actual depth of the chamfer or groove,



FIGURE 19-37 *Groove welds with dimensions.*

not the size of the weld. With the fillet weld, the size of the chamfer or groove is located directly to the left of the welding symbol and on the same side of the reference line, *Figure 19-37*. If a V groove weld symbol is shown without a size dimension, the size or depth is assumed to be equal to the thickness of the pieces.

Depth or Actual Size of Weld. The depth or actual size of the weld includes the penetration of the complete weld. This is illustrated in *Figure 19-38*. Note in this example that the depth or actual size of the weld is deeper than the depth of the chamfer. Occasionally, the depth or actual size of the weld is less than the size of the chamfer, *Figure 19-39*.

In order to call off the depth or actual size of the weld and the size of the chamfer or groove, a dual dimension is used and both are added to the left of the welding



FIGURE 19-38 *Depth or actual size of weld.*



FIGURE 19-39 *Size of weld only.*



FIGURE 19-40 *Size of weld is added to the left of the welding symbol in parentheses.*



FIGURE 19-41 *Example of effective throat-weld larger than groove.*



FIGURE 19-42 *Example of effective throat-weld smaller than groove.*

symbol. In order to differentiate between the two, the size of the chamfer or groove is added to the extreme left of the welding symbol. The size of the depth or actual size of the weld is added directly to the left of the welding symbol, but in parentheses, *Figure 19-40*. Usually the weld is larger than the groove, *Figure 19-41*.

If the weld is less than the size of the chamfer, the dimensions are added to the left of the welding symbol in the same manner, *Figure 19-42*.

Root Opening. The allowed space between parts is called the *root opening*, *Figure 19-43*. The root opening is applied **inside** the welding symbol, *Figure 19-44*.



FIGURE 19-43 *Root opening.*



FIGURE 19-44 *Size of root opening.*



FIGURE 19-45 *Chamfered angle.*

The root opening may be called off as a general note. For example, "unless otherwise noted, root opening for all groove welds is .06." If there is no opening between parts, a zero is added inside the welding symbol.

Chamfer Angle. In a groove weld, a V or bevel groove must be held to tight tolerances. The angle must also be included with the size dimension in order to obtain the exact required geometric size and shape of all manufactured parts. The angle is also added inside the welding symbol, *Figure 19-45*. Note that the leader line and arrow point toward the part with the chamfer. Because the welding symbol is placed above the reference line, the chamfer and weld are on the side opposite from the arrow.

Groove Radius. If a J or U groove weld must be held to tight tolerances, the angle and radius must be included with the size dimensions in order to obtain the exact required geometric size and shape of all manufactured parts. The angle is also added inside the welding symbol and the required radius is called off as a note, *Figure 19-46*. Note that the leader line and arrow point toward the part with the groove. Because the welding symbol is placed below the reference line, the groove and weld are on the side of the arrow.



FIGURE 19-46 *Required radius.*

Backweld—Backing Weld

A *back weld* is a weld applied to the opposite side of the joint after the major weld has been applied. A *backing weld* is a weld applied first, followed by the major weld. Both use the same welding symbol and both are used to strengthen a weld (refer back to Figure 19-2). The back weld is also used for appearance.

If a welding melt-through is required, the same symbol is used, except it is filled in solid, *Figure 19-47*. When the back weld or backing weld symbol is used, it is placed on the opposite side of the reference line from the groove weld symbol, *Figures 19-48* and *19-49*.

FIGURE 19-47 *Back weld symbol/melt-thru weld symbol.*



FIGURE 19-48 *Illustration of back weld symbol.*



FIGURE 19-49 *Illustration of back weld symbol.*

Plug and Slot Welds

The *plug weld* and *slot weld* both use the same welding symbol. The only difference between the two welds is the shape of the hole through which the weld is applied. A plug weld is made through a round hole. A slot weld is made through an elongated hole (refer back to Figure 19-2).

The plug or slot welding symbol is applied to the basic welding symbol and interpreted in exactly the same way. If the welding symbol is applied above the reference line, the hole or slot is on the opposite side of the arrow. If below the reference line, the hole or slot is on the same side as the arrow, *Figure 19-50.*

Size of Plug or Slot Weld. The given dimension for a plug or slot weld refers to the diameter of the plug or slot at the base of the weld. The required dimension is placed directly to the left of the plug or slot weld symbol, *Figure 19-51.* The size of the slot weld is drawn and dimensioned directly on the detail drawing.

Depth of Weld. Unless noted, the plug or slot weld hole is completely filled by the weld. If filling the hole is not necessary, the full depth of weld must be called off. The required depth of weld is added inside the welding symbol, *Figure 19-52.*



FIGURE 19-51 *Size of plug or slot weld.*



FIGURE 19-50 *Plug and slot welds.*



FIGURE 19-52 *Depth of weld.*



FIGURE 19-53 *Tapered plug or slot.*

Tapered Plug or Slot. If the plug or slot hole is tapered, the taper-inclusive angle is added directly above or below the welding symbol, ***Figure 19-53.***

Surface Weld

If a surface must have material added to it or must be built up, a *surface weld* is added (refer back to Figure 19-2). This welding symbol is **not** used to indicate the joining of parts together; therefore, the welding symbol is simply added below the reference line, ***Figure 19-54.***

Size of Surface Weld. If the surface is to be built up and a special height is **not** required, the welding symbol is drawn as illustrated in Figure 19-54. If the surface is to be built up and a specific height is required, the required height is added directly to the left of the welding symbol, ***Figure 19-55.*** If only a portion of

FIGURE 19-54 *Surface weld.*

FIGURE 19-55 *Site of surface weld.*



FIGURE 19-56 *Illustration of a surface weld.*

the surface is to be built up, that portion must be illustrated and dimensioned on the detail drawing, ***Figure 19-56.*** The actual weld is represented by section lining.

Flange Weld

A *flange weld* is used to join thin metal parts together. Instead of welding to the surfaces of the parts to be joined, the weld is applied to the edges of thin material. A weld applied to thin metal could burn right through.

There are two distinct flange weld symbols (refer back to Figure 19-2): the first is called an edge-flange weld, ***Figure 19-57;*** the other is called a corner-flange weld, ***Figure 19-58.*** The straight line of this welding symbol is always drawn to the left of the partially curved line, regardless of the actual joint being illustrated. The edge-flange or corner-flange weld symbol



FIGURE 19-57 *Edge-flange weld.*



FIGURE 19-58 *Corner-flange weld.*



FIGURE 19-59 *Edge-flange weld symbol.*



FIGURE 19-60 *Corner-flange weld symbol.*

is placed above or below the reference line to indicate OPPOSITE side or ARROW side, but it is never on both sides, *Figures 19-59* and *19-60*.

Dimensioning a Flange Weld. It requires three dimensions to fully dimension a flange weld: the radius of the flange, the height above the point of tangency between parts, and the size of the weld itself, *Figures 19-61* and *19-62*. The three dimensions are added to the welding symbol as indicated previously. The welding symbol should appear at the peak of the joint as illustrated. If there is to be a root opening, that is, a space between parts, the required space must be indicated on the drawing, **not** on the welding symbol, *Figure 19-63*.



FIGURE 19-61 *Dimensioning a flange weld.*



FIGURE 19-62 *Dimensioning a corner-flange weld.*



FIGURE 19-63 *Root opening.*

Multiple Reference Line

If there is more than one operation on a particular joint, these operations are indicated on *multiple reference lines*. The first reference line closest to the arrow is for the first operation, the second reference line is for the second operation or supplemental data, and the third reference line is for the third operation or test information, *Figure 19-64*.

Spot Weld

Spot welding is a resistance welding process done by passing an electric current through the exact location where the parts are to be joined. Spot welding is usually done to hold thin sheet metal parts together. The resistance weld process uses three standard types of welds, *Figure 19-65*. Each is explained in full.

The symbol for a spot weld, as illustrated in *Figure 19-66*, is located tangent to or touching the reference line, and it uses the same added supplemental data symbols and dimensions as are illustrated with the fusion welding process, *Figure 19-67*. The tail is *always* included, in order to indicate the process required to make the weld (refer back to Figure 19-22).



FIGURE 19-64 *Multiple reference line.*



FIGURE 19-65 *Spot welds.*

FIGURE 19-66 *Spot weld symbol.*



FIGURE 19-67 *Spot weld symbol used with reference line.*

Dimensioning the Spot Weld

The diameter size of the spot weld is added directly to the left of the weld symbol, *Figure 19-68.* Sometimes the diameter size is omitted, and a required shear strength is inserted in its place. In this condition, an explanation of the value is added to the drawing by a note, *Figure 19-69.*

The spacing of the spot weld is called off by a number directly to the right of the weld symbol. This number is the pitch, and refers to the center-to-center distance between spots, *Figure 19-70.* The



FIGURE 19-68 *Diameter of spot weld.*



FIGURE 19-69 *Shear strength of spot weld.*





FIGURE 19-70 *Pitch of spot welds.*

Industry Application

Fitness Equipment Corporation (FEC) is one of the largest manufacturers in the United States of heavy-gage fitness machines. Their equipment is used in some of the leading commercial health clubs and by several professional football teams. FEC's products are made primarily of steel tubing. Consequently, welding is one of the company's primary manufacturing processes.

Because welding is such an important process to the company, new hires in the drafting department spend their first six weeks of employment on the shop floor learning about welding. According to Jerry White, FEC's chief drafter "we want our drafting and design personnel to know as much about our welding processes as our welders. Otherwise, how can they properly specify the various welds that might be needed on a given project? They don't have to develop the hand-eye coordination of a welder, but we do want them to know what kind of weld is called for in a given situation, how to properly indicate it using correct symbology, and how to properly dimension welds."

When asked about this practice, FEC's drafters are universally positive in their responses. Carla McDaniels summarized her reaction to six weeks on the shop floor as follows: "I was apprehensive at first. Having never been on the shop floor of a manufacturing plant, I had visions of a dark, dungeon-like atmosphere where men in hoods used torches on steel bars. However, my mentor was a woman, and the welding shop at FEC is cleaner than my house. It turned out to be a great six weeks. I learned a lot about welding, but I also learned what the welders need from me when I prepare a drawing. I also learned why my instructors back at MacArthur Technical Institute had stressed the need to put myself in the shoes of the people who would use my drawings. There are things I would have put in my drawings that are not needed and other things I would have left out that are needed."

Another drafter said, "Let me put it this way: based on how much I learned on that shop floor in six weeks, if I ever decide to design houses for a living I'm going to first spend six weeks working with a carpenter."

number of welds for a particular joint is added above or below the welding symbol in parentheses.

Contour and Finish Symbols

Contour and finish symbols are added to the welding symbol exactly as is done in the fusion welding symbol, *Figure 19-71*.

Projection Weld

A *projection weld* is similar to a spot weld and uses the same welding symbol. One of the two parts has a series of evenly spaced dimples stamped into it. Each stamped dimple is the location of an individual spot weld, *Figure 19-72*. A projection weld allows more penetration and, as a result, is a much better weld. Note that the dimples are **not** illustrated on the detail drawing.

The reference line (OPPOSITE side-ARROW side significance) is changed slightly as used for a projection weld. The OPPOSITE side-ARROW side indicates



FIGURE 19-71 *Contour and finish symbols.*



FIGURE 19-72 *Projection weld.*



FIGURE 19-73 *Projection weld symbol—dimple on bottom.*



FIGURE 19-74 *Projection weld symbol—dimple on top.*

which of the two parts to be joined has the dimples on it, *Figures 19-73* and *19-74*.

Dimensioning, contour, and finish symbols are applied to projection welds exactly as they are for spot welds.

FIGURE 19-75 *Seam weld symbol.*



FIGURE 19-76 *Seam weld symbol used with reference line.*

Seam Weld

A *seam weld* is like a spot weld, except that the weld is actually continuous from start to finish.

The welding symbol is modified slightly to indicate a seam weld, ***Figure 19-75***. ***Figure 19-76*** indicates how the seam weld symbol is applied to the reference line.

Welding Template

In order to simplify and speed up the drawing time for welding symbols, welding templates can be used. The welding template standardizes the size of each welding symbol and provides a quick, ready reference for welding symbols, ***Figure 19-77***.

Design of Weldments

Welded items are held together by fixtures during the actual welding process. This maintains the proper relationships between the parts. However, once the parts are released from the fixture, the potential for warping and other problems is introduced. This problem can be solved for the most part through proper design practices. Designers should keep the following objectives in mind when designing weldments.

1. Design for the convenience of the welder or welding machine/robot.
2. Design for proper heat control in the area of the weld.
3. Design in appropriate clamping mechanisms to prevent warping.



FIGURE 19-77 *Welding template.*

4. Design in outlets for the welding atmosphere.
5. Design in the appropriate clearances to accommodate for filler material.
6. Consider ease of operation after the weld is completed.

Summary

- Welding is a permanent way to join metal pieces. Welding is less expensive and more satisfactory than the casting process.
- The basic welding symbol consists of a reference line, a leader line and arrow, and, if needed, a tail. The tail is added for specific information or notes in regard to welding specifications, processes, or reference information.
- The size of a weld must be fully dimensioned so that there is no question whatsoever as to its intended and designed size. When a weld length is not specified, it is assumed to be continuous for the full length.
- When a weld is not continuous and is needed in only a few areas, section lining is used to indicate where the weld should be placed.
- Intermittent welds are a series of short welds. An increment is the length of the weld; the pitch is the center-to-center distance between increments.
- If a special finish must be made to a weld, a contour symbol must be added to the welding symbol. Three kinds of contour symbols are used: flush, convex, and concave.
- Any weld not made in the factory is called a field weld.
- There are five basic kinds of welding joints: butt, corner, T-joint, lap, and edge.
- Spot welding is a resistance welding process done by passing an electric current through the exact location where the parts are to be joined.
- A projection weld is similar to a spot weld and uses the same welding symbol. Dimples (projections) are stamped into one of the metal pieces. Each dimple is a location for a spot weld. A projection weld allows for more penetration. A seam weld is also like a spot weld except that the weld is continuous from start to finish.

Review Questions

Answer the following questions either true or false.

1. A plug weld and a slot weld both use the same symbol.
2. A field weld is one of the six major types of welds.
3. An intermittent weld is a series of short welds.
4. A welding symbol placed below the line means to weld the opposite side.
5. A flange weld is used to join thin metal parts together.
6. A process reference is a number that is placed at the bottom of the drawing as a reference.

7. A back weld is a weld applied to the opposite side of the joint after the major weld has been applied.
8. A backing weld is a weld applied to the opposite side of the joint after the major weld has been applied.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** one of the major types of welds?
   a. fillet
   b. groove
   c. joint
   d. back or backing
2. Which of the following is the correct definition for the term *root opening*?
   a. the allowed space between parts
   b. the actual depth of the chamber or groove
   c. the actual resistance between two parts
   d. none of the above
3. Which of the following correctly identifies the major welding processes?
   a. resistance and fusion
   b. field and contour
   c. fillet and groove
   d. plug and slot
4. Which of the following is **not** one of the major types of welding joints?
   a. lap joint
   b. edge joint
   c. L-joint
   d. T-joint
5. Which of the following is **not** true regarding spot weldings?
   a. It is usually done to hold sheet metal together.
   b. It is stronger than a projection weld.
   c. It is represented by the same symbol as a projection weld.
   d. It is a resistance welding process.
6. Which of the following is **not** one of the types of groove welds?
   a. bevel groove
   b. flare V
   c. square
   d. flare U
7. What indicates a field weld on the welding symbol?
   a. a filled-in flag
   b. a filled-in circle
   c. a filled-in square
   d. a filled-in triangle
8. What indicates that a weld is to be continuous around an object?
   a. adding a small square between the reference line and the leader line
   b. adding a small circle between the reference line and the leader line
   c. adding a small rectangle between the reference line and the leader line
   d. adding a small triangle between the reference line and the leader line

Chapter 19 Problems

The following problems are intended to give the beginning drafter practice in studying the many factors involved in dimensioning and calling off welding processes. The student will sharpen skills in centering the views within the work area, line weight, dimensioning, and speed.

Conventional Instructions

The steps to follow in laying out the following problems are:

STEP 1 Study the problem carefully.

STEP 2 Choose the view with the most detail as the front view.

STEP 3 Make a sketch of the required views.

STEP 4 Add required dimensions to the sketch per the latest drafting standards.

STEP 5 Add welding symbols as required to the sketch per the latest welding standards.

STEP 6 Lightly lay out all required views and check that they are centered within the work area.

STEP 7 Check that all dimensions are added using the latest drafting standards.

STEP 8 Darken in all views using correct line thickness and add all dimensioning using light guidelines.

STEP 9 Recheck all work and, if correct, neatly fill out the title block using light guidelines and neat lettering.

STEP 10 Recheck that all required welding symbols are added correctly.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions

for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scales of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

Problems 19-1 through 19-11

Follow the listed steps, using the latest drafting standards.

PROBLEM 19-1



PROBLEM 19-2



PROBLEM 19-3



PROBLEM 19-4



PROBLEM 19-5



PROBLEM 19-6



PROBLEM 19-7



PROBLEM 19-8



PROBLEM 19-9



PROBLEM 19-10



PROBLEM 19-11



Problems 19-12 through 19-15

Convert the following problems from Chapter 5 from casting drawings to weldment drawings:

PROBLEM 19-12

Refer back to Problem 5-27.

PROBLEM 19-13

Refer back to Problem 5-28.

PROBLEM 19-14

Refer back to Problem 5-36.

PROBLEM 19-15

Refer back to Problem 5-37.

20

Modern Manufacturing: Materials, Processes, and Automation

KEY TERMS

Abrasive water jet machining (AWJM)
Alloy steel
Aluminum
Angle plate fixture
Angle plate jigs
Annealing
Arbor press
Band saw (or contour band machine)
Bending
Blanking
Boring mill
Box jig
Breakdown (or bender)
Broaches
Broaching machine
Built-up tool
Case hardening
Cast iron
Cast steels
Cast tool
Casting
Centrifugal casting
Ceramics
Channel jigs
Cheek
Chemical milling
Chuck
Clapper box
Closed jigs
Composites
Compound
Continuous path
Cope
Copper
Core prints
Cutoff saw
Cutting off
Cylindrical grinder
Die
Die casting
Draft
Drag
Drawing
Drill bushings
(illegible)

CHAPTER OUTLINE

Engineering materials • Traditional manufacturing processes • Casting • Forging • Extruding • Stamping • Machining • Special workholding devices • Heat treatment of steels • Nontraditional machining processes • Automation and integration (CAM and CIM/FMS) • Computer-aided manufacturing (CAM) • Industrial robots • CIM/FMS • Just-in-time manufacturing (JIT) • Manufacturing resource planning (MRPII) • Statistical process control (SPC) • Summary • Review questions

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Define the concept of engineering materials.
- Distinguish between the two broad categories of engineering materials.
- List the most widely used types of metals in modern manufacturing.
- List the most widely used nonmetals in modern manufacturing.
- Define the term *composites.*
- Describe the principal types of casting processes.
- Describe the most common types of forging processes.
- Define the term *machining.*
- Describe the most common machining processes.
- Explain the concept of computer-numerically controlled machines.

(continued)

(KEY TERMS continued)

Drill press
Drop forging
Duplex fixture
Elastomers
Electrical discharge grinding (EDG)
Electrical discharge machining (EDM)
Electrical discharge wire cutting (EDWC)
Electrochemical discharge grinding (ECDG)
Electrochemical grinding (ECG)
Electrochemical honing (ECH)
Electrochemical machining (ECM)
Electrochemical turning (ECT)
Electromechanical machining (EMM)
Electron beam machining (EBM)
Engineering materials
External broaching
Extruding
Finishing impression
Fixed-renewable bushing
Fixtures
Flask
Foolproofing
Forging
Forming
Filler
Gate
Green sand
Hardening
Heat treatment
High-performance alloys
Horizontal boring mills
Hurry-up-and-wait
Hydrodynamic machining (HDM)
Indexing fixture
Indexing jig
Internal broaching
Investment casting
Jigs
Laser beam machining (LBM)
Lathe
Lead
Lead time
Leaf jig
Liner bushings
Lost wax casting
Machining
Magnesium
Manufacturing
Maraging steel
Milling machine
Modified angle plate fixture
Modified angle plate jigs
Multistation jig
Nontraditional machining
Normalizing
Numerically controlled machine tools
Open die
Parting
Parting line
Pattern
Removing

(CHAPTER OBJECTIVES continued)

- Explain the concept of jigs.
- Explain the concept of fixtures.
- Describe the most widely used nontraditional machining processes.
- Explain the concept of automation.
- Explain the concept of computer-aided manufacturing (CAM).
- Define the term *robot.*
- Explain the concept of computer-integrated manufacturing (CIM).
- Explain the concept of the flexible manufacturing system (FMS).

This chapter describes the processes used in a modern manufacturing setting to produce metal and nonmetal products as well as the engineering materials from which these products can be made. It also describes how these processes have been automated and integrated in an effort to improve quality and increase productivity.

The ultimate purpose of any engineering drawing is to provide the information necessary to make or fabricate an object. To achieve this purpose an engineering drawing must completely describe and detail the desired object. The drawing must show the specific size and geometric shape of the object as well as furnishing the related information concerning the material specifications, finish requirements, and any special treatments required.

To properly construct an engineering drawing, the designer must be thoroughly familiar with the materials and methods used to transform the drawn image into the actual object specified in the drawing. By knowing the materials and basic processes used to manufacture an object, the designer can design the object with the manufacturing processes in mind. This will not only make manufacturing easier but will often reduce the cost of a manufactured product. Therefore, the purpose of this chapter is to acquaint the new designer with the basic processes used to fabricate objects, as well as the capabilities and limitations of the machine tools used to machine these objects to their final form.

Engineering Materials

Manufacturing is the enterprise through which raw materials are converted into finished products. This conversion adds value to the raw materials. In a modern engineering and manufacturing setting these

materials are referred to as *engineering materials*. Engineering materials can be divided into two broad categories: metals and nonmetals. Metals include steels, alloy steels, and a variety of high-performance alloys. Nonmetals include plastics, composites, elastomers, and ceramics.

Metals

Metals are widely used in modern manufacturing. The most frequently used metals are carbon steels; alloy steels; high-strength, low-alloy steels; stainless steels; maraging steels; cast steels; cast irons; high-performance alloys; tungsten, molybdenum, and titanium; aluminum; copper; magnesium; lead; tin; zinc; and powdered metals. These various metals are described in the following paragraphs.

Carbon Steels

The main elements in steels are iron and carbon. Carbon steels are divided into three groups based on their carbon content. Low-carbon steels contain from .001 to .30% carbon. Medium-carbon steels contain from .70 to 1.30% carbon. High-carbon steels contain from .70 to 1.30% carbon. Certain grades of carbon steels also contain boron to improve hardenability and aluminum to control grain size and promote deoxidation. The following types of products are made of carbon steels: bar, sheet, strip, plate, wire, tubing, and structural shapes.

Alloy Steels

An *alloy steel* is any steel that contains one or more alloying elements added to produce characteristics not available in unalloyed carbon steels. Widely used alloying elements include manganese, silicon, copper, aluminum, chromium, cobalt, columbium, molybdenum, nickel, titanium, tungsten, vanadium, and zirconium. Such alloys are added to improve the mechanical and physical properties of steels.

High-Strength, Low-Alloy Steels

These are steels that are significantly stronger than carbon steels as a result of the addition of small amounts of alloying elements and special processing. These alloying elements include manganese, silicon, phosphorus, copper, aluminum, chromium, niobium, vanadium, titanium, molybdenum, nickel, zirconium, nitrogen, and calcium. These steels are categorized according to composition. The different categories vary as to strength, toughness, formability, weldability, and corrosion resistance.

(KEY TERMS continued)

Photochemical machining
Piercing
Planers
Plasma
Plasma arc machining (PAM)
Plastics
Plate fixtures
Plate jigs
Point-to-point
Positioned
Powder metallurgy
Powdered metals
Power saw
Precision grinders
Press forging
Press-fit bushings
Process synchronization
Progressive die
Punching
Quench
Refractory metals
Renewable bushings
Repeatability
Riser
Robot
Rolling
Rotary ultrasonic machining (RUM)
Sand core
Sandwich jigs
Shaper
Shaving
Shearing
Shrink rule
Shrinkage
Slip-renewable bushings
Slitting
Sprue hole
Stainless steels
Stamping
Statistical process control (SPC)
Surface grinder
Table jigs
Tempering
Template jigs
Tin
Tolerance
Tool forces
Trimming
Ultrasonic machining (USM)
Ultrasonically assisted machining (UAM)
Upsetting
Vertical boring mills
Vertical turret lathe
Vise jaw fixture
Waste
Water jet machining (WJM)
Welded tool
Zinc

Stainless Steels

Stainless steels are steels that contain 10.5% or more chromium. The special appearance of stainless steels is the result of a chromium-based oxide film that coats the metal's surface. Stainless steels also contain a number of other elements that are added to improve their machinability and corrosion resistance. These elements include nickel, molybdenum, copper, titanium, silicon, manganese, columbium, aluminum, nitrogen, and sulfur. There are almost 60 standard grades of stainless steel, but there are five main types. These types are austenitic, ferritic, martensitic, prescription-hardening, and duplex.

Maraging Steels

Maraging steels are a special class of high-strength steels in which nickel is the primary alloy. The name *maraging* is derived from the term *martensite age hardening*, which is a process of age hardening of a matrix composed of low-carbon, iron-nickel martensite. The process used to produce maraging steels is a double-vacuum melting process. The first process involves vacuum-induction melting. The second process involves vacuum arc remelting. This double-vacuum process maintains a high level of purity and reduces residual elements. Maraging steels are produced in bar, plate, and sheet form.

Cast Steels

Cast steels are steels that are produced in ingot form by melting all component elements together and pouring the molten metal into a mold. This is an intermediate step. Cast steel ingots are subsequently hot or cold worked into another shape. Alloying elements include nickel, chromium, vanadium, and copper. The main types of cast steels are carbon, low-alloy, corrosion-resistant, and heat-resistant.

Cast Irons

Cast irons are metals in a family of cast ferrous metals. Cast irons are distinguished from steels by the relative carbon content (i.e., less than 2% in steels and over 2% in cast irons). In addition, cast irons also contain from 1% to 3% silicon. These differences are the basis of the corresponding differences in how steels and cast irons can be used. The metallurgical properties of cast irons make them easy to melt and cast. These are the following basic types of cast irons: white, malleable, gray, ductile, and compacted-graphite iron.

High-Performance Alloys

High-performance alloys are a group of metals that have high strength and/or high corrosion resistance over a broad range of temperatures. High-performance alloys are primarily iron-nickel, nickel, cobalt, or iron-based. They typically have a complex composition with at least three and sometimes over 10 component elements. Also known as the super-alloys, their most common elements include chromium, molybdenum, tungsten, columbium, aluminum, cobalt, titanium, carbon, and nitrogen. The most common applications of high-performance alloys are in aircraft and aerospace settings.

Tungsten, Molybdenum, and Titanium

Tungsten and molybdenum are known as *refractory metals* because of their exceptional ability to withstand high temperatures. They also have the following additional characteristics: low coefficient of expansion, high modulus of elasticity, high resistance to thermal shock, high conductivity, and excellent hardness properties at high temperatures. Unlike tungsten and molybdenum, titanium is not a refractory metal, but its properties are similar to such metals. The processes used to produce these three metals are similar. They are extracted from ore, processed into chemicals, and processed further into powders or sponges. Typical applications of tungsten and molybdenum are the automotive, aerospace, mining, chemical, processing, electrical, nuclear, petroleum processes, ordnance, and metal-processing industries.

Titanium is used primarily in the aerospace, chemical, and medical industries.

Aluminum

Aluminum is a bright, silvery metal that is very light. A given amount of ferrous metal will weigh three times as much as the same amount of aluminum. Aluminum is an abundant metal, accounting for approximately 8% of the earth's outer surface. Pure aluminum is ductile, soft, and weak compared with other metals. However, with the addition of alloying elements such as copper, magnesium, manganese, and zinc, it can be made much harder and stronger. Aluminum is light, an excellent conductor, and able to resist corrosion. Consequently, it is widely used in both manufacturing and construction.

Copper

Copper is a heavy metal that is salmon pink in its pure form and abundant. It is nonmagnetic and has

excellent conductivity. Only silver is a better conductor. There are over 300 different types of copper and copper alloys. They are produced in a variety of forms including strip, plate, sheet, pipe, tube, rod, forgings, wire, foil, extrusions, and castings. Copper is widely used in both manufacturing and construction.

Magnesium

Magnesium is a soft, silvery-white metal that lacks the strength needed for structural uses. However, it is extremely light and machinable. To increase its strength, magnesium is alloyed with aluminum, manganese, lithium, thorium, zinc, and zirconium. The result is a metal that can be machined at high speeds, has good conductivity, a high level of fatigue, and is dent resistant.

Lead

Lead is a dark gray metal that has the following characteristics: high density, low melting point, corrosion resistance, chemical stability, malleability, lubricity, and electrical properties. Lead can be easily produced in a variety of forms.

Tin

Tin is a silvery-white metal that is soft and ductile. Its high level of malleability allows tin to be drawn into wire or hammered into extremely thin sheets. Tin is too weak to be used in its pure form, but alloyed with antimony, copper, lead, zinc or silver, tin becomes useful. Its most common use is in coating steel containers used to preserve food. Tin is also used in solder alloys, bronzes, fusible alloys, type metals, pewter, and dental amalgams. Tin chemical compounds are used in the electroplating, ceramics, plastics, pesticide, and antifungal industries.

Zinc

Zinc is a bluish-white metal that is widely used in manufacturing. Only iron, aluminum, and copper are more widely used than zinc. Zinc is produced in castings and is widely used for coating other materials. Zinc alloys offer several advantages over other diecast metals, including ease of casting, strength, ductility, and the ability to hold close tolerances and to be cast in thin sections.

Powdered Metals

Powdered metals are exactly what the name says. They are produced by atomization, electrolysis, chemical reduction, or oxide reduction. Various powdered metals are mixed and sintered to produce alloys with an almost endless number of compositions. Sintering produces bonds among the various powdered particles. The properties of products made from powdered metals depend on which metals are mixed, in what amounts, and by what processes. These characteristics can be controlled by varying particle size, particle shape, size distribution, sieve analysis, bulk density of the powder, rate of flow into the die, and the compressibility of the powder in the die.

Nonmetals

Nonmetals are widely used in modern manufacturing. The most widely used nonmetals are plastics, composites, ceramics, and elastomers. These various nonmetals are described in the following paragraphs.

Plastics

Plastics are nonmetal materials that are made from either natural or synthetic resins. Most plastics used in modern manufacturing are made from synthetic resins. There are many different kinds of plastics, including polystyrene, high-impact polystyrene, acrylics, polycarbonate, ABS, acetal, nylon, polypropylene, polyethylene, epoxy, and phenolic. Most plastics used in an engineering or manufacturing setting are made from thermoplastic resins. Such plastics have the following characteristics: (a) thermal, mechanical, chemical, corrosion resistance, and fabricability; (b) ability to sustain high mechanical loads; and (c) predictable performance.

Thermosets. Thermosets are a special subset of engineering plastics that are used in applications where resistance to heat and environmental conditions is important. For example, thermosets have long been used for insulation in electrical and electronics applications. The recipes for thermoset molding compounds can be varied to create just the right characteristics for a given application. Distinctive properties of thermosets include dimensional stability, low-to-zero creep, low water absorption, maximum physical strength, good electrical properties, high heat deflection temperatures, high heat resistance, minimum thermal expansion, and specific gravities in the 1.35 to 2.00 range.

Thermoplastics. Thermoplastics are a special subset of engineering plastics that are very similar to thermosets. However, processing advantages have allowed thermoplastics to replace thermosets in many applications. The benefits of thermoplastics over thermosets are faster molding, lighter weights, ability to have thinner walls that allow for more complex

designs, and greater impact resistance. However, thermosets typically experience less creep at higher temperatures.

Composites

Composites are materials created by combining two or more materials. Perhaps the most readily recognizable composite is plywood. Fiberglass is another example of a composite. Composite technology is divided into four broad areas: organ matrix composites (resins), metal matrix composites, carbon-carbon composites, and ceramic matrix composites. Composites can be divided into two categories in terms of how they are produced; laminates and sandwiches. Laminates consist of two or more layers bonded together. Sandwiches consist of thick, low-density layers (i.e., honeycomb or foam materials) pressed between thin layers of higher strength, higher density material. Applications of composites are extensive and varied. They include aircraft and aerospace applications, athletic equipment, automobiles, prosthetic devices, printed circuit boards, boats, and many others.

Ceramics

Ceramics are materials made by combining metallic and nonmetallic elements such as oxides, carbides, and nitrites. Glass, bricks, tile, and porcelain are all common ceramics. Refractory ceramics are important in modern manufacturing because of their usefulness in electronics applications. They are used in thermistors, rectifiers, capacitors, transducers, and for high-voltage insulation. Characteristics of ceramics include the fact that they are hard, brittle, have a high melting point, have low conductivity, are chemically and thermally stable, have high compressive strength, and have high creep resistance.

Elastomers

The most recognizable form of elastomer is natural rubber. *Elastomers* are linear polymers that are able to stretch and return to their original shape and size (i.e., a rubber band). Widely used elastomers include polyacrylate, ethylene propylene, neoprene, polysulfide, silicone, and urethane. Common applications of elastomers include oil hoses, o-rings, electric insulation, belts, gaskets, seals, value disks, and foam padding.

Traditional Manufacturing Processes

The term *manufacturing processes* refers to the basic methods used by the shop to make the object described in the engineering drawing. The specific processes used to make the object depend on the object itself. In some cases the part may be cast, while other parts may be forged, extruded, or stamped. In many instances the part, once fabricated into its basic form, must also be machined to maintain a specific degree of accuracy or to produce a feature not possible with other manufacturing processes.

When the manufacturing shop receives the engineering drawing, in the form of a part print, it is first reviewed to ensure all pertinent data and information necessary to make the object are contained in the drawing. During this review, the shop personnel will consider several factors necessary to determine how the part must be made. These factors include: the type and condition of the material used to make the object, the overall size and shape of the part, the types of operations required, the required accuracy of the part, and the number of parts to be made.

The type and condition of the material used to make the part are important considerations. Some parts may be made from solid bar stock while other parts must be extruded, cast, forged, or stamped. In most cases, parts made from bar stock require the least lead time. The *lead time* is the interval from the time the shop receives the drawing until production begins. Most shops maintain a sufficient supply of bar stock to begin production as soon as the drawing is received. However, when a part must be extruded, cast, forged, or stamped, a longer lead time is required to make the necessary molds or dies to fabricate the object.

The size and shape of the object must be considered to determine if the object is within the capabilities of the shop to make. In addition, the size and shape may also determine the size of the machine tools required as well as the datum, or reference, surfaces used to locate the part during manufacture.

The types of operations required determine the types of equipment and machine tools needed to make the part. If, for example, the part requires holes, a drill press, vertical milling machine, or other machine tool may be used. The next consideration, the required accuracy of the part, also determines how the operations are performed. A hole with a required accuracy of .002″ (0.05 mm), for example, would require reaming, while a hole with a required accuracy of .020″ (0.5 mm) could be drilled.

The number of parts to be made will frequently determine if the part should be cast, forged, extruded, or machined from solid stock. Likewise, the number of parts will also determine if any special workholders are to be made. Larger production runs will normally justify more sophisticated tools and processes since the cost can be spread over a larger

number of parts. Smaller production runs normally demand the parts be made at the lowest possible cost with little or no investment in special molds, dies, or workholders.

While each of these factors has been separated for the purpose of this discussion, in practice each is considered as part of the other. These factors are so closely related in production that they frequently overlap, and one cannot be considered without the others.

The primary processes used to fabricate manufactured products are casting, forging, extruding, stamping, and machining. To use these processes to their best advantage, the designer must be familiar with the strengths and weaknesses of each process as well as the fundamental aspects of each process.

Casting

Casting is a process of pouring molten metal into a mold that contains the desired shape in the form of a cavity. The principal types of casting used in manufacturing today are sand casting, investment casting, centrifugal casting, and die casting.

Sand Casting

Sand casting is the most common type of casting method. The major components of the molds used to make sand castings are shown in ***Figure 20-1*** and include the *flask, pattern,* and *green sand.* The flask is a two-part box, or frame, used to contain the sand. The top half of the flask is called the *cope* and the bottom half is called the *drag.* Occasionally, a third section may be installed between the cope and drag. This section is called a *cheek,* and is used where a deep or complex shape must be cast. In sand casting the mold is prepared by ramming the green sand around a model of a part, called the pattern. The model is then removed to form the cavity for the molten metal. The plane of division between the cope and drag is called the *parting line.* In many castings, the parting line occurs at the approximate middle of the part. The parting line can be seen on most castings by a ragged line that is usually ground off.



FIGURE 20-1 *Components of a sand casting mold.* (From Thode, *Materials Processing,* Delmar Publishers Inc.)

The molten metal enters the mold through the *sprue hole* and is directed to the cavity by one or more *gates.* The sprue hole is formed by installing a sprue peg in the cope. This peg is then removed after the final ramming of the cope. The *riser* is used to vent the mold and to allow gases to escape. The riser also acts as a small reservoir to keep the cavity full as the metal begins to shrink during the cooling process.

Once the cope and drag are rammed and the pattern is removed, a solid part could be poured in the mold. However, in some cases a hollow part, or one that has large holes, must be poured. To reduce the amount of material needed to fill the cavity and to reduce the time necessary to machine the part, a *sand core* may be installed in the cavity. When sand cores are intended to be installed in a cavity, *core prints* must also be provided to locate and anchor the sand cores during the casting process. Core prints are normally a simple extension of the pattern.

Making Patterns. When patterns are made for casting, two important factors must always be considered. The first is the draft. *Draft* is the slope or taper of the sides of a pattern that permits it to be removed from the cope and drag without disturbing the cavity. The draft also permits the cast part to be removed easily from some molds. The amount of draft necessary will normally depend on the part being cast, but will normally be about 1°.

The second consideration is shrinkage. When metals are cast, a certain amount of *shrinkage* occurs as the metal cools. The specific amount of shrinkage depends on the metal being cast. Steel, for example, shrinks at a rate of approximately 3/16″ per foot, while cast iron shrinks about 1/8″ per foot. To allow for this shrinkage and to make sure the final part is the correct size, the pattern must be made slightly larger than the final size of the desired part.

When making a pattern, the pattern maker will normally use a shrink rule to compensate for the shrinkage. A *shrink rule, Figure 20-2,* is a standard steel rule that has the graduations marked for a specific amount of shrinkage. A shrink rule used for cast iron has an extra 1/8″ added to each foot, while a shrink rule for steel has an additional 3/16″ added.

In most instances, when a pattern must be made, the pattern maker will receive the engineering drawing that contains all the final sizes of the part. The pattern maker will then make all the necessary calculations needed to make the oversized pattern. But, occasionally, the pattern maker will be given a drawing

FIGURE 20-2 *Shrink rule.* (Courtesy L. S. Starrett Co.)

with all the calculations already made to produce the pattern. In either case, the patterns must be made to suit the material being cast.

Investment Casting

Investment casting produces parts with great detail and accuracy, while at the same time allowing very thin cross sections to be cast. In this process, the pattern is made by casting wax in the desired form. The pattern is then placed in a sand mold and the mold is fired to melt out the wax pattern. This process is also referred to as *lost wax casting*. The molten metal is then fed into the mold to produce the cast part.

Centrifugal Casting

Centrifugal casting, ***Figure 20-3***, is a process of pouring a measured amount of molten metal into a rotating mold. This process can be used for a single mold or multiple molds. The centrifugal force created by the rotation forces the molten metal to fill the cavity. This same centrifugal force, along with the measured amount of material, also controls the wall thickness of the cast part and results in a less porous cast surface than is possible with sand casting. The molds used for this purpose are usually permanent molds made from metal rather than sand. These molds are used repeatedly and produce highly accurate parts requiring very little machining. However, due to their cost, permanent molds are normally used only for high-volume production.



FIGURE 20-3 *Centrifugal casting.*

Die Casting

Die casting, ***Figure 20-4***, is a process in which molten metal is forced into metal dies under pressure. This process is very well suited for materials such as zinc, aluminum, copper, and magnesium alloys. Parts produced by die casting are superior in appearance and accuracy and require little or no machining to final size.

Powder Metallurgy

Powder metallurgy, ***Figure 20-5***, while not an actual casting process, does have some similarities to casting. In the *powder metallurgy* process, metal particles, or powder, are blended and mixed to achieve the desired composition. The powder is then forced into a die



FIGURE 20-4 *Die casting.* (From Thode, *Materials Processing*, Delmar Publishers Inc.)



FIGURE 20-5 *Producing parts with powder metallurgy.* (Courtesy Metal Powder Industry Foundation)

of the desired form under pressure from 15,000 to 100,000 pounds per square inch. The resulting heat fuses the powder into a solid piece that can be machined.

Forging

Forging is the process of forming metals under pressure using a variety of different processes. The most common forms of forging are drop forging and press forging. Other variations of forging include rolling and upsetting.

Drop Forging

Drop forging is the process of forming a heated metal bar, or billet, in dies. In practice, the heated metal is placed on a lower portion of a forging die and struck repeatedly with the upper die portion. This forces the metal into the shape of the cavity of the dies. The pressure required to form the metal is produced by a drop hammer.

Most drop forge dies contain at least four different stations, or dies, to complete the part, *Figure 20-6.* The first station is called the *fuller.* This station is used to rough-form the part to fit the other cavities. The second station, when used, is called the *breakdown,* or *bender.* This station forms the part into any special contours required by the next station, the roughing impression. The roughing impression rough-forms



FIGURE 20-6 *Drop forging process.*

the part to the desired form. The final station is called the *finishing impression* and is used to finish the part to the desired shape and size. Additional stations, such as a trimmer to remove the fins and a cutoff to sever the forged part from the bar, may also be included on the die if they are necessary.

Press Forging

Press forging is a single-step process in which the heated metal bar or billet is forced into a single die and is completed in a single press stroke. The press normally used for press forging is hydraulic.

Rolling

Rolling is a process in which the heated metal bar is formed by passing through rollers having the desired form impressed on their surfaces. Rolling is also frequently used to flatten and thin out thick sections.

Upsetting

Upsetting, Figure 20-7, is a process used to enlarge selected sections of a metal part. Bolt heads, for example, are normally produced by an upsetting process.



FIGURE 20-7 *Upsetting.*

Extruding

Extruding is a process of forcing metal through a die of a desired form and cross section. The bars produced are then cut to the required lengths. Typical examples of extruded parts include parts for aluminum windows and doors. Extrusions provide a nearly final shape, as shown in ***Figure 20-8*** and, in many cases, only need to be cut off and machined slightly to complete a finished part.

Stamping

Stamping is a process of using dies to cut or form metal sheets or strips into a desired form. The main tool used for metal stamping is a die. The term *die* has a double meaning. It can be used to describe the entire assembled tool or the lower cutting part of the tool. The exact meaning of the term can usually be determined from the context of its use. The principal parts of a die are shown in ***Figure 20-9.*** The upper die shoe is used to mount the punch. The die is mounted on the lower die shoe. The guide pins and guide pin bushings are used to maintain the alignment between the punch and die. The stripper is designed to strip the stock material from the punch after the cutting stroke of the die.



FIGURE 20-9 *Metal stamping die.*

When more than one operation takes place on a part during a single stroke, blanking and punching, for example, the operation is said to be *compound.* However, when several operations take place sequentially in a die, the die is called a *progressive die.*

The principal stamping operations normally performed are shearing, cutting off, parting, blanking, punching, piercing, perforating, trimming, slitting, shaving, bending, forming, drawing, coining, and embossing.

Operations that Produce Blanks

The operations that produce blanks are shearing, cutting off, parting, and blanking, ***Figure 20-10.*** *Shearing* is a cutting action performed along a straight line. *Cutting off* is a cutting operation performed on a part to produce an edge other than a straight edge. In many cases, cutting off is used to finish the edges of a part. Like shearing, cutting off does not produce any scrap. *Parting,* on the other hand, is also an operation used to finish the edges of



FIGURE 20-8 *Extruding.*



FIGURE 20-10 *Operations that produce blanks.*



FIGURE 20-11 *(A) Punching operation to produce holes; (B) Piercing operation to produce holes.*

a part, but, unlike the other operations, parting does produce scrap.

Blanking is an operation that produces a part cut completely by the punch and die. In blanking operations, the piece that falls through the die is the desired part. The scrap is the skeleton left on the stock strip.

Operations that Produce Holes

The operations that produce holes are punching, piercing, and perforating. *Punching* is an operation that cuts a hole in a metal sheet or strip, *Figure 20-11A*. In punching, the piece that falls through the die is scrap, and the area on the strip is the desired part. Punching is normally performed on parts that are to be blanked to provide holes for bolts, screws, or similar parts.

Piercing is an operation similar to punching, except that in piercing no scrap is produced, *Figure 20-11B*. A pierced hole is sometimes used to increase the thickness of metal around a hole for tapping threads in a stamped part. *Perforating* is simply a punching operation performed on sheets to produce either a uniform hole pattern or a decorative form on the sheet.

Operations that Control Size

The operations used to control size are trimming, slitting, and shaving, *Figures 20-12A* and *20-12B*. *Trimming* is an operation performed on formed or drawn parts to remove the ragged edge of the blank. *Slitting* is performed on large sheets to produce thin stock strips. Slitting may be performed by rollers or by straight blades. *Shaving* is an operation performed on a blanked part to produce an exact dimensional size or to square a blanked edge. Shaving produces a part with a close dimensional size, and a cut edge that is almost perpendicular to the top and bottom surfaces of the blanked part.

Operations that Bend or Form Parts

The operations used to bend or form parts are bending, forming, and drawing, *Figure 20-13*. *Bending* is an operation in which a metal part is simply bent to a desired angle. *Forming*, on the other hand, is an operation in which a part is bent or formed into a complex shape. Forming is also a catchall word frequently used to describe any bending operation that does not fall into one of the other categories. *Drawing* is a process of stretching and forming a metal sheet into a shape similar to a cup or top hat.



FIGURE 20-12 *(A) Operation that controls size-trimming; (B) Operation that controls size-shaving.*



FIGURE 20-13 *Operations that bend or form parts.* (From Thode, *Materials Processing,* Delmar Publishers Inc.)

Machining

Machining is the process of removing metal with machine tools and cutters to achieve a desired form or feature. The principal types of machine tools used to perform these operations are lathes, milling machines, drill presses, saws, and grinders. Other machines that are variations of the basic machines used in the machine shop include shapers and planers, boring mills, broaching machines, and numerically controlled machines. The specific type of machine used to perform a particular machining operation is determined by the type of operation and the degree of accuracy required.

Lathes

A lathe, *Figure 20-14,* is one of the most commonly used and versatile machine tools in the shop. Typically, a *lathe* performs such operations as straight and taper turning, facing, straight and taper boring, drilling, reaming, tapping, threading, and knurling, *Figure 20-15.*

In operation, the workpiece is held in the headstock and supported by the tailstock. The cutting tool is mounted in the tool post and is traversed past the rotating workpiece to machine the desired form, *Figure 20-16.* The most common method used to hold parts in a lathe is with a chuck. A *chuck* is a device much like a vise, having movable jaws that grip and hold the workpiece. The most popular type of chuck is the three-jaw chuck, but there are also two-jaw, four-jaw, and six-jaw chucks as well. Other types of devices used to hold and drive a workpiece in a lathe include collets, face plates, drive plates, and lathe dogs.

Milling Machines

Milling machines are used to machine workpieces by feeding the part into a rotating cutter. The two basic



FIGURE 20-14 *Tools for turning.* (Courtesy Monarch Co.)



FIGURE 20-15 *Basic lathe operations.* (From Thode, *Materials Processing,* Delmar Publishers Inc.)

variations of the milling machine are the vertical milling machine and the horizontal milling machine, *Figure 20-17.*

In operation, the milling cutter is mounted in either the spindle or arbor, and the workpiece is held on



FIGURE 20-16 *Lathe setup for straight turning.* (From Krar and Oswald, *Turning Technology,* Delmar Publishers Inc.)

the machine table. The most commonly used device to mount the workpiece for milling is the milling machine vise, but the workpiece may also be held directly on the machine table or in other workholding devices. The operations most frequently performed on a milling machine include plain milling, face milling, end milling, straddle milling, gang milling, form milling, keyseat milling, and gear cutting, *Figure 20-18. Figures 20-19A* and *20-19B* show two types of cutters commonly used for milling operations.

Drill Presses

A *drill press, Figure 20-20,* is a machine that is used mainly for producing holes. The principal types of drill presses used in the shop are the radial drill press and the sensitive drill press.

The operations normally performed on drill presses include drilling, reaming, tapping, chamfering, spotfacing, counterboring, countersinking, reverse countersinking, and reverse spotfacing, *Figure 20-21.*

FIGURE 20-17 *CNC milling machine.* (Courtesy Cincinnati Milacron)

FIGURE 20-18 *Basic milling machine operations.* (From Thode, *Materials Processing,* Delmar Publishers Inc.)

(A)

(B)

FIGURE 20-19 *(A) and (B) Standard milling cutters.* (Courtesy Cincinnati Milacron)

FIGURE 20-20 *Drill press.* (Courtesy Wilton Corp.)

When using a drill press, the workpiece is normally held in a vise or clamped directly to the machine table. The drill or other cutting tool is mounted in the machine spindle and is fed into the workpiece either by hand or with a mechanical feed unit.

Power Saws

The *power saws* used most often in the machine shop are the contour band machine or band saw and the cutoff saw, ***Figure 20-22.*** The contour band machine or *band saw* is used primarily for sawing intricate or detailed shapes; the *cutoff saw* is used to cut rough bar stock to lengths suitable for machining in other machine tools.



FIGURE 20-21 *Basic drill press operations.*



FIGURE 20-22 *CNC machine tool.* (Courtesy DoAll Corp.)

Precision Grinders

Precision grinders are available in several styles and types to suit their many and varied applications. The principal types of precision grinders used in the machine shop are the surface grinder and the cylindrical grinder, among others.

The *surface grinder*, ***Figure 20-23***, is mainly used to produce flat, angular, or special contours on flat workpieces. The most popular variation of this machine consists of a grinding wheel mounted on a horizontal spindle and a reciprocating table that traverses back and forth under the grinding wheel. One other variation of the surface grinder frequently found in the machine shop uses a vertical spindle and a round, rotating table, ***Figure 20-24***. The workpiece is generally mounted and held on a magnetic chuck during the grinding operation on both styles of surface grinders.

Cylindrical grinders are used to precisely grind cylindrical or conical workpieces. For grinding, the workpiece is mounted either between centers or in a precision chuck, much like a lathe. The grinding wheel is mounted behind the workpiece on a horizontal spindle. The table of the grinder traverses the



FIGURE 20-23 *Surface grinder.* (From Thode, *Materials Processing*, Delmar Publishers Inc.)



FIGURE 20-24 *Vertical spindle-rotating table surface grinder.* (From Thode, *Materials Processing*, Delmar Publishers Inc.)

workpiece past the grinding wheel in a reciprocating motion, while the workpiece rotates at a preset speed.

Shapers and Planers

Shapers and *planers* are machine tools that use single-point cutting tools to perform their cutting operations. The shaper uses a reciprocating ram to drive the cutter. The cutting tool on this machine tool is mounted on the end of the ram in a unit called the *clapper box*. The clapper box can be positioned vertically or at an angle, depending on the work to be performed. The depth of cut is adjusted by lowering the vertical slide of the clapper box or by raising the position of the table. The workpiece is mounted on the table or vise and is fed past the reciprocating cutter by the table feed. The length and position of the stroke are regulated by the position of the ram and are easily adjusted to suit the size of the workpiece.

Planers operate in a manner similar to the shaper. The major differences between these two machines are their size and method of cutting. The planer is normally much larger than the shaper and the work, rather than the cutter, moves on the planer. In operation, the workpiece is mounted on the table of the planer, and the table reciprocates under the stationary tool. As the table reciprocates, the tool is moved across the workpiece by the feed unit. The depth of cut is determined by the height of the tool from the table and is adjusted by lowering or raising the cross beam. The length and position of the cut are determined by the position of the table.

These processes are seldom used today.

Boring Mills

A *boring mill*, ***Figures 20-25*** and ***20-26***, is a machine tool normally used to machine large workpieces. The two common variations of these machines are



FIGURE 20-25 *Boring mill.* (Courtesy Cincinnati Milacron)



FIGURE 20-26 *CNC vertical machining center.* (Courtesy Cincinnati Milacron)

horizontal and vertical. The distinction between the two is determined by the position of the spindle. *Horizontal boring mills* perform a wide variety of different machining tasks normally associated with a milling machine but on a much larger scale. *Vertical boring mills* are commonly used to turn, bore, and face large parts in much the same way as a lathe. Another variation of the horizontal boring mill sometimes found in the machine shop is the *vertical turret lathe*. This machine serves the same basic function as the vertical boring mill but, rather than using a single tool, a vertical turret lathe uses a turret arrangement to mount and position the cutting tools.

Broaching Machines

A *broaching machine* is used to modify the shape of a workpiece by pulling tools called *broaches* across or through the part. Both internal and external forms can be broached. *Internal broaching* can produce holes



FIGURE 20-27 *Typical internal broached shapes.* (Courtesy The DuMont Corp.)

with a wide variety of different forms, *Figure 20-27*. *External broaching* is typically used to produce some gear teeth, plier jaws, and other similar details.

Another type of internal broaching operation is broached in an *arbor press* using a push-type, rather than a pull-type broach. This type of broaching is often used in the top to produce keyways or other simple shapes.

Numerically Controlled Machines

Numerically controlled machine tools represent the norm in machine tool design in wide use today. These machine tools are operated by computers, and they can markedly reduce the errors caused by human operators.

The two basic variations of these machines in use today are the point-to-point and the continuous path machines. The principal difference between the two is in the movements of the tool with reference to the workpiece. *Point-to-point* machines operate on a series of preprogrammed coordinates to locate the position of the tool. When the tool finishes at one point, it automatically goes to the next point by the shortest route. This type of control is very useful for drilling machines, but machines such as milling machines require greater control of the tool movement. So, *continuous path* controls are used to control the movement of the tool throughout the cutting cycle. For example, if a circle or radius were to be milled, the operator or programmer would need only to program a few points along the arc. The computer would compute the remaining points and guide the cutting tool throughout the complete cycle.

These controls are frequently used for a wide range of different machine tools, from drill presses and milling machines to lathes and grinders. Due to the advent of these controls, a whole new form of machine tool has evolved: the machining center, *Figure 20-28*. These machines can take a rough, unmachined part and completely machine the whole



FIGURE 20-28 *CNC machining center.* (Courtesy Cincinnati Milacron)

part without removing it from the machine or changing a setup.

Special Workholding Devices

Special workholding devices are frequently used to produce parts in high-volume production runs. The major categories of special workholding devices commonly used in the shop are jigs and fixtures. The primary function of jigs and fixtures is to transfer the required accuracy and precision from the operator to the tool. This permits duplicate parts to be produced within the specified limits of size without error. Both jigs and fixtures hold, support, and locate the workpiece; the principal difference between these tools is the method used to control the relationship of the tool to the workpiece. *Jigs* guide the cutting tool through a hardened drill bushing during the cutting cycle. *Fixtures*, on the other hand, reference the cutting tool by means of a set block, ***Figure 20-29.***

Classification of Jigs

Jigs are normally classified by the type of operation they perform and their basic construction. Typically, jigs are used to drill, ream, tap, countersink, chamfer, counterbore, and spotface. Jigs are also divided into two general construction categories: open and closed. *Open jigs* are jigs that cover only one side of the part and are used for relatively simple operations. *Closed jigs* are jigs that enclose the part on more than one side and are intended to machine the part on several sides without removing the part from the jig.

The most common types of jigs include plate jigs, angle plate jigs, box jigs, and indexing jigs. While there are several other distinct styles of jigs, these represent the most common forms.

Plate jigs, ***Figure 20-30,*** are the most common form of jig. These jigs consist of a simple plate that contains the required drill bushings, locators, and clamping elements. Typical variations of the basic plate jig include the *table jig*, ***Figure 20-31A,*** and the *sandwich jig*, ***Figure 20-31B.*** Another and even simpler version of the plate jig is the *template jig*, ***Figure 20-32.*** These jigs are used where accuracy and not speed is the prime consideration. Template jigs may or may not have drill bushings, and do not normally have a clamping device. This form of jig is frequently used for light machining or for layout work.

An *angle plate jig*, ***Figure 20-33,*** is a modified form of a plate jig in which the surface to be machined is not perpendicular to the locating surface. This type



FIGURE 20-29 *Referencing the tool to the workpiece.*



FIGURE 20-30 *Plate jig.*



FIGURE 20-31 *(A) Table jig; (B) Sandwich jig.*



FIGURE 20-32 *Template jigs.*



FIGURE 20-33 *Angle plate jig.*

of jig is often used to machine pulleys, gears, hubs, or similar parts. Another variation of this type of jig is the *modified angle plate jig*. These jigs are used to machine parts at angles other than 90°.

A *box jig*, ***Figure 20-34***, is designed to be used for parts that require machining on several sides. With these jigs, the part is mounted in the jig and clamped with a leaf or door. Other variations of the basic box jig include the *channel jig*, ***Figure 20-35A***, and the *leaf jig*, ***Figure 20-35B***. These jigs are similar in design to the box jig but they machine the part on only two or three sides, rather than all six sides.

An *indexing jig*, ***Figure 20-36***, is used primarily to machine parts that have machined details at intervals around the part. Drilling four holes 90° apart is a typical example of the type of work this jig is best suited to perform. Another type of jig that uses an indexing arrangement to locate the jig, rather than the part, is the *multistation jig*, ***Figure 20-37***. These jigs are used to machine several parts at one time.

Classification of Fixtures

Fixtures are classified by the type of machine they are used on, the type of operation performed, and by their basic construction features. The principal types of fixtures normally used in the shop include plate fixtures, angle plate fixtures, vise jaw fixtures, and





FIGURE 20-34 *Box jig.*





FIGURE 20-35 *(A) Channel jig; (B) Leaf jig.*



FIGURE 20-36 *Indexing jig.*





FIGURE 20-37 *Multistation jig.*

indexing fixtures. Typically, fixtures are used for milling, turning, sawing, grinding, inspecting, and several other varied operations.

A *plate fixture, Figure 20-38,* is the most common type of fixture. Like plate jigs, plate fixtures are simply a plate containing the locators, set blocks, and clamping devices necessary to locate and hold the workpiece and to reference the cutter. While similar in design to a plate jig, plate fixtures are normally made much heavier than plate jigs to resist the additional cutting forces.

An *angle plate fixture, Figure 20-39A,* and a *modified angle plate fixture, Figure 20-39B,* are simple modifications of the basic plate fixture design. These fixtures are used when the reference surface is at an angle to the surface to be machined.

A *vise jaw fixture, Figure 20-40,* is a useful modification to the standard milling machine vise. With this type of fixture, the standard jaws of a milling machine vise are replaced with specially shaped jaws to suit



FIGURE 20-38 *Plate fixture.*



FIGURE 20-39 *(A) Angle plate fixture; (B) Modified angle plate fixture.*



FIGURE 20-40 *Vise jaw fixture.*

the part to be machined. The result is an accurate fixture that can be made at a minimal cost. Since the clamping device is contained within the vise, this fixture is very cost effective. Likewise, one vise can be used for a countless number of different fixtures by simply changing the jaws.

Indexing fixtures, Figure 20-41, are mainly used to machine parts that have a repeating part feature. Typical examples of the types of parts that are machined in an indexing fixture are shown in *Figure 20-42.* Here again, the indexing feature may also be used to position the tool as well as the part. The *duplex fixture* shown in *Figure 20-43* shows a method of indexing the fixture to machine two parts. In use, the first part is machined while the second is loaded. The fixture is then rotated and the second is unloaded and a fresh part loaded. This process is continued throughout the production run.

Locating Principles

To properly machine any part in a jig or fixture, the part must first be located correctly. The first rule of locating is repeatability. *Repeatability* is the feature of a jig or fixture that permits parts to be loaded in the tool in the same position part after part. When selecting locators for a part, the prime considerations must be position, foolproofing, tolerance, and elimination of duplicate or redundant locators.

Locators must be *positioned* as far apart as practical, and should contact the workpiece on a reliable surface to ensure repeatability. The locators must also be designed to minimize the effect of chips or dirt.



FIGURE 20-41 *Indexing fixture.*

FIGURE 20-42 *Typical parts machined in an indexing fixture.*



FIGURE 20-43 *Duplex fixture.*

Figure 20-44 shows a few methods generally used to relieve locators to prevent interference from chips.

Foolproofing is simply a method used to prevent the part from being loaded incorrectly. A simple pin, *Figure 20-45,* is normally enough to ensure proper loading of every part. The *tolerance* of a locator is determined by the specific size of the part to be machined. As a general rule, the tolerance of jigs and fixtures should be approximately 30% to 50% of the part tolerance. For example, if a hole were to be located within .010″ (.25 mm) from an edge, the locators in the jig or fixture should be positioned within .003″ to .005″ (.08 mm to .13 mm) to make sure the part is properly positioned. An overly tight tolerance only adds cost, not quality, to a tool.

Finally, locators should never duplicate any location. As shown in *Figure 20-46,* a part should be located on only one surface. Locating a part on two parallel surfaces only serves to reduce the effectiveness of the location, and could improperly locate the part. First determine the reference surface, and use only that surface for locating.

Restricting Movement. Every part is free to move in a limitless number of directions if left unrestricted. But, for the purpose of jig and fixture

Industry Application

A MID-CAREER CHANGE

Mark Roberts is the senior tool designer at Reynolds Manufacturing, Inc. (RMI). He is known in design and drafting circles as one of the best tool designers in the business, but it took a career change to help Roberts find his niche. He started work right out of high school as a machining trainee for RMI. In only half the time it normally takes, Roberts had earned his "ticket" as a full-fledged machinist.

Before long he gained a reputation on the shop floor for making special workholding devices that improved the performance of machine tools, particularly on high-volume jobs. Over time, Roberts found himself spending more hours in the day making jigs and fixtures than in doing his machining jobs. After discussing the situation with his supervisor, Roberts decided that he wanted to design jigs and fixtures full time.

Everyone agreed that this would benefit the company. The only problem was that Roberts actually knew very little about design. He knew machines and machining processes. He could visualize what was needed, and he could make excellent jigs and fixtures. But because he knew nothing about design, his workholding devices tended to be cumbersome. In addition, because he could not communicate his ideas on paper, he had to design, make, and modify every device himself. This slowed the process considerably.

Roberts and his supervisor agreed that if he could design workholding devices, and develop understandable drawings, others could actually make them, thereby speeding the process. This realization caused Roberts to enroll in the night design and drafting program at Madison Technical Institute (MTI). He graduated with a certificate in mechanical design and drafting, and was MTI's student of the year. Within six months of his graduation, Roberts was doing so well in the area of jig and fixture design that his company was able to open a tool design division that now designs and manufactures jigs and fixtures for other companies.

Roberts is still the senior tool designer at RMI where the jig and fixture division is a commercial success. He also teaches tool design in the night program at Madison Technical Institute.



FIGURE 20-44 *Relieving locators.*



FIGURE 20-45 *Foolproofing a workholder.*



FIGURE 20-46 *Duplicate locating.*

design, the number of directions in which a part can move has been limited to twelve: six axial and six radial, *Figure 20-47*. The methods used to restrict these twelve movements normally depend on the part itself, but the examples in *Figures 20-48A* and *20-48B* show two methods that are frequently used. In the first example, a three-pin base restricts five directions of movement. In the second example, a five-pin base restricts eight directions of movement. In *Figure 20-48C*, a six-pin base restricts nine directions of movement.

Types of Locators. Locators are commercially available in many styles and types. *Figures 20-49A* through *20-49F* show several of the most common types of locators.



FIGURE 20-47 *Planes of movement.*

Clamping Principles

In addition to locators, most jigs and fixtures use some type of clamping device to restrict the directions of movement not contained by the locators. In the design of a clamping arrangement, several factors should be considered. These include the position of the clamps, clamping forces, and tool forces.

Clamps should always be positioned to contact the part at either its most rigid point or a supported



FIGURE 20-48 *(A), (B), and (C) Restricting part movement.*



FIGURE 20-49 *(A–C) Types of locators.*



FIGURE 20-49 *(Continued) (D–F) Types of locators.*



FIGURE 20-50 *Always clamp a part at its most rigid point or a supported point.*



FIGURE 20-51 *Clamping forces.*



FIGURE 20-52 *Tool forces.*

point. Clamping a part at any other point could bend or distort the part, as shown in ***Figure 20-50.*** The clamping forces used to hold a part should always be directed toward the most solid part of the tool. Clamping a part as shown in ***Figure 20-51A,*** will normally result in an egg-shaped part because the clamping forces are directed only toward each other. However, by clamping the part as shown in ***Figure 20-51B,*** not only is the part held securely, but the chance of distortion is greatly reduced. As a rule, use only enough clamping force to hold the part against the locators. The locators should always resist the bulk of the tool thrust, not the clamps.

When designing a jig or fixture, remember to direct the tool forces toward the locators, not the clamps. *Tool forces* are those forces generated by the cutting tool during the machining cycle. In most cases, the tool forces can be used to an advantage when holding any part. As shown in ***Figure 20-52,*** the downward tool forces are actually pushing the part into the tool. The rotational tool forces are contained by the locators. The only force the clamps need to hold are the forces generated by the drill as the point breaks out the opposite side of the part, and these forces are only a fraction of the cutting forces. So, when designing a jig or fixture, always direct the tool forces so that they act to hold the part in the tool. Use the clamps only to hold the part against the locators.

Types of Clamps. Clamps, like locators, are commercially available in many styles and types. *Figures 20-53A* through *20-53D* (page 748) show some of the more common types of clamps used for jigs and fixtures. The specific type of clamp you should select for any workholding application will normally be determined by the part and the type of holding force desired.

Basic Construction Principles

When designing any jig or fixture, the first consideration is normally the tool body. Tool bodies are generally made in any of three ways: cast, welded or built-up, *Figure 20-54* (page 749). *Cast tool* bodies are generally the most expensive and require the longest lead time to make. They do, however, offer such advantages as good material distribution, good stability, and good vibration-damping qualities. *Welded tool* bodies offer a faster lead time, but they must be machined frequently to remove any distortion caused by the heat of welding. The most popular and common type of tool body in use today is the built-up. *Built-up tool* bodies are made from pieces of preformed stock, such as precision-ground flat stock, ground rod, or plain cold-rolled sections that are pinned and bolted together. The principal advantages of using this type of construction are fast lead time, minimal machining, and easy modification.



FIGURE 20-53 *(A–D) Types of clamps.*



FIGURE 20-54 *Tool bodies.*

FIGURE 20-55 *Press-fit drill bushings.*

Drill Bushings. *Drill bushings* are used to position and guide the cutting tools used in jigs. The three basic types of drill bushing used for jigs are press-fit bushings, renewable bushings, and liner bushings.

Press-fit bushings, ***Figure 20-55,*** as their name implies, are pressed directly into the jig plate. These bushings are useful for short-run jigs or in applications where the bushings are not likely to be replaced frequently. The two principal types of press-fit bushings are the head type and headless type.

Renewable bushings are used in high-volume applications or where the bushings must be changed to suit different cutting tools used in the same hole. The two types of renewable bushings that are commercially available are the slip-renewable type, ***Figure 20-56A*** (page 749), and the fixed-renewable type, ***Figure 20-56B*** (page 749).

Slip-renewable bushings, ***Figure 20-56C*** (page 749), are used where the bushing must be changed quickly. Typical applications include holes that must be drilled, countersunk, and tapped. The bushings are held in place with a lock screw and need only be turned counterclockwise and lifted out of the hole. The next bushing is inserted in the hole and turned clockwise to lock it in place.



FIGURE 20-56 *(A–E) Renewable drill bushings.*

Fixed-renewable bushings are used for applications where the bushings do not need to be changed often, but where they are changed more often than press-fit bushings. High-volume production is a typical example where fixed renewable bushings are often used.

Liner bushings, ***Figure 20-56D,*** are used in conjunction with renewable bushings and provide a hardened, wear-resistant mount for renewable bushings. Liner bushings are actually press-fit bushings with a large-diameter hole. Like press-fit bushings, liner bushings are available in both a head type and a headless style. The clamps normally used to hold the fixed-renewable bushing in the jig plate are shown in ***Figure 20-56E.*** The screw is used to mount slip-renewable bushings, whereas the other three styles are used to secure the fixed-renewable bushings.

Several other variations of these basic bushing styles include special-purpose bushings, serrated and knurled bushings, and oil-groove bushings. Oil-groove bushings are shown in ***Figure 20-57.***



FIGURE 20-57 *Oil-groove bushings.*



FIGURE 20-58 *(A–F) Mounting drill bushings.*

Mounting Drill Bushings. When one is installing a drill bushing in the jig plate, the specific size of the jig plate and spacing from the part are important factors the designer must consider. As shown in *Figure 20-58A,* the jig plate should be one to two times the tool diameter. If a thinner jig plate must be used, a head-type bushing can be used to achieve the added thickness needed to support the cutting tool. The space between the jig plate and the workpiece should be one to one-and-one-half times the tool diameter for drilling, *Figure 20-58B,* and one-quarter to one-half the tool diameter for reaming, *Figure 20-58C.*

In those cases where both drilling and reaming operations are to be performed in the same hole, an arrangement similar to the one shown in *Figure 20-58D* may be used. Here the jig plate is properly positioned for drilling, and the bushing used for reaming is made longer to achieve the desired distance for reaming. When special shapes or contours must be drilled, the ends of the bushings can be modified to suit the contour and maintain the proper support for the cutting tool, *Figures 20-58E* and *20-58F.*

Set Blocks. Set blocks are used along with thickness gages to properly position the cutting tool with a fixture. The specific design of the set block is determined by the part and shape to be machined. The basic set block designs shown in *Figure 20-59* are typical of the styles found on many fixtures.



FIGURE 20-59 *Set blocks.*

Fastening Devices. The most common fastening devices used with jigs and fixtures are dowel pins and socket-head cap screws. Other fasteners sometimes used with these tools include the nuts and washers shown in *Figure 20-60.*

Heat Treatment of Steels

Heat treatment is a series of processes used to alter or modify the existing properties in a metal to obtain a specific condition required for a workpiece. The specific



FIGURE 20-60 *Nuts and washers frequently used with jigs and fixtures.*

properties normally changed by heat treatment include hardness, toughness, brittleness, malleability, ductility, wear resistance, tensile strength, and yield strength. The five standard heat treating operations normally performed on steel parts are hardening, tempering, annealing, normalizing, and case hardening.

Hardening is the process of heating a metal to a predetermined temperature, allowing the part to soak until thoroughly heated, and cooling rapidly in a cooling material called a *quench*. The most common quench media are air, oil, water, and a water and salt mixture called brine. Hardening is mainly used to increase the hardness, wear resistance, toughness, tensile strength, and yield strength of a workpiece.

Tempering is the process of heating a hardened workpiece to a temperature below the hardening temperature, allowing the part to soak for a specific time period, and cooling. Tempering is mainly used to reduce the hardness so the toughness is increased and brittleness is decreased. Almost every hardened part is tempered to control the amount of hardness in the finished part.

Annealing is the process of heating a part, soaking it until it is thoroughly heated, and slowly cooling it by turning off the furnace. Annealing is mainly used to completely remove all hardness in a metal. Frequently, hardened parts are annealed to be remachined or modified and then rehardened.

Normalizing is the process used to remove the effects of machining or cold-working metals. In this process, the metal is heated, allowed to soak, and cooled in still air. This process produces a uniform grain size and eliminates almost all stresses in the metal.

Case hardening is the process of hardening the outside surface of a part to a preselected depth. In most casehardening operations, carbon is added to the surface of the part by packing the part in a carbonous material, and then heating it so that the carbon is transferred into the surface of the part. Once the carbon is added to the surface of the part, the part is then hardened to produce a hardened shell around a normalized core.

Nontraditional Machining Processes

The term *nontraditional machining* encompasses a number of advanced machining processes that have been developed in response to the demands of modern manufacturing for more effective, more efficient ways to machine the many new materials that have been developed and are still being developed. Although they are still referred to as "nontraditional" processes, they are now common and widely used. The most widely used nontraditional machining processes are explained in this section.

Hydrodynamic Machining (HDM)

Hydrodynamic machining (HDM), Figure 20-61, removes material using a high-velocity, high-pressure stream of liquid solution. It is used primarily for slitting and contour-cutting many nonmetallic materials, such as wood and paper, asbestos, plastics, gypsum, leather, felt, rubber, nylon, fiberglass, and fiberglass-reinforced plastics. Some very thin workpieces of soft metal can be cut effectively by this process; steel sheet (0.005", 0.13 mm thick) and aluminum sheet (0.020", 0.51 mm thick) are processed, but water pressure in excess of 100 ksi (690 MPa) is usually required. Equipment that operates at these higher pressures is not commercially available. The cutting of hard metals using HDM remains mostly experimental.

Practical experience and experimental research has shown that, in some cases, brittle materials such as glass, acrylic, ceramics, and crystal do not appear suitable for cutting by the HDM process because these materials tend to develop severe cracks and may break under processing conditions.

Typically, soft materials are cut easily using HDM, and friable materials can be cut with good edge quality.



FIGURE 20-61 *Hydrodynamic machining (HDM).*

At its present stage of development, the industrial use of HDM is limited to the processing of relatively thin materials. When thicker materials are cut, stream lines increase significantly, causing poor edge quality.

Ultrasonic Machining (USM)

Ultrasonic machining (USM) **(*Figure 20-62*)** removes material using an abrasive slurry driven by a special tool vibrating at a high frequency along a longitudinal axis. It is used primarily for producing blind holes, through holes, slots, and irregular shapes. It is limited in complexity only by the configuration of the tooling. However, in some applications, tool wear and/or taper in the cut may discount the process's effectiveness. The depth-to-width ratio of the cut is usually less than about 3:1. Current practice is limited to 3.5″ (89 mm) diameter tools machining cavities up to about 2.5″ (64 mm) deep.



FIGURE 20-62 *Ultrasonic machining (USM).*

Rotary Ultrasonic Machining (RUM)

Rotary ultrasonic machining (RUM) **(*Figure 20-63*)** is similar to USM except that: (1) the grinding motion is rotary instead of longitudinal; (2) RUM uses diamond tools instead of steel or Monel; and (3) RUM uses the diamond of the tool to remove material while USM uses an abrasive slurry. RUM is used primarily in the development of prototypes. It is also used for machining ceramics, quartz, glass, ferrite computer parts, and composites.

The applications of RUM are currently limited by tool size. The horn/tool assembly must have a resonant (natural) frequency of about 20 kHz, so tool size is limited. Any variance in tool weight changes the natural frequency of the horn/tool assembly; too heavy a tool increases horn/tool assembly frequency beyond the resonant frequency of the transducer and power supply, causing the tool not to vibrate. Today, the largest vibrating horn feasible is about 1.5″ (38 mm) in diameter. Practical limit to tool weight is about 1.4 oz (40 g).

RUM is used widely in prototype work as well as production applications. The process is effective in producing prototypes because it can make precise parts that can be used to make molds for large-volume production runs.



FIGURE 20-63 *Cutting internal threads using rotary ultrasonic machining (RUM).*

The process is particularly effective in the machining of sintered materials such as ceramics and ferrites. Conventionally, these materials are machined and drilled in the "green" state—prior to firing. When fired, the materials experience as much as 16% shrinkage, which destroys the accuracy created during machining. RUM is used to machine materials such as these after firing, and close tolerance relationships are maintained. Some applications include the machining of precision ceramic components, drilling small holes in ceramic printed circuit boards, and drilling small-diameter, deep, intersecting holes in quartz for laser development.

Ultrasonically Assisted Machining (UAM)

Ultrasonically assisted machining (UAM) involves assisting such traditional machining processes as drilling and turning by coupling the tool with an external source of vibrating energy. It is used in most drilling and turning applications and is effective in reducing the amount of subsurface tearing and plastic flow. It also evens out tool wear.

Under certain conditions, ultrasonic lathe turning has been shown to increase cutting rates by factors of four in aluminum, and five in cutting steel. Nonmetallic materials have also shown marked increases in cutting rates when UAM is used. Alumina can be machined two times faster, and magnesium silicate can be machined up to four times faster in some cases, according to manufacturers of UAM equipment.

Some materials that are too brittle to machine traditionally can be machined effectively with UAM. For example, in one test, low-porosity mullite was machined with a good cut by applying ultrasonic vibrations to the tool post and carbide-tipped tool, but when ultrasonic power was turned off, the workpiece immediately shattered.

Some tests have shown that UAM reduces turning forces in some materials as much as 30–50% as compared to traditional turning methods. In the same tests, it was shown that surfaces produced by UAM exhibited a matte finish, evidence of more complete shearing of the chips from the workpiece. This phenomenon is in sharp contrast to traditional machining, which often produces a glossy surface as a result of tearing, materials enfoldment, and burnishing. Subsurface tearing and plastic flow are reported to be all but eliminated by UAM.

Electromechanical Machining (EMM)

Electromechanical machining (EMM) is a process that improves the performance of traditional machining processes. Metal removal is accomplished in the traditional manner (i.e., drilling, milling, turning, etc.) with the exception that the workpiece is electrochemically polarized by applying a controlled voltage across the connection point between the workpiece and an electrolyte. This changes the surface of the workpiece, making it easier to machine.

The limited feasibility of electromechanical turning (EMT) and electromechanical drilling (EMD) has been demonstrated in both laboratory and plant settings. The limited testing conducted to date indicates advantages of surface finish, tool wear, hole tolerance, and chip configuration. However, maximum improvement is tied closely to optimization of electrolytes, and it has been shown that the electrolytes should be modified through the use of inhibitors to minimize corrosion of machine tool components.

Electrochemical Discharge Grinding (ECDG)

Electrochemical discharge grinding (ECDG) is a combination of two processes: electrochemical grinding (ECG) and electrical discharge grinding (EDG). In ECDG, alternating current or pulsating direct current moves from a bonded graphite wheel (conductor) to a positively charged workpiece. No mechanical contact is made between the workpiece and the wheel. Instead, an electrolyte is pumped into the gap and it serves as the connecting agent. Material removal occurs as follows: (1) the ECG process converts the surface of the metal into an oxide film, and (2) the EDG process removes the oxide film.

The production uses of ECDG are somewhat limited, although certain applications exist that are routinely performed, mostly in the grinding and sharpening of carbide tooling. Nearly any electrically conductive material can be processed, but careful comparison of the relative advantages and disadvantages of ECDG versus processes such as ECG and EDG should be made before specifying the process. For example, ECDG can remove material five times faster than EDG, but it uses up to 15 times the current used in EDG. Typical production tolerances of ±0.001″ (0.03 mm) are achieved with ECDG.

Current successful applications of the process include grinding and sharpening of carbide inserts, generation of delicate profiles using form grinding, grinding of honeycomb materials, and grinding of carbide thread chasers.

Electrochemical Grinding (ECG)

Electrochemical grinding (ECG) (**Figure 20-64**) combines an electrochemical reaction that occurs on the surface of the metal with abrasion. Subsequently, it is



FIGURE 20-64 *Electrochemical grinding (ECG).*

applied to the metal's surface to remove material. The process is typically used on tough, hard metals. The abrasion is applied by a rotary grinding wheel that grinds off oxidized surface metal.

In operations in which ECG can be applied, it produces results far beyond those that conventional grinding methods can provide. In many cases it can reduce abrasive costs up to 90%. This reduction is most easily observed in connection with diamond wheels and carbide grinding. However, it is also significant with respect to steel and alloy steel grinding with nondiamond wheels.

Also, because it is a cool process, ECG can be used to grind any electrically conductive material without damage to it from heat. Therefore, ECG can simplify fracture-inspection procedures or entirely eliminate scrap due to grinding-heat fractures. In addition, this process can grind steel or alloy steel parts without generating any burr. Thus, the costly operation of subsequent deburring is automatically eliminated.

Electrochemical Honing (ECH)

Electrochemical honing (ECH) is a process similar to ECG. It combines electrochemical oxidation of surface metal and abrasion. The primary difference is that honing is a process of removing material inside a drilled hole. Consequently, the abrasion is applied using nonconductive honing stones attached to a tool that rotates and reciprocates.

To be processed by ECH, workpieces must be conductive. The process is most effective when used to hone hard, tough metals and is well suited for the processing of parts that are susceptible to heat distortion. Electrochemical honing causes little heat buildup and no significant stresses, and automatically deburrs the workpiece. The process is particularly effective for parts that require fast stock removal with good surface finish control.

Electrochemical Machining (ECM)

Electrochemical machining (ECM) (***Figure 20-65***) is a broad concept that applies to a number of process variations that all use an electrolytic action in removing metal. With ECM, electricity is combined with a chemical to form a reaction that is the opposite of metal plating. ECM can be used with any conductive workpiece but is used most often with hard metals. Its best application is external shaping of materials.

ECM is used in a wide variety of industries to machine many different metals. Experience has shown, however, that not all materials can be machined successfully (to acceptable metal removal rates and surface finish) using the ECM process. For example, some high-silicon aluminum alloys, such as cast alloys with substantial silicon content, sometimes cannot be machined with acceptable surface finish. Some troublesome experiences have been documented with SAE 332 aluminum pistons with 10% silicon, for example.

Electrochemical Turning (ECT)

Electrochemical turning (ECT) is a variation of ECM. The same basic principles apply except that the workpiece rotates. The primary application of ECT is the machining of large, disc-shaped forgings. In some cases, full-face electrodes are plunged into a rotating disc. Bearing races have been finished, with close



FIGURE 20-65 *Electrochemical machining (ECM).*

tolerances and with surface roughness held to less than 5 in. (0.13 μm) R_a. Another application, AISI 316 stainless steel workpieces (2.5″, 6.35 mm diameter), are electrochemically turned, using an electrolyte of NaCl and $NaNO_3$ (3:3), to a surface finish of less than 10 in. (0.25 μm) R_a with out-of-roundness of less than 0.0002″ (0.005 mm) TIR.

Electron Beam Machining (EBM)

Electron beam machining (EBM) is a thermal energy process. This means it uses thermal energy to remove metal. The thermal energy comes in the form of a pulsating stream of high-speed electrons that are focused on a very small area of the workpiece by electrostatic and electromagnetic fields. Material removal occurs as the result of melting or evaporation. EBM is used for drilling small wire-drawing dies, metering holes, and holes for spinnerets used in textile manufacturing.

Any known material, metal or nonmetal, that will exist in high vacuum can be cut, although experience has shown that diamonds do not cut well. Holes with depth-to-diameter ratios up to 100:1 can be cut. Limitations include high equipment costs and the need for a vacuum, which usually necessitates batch processing and restricts workpiece size. The process is generally economical only for small cuts in thin parts.

Electrical Discharge Machining (EDM)

Electrical discharge machining (EDM) **(Figure 20-66)** is a process that removes metal using a series of rapidly recurring electrical discharges between an electrically charged cutting tool and the workpiece submerged in a dielectric fluid.

The application of EDM is limited to the machining of electrically conductive workpiece materials, but the process has the capability of cutting these materials regardless of their hardness or toughness. Nonconductors such as glass, ceramics, or plastics cannot be machined using EDM techniques. Machining of hardened steel using EDM eliminates the need for subsequent heat treatment with possible distortion. Complex shapes can be cut in hardened steel or carbide without costly sectional construction being necessary.

The production of stamping dies is a major application afforded by using EDM to match one portion of the die made conventionally. Extruding, heading, drawing, forging, and die casting dies, as well as molds for plastics, are also made using EDM techniques.

Electrical Discharge Wire Cutting (EDWC)

Electrical discharge wire cutting (EDWC) **(Figure 20-67)** is a process that is similar to the band-sawing process. Material removal occurs as the result of an electrical discharge as a wire electrode is drawn through the workpiece. EDWC can be used only with conductive workpieces. Primary applications of EDWC include the production of stamping dies, prototypes, molds, lathe tools, special form inserts, pot and wobble broaches, extrusion dies, and templates.

As is the case with any electrical discharge process, EDWC requires that the workpiece be electrically conductive. The cut produced by the process is free of flaring and is controllable to produce small radii.



FIGURE 20-66 *Electrical discharge machining (EDM).*



FIGURE 20-67 *Electrical discharge wire cutting. (EDWC)*

Workpieces up to about 6″ (152 mm) in thickness can be processed using standard equipment; workpiece stacking effects greater productivity.

Normally produced from hardened metals such as tool steel, stamping dies are routinely cut using EDWC. The process facilitates cutting after heat treatment, thereby eliminating distortion. The use of EDWC in the manufacturing of dies affords significant savings. By conventional methods, dies are sometimes split into two or more sections to facilitate grinding with an optical projection form grinder. Usually, after the contour has been ground in the split sections, the sections are fitted in a holder or adapter. This time-consuming and costly process is eliminated with EDWC employed to produce the dies. Some experts claim that tool components such as dies can be produced in less than one-third the time required by conventional methods.

Electrical Discharge Grinding (EDG)

Electrical discharge grinding (EDG) is similar to EDM in that it employs rapidly recurring electrical discharges between an electrode and the workpiece in a dielectric fluid. The difference is that with EDG the electrode is a rotating wheel made of graphite or brass. Primary applications include the grinding of steel and carbide at the same time, thin sections, and brittle and fragile parts.

EDG is generally used for operations such as the following: grinding steel and carbide at the same time without wheel loading, grinding thin sections on which abrasive-wheel pressures might cause distortion, grinding brittle materials or fragile parts on which abrasive materials might cause fracturing, grinding through forms for which diamond-wheel costs would be excessive, and grinding circular forms in direct competition with abrasive-wheel methods.

Electrical discharge grinding is used to grind hard materials such as carbide form tools, hardened steel gear racks, or tungsten carbide inserts. The process is also used to grind hardened lamination dies. Cast iron workpieces are usually not processed using EDG because sand inclusions can damage the graphite grinding wheel.

Laser Beam Machining (LBM)

Laser beam machining (LBM) (**Figure 20-68**) is a process that uses lasers for performing operations that are traditionally performed with cutting tools. These operations include cutting, drilling, slotting, and scribing. The basic principle of LBM is the conversion of electrical energy into coherent light. This coherent light or laser beam is focused on the workpiece where it is converted into thermal energy. This thermal energy melts or vaporizes the material. LBM has broad applications, but it is particularly effective at cutting and drilling.



FIGURE 20-68 *Solid state laser beam machining (LBM).*

Any industrial application of the laser should be based on one of three criteria: (1) it can perform a superior job in terms of quality and cost over existing methods, (2) it is the only tool capable or available for the specific job, or (3) it allows restructuring of the manufacturing process, resulting in lower total cost. The cost of using laser systems falls into two categories: (1) the capital investment for the laser system, and (2) the operational cost. At present both the equipment and the direct operational costs of a laser are higher than those of comparable conventional equipment and methods.

Because of the laser's ability to melt or vaporize any known metal and operate in any desired atmospheric environment, it is sometimes preferred over EBM (electron beam machining), which requires a vacuum chamber for certain applications. Other advantages include: (1) the ability to machine areas not readily accessible and extremely small holes, (2) the fact that no direct contact exists between the tool (laser) and the workpiece, (3) small heat-affected zones, and (4) easy control of beam configuration and size of exposed area.

Plasma Arc Machining (PAM)

Plasma arc machining (PAM) (**Figure 20-69**) is a process that makes use of a plasma arc to remove



FIGURE 20-69 *Plasma arc machining (PAM).*

material. *Plasma* is a gas that has been heated to the point that it ionizes and becomes electrically conductive. With PAM, a stream of ionized particles directed through a nozzle against the workpiece removes material. The primary applications of PAM are hole piercing, stack cutting, gouging, grooving, and bevel cutting.

The plasma arc can be used for "machining" or removing the metal from the surface of a rotating cylinder to simulate a conventional lathe or turning operation. As the workpiece is turned, the torch is moved parallel to the axis of the work. The torch is positioned so the arc will impinge tangentially on the workpiece and remove the outer layer of metal. Cutting can be accomplished with the workpiece rotating in either direction relative to the torch, but best results are obtained when the direction of rotation permits use of the shortest arc length for cutting. The flow of molten metal being removed must be in such a direction that it does not tend to adhere to the hot surface that has just been machined.

Chemical Milling

Chemical milling is a process that etches or shapes workpieces to close tolerances by chemically induced material removal. Primary applications include metal removal from irregularly shaped workpieces, reduction of web thicknesses, removal of the decarburized layer from low-alloy steel forgings, improved surface finish, and removal of defects.

In general, chemical milling is used to remove metal from a portion or the entire surface of formed or irregularly shaped parts such as forgings, castings, extrusions, or formed wrought stock; reduce web thicknesses below practical machining, forging, casting, or forming limits; taper sheets and preformed shapes; produce stepped webs, resulting in consolidation of several details into one integral piece; remove the decarburized layer from low-alloy steel forgings; remove up to 0.125″ (3.2 mm) per surface of metal to remove decarb and also create finished dimensions of die forgings; improve surface finish; remove surface cracks, laps, and other defects of forgings; remove alpha case from titanium forgings; and improve surface finish and control dimensions of aluminum forgings.

Photochemical Machining

Photochemical machining, also known as chemical blanking, involves producing parts by chemical action. It is accomplished by placing an exact image of the part to be produced on a sheet of metal (the prototype must be chemical-resistant) and immersing them both in a chemical. The chemical action dissolves all of the metal except the desired part. Most photochemically machined parts are thin and flat.

Photochemical machining has a number of applications wherein it provides unique advantages. Some of these include: working on extremely thin materials when handling difficulties and die accuracies preclude the use of normal mechanical methods; working on hardened or brittle materials when mechanical action would cause breakage or stress-concentration points—chemical blanking works well on spring materials and hardened materials that are relatively difficult to punch; production of parts that must be absolutely burr-free; production of extremely complex parts for which die costs would be prohibitive; and producing short-run parts for which the relatively low setup costs and short time from print to production offer advantages. This is especially important in research and development projects and in model shops.

Water Jet Machining (WJM)

Unlike the nontraditional processes presented so far, *water jet machining (WJM)* is used with nonmetal workpieces. It involves cutting plastics, nonmetal composites, ceramics, glass, and wood by directing a thin, pressurized jet of water against the workpiece.

Abrasive Water Jet Machining (AWJM)

Abrasive water jet machining (AWJM) (**Figure 20-70**) is similar to WJM except that an abrasive is added to the water jet after it exits the nozzle. This allows



FIGURE 20-70 *Abrasive water jet machining (AWJM).*

AWJM to be used with brittle and/or heat-sensitive materials such as glass, composites, and plastics.

Automation and Integration (CAM and CIM/FMS)

There have been four phases in the development of shop and manufacturing processes:

1. Manual phase
2. Mechanization phase
3. Automation phase (CAM)
4. Integration phase (CIM/FMS)

Of course, there has been and continues to be a good deal of overlap among these phases. Manual manufacturing did not suddenly stop when the age of mechanization began, nor did mechanized manufacturing stop when the automation phase began. Correspondingly, the beginning of the integration phase did not bring automated manufacturing to a sudden stop.

It takes many years for a given stage in the development of shop and manufacturing processes to phase out completely. For example, by the year 1900, mechanized manufacturing had replaced manual manufacturing as the dominant approach. However, manual manufacturing was still widely practiced at that time. Today, automated manufacturing has become the dominant approach; nevertheless, mechanized manufacturing is still widely practiced, and even manual manufacturing is still practiced in very isolated cases.

At present, we are seeing the integration phase emerge. It will eventually dominate but not completely replace—at least not for a long time—the other three approaches.

The manual phase preceded the Industrial Revolution. During these early times, manufactured products were produced by hand, using a variety of manual tools. The Industrial Revolution ushered in the mechanization phase. The fundamental component of this phase was the machine. Early machines were steam powered, while later machines, of course, were dependent on electricity. In this phase, machines such as mills, drills, saws, and lathes did the work, but people provided the control.

The automation phase has changed the way machines are controlled. It has also lessened the amount of human involvement in manufacturing. With the automation approach, manufacturing machines are controlled by computer. This has come to be known as CAM or computer-aided manufacturing. CAM machines are operated automatically according to computer programs. People still write the programs, set up the machines, monitor operations, and unload machines.

With CAM, individual operations such as milling, drilling, turning, and cutting are automated, but they still operate independently of each other. The most advanced manufacturing approach to date—computer-integrated manufacturing or CIM—solves this problem by linking automated manufacturing processes with other processes such as materials handling, warehousing, contracts and bids, scheduling, and design. CIM represents a major step toward the wholly automated factory. These two concepts—CAM and its eventual successor CIM—deserve special attention.

Computer-Aided Manufacturing (CAM)

Through CAM, such manufacturing processes as machining and materials handling can be automated. CAM encompasses any manufacturing process that is automated through the use of the computer, but the best examples of CAM are computer numerical control (CNC) of machine tools and robotics.

Computer Numerical Control (CNC)

Numerical control is a method of controlling machine tools by using coded programs. These programs consist of numbers, letters, and special characters that define the path of the machine tool in accomplishing specific tasks. When the job changes, the program

must be rewritten to accommodate the change. The programmability feature is the key to the growth of NC. Machine tools that are programmable are more flexible than their nonprogrammable counterparts.

NC is a broad term that encompasses the traditional approach to NC as well as the more modern outgrowths of CNC and direct numerical control (DNC).

The first NC machines used punched cards as the programming medium. Later, punched tape was substituted, which was an improvement over manual control but did have some disadvantages. Paper tape was easy to damage and difficult to correct or edit.

Mylar tape, as a less fragile medium, began to replace paper tape. This solved the problem of frequent damage but did not make punched tape any easier to edit. Such problems, coupled with advances in microelectronic technology, led to the use of computers as the means for programming machine tools. Computers solved the damage and editing problems, and this gave birth to both CNC and DNC. CNC involves using a computer in writing, storing, and editing NC programs. DNC involves using a computer as the controller for one or more NC machines, *Figure 20-71*. A more advanced form of DNC is called "distributive numerical control," *Figure 20-72*.

In this concept there is a host coupler and several intermediate computers that are tied to NC machines, robots, and other NC manufacturing devices. The main host computer is the central repository for all programs for all jobs. Specific programs for specific jobs are "dumped" from the host computer to the intermediate computers. This cuts down on the



FIGURE 20-71 *Direct numerical control.* (Adapted from Seames, *Computer Numerical Control,* Delmar Publishers Inc.)



FIGURE 20-72 *Distributive numerical control.* (Adapted from Seames, *Computer Numerical Control,* Delmar Publishers Inc.)

amount of time required to get the programmed instructions from the computer to the machine tool. CNC machines are available for most machining processes, including cleaning and finishing, inspection and quality control, pressing and forming, and material removal.

Figure 20-73 is a CNC bed-type vertical machining center.

Figure 20-74 is a CNC milling machine.

Figure 20-75 is a Cincinnati Milacron Maxim 500 Horizontal CNC Machining Center.

All of the CNC machines shown in Figures 20-73 through 20-75 have controllers. There are as many different controllers as there are CNC machines. Regardless of the type of controller, there must be some means of storing and inputting programs that instruct the machines. These means are called input media.

FIGURE 20-73 *CNC machining center.* (Courtesy Bridgeport Machines Inc.)



FIGURE 20-74 *Turning process.* (Courtesy Bridgeport Machines Inc.)



FIGURE 20-75 *CNC machining center.* (Courtesy Cincinnati Milacron)

The most frequently used types of input media are punched tape and magnetic tape. Punched tape may be either the paper or Mylar (plastic) variety. Mylar is more widely used because it is less prone to damage.

With earlier CNC machines a tape punch was used to put holes in a tape that was fed through it. The holes represented the program code. The punched tape was run through a tape reader that sensed the holes and fed the code into the controller. A problem with this type of input media is that it is easy to make an error when punching the tape and difficult to correct it.

An improvement to this early, cumbersome method of input is to interface a tape punch directly with a microcomputer. The code is typed via the microcomputer's keyboard. As the code is entered, it is stored so that it can be checked for accuracy and edited. Once correct, it is fed to the tape punch, and the tape is prepared. This solves the error correction problem.

Magnetic tape is now more popular than punched tape. With this type of medium the program code is affixed to the tape as magnetic spots rather than as holes punched through it. Because this type of medium is becoming so popular, standards for format and coding have been developed by the Electronics Industries Association.

CNC is the most modern and most technologically advanced method of controlling manufacturing machines. However, it is not the best control method in every case. Like any technological development, CNC has its advantages and disadvantages. There are times when the traditional manual approach is better. CNC is indicated when one or both of the following factors is important:

- Increased productivity
- Decreased labor and production costs

When CNC is indicated, there are advantages and disadvantages with which students of CAD/CAM should be familiar. The advantages include:

1. Better production and quality control
2. Increased productivity, flexibility, accuracy, and uniformity
3. Reduced labor, production, tool, and fixture costs
4. Less parts handling and tool storage

There are other advantages of CNC; however, these are the most important. There are also disadvantages associated with CNC. Those most frequently stated are:

1. High up-front costs
2. Higher operating costs
3. Retraining costs
4. Potential personnel problems

The advantages of CNC outweigh the disadvantages. But the list of disadvantages does make the point that it is not always the appropriate choice.

CNC Applications

CNC applications can be viewed at two levels. First, there is the industry level. At this level, all of the various manufacturing industries use CNC machines. These include:

- Aerospace manufacturers
- Electronics manufacturers
- Automobile, truck, and bus manufacturers
- Appliance manufacturers
- Tooling manufacturers
- Locomotive/train manufacturers

The second application level to consider is the machine level. At this level, CNC applications include:

- Cleaning and finishing applications
- Material removal applications
- Presswork and forming applications
- Inspection/quality control applications

Cleaning and finishing machines perform such tasks as washing, degreasing, blasting, lapping, grinding, and deburring. There are currently several CNC cleaning and finishing machines on the market.

Material removal machines include mills, lathes, grinders, drills, and saws. All such machines may be CNC controlled. In fact, this is the machine level application area most strongly associated with CNC.

Presswork and forming machines perform such tasks as pressing, stamping, blanking, punching, bending, and swagging. There are currently several CNC presswork and forming machines on the market.

Inspection and quality control machines perform such tasks as measuring, gaging, testing, and weighing. There are several CNC inspection and quality control machines on the market.



FIGURE 20-76 *Industrial robot.* (Courtesy Rixan Associates Inc.)

Industrial Robots

As is sometimes the case with new and emerging technological developments, there are a variety of definitions used for the term "robot." Depending on the definition used, the number of robot installations in this country and others will vary widely. There are a variety of single-purpose machines used in manufacturing plants that, to the lay person, would appear to be robots. These machines are hardwired to perform one function. They cannot be reprogrammed to perform a different function. These single-purpose machines do not fit the definition of industrial robots that is coming to be widely accepted. This definition is the one developed by the Robot Institute of America:

> A robot is a reprogrammable multifunctional manipulator designed to move material, parts, tools, or specialized devices through variable programmed motions for the performance of a variety of tasks.

Notice that the RIA's definition contains the words "reprogrammable" and "multifunctional." It is these two characteristics that separate the true industrial robot from the various single-purpose machines used in modern manufacturing firms. The term "reprogrammable" implies, first, that the robot operates according to a written program, and, second, that this program can be rewritten to accommodate a variety of manufacturing tasks. The term "multifunctional" means that the robot is able, through reprogramming and the use of a variety of end effectors, to perform a number of different manufacturing tasks. Definitions written around these two critical characteristics are becoming the accepted definitions among manufacturing professionals. *Figures 20-76* and *20-77* are examples of modern industrial robots that fit this definition.

The microprocessor was the enabling device with regard to the wide-scale development and use of industrial robots. But major technological developments do not take place simply because of a new capability. Something must provide the impetus for taking advantage of the new capability. In the case of industrial robots, the impetus was economics.

In the 1970s it became imperative for the United States to produce better products at lower costs in order to be competitive with foreign manufacturers. Other factors, such as the need to find better ways of performing dangerous manufacturing tasks, contributed to the development of industrial robots. However, the principal rationale has always been, and is now, improved productivity.

Industrial robots offer a number of benefits that account for the rapid current and projected growth of industrial robot installations.

1. Increased productivity
2. Improved product quality



FIGURE 20-77 *Industrial robot.* (Courtesy Rixan Associates Inc.)

3. More consistent product quality
4. Reduced scrap and waste
5. Reduced reworking costs
6. Reduced raw goods inventory
7. Direct labor cost savings
8. Savings in related costs, such as lighting, heating, and cooling
9. Savings in safety-related costs
10. Savings from correctly forecasting production schedules

The Robot System

Work in a manufacturing setting is not accomplished by a robot. Rather, it is accomplished by a robot system. A robot system has four major components: the controller, the robot arm or manipulator, the end-of-arm tools, and the power sources, *Figure 20-78.* These components, coupled with the various other pieces of equipment and tools needed to perform the job for which a robot is programmed, are called the robot's work cell.

Figure 20-79 contains a schematic drawing of the work cell for the Cincinnati Milicron Corporation's T3-726 robot, which is used for TIG welding. Notice that the work cell contains not only the robot system



FIGURE 20-78 *The robot system.*



FIGURE 20-79 *Robot work cell.* (Courtesy Cincinnati Milacron)

but an index table, an operator's safety shield, and special welding equipment.

The contents of a robot's work cell will vary according to the application of the robot. However, the one constant in a robot's work cell is the robot system.

The Controller. A *robot* is a special-purpose device similar to a computer. As such, it has all the normal components of a computer, including the central processing unit—made up of a control section and an arithmetic/logic section—and a variety of input and output devices.

The controller for a robot system does not look like the microcomputer one is used to seeing on a desk. It must be packaged differently so as to be able

to withstand the rigors of a manufacturing environment. Typical input/output devices used in conjunction with a robot controller include teach stations, teach pendants, a display terminal, a controller front panel, and a permanent storage device.

Teach terminals, teach pendants, or front panels are used for interacting with the robot system. These devices allow humans to turn the robot on, write programs, and key in commands to the robot system. Display terminals give operators a soft copy output source. The permanent storage device is a special device on which reusable programs can be stored. *Figure 20-80* is a photograph of a robot system. Notice the teaching box and controller.

Mechanical Arm. The mechanical arm, or manipulator, is the part of a robot system with which most people are familiar. It is the part that actually performs the principal movements in doing manufacturing-oriented work. Mechanical arms are classified according to the types of motions of which they are capable. The basic categories of motion for mechanical arms are rectangular, cylindrical, and spherical. *Figure 20-81* is a drawing of the mechanical arm for the Unimate Puma Series 700 robot.

End-of-Arm Tooling. The human arm by itself can perform no work. It must have a hand, which in turn, grips a tool. The mechanical arm of a robot, like the human arm, can perform no work. It, too, must have a hand, a tool, or a device that combines both functions. On industrial robots, the function of the wrist is performed by the tool plate. The tool plate is a special device to which end-of-arm tools are attached. The tools themselves vary according to the types of tasks the robot will perform. Any special device or tool attached to the tool plate to allow the robot to perform some specialized task is classified as an end-of-arm tool or an end effector.



FIGURE 20-80 *Robot with programming device.* (Courtesy UNIMATION Inc.)



FIGURE 20-81 *Robot mechanical arm.* (Courtesy UNIMATION Inc.)

The Power Source. A robot system can be powered by three different types of power. The power sources used in a robot system are electrical, pneumatic, or hydraulic. The controller, of course, is powered by electricity, as is any computer. The mechanical arm and end-of-arm tools may be powered by either pneumatic or hydraulic power. Some robot systems will use all three types of power. For example, a given robot might use electricity to power the controller, hydraulic power to manipulate the arm, and pneumatic power to manipulate the end-of-arm tool. Hydraulic power is fluid based. Pneumatic power comes from compressed gas.

Figure 20-82 shows a widely used industrial robot with a gripper device as an end-of-arm tool. The tool plate is the rectangular plate immediately behind the gripper.



FIGURE 20-82 *End-of-arm-gripper.* (Courtesy Cincinnati Milacron)

CIM/FMS

Computer-integrated manufacturing is the most modern, most automated form of production. It involves tying different phases of production together into one wholly integrated system. The term "flexible manufacturing system" is sometimes used synonymously with computer-integrated manufacturing system. Actually, however, a flexible manufacturing system is one type of CIM system designed for medium-range production volumes and moderate flexibility. Other types of CIM systems are special systems and manufacturing cells. There are other terms that have been used to describe the same concept, but CIM and FMS are the two that are most widely used today.

There are several different types of computer-integrated manufacturing systems. This is because each system is designed to meet the specific needs of the individual manufacturing setting where it will be used. However, in general, a CIM system is any computerized manufacturing system in which numerically controlled machines are joined together and connected by some form of automated material handling system.

Figure 20-83 shows CNC machining centers linked together in an automated cell. In this system, two CNC machining centers are linked together by a cart-type material handling system. The cart system is further linked to four part load/unload stations to permit untended operation.

In a CIM system such as this, the computer is used in several ways: (1) it is used to control CNC machines;

FIGURE 20-83 *Example of a CIM system.* (Courtesy Cincinnati Milacron)

FIGURE 20-84 *FMS cellular manufacturing.* (Courtesy Cincinnati Milacron)

(2) it is used to control the materials handling system; and (3) it is used for monitoring all production tasks accomplished by the system.

(Note: Safety equipment may have been removed or opened to clearly illustrate products and must be in place prior to operation.)

Figure 20-84 is a photograph of a flexible manufacturing machine/robot cell. In this CIM system, rough castings are machined and inspected. The system contains two CNC machines, gaging devices, a conveyor, and two robots. The rough castings are loaded onto the conveyor by a robot, and finished castings are unloaded by a robot.

Figure 20-85 is a photograph of a composite tape laying (CTL) system. The CTL system automatically dispenses tape at speeds of 100 feet per minute. Tape can be automatically laid in 3″, 6″, or 12″ widths, debulked, cut, and overlaid ply-on-ply. Such systems are used in the manufacture of aircraft and space products.

In spite of advances in manufacturing automation, there is human involvement with a CIM system.

FIGURE 20-85 *ATL.* (Courtesy Cincinnati Milacron)

Typically, this involvement falls into six broad categories: (1) loading raw stock and materials onto the system for processing; (2) unloading processed workpieces from the system; (3) changing tools on machines within the system; (4) setting tools on machines within the system; (5) continuous maintenance of the system; and (6) occasional repair of the system when there is a breakdown or malfunction.

Stand-alone CNC machines are used in low-volume manufacturing applications that require a high degree of flexibility in order to produce a wide variety of parts. They represent one extreme of the manufacturing spectrum. At the other extreme are transfer lines. Transfer lines are used in high-volume manufacturing applications where all parts produced are identical. Transfer lines are not flexible; they cannot accommodate variety.

Transfer lines are a major component of what is sometimes referred to as "Detroit Automation." A transfer line consists of several workstations linked together by materials-handling devices that transfer workpieces from station to station.

The first station holds the raw material. The last station is a bin for collecting the finished parts. Each station in-between performs some type of operation on the parts as they pass through. The transfer of parts from station to station, and the work performed on them, are automatic. Transfer lines are appropriate in situations that involve the high-volume production of identical parts.

There has always been a gap between these two extremes, and there has always been a need to fill this gap. The medium-volume, moderate-flexibility manufacturing situation has long been a problem in need of a solution. CIM systems are such a solution. CIM fills the void between stand-alone CNC machines and transfer lines, *Figure 20-86.*

CIM offers a number of advantages that, when taken together, form the rationale for this modern



FIGURE 20-86 *Volume/flexibility continuum.*

approach to medium-volume, flexible production. The most important of these are:

1. Produces families of parts
2. Accommodates the random introduction of parts
3. Requires less lead time
4. Allows a closer relationship between parts to be produced and workpieces loaded onto the system
5. Allows better machine utilization
6. Requires less labor

CIM systems reduce the amount of direct and indirect labor costs associated with finished workpieces. This is because CIM systems require less human involvement in producing them. Ten to 12 traditional CNC machines require 10 to 12 operators. A CIM system with 10 to 12 CNC machines might require as few as four people. This means less direct labor. Indirect labor costs resulting from such tasks as materials handling are also reduced with CIM. This is because most material handling in CIM systems is automated.

Types of CIM Systems

CIM systems fall between transfer lines and stand-alone CNC machines on a graph of production volume versus part variety flexibility. By applying these same criteria—production volume and part variety—CIM systems can be divided into three categories, *Figure 20-87.*

1. Special systems
2. Flexible manufacturing systems
3. Manufacturing cells

The preceding systems are listed in order from the least flexible (special systems) to the most flexible (manufacturing cells). Of all CIM systems, those classified as special systems are capable of the most volume production and the least flexibility. Special systems might produce as many as 15,000 parts per year, but they are limited to less than 10 different part types.

Flexible manufacturing systems represent the middle group in CIM systems. An FMS might have a production volume as high as 2,000 parts per year and a capability of handling as many as 200 different parts.



FIGURE 20-87 *Categories of CIM systems.*

Figure 20-88 is a diagram of an FMS produced by Cincinnati Milacron.

The most flexible of CIM systems are manufacturing cells, which, in turn, are capable of the lowest production volumes. A manufacturing cell might have a production volume as low as 500 parts per year but a capability of handling as many as 500 different part types.

Just-in-Time Manufacturing (JIT)

Just-in-time manufacturing (JIT) is an approach to manufacturing that seeks to completely eliminate waste. The term *waste* is used here in the broadest sense and encompasses rejected parts, wasted personnel time, wasted machine time, excessive inventory, and any other situation that wastes time, material, or any other manufacturing resource. JIT has the following basic characteristics.

Process Synchronization

This characteristic is what gives JIT its name. *Process synchronization* means that all processes involved in producing a product are in balance and synchronized so that production flows smoothly and continuously. Traditionally, production processes have been operated on a *hurry-up-and-wait* basis. While one process is hurrying to complete its task, the next one in succession is idle. Process synchronization smoothes this out so that each successive process receives its material just-in-time to be processed.



FIGURE 20-88 *CIM system.* (Courtesy Cincinnati Milacron)

Simplicity

This characteristic is fundamental to JIT, the view being that the simpler things are, the easier JIT will be to accomplish. With JIT a continuous effort is made to simplify processes so that they can be performed with a continually decreasing amount of resources.

Wholistic View

This characteristic means that JIT cannot be accomplished by any individual unit operating in isolation. The entire company—all units—must be included in the effort. All processes, from purchasing to accounting and production, must be synchronized in order for JIT to work properly.

Manufacturing Resource Planning (MRPII)

Manufacturing resource planning is often referred to as MRPII to distinguish it from its predecessor, which was material requirements planning (MRP). MRP was a way to reduce inventory and waste through systematic planning for material requirements. MRPII is a broader concept that allows companies to systematically plan for all resources needed in manufacturing (i.e., material, capacity of production systems, personnel, time, etc.).

An MRPII system is computer based and typically consists of at least the following four components: (1) control database; (2) planning database; (3) functional modules; and (4) integrated modules. The control database contains inventory data and a master file on workcenters. The planning database contains a bill of materials file and a process routing file. Functional modules include production scheduling, capacity planning, material planning, and job cost reporting. Integrated modules or modules that might be integrated include such areas as sales, accounting, customer order processing, payroll, etc. Using MRPII properly simplifies the implementation of JIT because it helps synchronize all processes that are either directly or indirectly involved in producing the products in question.

Statistical Process Control (SPC)

Statistical process control (SPC) is a process that uses statistical control charts to monitor production processes in an attempt to reduce the amount of scrap and rework. Tolerances are transformed into upper and lower control limits that are placed on a chart. Periodically, points that correspond to the processing performance of the system are plotted on this chart. The plots are monitored visually or electronically. As long as all points plotted fall within established limits on the chart, the process is under control. If a point falls outside of the limits, corrections should be made immediately to prevent further production of unacceptable parts.

Summary

- Engineering materials are the raw materials that are converted into finished products in manufacturing. They can be divided into two broad categories: metals and nonmetals. Metals include steels, alloy steels, and a variety of high-performance alloys. Nonmetals include plastics, composites, elastomers, and ceramics.
- Casting is a process in which molten material is poured into a mold that contains the desired shape in the form of a cavity. The principal types of casting processes are sand casting, investment casting, centrifugal casting, and die casting.
- Forging is the process of forming metals under pressure using a variety of different processes. The most common forms of forging are drop forging and press forging. Other variations include rolling and upsetting.
- Extruding is a process of forcing metal through a die of a desired form and cross section.
- Stamping is a process of using dies to cut or form metal sheets or strips into a desired form.
- Machining is the process of removing metal with machine tools and cutters to achieve a desired form or feature. The principal types of machine tools are lathes, milling machines, drill presses, saws, and grinders.
- Special work holding devices are used to produce parts in high-volume production runs. These devices are called jigs and fixtures. Both jigs and fixtures hold, support, and locate the workpiece. Jigs guide the cutting tool through a hardened bushing during the cutting cycle. Fixtures reference the cutting tool by means of a set block.
- Heat treatment is a series of processes used to alter or modify the existing properties in a metal to obtain a specific condition required for a workpiece.
- Nontraditional machining encompasses a number of advanced machining processes that have been developed in response to the demands of modern manufacturing for more effective, more efficient ways to machine the many new materials that are now available.

- Computer-aided manufacturing (CAM) encompasses any manufacturing process that is automated through the use of computers. Examples of CAM are computer numerical control of machine tools and robotics.
- A robot is a reprogrammable, multifunctional manipulator designed to move materials, parts, tools, or specialized devices through variable programmed motions for the performance of a variety of tasks.
- Computer-integrated manufacturing (CIM) is the most modern form of production. It involves tying different phases of production together.
- A flexible manufacturing system is one type of CIM system designed for medium-range production volumes and moderate flexibility.
- Just-in-time manufacturing (JIT) is an approach to manufacturing that seeks to eliminate waste. Waste encompasses rejected parts, personnel time, machine time, excessive inventory, or any other resource. The key to JIT is process synchronization.
- Manufacturing resource planning or MRPII is a computer-based approach that allows companies to systematically plan for all resources needed in manufacturing (i.e., material, personnel, time, capacity of production systems, etc.).

Review Questions

Answer the following questions either true or false.

1. The term *lead time* means the interval of time from when the shop receives the drawing until production begins.
2. The cope and the cheek are terms used to describe the top and bottom sections of the flask used for casting.
3. The amount of shrinkage and the amount of expansion must be considered when making a pattern for casting.
4. The approximate percentage of shrinkage for steel is 3/16″ per foot.
5. Investment casting is also referred to as lost wax casting.
6. Centrifugal casting is the casting process in which molten metal is forced into metal dies.
7. There are usually six stations in a drop forge die.
8. Operations such as slitting, trimming, and shaving control size.
9. A drop hammer is the principal tool used in metal stamping.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** one of the major factors to consider before any part is made?
   a. the material the part will be made of
   b. the overall size and shape of the finished object
   c. types of operations required
   d. the cost of manufacturing the part
2. Which of the following is **not** one of the primary methods used to fabricate manufactured products?
   a. welding
   b. extruding
   c. stamping
   d. forging
3. Which of the following is **not** one of the common forging processes?
   a. rough forging
   b. drop forging
   c. press forging
   d. rolling
4. Which of the following is **not** one of the stamping operations that produces blanks?
   a. cutting off
   b. shearing
   c. trimming
   d. blanking
5. Which of the following stamping operations does not produce holes?
   a. punching
   b. piercing
   c. perforating
   d. all of the above
6. Which of the following is the most common type of fixture?
   a. plate fixture
   b. angle plate fixture
   c. vise jaw fixture
   d. indexing fixture
7. Which of the following is **not** one of the four operations used to bend or form parts?
   a. machining
   b. drawing
   c. forming
   d. bending
8. Which of the following is **not** one of the four machine tools used for machining parts?
   a. drill press
   b. fixtures

c. milling machine
d. lathe

9. Which of the following is **not** true regarding the plate jig?
   a. It is the most common form of jig.
   b. It is the least common form of jig.
   c. A typical variation of the plate jig is the table jig.
   d. A typical variation of the sandwich jig is the table jig.
10. Which of the following is **not** one of the operations normally performed on a drill press?
   a. cutting
   b. tapping
   c. reaming
   d. drilling
11. Which of the following is **not** an element of JIT?
   a. to eliminate waste
   b. process synchronization
   c. to build up inventory
   d. each process receives its material just in time
12. Which of the following is **not** an element of MRPII?
   a. control database
   b. planning database
   c. functional database
   d. integrated database

21

Drafting Applications: Pipe, Structural, Architectural, Civil Engineering, and GIS

CHAPTER OUTLINE

Types of pipe • Types of joints and fittings • Types of valves • Pipe drawings • Dimensioning pipe drawings Structural drafting • Pre-engineered metal buildings Architectural drafting • Civil engineering drafting Geographic information system • Summary • Review questions • Chapter 21 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Explain the appropriate applications of the most widely used types of pipe.
- Describe the three broad classifications of pipe joints and fittings.
- Explain the most widely used types of pipe valves.
- Demonstrate proficiency in developing pipe drawings.
- Describe the most widely used components in structural construction.
- Demonstrate proficiency in developing structural drawings.
- Demonstrate proficiency in developing plans for pre-engineered metal buildings.
- Explain each of the components in a set of residential plans.
- Compare/contrast residential and commercial architectural plans.
- Demonstrate proficiency in developing architectural plans.

(continued)

KEY TERMS

Anchor bolt plan
Attribute data
Buffering
Check valves
Contour lines
Eave strut connection details
Electrical plan
Elevations
Extracting
Floor plan
Foundation plan
Gate valves
Generalizing
Georelational data model
Geographic information systems
Girt connection details
Globe valves
Heating, ventilation, and air conditioning plan (HVAC)
Interval
Legal descriptions
Lot and block
Manual of Steel Construction
Mark number
Metes and bounds
Network analysis
Placing drawings
Plot plan
Point-in-polygon responses
Polygon overlay
Pre-engineering
Purlin connection details
Rectangular system
Relational database management systems
Roof plan
Spatial analysis
Spatial data
Spatial queries
Structure
Topology
What-if scenarios

(CHAPTER OBJECTIVES continued)

- Demonstrate proficiency in fundamental civil engineer drawing.
- Explain the applications of geographic information systems (GIS).

This is an application chapter that allows students to use the design and drafting skills they have learned in developing real-world projects in the areas of pipe, structural, and architectural drafting. Projects developed in this chapter relate directly to specific design and drafting career fields.

Types of Pipe

The wide variety of fluids used by modern society requires a number of different types of pipe. The most widely used of these are:

- Steel pipe
- Brass and copper pipe
- Plastic pipe
- Cast iron pipe
- Copper tubing

Steel Pipe

Steel pipe is well suited for high-pressure and high-temperature applications. It is frequently used in piping systems that transport water, oil, petroleum, and steam. Steel pipe comes in several cross-sectional configurations. The most widely used of these are the standard, extra strong, and double extra strong configurations, *Figure 21-1*. There are actually 10 different cross-sectional configurations for steel pipe.

Steel pipe is specified by a nominal diameter callout. The actual diameter will vary slightly from the nominal. The American National Standard Institute (ANSI) specifies pipe in 10 different schedules. Each schedule corresponds to a wall thickness. For example, standard and extra strong pipe are Schedules 40 and 80, respectively. The nominal diameter for pipe up to 12″ refers to the inside diameter. Callouts are given in inches or millimeters. The nominal diameter for pipe over 12″ refers to the outside diameter.



FIGURE 21-1 *Schedule of pipe.*

Cast Iron Pipe

Cast iron pipe is used most frequently for underground applications—to transport water, gas, and sewage. It is well suited for low-pressure steam connections also.

Brass and Copper Pipe

Brass and copper pipe are used in applications where corrosion will be a problem. Because brass and copper are able to withstand corrosion, the expected lifetime of a piping system in a high-corrosive setting will be longer if brass or copper pipe is used.

Copper Tubing

Copper tubing is used extensively in applications where vibration and misalignment are important factors. It is used in hydraulic and pneumatic applications, such as industrial settings involving robots, and in automotive settings.

Plastic Pipe

Plastic pipe is used extensively in modern piping settings. It is highly resistant to corrosion and chemical degradation. Plastic pipe is flexible and can be easily installed. However, it is not used where heat or pressure are factors. Plastic pipe does not have the chemical makeup to withstand heat or the wall strength to withstand high pressures.

Types of Joints and Fittings

Each kind of pipe explained in the previous section comes in straight length. However, piping systems require turns and branches and changes of size. In every instance where a pipe must change directions or size there is a joint. Joints are accomplished using fittings. There are three broad classifications of fittings:

1. Screwed
2. Flanged
3. Welded

Figure 21-2 illustrates these three types of fittings.

Engineers and drafters need to be able to specify pipe fittings. A given pipe fitting is specified by stating the nominal pipe size, the name of the fitting, and the material out of which the fitting is made. Any fitting that is used to connect different sizes of pipes is referred to as a "reducing fitting." When specifying reducing fittings, you must state the nominal pipe sizes for both the large and small end of the fitting. The large size is stated first. There are enough differences among screwed, flanged, and welded fittings that each must be studied separately.



FIGURE 21-2 *Pipe connections.*

Screwed Fittings

Screwed fittings are generally used in applications requiring small diameter pipe of 2.5″ or less. The threaded end of the pipe and the internal threads on the fitting are usually coated with a special lubricant to seal the joint and to ease the connection process. ***Figures 21-3, 21-4, 21-5*** (page 775), and ***21-6*** (page 776) contain information on the most commonly used threaded type fittings. Figure 21-3 contains information on the 90° elbow, 90° street elbow, 45° elbow, 45° street elbow, and 90° reducing elbow. The table accompanying each illustration gives the type sizes with which that particular fitting can be used, the various dimensions in which it is available, and the weight of the fitting itself. Figure 21-4 contains information for blind flange, screwed flange, and flat band cap fittings, as well as bushings. Figure 21-5 contains information on union, coupling, cross, tee, and reducing tee fittings. Figure 21-6 contains information on plug, return bend, and lock nut fittings, as well as reducers and nipples.

There are two types of American Standard pipe threads: tapered and straight. Tapered threads are more common. Straight threads are usually used only for special applications. The ANSI Standard for Pipe Threads is ANSI/ASME B1.20.1-1983 (R1992). ***Figure 21-7*** (page 777) illustrates the conventions used for drawing pipe threads. ***Figure 21-8*** (page 777) illustrates the American National Standard taper pipe thread notation methods. Both types of threads have the same number of threads per inch.

Flanged Fittings and Joints

Some piping applications require that the piping systems occasionally be disassembled. When this is the case, flanged fittings are appropriate. Flanged fittings and adjoining pipes are bolted together. On occasion, flanged fittings and pipe may be welded together. However, they are normally bolted or glued together. ***Figure 21-9*** (page 777) contains size, weight, and dimensional data for the most common type of flanged fittings: 90° elbows, 45° elbows, tees, and reducers.

Welded Fittings and Joints

Some piping applications, such as high-pressure and high-temperature systems, require permanent fittings and joints. When this is the case, welded fittings are used. To accommodate the welding process, the connection ends of welded fittings as well as the ends of adjoining pipe are usually beveled. Welded fittings usually weigh less than flanged or screwed fittings, and they are easier to insulate.

Types of Valves

Fluids and gases do not just flow freely through piping systems. They must be regulated, and at certain points stopped. There are a number of different types of valves, including gate, globe, jet, swiveled joint, ball, check, and butterfly. The most frequently used of these are gate, globe, and check valves. These commonly used types of valves are illustrated in ***Figures 21-10*** (page 778), ***21-11*** (page 778), and ***21-12*** (page 778).

Gate Valves

Gate valves are used to turn the flow of liquids through a pipe on or off without restricting the flow of the liquids through the valve or with as little restriction as possible. Gate valves are not meant to be used to regulate the degree of flow. ***Figures 21-13*** (page 779) and ***21-14*** (page 780) contain dimensional data for two commonly used gate valve configurations.

Globe Valves

Globe valves are used to turn the flow of liquids through a pipe on and off, and they are used also to regulate the flow of fluids through the valve to the desired level. ***Figures 21-15*** (page 781) and ***21-16*** (page 782) contain dimensional data for two commonly used configurations of globe valves.

Check Valves

Check valves are used to restrict the flow of liquids through a pipe in only one direction. A backward flow

AVAILABLE STYLES AND SIZES

90° ELBOW

REFERENCE	PIPE SIZE, INCHES														
	⅛	¼	⅜	½	¾	1	1¼	1½	2	2½	3	3½	4	5	6
A	11/16	13/16	15/16	1⅛	1 5/16	1 7/16	1¾	1 15/16	2¼	2 11/16	3⅛	3 7/16	3¾	4½	5⅛
Weight	.055	.060	.095	.145	.210	.355	.705	.790	1.180	1.670	2.590	3.250	4 065	6.900	9.800



90° STREET ELBOW

REFERENCE	PIPE SIZE, INCHES										
	⅛	¼	⅜	½	¾	1	1¼	1½	2	2½	3
A	11/16	13/16	15/16	1⅛	1 5/16	1 7/16	1¾	1 15/16	2¼	2 11/16	3⅛
B	1⅛	1 5/16	1 7/16	1⅝	1⅞	2⅛	2½	2 11/16	3 3/16	3 13/16	4½
Weight	025	045	085	.140	.180	.205	.495	.750	1.250	1 850	2.900



45° ELBOW

REFERENCE	PIPE SIZE, INCHES														
	⅛	¼	⅜	½	¾	1	1¼	1½	2	2½	3	3½	4	5	6
A	11/16	¾	13/16	⅞	1	1⅛	1 5/16	1 7/16	1 11/16	1 15/16	2 3/16	2⅜	2⅝	3 1/16	3 15/32
Weight	.040	.040	.075	.115	.200	.260	.455	.605	.970	1.420	1.925	2.530	3.335	5.650	8.700



45° STREET ELBOW

REFERENCE	PIPE SIZE, INCHES									
	⅛	¼	⅜	½	¾	1	1¼	1½	2	2½
A	—	—	—	11/16	13/16	1⅜	1 17/32	1 5/16	1⅜	2 1/16
B	—	—	—	13/16	1⅜	1 17/32	1 23/32	2¼	2⅜	2½
Weight	—	—	—	.140	.180	.205	.495	.700	1.000	1.625



90° REDUCING ELBOW

Size	Weight
½" x ¼"	.115
½" x ⅜"	.120
¾" x ½"	.190
1" x ½"	.260
1" x ¾"	.300
1¼" x ¾"	.405
1¼" x 1"	.470

Size	Weight
1½" x 1"	.560
1½" x 1¼"	.720
2" x 1¼"	1.000
2" x 1½"	1.030
2½" x 2"	1.745
3" x 2"	2.205
3" x 2½"	2.315

Size	Weight
4" x 3"	3.065

LATERALS — 1. 45° Y

a. Size Range - ½" through 3"

b. Dimensional Standard - F-52618-C (Revision)

NOTE: Any reducing fittings not specifically listed can be produced on a Special Order basis and will be subject to a Special Order charge of 25% of the listed retail price.

(For additional fittings see Page 8)

FIGURE 21-3 *Pipe fittings.* (Courtesy Latrobe Foundry Machine and Supply Co.)

AVAILABLE STYLES AND SIZES

FLANGE - Blind

REFERENCE	PIPE SIZE, INCHES										
	½	¾	1	1¼	1½	2	2½	3	3½	4	6
A	3½	3⅞	4¼	4⅝	5	6	7	7½	8½	9	11
B	7/16	7/16	7/16	½	9/16	⅝	11/16	¾	13/16	15/16	1
C	2⅜	2¾	3⅛	3½	3⅞	4¾	5½	6	7	7½	9½
D	⅝	⅝	⅝	⅝	⅝	¾	¾	¾	¾	¾	⅞
E	4	4	4	4	4	4	4	4	8	8	8
Weight	.275	.385	.560	.765	1.015	1.640	2.440	3.075	4.730	5.285	9.250



FLANGE - Screwed

FOR REDUCING, SLIP-ON, FLOOR AND WELDING NECK FLANGES SEE PAGE 8.

REFERENCE	PIPE SIZE, INCHES											
	½	¾	1	1¼	1½	2	2½	3	3½	4	5	6
A	3½	3⅞	4¼	4⅝	5	6	7	7½	8½	9	10	11
B	⅝	⅝	11/16	13/16	⅞	1	13/16	1¼	1¼	15/16	17/16	19/16
C	2⅜	2¾	3⅛	3½	3⅞	4¾	5½	6	7	7½	8½	9½
D	⅝	⅝	⅝	⅝	⅝	¾	¾	¾	¾	¾	⅞	⅞
E	4	4	4	4	4	4	4	4	8	8	8	8
Weight	.255	.375	.550	.740	.970	1.530	2.385	2.835	4.250	4.565	5.650	6.850



CAP - Flat Band

REFERENCE	PIPE SIZE, INCHES														
	⅛	¼	⅜	½	¾	1	1¼	1½	2	2½	3	3½	4	5	6
A	19/32	25/32	27/32	11/16	15/32	1¼	15/16	115/32	19/16	21/32	21/16	23/32	23/16	2⅜	2⅝
Weight	.015	.025	.050	.075	.100	.150	.290	.350	.450	.760	1.435	1.825	3.080	4.950	6.500



BUSHINGS

Size	Weight
¼" x ⅛"	.010
⅜" x ⅛"	.020
⅜" x ¼"	.015
½" x ⅛"	.045
½" x ¼"	.030
½" x ⅜"	.030
¾" x ¼"	.055
¾" x ⅜"	.050
¾" x ½"	.045
1" x ¼"	.110
1" x ⅜"	.105
1" x ½"	.090

Size	Weight
1" x ¾"	.070
1¼" x ⅜"	.170
1¼" x ½"	.165
1¼" x ¾"	.145
1¼" x 1"	.130
1½" x ½"	.215
1½" x ¾"	.210
1½" x 1"	.205
1½" x 1¼"	.125
2" x ½"	.370
2" x ¾"	.370
2" x 1"	.365

Size	Weight
2" x 1¼"	.325
2" x 1½"	.285
2½" x 1"	.785
2½" x 1¼"	.755
2½" x 1½"	.715
2½" x 2"	.605
3" x 1¼"	1.095
3" x 1½"	1.015
3" x 2"	.895
3" x 2½"	.705
3½" x 2"	1.120
3½" x 2½"	.920

Size	Weight
3½" x 3"	.750
4" x 1½"	1.860
4" x 2"	1.720
4" x 2½"	1.535
4" x 3"	1.255
5" x 2"	2.600
5" x 3"	2.350
5" x 4"	2.000
6" x 3"	3.950
6" x 4"	3.600
6" x 5"	3.250

FIGURE 21-4 *Pipe fittings.* (Courtesy Latrobe Foundry Machine and Supply Co.)

AVAILABLE STYLES AND SIZES

UNION

REFERENCE	PIPE SIZE, INCHES												
	1/8	1/4	3/8	1/2	3/4	1	1 1/4	1 1/2	2	2 1/2	3	3 1/2	4
A	1 9/16	1 13/16	1 15/16	2	2 1/8	2 3/4	3	3	3 1/4	3 3/8	4 1/8	4 7/8	5
Weight	145	130	.170	255	330	505	790	.815	1 250	1.745	2.865	5.000	5.800



COUPLING

FOR HALF COUPLINGS AND HEAVY WALL COUPLINGS SEE PAGE 8

REFERENCE	PIPE SIZE, INCHES														
	1/8	1/4	3/8	1/2	3/4	1	1 1/4	1 1/2	2	2 1/2	3	3 1/2	4	5	6
A	19/32	3/4	29/32	11/16	1 11/32	1 5/8	1 31/32	2 15/64	2 23/32	3 5/16	3 15/16	4 7/16	4 15/16	6 1/16	7 3/16
B	15/16	1 1/32	1 5/32	1 5/16	1 9/16	1 13/16	2 1/16	2 5/16	2 9/16	2 7/8	3 1/16	3 7/16	3 7/16	4 1/8	4 1/8
Weight	020	025	035	.060	.100	.135	.230	.310	.500	.730	1.015	1.740	2.040	3.300	4.500



CROSS

REFERENCE	PIPE SIZE, INCHES												
	1/8	1/4	3/8	1/2	3/4	1	1 1/4	1 1/2	2	2 1/2	3	3 1/2	4
A	11/16	13/16	15/16	1 1/8	1 5/16	1 7/16	1 3/4	1 15/16	2 1/4	2 11/16	3 1/8	3 7/16	3 3/4
Weight	050	.085	.155	.215	340	.565	.825	1.115	2.115	2.730	4.000	5.200	6.210



TEE

FOR LATERALS SEE PAGE 2

REFERENCE	PIPE SIZE, INCHES														
	1/8	1/4	3/8	1/2	3/4	1	1 1/4	1 1/2	2	2 1/2	3	3 1/2	4	5	6
A	11/16	13/16	15/16	1 1/8	1 5/16	1 7/16	1 3/4	1 15/16	2 1/4	2 11/16	3 1/8	3 7/16	3 3/4	4 1/2	5 1/8
Weight	060	.070	.130	.180	.285	.435	.745	1.060	1.760	2.250	3.035	4.135	5.580	9.510	13.000



REDUCING TEE

NOTE: In the listing of reducing tees, the last dimension shown is the size of the branch.

Size	Wt.
1/2" x 1/2" x 1/4"	195
1/2" x 1/2" x 3/8"	190
1/2" x 1/2" x 3/4"	320
3/4" x 1/2" x 1/2"	320
3/4" x 1/2" x 3/4"	305
3/4" x 3/4" x 3/8"	315
3/4" x 3/4" x 1/2"	305
3/4" x 3/4" x 1"	465
1" x 1/2" x 1/2"	190
1" x 3/4" x 1/2"	515
1" x 3/4" x 3/4"	495
1" x 3/4" x 1"	465
1" x 1" x 3/8"	495

Size	Wt.
1" x 1" x 1/2"	485
1" x 1" x 3/4"	.465
1" x 1" x 1 1/4"	850
1" x 1" x 1 1/2"	1 300
1 1/4" x 3/4" x 1 1/4"	.830
1 1/4" x 1" x 3/4"	885
1 1/4" x 1" x 1"	855
1 1/4" x 1 1/4" x 1/2"	850
1 1/4" x 1 1/4" x 3/4"	850
1 1/4" x 1 1/4" x 1"	800
1 1/4" x 1 1/4" x 1 1/2"	1 170
1 1/2" x 3/4" x 1 1/2"	1 220
1 1/2" x 1" x 1"	1 300

Size	Wt.
1 1/4" x 1" x 1 1/2"	1.180
1 1/2" x 1 1/4" x 1"	1 230
1 1/2" x 1 1/4" x 1 1/4"	1 170
1 1/2" x 1 1/2" x 1/2"	1 245
1 1/2" x 1 1/2" x 3/4"	1.220
1 1/2" x 1 1/2" x 1"	1.180
1 1/2" x 1 1/2" x 1 1/4"	1.115
1 1/2" x 1 1/2" x 2"	1.280
2" x 1 1/2" x 1 1/2"	1.315
2" x 1 1/2" x 2"	1.755
2" x 2" x 1/2"	0.995
2" x 2" x 3/4"	1.290
2" x 2" x 1"	1.300

Size	Wt.
2" x 2" x 1 1/4"	1.325
2" x 2" x 1 1/2"	1.470
2" x 2" x 2 1/2"	1.910
2 1/2" x 2" x 2"	1.925
2 1/2" x 2 1/2" x 2"	2.095
3" x 3" x 2"	2.690
4" x 4" x 2"	4.015
4" x 4" x 3"	5.095
6" x 6" x 4"	10.850

FIGURE 21-5 *Pipe fittings.* (Courtesy Latrobe Foundry Machine and Supply Co.)

AVAILABLE STYLES AND SIZES

PLUG

COUNTERSUNK PLUGS

REFERENCE	PIPE SIZE, INCHES														
	1/8	1/4	3/8	1/2	3/4	1	1 1/4	1 1/2	2	2 1/2	3	3 1/2	4	5	6
A	5/8	11/16	13/16	7/8	1	1 3/16	1 7/16	1 3/8	1 9/16	1 11/16	1 13/16	2	2 3/16	2 3/8	2 9/16
Weight	.010	.015	.020	.030	.055	.090	.150	.215	315	.560	.755	.910	1.500	2.150	3.500

COUNTERSUNK PLUGS - Square Head Size Range 3/8" through 4"
Dimension Standard - ANSI B16.14-1949

RETURN BEND - Close

REFERENCE	PIPE SIZE, INCHES								
	1/8	1/4	3/8	1/2	3/4	1	1 1/4	1 1/2	2
A	–	–	–	1 1/4	1 1/2	1 3/4	2 1/4	2 1/2	3 1/4
B	–	–	–	2 3/8	3 5/32	3 29/32	4 21/32	5 7/32	6 19/32
Weight	–	–	–	205	275	.440	780	1 000	1 840



LOCK NUT

REFERENCE	PIPE SIZE, INCHES										
	1/8	1/4	3/8	1/2	3/4	1	1 1/4	1 1/2	2	2 1/2	3
A	–	5/32	3/16	1/4	5/16	3/8	7/16	1/2	5/8	3/4	13/16
Weight	–	.015	.020	025	045	.080	105	.175	.345	.425	740

REDUCERS

Size	Weight
1/4" x 1/8"	.040
3/8" x 1/8"	.060
3/8" x 1/4"	.060
1/2" x 1/4"	.100
1/2" x 3/8"	.095
3/4" x 1/4"	.150
3/4" x 3/8"	.130
3/4" x 1/2"	.160
1" x 1/2"	.215

Size	Weight
1" x 3/4"	.240
1 1/4" x 3/4"	.330
1 1/4" x 1"	.340
1 1/2" x 3/4"	.480
1 1/2" x 1"	.490
1 1/2" x 1 1/4"	.560
2" x 1"	.710
2" x 1 1/4"	.745

Size	Weight
2" x 1 1/2"	.825
2 1/2" x 2"	1.180
2 1/2" x 1 1/2"	1.200
3" x 2"	1.790
3" x 2 1/2"	1.750
4" x 3"	3.375
5" x 4"	4.75
6" x 4"	5.00
6" x 5"	5.00

NIPPLES - Close

ADDITIONAL NIPPLES *

Pipe Size	Length	Weight	Pipe Size	Length	Weight	Pipe Size	Length	Weight	Pipe Size	Length	Weight
1/8"	3/4"	.005	3/4"	1 3/8"	.045	1 1/2"	1 3/4"	.135	3"	2 5/8"	.570
1/4"	7/8"	.010	1"	1 1/2"	.075	2"	2"	.210	3 1/2"	2 3/4"	.720
3/8"	1"	.015	1 1/4"	1 5/8"	.105	2 1/2"	2 1/2"	.415	4"	2 7/8"	.895
1/2"	1 1/8"	.030									

* NIPPLES 1. Long Nipples a. Size Range – 1/8" through 4"
b. Length – through 12"

FIGURE 21-6 *Pipe fittings.* (Courtesy Latrobe Foundry Machine and Supply Co.)

is checked by the valve, which is activated by any change in the direction of flow. *Figures 21-17* (page 783) and *21-18* (page 784) contain dimensional data for two commonly used configurations of check valves.

Pipe Drawings

Pipe drawings are used like any other design drawing, to convey the intentions of the designer and engineer to the tradespeople who will actually construct the piping system. There are two types of pipe drawings: single-line and double-line. *Figure 21-19* (page 785) is an example of a double-line drawing. *Figure 21-20* (page 785) is an example of the single-line version of the same drawing. Single-line drawings, since they are schematic, can be drawn much faster. However, drafters and engineers should be familiar with both double-line and single-line versions of pipe drawings, since both have applications on the job.

Single-Line Drawings

Single-line pipe drawings consist of schematic, symbolic representations of valve fittings connected by a single line that represents the center line of the pipe.



FIGURE 21-7 *Pipe thread conventions.*



FIGURE 21-8 *Pipe thread notation.* (Reprinted from *ANSI/ASME Standard B1.20.1-1983 (R1992).* Courtesy ANSI/ASME)



AVAILABLE STYLES AND SIZES

90° ELBOW

REFERENCE	PIPE SIZE, INCHES					
	1½	2	2½	3	4	6
A	4	4½	5	5½	6½	8
Weight	5	6¼	8	8½	10	20

45° ELBOW

REFERENCE	PIPE SIZE, INCHES					
	1½	2	2½	3	4	6
A	2¼	2½	3	3	4	5
Weight	3	4	10	6	6½	16

TEE

REFERENCE	PIPE SIZE, INCHES					
	1½	2	2½	3	4	6
A	4	4½	5	5½	6½	8
Weight	5	9	13	13½	20	30

REDUCER

REFERENCE	PIPE SIZE, INCHES					
	2 x 1½	2½ x 1½ 2½ x 2	3 x 2 3 x 2½	4 x 3	6 x 3	6 x 4
A	5	5½	6	7*	9*	9*
Weight	4	6	8	9	12¼	14

356-F

*Face-to-face dimension

All 3" fittings have a 7 1/2" flange diameter, a 6" bolt circle diameter, 4 bolt holes and 3/4" diameter bolt holes.

All 4" fittings have a 9" flange diameter, a 7 1/2" bolt circle diameter, 8 bolt holes and 3/4" diameter bolt holes.

All 6" fittings have an 11" flange diameter, a 9 1/2" bolt circle diameter, 8 bolt holes and 7/8" diameter bolt holes.

All 1 1/2" fittings have a 5" flange diameter, a 3 7/8" bolt circle diameter, 4 bolt holes and 5/8" diameter bolt holes.

All 2" fittings have a 6" flange diameter, a 4 3/4" bolt circle diameter, 4 bolt holes and 3/4" diameter bolt holes.

All 2 1/2" fittings have a 7" flange diameter, a 5 1/2" bolt circle diameter, 4 bolt holes and 3/4" diameter bolt holes.

FIGURE 21-9 *Pipe fittings.* (Courtesy Latrobe Foundry Machine and Supply Co.)

Figure 21-21 (pages 785 and 786) contains all of the various schematic symbols used for representing pipe fittings and valves on single-line pipe drawings. *Figure 21-22* (page 787) contains the graphic symbols used for representing piping on single-line pipe drawings.

Like mechanical drawings, pipe drawings may be drawn using orthographic or isometric projection. Single-line orthographic projection is the recommended form of representation in most cases. *Figure 21-23* (page 787) is an example of single-line orthographic projection of a pipe drawing. Single-line



FIGURE 21-10 *Gate valve.*



FIGURE 21-11 *Globe valve.*



FIGURE 21-12 *Check valve.*

isometric projection, as illustrated in *Figure 21-24* (page 787), is often used for assembly and layout work because the drawing is easier for tradespeople to understand. Regardless of whether you are using orthographic or isometric projection, there are certain drawing conventions with which you should be familiar. The most important of these are crossings, connections, fittings, and machine/devices.

Crossings. When lines representing pipe on a drawing cross but do not intersect or make connections, they are usually drawn without breaks. However, on occasion it will be necessary to show breaks so that tradespeople using the plans will be absolutely sure as to which pipe is nearest to them and which is farthest away. When such a need arises, breaks can be used as illustrated in *Figure 21-25* (page 788). When one uses break, it should be wide enough to be easily seen but not so wide as to create an inordinate gap. A widely used rule of thumb is to make the break from 5 to 10 times the thickness of the lines representing the pipe.

Connections. All of the various means of making connections at joints and fittings fall into two categories: permanent and detachable. On single-line pipe drawings, permanent connections are indicated by using a heavy dot. Detachable connections are indicated by a single thick line. Both of these methods are illustrated in *Figure 21-26* (page 788).

Fittings. When drawing fittings on single-line drawings it is sometimes necessary to be able to indicate whether a pipe is coming toward the viewer or going away from the viewer. It is also necessary at times to indicate whether the viewer is looking at a front view of the fitting or a rear view. All of the varied types of single-line drawing situations that you may confront when drawing fittings are covered in Figure 21-21. Refer to Figure 21-21 when drawing any type of single-line fitting symbol.

Machines and Devices. Most piping systems will tie into machines, devices, and other types of apparatus, *Figure 21-27* (page 788). When this is the case, the machines, devices, and other types of apparatus can be drawn using thin phantom lines.

Dimensioning Pipe Drawings

There are several dimensioning rules that apply specifically to pipe drawings with which you should be familiar. The most important of these are summarized in the following list.

- Dimensions for pipes and pipe fittings should be shown from center-to-center of pipe and to the outside face of the pipe end or flange.
- The length of pipe is not shown on the drawing except in rare cases.
- Pipe sizes are shown on the drawing using leader lines or as a general note.
- Fitting sizes are shown on the drawing using leader lines or as a general note.
- Pipes with bends should be dimensioned from vertex to vertex.
- The radii of bent pipe should be indicated using a leader line. Supplementary angles of bent pipes should be dimensioned in the normal manner.



STAINLESS STEEL GATE

CLASS 150

FIGURES: 110 (½″ to 2″), 114 (½″ to 2″), 116 (1½″ to 12″), 117 (½″ to 12″)

DESIGN DESCRIPTION:

Outside Screw and Yoke
Bolted Bonnet
Rising Stem
Non-Rising Handwheel
Integral Seats
Threaded Ends (Fig 110)
Socket Weld Ends (Fig. 114)
Buttwelding Ends (Fig. 116)
Flanged Ends (Fig. 117)
Male-Female Bonnet Joint Sizes ½″ to 1″ Incl.
Double Disc Ball-and-Socket Type Wedge
Flat Faced Flanged Valves, Specify Fig. 117-FF







Note: For Valve Services at Temperatures above 700°F, the Aloyco Engineering Department should be consulted for materials and features.

For Engineering Specifications and Data, see Engineering Section of Catalog.

PARTS AND MATERIAL LIST:

DESCRIPTION	ALOYCO 18-8 SMO	DESCRIPTION	ALOYCO 18-8 SMO
1 body*	A351 GR CF8M	15 yoke bushing†	wrought B16 or cast B584-C83600
2 bonnet	A351 GR CF8M	16 handwheel	malleable iron
3 male disc	wrought-type 316 or	17 yoke nut set screw	type 303
4 female disc	cast A351 GR CF8M	18 disc arm pin	type 316
5 disc arm	A351 GR CF8M	19 handwheel key	steel
6 gasket†	comp. asbestos or teflon	20 yoke bushing nut†	wrought B16 or cast B584-C83600
7 stem	type 316	21 grease fitting	steel
8 bonnet bolt	A193 GR B8	22 yoke	CF8
9 bonnet bolt nut	A194 GR 8F	23 yoke bolt	A193 GR B8
10 gland plate	A351 GR CF8M	24 yoke bolt nut	A194 GR 8F
11 gland follower	wrought-type 316 or cast A351 GR CF8M	25 gland stud	A193 GR B8
12 packing†	braided asbestos or teflon	26 gland stud nut	A194 GR 8F
13 gland bolt	A193 GR B8		
14 gland bolt nut	A194 GR 8F		

Remarks: *Body material on threaded and welding end valves is ELC grade Other Alloys available. (Refer to Introduction)

†Unless otherwise specified, these valves may be supplied at the manufacturer's option with: PTFE Gasket and Packing; Type 303 yoke bushing and nut. Such valves are limited to a temperature of 550 F and are so tagged.

DIMENSIONS IN MM AND INCHES:

SIZE	MM / INCH	15 / ½	20 / ¾	25 / 1	32 / 1¼	40 / 1½	50 / 2	65 / 2½	80 / 3	100 / 4	150 / 6	200 / 8	250 / 10	300 / 12
a(110, 114)	mm	70	80	89	108	114	121	..	.	.	..	..	....	—
	inch	2¾	3	3½	4¼	4½	4¾							
a(116)	mm	—	—	—	—	165	216	241	283	305	403	419	457	502
	inch					6½	8½	9½	11⅛	12	15⅞	16½	18	19¾
a(117)	mm	108	118	127	—	165	178	191	203	229	267	292	330	356
	inch	4¼	4⅝	5		6½	7	7½	8	9	10½	11½	13	14
b(110, 114)	mm	210	210	238	277	286	337	—	—	—	—	—	—	—
	inch	8¼	8¼	9⅜	10⅞	11¼	13¼							
b(116, 117)	mm	210	210	235	—	291	337	394	432	527	781	1016	1219	1524
	inch	8¼	8¼	9¼	—	11 7/16	13¼	15½	17	20¾	30¾	40	48	60
c	mm	89	100	100	127	127	150	178	191	250	305	356	406	457
	inch	3½	4	4	5	5	6	7	7½	10	12	14	16	18
d(114)	mm	13	13	13	13	13	16	—	—	—	—	—	—	—
	inch	½	½	½	½	½	⅝							
d(117)	mm	11	11	11	—	14	16	18	19	24	25	29	30	32
	inch	7/16	7/16	7/16	—	9/16	⅝	11/16	¾	15/16	1	1⅛	1 3/16	1¼

WEIGHTS IN KG AND POUNDS:

110, 114	kg	2 8	2 9	4 0	5 9	7.0	9.0	—	—		.	.	—	—
	lb	6 3	6 5	9	13	15.5	20							
116	kg	—	—	.		7.0	10	14	16	26	56	91	151	223
	lb					15 5	21	30	35	63	124	201	332	492
117	kg	3 6	4.3	5.4	—	9.9	14	19	24	40	72	124	206	305
	lb	8	9.5	12		22	30	42	51	88	158	275	455	675

APPLICABLE CLASS 150 STANDARDS:

End Flanges, ANSI B16.5
Pipe Threads, ANSI B2.1
Design, API 603
Wall Section, ANSI B16.34
SW Ends (Bore and Depth), ANSI B16.11
BW Ends (Schedule 40), ANSI B16.25 and B16.10
Face-to-Face, ANSI B16.10
Pressure-Temperature Ratings, ANSI B16.34-1977

FIGURE 21-13 *Gate valve data.* (Courtesy Crane-Aloyco Inc.)





Fig. 9126

STAINLESS STEEL GATE

CLASS 150

FIGURES: 9126, 9127 (14″ to 24″)

DESIGN DESCRIPTION:

Outside Screw and Yoke
Bolted Bonnet
Rising Stem
Non-rising Handwheel
Solid Wedge

For Flat Faced Flanged Valves, Specify Fig. 9127-FF
Roller Bearing Yoke
Renewable Seat Rings
Buttwelding Ends (Fig. 9126)
Flanged Ends (Fig. 9127)

PARTS AND MATERIAL LIST:

DESCRIPTION	ALOYCO 18-8 SMO	DESCRIPTION	ALOYCO 18-8 SMO
1 body*	A351 GR CF8M	16 yoke bushing	B584 alloy C86200
2 bonnet	A351 GR CF8M	17 roller bearing	steel
3 wedge	A351 GR CF8M	18 yoke cap	CF8
4 seat ring	A351 GR CF8M	19 yoke cap bolt	A193 GR B8
5 gasket	comp. asbestos	20 yoke cap bolt nut	A194 GR 8F
6 stem	type 316	21 handwheel	malleable iron
7 bonnet studbolt	A193 GR B7	22 oil seal	flax
8 bonnet studbolt nut	A194 2H	23 yoke bushing nut	B584 alloy C86200
9 gland plate	A351 GR CF8M	24 handwheel key	steel
10 gland follower	A351 GR CF8M	25 yoke nut set screw	type 303
11 packing	braided asbestos	26 grease fitting	steel
12 stem hole bushing	A351 GR CF8M	27 hinge bolt	A193 GR B8
13 gland eyebolt	A193 GR B8	28 hinge bolt nut	A294 GR 8F
14 gland eyebolt nut	A194 GR 8F	29 yoke studbolt**	A193 GR B8
15 yoke	CF8	30 yoke studbolt nut**	A194 GR 8F

Remarks: *Body material on welding end valves to be ELC grade.
**Not shown.
Other Alloys Available. Refer to Introduction.

Note: For Valve Services at Temperatures above 700°F, the Aloyco Engineering Department should be consulted for materials and features.

DIMENSIONS IN MM AND INCHES:

SIZE	MM / INCH	350 / 14	400 / 16	450 / 18	500 / 20	600 / 24
a(9126)	mm	571	610	660	711	813
	inch	22½	24	26	28	32
a(9127)	mm	381	406	432	457	508
	inch	15	16	17	18	20
b	mm	1765	1870	2140	2369	2753
	inch	69½	73⅝	84¼	93¼	108⅜
c	mm	508	559	610	660	762
	inch	20	22	24	26	30
d(9127) thickness of flange	mm	35	37	40	43	48
	inch	1⅜	$1^{7}/_{16}$	$1^{9}/_{16}$	$1^{11}/_{16}$	1⅞

WEIGHTS IN KG AND POUNDS:

9126	kg	342	474	535	708	1043
	lb	754	1046	1180	1560	2300
9127	kg	419	559	644	848	1234
	lb	924	1232	1420	1870	2720

APPLICABLE CLASS 150 STANDARDS

End Flanges, ANSI B16.5
Design, ANSI B16.34
Wall Section, API 600

Buttwelding Ends (Schedule 40), ANSI B16.25 and B16.10
Face-to-Face, ANSI B16.10
Pressure-Temperature Ratings, ANSI B16.34-1977

FIGURE 21-14 *Gate valve data.* (Courtesy Crane-Aloyco Inc.)

STAINLESS STEEL GLOBE

CLASS 150

FIGURES: 422 (½″ to 2″), 427 (½″ to 6″)

DESIGN DESCRIPTION:

"V" Port Throttling
Bolted Bonnet
Outside Screw and Yoke
Position Indicator
Rising Stem
Non-rising Handwheel
Threaded Ends (Fig. 422)
Flanged Ends (Fig. 427)
When Flat Face End Flanges are Required Order as 427-FF



Fig. 422
Threaded Ends

PARTS AND MATERIAL LIST:

DESCRIPTION	ALOYCO 18-8 SMO	DESCRIPTION	ALOYCO 18-8 SMO
1 body	A351 GR CF8M	13 yoke bushing	cast B584 alloy 836 or wrought B16 half hard
2 bonnet	A351 GR CF8M	14 handwheel	malleable iron
3 disc	A351 GR CF8M	15 indicator	CF-16F
4 stem	type 316	16 indicator bolt	A193 GR B8
5 gasket	PTFE	17 escutcheon pins	type 304
6 bonnet bolts	A193 GR B8	18 indicating plate	type 304
7 bonnet bolt nuts	A194 GR 8F	19 yoke bushing nut	cast B584 alloy 836 or wrought B16 half hard
8 gland plate	CF8M	20 handwheel key	steel
9 gland follower	type 316	21 disc pin	type 316
10 packing	PTFE	22 yoke nut set screw	type 303
11 gland bolts	A193 GR B8		
12 gland bolt nuts	A194 GR 8F		

Other Alloys available. (Refer to Introduction)



Fig. 427
Sizes ½″ to 6″

DIMENSIONS IN MM AND INCHES:

SIZE	MM / INCH	15 ½	20 ¾	25 1	40 1½	50 2	65 2½	80 3	100 4	150 6
a	mm	86	95	108	140	165	—	—	—	—
	inch	3⅜	3¾	4¼	5½	6½				
a (F)	mm	108	117	127	165	203	216	241	292	406
	inch	4¼	4⅝	5	6½	8	8½	9½	11½	16
b	mm	180	235	259	283	308	330	368	419	584
	inch	$7^{11}/_{16}$	9¼	$10^{3}/_{16}$	11⅛	12⅛	13	14½	16½	23
c	mm	102	127	127	152	178	191	254	305	356
	inch	4	5	5	6	7	7½	10	12	14

WEIGHTS IN KG AND POUNDS:

422	kg	1.8	2.7	4.5	7.2	9.5	—	—	—	—
	lb	4	6	10	16	21				
427	kg	2.7	4	5.9	9.5	13	20	26	43	78
	lb	6	9	13	21	29	43	58	95	173

APPLICABLE CLASS 150 STANDARDS:

End Flanges, ANSI B16.5
Wall Section, ANSI B16.34
Face-to-Face, ANSI B16.10
Pressure-Temperature Ratings, ANSI B16.34-1977
Pipe Threads, ANSI B2.1



Fig. 422 (½″ to 2″)

FIGURE 21-15 *Globe valve data.* (Courtesy Crane-Aloyco Inc.)



STAINLESS STEEL GLOBE CLASS 150

FIGURES: 502 (½″ to 2″), 504 (½″ to 2″), 507 (½″ to 10″)

DESIGN DESCRIPTION:

Outside Screw and Yoke
Bolted Bonnet
Renewable PTFE Disc
Retained Gasket
Rising Stem and Handwheel
For Flat Faced Flanged Valve
Specify Fig. 507 FF

Integral Seat
Threaded Ends (Fig. 502)
Socket Weld Ends (Fig. 504)
Flanged Ends (Fig. 507)
Valves in Sizes 8″ and 10″ Have
Disc Guide Below Seat





Separable Yoke Detail
Sizes 8″ and 10″ only



Fig. 502 & 504

PARTS AND MATERIAL LIST:

DESCRIPTION	ALOYCO 18-8 SMO
1 body*	A351 GR CF8M
2 bonnet	A351 GR CF8M
3 disc holder	cast-CF8M, wrought-type 316
4 disc	PTFE
5 disc holder plate	cast-CF8M,
6 swivel nut	wrought-type 316
7 stem	type 316
8 gasket	PTFE
9 bonnet bolt	A193 GR B8
10 bonnet bolt nut	A194 GR 8F
11 gland plate	CF8M
12 gland follower	cast-CF8M, wrought-type 316
13 packing	PTFE

DESCRIPTION	ALOYCO 18-8 SMO
14 gland bolt	A193 GR B8
15 gland bolt nut	A194 GR 8F
16 yoke ***	CF8
17 yoke bushing	B16 half hard
18 yoke bushing nut	B16 half hard
19 yoke bolt ***	A193 GR B8
20 yoke bolt nut ***	A194 GR 8F
21 handwheel	malleable
22 swivel nut pin	type 316
23 disc holder plate nut**	type 316
24 disc holder nut pin	type 316
25 handwheel nut	type 303
26 yoke nut pin	type 303
27 I.D. plate	type 304

Remarks: *Body material on threaded and welding end valves is ELC grade
**Sizes ½″ to 2″ incl.
***Sizes 8″ and 10″ only.
Other Alloys Available. Refer to Introduction
Note: For Valve Services at Temperatures above 700°F, the Aloyco Engineering Department should be consulted for materials and features.

DIMENSIONS IN MM AND INCHES:

SIZE	MM / INCH	15 ½	20 ¾	25 1	40 1½	50 2	65 2½	80 3	100 4	150 6	200 8	250 10
a(502,504)	mm	86	95	108	140	165	—	—	—	—	—	—
	inch	3⅜	3¾	4¼	5½	6½						
a(507)	mm	108	117	127	165	203	216	241	292	406	495	622
	inch	4¼	4⅝	5	6½	8	8½	9½	11½	16	19½	24½
b(502,504)	mm	165	210	248	283	305	—	—	—	—	—	—
	inch	6½	8¼	9¾	11⅛	12						
b(507)	mm	165	210	251	283	305	327	359	425	533	622	822
	inch	6½	8¼	9⅞	11⅛	12	12⅞	14⅛	16¾	21	24½	32⅜
c	mm	67	76	102	127	152	178	203	254	305	406	457
	inch	2⅜	3	4	5	6	7	8	10	12	16	18
d(504) Depth of Socket	mm	10	13	13	13	16	—	—	—	—	—	—
	inch	⅜	½	½	½	⅝						
d(507) Flange Thickness	mm	11	11	11	14	16	17	19	24	25	29	30
	inch	7/16	7/16	7/16	9/16	⅝	11/16	¾	15/16	1	1⅛	1 3/16

WEIGHTS IN KG AND POUNDS:

502,504	kg	2.7	5	5	7.3	11	—	—	—	—	—	—
	lb	6	10	10	16	24						
507	kg	5	6.4	6.4	10	15	20.8	26	43	78	128.8	188.7
	lb	10	14	14	22	34	46	58	95	173	284	416

APPLICABLE CLASS 150 STANDARDS:

End Flanges, ANSI B16.5
Wall Section, ANSI B16.34
Face-to-Face, ANSI B16.10
Pipe Threads, ANSI B2.1
Socket Weld Ends (Bore and Depth), ANSI B16.11
Pressure-Temp. Ratings, ANSI B16.34-1977
Maximum Service Temperature, 450°F

FIGURE 21-16 *Globe valve data.* (Courtesy Crane-Aloyco Inc.)



Fig. 557
Flanged Ends

STAINLESS STEEL LIFT CHECK VALVES

CLASS 150

FIGURES: 550 (¼″ to 2″), 554 (¼″ to 2″), 556 (½″ to 6″), 557 (½″ to 6″)*



Fig. 557
Sizes ½″ to 6″

DESIGN DESCRIPTION:

Horizontal Type
Bolted Cover
Retained Gasket
Regrinding Disc
Integral Seat

Threaded Ends (Fig. 550)
Socket Weld Ends (Fig. 554)
Buttwelding Ends (Fig. 556)
Flanged Ends (Fig. 557)

Disc Detail
Sizes ¼″ to ¾″ incl.

PARTS AND MATERIAL LIST:

DESCRIPTION	ALOYCO 18-8 SMO
1 body*	A351 GR CF8M
2 cover	A351 GR CF8M
3 disc	cast CF8M or wrought type 316
4 disc guide**	type 316
5 cover bolt	A193 GR B8
6 cover bolt nut	A194 GR 8F
7 gasket	comp. asbestos

Remarks: *Body material on threaded and welding end valves is ELC grade. Other Alloys available. (Refer to Introduction)
**Sizes ¼″ to ¾″ incl.
†Unless otherwise specified, these valves may be supplied at the manufacturer's option with: PTFE Gasket.

Note: For Valve Services at Temperatures above 700°F, the Aloyco Engineering Department should be consulted for materials and features.

DIMENSIONS IN MM AND INCHES:

SIZE	MM / INCH	6 / ¼	10 / ⅜	15 / ½	20 / ¾	25 / 1	40 / 1½	50 / 2	65 / 2½	80 / 3	100 / 4	150 / 6
a (550,554)	mm	79	79	86	95	108	140	165	—	—	—	—
	inch	3⅛	3⅛	3⅜	3¾	4¼	5½	6½				
a (556,557)	mm	—	—	108	117	127	165	203	216	241	292	406
	inch			4¼	4⅝	5	6½	8	8½	9½	11½	16
b	mm	67	67	67	76	86	102	116	133	146	168	200
	inch	2⅝	2⅝	2⅝	3	3⅜	4	4 9/16	5¼	5¾	6⅝	7⅞
d (554)	mm	10	10	10	13	13	13	16	—	—	—	—
	inch	⅜	⅜	⅜	½	½	½	⅝				
d (557)	mm	—	—	11	11	11	14	16	17	19	24	25
	inch			7/16	7/16	7/16	9/16	⅝	11/16	¾	15/16	1

WEIGHTS IN KG AND POUNDS:

550,554	kg	1.4	1.4	1.8	2.3	2.9	5.9	7.3	—	—	—	—
	lb	3	3	4	5	6.3	13	16				
556	kg	—	—	2	2.7	3.4	6.8	10	12	18.6	28	51
	lb			4.5	6	7.5	15	22	26	41	61	112
557	kg	—	—	2.3	3	4.1	8	12.7	14	22	34	68
	lb			5	7	9	17.5	28	31	48	75	150



Fig. 556
Buttwelding Ends
½″ to 6″



Fig. 550
Threaded Ends
Fig. 554
Socket Weld Ends

APPLICABLE CLASS 150 STANDARDS:

End Flanges, ANSI B16.5
Wall Section, ANSI B16.34
Face-to-Face, ANSI B16.10
Pipe Threads, ANSI B2.1

SW Ends (Bore and Depth), ANSI B16.11
BW Ends (Sch. 40), ANSI B16.25 and B16.10
Pressure-Temp. Ratings, ANSI B16.34-1977

FIGURE 21-17 *Check valve data.* (Courtesy Crane-Aloyco Inc.)

STAINLESS STEEL LIFT CHECK VALVES

CLASS 600

FIGURES: 4550-A (½″ to 2″)
4554-A (½″ to 2″)
4557-A (½″ to 2″)



Fig. 4550-A
Threaded Ends

DESIGN DESCRIPTION:

Bolted Cover
Integral Seat
Horizontal Type
Threaded Ends (Fig. 4550-A)
Socket Weld Ends (Fig. 4554-A)
Buttwelding Ends (Fig. 4557-A)

PARTS AND MATERIAL LIST:

DESCRIPTION	ALOYCO 18-8 SMO
1 body	A351 GR CF8M
2 cover	A351 GR CF8M
3 disc	type 316
4 disc guide (½″ and ¾″)	type 316
5 cover studbolt	A193 GR B8
6 cover studbolt nut	A194 GR 8F
7 gasket	comp. asbestos

Other Alloys Available. Refer to Introduction.



Fig. 4550-A
Sizes ½″ to 2″

DIMENSIONS IN MM AND INCHES:

SIZE	MM / INCH	15 / ½	20 / ¾	25 / 1	40 / 1½	50 / 2
a(4550-A,4554-A)	mm	95	108	127	165	191
	inch	3¾	4¼	5	6½	7½
a(4557-A)	mm	165	191	216	241	387
	inch	6½	7½	8½	9½	15¼
b	mm	94	94	97	148	165
	inch	$3^{11}/_{16}$	$3^{11}/_{16}$	$3^{13}/_{16}$	$5^{13}/_{16}$	6½
d(4554-A)	mm	10	13	13	13	16
	inch	⅜	½	½	½	⅝
d(4557-A)	mm	14	16	17	22	25
	inch	$^9/_{16}$	⅝	$^{11}/_{16}$	⅞	1

WEIGHTS IN KG AND POUNDS:

4550-A,4554-A	kg	2.3	3	5	10	14
	lb	5	7	11	22	30
4557-A	kg	5	6.3	10	15	22
	lb	11	14	22	32	48



Disc Detail
Sizes ½″ and ¾″

APPLICABLE CLASS 600 STANDARDS:

End Flanges, ANSI B16.5
Wall Section, ANSI B16.34
Face-to-Face, ANSI B16.10
Buttwelding Ends (Schedule 40), ANSI B16.25 and B16.10
Pipe Threads, ANSI B2.1
Pressure-Temperature Rating, ANSI B16.34-1977
Socket Weld Ends (Bore and Depth), ANSI B16.11

Note: For Valve Services at Temperatures above 700°F, the Aloyco Engineering Department should be consulted for materials and features.



Fig. 4554-A
Socket Weld Ends
½″ to 2″



Fig. 4557-A
Buttwelding Ends
½″ to 2″

FIGURE 21-18 *Check valve data.* (Courtesy Crane-Aloyco Inc.)



FIGURE 21-19 *Double-line pipe drawing.*



FIGURE 21-20 *Single-line pipe drawing.*

- Outside diameters and wall thicknesses of pipe may be indicated on the drawing using a leader line or may be made part of a general note.
- A bill of material should be developed and placed directly on the pipe drawing or attached to it.

Single-Line Isometric Piping Drawings

Isometric piping drawings are prepared in a manner similar to mechanical piping drawings. The lines representing pipes are drawn parallel to either the X, Y, or Z axis, ***Figure 21-28*** (page 788). Flanges are represented using short strokes of equal thickness, ***Figure 21-29*** (page 788). Notice that flanges for horizontal pipe are drawn vertically and flanges for vertical pipe are drawn at the appropriate 30° angle to the horizontal.

Figure 21-30 (page 788) illustrates the various methods used for drawing valves. The unidirectional dimensioning illustrated in ***Figure 21-31*** (page 788) should be used in isometric piping drawings.



FIGURE 21-21 *Symbols for pipe fittings and valves.*



FIGURE 21-21 *(Continued) Symbols for pipe fittings and valves.*

AMERICAN STANDARD GRAPHICAL SYMBOLS FOR PIPING

AIR CONDITIONING

28 BRINE RETURN
29 BRINE SUPPLY
30 CIRCULATING CHILLED OR HOT-WATER FLOW
31 CIRCULATING CHILLED OR HOT-WATER RETURN
32 CONDENSER WATER FLOW
33 CONDENSER WATER RETURN
34 DRAIN
35 HUMIDIFICATION LINE
36 MAKE-UP WATER
37 REFRIGERANT DISCHARGE
38 REFRIGERANT LIQUID
39 REFRIGERANT SUCTION

HEATING

40 AIR-RELIEF LINE
41 BOILER BLOW OFF
42 COMPRESSED AIR
43 CONDENSATE OR VACUUM PUMP DICHARGE
44 FEEDWATER PUMP DISCHARGE
45 FUEL-OIL FLOW
46 FUEL-OIL RETURN
47 FUEL-OIL TANK VENT
48 HIGH-PRESSURE RETURN
49 HIGH-PRESSURE STEAM
50 HOT-WATER HEATING RETURN
51 HOT-WATER HEATING SUPPLY
52 LOW-PRESSURE RETURN
53 LOW-PRESSURE STEAM
54 MAKE-UP WATER
55 MEDIUM PRESSURE RETURN
56 MEDIUM PRESSURE STEAM

PLUMBING

57 ACID WASTE
58 COLD WATER
59 COMPRESSED AIR
60 DRINKING-WATER FLOW
61 DRINKING-WATER RETURN
62 FIRE LINE
63 GAS
64 HOT WATER
65 HOT-WATER RETURN
66 SOIL, WASTE OR LEADER (ABOVE GRADE)
67 SOIL, WASTE OR LEADER (BELOW GRADE)
68 VACUUM CLEANING
69 VENT

PNEUMATIC TUBES

70 TUBE RUNS

SPRINKLERS

71 BRANCH AND HEAD
72 DRAIN
73 MAIN SUPPLIES

FIGURE 21-22 *Symbols for piping.*



FIGURE 21-23 *Orthographic single-line pipe drawing.*



FIGURE 21-24 *Isometric single-line pipe drawing.*



FIGURE 21-25 *Drawing crossing pipe.*



FIGURE 21-26 *Drawing pipe connections.*



FIGURE 21-27 *Drawing adjoining machinery.*



FIGURE 21-28 *Isometric axes.*



FIGURE 21-29 *Drawing flanges.*



FIGURE 21-30 *Drawing valves.*



FIGURE 21-31 *Isometric pipe drawing.*

Structural Drafting

A *structure* is anything constructed of parts. In heavy construction this encompasses commercial buildings, industrial buildings, bridges, towers, parking decks, stadiums, and numerous other types of structures. *Figures* 21-32 and 21-33 are examples of modern

FIGURE 21-32 *Cleveland state office building.* (Courtesy Bethlehem Steel Corp.)

FIGURE 21-33 *ADT executive offices.* (Courtesy Precast/Pre-stressed Concrete Institute)

structures. Structures such as those shown in these figures are constructed of many parts. The overall structure must be designed and the design must be documented by engineering drawings. In addition, each individual part must be designed and the design must be documented by shop drawings. Structural drafting consists of preparing the documentation for the design of a structure so that the individual parts can be manufactured and the overall structure erected.

Documentation prepared by structural drafters consists primarily of engineering drawings and shop drawings. Engineering drawings convey structural design information (i.e., what types of products are to be used and in what sizes, how the various parts fit together, how the individual parts are connected, etc.). They consist of various types of framing plans (i.e., anchor bolt, column, beam, floor, and roof framing plans); sections; and connection details. ***Figure 21-34*** (page 790) is an example of an engineering drawing. It is a framing plan showing the placement of steel beams and joints for a commercial building. The original material used for preparing structural engineering drawings is typically a set of architectural plans and/or a set of engineering sketches and calculations.

Shop drawings convey all of the information needed to manufacture the individual parts of a structure and are sometimes referred to as detail drawings. They consist of the necessary views of individual members with sectional views added when necessary and a bill of material. ***Figure 21-35*** (page 791) is an example of a structural steel shop drawing showing all the information necessary to fabricate several steel beams. It also contains a bill of material showing all of the various materials needed to fabricate the beams shown on this shop drawing.

Drawing, Checking, Correcting, and Revising

Structural drafters prepare original drawings—engineering and/or shop drawing—using either CAD or manual drafting techniques. The drawings are then checked by a more experienced drafter, known as a checker, and an engineer. Checkers and engineers make sure the drawings conform to the specifications of the original material used to prepare them and that the drafter has correctly interpreted engineering calculations/sketches/instructions. Corrections that need to be made are marked on a checkprint, and the drafter corrects the original.

Drawings that have been produced, checked, and corrected must also be changed on occasion. Such changes are known as revisions. A revision is typically required as the result of an engineering or architectural change, whereas a correction is usually made as the result of a drafting error. Revisions are typically specified on a document called an Engineering Change Order (ECO). ***Figure 21-36*** (page 792) is an example of an ECO. Normally the cost of making revisions is charged against the company or department that ordered them.

Structural Products

The products that become the individual components of a structure are standardized for the most part. They are steel and concrete and, to a lesser extent, wood products. ***Figure 21-37*** (page 792) illustrates the most



FIGURE 21-34 *Engineering drawing.* (Courtesy Scott Steel Inc.)



FIGURE 21-35 *Structural steel shop drawing.* (Courtesy Scott Steel Inc.)

Scotford Steel International
832 Skipper Avenue
Fort Walton Beach, Florida 32548
904/863-5323

• Engineering Change Order •

Job Number 1759-A Date 3/11/93

Contractor Sharper Construction Co.

Architect Rand & Kendrick, AIA

Description of Change:

Shorten beams M7 and M8
by 3 inches

Wanda Clifford
Signature (Requesting)

(Signature (Approving)

FIGURE 21-36 *Engineering drawing.* (Courtesy Scott Steel Inc.)



FIGURE 21-37 *Structural steel shapes.* (From Goetsch, *Structural Drafting,* Delmar Publishers Inc.)

widely used structural steel shapes. They are W shapes, S shapes, M shapes, HP shapes, C shapes, MC shapes, equal-legged angles, unequal-legged angles, square tubing, rectangular tubing, circular tubing, pipe, and structural tees.

The various steel shapes shown in Figure 21-37 may be used to form the vertical and horizontal members in the structural skeleton of a building, stadium, tower, or any other type of structure. Vertical members are called columns. Horizontal members may be beams, joists, or girders. The *Manual of Steel Construction* published by the American Institute for Steel Construction (AISC) contains the dimensions and other design and drafting-related information for structural steel shapes. ***Figure 21-38*** is a page excerpted from the *Manual of Steel Construction*. Structural steel drafters



W Shapes
Dimensions

Shape	Area, A	Depth, d		Web: Thickness, t_w		$t_w/2$	Flange: Width, b_f		Flange: Thickness, t_f		Distance: k, k_{des}	Distance: k, k_{det}	Distance: k_1	Distance: T	Distance: Workable Gage
	in.^{2}	in.		in.		in.	in.		in.		in.	in.	in.	in.	in.
W16×100	29.5	17.0	17	0.585	9/16	5/16	10.4	10 3/8	0.985	1	1.39	1 7/8	1 1/8	13 1/4	5 1/2
×89	26.2	16.8	16 3/4	0.525	1/2	1/4	10.4	10 3/8	0.875	7/8	1.28	1 3/4	1 1/16		
×77	22.6	16.5	16 1/2	0.455	7/16	1/4	10.3	10 1/4	0.760	3/4	1.16	1 5/8	1 1/16		
×67[c]	19.7	16.3	16 3/8	0.395	3/8	3/16	10.2	10 1/4	0.665	11/16	1.07	1 9/16	1		
W16×57	16.8	16.4	16 3/8	0.430	7/16	1/4	7.12	7 1/8	0.715	11/16	1.12	1 3/8	7/8	13 5/8	3 1/2[g]
×50[c]	14.7	16.3	16 1/4	0.380	3/8	3/16	7.07	7 1/8	0.630	5/8	1.03	1 5/16	13/16		
×45[c]	13.3	16.1	16 1/8	0.345	3/8	3/16	7.04	7	0.565	9/16	0.967	1 1/4	13/16		
×40[c]	11.8	16.0	16	0.305	5/16	3/16	7.00	7	0.505	1/2	0.907	1 3/16	13/16		
×36[c]	10.6	15.9	15 7/8	0.295	5/16	3/16	6.99	7	0.430	7/16	0.832	1 1/8	3/4		
W16×31[c]	9.13	15.9	15 7/8	0.275	1/4	1/8	5.53	5 1/2	0.440	7/16	0.842	1 1/8	3/4	13 5/8	3 1/2
×26[c,v]	7.68	15.7	15 3/4	0.250	1/4	1/8	5.50	5 1/2	0.345	3/8	0.747	1 1/16	3/4	13 5/8	3 1/2
W14×730[h]	215	22.4	22 3/8	3.07	3 1/16	1 9/16	17.9	17 7/8	4.91	4 15/16	5.51	6 3/16	2 3/4	10	3-7 1/2-3[g]
×665[h]	196	21.6	21 5/8	2.83	2 13/16	1 7/16	17.7	17 5/8	4.52	4 1/2	5.12	5 13/16	2 5/8		3-7 1/2-3[g]
×605[h]	178	20.9	20 7/8	2.60	2 5/8	1 5/16	17.4	17 3/8	4.16	4 3/16	4.76	5 7/16	2 1/2		3-7 1/2-3
×550[h]	162	20.2	20 1/4	2.38	2 3/8	1 3/16	17.2	17 1/4	3.82	3 13/16	4.42	5 1/8	2 3/8		
×500[h]	147	19.6	19 5/8	2.19	2 3/16	1 1/8	17.0	17	3.50	3 1/2	4.10	4 13/16	2 5/16		
×455[h]	134	19.0	19	2.02	2	1	16.8	16 7/8	3.21	3 3/16	3.81	4 1/2	2 1/4		
×426[h]	125	18.7	18 5/8	1.88	1 7/8	15/16	16.7	16 3/4	3.04	3 1/16	3.63	4 5/16	2 1/8		
×398[h]	117	18.3	18 1/4	1.77	1 3/4	7/8	16.6	16 5/8	2.85	2 7/8	3.44	4 1/8	2 1/8		
×370[h]	109	17.9	17 7/8	1.66	1 5/8	13/16	16.5	16 1/2	2.66	2 11/16	3.26	3 15/16	2 1/16		
×342[h]	101	17.5	17 1/2	1.54	1 9/16	13/16	16.4	16 3/8	2.47	2 1/2	3.07	3 3/4	2		
×311[h]	91.4	17.1	17 1/8	1.41	1 7/16	3/4	16.2	16 1/4	2.26	2 1/4	2.86	3 9/16	1 15/16		
×283[h]	83.3	16.7	16 3/4	1.29	1 5/16	11/16	16.1	16 1/8	2.07	2 1/16	2.67	3 3/8	1 7/8		
×257	75.6	16.4	16 3/8	1.18	1 3/16	5/8	16.0	16	1.89	1 7/8	2.49	3 3/16	1 13/16		
×233	68.5	16.0	16	1.07	1 1/16	9/16	15.9	15 7/8	1.72	1 3/4	2.32	3	1 3/4		
×211	62.0	15.7	15 3/4	0.980	1	1/2	15.8	15 3/4	1.56	1 9/16	2.16	2 7/8	1 11/16		
×193	56.8	15.5	15 1/2	0.890	7/8	7/16	15.7	15 3/4	1.44	1 7/16	2.04	2 3/4	1 11/16		
×176	51.8	15.2	15 1/4	0.830	13/16	7/16	15.7	15 5/8	1.31	1 5/16	1.91	2 5/8	1 5/8		
×159	46.7	15.0	15	0.745	3/4	3/8	15.6	15 5/8	1.19	1 3/16	1.79	2 1/2	1 9/16		
×145	42.7	14.8	14 3/4	0.680	11/16	3/8	15.5	15 1/2	1.09	1 1/16	1.69	2 3/8	1 9/16		

[c] Shape is slender for compression with $F_y = 50$ ksi.
[g] The actual size, combination, and orientation of fastener components should be compared with the geometry of the cross-section to ensure compatibility.
[h] Flange thickness greater than 2 in. Special requirements may apply per AISC Specification Section A3.1c.
[v] Shape does not meet the h/t_w limit for shear in Specification Section G2.1a with $F_y = 50$ ksi.

FIGURE 21-38 *Page from the* Manual of Steel Construction. (Courtesy American Institute of Steel Construction)

must have a copy of this manual or ready access to it in order to prepare engineering and/or shop drawings.

Concrete products are either pre-stressed, precast, post-tensioned, or poured-on-site. Pre-stressed and post-tensioned products have steel cables running through them that are stretched to create tension that is equal to or greater than the opposite forces they will be subjected to when incorporated as part of a structure. These cables are in addition to the reinforcing bars, plates, and welded wire mesh normally cast into all structural concrete members. Precast products contain all of these items except the stressed steel cables. Poured-on-site concrete members do not contain the tensioned cables. They are strengthened with reinforcing bars, welded wire mesh, and steel plates only. Precast and poured-onsite members are the same except for where the pouring of concrete takes place; in a plant for precast and on-site for poured-on-site products.

With pre-stressed concrete products, the steel cables are tensioned before the concrete is poured into the form or before it is extruded in the case of cored flat slabs. With post-tensioned products the cables are placed in the form encased in a special conduit and tensioned after the concrete has cured.

Figures 21-39 and *21-40* illustrate some of the more widely used pre-stressed and post-tensioned concrete products. They include double-tee members, single-tee members, solid flat slabs, cored flat slabs, L-shaped beams, inverted T-shaped beams, rectangular beams, tee joists, and keystone joists.

Connecting Structural Members

The two most widely used methods for connecting individual structural members are bolting and welding. Structural steel construction uses both widely. Concrete construction relies more on welding but



FIGURE 21-39 *Standard precast concrete products.* (From Goetsch, *Structural Drafting,* Delmar Publishers Inc.)





FIGURE 21-40 *Standard precast concrete products.* (From Goetsch, *Structural Drafting,* Delmar Publishers Inc.)



FIGURE 21-41 *Structural steel pipe fabricated as a column.* (Courtesy Scott Steel Inc.)



FIGURE 21-42 *Welded connections.* (From Goetsch, *Structural Drafting,* Delmar Publishers Inc.)

does use some bolted connections. The information contained in Chapter 13 applies to the bolts that are used to fasten structural members. ***Figure 21-41*** shows a structural steel pipe column that will be bolted at the bottom (base plate) and at the top (top plate).

The information structural drafters need to know about welding and the proper use of welding symbols is covered in Chapter 19. ***Figure 21-42*** shows both steel and pre-stressed concrete members connected by welding. ***Figure 21-43*** shows the welding types and their corresponding symbols as approved by the American Institute of Steel Construction (AISC).

Structural Steel Drawings

The point was made earlier that structural steel drawings consist of both engineering drawings and shop or detail drawings. Engineering drawings are used to communicate what products are to be used; in what sizes and shapes; and how they are to be spaced, connected, and otherwise put together to form a structure. Engineering drawings for structural steel construction consist of framing plans, sections (as needed), and connection details. ***Figure 21-44*** (page 798) is an example of a second-floor framing plan for a commercial building. ***Figure 21-45*** (page 799) is an example of connection details for such a building.

Shop or detail drawings are used to fabricate the individual structural members that are laid out on the engineering drawings. They are very detailed and typically are accompanied by a bill of material. ***Figure 21-46*** (page 800) is a shop drawing showing the fabrication details for several structural steel beams. The shop drawing contains a bill of material listing all of the material needed to fabricate each beam.

Prequalified Welded Joints

Basic Weld Symbols

Back	Fillet	Plug or Slot	Groove or Butt						
			Square	V	Bevel	U	J	Flare V	Flare Bevel

Supplementary Weld Symbols

Backing	Spacer	Weld All Around	Field Weld	Contour		For other basic and supplementary weld symbols, see AWS A2.4
				Flush	Convex	

Standard Location of Elements of a Welding Symbol



Note:
Size, weld symbol, length of weld, and spacing must read in that order, from left to right, along the reference line. Neither orientation of reference nor location of the arrow alters this rule.

The perpendicular leg of ◺, V, Y, ◸, weld symbols must be at left.

Arrow and other side welds are of the same size unless otherwise shown. Dimensions of fillet welds must be shown on both the arrow side and the other side symbol.

The point of the field weld symbol must point toward the tail.

Symbols apply between abrupt changes in direction of welding unless governed by the "all around" symbol or otherwise dimensioned.

These symbols do not explicitly provide for the case that frequently occurs in structural work, where duplicate material (such as stiffeners) occurs on the far side of a web or gusset plate. The fabricating industry has adopted this convention: that when the billing of the detail material discloses the existence of a member on the far side as well as on the near side, the welding shown for the near side shall be duplicated on the far side.

FIGURE 21-43 *Welding types of symbols.* (Courtesy American Institute of Steel Construction)



FIGURE 21-44 *Second-floor framing plan.* (Courtesy Scott Steel Inc.)

Industry Application

Versatility Is Good for the Career

As a drafting and design student at Jonesborough Technical Institute, Juanita Vargas had disagreed with what was known as the school's *versatility rule*. The rule reads as follows: "In order to graduate, a student must demonstrate entry-level job skills in at least two fields of drafting." The purpose of the rule is to make JTI's students versatile job seekers once they graduate.

Vargas liked mechanical drafting. She liked the precision of machined parts held to close tolerances. She wanted to make her living as a mechanical design and drafting technician; she had no interest in any other drafting field. However, a rule is a rule, so Vargas also learned structural drafting. She selected this field because structural steel drawings have, in her opinion, some of the characteristics of machine drawings.

Upon graduation Vargas secured a good job with a tool and die manufacturer in a city about 500 miles from her hometown. She liked her job, but was constantly homesick. After she had worked there for three years, her company diversified its holdings by purchasing a structural engineering firm with offices in four different cities, including Vargas's hometown. Soon the word went out that drafting technicians were needed at all four of the newly acquired engineering firms. Vargas and her fellow drafters were told they could transfer if they knew anything about structural drafting, particularly structural steel.

Vargas, who by now had become unbearably homesick, jumped at the chance. Saying a silent "thank you" to Jonesborough Technical Institute for its versatility rule, Vargas packed her bags and moved home. Not only did she get a job in her hometown, Vargas also got a promotion. Versatility is good for the career.



FIGURE 21-45 *Connection details.* (From Goetsch, *Structuring Drafting,* Delmar Publishers Inc.)



FIGURE 21-46 *Structural steel shop drawing.* (Courtesy Scott Steel Inc.)

Structural Concrete Drawings

Structural concrete products may be poured-on-site, precast, pre-stressed, or post-tensioned. Regardless of the approach, engineering and shop drawings are needed. In the case of concrete members that are poured on-site, shop drawings are known as *placing drawings*. Placing drawings show the placement of reinforcing bars in the on-site form. Shop drawings and placing drawings serve the same purpose. The difference is in where the work occurs, in a shop or on-site.

Engineering drawings are used to communicate what products are to be used, in what sizes and shapes, and how they are to be spaced, connected, and otherwise put together to form a structure. Engineering drawings for structural concrete consist of framing plans, sections (as needed), and connection details. ***Figure 21-47*** is an example of an engineering drawing for a small industrial building. The drawing contains a roof framing plan and sections. The sections also double as connection details. The roof is to be constructed of 4′-0″ wide cored flat slabs.

Shop and/or placement drawings are used to fabricate the individual structural members that are laid out on the engineering drawings. They are very detailed and must communicate every individual piece of material that is to be embedded in the concrete. Such drawings are typically accompanied by a bill of material.

Figure 21-48 (page 803) is a shop drawing for a solid flat slab member with one side beveled. It contains 17 pre-stressed steel strands that run lengthwise and are wrapped by reinforcing bars spaced lengthwise at 1′-0″ intervals (MK443). There are lifting hooks made of bent reinforcing bars (lha) for lifting the member out of the form, placing it on a truck for transportation to the construction site, and erecting it as part of the structure. Plates for welded connections (swpl) are placed along the edges at 7′-0″ intervals. There is a bill of material on the right side of the drawing.

Pre-Engineered Metal Buildings

A special subset of the field of structural steel design, drafting, and construction is the pre-engineered metal building. Pre-engineered metal buildings can be used for a variety of applications including warehouses, manufacturing facilities, churches, office facilities, schools, gymnasiums, airplane hangars, retail facilities, ministorage facilities, and numerous other uses.

The principal differences between the construction of a regular structural steel building and a pre-engineered metal building are as follows:

1. With a regular structural steel building, engineers begin with an architect's plan and develop a structural steel framework that will accommodate the building in question. With pre-engineered metal buildings, the engineering calculations for the various building products have already been done. Design personnel need only to select the appropriate materials in the proper sizes for the situation in question.
2. With regular structural steel buildings, the steel components are typically (although not always) larger and of a heavier grade. Pre-engineered metal buildings typically use smaller, lighter steel components for the building frame.
3. With regular steel buildings, there is often much cutting, fitting, and welding to do on-site during the course of constructing the building. With pre-engineered metal buildings various metal components are not just pre-engineered; they are pre-sized, prefabricated, and numbered.
4. Regular structural steel buildings typically require more equipment, more tools, and more expertise to erect than pre-engineered metal buildings. Regular structural steel buildings also usually take more time to erect than pre-engineered metal buildings.

Products Used in Pre-Engineered Metal Buildings

Pre-engineered metal buildings are constructed from a variety of standard metal products. The following components are commonly used in pre-engineered metal buildings:

Eave strut—A cold-formed C-section fabricated for the proper roof pitch. Eave struts ensure that the metal building is weather-tight at the eaves of the roof, ***Figure 21-49*** (page 804).

Purlin and girt—Cold-rolled Z-sections are the principal structural members attached to the building's frame (Figure 21-49). Girts are used in the walls of the building. Purlins are used in the roof. Roof and wall sheeting is attached to the girts and purlins.

Base angle and sheeting angle—Cold-rolled angles. Base angles are attached to the concrete floor of the building and provide a continuous base to which the bottom of the sheeting panels can be



FIGURE 21-47 *Engineering drawing.* (Courtesy Southern Pre-stressed Inc.)



PLT/JOB NO.	56/6203
PRODUCT	WP14FS
MARK NO.	84
NO. REQD.	1
CONC. TYPE	DT
YDS OF CONC.	8.55
WEIGHT	346
STRANDING	REINF
LENGTH	26'-10 1/2"
WIDTH	7'-11 1/8"
RELEASE	2500
U/M	SF

"EMBEDDED ITEMS"

ITEM	NO. REQD	ITEM	NO. REQD
swa1	1		
ss9	2		
waa	2		
swp1	8		
eic	2		
lha	8		
sp1	16		
S090600	2		
S052608	17		
MK443	29		
sba	2		

SHIPPED LOOSE ITEMS

ITEM	NO. REQD	ITEM	NO. REQD
caa	1		
cac	4		

TOP FINISH: STEEL TROWEL
DWN BY: GMK DATE: 11/04/91
CKD BY: GPS DATE: 1-2-92

"REVISIONS"

NO.	BY	DATE	CKD BY	REMARKS

FIGURE 21-48 *Shop drawing.* (Courtesy Southern Pre-stressed Inc.)



FIGURE 21-49 *Standard components.*



FIGURE 21-50 *Standard sheeting panel.*

attached (Figure 21-49). Sheeting angles are similar but are used for attaching the sheeting panels at the rake of the building.

Roof and wall sheeting panels—There are a number of different types of roof and wall sheeting panels available for use in constructing pre-engineered metal buildings. Some are used primarily for walls, some just for roofs, and some for both; others are architectural or decorative in nature. Some of the more commonly used shapes of sheeting panels are shown in ***Figures 21-50*** through ***Figure 21-53***.

Columns and beams—The rigid-frame system for a pre-engineered metal building consists of columns and beams, as it does with any structural steel building. The types of steel shapes used for columns and beams are the same as those shown earlier in this chapter. ***Figure 21-54*** is a cross section showing a widely used rigid-frame system for pre-engineered metal buildings.

Anchor Bolt Plan

An *anchor bolt plan* is a symbolic representation of the layout of the anchor bolts in the building's foundation/floor system. It is a plan-view drawing that shows where the anchor bolts are to be located in the floor system. The bases of the various columns used in the rigid-frame system for the building will be attached to the anchor bolts. Consequently, getting the locations of the anchor bolts correct is critical. ***Figure 21-55*** is an example of an anchor bolt plan for a pre-engineered metal building. ***Figure 21-56*** is a sectional view cut through the foundation/floor system to show the vertical placement of anchor bolts and to give various notes relating to the foundation and anchor bolts.

Rigid-Frame Cross Sections

The rigid frame for a pre-engineered metal building consists of the columns that are attached to the floor



PANEL PROFILE



PARTIAL CROSS SECTION

FIGURE 21-51 *Standard sheeting panel.*



PANEL PROFILE



CROSS SECTION

FIGURE 21-52 *Standard sheeting panel.*



FIGURE 21-53 *Standard sheeting panel.*



FIGURE 21-54 *Typical rigid-frame section.*

system by anchor bolts and the beams that are attached to the columns. A cross section through the building shows the configuration used for the building in question. *Figure 21-57* shows a typical rigid-frame cross section without dimensions. The dimensions are selected by drafting personnel from a chart such as the one shown in *Figure 21-58* based on the desired width and height of the building. These dimensions for various widths and heights of buildings using 20, 30, or 40 psf steel are an example of *pre-engineering*. Rigid-frame cross sections come in a variety of designs.

Roof Framing and Sheeting Plans

The roof framing plan shows the arrangement and spacing of the purlins that are attached to the roof beams. The sheeting plan shows the spacing and arrangement of the sheeting panels for the roof. *Figure 21-59* is an example of a roof framing plan for a pre-engineered metal building. *Figure 21-60* is an example of a roof sheeting plan for a metal building.

Sidewall and Endwall Framing and Sheeting Plans

Sidewall framing plans show the location of the girts, eave struts, and base angles to which the side sheeting panels will be attached. Side sheeting plans show the general arrangement of the side sheeting panels for the side of the building in question. Endwall framing and sheeting plans serve the same purpose and show the same information but for the ends of the building.

Drawing the Sidewall and Endwall Framing and Sheeting Plans

Figure 21-61 is an example of a sidewall framing plan. *Figure 21-62* is the corresponding sidewall sheeting plan. Very little detail is required in either of these plans. The sidewall framing plan uses single lines to show the spacing of the columns that make up the rigid frame for the building as they sit on the concrete slab. It also shows the location (vertically) of girts and eave struts. It is understood that base angles are located at the top edge of the concrete slab.

The sidewall sheeting plan requires even less detail. It simply shows the number of panels and their arrangement. Length and width dimensions of the individual panels are precalculated and do not need to be shown on the sheeting plan. Notice in Figure 21-62 that each panel has a *mark number*. Panels that are of the same width and height have the same mark number. In the case of Figure 21-62 all of the panels with mark number 2 are of one width and length. Those with mark number 1 have a different width



FIGURE 21-55 *Anchor bolt plan.*



FOUNDATION NOTES:

1. CONCRETE SHALL BE 3000 PSI IN 28 DAYS
2. CONCRETE SLAB, APRONS, AND DOOR STOOPS SHALL BE REINFORCED WITH 6x6 10/10 WWM.
3. 6 MIL POLY VAPOR BARRIER SHALL BE PLACED BETWEEN FLOOR SLAB AND COMPACTED SUB–GRADE.
4. ALL REINFORCEMENT BARS SHALL BE GRADE 60.
5. VERIFY ANCHOR BOLT SIZE AND LOCATIONS WITH BUILDING MANUFACTURER'S DRAWINGS PRIOR TO CONCRETE PLACEMENT.
6. ANCHOR BOLTS SHALL HAVE A 3" PROJECTION AND EXTEND TO LOWER 1/3 OF FOOTING DEPTH.
7. ANCHOR BOLTS STRENGTH SHALL BE A 36 GRADE.



3/4" ANCHOR BOLTS

NOTE: TOP OF FOOTING AT ANCHOR BOLT ① SHALL BE 8" BELOW FINISH FLOOR.

FIGURE 21-56 *Foundation section accompanying the anchor bolt plan.*



FIGURE 21-57 *Typical rigid-frame cross section.*

than those with mark number 2, but both panels numbered with a mark number 1 are of the same width and length. The framing plan tells erectors to begin on either end with a mark number 1 panel, attach 23 mark number 2 panels, and finish off at the other end with a mark number 1 panel.

The same rules and practices apply when developing the endwall framing and sheeting plans (*Figure 21-63* and *Figure 21-64*). Notice in Figure 21-64 that, beginning at either the left or right side of the plan, each sheeting panel gets successively longer in the height direction until reaching the two center panels (mark number 12). Each panel is clearly marked to guide the erectors in attaching it to the building frame.

Connection Details

The connection details required in a set of plans for a pre-engineered metal building can vary depending on the nature and characteristics of the building. However, regardless of the size of the building, the configuration of the rigid frame, and the types of sheeting panels selected, at least three connection details are always needed:

- Girt connection details
- Purlin connection details
- Eave strut connection details

TABLE OF ENGINEERING CALCULATIONS								
20 PSE LL					30 PSE LL			
WD	HT	B	C	E	WD	HT	B	C	E
20	10	8'–0"	8"	14"	20	10	8'–0"	8"	17"
20	12	10'–0"	8"	14"	20	12	10'–0"	8"	17"
20	14	12'–0"	8"	14"	20	14	12'–0"	8"	17"
20	16	14'–0"	8"	14"	20	16	14'–0"	8"	17"
20	20	18'–0"	8"	14"	20	20	18'–0"	8"	17"
30	10	8'–0"	8"	14"	30	10	8'–0"	8"	17"
30	12	10'–0"	8"	14"	30	12	10'–0"	8"	17"
30	14	12'–0"	8"	14"	30	14	12'–0"	8"	17"
30	16	14'–0"	8"	14"	30	16	14'–0"	8"	17"
30	20	18'–0"	8"	14"	30	20	18'–0"	8"	17"
40	12	10'–0"	9"	15"	40	12	10'–0"	9"	20"
40	14	12'–0"	9"	15"	40	14	12'–0"	9"	20"
40	16	14'–0"	9"	15"	40	16	14'–0"	9"	20"
40	20	18'–0"	9"	15"	40	20	18'–0"	9"	20"



FIGURE 21-58 *Dimensions are pre-engineered for different heights and widths.*



FIGURE 21-59 *Roof framing plan.*

Girt Connection Details

Girt connection details show how the girts are connected to the columns in the rigid frame. A typical girt-to-column connection involves bolting girt clips to the web of the column and bolting the girts to the girts clips (see ***Figure 21-65***). Girt connection details should show the connection, give bolt spacing dimensions, and specify the size of bolts to be used. Engineering and design personnel determine the size and spacing of bolts for the connections and provide this information to drafting personnel either through sketches or pre-engineered tables (although experienced drafting personnel will usually know since connections of pre-engineered metal buildings are typically standardized within companies).

Purlin Connection Details

Purlin connection details show how purlins are connected to the rafters in the rigid frame. A typical purlin-to-rafter connection involves bolting the purlin to the rafter, overlapping purlins, and bolting the overlapped purlins together (see ***Figure 21-66***). Purlin connection details should show the purlin connected to the rafter, the amount of overlap between purlins, and the bolt spacing. Engineering and design personnel determine the size and spacing of bolts and the amount of overlap required and provide this information to drafting personnel through either sketches or pre-engineered tables.

Eave Strut Connection Details

Eave strut connection details show how eave struts are connected to the rigid frame. This can be accomplished in various ways depending on the type of rigid



FIGURE 21-60 *Roof sheeting plan.*



FIGURE 21-61 *Sidewall framing plan.*

FIGURE 21-62 *Sidewall sheeting plan.*



FIGURE 21-63 *Endwall framing plan.*



FIGURE 21-64 *Endwall sheeting plan.*



FIGURE 21-65 *Typical grit connection detail (to column).*



FIGURE 21-66 *Typical purlin connection detail (to rafter) showing overlap.*



FIGURE 21-67 *Typical eave strut connection detail.*

frame used. An eave strut connection detail should show the eave strut connected to the column in the rigid frame or to an eave strut bracket that is connected to the column by a shop weld when the rigid frame is fabricated (see *Figure 21-67*). Engineering and design personnel determine how the actual connection will be made and convey this information to drafting personnel either through sketches or by using standardized details.

Architectural Drafting

Architectural drafting is the process of documenting the designs developed by architects. Architects are called on to plan and design a variety of different types of structures. However, most of an architect's work is typically focused on residential and commercial buildings including single-family houses, town houses, apartments, model communities, and a variety of different types of commercial buildings including office buildings, industrial plants, stores, banks, malls, hospitals, schools, libraries, and so on.

Architectural drafters prepare plans that convey and document an architect's design for any of these types of structures as well as other types. The best way to understand this field is to divide it into two broad categories as follows: residential architectural drafting and commercial architectural drafting.

Residential Plans

Residential design involves the development of the design for a residential structure (i.e., single-family dwelling, cottage, town house, apartments, etc.). The design process involves such considerations as how the structure will fit into its environment, space and room planning, aesthetics and function, material selection, code compliance, and many others.

A complete set of plans documenting an architect's design and showing how all of these considerations have been accommodated includes the following: plot plan; foundation plan; floor plan; elevations; heating, ventilation, and air conditioning (HVAC) plan; electrical plan; and framing plans (for roofs, floors, or both). The floor plan also doubles as the plumbing plan in modern construction. The contents of each component is described in the following paragraphs.

Plot Plan

A *plot plan* is a plan view of the building site showing where the structure is located on the lot. Surveyors provide the original material for plot plans. It should contain the following information: property lines showing the compass bearing and length of each; shape, location, and size of the building or buildings on the site; elevation of each corner of the site; north arrow; streets, sidewalks, driveways, patios; utilities and easements; wells, septic tanks, and drain fields (as applicable); scale of the drawing and a property description (i.e., lot and block number, street address, or legal description from a survey). Additional information that might be shown on the drawing but is not required includes the following: fences and retaining walls; trees, bushes, shrubs, rivers/streams, and other natural components; and contour lines. *Figure 21-68* is an example of a plot plan that contains the necessary information.

Foundation Plan

A *foundation plan* is a plan view in section that shows the understructure of the building. It should contain the following information: footings for piers, columns, and foundation walls; foundation walls; columns; piers; retention walls; partition walls, doors, and plumbing fixtures in houses with a basement; windows, vents, doors, and other openings in the foundation walls; beams; pilasters; floor joists (direction, spacing, and size); drains, sump, air-conditioning line; dimension; scale of the drawing; applicable notes; and footing/foundation sections and details. *Figure 21-69* is an example of a foundation plan that contains the necessary information.

Floor Plan

The floor plan is the most important component in a set of residential plans. It is the heart of the plans. A *floor plan* is a plan view of the structure in section with the ceiling and roof removed. It should contain



FIGURE 21-68 *Plot plan.* (Courtesy Barton Homes Inc.)

the following information: all necessary dimensions; exterior and interior walls; doors, windows, and other openings; built-in cabinets; appliances; plumbing fixtures; stairs; fireplaces; freestanding structures (i.e., garage); decks, patios, and porches; room labels; notes; door schedule; window schedule; area information (i.e., living area, porch area, garage, etc.); and scale of the drawing. ***Figure 21-70*** is an example of a floor plan that contains the necessary information.

Elevations

Elevations are orthographic views of the front, back, and sides of the structure. Most elevations are exterior views. However, interior elevations of the kitchen, bathrooms, and utility areas are frequently included in residential plans. Exterior elevations should contain the following information: grade lines, finished floor line, ceiling line, locations of corners of exterior walls, windows, doors, all roof features (i.e., gables, dormers, chimneys, etc.), vertical dimensions, porches, decks, patios, sun-rooms, applicable material symbols, and special details as required. ***Figure 21-71*** (page 815) is an example of elevations that contain the necessary information. Notice that the kitchen, bath, and utility area interior elevations are not contained on this sheet. As is often the case, they are drawn on another sheet that has more room (see Sheet 5, ***Figure 21-72***, page 816).

HVAC Plan

The *heating-ventilation/air-conditioning plan (HVAC)* shows the duct work for the house's heating and cooling system superimposed on the floor plan without dimensions. The location of interior and exterior heating/cooling units, size of duct work, direction of air flow, notes, details as needed, hot water heater, thermostat, registers, inlets, and vents should also be shown. Figure 21-72 is an example of an HVAC plan containing the necessary information. Notice that this sheet also contains interior elevations. This is a



FIGURE 21-69 *Foundation plan.* (Courtesy Barton Homes Inc.)



DOOR SCHEDULE

NUM	SIZE	RO	DESCRIPTION	SWING	QTY
01	3068	38"x82"	METAL ENTRY, INSULATED	LHIO	1
02	2868	34"x82"	METAL ENTRY, HALF LITE, INSULATED	RHIO	1
03	2868	34"x82"	METAL ENTRY, INSULATED	LHIO	1
04	2868	34"x82"	FLUSH BIRCH VENEER	LH	2
05	2868	34"x82"	FLUSH BIRCH VENEER	RH	2
06	2468	30"x72"	FLUSH BIRCH VENEER	LH	2
07					
08	2068	26"x82"	FLUSH BIRCH VENEER	LH	2
09	2068	26"x82"	FLUSH BIRCH VENEER	RH	2
10	2868	30"x82"	FLUSH BIRCH VENEER	LH	1
11	2868	30"x82"	FLUSH BIRCH VENEER	RH	1
12	6068	74"x82"	FLUSH BIRCH VENEER BIPASS	NA	1
13	6068	*	SLIDING GLASS DOOR	OX	1
14	6068	*	SLIDING GLASS DOOR	OXO	1
15	16070	198"x85"	OVERHEAD GARAGE DOOR	NA	1
16	3068	38"x81"	ALUM SCREEN DOOR	RHOS	1

WINDOW SCHEDULE

TAG	SIZE	RO	DESCRIPTION	QTY
A	2050	*	ALUM H/S W/ 1/2" S.G.C.	4
B	3050	*	ALUM H/S W/ 5/8" S.G.C.	1
C	6040	*	ALUM H/S W/ 1/2" S.G.C.	1
D	3040	*	ALUM H/S W/ 1/2" S.G.C.	1
E	5040	*	ALUM H/S W/ 1/2" S.G.C.	4
F	4040	*	ALUM H/S W/ 1/2" S.G.C.	1
G	1080	18 1/2"x82 1/2"	FIXED W/ 1/2" S.G.C.	1

* SEE MANUFACTURER'S SPECIFICATIONS FOR ROUGH OPENING DIMENSION

NOTES:

FRAMING:

1. PROVIDE DRAPERY BLOCKING ONE STUD SPACE EACH SIDE OF WINDOW OPENING
2. MEDICINE CABINET ROUGH-IN PER MANUFACTURER'S SPECIFICATIONS
3. VERIFY H.V.A.C. UNIT SIZE BEFORE FRAMING PLATFORM
4. SEE PLOT PLAN FOR SIDEWALK AND DRIVEWAY CONFIGURATION
6. SEE H.V.A.C. PLAN FOR FURR DOWN LOCATIONS

PLUMBING:

1. PROVIDE LEDGER BLOCKING FOR TUBS
2. ALL BATHS TO HAVE SANITARY SEWER CLEANOUTS WHERE POSSIBLE
3. PROVIDE PRESSURE TEST ON ALL SYSTEMS
4. REPLACE FRAMING REMOVED DURING STACKOUT
5. NOTE HOSE BIBBS-3 TOTAL
6. ROUTE STACKS OUT BACK WHERE FEASIBLE
7. PROVIDE 1/2" WATER SUPPLY UNDER SLAB FOR REF. ICEMAKER

A ACCESSORY & SHELF HEIGHT DETAIL
SCALE: 1/2" = 1'-0"

AREA:
LIVING 1609 SQ.FT.
GARAGE 446 SQ.FT.
SCREEN PORCH 171 SQ.FT.

CEDAR RIDGE – LOT 171

FLOOR PLAN

SCALE: 1/4" = 1'-0"

SHEET 3

DRAWN BY: T.C.S
DATE: 24 JULY 91
APPROVED:
REVISED:
CRITT-3

FIGURE 21-70 *Floor plan.* (Courtesy Barton Homes Inc.)



FIGURE 21-71 *Elevations.* (Courtesy Barton Homes Inc.)



FIGURE 21-72 *HVAC plan.* (Courtesy Barton Homes Inc.)

common practice to cut down on the number of sheets in the overall set of plans.

Electrical Plans

The *electrical plan* shows the house's electrical system superimposed on a floor plan without dimensions. It should contain the following information: service entrance capacity, meter and distribution panel, location and types of switches, location and types of lighting fixtures, number and types of electrical circuits, details as needed, notes, electrical symbol legend, and an indication of which fixtures are connected to which switches. ***Figure 21-73*** is an example of an electrical plan with the necessary information.

Roof Plan

The *roof plan* is a plan view showing the location and spacing of rafters and/or trusses. It should also contain a truss schedule, details as needed, and truss diagrams as needed. It is superimposed on the floor plan without dimensions. ***Figure 21-74*** is an example of a roof plan with the necessary information.

Commercial Plans

Commercial architectural plans differ somewhat from residential plans. The major difference is in who produces the various components of the plans. With residential plans all components can be produced by an architect, residential designer, and/or architectural drafter including the plot, electrical, and HVAC plans. This is not the case with commercial plans.

A complete set of commercial plans will usually contain architectural, civil engineering, structural (as needed), electrical, and mechanical (HVAC and plumbing) drawings. The architectural component of the plans (i.e., floor plans, elevations, sections, and details) is prepared by an architect or architectural drafter. The component relating to the site is prepared by a civil engineer, the structural component by a structural engineer, the electrical by an electrical engineer, and the mechanical by a mechanical engineer.

Architectural drafters and designers in a commercial setting prepare floor plans, elevations, sections, and details. The basic contents of these plans are similar to those in residential plans. ***Figure 21-75*** (page 820) is an example of a commercial floor plan. Notice that in addition to the plan view in sections of the building it contains several sectional details.

Each detail has a designator that, when translated, gives its numerical designation, the sheet on which it is cut, and the sheet on which it is drawn. For example, sectional detail "1-A2-A2" can be interpreted as follows:

1 = Detail number (1)
A2 = Sheet on which the detail is cut (A2)
A2 = Sheet on which the detail is drawn (A2)

This floor plan also contains a symbols legend, material legend, equipment legend, keynotes, a scale indicator, and title block information.

Figure 21-76 (page 821) is an example of commercial elevations. In addition to the elevations themselves, it contains two full sections cut through the building, and a roof plan. ***Figure 21-77*** (page 822) contains numerous other miscellaneous sections and details commonly found in a set of commercial plans plus their corresponding notes.

Civil Engineering Drafting

Civil engineering drafting is the field that deals with mapping, plot plans, earthwork, highways, roads, bridges, and profiles of the earth. Civil drafting technicians work in civil engineering companies, for surveyors, and in city, county, state, and federal government road and engineering departments. The fundamentals of civil engineering drafting include the following:

- Legal descriptions
- Plot plans
- Contour lines
- Rectangular systems

Other more advanced topics such as profiles, highway layouts, earthwork, and geographic information systems (GIS) will not be dealt with in this section.

Legal Descriptions

The two most widely used systems for describing property boundaries are the metes and bounds system and the lot and block system. The *metes and bounds* system uses selected known points of origin and then describes property boundaries in relation to this point-of-beginning or POB. The property in question is actually described using compass bearings and distances. *Lot and block* descriptions are used to describe parcels of land that are surveyed and platted on subdivision maps that are officially filed in the office of the clerk of the court (county level).

Plotting Legal Descriptions

All metes and bounds descriptions start at a permanent monument or some other fixed and observable point of beginning. Metes are property lines that are measured in established units (i.e., feet, inches, meters, yards,



FIGURE 21-73 *Electrical plan.* (Courtesy Barton Homes Inc.)



FIGURE 21-74 *Roof plan.* (Courtesy Barton Homes Inc.)



FIGURE 21-75 *Commercial floor plan.* (Courtesy Kendrick, David, and Dowling Architects Inc.)



BUILDING SECTION
SC: 1/8" = 1'-0"

BUILDING SECTION
SC: 1/8" = 1'-0"

KEYNOTES:
1. STANDING SEAM ROOF SYSTEM - SEE SPECIFICATIONS
2. 2" THK RIGID INSULATION (R 18 MIN.) WITH 1 1/2" NAIL BASE
3. STEEL DECKING - SEE STRUCTURAL
4. STEEL PURLINS - SEE STRUCTURAL
5. STEEL BEAM - SEE STRUCTURAL
6. SUSPENDED ACOUSTIC CEILING SYSTEM
7. CEMENT PLASTER CEILING SYSTEM
8. EXISTING STEEL ROOF STRUCTURE TO REMAIN
9. INDICATES WALL SYSTEMS THAT EXTEND FULL HEIGHT AND SEAL TO ROOF DECK STRUCTURE
10. 8" HIGH CAST ALUMINUM LETTERS - SEE SPECIFICATIONS
11. 3 SOLDIER COURSE OF BRICK - TYPE 2
12. BRICK VENEER - TYPE 1
13. NOT USED
14. METAL GABLE PANEL SYSTEM WITH INVERTED SEAM



ROOF PLAN
SC: 1/16" = 1'-0"

EAST BUILDING ELEVATION
SC: 1/8" = 1'-0"

SOUTH BUILDING ELEVATION
SC: 1/8" = 1'-0"



WEST BUILDING ELEVATION
SC: 1/8" = 1'-0"



NORTH BUILDING ELEVATION
SC: 1/8" = 1'-0"

KENDRICK DAVID DOWLING ARCHITECTS INC.
111 FERRY RD. SE. FT. WALTON BEACH, FL 32548
TEL (904) 243 9158 FAX (904) 664-2274

JM KENDRICK III, AIA
DON W. DAVID JR. AIA
JAMES DOWLING AIA
JAMES D. YEN
JOHN M. KENDRICK AIA
AR0011826 AR0011826

ELEVATIONS, ROOF PLAN & BUILDING SECTIONS

CLASSROOM BUILDING FOR PAXTON SCHOOL
PAXTON, FLORIDA

PROJECT NO 9115
DATE DEC. 23, 1991
DRAWN BY MD
CHECKED BY RK

A3

SHT 10 OF 18

FIGURE 21-76 *Commercial elevations.* (Courtesy Kendrick, David, and Dowling Architects Inc.)



KEYNOTES:

1. BRICK VENEER – SEE ELEVATION FOR COLOR/TYPE.
2. BRICK SOLDIER COURSES (3) – SEE ELEVATION FOR COLOR/TYPE.
3. RIGID INSULATION (R5 MINIMUM).
4. ASPHALTIC EMULSION AS DAMPPROOFING.
5. 8" CMU – SEE SCHEDULE FOR FINISH
6. MEMBRANE FLASHING
7. COTTON WICK SPACING NOT TO EXCEED 24" O.C
8. SEALANT
9. STEEL BRICK ANGLE – SEE STRUCTURAL – PAINT TO MATCH DOOR FRAME
10. HOLLOW METAL DOOR FRAME – SEE SCHEDULE GROUT SOLID AT ALL CMU
11. 3-5/8" GALV STEEL STUDS AT 16" O.C.
12. BATT INSULATION (R-11 MIN.)
13. 1/2" GYPSUM BOARD – SEE SCHEDULE FOR FINISH
14. (2) 3-5/8" GALV STEEL STUDS WITH GALV STUD TRACK BOTH SIDES SCREWED
15. DOOR – SEE SCHEDULE
16. THRESHOLD – SEE SCHEDULE – SET IN FULL MASTIC BED
17. SLOPE CONCRETE AWAY FROM DOOR (MAX. SLOPE 1" = 12")
18. CARPET – SEE SPECS
19. PVC – EDGE TRIM
20. SHEET VINYL – SEE SPECS
21. RUBBER BASE
22. SEE SCHEDULE FOR FLOOR FINISH
23. CONCRETE FLOOR SLAB – SEE STRUCTURAL
24. VAPOR BARRIER
25. 1/2" EXPANSION JOINT
26. GROUT SOLID ALL CELLS SOLID TO LEVEL OF FINISH FLOOR
27. CONCRETE WALKWAY – SEE CIVIL
28. 1/2" GYPSUM SHEATHING
29. SUSPENDED ACOUSTIC PANEL CEILING SYSTEM WITH EXPOSED GRID
30. STEEL CHANNEL – SEE STRUCTURAL
31. STEEL ANGLE – SEE STRUCTURAL
32. CONTINUOUS HOLD DOWN AND DRIP EDGE BY ROOFING MANUFACTURER
33. CONCRETE METAL ROOF CLIP WITH VENT SPACER
34. STEEL BEAM – SEE STRUCTURAL
35. METAL GABLE PANEL WITH INVERTED SEAM – BY STANDING SEAM ROOFING MANUFACTURER
36. STANDING SEAM METAL ROOF SYSTEM
37. EAVE TRANSITION @ ROOF/FASCIA
38. STEEL PURLIN – SEE STRUCTURAL
39. EAVE FLASHING PIECE BY STANDING SEAM MANUFACTURER
40. GALV. STEEL DECKING – SEE STRUCTURAL
41. 2-1/2" RIGID INSULATION (R18 MIN) WITH 1/2" PLYWOOD NAIL BASE (3" OVERALL THICKNESS)
42. 30# FELT
43. PRESSURE TREATED (2) 2x6 TRIM TO FIT
44. RIGDE PIECE BY STANDING SEAM MANUFACTURER
45. CONT. CLOSURE PIECE BY STANDING SEAM MANUFACTURER
46. 5/8" TYPE 'X' GYPSUM BOARD– SEE SCHEDULE FOR FINISH.
47. EXISTING STEEL ROOF STRUCTURE TO REMAIN.
48. NEW DOUBLE TIER LOCKERS – SEE SPECS
49. 6" GALV STEEL STUDS AT 16" O.C
50. WALL CORNER GUARDS – SEE SPECS
51. EXISTING STEEL PIPE COLUMN TO REMAIN
52. EXTEND WALL SYSTEM TO ROOF DECK/STUCTURE AND SEAL
53. ALUMINUM WINDOW UNIT WITH ALUMINUM RECIEVER/ SUBFRAME
54. ALUMINUM SILL PIECE
55. CONTINUOUS HOLD DOWN CLIP
56. PRESSURE TREATED 2x8 TRIM TO FIT, WITH 1/2" DIA ANCHOR BOLT COUNTER SINK AT 32" O.C MAX
57. 3/4" EXTERIOR GRADE PLYWOOD WITH PLASTIC LAMINATE ON ALL EXPOSED SURFACES

KENDRICK DAVID DOWLING ARCHITECTS, INC.
111 FERRY RD SE, FT. WALTON BEACH FL. 32548
TEL:(904) 243-9138 FAX:(904) 864-2374

JIM KENDRICK III, AIA AR0009303
DON W. DAVID JR., AIA AR0009305
JAMES R. DOWLING AIA AR0009385
JAMES A. FENDRICK,AIA AR0011826

SECTIONS & DETAILS

CLASSROOM BUILDING FOR PAXTON SCHOOL
PAXTON, FLORIDA

PROJECT NO: 9115
DATE: DEC. 23, 1991
DRAWN BY: MD
CHECKED BY: RK

A5

SHT 12 OF 18

FIGURE 21-77 *Commercial details and sections.* (Courtesy Kendrick, David, and Dowling Architects Inc.)



FIGURE 21-78 *Lots with metes and bounds descriptions.*



FIGURE 21-79 *Lot and block descriptions.*

rods, links, etc.). Bounds are property boundaries that are formed by the lines of adjacent properties, rivers, streams, roads, lakes, bays, etc. ***Figure 21-78*** contains three parcels of land with metes and bounds descriptions. The description for Parcel A reads as follows:

> A parcel of land in Okaloosa County, Florida, beginning at a permanent survey marker located at the intersection of the north right-of-way of Jones Street and the west right-of-way of Market Street. From this point, go N00°00′E 68′ to a metal stake. Then, turn to a heading of N82°01′30″W and go 53′-4″ to a metal stake. Then turn to a heading of S00°00′00″E and go 76′ to a metal stake located on the north right-of-way of Jones Street. Then turn to a heading of N89°30′45″E and go 53′ back to the point of beginning.

With the compass bearings and the distances known, a parcel of property can be drawn. Compass bearings are given in degrees, minutes, and seconds. The compass bearing N82°01′30″W is read as follows:

> From north, turn 82 degrees, one minute and 30 seconds toward the west.

Compass bearings used in metes and bounds descriptions will always begin with either north or south and turn toward either the west or the east. For example, the bearing N00°00′00″E is interpreted as follows:

> From north, turn zero degrees, zero minutes, and zero seconds toward the east. In other words, go due north. The compass bearing N00°00′00″W is also due north. When going due north or due south, the east and west components can be used interchangeably.

Lot and Block Descriptions

Property that is subdivided, platted, and filed in the official records of the office of the county clerk may be described using lot and block numbers. Subdivisions are typically divided into blocks and the blocks are, in turn, divided into lots, ***Figure 21-79***. This figure shows Block A of a subdivision known as Elmwood Estates. The actual metes and bounds description for the entire subdivision as well as a subdivision plat (property map) are on file in the official records of the county in question. Consequently, lots in the subdivision can be described using lot and block designations (i.e., Lot 3, Block A, Elmwood Estates Subdivision). Anyone who needs a more definitive description of a parcel in the subdivision can refer to the subdivision plat in the county's official records.

Plot Plans

A set of plans for a commercial building or a residential dwelling must contain a plot plan, ***Figure 21-80***. The plot plan locates the building and other key features on the piece of property in question. The requirements for what information must be contained on a plot plan vary from state to state and even from community to community. However, the following list contains the types of information that are typically required:

- Legal description of the property (using lot and block, metes and bounds, or rectangular system)
- North arrow and drawing scale
- Roads (existing, planned, and proposed)
- Driveways, walkways, parking areas, patios, and decks



FIGURE 21-80 *Residential plot plan.*



FIGURE 21-81 *Contour lines and slopes.*

- Current, planned, and proposed structures on the property
- Locations (as applicable) of wells, water lines, gas lines, power lines, sewer lines, septic tanks, drain fields, leach lines, soil test holes, rain drains, footing drains, and drive/walkway drains
- Elevations of property corners and at the street (measured at the center line of the driveway)
- Ground slope arrow
- Setback dimensions
- Easements

Contour Lines

Contour lines are used on topographical maps to connect points of elevation. To a person who can interpret their meaning, contour lines tell whether the land in question is flat or hilly, gently sloped or radically sloped, concave or convex.

In reading contour lines, a key characteristic to consider is *interval*. The greater the interval between contour lines, the more gradual the slope. A shorter interval indicates a steeper slope, ***Figure 21-81***. Streams and ridges are special topographical features that can also be represented using contour lines. ***Figure 21-82*** shows how contour lines appear at a stream. Notice



FIGURE 21-82 *Contour lines and streams.*

that they form a V that points upstream. ***Figure 21-83*** shows how a ridge can be indicated by contour lines.

There are three different types of contour lines as shown in ***Figure 21-84***. Index contour lines are thicker than the others and are spaced at intervals of five so that every fifth line is an index line. The index line is broken periodically and labeled with the elevation.

Intermediate contour lines are thin, unbroken lines between the interval contour lines. Supplementary contour lines are dashed and typically represent half of the distance between contour lines. Regardless of



FIGURE 21-83 *Contour lines and ridges.*



FIGURE 21-84 *Types of contour lines.*

the relative slope of the land, every fifth contour line is an index contour. Consequently, the contour interval value (i.e., 2, 5, 10 . . . feet) can vary.

Rectangular System

The U.S. Bureau of Land Management developed a method of describing land called the *rectangular system*. The system is used in the following states:

- Alabama
- Alaska
- Arizona
- Arkansas
- California
- Colorado
- Florida
- Idaho
- Illinois
- Indiana
- Iowa
- Kansas
- Louisiana
- Michigan
- Minnesota
- Mississippi
- Missouri
- Montana
- Nebraska
- Nevada
- New Mexico
- North Dakota
- Ohio
- Oklahoma
- Oregon
- South Dakota
- Utah
- Washington
- Wisconsin
- Wyoming

Land in these states is divided into a grid of blocks called townships, ***Figure 21-85***. Each major segment of land has both a township and a range number. For example, a designation might be T24NR36E. This designation reads as follows: Township 24 North, Range 36 East. Township designations come from the vertical columns that run north and south in this figure. The designations east and west relate to the line marked as the principal meridian. The designations north and south relate to the line marked as the baseline.

Subdividing Townships

A full-sized township is a tract of land six miles square. Exceptions to this rule are created by geographical features such as shorelines, natural borders, rivers, and large bodies of water. For example, many of the townships in Florida are irregularly shaped and less than full size. Regardless of their actual shape and size, townships are divided into sections as shown in Figure 21-85.

Subdividing Sections

Sections can be subdivided into an almost unlimited number of smaller units. For example, the section shown in ***Figure 21-86*** contains several smaller subunits. Ten of these parcels have been numbered.



FIGURE 21-85 *Rectangular system.*



FIGURE 21-86 *Rectangular legal descriptions.*

Using the rectangular system, the *legal descriptions* of these numbered parcels are as follows:

1. The SE ¼ of Section 26T25R2E (Reads as follows: the southeast one-quarter of Section 26 in Township 25, Range 2 East).
2. The eastern ½ of the NE 1.4 of Section 26T25R2E.
3. The western ½ of the NE 1.4 of Section 26T25R2E.
4. The northern ½ of the NW 1.4 of Section 26T25R2E.
5. The southern ½ of the NW 1.4 of Section 26T25R2E.
6. The southeast ¼ of the SW 1.4 of Section 26T25R2E.
7. The southeast ¼ of the NE 1.4 of the SW 1.4 of Section 26T25R2E.
8. The northwest ¼ of the NE 1.4 of the SW 1.4 of Section 26T25R2E.
9. The southern ½ of the NW 1.4 of the SW 1.4 of Section 26T25R2E.
10. The eastern ½ of the SW 1.4 of the SW 1.4 of Section 26T25R2E.

The key to reading this type of legal description is to begin at the end and read backwards. This will simplify the process by beginning with the large and working toward the small. For example, look at number 7 in this list of legal descriptions. Reading backwards the component parts are as follows:

- Section 26T25R2E
- SW ¼ of the section
- NE ¼ of that parcel
- SE ¼ of that parcel

Geographic Information System

A *geographic information system (GIS)* is a computer system that collects, stores, retrieves, analyzes, and displays spatial and attribute data relating to features on, under, and above the ground. Spatial data in this sense are data that describe the location of features on and under the ground. These features are represented by points, lines, or polygons that have their own unique location in the world. For example, consider a parcel of land in a typical community and all of the various types of interrelated data that may be collected concerning the parcel (***Figure 21-87***). The types of data shown in this figure are just a few examples of the types that can be collected and used with a GIS.

Attribute data can be any type of data about a feature other than its location in the world. For example, if the feature is a building, attribute data may include the following:

- Square footage
- Number of floors
- Principal building material (steel, concrete, wood frame)
- Any other data that describe or define the building beyond its location

FIGURE 21-87 *Types of data that might be collected and stored in a GIS database.*

What makes GIS software special is its ability to examine spatial relations and answer what-if questions. For example, the following types of questions may concern city or county engineers and planners in a given community:

- What if we rezone an area to allow for additional construction?
- Will there be any negative effects on the water table?
- Can the area accommodate the new infrastructure that would be needed (e.g., roads, utilities, and drainage)?
- How will the additional solid and liquid waste treatment requirements affect the area?
- What if drilling for oil is permitted in a given area?
- How will the local river be affected?
- What impact will drilling have on the nearby children's park?
- Will underground utilities have to be rerouted?

A GIS map file can represent the entire world or any part of it to desired level of detail. The part of the world put in the system can have many different types of attributes (e.g., political boundaries, population density, zip codes, census designations, streets, and bridges). A GIS map file can be created for any type of data that have geographic linkages.

Everything that is under, on, or above the land is interrelated, ***Figure 21-88.*** Any action that affects one feature in a spatial system can affect other features. A major benefit of a GIS is that it can help prevent decisions that create spatial conflicts that can have adverse and unintended consequences.

One of the difficulties with making land-use decisions is that they cannot be made in a vacuum. One seemingly isolated and well-intended activity such as constructing a culvert system to prevent flooding may unwittingly cause an even worse problem than flooding. For example, it may cut through underground utility, water, and/or sewer lines that engineers forgot were there or it may transfer toxic runoff into the community's principal water source. A GIS allows planners to consider the potential domino effects one action can have on all features within a spatial system (Figure 21-88).

Key Gis Concepts

The first concept to understand about GIS is the *georelational data model.* This model serves as the tie between *spatial data* and *attribute data.* Any attribute data that can be linked to geographic locations is linked by the georelational data model. For example, a GIS map may show the geographic locations of the largest electricity or water users in the community.



FIGURE 21-88 *Related features in a selected location.*

Spatial data are stored as points, lines, and polygons that occupy a specific location in space. In this way, planners are able to relate various features to each other as well as attributes relating to those features. For example, the county's records for solid waste disposal can be linked by the GIS with the locations of residential, commercial, and/or government buildings in the county.

Attribute data can be almost any kind of information relating to what is under, on, and/or above the ground in any specified location or anything that is inside a given component. For example, say the feature in question is a tree. What kind of tree is it? How tall is it? When was it last harvested? How old is it? The answers to these questions are attribute data. A GIS uses a type of software called *relational database management systems (RDBMS)* to relate data stored in the database. The relationship between and among files is based on a common element contained in the files. The computer will key on this common element when retrieving data in response to *what-if scenarios* posed by planners, engineers, and technicians.

A final but fundamental GIS concept is *topology*. This concept is a mathematic system that defines relationships among geometric objects/shapes (such as polygons that represent parcels of land, buildings, or other features). These relationships include adjacency, connectivity, contiguity, and proximity. Are several parcels (building, features, etc.) adjacent? Are they connected? Are they contiguous? Humans can see these spatial relationships, but computers are blind in the human sense. Consequently, they must determine spatial relationships mathematically. Topology gives computers this capability. ***Figure 21-89*** is an example of a GIS database that was developed for specific applications. The database in Figure 21-89 was developed to assist in the launch of missiles into space. The desired capabilities on the left are supported by the data on the right.

How a GIS Is Used

The best way to understand a GIS is to consider an actual example of how one is used. ***Figure 21-90*** contains a map of a college campus. A GIS could be used by the college's Facilities Management Office for maintaining the master plan for maintenance, renovation, remodeling, and numerous other functions.

The map shows the location on the campus of all facilities, including buildings, roads, parking lots, and athletic facilities. The legend shows the letter designation for each building, which, in turn, has a descriptive name based on its function (e.g., Administration, Gymnasium/Wellness Center, and Arts Center). All pertinent locational data relating to buildings and facilities are stored in the GIS database.

In addition to the locational data, there are also attribute data for all pertinent features below and on the ground. For example, consider Building E, the Learning Resources Center, from the campus map in Figure 21-90. Attribute data for this building may include the following:

- *Floor plans for each level*
  - Maintenance data for all rooms on all floors
  - Past, present, and planned renovation data for all rooms
  - Contents of each room (chairs, tables, computers, audiovisual equipment, etc.)
- *Air conditioning and heating plan for the building*
  - Maintenance schedules
  - Equipment specifications
- *Electrical plan for the building*
  - Maintenance schedules

SPACE LAUNCH FACILITIES APPLICATION

Desired Capability	Relevant Data Stored
■ Telemetry Data Display	■ Tracking station locations, 3-D spatial relationships
■ Range Tracking	■ Moving location, dynamic zones of impact probability
■ Command Destruct Criteria	■ Graded overall constraints zones
■ Down Range Depiction	■ Visualization of safety constraints, real-time tracking
■ Safety Buffer Zone Analysis (in Real Time)	■ Dynamic quantity/distance explosive zones
■ Large Vehicle Routing	■ Alternative route selections, automated evacuation
■ Security Planning	■ Security zones, SCIP locations, alarmed areas

FIGURE 21-89 *GIS database for a space launch facilities application.*

FIGURE 21-90 *GIS map for a college campus.*

- Specifications for electrical equipment, lines, and fixtures
- *Data and voice lines plan for the building*
  - Maintenance schedules
  - Specifications for the system and all components
- *Fire alarm plan for the building*
  - Maintenance schedules
  - Specifications for the system and all components
- *Sprinkler (fire suppression)*
  - Maintenance schedule
  - Specifications for the system

The same information could be stored about all of the buildings on campus. Similar information could be stored about all features on the campus. Having this information readily available—along with all of the locational data—gives the college's facilities management personnel powerful capabilities.

GIS Capabilities: Spatial Analysis

Every GIS has certain standard capabilities. This section explains traits of those standard capabilities that fall under the heading of *spatial analysis*. *Spatial queries* allow users to pose what-if scenarios concerning features on the map. The GIS bases its responses to spatial queries on points, lines, and polygons. *Point-in-polygon responses* locate specific points that lie within specific polygons. For example, say a company needed to show the local fire department the location of all fire extinguishers in a given building. The polygon would be the building, and each fire

extinguisher would show up as a point superimposed on the building's floor plan as displayed on a computer terminal screen or printed in hard form.

Polygon overlay involves the generation of a new polygon by overlaying two or more polygons. For example, say company personnel want to make sure that the installation of fiber optic cables will not interfere with the existing electrical system. The GIS could overlay the existing electrical system (one polygon) over the floor plan of the building in question (a second polygon). It could then overlay the proposed fiber optic system plan over the first two. The newly created polygon when displayed would point out visually any potential wiring conflicts.

Buffering generates new polygons around a set of points, lines, or other polygons. Nearest neighbor is a GIS capability that identifies the closest features to another feature. This capability is especially valuable in keeping track of features as they relate to other features. For example, say the college in Figure 21-90 wants to add a new business and industry training center in the area between its west entrance and its main entrance. What features are the nearest neighbors on the ground and underground? If one of the nearest neighbors turns out to be a large tract of environmentally sensitive wetlands in this area, the college may decide to put the new training center elsewhere.

Network analysis is a GIS capability that allows users to perform flow analysis, routing determinations, and/or orders stops. The college in Figure 21-90 may use this capability to analyze traffic flow patterns, student routing patterns between classes, or storm drainage flow analysis.

GIS APPLICATIONS CHECKLIST FOR A COMPANY

- Comprehensive/Master Planning
- Facilities Management
- Facilities Siting
- Utilities Planning
- Water Resource Projects
- Natural Resources Management
- Wetlands Inventory
- Environmental Restoration/Compliance
- Hazardous Material/Waste Management
- Environmental Health Risk Assessment
- Historical/Archaeological Site Protection
- Fire and Emergency Vehicle Dispatch
- Maintenance Team Dispatch
- Security Response and Planning
- Space Utilization
- Pavement Management
- Floodplain Management
- Terrain Analysis
- Communication Network Planning
- Logistics Planning

FIGURE 21-91 *Uses of a GIS at a company.*

GIS Capabilities: Attribute Queries

Attribute queries pull information about the attributes of features that are shared in the database. How they are organized and displayed depends on the nature of the specific inquiry in question.

Extracting is a GIS capability that selects a subset of data from a broader set. For example, say the college in Figure 21-90 wants to know how many classrooms it has that have wall-mounted videotape players. This would be the subset. The broad set of data includes all classrooms.

Generalizing is a capability that combines polygon features based on common or similar attributes. For example, the college in Figure 21-90 may want to see a list of all rooms on campus that have been recarpeted within the last six months. A floor plan could be displayed with the subject rooms highlighted.

GIS and CAD

The wedding of GIS and CAD makes for a perfect marriage. GIS is, at its heart, a database system. As such, a GIS is best at storing, analyzing, and displaying data. CAD, on the other hand, is graphics based. It displays pictures. Put these two concepts together, and users get the best of two worlds—conveniently organized data that are augmented visually by drawings. For example, the campus map in Figure 21-90 is a product of the marriage of CAD and GIS. The ability to display data in a graphic format simplifies matters when it comes to the user interface. Even nontechnical users can understand a picture. *Figure 21-91* shows typical uses of GIS for a given company.

Summary

- The most widely used types of pipe are steel, cast iron, brass, copper, copper tubing, and plastic.
- The three broad classifications of fittings are screwed, flanged, and welded.
- Fluids and gases flowing through pipe are regulated or stopped at certain points by valves. The most widely used types of valves are gate, globe, jet, swiveled joint, ball, check, and butterfly.
- Pipe drawings serve the same purpose as other types of technical drawings. They convey the intentions of the designer and engineer to the tradespeople who will construct the pipe system. There are two types of pipe drawings: single-line and double-line.
- A structure is anything constructed of parts such as commercial buildings, bridges, towers, parking decks, and stadiums.
- Documentation prepared by structural drafters consists primarily of engineering drawings and shop drawings. Engineering drawings convey structural design information. Shop drawings convey all of the information needed to manufacture the individual parts of the structure and are sometimes called detail drawings. Pre-engineered metal buildings require plans that include anchor bolt plans, rigid-frame cross-sections, and framing and sheeting plans.
- Architectural drafting is the process of documenting the design developed by an architect. Residential plans include: a plot plan; foundation plan; floor plan; elevations; heating, ventilation, and air conditioning (HVAC) plan; electrical plan; and framing plans.
- Plans for commercial buildings contain architectural, civil engineering, electrical, and mechanical components. The architectural component includes floor plans, elevations, sections, and details.
- The basics of civil engineering drafting include legal descriptions (metes and bounds, lot and block), plot plans, contour lines, and the rectangular system.
- GIS systems collect, store, retrieve, analyze, and display spatial and attribute data relating to features on, under, and above the ground.

Review Questions

Answer the following questions either true or false.

1. It is important for engineering and drafting students to be proficient in pipe drawing.
2. A correction is required to do an engineering or architectural change.
3. A revision is usually done when a mistake or drafting error must be fixed.
4. Bolting and welding are the two most widely used methods for connecting structural members.
5. Engineering drawings convey structural design information.
6. Shop drawings convey all information needed to manufacture the individual parts of a structure and are sometimes referred to as detail drawings.
7. All metes and bounds descriptions start at a permanent monument or some other fixed point of beginning.
8. Prefabricated metal buildings cannot be used for anything but warehouses.
9. GIS is just another application of CAD.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** one of the most widely used types of pipe?
   a. steel
   b. aluminum
   c. copper
   d. brass
2. Which of the following is **not** one of the three broad classifications of pipe?
   a. standard
   b. extra strong
   c. double extra strong
   d. triple extra strong
3. Which of the following is **not** one of the three most widely used categories of valves?
   a. swivel
   b. gate
   c. check
   d. globe
4. Which of the following is **not** among the typical components in a set of residential architectural drawings?
   a. plot plan
   b. foundation plan
   c. elevations
   d. civil engineering plans
5. Which of the following is **not** among the typical components in a set of commercial architectural drawings?
   a. civil engineering plans
   b. mechanical drawings

c. electrical drawings
d. baseline drawings

6. Property that is subdivided, plotted, and filed in the official records may be described using the following method:
   a. metes and bounds
   b. rectangular
   c. lot and block
   d. contour
7. Which of the following is part of a typical set of plans for a pre-engineered metal building?
   a. metes and bounds plan
   b. orthographic plan
   c. rigid-frame cross section
   d. lot and block plan
8. Select all of the following that are common application of GIS.
   a. fire alarm system in a building
   b. electrical plan for a building
   c. identifying spatial conflicts
   d. extracting subset data

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

Chapter 21 Problems

PROBLEM 21-1

Problem 21-1 is a single-line isometric pipe drawing. Convert this drawing into a single-line orthographic drawing showing the following views of the system: top, front, right side, and left side.



SANITARY SEWER RISER DIAGRAM
NTS

PROBLEM 21-2

Problem 21-2 is a double-line orthographic pipe drawing. Convert it into a single-line orthographic drawing.



CHEMICAL POT FEEDER DETAIL
N.T.S.

PROBLEM 21-3

Problem 21-3 is a double-line orthographic pipe drawing. Convert it into a single-line orthographic drawing.



WET PIPE SPRINKLER SERVICE
NTS

PROBLEM 21-4

Problem 21-4 is a double-line orthographic pipe drawing. Convert it into a single-line orthographic drawing.



CHEMICAL POT FEEDER
N.T.S.

PROBLEM 21-5

Problem 21-5 is a double-line representation of a piping system. Reconstruct the drawing as shown in single-line representation.



PROBLEM 21-6

Problem 21-6 is an engineering drawing for a set of bleachers. Reconstruct the entire drawing making the following changes: (a) add 21′–6″ to the *Out-to-Out* dimension and adjust all others accordingly; and (b) add one more row of bleachers at the bottom.



PROBLEM 21-7

Problem 21-7 is an engineering drawing for a pedestrian bridge. Reconstruct the entire drawing making the following change: add one more 33′–2″ bay to the bridge and adjust all dimensions accordingly.



PROBLEM 21-8

Problem 21-8 is a shop drawing for a pre-stressed concrete beam. Reconstruct the entire drawing making the following change: change the depth of the beam to 1′–6″ and adjust accordingly.



PROBLEM 21-9

Problem 21-9 is a shop drawing for a precast concrete flat slab. Reconstruct the entire drawing making the following change: decrease the width by 1′–1″ and the length by 9″ and adjust accordingly.



PROBLEM 21-10

Figure 21-71 is a floor plan for a residential dwelling. Subtract 11″ from the overall length and width of this figure. Now make all necessary adjustments to the floor plan.

PROBLEM 21-11

Using the floor plan developed in the previous problem as the nucleus, develop a complete set of residential plans.

PROBLEM 21-12

Figures 21-75, 21-76, and 21-77 contain the basic architectural plans for a classroom building. Add one additional classroom (106) and revise the entire set of plans accordingly.

PROBLEM 21-13

Draw the following parcel at a scale of 1″ = 30′. Beginning at a permanent concrete marker that is the southeast corner of the parcel described herein, turn N7°00′ 00″W and travel 117.01′. Then turn N82°30′30″W and travel 107.02′; then turn S52°00′15″N and travel 131.03 feet. Then turn due east to the point of beginning (a distance of 126′).

PROBLEM 21-14

Figure 21-78 shows three parcels described using the metes and bounds method. Write a legal description for Parcel B.

PROBLEM 21-15

Redraw the three parcels and roads as shown in Figure 21-78, adding a fourth parcel (Parcel D) to the west of Parcel C. Select an appropriate scale. The parcel should be 53′ wide along Jones Street.

PROBLEM 21-16

- At a scale of 1″ = 300′, draw a complete section as shown in Figure 21-86. Divide it into quarter sections. Refer to Figure 21-85 for dimensions. Plot the following parcels on your section map.
- The north half of the SE ¼ of the section.
- The SE ¼ of the NW ¼ of the section.
- The SW ¼ of the NE ¼ of the SW ¼ of the section.
- The southern 1.2 of the SE ¼ of the NE ¼ of the SW 1.4 of the section.

PROBLEM 21-17

Using Figures 21-68 through 21-86 as a guide, develop a set of plans for a pre-engineered metal building that will be built on a concrete slab that is 40′ wide and 60′ long.

22

The Design Process

CHAPTER OUTLINE

Time • Learning the design process • The design process: phases and steps • Design projects: routine and non-routine • Modern design practices and standards • Summary • Review questions • Chapter 22 problems

CHAPTER OBJECTIVES

Upon completion of this chapter, students should be able to do the following:

- Follow the phases and steps in the design process to do a routine design project as an individual effort.
- Follow the phases and steps in the design process to do a non-routine design project as a member of a team.
- Use various techniques such as the creative process, attribute listing, a decision table, and model building (actual and computer-generated) to enhance the steps in the design process.
- Use various information sources such as vendor catalogs, technical texts, technical periodicals, and technical handbooks to augment the steps in the design process.
- Identify the various types of technical drawings you would use in the design process such as freehand sketches, design development layout drawings, kinematic layout drawings, and detail and assembly drawings.
- Discuss the objectives of DFM, DFA, DFR, and DFD.

(continued)

KEY TERMS

Abstract
Alternatives
Analysis
Attribute listing
Constraints
Costs
Creative process
Decision table
Design file
Design hints
Design process
External clients
Human factors
Internal clients
Iterate
Layout development drawings
Letter of transmittal
Log
Non-routine designs
Oral presentation
Parametric design
Phases (in the design process)
Planning chart
Progress report
Prototypes
Rapid prototyping
Reverse engineering
Routine designs
Safe designs
Solution description
Specifications
Steps (in the design process)
Testbed
Vendor catalogs
Virtual prototyping

(CHAPTER OBJECTIVES continued)

- Recognize current trends in manufacturing such as TQM, ISO 9000, parametric design, and rapid prototyping.
- Identify the roles of drafters, designers, and engineers in the steps of the design process.

The *design process* is a plan of action for reaching a goal. The plan, sometimes labeled problem-solving strategy, is used by engineers, designers, drafters, scientists, technologists, and a multitude of professionals. This strategy, the design process, occurs in five *phases* during a product design, and each phase has a number of *steps*. The following phases occur sequentially with some overlapping, as shown in *Figure 22-1*.

Phase I	Recognize and Define the Problem
Phase II	Generate Alternative Solutions: SYNTHESIS
Phase III	Evaluate Alternative Solution Ideas: ANALYSIS
Phase IV	Document, Specify, and Communicate the Solution
Phase V	Develop, Manufacture, and Deliver

The steps, not shown in Figure 22-1, may occur sequentially; however, each phase has a different number of steps depending on the complexity of the problem to be solved and the time available.

Time

The available time, whether hours, days, months, or years, controls the starting and stopping of the phases during the design process. Therefore, successful problem solving requires careful planning. And since the phases must occur within the time span, they must be scheduled as needed to reach the required goal.



FIGURE 22-1 *The phases in the design process.*

Learning the Design Process

Learn the design process by doing it! That is, follow the phases and steps, as a guide, to do at least two design projects. First, individually, do a routine design project. Next, in a group, do a non-routine design project. Use these design experiences to augment and expand your design skills, and to acquire an understanding that the design process can be modified to suit the level and complexity of the problem to be solved. This chapter provides the following to get you started:

1. An outline and discussion of the phases and steps in the design process, *Figure 22-2*
2. A discussion of routine design projects (the type usually assigned to a neophyte drafter, designer, or engineer as their first task in a company)
3. A discussion of non-routine design projects (the type assigned to more experienced drafters, designers, and engineers as they assume more responsibility in their respective jobs)
4. A collection of design hints to enhance your problem-solving skills and design solutions
5. Examples from a non-routine design project (done by a student group)

Follow the phases and steps in Figure 22-2, generally in the sequence shown. Use the steps as a checklist. Samples from the student group's non-routine design project (#5 above) are included in the following discussion when appropriate.

The Design Process: Phases and Steps

Phase I Recognize and Define the Problem

STEP 1 Establish Plans for the Phases, Steps, and Records

STEP 2 Gather Information
- a. Primary Sources
- b. Secondary Sources

STEP 3 Combine Information into a Preliminary Definition
- a. Constraints
- b. Specifications
- c. Preliminary Solution Ideas
- d. Iterate

STEP 4 Prepare a Progress Report
- a. Internal Clients
- b. External Clients

DESIGN PROCESS: PHASES AND STEPS

PHASE I
RECOGNIZE AND DEFINE THE PROBLEM

STEP 1 Establish Plans for the Phases, Steps, and Records

STEP 2 Gather Information
a. Primary Sources
b. Secondary Sources

STEP 3 Combine Information into a Preliminary Definition
a. Constraints
b. Specifications
c. Preliminary Solution Ideas
d. Iterate

STEP 4 Prepare a Progress Report
a. Internal Clients
b. External Clients

PHASE II
GENERATE ALTERNATIVE SOLUTIONS: SYNTHESIS

STEP 5 Generate Solution Ideas
a. Use Systematic Techniques
b. Use Creative Techniques and Attitudes

PHASE III
EVALUATE ALTERNATIVE SOLUTION IDEAS: ANALYSIS

STEP 6 Sift, Combine, and Prepare Solution Ideas for Analysis
a. Preliminary Preparation
b. Specific Preparation

STEP 7 Compare Solution Alternatives to Constraints and Specifications
a. Iterate
b. Persevere
c. Qualitative Evaluation
d. Quantitative Evaluation

STEP 8 Conduct a Design Review
a. In-House Design Reviews
b. Outside Design Reviews

STEP 9 Refine the Final Solution

PHASE IV
DOCUMENT, SPECIFY, AND COMMUNICATE THE SOLUTION

STEP 10 Prepare Drawings and a Written Report

STEP 11 Give an Oral Presentation

PHASE V
DEVELOP, MANUFACTURE, AND DELIVER

STEP 12 Prepare Technical Detail Drawings of Each Component to Be Manufactured

STEP 13 Schedule Assembly, Final Testing, Packaging, and Delivery

STEP 14 Keep Records

FIGURE 22-2 *Phases and steps in the design process.*

Step 1 Establish Plans for the Phases, Steps, and Records. Make a *planning chart,* which is an excellent visual display of when phases and steps are scheduled to begin and end, *Figure 22-3.* Note that over each bar is the name of the individual responsible for that activity, whether the individual does all of the work or not. Refer to Figure 22-21 for the completed chart.

Start and keep a *log* of activities and the time spent. Each individual in the group should keep a log. Newspaper-style entries, who—what—where—when—why, are useful because they tell specifically what was done. Supervisors use the information for checking progress and for accounting purposes. But more importantly, the phone numbers, names, dates, and facts may be useful on future projects. Instructors use the log information for checking progress and for grading purposes. See *Figure 22-4* for a sample log from a student's notebook. Refer to Figure 22-20 for a more complete log.

Some companies may require selected individuals to keep a more detailed log-design notebook for legal purposes or for patent development. For patent development, each page is bound, numbered, and then arranged to be signed by a knowledgeable witness.

Start a design file with every page dated to agree with the log, and file the pages chronologically for easy reference. Each individual keeps a *design file,* which includes freehand sketches, machine copies of technical information, copies of related drawings, summaries of telephone conversations and interviews, and vendor brochures. Samples from a student's design file are in *Figures 22-5A* and *22-5B.* A group log and file may be required by a supervisor in industry.

Step 2 Gather Information.

a. *Primary Sources.* Contact the source of the problem, who will provide information to establish most of the project's constraints and specifications, verbally or in writing. Later, in Step 4, confirm any verbal decisions made by the source, in a progress report.

Next, review similar products and experiences for information because most designs are actually new combinations of existing ideas.

b. *Secondary Sources.* Investigate secondary sources, which include a variety of people and references.

The following checklist can be expanded to fit the needs of specific problems.

People: shop personnel (machine, structural, electronic, electrical, packaging, shipping, welding . . .)

Practicing professionals: (engineers, lawyers, doctors, technologists, scientists . . .)

PLANNING CHART									
TEMPOROMANDIBULAR JOINT FLEXOR									
K. Anderson	M. Bui		A. Hamamoto			W. Peterson			
ACTIVITY	WEEK								
	1	2	3	4	5	6	7	8	9
PHASE I		MB							
Get Organized	KA								
Client/Meeting		AH							
Information Search		WP							
Project Define		WP				◉ MILESTONE			
Progress Report			MB ◉						

FIGURE 22-3 *Planning chart for student group.*

TIME LOG	W. PETERSON		
TEMPOROMANDIBULAR JOINT FLEXOR			
DATE	ACTIVITY	TIME HR	CUM. TIME HR
10-2	Met with Anderson, Bui, Hamamoto- - Exchanged phone numbers - Copied Dr. P's proposal	½	½
10-8	MET - KA MB & AH - discussed proposal - made up questions for Dr. P Discussed planning chart	2 ¾	3 ¼

FIGURE 22-4 *Log.*

PRELIMINARY DESIGN CONSIDERATIONS

1. SIZE — Date 10-10
2. POWER
   –BELT POWER PACK
   –CHARGER
3. CONTROLS
   –FREQUENCY
   –OPENING
   –PATIENT OR DR.?
4. EXPECTED PRODUCTION
   –REUSABLE?
5. COST
6. MATERIALS
   –STAINLESS
   –PLASTIC
   –FDA RESTRICTIONS
7. NOISE LEVEL
8. FORCES REQUIRED
   –OPENING
   –CLOSING
9. SAFETY OVERDRIVE
10. JAW DIMENSIONS
11. ACCURACY

FIGURE 22-5A *File: Preliminary design considerations.*



Date 10-10

a – MAXILLARY ACRYLIC SPLINT
b – MANDIBULAR ACRYLIC SPLINT
c – BUCCAL TUBES
d – UPPER MEMBER
e – LOWER MEMBER
f – PNEUMATIC PISTON
g – UNIVERSAL JOINTS

FIGURE 22-5B *File: Information from clients.*

City services: (fire, police, waste, utility, library)

Most helpful for students: (Instructors, Librarians, and Shop Personnel)

Patents: Note that most of the information on a patented device only appears in Patent documents.

References:

Books (textbooks on specific topics):

Best listing of references found to date: Kolb, John and Ross, Steven, *Product Safety and Reliability*, 1980, McGraw-Hill, Inc. (It also contains more

than 45 pages of checklists for designers and installers.)

Handbooks: Each engineering discipline has a handbook, e.g., aeronautical, chemical, civil, electrical, mechanical, materials . . .

Standards and codes (a small sampling):

ANSI American National Standards Institute

ASTM American Society for Testing Metals

Mil Military Standard

UL Underwriters Laboratory ISO 9001 Catalogs: Vendor (products, hardware, electrical, electronic, structural shapes . . .)

Thomas Register (listing of companies, what they make, their address, sample catalogs . . .)

McMaster-Carr Supply Co. (Most complete hardware catalog found to date, P.O. Box 54960, Los Angeles, CA 90054, 213/945-2811)

Computer sources (CDs)

Vendor Catalogs. Vendors provide customers with convenient guides to select products and materials from their catalogs, *Figures 22-6A* through *E* (pages 844–848).

a. *Machine Elements.* V-belt drives, ball and roller bearings, roller chain drives, clutches, brakes, couplings, gearmotors (motor and gear reduction box as one unit), shafting, motors (AC and DC), and controls, all have similar guidelines for selecting them. These guidelines include formulas, tables, and charts to convert most customer

ROLLER CHAIN DRIVE SELECTION

The following considerations are very important in the selection and application of roller chain drives:

HORSEPOWER RATINGS — This catalog lists Horsepower Ratings for ANSI Series, single pitch, single strand chains No. 25 through No. 160 (and lightweight machinery series No. 41 and No. 43). Ratings are listed for various numbers of teeth and speeds of the smaller sprocket. Ratings for intermediate numbers of teeth or RPM may be determined by interpolation. The ratings reflect a service factor of 1, a chain length of approximately 100 pitches, the use of recommended lubrication methods and a drive arrangement where two aligned sprockets are mounted on parallel horizontal shafts. For maximum service life, sprockets with small numbers of teeth, operating at moderate to high speeds or near the rated horsepower should have hardened teeth. Approximately 15,000 hours of service life at full load operation may be expected under these conditions.

NO. OF TEETH — It is good practice to select a pinion sprocket with no less than 17 Teeth, to assure 120° of chain wrap and minimize overhung load. However, certain conditions, i.e., space limitations, light loads, intermittent duty, etc. will permit the use of smaller pinions.

RATIO — Sprocket ratios should not exceed about 6 to 1 for normal chain life.

HARDENED TEETH — Boston Gear steel sprockets can be hardened. Consult the factory for recommended procedure.

CENTER DISTANCE — The correct center distance is very important. In designing chain drives, it is important that the Center Distance should be long enough to provide at least 120° of chain wrap on the smaller sprocket.

RELATIVE SHAFT LOCATIONS — It is desirable that the line between the two shaft centers be as nearly horizontal as possible. If this line is more than 60° from the horizontal, special precautions should be taken.

A roller chain consists essentially of numerous small bearings operating under high pressures and requires adequate lubrication. There are four basic types of lubrication suggested for chain drives, depending on the chain speed and the power transmitted. The Horsepower Rating Tables indicate the type of lubrication recommended.

TYPE I — MANUAL LUBRICATION

Manual lubrication is accomplished by applying oil with a brush or spout can to the inside of the chain at the edges of the side plates. Volume and frequency should be determined by periodic inspection.

TYPE II — DRIP LUBRICATION

Oil is directed between link plate edges from a drip lubricator. Only enough oil to keep the chain moist is necessary and a light metal splash guard will keep the floor and surroundings clean.

TYPE III — BATH OR DISC LUBRICATION

With bath lubrication, the lower strand of the chain runs through a sump of oil. The oil level should reach the pitch line of the chain at its lowest point while operating. With disc lubrication, the chain operates above the oil level. The disc picks up oil from the sump and deposits it on the chain, usually by means of a trough. The disc diameter should be such as to produce rim speeds from 600 minimum to 8000 maximum FPM. This type of lubrication requires that the drive be enclosed in an oil-tight chain case.

TYPE IV — OIL STREAM LUBRICATION

The lubricant is usually supplied by a circulating pump capable of supplying the chain drive with a continuous stream of oil. The oil should be applied inside the chain loop evenly across the chain width, and directed at the lower strand. This type of lubrication requires that the drive be enclosed in an oil-tight chain case.

Recommended lubricant viscosities for various ambient temperatures are listed in the following table:

Temp. Degrees F.	Lubricant	Temp. Degrees F.	Lubricant
20-40	SAE20	100-120	SAE40
40-100	SAE30	120-140	SAE50

SURROUNDING CONDITIONS — Abrasive, corrosive, or high temperature conditions can shorten chain life. If adverse conditions exist, special precautions should be taken. It may be advisable to use a drive with higher capacity than normal, stainless steel chain, etc.

Roller chain drives may be selected with the following procedure:

a. From Table #1 of the Application Classification Chart on Page A94, determine the Service Factor.

b. Multiply the Application HP by the Service Factor to obtain a Design HP.*

c. The Selection Table below may be used to select an appropriate chain size using a sprocket of 17 teeth or larger.

d. From the appropriate horsepower rating table (pages B6-B8) determine the minimum size sprocket needed to provide, at the required speed, a rating equal to (or greater than) the Design horsepower.

e. The tables on pages B9-B11 may then be used to select number of sprocket teeth, shaft center distance and chain length of a drive suitable for the application.

*For Stainless Steel Chains, operating under wet or dry conditions, the Design Horsepower must be multiplied by a Factor (see Table below) for selection purposes.

NOTE: Standard Steel Chains are not recommended for wet or dry applications.

Application Conditions	Factor
Wet (Moisture)	2.0
Dry (Unlubricated)	5.0

Horsepower ratings of Multiple Strand chain may be obtained by multiplying the Single Strand rating by the proper Factor from the following table:

MULTIPLE STRAND RATING FACTORS

Number of Strands	Double	Triple	Quadruple
Rating Factor	1.7	2.5	3.3

These Horsepower Ratings are based on certain operating conditions, see Page B4.

FIGURE 22-6A *Roller chain drive selection considerations.* (Courtesy Boston Incom International Inc.)

SELECTION TABLE

RPM of Smaller Sprocket*	DESIGN HORSEPOWER												
	1/2	1	1-1/2	2	3	4	5	7-1/2	10	15	20	25	30
	CHAIN NUMBER												
1800	25	25	35	35	35	40	40	40	50	80	60 — 2	80 — 2	—
1500	25	25	35	35	35	40	40	40	60	60	80	60 — 2	80 — 2
1200	25	35	35	35	40	40	40	50	60	60	60	80	100
1000	25	35	35	35	40	40	40	50	60	60	80	80	80
800	25	35	35	40	40	40	50	50	60	60	80	80	80
700	25	35	35	40	40	50	50	50	60	80	80	80	80
600	35	35	35	40	40	50	50	60	60	80	80	80	100
500	35	35	40	40	50	50	50	60	80	80	80	100	100
400	35	35	40	40	50	50	60	60	80	80	100	100	100
350	35	40	40	40	50	50	60	80	80	80	100	100	100
300	35	40	40	50	50	60	60	80	80	100	100	100	120
250	35	40	40	50	50	60	60	80	80	100	100	120	120
200	35	40	50	50	60	60	80	80	80	100	120	120	120
175	40	40	50	50	60	80	80	80	100	100	120	120	140
150	40	50	50	60	60	80	80	80	100	120	120	120	140
125	40	50	50	60	80	80	80	100	100	120	120	140	140
100	40	50	60	60	80	80	80	100	100	120	140	140	160
80	40	50	60	80	80	80	100	100	120	140	140	160	160
70	50	60	60	80	80	80	100	120	120	140	160	160	
60	50	60	80	80	80	100	100	120	120	140	160		
50	50	60	80	80	80	100	100	120	140	160	160		
40	50	60	80	80	100	100	120	120	140	160			
30	60	80	80	100	100	120	120	140	160				
25	60	80	80	100	120	120	140	140	160				
20	60	80	100	100	120	120	140	160					
15	80	100	100	120	120	140	160						
10	80	100	120	120	140	140							

*Based on 17-Tooth Sprocket.

FIGURE 22-6B *Roller chain drive selection procedure.* (Courtesy Boston Gear Incom International Inc.)

applications and environmental conditions to numbers or letters in their catalogs.

For example, assume that the belt conveyor shown in ***Figure 22-6F*** (page 849) needs a roller chain drive to transmit power from the gearmotor's 200 RPM output shaft to the headshaft of the conveyor. Calculations indicate 14 horsepower to operate the conveyor at 500 FPM (feet per minute).

The roller chain drive, sprockets, and chain can be selected from a vendor's catalog using the tables in Figures 22-6A-E. Figure 22-6A contains general guidelines for selecting and applying roller chain drives. To select a roller chain drive, follow the five steps in Figure 22-26A. The first step determines the service factor to be 1.25, as indicated in Figure 22-6C, assuming heavy duty, not uniformly fed and operating less than 10 hours per day. Step 2 says that the design horsepower is the calculated horsepower times the service factor, (14) (1.25) = 17.5. The third step is to use the design horsepower in the selection table in Figure 22-6B to determine chain size. Chain size No. 120 with a 17-tooth smaller sprocket will work. The next step (using Figure 22-6D) indicates that an 11-tooth smaller sprocket will theoretically work; however, good practice dictates the use of a 17-tooth sprocket according to comments in Figure 22-6A. Finally, for the fifth step use Figure 22-6E to find the larger sprocket to give a drive ratio of 2.50. A 42-tooth sprocket combined with a 17-tooth gives a ratio of 2.47, which is close enough. The center distance between the two sprockets using a 64-inch-long chain will be 16.777 inches.

b. *Engineering materials and shapes* can be selected from *vendor catalogs.*

(i) The catalogs published by vendors of materials list materials and their typical uses to aid in their selection. To illustrate, one catalog describes 6061 aluminum as being heat treatable, having good formability (will not crack during bending), having good weldability, and being corrosion resistant. Also, 6061 aluminum is used for structural application, boats, and transportation equipment.

(ii) Some materials are selected primarily on the basis of their shape; for example, steel and aluminum are rolled into plates, bars, channels, beams, and angles and are extruded into pipe, square tubes, and rectangular tubes.

APPLICATION CLASSIFICATION FOR VARIOUS LOADS

Type of Machine To Be Driven	Chart I For all Drives — Service Factor — Loading: Not More Than 15 Mins. In 2 Hrs.	Not More Than 10 Hrs. per Day	More Than 10 Hrs. per Day
AGITATORS			
Pure Liquid	0.80	1.00	1.25
Semi-Liquids, Variable Density	1.00	1.25	1.50
BLOWERS			
Centrifugal and Vane	0.80	1.00	1.25
Lobe	1.00	1.25	1.50
BREWING AND DISTILLING			
Bottling Machinery	0.80	1.00	1.25
Brew Kettles — Continuous Duty	—	—	1.25
Cookers — Continuous Duty	—	—	1.25
Mash Tubs — Continuous Duty	—	—	1.25
Scale Hopper — Frequent Starts	—	1.25	1.50
CAN FILLING MACHINES	—	1.00	—
CANE KNIVES	—	1.50	—
CAR DUMPERS	—	1.75	—
CAR PULLERS	—	1.25	—
CLARIFIERS	—	1.00	1.25
CLASSIFIERS	—	1.25	1.50
CLAY WORKING MACHINERY			
Brick Press & Briquette Machine	—	1.75	2.00
Extruders and Mixers	1.00	1.25	1.50
COMPRESSORS			
Centrifugal	—	1.00	1.25
Lobe — Reciprocating, Multi-Cycle	—	1.25	1.50
Reciprocating — Single Cycle	—	1.75	2.00
CONVEYORS — UNIFORMLY LOADED & FED			
Apron	—	1.00	1.25
Assembly-Belt — Bucket or Pan	—	1.00	1.25
Chain — Flight	—	1.00	1.25
Oven — Live Roll — Screw	—	1.00	1.25
CONVEYORS — HEAVY DUTY NOT UNIFORMLY FED			
Apron		1.25	1.50
→ Assembly-Belt — Bucket or Pan	—	1.25	1.50
Chain — Flight	—	1.25	1.50
Live Roll	—	—	—
Oven — Screw	—	1.25	1.50
Reciprocating — Shaker	—	1.75	2.00
CRANES AND HOISTS			
Main Hoists			
Bridge and Trolley Drive	*	1.00	1.25
CRUSHER			
Ore, Stone	—	1.75	2.00
Sugar	—	1.50	1.50
ELEVATORS			
Bucket — Uniform Load	—	1.00	1.25
Bucket — Heavy Load	—	1.25	1.50
Centrifugal Discharge	—	1.25	1.50
Freight	—	1.25	1.50
Gravity Discharge	—	1.00	1.25
ELEVATORS			
Bucket — Uniform Load	—	1.00	1.25
Bucket — Heavy Load	—	1.25	1.50
Centrifugal Discharge	—	1.25	1.50
Freight	—	1.25	1.50
Gravity Discharge	—	1.00	1.25
FANS			
Centrifugal — Light (Small Diam.)	—	1.00	1.25
Large Industrial	—	1.25	1.50

Type of Machine To Be Driven	Chart I For all Drives — Service Factor — Loading: Not More Than 15 Mins. In 2 Hrs.	Not More Than 10 Hrs. per Day	More Than 10 Hrs. per Day
FEEDERS			
Apron — Belt — Screw	—	1.25	1.50
Disc	—	1.00	1.25
Reciprocating	—	1.75	2.00
FOOD INDUSTRY			
Beet Slicer	—	1.25	1.50
Cereal Cooker	—	1.00	1.25
Dough Mixer —Meat Grinder	—	1.25	1.50
GENERATORS (NOT WELDING)	—	1.00	1.25
HAMMER MILLS	—	1.75	2.00
HOISTS			
Heavy Duty	—	1.75	2.00
Medium Duty and Skip Type	—	1.25	1.50
LAUNDRY TUMBLERS	—	1.25	1.50
LINE SHAFTS			
Uniform Load	—	1.00	1.25
Heavy Load	—	1.25	1.50
MACHINE TOOLS			
Auxiliary Drive	—	1.00	1.25
Main Drive — Uniform Load	—	1.25	1.50
Main Drive — Heavy Load	—	1.75	2.00
METAL MILLS			
Draw Bench Carriers & Main Drive	—	1.25	1.50
SLITTERS	—	1.25	1.50
TABLE CONVEYORS — NON REVERSING			
Group Drives	—	1.25	1.50
Individual Drives	—	1.75	2.00
Wire Drawing, Flattening or Winding	—	1.25	1.50
MILLS ROTARY TYPE BALL & ROD			
Spur Ring Gear and Direct Connected	—	—	2.00
Cement Kilns, Pebble	—	—	1.50
Dryers and Coolers	—	—	1.50
Plain and Wedge Bar	—	—	1.50
Tumbling Barrels	—	—	2.00
MIXERS			
Concrete — Continuous	—	1.25	1.50
Concrete — Intermittent	—	1.25	1.50
Constant Density	—	1.00	1.25
Semi-Liquid	—	1.25	1.50
OIL INDUSTRY			
Oil Well Pumping	—	—	*
Chillers, Paraffin Filter Press	—	1.25	1.50
Rotary Kilns	—	1.25	1.50
PAPER MILLS			
Agitator (Mixer)	—	1.25	1.50
Agitator — Pure Liquids	—	1.00	1.25
Barking Drums — Mechanical Barkers	—	1.75	2.00
Bleacher	—	1.00	1.25
Beater	—	1.25	1.50
Calender Heavy Duty	—	—	2.00
Calender Anti-Friction Brgs.	—	1.00	1.25
Cylinders	—	1.25	1.50
Chipper	—	—	2.00
Chip Feeder	—	1.25	1.50
Coating Rolls — Couch Rolls	—	1.00	1.25
Conveyors — Chips — Bark — Chemical	—	1.00	1.25
Conveyors — Log and Slab	—	—	2.00
Cutter	—	—	2.00
Cylinder Molds, Dryers (Anti-Friction Brg.)	—	—	1.25
Felt Stretcher	—	1.25	1.50
Screens — Chip and Rotary	—	1.25	1.50
Thickener (AC)	—	1.25	1.50
Washer (AC)	—	1.25	1.50
Winder — Surface Type	—	—	1.25

FIGURE 22-6C *Service factors for various applications.* (Courtesy Boston Gear Incom International Inc.)

Small Sprocket		HP RATINGS — STANDARD SINGLE * STRAND ROLLER CHAIN — NO. 120 — 1-1/2" PITCH																	
RPM→		10	20	30	50	75	100	125	150	200	250	300	400	500	600	700	800	900	1000	1200
Teeth	P.D.																			
11	5.324"	1.37	2.56	3.68	5.82	8.40	10.9	13.3	15.6	20.3	24.8	29.2	37.8	46.3	54.5	46.3	37.9	31.8	27.1	20.6
13	6.268	1.64	3.06	4.41	6.97	10.1	13.0	15.9	18.7	24.3	29.7	35.0	45.3	55.4	65.3	59.5	48.7	40.8	34.9	26.5
15	7.215	1.91	3.57	5.14	8.13	11.7	15.2	18.6	21.9	28.3	34.7	40.8	52.9	64.6	76.1	73.8	60.4	50.6	43.2	32.9
17	8.164	2.19	4.09	5.88	9.31	13.4	17.4	21.3	25.0	32.4	39.7	46.7	60.5	74.0	87.2	89.0	72.8	61.0	52.1	39.6
19	9.114	2.47	4.61	6.64	10.5	15.2	19.6	24.0	28.2	36.5	44.8	52.7	68.2	83.4	98.3	105	86.1	72.1	61.6	46.8
21	10.064	2.75	5.13	7.39	11.7	16.9	21.8	26.7	31.4	40.7	49.8	58.7	76.0	93.0	110	122	100	83.8	71.6	54.4
Lubrication #		Type I		Type II					Type III				Type IV							

FIGURE 22-6D *Horsepower ratings for No. 120 roller chain.* (Courtesy Boston Gear Incom International Inc.)

Square and rectangular shapes are easier to join in fabricating than pipe sections. Pipe sections are equally strong in all directions.

(iii) Materials may be selected on the basis of their weight, rigidity, and coefficient of expansion due to temperature changes. INVAR is used in instrumentation because of its low coefficient of expansion of 1.6×10^{-6} inches per inch per degree Fahrenheit.

(iv) Additional bases for selecting materials are corrosion resistance, machinability, strength, and electrical properties.

(v) Combinations of all of the above, plus aesthetics and prior experiences, may be used for selecting materials.

Call or visit a local vendor of materials or machine elements, and request one of their catalogs. Usually, they are eager to have their catalogs in the hands of future buyers, so they are happy to donate one or more.

Furthermore, since most vendors handle a variety of products, a call or a visit may result in a small library!

Step 3 Combine Information into a Preliminary Definition. Prepare a preliminary definition of the problem so that all parties concerned can see the direction and course of the project. The definition mainly consists of two types of statements, *constraints* and *specifications*. These are written as specifically as possible even at this early stage in the project. For example, a vague specification might say that the product is to be safe to use. A more specific specification would say that the product will be safe to use by a 12-year-old child who can read and understand simple directions, and that the directions will be affixed to the product.

a. *Constraints.* List the more restrictive constraints, such as cost, delivery date, availability of materials, codes, and standards. Then, list the less restrictive ones, such as shop capability, available personnel, product life, and aesthetics.

b. *Specifications.* Divide specifications into two main categories, performance and design. Performance specifications describe what the design is to do, what it is to accomplish, what it is to produce, who is to use it, what environment it will operate in, how it will be maintained, how safe it is, and how easy it is to use. Design specifications indicate what materials are to be used and how they are to be fabricated and finished. Purchased products also are included.

Well-written specifications are stated so that they can be tested or measured. For example, the chemistry and strength of a material can be measured and tested, respectively. Resistance, frequency, volume, temperature, and weight can all be measured.

c. *Preliminary Solution Ideas.* Collect preliminary solution ideas that occur while the definition, constraints, and specifications are being developed and written. File these for use in Phase II.

d. *Iterate.* Return to Step 2 to gather further information and to revise the definition. Returning and revising is an iterative process that occurs continually throughout the design process.

Step 4 Prepare a Progress Report. Prepare a *progress report* to the client, who is usually the primary contact during the project. By now, approximately one-fourth of the project time will have been used, so a report to the client should be made preferably in writing. Include the current definition—constraints and specifications—so that if there are any misunderstandings, they can be resolved early in the project. Decisions made verbally should be summarized. Indicate immediate plans and ask for confirmation as soon as possible. The client, a person or an organization, wants to know how the project is progressing and if any problems have arisen.

SPEED RATIOS — CENTER DISTANCES — CHAIN LENGTHS

Teeth on DriveN Sprocket	Teeth on DriveR Sprocket														
	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
15	1.36 6.469 26	1.25 7.235 28	1.15 6.993 28	1.07 7.748 20	1.00 7.500 30				RATIO CENTER DISTANCE — IN PITCHES CHAIN LENGTH — IN PITCHES To obtain corresponding values in INCHES, multiply by the appropriate Chain Pitch.						
16	1.45 7.207 28	1.33 6.971 28	1.23 7.736 30	1.14 7.494 30	1.07 8.249 32	1.00 8.000 32									
17	1.55 7.943 30	1.42 7.710 30	1.31 7.473 30	1.21 8.237 32	1.13 7.994 32	1.06 8.749 34	1.00 8.500 34								
18	1.64 7.669 30	1.50 8.446 32	1.38 8.212 32	1.29 7.975 32	1.20 8.737 34	1.13 8.495 34	1.06 9.249 36	1.00 9.000 36							
19	1.73 8.404 32	1.58 8.174 32	1.46 8.949 34	1.36 8.714 34	1.27 8.477 34	1.19 9.238 36	1.12 8.995 36	1.06 9.749 38	1.00 9.500 38						
20	1.82 8.124 32	1.67 8.909 34	1.54 8.679 34	1.43 9.452 36	1.33 9.216 36	1.25 8.978 36	1.18 9.739 38	1.11 9.495 38	1.05 10.249 40	1.00 10.000 40					
21	1.91 8.857 34	1.75 8.632 34	1.61 9.414 36	1.50 9.183 36	1.40 9.955 38	1.31 9.718 38	1.24 9.479 38	1.17 10.239 40	1.11 9.995 40	1.05 10.749 42	1.00 10.500 42				
22	2.00 9.590 36	1.83 9.365 36	1.69 9.139 36	1.57 9.918 38	1.47 9.686 38	1.37 10.457 40	1.29 10.220 40	1.22 9.980 40	1.16 10.740 42	1.10 10.496 42	1.05 11.249 44	1.00 11.000 44			
23	2.09 9.304 36	1.92 10.098 38	1.77 9.872 38	1.64 9.645 38	1.53 10.422 40	1.44 10.189 40	1.35 10.959 42	1.28 10.721 42	1.21 10.481 42	1.15 11.240 44	1.10 10.996 44	1.05 11.749 46	1.00 11.500 46		
24	2.18 10.037 38	2.00 9.815 38	1.85 10.605 40	1.72 10.378 40	1.69 10.150 40	1.50 10.926 42	1.41 10.692 42	1.33 11.461 44	1.26 11.222 44	1.20 10.982 44	1.14 11.741 46	1.09 11.496 46	1.04 12.249 48	1.00 12.000 48	
25	2.27 9.744 38	2.08 10.547 40	1.92 10.324 40	1.79 11.112 42	1.67 10.884 42	1.56 10.654 42	1.47 11.429 44	1.39 11.195 44	1.31 11.963 46	1.25 11.723 46	1.19 11.483 46	1.14 12.241 48	1.09 11.996 48	1.04 12.750 50	1.00 12.500 50
30	2.72 11.345 44	2.50 12.161 46	2.31 11.943 46	2.14 12.746 48	2.00 12.522 48	1.88 12.299 48	1.76 13.087 50	1.67 12.858 50	1.58 13.638 52	1.50 13.406 52	1.43 13.172 52	1.36 13.942 54	1.30 13.705 54	1.25 14.469 56	1.20 14.228 56
32	2.91 12.812 48	2.66 12.597 48	2.46 12.379 48	2.28 13.188 50	2.14 12.967 50	2.00 13.765 52	1.88 13.539 52	1.78 13.314 52	1.68 14.099 54	1.60 13.869 54	1.52 14.646 56	1.45 14.413 56	1.39 14.178 56	1.33 14.946 58	1.28 14.708 58
35	3.18 13.976 52	2.92 13.761 52	2.69 13.546 52	2.50 14.361 54	2.33 14.141 54	2.19 13.921 54	2.06 14.721 56	1.94 14.497 56	1.84 15.288 58	1.75 15.061 58	1.67 14.833 58	1.59 15.613 60	1.52 15.382 60	1.46 16.155 62	1.40 15.921 62
36	3.27 13.668 52	3.00 14.495 54	2.77 14.279 54	2.57 14.063 54	2.40 14.874 56	2.25 14.653 56	2.12 14.433 56	2.00 15.230 58	1.89 15.006 58	1.80 15.795 60	1.71 15.567 60	1.64 15.338 60	1.56 16.117 62	1.50 15.886 62	1.44 16.658 64
40	3.64 15.561 58	3.34 15.349 58	3.08 15.136 58	2.86 15.961 60	2.67 15.764 60	2.50 15.528 60	2.35 16.339 62	2.22 16.119 62	2.10 16.920 64	2.00 16.697 64	1.90 16.473 64	1.82 17.262 66	1.74 17.035 66	1.67 17.818 68	1.60 17.588 68
42	3.82 15.983 60	3.50 15.773 60	3.23 16.605 62	3.00 16.391 62	2.80 16.177 62	2.62 16.994 64	2.47 16.777 64	2.34 16.557 64	2.21 17.364 66	2.10 17.142 66	2.00 17.939 68	1.91 17.714 68	1.83 17.489 68	1.75 18.275 70	1.68 18.047 70
45	4.09 17.139 64	3.75 16.930 64	3.46 16.719 64	3.22 17.553 66	3.00 17.340 66	2.81 18.161 68	2.65 17.945 68	2.50 17.728 68	2.37 18.536 70	2.25 18.317 70	2.14 18.096 70	2.04 18.895 72	1.96 18.671 72	1.88 19.463 74	1.80 19.237 74

FIGURE 22-6E *Speed ratios—center distance—chain lengths.* (Courtesy Boston Gear Incom International Inc.)



FIGURE 22-6F *Belt conveyor system schematic.*

For the purposes of this discussion, clients are divided into two groups.

a. *Internal Clients* are instructors in classrooms and supervisory persons in industry. And even with this close proximity to the client, important communications should be in writing.

b. *External Clients* comprise a large variety of people and organizations, both in classrooms and in industry. In classroom situations, an external client could be another instructor, a student, a department, a design contest, a handicapped person, a rehabilitation department, a local government, or a national organization. In industry, the external client could be another company; an individual; a department in a city, state, or national government; the military; or even another nation.

Phase II Generate Alternative Solutions: Synthesis

STEP 5 Generate Solution Ideas
a. Use Systematic Techniques
b. Use Creative Techniques and Attitudes

Step 5 Generate Solution Ideas. Review the solution ideas already collected and realize that additional effort and discipline need to be exerted to generate more. Frequently, an idea for a solution occurs early in the process, and there is a tendency—especially among students, because of their time constraints—to select the first idea as the final solution. Successful problem solvers know that additional ideas can be generated beyond the initial obvious ones by continuing to focus on the design problem and employing two types of idea-generating techniques: systematic techniques and creative techniques. Having a creative attitude also helps.

a. *Use Systematic Techniques.* Verb lists provide a systematic checklist for generating new ideas, primarily building on existing ones. Ask the following questions regarding the idea being considered:

- Can it be modified?
- Can it be made larger? Smaller?
- Can it be used for something else?
- Can other materials be substituted?
- Can components be rearranged?
- Can it be combined with another idea?

Divide an idea into smaller parts so that each part can be systematically examined and developed.

Human Factors. There are published tabulations of body dimensions of average males, females, and children. These are called the *human factors*. This statistical data may be found in textbooks and handbooks: however, for classroom designs use a classmate or yourself for measurements, since most of the adult population is close to the average size. Use children if needed.

For a design file, observe or measure objects designed for average humans. Typical designs include chairs, tables, desks, computer stations, work counters, doorknobs, ladder rungs, switches, handles, and numerous objects encountered daily.

Also, consider and observe the various techniques that are used to interface machines with human operators. A variety of sounds such as voices speaking messages, a number of visual devices using a multitude of colors, numerous tactile devices such as clicks during dialing, and different shapes of knobs are all used.

Try a 180-degree approach. For instance, instead of breaking a walnut shell with a hammer, poke a hollow needle inside and explode the shell with air pressure.

List the obvious attributes of an object to uncover ideas.

- Describe the size using dimensioned sketches.
- List the intended functions of the object.
- Outline how it was probably manufactured.
- List the materials used to make it.
- Describe any other features, such as aesthetics, weight, and color.

Use attribute listing, not only to generate ideas, but also as a checklist for the design of parts on technical drawings. That is, check for complete dimensions to describe the geometry of each part and dimensions to locate each feature, such as bolt holes, slots, special surfaces, and datums. Review appropriate dimensions to ensure the function of the part, for example, clearances and fits. Check the material specified for the part, and whether or not the manufacturability of the part was considered during the design phase. Finally, check all remaining attributes, such as how easily the part can be assembled, surface finishes, heat treatments, and aesthetics. Also list the not-so-obvious attributes, such as other uses that were not intended functions. Developing the habit of proposing these "not-so-obvious" uses for objects will help to generate new ideas for future designs.

Figure 22-7 shows the obvious attributes of a paper clip, and the not-so-obvious ones are listed in *Figure 22-8.*

Browse through technical texts, periodicals, and handbooks that contain numerous ideas for components, mechanisms, and applications of existing products. The list that follows includes the three types.

- Texts:

  Herkimer, Herbert, *The Engineer's Illustrated Thesaurus,* 1952, Chemical Publishing Co.

  Schwartz, Otto B./Grafstein, Paul, *Pictorial Handbook of Technical Devices,* 1971, Chemical Publishing Co.

  McCormick, Ernest J., *Human Factors Engineering,* 1970, McGraw-Hill, Inc.

  Chapanis, A., *Man-Machine-Engineering,* 1965, Wadsworth Publishing Co.

- Periodicals (found in most libraries):

  Machine Design

  Product Engineering

  Test and Measurement World

EXAMPLE OF OBVIOUS ATTRIBUTES



FIGURE 22-7 *Attributes of a paper clip.*

EXAMPLES OF NOT-SO-OBVIOUS ATTRIBUTES	
AS IS	**CHANGE**
–dig out ear wax	–fish hook
–make a chain	–cake tester
–balance for paper airplane	–electrical conductor
–clip other items	–chess pieces
–sinker for fishing	–lock pick
–checkers	–artistic shape
–poker chips	–therapy–bend for relaxing
–hanger for small picture	–melt many to make casting
–standard of weight	–fatigue failure demo

FIGURE 22-8 *Not-so-obvious attributes.*

Control Engineering

Medical Product Manufacturing News

Hydraulics and Pneumatics

Research and Development

Engineer's Digest

- Handbooks:

  Shigley, Joseph E., *Standard Handbook of Machine Design,* 1986, McGraw-Hill, Inc.

  Laughner, V. H./Hargan, A. D., *Handbook of Fastening and Joining of Metal Parts,* 1956, McGraw-Hill, Inc.

  Horger, A. J., *ASME Handbook Metals Engineering Design,* 1965, ASME.

b. *Use Creative Techniques and Attitudes.* A clear understanding of the *creative process* will help to generate ideas. The process—as described by

technical people, composers, writers, builders, doctors, hobbyists, and many others—proceeds as follows:

(i) Accumulate all the information about the problem being attacked; that is, thoroughly and conscientiously get involved in the problem, even emotionally if necessary. This involvement, according to creative individuals, causes the subconscious portion of the brain to be alerted that a problem needs solving. Next, relax and let the information collected . . .

(ii) Incubate with other ideas that the subconscious brain retrieves from memory locations. Take a walk, jog. Plop both feet upon a desk and lean back while contemplating the ceiling. (Supervisors may need to be informed that the "process" is working.) Soon, one hopes an idea will surface in the conscious portion of the brain; that is, the idea . . .

(iii) Illuminates its presence and causes exclamations like, "Eureka, I've got it!" Finally, the idea needs to be . . .

(iv) Verified. Does it actually solve the problem? Meet the constraints? Satisfy the specifications?

Develop a creative attitude and behavior by adopting characteristics of creative people. Several are listed here.

1. *Keep an open mind. Be willing to accept change and new ideas.*
2. *Look for similarities and unusual relationships.*
3. *Think positive. Avoid or ignore negative comments such as:* "It's been tried before." "It's not logical." "What a dumb idea." "It'll never work."
4. *Be persistent.*
5. ALWAYS CARRY A NOTEBOOK!!!!!!! Ideas come when least expected and may be lost if not recorded.

Participate in exercises designed to revive creative talents, buried during years of being told what to do and to conform. For example, the late Professor John Arnold, M.I.T. and Stanford University, proposed a fictitious planet, Arcturus IV, populated with creatures who were unusually tall and slow moving, had reaction times one-tenth as fast as humans, had three fingers on each hand, had three eyes, one of which had x-ray vision, and breathed methane. Professor Arnold asked his students to design an automobile-type vehicle for these inhabitants. Tackle this problem before reading on, and compare your design ideas with those of other members of your class. For example, what speed limit should be required due to the slow reaction time of the inhabitants?

Build a simple model related to the design problem being developed. Building a model, or a prototype, almost always produces new ideas because of the simultaneous involvement of the hands, eyes, and brain, plus the three-dimensional insight. Models can be inexpensive—cardboard, balsa wood, tape, etc. Computer graphics can be used.

Do exercises to develop imagination, for the same reason that muscles are exercised: for growth and to avoid atrophying. One convenient source of creative exercises is the daily newspaper, which contains word puzzles, crossword puzzles, and picture puzzles.

Try the following exercises to help develop a creative attitude:

1. Use analogies. For example, pretend to be one of the components in a machine and imagine how each part would function if designed a certain way. What would happen if the design were changed?
2. Systematically propose that a product be changed in any one of the following ways: made bigger, smaller, longer, shorter, colorful, drab, nontraditional, expensive, or cheap.

Read books devoted to developing creativity and try some of their recommendations.

A person's creative potential can be enhanced by taking courses in areas outside of engineering and technology. Take courses to obtain different points of view in other disciplines, such as biology, geology, agriculture, environment, political science, art, philosophy, or oceanography.

Brainstorm according to the ideas of Alex Osborne in his *Applied Imagination*. The procedure is simple to follow. Meet with a group who are willing to abide by the following guidelines:

1. Have one person *record ideas as they are generated,* on a surface visible to all participants. New ideas often stem from the visible ones.
2. Agree that *no one is to criticize* any ideas while the brainstorming is in progress, no matter how ridiculous an idea may seem. Frequently, viable ideas stem from less obvious ones.
3. Meet in as *pleasant surroundings* as practical, and include refreshments. Several one-hour sessions produce better results than one long session.
4. Finally, *meet to critique the ideas* for possible solutions.

Brainstorming can also be done individually.

Develop observation skills through freehand sketching by looking at a component while imagining how a sketch of the component would be made. Of course, do the sketch if possible! Looking at an object while imagining how a sketch would be made causes the viewer to see more about the object than he or she would if only a casual glance were given. Try sketching assemblies of components, also.

Assume now that a number of design ideas have been generated. The group usually wants to continue in this creative mode because creating is a satisfying activity. However, since time controls the schedule, the group needs to move on. Students involved in the design process for the first time reluctantly leave this synthesis phase believing that if they had more time they could do a better job. Creative professionals know that they must do the best they can in each phase, in the time available, and then move on to complete their projects within the schedule.

So now is the time to focus on evaluating instead of generating.

Phase III Evaluate Alternative Solution Ideas: Analysis

STEP 6 Sift, Combine, and Prepare Solution Ideas for Analysis
- a. Preliminary Preparation
- b. Specific Preparation

STEP 7 Compare Solution Alternatives to Constraints and Specifications
- a. Iterate
- b. Persevere
- c. Qualitative Evaluation
- d. Quantitative Evaluation

STEP 8 Conduct a Design Review
- a. In-House Design Reviews
- b. Outside Design Reviews

STEP 9 Refine the Final Solution

Step 6 Sift, Combine, and Prepare Solution Ideas for Analysis. Sift through all the collected ideas and keep those that seem to have potential as a part solution or as a complete solution. File the remaining ideas for possible use in the future.

a. *Preliminary Preparation.* Expand each potential idea in more detail. Clarify, if possible, vague statements and generalities. Ask each member of the group to develop preliminary statements and sketches of those of his or her ideas that survived the initial sifting and culling.

Do further research, if needed, to expand the ideas.

b. *Specific Preparation.* Prepare *layout development drawings* of the preliminary sketches. Layout drawings are essentially a designer's freehand sketch redrawn to scale with instruments or a computer. Designers use two types, design development and kinematic development (the latter is used primarily for mechanical products). Schematic layouts, using lines and symbols, but not to scale, are used for electronic circuits, electrical circuits, piping diagrams, routing paths, processing steps, chemical plants, and logic circuits.

A design development layout drawing is made from a freehand sketch of a design idea for an anchor bolt puller shown in *Figure 22-9A.* The design idea is drawn to scale in the design development layout drawing, *Figure 22-9B.* Notes and comments may be in writing or in casual lettering. Compare this informal approach to the formal technical detail and assembly drawings for shop use, which have standard lettering, lines, and symbols made on standard-size drawing sheets, complete with title blocks.

Use the design development layouts to establish the locations and sizes of parts to be fabricated so as to ensure the functions of the final product. Also use this layout to verify that purchased products will fit where required.

In industry, designers forward their design development layout drawings to drafters who prepare the formal technical detail and assembly drawings. Students in classrooms do both.

A kinematic development layout drawing is shown in *Figure 22-10.* This type of layout shows the relative motions of assembled components, verifies the function of the assembly, checks for interferences, and does velocity plus acceleration analyses. The kinematic analyses are usually done in a two-dimensional format even though the assemblies are, of course, three dimensional.

A useful complement to the kinematic development layout drawing is a simple cardboard-thumbtack model, as illustrated in *Figure 22-11.* CAD systems with programs for kinematic analyses are also useful and available.

Use cardboard-and-glue models (noted earlier) to further complement the layout drawings. Students, designers, drafters, and practicing engineers attest that two major phenomena happen during the process of making a model of a portion or all of a design from a design development layout. One, they discover that the components in the three-dimensional model may not work as planned, so adjustments and refinements are required. And



FIGURE 22-9A *Freehand sketch of a design idea.*



FIGURE 22-9B *Design development layout.*



FIGURE 22-10 *Kinematic development layout.*



FIGURE 22-11 *Kinematic model.*

two, new solution ideas surface, ideas no one had considered. They believe that the combination of using their hands and eyes while shaping and assembling materials triggers an untapped area in their subconscious minds. Furthermore, since ideas evolve as pictures in the mind, sketching, drawing, and model making seem to enhance the forming of these pictures.

Two additional advantages of cardboard models are the relative low cost (compared to prototypes) and the fact that the model may be used later in a design review.

The solution ideas that have been expanded and prepared for further analyses can now be considered as solution alternatives.

Step 7 Compare Solution Alternatives to Constraints and Specifications.

a. *Iterate.* Review Phases I and II for possible additions or deletions to the constraints and specifications. New information may have been discovered. The client may want changes made.

b. *Persevere.* Be cognizant of a morale problem that may occur at about this time in the design process. Imagine that a group, or an individual, has started a project with high hopes and confidence that a solution can be found. However, even though the first five or six steps have been conscientiously done, no real viable solution ideas have been generated. The individual or all of the participants find themselves at a low point in the morale curve shown in ***Figure 22-12***. They discover that there is more to the problem than they thought, and useful information is difficult to find. They become discouraged. However, experienced problem solvers know that perseverance will get them through the slump, and that satisfactory results eventually will follow. They know that toward the end of Phase IV their morale and self-confidence for attacking problems will be higher than when they started.

c. *Qualitative Evaluation.* Compare solution alternatives with what has been done before. If a solution alternative is similar to existing designs, either within the company or in industry, the feasibility of it is relatively easy to determine.

Use a range technique for evaluating preliminary alternatives. Intuition, experience, and judgment help to determine if the size or thickness of a member is within a reasonable range. For example, most students could evaluate design alternatives for home-use ladders based on their own experiences. Similar range approaches have names like back-of-the-envelope calculations and order-of-magnitude analyses. Interestingly, all of these



FIGURE 22-12 *Morale curve.*

approaches are useful in designing as well as in evaluating.

d. *Quantitative Evaluation.* Build a *prototype* of part or all of a solution alternative. For example, a student group had the problem of compressing a 2′ × 2′ × 4′ bale of hay into a 2′ × 2′ × 2′ cube so that their farmer client could ship more hay per shipload from Seattle, Washington, to a port in northern Alaska. The hay compressor was to be part of a complete hay-baler machine. One key factor that they needed for their design was the force required to compress a bale to half size. So they made a crude, but effective, set of rectangular welded-steel boxes, one to telescope within the other, to hold a bale in a testing machine that could generate up to 60,000 pounds of compressive force. See *Figure 22-13* for a conceptual sketch showing the two containers and the bale of hay. The students learned that to compress the bale to half size required 14,000 pounds of force. A hydraulic cylinder was selected to provide the force.

Another type of prototype building is a process called stereolithography. Actual solid models are created layer by layer by an electronic-laser process in a special liquid solution. A focused beam causes the liquid to solidify over exact areas at accurate locations. It adheres to the previous layer, until a complete component is built up.

Two alternatives to actually building a prototype of a proposed design can be done on a computer: wireframe drawing and solid modeling.

Perspective, wireframe drawings (line drawings in perspective of objects, no hidden lines) on expensive computer systems that can rotate views and zoom into or out of buildings, or marine vessels, are used by architects and marine engineers to visualize what the internal structure would look like.

Solid modeling on a computer screen can be helpful in evaluating a design for shape, structure, and interferences. Also, the solid model can be used as the basis for a finite-element analysis for checking the strength of an object.

Consider the feasibility of each alternative by asking questions such as: How much will it cost? Can the shop make it? Are engineering materials available? Are finished components available? Are sufficient labor hours available? Can the delivery date be met?

Manufacturing Process Costs. The following sample list is headed by the least costly and ends with the most costly manufacturing process. *Costs* are also related to the roughness of the surfaces of the materials. The roughness is a result of the manufacturing or production processes.

Sawing	Rough Surfaces
Cutting (torch)	(lower cost)
Drilling	
Turning	
Punching	
Milling	Average Surface Roughness
Reaming	(Average Cost)
Broaching	
Grinding	
Polishing	
Honing	
Lapping	Smooth Surface (Higher Cost)

Relative Costs of Materials. Use relative cost numbers as an aid to evaluating the feasibility of a design alternative, and for establishing approximate costs. Mild steel is given a factor of 1.00; all other engineering materials are given relative numbers. Find the current cost of mild steel, and use the relative numbers to establish costs of the other materials. Revise the numbers as needed.

Material	Relative Cost (By Weight)
Mild steel	1.00
Spring steel	2.00
Tool steel	11.00
Cast iron	3.00
Aluminum	6.00
Stainless steel	7.00
Brass	7.00
Copper	7.50
Titanium	130.00
Teflon	67.00
Nylon	19.00
Rubber	4.00
Wood	1.00



FIGURE 22-13 *Prototype test.*

Safe Designs. Use the following checklist to provide *safe designs,* safe installations, and protection against negligence suits.

Document the design to show evidence of the following:

a. Accurate calculations
b. Proper use of codes and standards
c. Use of state-of-the-art technology
d. Proper use of materials and hardware
e. Having run tests, if appropriate
f. Use of proper manufacturing processes, proper fasteners, and appropriate heat treatments
g. A quality control program
h. Preparation of instructions for safe use
i. Addition of warning signs to the product
j. Having told future owners of the proper safety devices and practices needed, such as guards around any exposed moving parts of machines, and painted stripes to show danger areas
k. Thorough exploration of all possible uses of the product other than those for which it was designed

Access. Locate fasteners and components for installation and servicing so personnel can have access to them with their hands and tools. Also, provide access to weld areas for welders.

Vibration. Use locking devices such as lock washers and lock nuts on threaded fasteners subjected to vibration. Some high-speed engines have wires passing through holes in the nuts to prevent the nuts from backing off because of vibrating conditions.

Fatigue. Avoid sharp changes of cross-section and small fillet radii on parts subjected to varying loads. See *Figure 22-14* for examples of good and poor practices. The sharp corners and radii (and scored surfaces) cause stress concentrations and therefore, possible fatigue failure.

Cleaning/Corrosion. Provide sloping surfaces wherever standing fluids could cause corrosion. For example, tank bottoms should slope toward a drain hole so that chemicals and cleaning fluids can be completely drained. Upper surfaces should slope to prevent standing rainwater or melting snow.

Temperature. Avoid stringent tolerances on dimensions of parts subjected to extreme temperature changes. Furthermore, check the strength and ductility of materials at extreme temperatures. Also, the temperature of a part may need to be specified for verifying some critical dimensions at that temperature if tolerance on the dimension is less than ±0.0002″.



FIGURE 22-14 *Fatigue considerations.*

DECISION TABLE

Criteria	Weighting Factor	Walk	Bike	Bus	Car
$	10	10 100	7 70	6 60	4 40
Protection from weather	7	3 21	2 14	7 49	8 56
Time spent	6	2 12	5 30	4 24	6 36
Safety	3	7 21	6 18	9 27	8 24
Reliability	8	9 72	8 64	6 48	7 56
		226	**196**	**208**	**212**

FIGURE 22-15 *Decision table.*

Prepare a *decision table* to systematically compare each solution alternative with every other alternative as to how well each one satisfies the constraints and specifications from the definition of the problem in Step 3.

An example decision table is shown in *Figure 22-15.* Although the example is simple, and was made up for illustration purposes, the procedure is the same

for more complex analyses. The example is based on the question to a class, "Which alternative for transportation to and from school for a distance of five miles (10 miles round trip) is the best one?" The class was asked to create a decision table for a quantitative evaluation of four transportation alternatives, walk, bike, bus, and car. First, a list of criteria was generated and tabulated in the left-hand column. Next, each criterion was compared to every other criterion and was given a weighting factor for its relative importance according to the students.

The four alternatives then were systematically compared against each other for each criterion. First, the expense criterion was considered. Walking was the least expensive, so it rated a score of 10 as compared to a car, which was given a 4. Biking and bussing scored 7 and 6, respectively.

After the four alternatives were compared in relation to each criterion, products of the weighting factors and the scores were totaled for each alternative. Walking scored the highest; therefore, walking would be the alternative to investigate and develop further. The bus and car are close contenders and should also be looked over once more.

To evaluate solution alternatives in a design project, list the constraints and specifications in the left-hand column and give them weighting factors. Then list the alternatives across the top. Compare and rate every alternative with the others for each constraint and specification.

Finally, compute the products of the weighting factors and the alterative scores, total the products for each alternative, and select the alternatives with the higher totals for further study.

Finally, select the best one, realizing that it is the best for the time available, the information collected, and the judgment of the group. Even though it is difficult to do, a decision must be made so that the project stays on schedule.

Schedule a design review next.

Step 8 Conduct a Design Review.

a. *In-House Design Reviews.* Prepare drawings, transparencies, slides, models, and appropriate documents to effectively and efficiently communicate the design solution to the attendees.

In a classroom, present sufficient information so that the students in other groups will ask thoughtful questions and make helpful comments. The goal of the review is to benefit from the collective expertise of classmates and to be sure that all facets of the design have been considered.

The instructor may be the only nonstudent present, as clients usually do not attend. Also, the instructor may schedule more than one design review throughout the project or may have conferences with each group.

During the design review, have someone record the questions and comments for modifying or reassessing the solution soon afterwards.

An in-house design review in industry is more comprehensive because, in addition to technical personnel, representatives from accounting, finance, sales, management, manufacturing, shipping, and installation may be present. Furthermore, the design solution discussed may involve a variety of products or an entire complex system.

b. *Outside Design Reviews.* An outside design review provides information to the client at a location selected by the client. Often, the main objective of an outside design review is to "sell" ideas to a client, whether the client is a private citizen, a private company, or a governmental organization. Companies and governmental organizations publish requests for bids or proposals on a variety of projects, such as aircraft, spacecraft, dams, highways, buildings, chemical processes, electronic devices, electrical systems, power plants, vehicles, military devices, ships, submarines, and numerous products. The bidding individual or proposing organization prepares an outside design review, and if the bid or proposal is accepted and a contract is signed, the bidder starts a new design process in more detail than the one leading to the outside review.

Students may give outside design reviews to a client as progress reports; however, most classroom projects require only in-house design reviews that lead to the final solution.

Step 9 Refine the Final Solution. Review the questions, comments, and suggestions recorded during the in-house review and decide which ideas to incorporate in design changes or additions. Revise previous steps if necessary; however, time constraints dictate that the next phase should be started soon.

Phase IV Document, Specify, and Communicate the Solution

STEP 10 Prepare Drawings and a Written Report

STEP 11 Give an Oral Presentation

In classroom projects, Phase IV requires about one-half of the time available. Moreover, most classroom projects end with Phase IV because of limited time, limited shop facilities, and limited funds.

In industry, Phase IV and Phase V overlap, and together they consume approximately one-half of the time available.

Step 10 Prepare Drawings and a Written Report. Use the informal development layout drawings for preparing the formal technical detail and assembly drawings in standard views, lines, dimensions, and symbols. Only those parts that require shop processes are detailed in technical drawings. Parts—such as fasteners, keys, and pins—that do not require shop processes only appear in the parts list of the assembly drawings. Purchased components such as motors, switches, and bearings appear in assembly drawings in the parts list and are usually drawn in outline form.

Four examples of technical detail drawings of components to be made in a shop are shown in *Figure 22-16* and *Figures 22-17 A, B,* and *C*. Figure 22-16 is a subassembly of structural steel parts, welded together for use in the anchor bolt puller. Figures 22-17A, B, and C show several individual components. *Figure 22-18A* (page 860) is an assembly drawing with a parts list (*Figure 22-18B,* page 861) for the complete anchor bolt puller. Note that the subassembly from Figure 22-16 is given only one part number in the assembly drawing parts list.

Logical Dimensioning. Design components so they can be measured readily and logically—for two main reasons. One, shop personnel need to locate points, planes, and features such as holes from reference planes or surfaces. Two, the function of the component needs to be ensured.

Shop personnel use a large number of measuring devices, some very sophisticated, some relatively simple, but all measure from a reference plane or surface that is usually machined. Some of the more common measuring devices and their measuring capabilities are:

a. Flat, stainless steel scale: to 0.010″
b. Micrometer: inside and outside: to 0.0002″
c. Vernier calipers: inside and outside: to 0.001″
d. Lathes, milling machines, shapers, boring machines, and gear cutters with calibrated dials to indicate the movement of the cutting tool or the part being machined: to 0.0005″
e. Some newer milling machines and numerically controlled machines with electronic readouts: to 0.0001″

Engineers, designers, and drafters can facilitate these shop processes by dimensioning components from obvious reference planes or surfaces. The plane or surface may need to be created in the manufacturing process.

Ensure the function of a component or an assembly of components by dimensioning to common reference planes or surfaces. An example to illustrate reference



FIGURE 22-16 *Technical detail drawing of subassembly.*



FIGURE 22-17A *Technical detail drawing of a spacer.*



FIGURE 22-17B *Technical detail drawing of a support plate.*

planes is shown in *Figure 22-19.* The two identical L-shaped brackets are cast iron. Surface no. 1 is milled to establish a plane of reference to locate vertical surface no. 2 to be perpendicular to surface no. 1. Then, the hole at no. 3 is machined perpendicular to surface no. 2 (and hence parallel to surface no. 1) so the shaft for the roller will be horizontal. The two holes in the bracket would probably be located with respect to vertical surface no. 2 and centered about the center line of the machined hole, surface no. 3.



FIGURE 22-17C *Technical detail drawing of an angle stop.*



FIGURE 22-18A *Assembly drawing of anchor bolt puller frame.*

A more exact dimensioning technique called positional tolerancing and form tolerancing (or geometrical tolerancing) establishes datum surfaces for referencing dimensions and features. The technique requires more skill and time to apply; however, time and money are saved because fewer parts are scrapped. They fit better and their function is assured.

This tolerancing technique has grown as machines and systems have become more complex and expensive. Furthermore, when one company manufactures components that will be assembled together with



FIGURE 22-18B *Parts list for anchor bolt puller*



FIGURE 22-19 *Reference plane for dimensioning.*

components from another company, the dimensioning and features need to be accurately located so the components will go together. Refer to Chapter 12, Geometric Dimensioning and Tolerancing, for detailed information.

Technical detail and assembly drawings in industry are similar to the anchor bolt puller drawings, but with several differences. Complex drawing-numbering systems tell the user which ones are details, where individual components are used, which ones are assemblies, and which job or contract used the drawings. These systems are as varied as the number and size of industries and organizations. (Refer to Chapter 17.) Usually the drawings are on larger sheets. Also, each individual part needing to be processed in a shop is detailed separately to accommodate accounting procedures and to merge into the flow of information within the company.

Design Hints

Use *design hints* during all phases of the design process as extensions to the design hints already included. These design hints help in initial designing and become checklists as the project progresses. Keep a file during design problem experiences to expand these lists, and remember: CARRY A NOTEBOOK AT ALL TIMES!!!

Attribute Listing for Checking Drawings. Use the technique of *attribute listing* as a systematic guide for checking the completeness of technical detail drawings. For example, ask the following questions:

a. What is the function? The function dictates the dimensioning plan.

b. What size is it? Are all geometrical shapes dimensioned? Are all the features located?

c. What materials are used?

d. Can it be made? How will it be manufactured? What processes will be used?

e. What other facets need to be checked? Surface finish? Weight? Vibration? Safety? Aesthetics?

"Rules of Thumb." Use "rules of thumb," practical guides based on experience, to establish or check "ballpark" (within +1 or –10%) quantities. Use them as qualitative checks.

a. *Tolerance.* As a beginning problem solver in technical fields, keep in mind that the tighter the tolerance on the dimensions of an object, the more the object costs. Tolerances should only be as tight (small) as needed to ensure the function of the part. Use as a conceptual reference the thickness of the paper this sentence is written on: It is .003″ to .004″ or 0.08 mm to 0.10 mm thick. Most machinists and machines can easily work to .001″, but .0001″ takes more time and costs more.

b. *Rigidity.* "When in doubt make it stout." This statement is just a reminder that not all designs need to be based on an extensive stress analysis and strength of a material. Rigidity and accurate locations may be more important than strength. For example, a surveyor's transit needs to be rigid to keep the lenses aligned. Instrument panels need to be rigid to support the dials and meters and to prevent vibration. Another practical application of the statement refers to sizing members when budgets are low. That is, a brief stress analysis producing a conservative size (stout) is less expensive than an extensive analysis and a more exact size.

c. *Murphy's Law.* "Anything that can go wrong will go wrong." Use this guide to evaluate how a designed part or assembly might behave. A more important application is to ask, "How could someone misuse the part or assembly?"

d. *Weld Size.* Fillet and butt welds constitute approximately 85% of all welds used in industry. And if the thinnest cross-section dimension of the weld is at least as thick as the thinnest member joined, the weld will be as strong as the members, assuming that the weld is done by a skilled welder.

e. *Threads.* The depth of threads for steel threaded fasteners should be equal to the diameter of the fastener. Use 1.5 to 2.0 times the diameter for the depth of threads for non-ferrous threaded fasteners, or steel fasteners in non-ferrous metals.

f. *Intuitive Ranges.* Early in a design, establish sizes by asking what would be a reasonable range for this size. Establish performance, weights, and function in a similar manner. During an analysis, ask questions such as: Is this a reasonable size? Weight? Function? Performance?

Prepare a written report for the client. Although each client's needs in a report differ, the parts of reports are similar and all the parts should be included. The order is arranged to suit the information to be communicated.

Use the following discussion as a guide for preparing professional, typed project reports to clients. Refer to samples from a student group's report later in the chapter.

a. *Letter of Transmittal.* A letter to the client, separate from but enclosed with the report, saying that the project has been completed, the report is enclosed, and that working with the client on future projects is anticipated. Fee statements may be a part of the letter. Include phone number(s) where the client can call for questions, and an address for mailing fees.

b. *Cover.* Enclose the report in a folder, unless otherwise directed.

c. *Title Page.* Include title, by whom written, to whom submitted, date, and organization (college or company).

d. *Abstract.* Include one or two sentences about the content of the report to capture a potential reader's interest. For product designs, describe the product, specify its performance, and give the cost or price.

e. *Table of Contents.* List the main headings and the subheadings, with appropriate page numbers. List the illustrations, drawings, and tables, plus an appendix if used.

f. *Introduction.* Describe briefly—who, what, when, where, and why—the origin of the project/problem, because even though the client knows this information, other members of the client's organization—who may not—might read the report.

g. *Solution Description.* A written portion should use a liberal number of headings and subheadings and should describe the final solution, including the performance specifications and the design specifications. List the constraints, costs, materials, and special features. Also include the delivery date. Refer to illustrations, figures, charts, graphs, and drawings for efficient communication.

h. *Analyses.* Summarize the major assumptions and calculations. Place detailed *analyses* in an appendix.

i. *Costs.* For a classroom project, which usually ends with Phase IV, list the basic direct costs that the client would have to outlay to have the design made. These costs could include materials, shop labor, and a number of purchased components—fasteners, pins, shafts, switches, controls, electronic circuits, motors, and similar hardware. Even if the classroom project continues through Phase V and a prototype is built, the client will most likely be required to reimburse the students **only** for the actual expenses incurred. The excellent learning experience is payment for the students' labor!

In industry, only the selling price would be given in the report because the basis for arriving at the selling price (labor rates, material costs, overhead, sales, and profit margin) would be proprietary information.

j. *Drawings.* Include the technical assembly drawings in the main report, and the technical detail drawings in an appendix. Pictorial drawings (isometric, oblique, or perspective) may also be appropriate, depending upon the client's technical experience and background.

k. *Illustrations, Figures, Charts, and Graphs.* Check the illustrations, figures, charts, and graphs for complete information. Each one should have a legend. In addition, charts and graphs should have clearly marked and labeled axes.

l. *Alternatives.* Convince the client that a thorough investigation was done by the design group by including a brief summary of the *alternatives* that were considered but discarded. Use partially dimensioned sketches, drawings, and pictorials with appropriate comments as to why the alternatives were not selected.

m. *Recommendations.* Discuss briefly any recommended further developments or investigations that relate to the project. For example, one of the discarded alternatives may have some potential and should be investigated further.

n. *References.* List references and the specific pages that were used. Number the references, and use these numbers in the text of the report.

o. *Appendices.* Place information in the appendices that does not logically fit in the main report. Such information includes extensive calculations, computer printouts, vendor brochures, catalogs, machine copies of referenced material, and technical detail drawings.

In industry, when a company or organization wants to "sell" its expertise to clients it includes a roster of individuals, indicating each individual's technical skills, education, and experience. A summary of projects completed by the company may be included.

Most organizations have an established format for their reports. A number of companies and organizations use computers to store boiler plate information that appears in all of their reports. Standard paragraphs and phrases appear at the beginning and at the end of their reports—hence, the wrap-around image of a boiler. New material fills the blanks.

Rewrite the report text at least two times, whether a classroom report is being prepared or one in industry! Check for completeness. Check grammar, punctuation, and style. Avoid clichés. Eliminate unnecessary words.

Step 11 Give an Oral Presentation. Prepare an *oral presentation* of the design solution to the client. The following guidelines for planning a presentation apply to student presentations as well as those done in industry.

a. For a simple, but effective presentation, first tell the audience **what is** going to be presented. Then, present the material. Concluding, tell the audience **what was** presented.

b. Make projected words and numbers large enough so everyone can read them. A conservative guide is to make the letters on the screen as high as 1/250 of the distance to the person the farthest away from the screen. Thus a 25-meter distance requires letters on the screen to be 0.1 meter high. Typed material reproduced on transparencies is usually unsatisfactory.

c. Restrict the number of different ideas on a visual to five or less. If more are on the transparency, distribute a copy to the audience beforehand.

d. Use a pointer.

e. Use models large enough to be seen easily.

f. PRACTICE at least once. One or more persons can do the presentation.

g. Allow time for questions.

In industry, a final oral presentation made to a client at the end of Phase IV could be done by a consulting-type firm whose final "product" consists of engineering drawings and a written report.

Oral Presentations. Public speaking is an important skill for engineers, designers, and drafting technicians.

During the design process discussed in this chapter, oral presentations are scheduled at least two times, the design review and the final presentation. As a guide for giving these two presentations, and others, use the following three practical steps noted earlier.

1. Tell them what you're going to tell them.
2. Tell them.
3. Tell them what you've told them.

Further guidelines are in the exercises at the end of the chapter.

Phase V Develop, Manufacture, and Deliver

STEP 12 Prepare Technical Detail Drawings of Each Component to Be Manufactured

STEP 13 Schedule Assembly, Final Testing, Packaging, and Delivery

STEP 14 Keep Records

Arrange for the necessary paperwork, drawings, materials manufacturing processes, personnel, and funds to develop the device or system to meet the client's requirements.

These requirements may range from modifying an existing device to producing a state-of-the-art system. Thousands of different combinations of requirements occur in industry, so describing them all here is impractical. Consequently, a more appropriate task for this chapter is to present the steps that are common to most industries.

Step 12 Prepare Technical Detail Drawings of Each Component to Be Manufactured. These drawings "get the wheels turning" within a company. A typical drawing enclosed in a clear-plastic folder may follow the component through a manufacturing area from casting or forging, to machining, to heat treating, to finishing, to assembly and delivery. Additional areas could include checking, quality control, subassembly, and temporary storage.

Step 13 Schedule Assembly, Final Testing, Packaging, and Delivery. Plan the final processes prior to sending the product to the client. Compare appropriate subassemblies and complete assemblies with the specifications, particularly performance specifications. For example, an electronic device may be tested in a variety of environments before being released for shipment.

Design packaging and shipping containers so that the product will survive shipping without damage. Some devices and assemblies must endure more severe loading enroute than after being installed—for example, large frames, large cylindrical-shaped housings, and pressure vessels.

Write maintenance and service manuals to help prolong the life of the product. Provide instructions for proper and safe use of the product.

Step 14 Keep Records. Document and file all aspects of the product's development and use. Record the sources and quality of materials used. File the detail and assembly drawings. Summarize the manufacturing processes, and prototype testing results. Add feedback comments from the client. Request cost, accounting, purchasing, and related records from appropriate personnel.

These records are useful for future use if the client wants replacement parts or another complete product. Also, other customers may purchase the product.

Drafters in Industry. Technical drawings were discussed in detail for Step 10 of Phase IV, primarily because student projects usually end with detail and assembly drawings. Drafters in industry would most likely do the detail and assembly drawings during Step 12 of Phase V. The difficulty of their drawing assignments would vary, depending on their experience.

Newly hired drafters soon find that in industry there are a number of sources of assistance. Colleagues in the drafting room can be very helpful by showing new members where to find information on previous jobs done by the company—things like where catalogs are filed, which CDs are available with vendor information, who to contact in the shop for fabricating and assembly practices, and where to have their drawings printed, plotted, and filed.

Experienced drafters not only do the technical drawings, but they become involved in designing. They develop ideas using layout drawings, solid modeling on computers, and frequently use cardboard, glue, and balsa wood to verify their ideas.

Two types of projects for students who are learning the design process are discussed next.

Design Projects: Routine and Non-Routine

Routine Design Problems

Routine design projects and problems are used to introduce new members of an organization to the

various people in the company and to the routes design information needs to flow through. Beginning engineers, designers, technologists, and drafters need to know how jobs are initiated, documented, processed, and completed. An effective way to start these new employees is to assign routine projects and problems to them.

These first assignments usually are assigned to an individual and are characterized as follows:

a. The problem may be a modification to an existing product line, a change in the company's plant facilities, or just a drawing change.
b. The problem difficulty matches the individual's abilities and skills.
c. Information is communicated in a memorandum in a typical industrial format, such as an ECO (engineering change order) or an EDO (engineering design order).
d. Requirements are clearly stated and the information is nearly complete; however, some new data may be needed.
e. An analysis may be required.
f. For guidance, there are similar designs, knowledgeable colleagues, the company library, and vendor catalogs.
g. Technical drawings are required; they become part of the documentation of the modification or change.
h. Labor and materials costs are always present.
i. A condensed design process is followed; however, all the essential steps are followed, including planning, keeping a log, keeping a file, understanding the problem, synthesis, analysis, comparing alternatives, reviewing designs with supervisors, documenting the project in drawings and text, manufacturing, assembly, and installation.

An example first assignment that a newly graduated engineering student received in an EDO was to design a support for a tank containing a liquid for a papermaking process. But before resolving the technical parts of the support, the new engineer, escorted by the chief engineer, was introduced to personnel in drafting, purchasing, the shop, and the papermaking area where the tank was to be installed. Further introductions included individuals in general supplies, copy service, and even those who made coffee.

The technical challenges involved load calculation, sizing beams and columns, and finally, making a design development layout drawing. The chief engineer was consulted before the layout was handed to a drafter. The drafter questioned a few items and then produced technical detail drawings plus an assembly drawing.

The new engineer checked, approved, and signed the drawings. Then he followed them through the shop and ultimately used the drawings at the installation site.

The last step was to document the project. The drawings and vendor information were filed. A short written report summarized the need for the tank support, and a copy of the EDO was included. Cost information from the accounting department completed the file.

Non-Routine Design Problems

Non-routine design problems are assigned to experienced engineers, designers, technologists, and drafters—their complexity and level of difficulty in direct proportion to the experience, skills, and ability of the recipients. Usually a team of technical personnel attack non-routine design problems.

Non-routine design problems are characterized as follows:

a. The problem originates outside the company, and it stems from the needs of a client who may be an individual, another company, or a governmental organization.
b. A team of individuals with diverse backgrounds or a group with similar backgrounds is formed, depending on the experience, skills, and abilities required.
c. The problem, not clearly defined, must be researched thoroughly so that constraints and specifications can be written.
d. A complete design process, with phases and steps, is required, from the initial planning to the final delivery and installation. More alternatives are generated than for routine problems, and, therefore, more decisions are made.
e. The projects require a longer time span than routine projects.
f. Detailed planning is required for personnel assignments and hours, materials procuring, budget allocations, production processes, and delivery/installation.
g. More engineering trade-offs occur. A *trade-off* is a compromise, usually between costs and materials. For example, an expensive material (titanium) may cost more but weigh less than a less costly material (aluminum) that weighs more.

Since non-routine design problems vary as widely as the number and size of problem sources—individuals to organizations—there are no typical non-routine problems. However, the manner in which they are attacked—the design process—is typical. Therefore, follow the phases and steps presented in this chapter to obtain an insight into the efficacy of this process. Then, formulate your own design process as needed.

Examples from a student team member's log, the team's planning chart, and the team's project report are included here for your information. The challenge given to the student team from a doctor was to design a device that would exercise the muscles of a patient's jaw continuously, day and night, to accelerate healing of the jaw muscles after an operation.

The following lists some of the more important aspects of the step process just described. Use it to review the art that follows.

- Log (Step 1) **Figure 22-20**
- Planning Chart (Step 1) **Figure 22-21**
- Information from the Client (Step 1) **Figures 22-22A, B, and C**
- Progress Report (Step 4) **Figure 22-23**
- Letter of Transmittal (Step 10) **Figure 22-24**
- Title Page and Abstract (Step 10) **Figure 22-25**
- Table of Contents (Step 10) **Figure 22-26** (page 870)
- Introduction (Step 10) **Figure 22-27** (page 870)
- Power Pack Assembly Sketch (Step 10) **Figure 22-28** (page 871)

TIME LOG	W. PETERSON		
	TEMPOROMANDIBULAR JOINT FLEXOR		
DATE	ACTIVITY	TIME HR	CUM. TIME HR
10-2	Met with Anderson, Bui, Hamamoto- - Exchanged phone numbers - Copied Dr. P's proposal	½	½
10-8	MET - KA MB & AH - discussed proposal - made up questions for Dr. P Discussed planning chart	2 ¾	3 ¼
10-10	Questions for Dr. P MET at Dr. P's Office in MED SCHOOL	2 ½	5 ¾
10-15	Discussed electrical circuits w/ MB	¼	6
10-17	MET w/ group, checked drawings/ went to hobby shop for solenoids Worked on progress report w/MB Typed progress report	2 ¼	8 ¼
10-20	Talked to Mike Wieggand re: valves Group meeting	2	10 ¼
10-30	Contacted vendors for bellows information Prepared transparencies for DESIGN REVIEW - worked with Hamamoto	3	13 ¼
11-1	Trip to surplus yard — found plastics	2 ½	15 ¾

FIGURE 22-20 Log

PLANNING CHART

TEMPOROMANDIBULAR JOINT FLEXOR

K. Anerson — M. Bui — A. Hamamoto — W. Peterson

ACTIVITY	WEEK 1	2	3	4	5	6	7	8	9
PHASE I		MB							
Get Organized	KA								
Client/Meeting		AH							
Information Search		WP							
Project Define		WP				◉ MILESTONE			
Progress Report			MB ◉						
PHASE II				KA					
Generate Alternatives					KA				
PHASE III					AH				
Analysis/Evaluation					AH				
Layout Drawings					KA				
Decision					MB				
Design Review					AH ◉				
Revise Final Solution						WP			
PHASE IV							WP		
Final Analysis							MB		
Materials							MB		
Rough Draft of Report						WP			
Drawings – Detail Assembly							AH		
Model							KA		
Oral Presentation									KA ◉
Final Written							WP		◉

FIGURE 22-21 *Planning chart for student group.*

PRELIMINARY DESIGN CONSIDERATIONS

1. SIZE — Date 10-10
2. POWER
   - –BELT POWER PACK
   - –CHARGER
3. CONTROLS
   - –FREQUENCY
   - –OPENING
   - –PATIENT OR DR.?
4. EXPECTED PRODUCTION
   - –REUSABLE?
5. COST
6. MATERIALS
   - –STAINLESS
   - –PLASTIC
   - –FDA RESTRICTIONS
7. NOISE LEVEL
8. FORCES REQUIRED
   - –OPENING
   - –CLOSING
9. SAFETY OVERDRIVE
10. JAW DIMENSIONS
11. ACCURACY

FIGURE 22-22A *File: Preliminary design considerations.*



Date 10-10

a – MAXILLARY ACRYLIC SPLINT
b – MANDIBULAR ACRYLIC SPLINT
c – BUCCAL TUBES
d – UPPER MEMBER
e – LOWER MEMBER
f – PNEUMATIC PISTON
g – UNIVERSAL JOINTS

FIGURE 22-22B *File: Information from clients.*

- Alternatives Discarded (Step 10) **Figure 22-29** (page 872)
- Final Recommendations (Step 10) **Figure 22-30** (page 873)
- Appendix: Materials, Electrical Schematics, and Costs (Step 10) **Figures 22-31A, B, and C** (pages 873–874)



FIGURE 22-22C *File: Information from clients.*

Modern Design Practices and Standards

Drafters, designers, and engineers entering technical industry today will find that the adjective "changing" describes current technology better than any other word. A number of these ongoing changes are described briefly in the following paragraphs.

One trend in industries that manufacture devices is to develop prototypes earlier in the design process than in previous years. Two terms describing this trend are *rapid prototyping* and *virtual prototyping*. Stereolithography (SL), mentioned earlier in this chapter, is a rapid prototype builder. SL involves building a solid model layer by layer by an electronic-laser process that uses data from 3-view

Date 10-10

Department of Mechanical Engineering
(School)
(City, State, Zip Code)

Dr.
University Hospital
(City, State, Zip Code)

Dear Dr.,

This letter is to inform you of our design team's progress and decisions regarding your CPM (continuous passive motion) device. We have discussed the design criteria set forth in your proposal and also examined the additional criteria we discussed with you at our last meeting. Presently, we are considering the feasibility of a pneumatic device with an external power pack. We are currently evaluating this concept and its ability to meet the following criteria:

1) Weight: less than 4 oz
2) Accurate and adjustable movement
3) Frequency in the range of 2–3 cycles per minute with a maximum range of 1–4 cycles per minute
4) Device must be safe for use by a 10-year-old and older for 24 hours at a time
5) Operation must be simple (few moving parts and adjustable by anyone who can read and understand simple directions)
6) Low cost (less than $500, including labor and materials)
7) Parts must be readily available (most from local sources)

Based on our pending evaluation of the above, we will pick what we feel is the best design, and prepare a report outlining our choice. Included in the report will be a cost analysis, detail and assembly drawings, and an overall evaluation. This report will be presented to you at a date and time decided by our instructor.

If you have any questions, please contact us through our instructor.

Sincerely,

W. Peterson

K. Anderson

M. Bui

A. Hamamoto

FIGURE 22-23 *Progress report.*

Date 12-6

Department of Mechanical Engineering
(School)
(City, State, Zip Code)

Dr.
University Hospital
(City, State, Zip Code)

Dear Dr.,

This letter is to inform you that we have completed our design for a CPM device to be used in your research project. The enclosed report details the design, giving complete drawings, a cost analysis, and future design considerations.

The design is now ready for the prototype stage.

We are pleased to have had the opportunity to work on this project for you, and we hope we will be able to work with you more in the future.

Sincerely,

W. Peterson

K. Anderson

M. Bui

A. Hamamoto

FIGURE 22-24 *Letter of transmittal.*

DESIGN PROJECT: TEMPOROMANDIBULAR JOINT FLEXOR

SUBMITTED TO: DOCTOR

DEPARTMENT OF ORTHODONTICS
UNIVERSITY MEDICAL SCHOOL
(CITY, STATE, ZIP CODE)
Date 12-6

BY: W. PETERSON
K. ANDERSON
M. BUI
A. HAMAMOTO

ABSTRACT

This report contains a description of a continuous passive motion (CPM) device to exercise the temporomandibular joint (TMJ). Briefly, the design incorporates the use of two compressible bellows that are connected by an air hose. While one of the bellows is compressed at a controlled rate, the other bellows expands at a controlled rate. The system is based on user feedback and provides for excellent emergency override, which is essential for safe use. The device costs less than $200.

FIGURE 22-25 *Title page and abstract.*

drawings. A more recent rapid process uses data from MRI (magnetic resonance imaging) examinations to generate plastic prototypes of human joints that need to be replaced. Doctors use the prototype models for guidance during operations; the data is used also for developing the metallic versions of the joint. This overall process is so accurate that the replacement joint needs little or no modification before installation.

An example of virtual prototyping requires a special head-mounted viewer and a hand-mounted positioning monitor for prototype development of a

TABLE OF CONTENTS PAGES

INTRODUCTION 1

SOLUTION/DESCRIPTION . . . . . 1 – 3

COSTS . . . . . 4 – 6

DRAWINGS . . . . . 7 – 25

ALTERNATIVES . . . . . 26 – 29

FINAL RECOMMENDATIONS . . . . . 29 – 30

REFERENCES 31

APPENDIX 1 Delrin Properties

APPENDIX 2 Analysis of Air Flow, Stress Analysis

APPENDIX 3 Vendor Catalogs

FIGURE 22-26 *Table of contents.*

INTRODUCTION

This project stems from a graduate research project in the department of orthodontics. Studies have shown that the continuous passive motion (CPM) on joints such as knees, elbows, and fingers have proven to be quite successful in alleviating post-operative pain, swelling, and adhesions. It is the Doctor's hopes as well as ours that a similar application of this research on the temporomandibular joint will prove to be equally successful. Our task was to develop a device that would work the jaw up and down to a controlled distance in a slow cyclic manner and at the same time provide a maximum in safety. It was also necessary to use feedback switches to control the inflating and deflating of a bellows that opened and closed the jaw of the patient so that any irregularities or overwhelming resistance to CPM by the individual (sneezing, coughing, yawning, etc.) will immediately be sensed by the system and the necessary override would be provided automatically.

FIGURE 22-27 *Introduction.*

backhoe cab. The person wearing the viewer (probably the customer) can visualize the cab of the machine and the positions of the controls before the backhoe is built. Prior to virtual prototyping, expensive wood models of the cabs were constructed.

Additional rapid prototyping methods include:

- *Fusion Deposition Modeling* involves controlled placing of low-melting-point thermostatic filament to build up a model.
- *Laminated Object Manufacturing* builds models by fusing layers of plastic-coated papers cut out by a computer-controlled laser.
- *Selective Laser Sintering* prepares "slices" of an object using fused granules.
- *Solid Ground Curing* uses slices or layers of polymers to build models.

Another trend known as *parametric design* allows drafters and designers to change dimensions in three-dimensional computer models and have all affected dimensions change accordingly. Also, design parameters such as beam sizes, shaft diameters, the number of coils in a spring, and so on, would be modified to suit the dimension changes.



FIGURE 22-28 *Power pack assembly sketch.*

An international trend may affect your future job assignments. The desire of companies—both domestic and international—to sell their products in international markets created a need for international standards to ensure consistent quality and performance. To participate and be internationally competitive, your company must obtain certification based on ISO 9000 of the International Standards Organization. Your involvement will most likely be in the technical drawing documentation for certification. Each company must document clearly what it plans to do and then keep copious records to show that it has carried out its plan. An excellent treatise on this subject is *Understanding and Implementing ISO 9000 and ISO*

ALTERNATIVES CONSIDERED AND DISCARDED

1. Pneumatic Cylinders as Actuators
   Advantages:
   ..small in size
   Disadvantages:
   ..limited control of expansion rate
   ..higher working pressures, noise
   ..difficult to find stroke and size in standard products
   ..lubrication may be a problem
   ..allows minimal user resistance

2. Source of Compressed Air: Bottle and Intricate Valving
   Advantages:
   ..power pack simple and light-weight
   ..no batteries
   ..volume of air easily varied
   Disadvantages:
   ..complicated valving
   ..supplying air bottles cumbersome
   ..compressor needed to charge bottles
   ..noise
   ..difficult to get emergency override

3. Motor-Driven Cam and Linkage
   Advantages:
   ..simple to construct
   Disadvantages:
   ..difficult to interrupt
   ..excessive weight
   ..bulky, physically restrictive
   ..little adjustment
   ..little freedom of jaw movement (patients need rotation, translation, and lateral movements)

FIGURE 22-29 *Alternatives discarded.*

Standards, Goetsch and Davis, 1998, Prentice Hall. The authors digested a somewhat confusing set of ISO standards and substandards and have derived a comprehensive checklist to guide companies seeking registration to and through the proper standards.

Coupled with promoting the requirements of the ISO standards is another trend toward encouraging companies to develop a philosophy of TQM (Total Quality Management). Preparing a company for ISO 9000 certification and developing a TQM philosophy is somewhat similar to the phases in the design process. The planning, preparation, and execution phases in the Goetsch and Davis text involve defining the problems, generating solutions, evaluating them, selecting the best ones, and then implementing them.

An interesting trend in teaching technology has evolved from an industrial practice of thoroughly investigating competitive products by dissecting them and studying the components. Some schools call this procedure *reverse engineering.*

Several trends maturing in past decades involve companies that mass-produce products. Two of the trends, discussed in detail in Chapter 17, are outlined briefly in the next section. Then, two more recent trends are noted.

Design for Manufacturability (DFM) and Design for Assembly (DFA)

Design hints for DFM include goals such as the following:

- Minimize the number of parts.
- Minimize part variations.
- Design parts for more than one function or use.
- Design parts for ease of manufacturing.
- Use fasteners that handle easily and can be readily installed.
- Arrange assembly of parts so they assemble in layer fashion.
- Avoid flexible parts.

These goals are discussed early in the design process in meetings where not only designers, drafters, and engineers attend, but manufacturing

FINAL RECOMMENDATIONS

ASSUMPTIONS

It is important to note that any state-of-the-art design is subject to change since so many variables, having no cut-and-dried answers, must be dealt with, and values must sometimes be assumed using good engineering judgement. Some of the variables in this design project include average mouth dimensions, forces to open and close the jaw, allowable weights for the mouthpiece and powerpack, influence of an oversize solenoid valve on battery life, and so on.

PROTOTYPE

The presence of these types of variables strongly implies a need for prototype testing to see if the actual design concept is valid. A second type of testing might be called human factor testing, which involves sizing and comfort factors. Are the dimensions on the mouthpiece satisfactory to accommodate an average-size person? Is the size of the powerpack cumbersome? Are weights unbearable? Are jaw movements restricted?

SOLENOID

It was previously mentioned that the specific solenoid valve was oversized. At this point in time the valve is the smallest one made. Because of its power consumption, which is excessive (7 watts max), the battery must be extraordinarily large. It is hoped that eventually a smaller solenoid valve could be purchased or even designed to be much more economical. This could drastically increase battery life and decrease battery size, ultimately decreasing the size of the powerpack.

CNC LATHE

From a manufacturing viewpoint it is recommended that the prototype have all its plastic parts machined on the CNC lathe, since molds are expensive as used in injection molding. However, if the device is ever mass produced, it is recommended that injection molding be the way to go, since production would be much faster, decreasing labor costs per unit.

FIGURE 22-30 *Final recommendations.*

APPENDIX NO. 1

DELRIN

The material chosen for the mouthpiece is Delrin. Delrin is a trade name for an acetal homopolymer. It was chosen because it has many desirable characteristics. Some of the advantages of Delrin are:

1) Good chemical resistance, especially to organic compounds

2) Desired regulatory status:
   a) FDA approved for intermittent contact with aqueous or alcohol-based foods
   b) USDA approved for meat and blood

3) Can be machined like soft brass

4) Can be welded or adhesively bonded

5) Forms good mechanical joints

6) Has good structural integrity

7) Tensile strength (at break) 9700 psi

8) Yield strength 9500 – 1200 psi

9) High impact resistance

10) Rockwell hardness 92 – 94

FIGURE 22-31A *Appendix: Material.*



FIGURE 22-31B *Appendix: Electrical schematic.*

personnel participate also. Design hints for DFA include goals such as the following:

- Use "pick-and-place" robots for simple, routine placement of parts.
- Keep the number of parts to a minimum (DFM guideline also).
- Use gravity and vibration for moving parts into assembly areas.
- Avoid parts that may tangle (hang up on each other).
- Use tapers and chamfers to guide parts into position.
- Avoid time-consuming manual operations such as screw-driving, soldering, and riveting.

These goals are also discussed early in the design process in the same engineering and manufacturing meetings previously noted.

Designing for Recyclability (DFR) and Designing for Disassembly (DFD)

Recently, a large manufacturing company that produces automobiles, several companies that produce large appliances, and one large company that produces

QUANTITY	PART NO.	DESCRIPTION	COST
1	NP8-6	Yuasa Battery	$29.55
1	BC-3B	Yuasa Charger	$5.39
1	B11DK 040	Skinner Solenoid Valve	$33.00
1	1615 900-1	Mini Motor (9 rpm) 6v DC	$50.00
1	Rel CY6-5DC-SCO	Relay (Lafayette)	$4.88
2	80511-E	SPST Momentary switch (Lafayette)	$2.94
1	ZC-10B	Fuse Holder (Lafayette)	$1.20
1	3MP10A-10	10-Teeth pinion	$6.34
1	3MP10A-40	40-Teeth gear	$8.59
1	3CCF-50-E	Min-E-Pitch Chain 55 link	$3.24
1	E-62-10K	Unimax Switch	$3.08
1	4PTN-50K	Potentiometer 50 Kohm	$1.98
1	CH3-R10	Charging Jack	$2.99
	Miscellaneous Parts, Tubing, Fittings, Screws		$30.00
		TOTAL	$183.18

FIGURE 22-31C *Appendix: Costs.*

computers have initiated programs for DFR and DFD. Their goals are to recover as much material as feasible, mainly metals and plastic, to use again. Not only are their programs economically sound, they acknowledge the fact that landfills are becoming less available, and some basic materials are becoming scarce. Both DFR and DFD programs are considered early in the design process, as are DFM and DFA. Design hints for DFR and DFD include the following:

- Mark plastic molded parts for easy identification.
- Reduce number of different plastics used.
- Make assembly easy with snap-together parts (also easy to disassemble).
- Avoid permanent attachment (adhesives) of dissimilar materials.
- Use materials that can be recycled or used in other products.

The automobile manufacturer found that recycling engine blocks, alternators, starter motors, water pumps, and differentials cut expenses significantly. A manufacturer of large appliances marks all plastic parts (over 50 grams) with an SAE (Society of Automotive Engineers) identification, which gives the type and recyclability of the parts. The computer manufacturer recycles glass and phosphorus from CRTs, plastics from housings (ground up and made into shingles), and metals from parts (steel, aluminum, and copper).

Summary

- The phases and steps in the design process are as follows: recognize and define the problem, generate alternative solutions, evaluate, document, and develop.
- Various techniques for complementing the design process are the creative process, attribute listing, decision tables, and model building.
- The technical drawings used in the design process are the same as those emphasized in Chapter 17; freehand sketches, layout drawings, and detail and assembly drawings.
- Design students should ALWAYS CARRY A NOTEBOOK to record design ideas.
- A well-written specification is written so that it can be tested or measured.
- Sources of design information include vendor catalogs, periodicals, patents, textbooks, and handbooks.
- Modern design practices and standards include DFM, DFA, DFR, DFD, rapid prototyping, parameter design, visual prototyping, ISO 9000 standards, and reverse engineering.

Review Questions

Answer the following questions either true or false.

1. A planning chart provides a visual display of when phases and steps are scheduled to begin and end.
2. One reason why a log is kept is because it could be useful on future projects.
3. Some sources of technical material are reference books, standards and codes, and catalogs.
4. Preliminary and design are the two major categories of specifications.
5. Iteration is the process of returning and revising, which occurs continually throughout the design process.
6. It is standard practice to give the first progress report when the project is 50% complete.
7. An attribute listing is a listing of characteristics.
8. Designers should carry a notebook at all times.
9. A design layout drawing is made from a freehand sketch of a design idea drawn to scale.
10. A decision table is used to determine the date the project will be completed and delivered to the client.

Answer the following questions by selecting the best answer.

1. Which of the following is **not** one of the five phases of the design process?
   a. Recognize and define the problem.
   b. Generate alternative solutions—synthesis.
   c. Evaluate solution ideas—analyze.
   d. Evaluate available time.
2. Which of the following is **not** typically a characteristic of a creative person?
   a. an open mind
   b. thinks positive
   c. pessimistic
   d. accepts change
3. Which of the following is **not** an advantage of making a cardboard-glue model?
   a. no use for the model later
   b. low cost
   c. promotes new ideas
   d. discover if the item will work as planned

4. Which of the following is **not** one of the practical steps for giving an oral presentation?
   a. Tell them what you are going to tell them.
   b. Tell them.
   c. Tell them again.
   d. Tell them what you've told them.
5. Which of the following is **not** a component of a brainstorming session?
   a. Record ideas.
   b. Criticize others' ideas.
   c. Have several sessions if necessary.
   d. Meet to critique ideas.
6. Which of the following is **not** true regarding non-routine design projects?
   a. They are usually given to experienced design project personnel.
   b. They usually require more time than routine design projects.
   c. Detailed planning is required.
   d. Fewer engineering trade-offs occur.
7. Which of the following acronyms has the **incorrect** definition?
   a. DFM—Design for Manufacturability
   b. DFA—Design for Assembly
   c. DFR—Design for Readability
   d. DFD—Design for Disassembly
8. Which of the following is **not** a reason for keeping a log of activities?
   a. for future projects
   b. for accounting purposes
   c. to track progress of the project
   d. a place to keep freehand sketches

Chapter 22 Problems

The following problems complement the design process and provide practice in understanding and learning the steps before attacking routine and non-routine design projects.

CAD Instructions

Students who plan to complete the following problems on a CAD system should begin with these general instructions. Before reading the specific instructions for each activity, go through each step in the following planning checklist. The checklist applies to any CAD system and will help ensure the optimum use of your time and resources.

1. Analyze the problem carefully. Decide exactly what you are being asked to do.
2. Determine what resources and references (if any) you will need in order to complete the problem. Collect those references and resources and have them readily available.
3. Decide if any particular standards apply to the project and have those standards available.
4. Determine what types of views will be required and how many of each.
5. Determine what the final plotted scale of the drawing will need to be, and select the appropriate paper size for plotting/printing.
6. Plan your drawing sequence. In what order will you develop the drawing (i.e., lines, features, dimension lines, leaders, dimensions)?
7. Review the various CAD commands you will have to use in order to develop the drawing.
8. Examine your CAD system to ensure that everything is in working order, then begin the project.

PROBLEM 22-1 (STEP 2)

Prepare a five-minute oral presentation on one of the following sources of information. Use transparencies for an overhead projector. Suggestions for transparencies (Tx):

Tx 1. Name of source, its location, and name of speaker.
Tx 2. Outline of the talk:
   a. description of the source and its specific location
   b. why source is useful to designers
   c. example of use of source
   d. conclusion
Tx 3. Description of source and its location.
Tx 4. Why source is useful to designers.
Tx 5. Example of use of source.
Tx 6. Conclusion.

Suggested Sources:
1. ASTI (Applied Science and Technology Index)
2. ASTM (American Society for Testing Materials)
3. ANSI (American National Standards Institute)
4. Patents
5. UL (Underwriter's Laboratory)
6. *Machinery's Handbook*
7. Handbook (instructor's or your choice)
8. Vendor's catalog

PROBLEM 22-2 (STEP 3)

Prepare performance and design specifications for one of the items in the following list. Well-written specifications can be verified by testing. For example, instead of specifying that a bumper jack will be easy to use, lightweight, and made of metal, well-written "specs" would be the following: easy to use by a licensed driver who is not handicapped, a maximum of 20 pounds of force to operate, weighs less than 10 pounds, and is made of SAE 1035 steel. Include a sketch with notes and dimensions.

1. Screwdriver for use in average household
2. Light switch in average household
3. Can opener for kitchen use
4. Knife for kitchen use
5. Pliers for electrician or average household
6. Hammer for carpenter or average household
7. Wood saw
8. Metal saw (hacksaw)

PROBLEM 22-3: (STEP 7)

Prepare a decision table using criteria and weighting factors for the situations listed. Generate at least three alternatives for each situation.

1. Vehicle for town driving
2. Vehicle for country driving
3. Vehicle for backwoods driving
4. Vacation
5. College to attend
6. Job choice in one city
7. Job choice for different locations (West Coast, East Coast, South, North, etc.)
8. Your choice

PROBLEM 22-4: (STEP 6)

Prepare a freehand sketch of a relatively uncomplicated design and then prepare a design development layout drawing of the sketched design. Draw the object to scale, but add notes and dimensions in an informal manner. No title block is needed. Complete information is required. Design suggestions:

1. Wall bracket to support object of your choice. Instructor's choice. Use welded assemblies.
2. Minor modification of a component from:
   a. This text (instructor's choice)
   b. Your choice
   c. Instructor's choice

PROBLEM 22-5 (STEP 6)

Prepare a kinematic development layout drawing of one of the assembly drawings to follow or of an assembly assigned by your instructor (Problems 22-5A through 22-5E).

Suggestions for Kinematic Analyses:

1. Redraw the figures as single straight lines to represent the linkages.
2. Construct radii about fixed points of rotation.
3. Trace, on a separate sheet of paper, the lines representing the linkages whose motions are to be analyzed.
4. Use the lines as underlays to locate the new positions.

PROBLEM 22-5A (STEP 6)

The figure to the right shows the linkages and hydraulic cylinder to operate a jet-blast deflector EF. The hydraulic cylinder AB causes linkage CD to rotate CCW (counterclockwise) about point C, which causes linkage DE to move the deflector EF in a CW (clockwise) direction. When EF is in the maximum CW position it acts as a shield for personnel standing behind jet aircraft when the jets are warming up for launching from an aircraft carrier. Determine the maximum CW angle that EF rotates and the change in length (stroke) of cylinder AB to obtain the maximum angle. Draw lines EF, DE, CD, and AB when they are in the position for the maximum CW rotation of EF.



ALL DIMENSIONS IN MM

PROBLEM 22-5B (STEP 6)

One application of a four-bar linkage is to control the movement of the hood of an automobile: a pair of four-bar linkages supports the hood. Linkage GH is attached to the hood as shown in the figure. When the hood closes, GH rotates and translates to a horizontal position. Determine the total CCW (counterclockwise) rotation of the hood from the open to the closed position. Also determine the change in length of the spring SP from the open to closed positions. Draw the lines representing the linkages and the spring in the closed position.



PROBLEM 22-5C (STEP 6)



PROBLEM 22-5D (STEP 6)



PROBLEM 22-5E (STEP 6)



PROBLEM 22-6 (STEPS 1–11)

The 19-step Kraft Mill Engineering Roadmap summarizes a design process from a company for improving or changing the company's plant facilities. A recent graduate from an engineering program sent the summary to one of her professors to show what she was doing during the first few months on the job.

Kraft Mill Engineering Roadmap

1. PROJECT SCOPE: Define the problem to be resolved, the changes that are required, and the objective to be achieved.
2. SCOPE REVIEW MEETING: Verify that both Maintenance and Operations approve of the project scope.
3. PRELIMINARY DESIGN: Select several options for consideration. Prepare rough cost estimates, sketch general layouts/schematics, and estimate R01/payback for each option.
4. PRELIMINARY DESIGN REVIEW MEETING: Select one or two options to pursue. Obtain Management's approval to proceed. Determine if project is to be capitalized or expensed.
5. SUBMIT AR OR WO: Write a cost estimate. Use class ±10%, ±20%, or ±40%, as required. Write and submit an AR (Authorization Request) or a WO (work order).
6. RECEIVE APPROVED AR OR WO: No money may be spent until approval is received.
7. DETAILED DESIGN: Make detailed layout drawings and flow schematics. Do energy balance. Develop schedule; make time-bar diagram for larger projects. Determine equipment requirements.
8. PROJECT DESIGN REVIEW MEETING: Obtain "buy off" from Operations and Maintenance of the design and layout. Verify schedule, shut-down periods, etc. Decide whether contractors or the mill will provide labor.
9. BIDS: Prepare bid package for material and for labor. Draw up a bidders list. Send to Purchasing Dept. and go out for bids.
10. REVIEW BIDS: Select the best one or two vendors for each portion of the project. Run background check on contractors. Check references of equipment manufacturers.
11. VENDOR APPROVAL MEETING: Obtain approval to purchase equipment and/or hire contractors.
12. PURCHASE ORDERS: Award bids. Write purchase orders (POs).
13. EQUIPMENT TRACKING: Track equipment as it comes into mill. Store in safe place until installation.
14. CONSTRUCTION: Install equipment.
15. PRE–START-UP: Obtain and file vendor drawings, guarantees, and instruction files. Set up spare parts in the storeroom. Write an operating manual. Develop a start-up plan.
16. PRE–START-UP: Review start-up plan. Set a start-up date.
17. START-UP: Put system into operation.
18. PROJECT REVIEW: Either hold meeting or circulate memo. Restate original project scope. Review the project. Determine that the desired objectives were (or were not) met. Discuss any problems. State final project cost.
19. PROJECT CLOSEOUT: Do necessary paperwork to close out project. Sign the WO as complete, or fill out an AR Capital Job Closure Form.

Note: Some of these events overlap. Depending on the size and type of job, some events may be deleted or some more may need to be added.

Study the 19 steps and do all or any one of the following as assigned by your instructor:

1. Prepare a planning chart assuming that a six-month period is required for a particular plant modification, and that you are doing the job.
2. Relate the 19 steps to the design process discussion in this chapter.
3. List and comment on the different people most likely contacted during the 19 steps.
4. Comment on the apparent meaning of some of the terms and acronyms: for example, scope, ROI, capitalized, expensed, AR, WO, ±10% class, ±20% class, ±40% class, time-bar diagram, flow schematic, buy-off, bid package, background check, PO, tracking, and AR Capital Job Closure Form.

PROBLEM 22-7 (STEP 6)

1. Contact local vendors of material to obtain current prices of common ones, such as steel shapes (angles, plates, bars, channels, and beams). Note that prices are usually given in dollars per 100 pounds and that price reductions are given for purchasing large quantities (e.g., a full railroad car).
2. Contact vendors of finished components—such as motors, switches, controls, bearings, chain, and similar products—to obtain costs to several categories of buyers.
   - **a.** Private individuals usually pay the full retail price.
   - **b.** Companies that include the finished components in a kit may get a 15% to 30% discount from the vendors because the companies sell the kits to customers.
   - **c.** Companies that include the finished components as an integral part of an assembled machine are called original equipment manufacturers (OEM). They may receive even larger discounts.

PROBLEM 22-8: (STEP 6)

Frequently, professionals are asked to make quick estimates during conversations over lunch or while phoning a client. This type of quick thinking is also an excellent approach to use for checking final results, whether it is homework in an engineering science course or a system in industry. Ask questions such as, does this look right, does this look reasonable, or does the output seem reasonable for the input?

For practicing "back-of-the-envelope" thinking and calculations, do the following in a time period assigned by your instructor and record the assumptions made:

1. Estimate the quantities of food and the cost of lunch for all of the people in your classroom.
2. Estimate the number of gallons of water used by your school in one day. (Perhaps maintenance personnel can verify the accuracy of the estimate.)
3. Estimate the cost of transporting a college football team 1,000 miles, and expenses for a three-day road trip.
4. Estimate the selling price of a new automobile, truck, van, sports car, or motorcycle based on the price per pound of existing vehicles.
5. Estimate selling prices of other products using the approach in #4.

PROBLEM 22-9 (STEP 12)

List the manufacturing processes required to make the problem parts shown in the following figures.

PROBLEM 22-9A



PROBLEM 22-9B



PROBLEM 22-9C



PROBLEM 22-9D

List the manufacturing processes required to make the part or parts assigned by your instructor.

PROBLEM 22-10: (STEP 5)

From memory, make a freehand sketch of an object shown to you for a limited time by your instructor. Then, do a second freehand sketch of the same object while you have a much longer time to view and examine it.

This practice of viewing an object knowing you have to sketch it from memory will train you to see and remember more than you would at a casual glance.

PROBLEM 22-11: (STEP 5)

List the obvious attributes of one of the following items. Include a freehand dimensioned sketch of the object. Then list all the not-so-obvious uses of the object. Be creative.

1. Kitchen table
2. Clothespin
3. Bookshelves
   a. Wood
   b. Metal
4. Cardboard milk carton
5. Plastic container of 35 mm film
6. Screwdriver
7. Nail

Routine Design Problems (RDP)

The routine design problems listed here are intended to give you experience in the design process while doing problems similar to those assigned to new employees in technical industries. Use the steps, as needed, in the design process to produce the following short report (printed or typed). The steps most needed are 2, 3, 5, 6, and 10.

1. A statement of the problem in your own words
2. A list of information sources used
3. Freehand sketch(es) or preliminary ideas of what needs to be done
4. Design development layout drawings of the ideas in the freehand sketches
5. Kinematic development layout drawings, if required
6. Complete detail and assembly drawings with parts lists
7. Cost analysis
8. Conclusions and recommendations
9. Appendices
   a. Machine copies of 3, 4, 5, and 6 (These copies will show how well pencil drawings reproduce as plotted or printed copies if CAD is used.)
   b. Vendor catalog information
   c. Any additional materials: work order, photographs, etc.
10. A title page and a folder for the report

PROBLEM 22-12 (RDP)

Refer to the torque wrench assembly in the accompanying figure and do the following:

1. Make the wrench just two times as large as shown for all dimensions.
2. Select steel for the handles and the fasteners.
3. Determine the bending stress in the necked-down portion of the handle. Specify as large a radius as practical at the necked-down location to avoid stress concentration. The bending stress will depend on the assumed force F and the length L.



F = FORCE BY OPERATOR IN POUNDS (NEED TO ASSUME)
L = ASSUME DISTANCE FROM F TO d IN INCHES
d = DIAMETER OF NECKED–DOWN PORTION IN INCHES

STRESS DUE TO MOMENT F X L AT d IS

$$\text{STRESS} = \frac{(F \times L)(d/2)}{(d^4)/64} \text{ IN POUNDS PER SQUARE INCH}$$

PROBLEM 22-13 (RDP)

Refer to the clamp shown in the accompanying figure and assume that parts no. 1 and no. 2 are to be aluminum, and parts no. 3 and no. 4 are steel. When threads in aluminum may be too weak because of the softer metal, a threaded-steel insert is pressed into the aluminum. Use an insert with appropriate threads inside and a nominal outside diameter of 15 mm, but dimensioned for an FN-2 medium-drive fit.

Increase the 18 mm dimension for parts no. 1 and no. 2 to 25 mm.



PROBLEM 22-14 (RDP)

The clamp shown in the accompanying figure needs to be modified to clamp rectangular assemblies 50 × 300 mm between the two threaded members instead of between the tapered extensions. The thread size should be increased 100% in diameter. Make any other changes that seem appropriate. Select materials. (*Note:* Part no. 4 must function like part no. 3, and the tapered portions of parts no. 1 and no. 2 are no longer needed.)



PROBLEM 22-15 (RDP)

Modify the screw jack shown in the accompanying figure to have an eight-inch vertical movement instead of the apparent four-inch vertical one.



PROBLEM 22-16 (RDP)

Modify the roller assembly shown as follows:

1. Make the shaft, part no. 3, 1″ diameter × 3″ long.
2. Change the roller, part no. 2, to have a bronze bushing 1″ inside diameter, 1.25″ outside diameter × 1.6888″ long; FN-2 Fit for the 1.25″ diameter and RC-3 for the 1″ inside diameter.
3. Change the supports, part no. 1, to have set screws to keep the shaft, no. 3, from turning.



PROBLEM 22-17 (RDP)

Change the vise shown in the accompanying figure to be 50% longer and 75% wider. In a kinematic layout drawing, show the extreme open and closed positions.



PROBLEM 22-18 (RDP)

Develop the concept of the beverage can crusher shown in the accompanying figure. Use standard materials and parts as indicated. Include a kinematic layout drawing showing extreme positions of the crusher head.



PROBLEM 22-19 (RDP)

Use press-fit drill bushings with heads to make a leaf-type jig for the hole pattern shown in the part to be drilled.



Non-Routine Design Problems

These non-routine problems are designed to give you experience in the overall design process, but mostly in Phases I–IV, Steps 1–11. When it is feasible, you are encouraged to build prototypes and discuss Steps 12 and 13 in Phase V.

Your instructor will most likely form student design teams to resolve the non-routine design problems, Problems 22-20 through 22-40, and the "real" problems from the suggested sources. Effective communication between members seems to be the major contributing factor to a team's success. What do you think?

The following groups of non-routine problems fall into three time-related categories: short, medium, and long projects. Suggestions for hours to allot for the three categories are included. Submit all reports in a cover with an appropriate title.

Short Non-Routine Design Problems

Suggestions: Allot 10–15 hours for one person to complete them; allot 5–7 hours for a team of two, etc.

Develop the problem only through Phase I of the design process. That is, prepare a plan of action for one or more students (Step 1 and Step 2), define the problem (Step 3), and prepare a progress report to a real or an assumed client (Step 4). Start a log and design file as assigned.

PROBLEM 22-20

Develop a toy for a ( )-year-old child confined to a bed or a wheelchair. *Note:* Select or be assigned the child's age.

PROBLEM 22-21

Design a small-capacity trailer that can be pulled by an automobile and that can be dismantled and stored in a relatively small space.

PROBLEM 22-22

Design a means of mounting posts on automobiles or pick-up trucks for games such as badminton or volleyball at remote picnic sites.

PROBLEM 22-23

Design a novel or practical use for discarded tires, cars, cartons, cans, or bottles.

PROBLEM 22-24

Design a portable can crusher for aluminum or steel for use in areas where numerous cans are deposited or tossed: for example, on roadsides.

PROBLEM 22-25

Design a teaching aid for one of the courses in your school, in a local high school, or in a local elementary school.

PROBLEM 22-26

Design a portable solar cooker.

Medium Non-Routine Design Problems

Suggestions: Allot 20–30 hours for one person to complete them; allot 10–15 hours for a team of two, etc. Develop the following problems through Steps 1–8 of the design process. Present your progress report to your classmates, with all members taking part in the presentation. Start a log, start a design file, and prepare a planning chart.

PROBLEM 22-27
Do any one of the Short Non-Routine Design Problems listed, but pursue the problem through Step 8.

PROBLEM 22-28
Design a device to assist an individual who has no legs, but full use of two arms, to get into a wheelchair from the floor, and back to the floor.

PROBLEM 22-29
Design a device to lift a 150-pound handicapped person out of a swimming pool.

PROBLEM 22-30
Design a study or work area for an individual with little income who is confined to a wheelchair.

PROBLEM 22-31
Design a means to use "pedal power" from a typical one-speed bicycle for performing a useful function such as sawing, sewing, mixing, pumping, etc.

Long Non-Routine Design Problems

Suggestions: Allot 40–60 hours for one person to complete them; allot 20–30 hours for a team of two, etc. Develop the following problems through Phase IV of the design process. Note that Phase IV usually requires at least half the total time allotted to a project whenever complete detail and assembly drawings are needed.

PROBLEM 22-32
Do any one of the short or medium non-routine design problems previously listed, but develop the problem through Phase IV of the design process.

PROBLEM 22-33
Design a means to rid aluminum beverage cans of moisture. The cans arrive in truckloads at a recycling center and the driver wants to be paid a realistic price, based on the actual metal turned in, within half an hour.

PROBLEM 22-34
Design an inexpensive fruit dryer.

PROBLEM 22-35
Design a powered vehicle to move one or more employees throughout a huge manufacturing plant or warehouse. The vehicle should be cost effective; that is, enough time (money) should be saved to justify its use.

PROBLEM 22-36
Modify a tricycle to accommodate a child with minimal leg use.

PROBLEM 22-37
Design a safe vehicle for coasting on a track, and the track, for children weighing up to 100 pounds.

PROBLEM 22-38
Design a pool cue for a one-armed person.

PROBLEM 22-39
Design a manually powered device for lifting 25 kilograms and heavier weights, vertically, at least one meter.

PROBLEM 22-40
Design a device that utilizes a typical automobile jack to perform another function(s) such as pressing, clamping, splitting wood, operating a simple "jaws of life" mechanism, etc.

Other Sources

The following lists describe a number of general sources for finding real, non-routine design problems. These problems are usually arranged for by instructors. After bringing together the source of the real problem (the client) with the design team (or an individual student) the instructor can step back and become an advisor-coach. Real, non-routine design problems are usually longer, often due to the extra time spent visiting and corresponding with clients.

1. School Classroom demonstrators of basic principles of chemistry, physics, statics, dynamics, mechanics of materials, engineering sciences, and manufacturing processes.
2. Handicapped
   a. Designs to help individuals confined to a wheelchair to:
      (i) Reach objects and prepare meals in a kitchen
      (ii) Obtain exercise
      (iii) Obtain access to heights higher than curbs
      (iv) Have access to classroom work surfaces
      (v) Have work surfaces on the wheelchair
   b. Designs to continually flex injured elbows and knee joints to accelerate healing.
   c. Designs to aid communications for individuals who have speech difficulties.
3. Hospitals
   a. Games or devices for children who are confined to a bed and have limited use of their arms.
   b. Devices to help injured individuals to perform simple functions such as dress, read, play games, and eat.
4. Civic Organizations
   a. Designs for YWCA or YMCA
   b. Designs to assist scouting programs such as neighborhood improvement projects
5. Local Industry
   a. Projects for the industry
   b. Projects for the industry's client
6. Private individuals (designs for)
   a. Home improvements
   b. Hobbies
   c. Inventions
   d. Invalid care
7. City (designs for)
   a. Better parking meters
   b. Playgrounds
   c. Park facilities
   d. Signs
   e. Junior Achievement
8. State (designs for)
   a. Signs
   b. Parks
   c. Recreational facilities
9. National (designs for)
   a. Design contests (Alcoa, Lincoln Arc Welding, Engineering Societies . . .)
   b. Environment
10. International (designs for)
    a. Third World countries
    b. To help Peace Corps. volunteers

Appendix A Tables

Contents

Table		Page
1	Inches to Millimeters/Millimeters to Inches	891
2	Inch/Metric—Equivalents	892
3	Metric Equivalents	893
4	Multipliers for Drafters	894
5	Circumferences and Areas of Circles	896
6	Trigonometric Formulas	897
7	Right-Triangle Formulas	898
8	Oblique-Angled Triangle Formulas	899
9	Running and Sliding Fits (Values in thousandths of an inch and millimeters)	900
10	Locational Clearance Fits (Values in thousandths of an inch and millimeters)	901
11	Locational Transition Fits (Values in thousandths of an inch and millimeters)	902
12	Locational Interference Fits (Values in thousandths of an inch and millimeters)	903
13	Force and Shrink Fits (Values in thousandths of an inch and millimeters)	904
14	Unified Standard Screw Thread Series	905
15	Drill and Tap Sizes	906
16	Drilled Hole Tolerance (Under normal shop conditions)	907
17	Inch-Metric Thread Comparison	910
18	ISO Basic Metric Thread Information	911
19	Key and Keyway Sizes	912
20	Woodruff Key Sizes for Different Shaft Diameters	913
21	Sheet Metal and Wire Gage Designation	914
22	Bend Allowance for 90° Bends (Inch and Millimeter)	915
23	Bend Allowance for Each 1° of Bend (Inch and Millimeter)	916
24	Spur/Pinion Gear Tooth Parts	917
25	Surface Texture Roughness	917
26	Properties, Grade Numbers, and Usage of Steel Alloys	918
27	American National Standards of Interest to Designers, Architects, and Drafters	919
28	ANSI B4.1-1967, R1994 Running and Sliding Fits	920
29	ANSI B4.1-1967, R1994 Clearance Fits	921
30	ANSI B4.1-1967, R1994 Transition Fits	922
31	Interference Locational Fits	923
32	Standard Force and Shrink Fits	924

INCHES TO MILLIMETERS

in.	mm	in.	mm	in.	mm	in.	mm
1	25.4	26	660.4	51	1295.4	76	1930.4
2	50.8	27	685.8	52	1320.8	77	1955.8
3	76.2	28	711.2	53	1346.2	78	1981.2
4	101.6	29	736.6	54	1371.6	79	2006.6
5	127.0	30	762.0	55	1397.0	80	2032.0
6	152.4	31	787.4	56	1422.4	81	2057.4
7	177.8	32	812.8	57	1447.8	82	2082.8
8	203.2	33	838.2	58	1473.2	83	2108.2
9	228.6	34	863.6	59	1498.6	84	2133.6
10	254.0	35	889.0	60	1524.0	85	2159.0
11	279.4	36	914.4	61	1549.4	86	2184.4
12	304.8	37	939.8	62	1574.8	87	2209.8
13	330.2	38	965.2	63	1600.2	88	2235.2
14	355.6	39	990.6	64	1625.6	89	2260.6
15	381.0	40	1016.0	65	1651.0	90	2286.0
16	406.4	41	1041.4	66	1676.4	91	2311.4
17	431.8	42	1066.8	67	1701.8	92	2336.8
18	457.2	43	1092.2	68	1727.2	93	2362.2
19	482.6	44	1117.6	69	1752.6	94	2387.6
20	508.0	45	1143.0	70	1778.0	95	2413.0
21	533.4	46	1168.4	71	1803.4	96	2438.4
22	558.8	47	1193.8	72	1828.8	97	2463.8
23	584.2	48	1219.2	73	1854.2	98	2489.2
24	609.6	49	1244.6	74	1879.6	99	2514.6
25	635.0	50	1270.0	75	1905.0	100	2540.0

The above table is exact on the basis: 1 in. = 25.4 mm

MILLIMETERS TO INCHES

mm	in.	mm	in.	mm	in.	mm	in.
1	0.039370	26	1.023622	51	2.007874	76	2.992126
2	0.078740	27	1.062992	52	2.047244	77	3.031496
3	0.118110	28	1.102362	53	2.086614	78	3.070866
4	0.157480	29	1.141732	54	2.125984	79	3.110236
5	0.196850	30	1.181102	55	2.165354	80	3.149606
6	0.236220	31	1.220472	56	2.204724	81	3.188976
7	0.275591	32	1.259843	57	2.244094	82	3.228346
8	0.314961	33	1.299213	58	2.283465	83	3.267717
9	0.354331	34	1.338583	59	2.322835	84	3.307087
10	0.393701	35	1.377953	60	2.362205	85	3.364457
11	0.433071	36	1.417323	61	2.401575	86	3.385827
12	0.472441	37	1.456693	62	2.440945	87	3.425197
13	0.511811	38	1.496063	63	2.480315	88	3.464567
14	0.551181	39	1.535433	64	2.519685	89	3.503937
15	0.590551	40	1.574803	65	2.559055	90	3.543307
16	0.629921	41	1.614173	66	2.598425	91	3.582677
17	0.669291	42	1.653543	67	2.637795	92	3.622047
18	0.708661	43	1.692913	68	2.677165	93	3.661417
19	0.748031	44	1.732283	69	2.716535	94	3.700787
20	0.787402	45	1.771654	70	2.755906	95	3.740157
21	0.826772	46	1.811024	71	2.795276	96	3.779528
22	0.866142	47	1.850394	72	2.834646	97	3.818898
23	0.905512	48	1.889764	73	2.874016	98	3.858268
24	0.944882	49	1.929134	74	2.913386	99	3.897638
25	0.984252	50	1.968504	75	2.952756	100	3.937008

The above table is approximate on the basis: 1 in. = 25.4 mm, 1/25.4 = 0.039370078740+

TABLE 1

INCH/METRIC—EQUIVALENTS

Fraction	Decimal Equivalent		Fraction	Decimal Equivalent	
	Customary (in.)	Metric (mm)		Customary (in.)	Metric (mm)
1/64	.015625	0.3969	33/64	.515625	13.0969
1/32	.03125	0.7938	17/32	.53125	13.4938
3/64	.046875	1.1906	35/64	.546875	13.8906
1/16	.0625	1.5875	9/16	.5625	14.2875
5/64	.078125	1.9844	37/64	.578125	14.6844
3/32	.09375	2.3813	19/32	.59375	15.0813
7/64	.109375	2.7781	39/64	.609375	15.4781
1/8	.1250	3.1750	5/8	.6250	15.8750
9/64	.140625	3.5719	41/64	.640625	16.2719
5/32	.15625	3.9688	21/32	.65625	16.6688
11/64	.171875	4.3656	43/64	.671875	17.0656
3/16	.1875	4.7625	11/16	.6875	17.4625
13/64	.203125	5.1594	45/64	.703125	17.8594
7/32	.21875	5.5563	23/32	.71875	18.2563
15/64	.234375	5.9531	47/64	.734375	18.6531
1/4	.250	6.3500	3/4	.750	19.0500
17/64	.265625	6.7469	49/64	.765625	19.4469
9/32	.28125	7.1438	25/32	.78125	19.8438
19/64	.296875	7.5406	51/64	.796875	20.2406
5/16	.3125	7.9375	13/16	.8125	20.6375
21/64	.328125	8.3384	53/64	.828125	21.0344
11/32	.34375	8.7313	27/32	.84375	21.4313
23/64	.359375	9.1281	55/64	.859375	21.8281
3/8	.3750	9.5250	7/8	.8750	22.2250
25/64	.390625	9.9219	57/64	.890625	22.6219
13/32	.40625	10.3188	29/32	.90625	23.0188
27/64	.421875	10.7156	59/64	.921875	23.4156
7/16	.4375	11.1125	15/16	.9375	23.8125
29/64	.453125	11.5094	61/64	.953125	24.2094
15/32	.46875	11.9063	31/32	.96875	24.6063
31/64	.484375	12.3031	63/64	.984375	25.0031
1/2	.500	12.7000	1	1.000	25.4000

TABLE 2 From *Drafting for Trades and Industry—Basic Skills*, Nelson. Delmar Publishers Inc.

METRIC EQUIVALENTS

LENGTH

U.S. to Metric	*Metric to U.S.*
1 inch = 2.540 centimeters	1 millimeter = .039 inch
1 foot = .305 meter	1 centimeter = .394 inch
1 yard = .914 meter	1 meter = 3.281 feet or 1.094 yards
1 mile = 1.609 kilometers	1 kilometer = .621 mile

AREA

1 $inch^2$ = 6.451 $centimeter^2$	1 $millimeter^2$ = .00155 $inch^2$
1 $foot^2$ = .093 $meter^2$	1 $centimeter^2$ = .155 $inch^2$
1 $yard^2$ = .836 $meter^2$	1 $meter^2$ = 10.764 $foot^2$ or 1.196 $yard^2$
1 $acre^2$ = 4,046.873 $meter^2$	1 $kilometer^2$ = .386 $mile^2$ or 247.04 $acre^2$

VOLUME

1 $inch^3$ = 16.387 $centimeter^3$	1 $centimeter^3$ = 0.61 $inch^3$
1 $foot^3$ = .028 $meter^3$	1 $meter^3$ = 35.314 $foot^3$ or 1.308 $yard^3$
1 $yard^3$ = .764 $meter^3$	1 liter = .2642 gallons
1 quart = .946 liter	1 liter = 1.057 quarts
1 gallon = .003785 $meter^3$	1 $meter^3$ = 264.02 gallons

WEIGHT

1 ounce = 28.349 grams	1 gram = .035 ounce
1 pound = .454 kilogram	1 kilogram = 2.205 pounds
1 ton = .907 metric ton	1 metric ton = 1.102 tons

VELOCITY

1 foot/second = .305 meter/second	1 meter/second = 3.281 feet/second
1 mile/hour = .447 meter/second	1 kilometer/hour = .621 mile/second

ACCELERATION

1 $inch/second^2$ = .0254 $meter/second^2$	1 $meter/second^2$ = 3.278 $feet/second^2$
1 $foot/second^2$ = .305 $meter/second^2$	

FORCE

N (newton) = basic unit of force, $kg\text{-}m/s^2$. A mass of one kilogram (1 kg) exerts a gravitational force of 9.8 N (theoretically 9.80665 N) at mean sea level.

TABLE 3

MULTIPLIERS FOR DRAFTERS

Multiply	By	To Obtain
Acres	43,560	Square feet
Acres	4047	Square meters
Acres	1.562×10^{-3}	Square miles
Acres	4840	Square yards
Acre-feet	43,560	Cubic feet
Atmospheres	76.0	Cms. of mercury
Atmospheres	29.92	Inches of mercury
Atmospheres	33.90	Feet of water
Atmospheres	10,333	Kgs./sq. meter
Atmospheres	14.70	Lbs./sq. inch
Atmospheres	1.058	Tons/sq. ft.
Board feet	144 sq. in. × 1 in.	Cubic inches
British Thermal Units	0.2520	Kilogram-calories
British Thermal Units	777.5	Foot-lbs.
British Thermal Units	3.927×10^{-4}	Horsepower-hrs.
British Thermal Units	107.5	Kilogram-meters
British Thermal Units	2.928×10^{-4}	Kilowatt-hrs.
BTU/min.	12.96	Foot-lbs./sec.
BTU/min.	0.02356	Horsepower
BTU/min.	0.01757	Kilowatts
BTU/min.	17.57	Watts
Cubic centimeters	3.531×10^{-5}	Cubic feet
Cubic centimeters	6.102×10^{-2}	Cubic inches
Cubic centimeters	10^{-6}	Cubic meters
Cubic centimeters	1.308×10^{-6}	Cubic yards
Cubic centimeters	2.642×10^{-4}	Gallons
Cubic centimeters	10^{-3}	Liters
Cubic centimeters	2.113×10^{-3}	Pints (liq.)
Cubic centimeters	1.057×10^{-3}	Quarts (liq.)
Cubic feet	2.832×10^{4}	Cubic cm
Cubic feet	1728	Cubic inches
Cubic feet	0.02832	Cubic meters
Cubic feet	0.03704	Cubic yards
Cubic feet	7.48052	Gallons
Cubic feet	28.32	Liters
Cubic feet	59.84	Pints (liq.)
Cubic feet	29.92	Quarts (liq.)
Cubic feet/min.	472.0	Cubic cm/sec.
Cubic feet/min.	0.1247	Gallons/sec.
Cubic feet/min.	0.4720	Liters/sec.
Cubic feet/min.	62.43	Pounds of water/min.
Cubic feet/sec.	0.646317	Millions gals./day
Cubic feet/sec.	448.831	Gallons/min.
Cubic inches	16.39	Cubic centimeters
Cubic inches	5.787×10^{-4}	Cubic feet
Cubic inches	1.639×10^{-5}	Cubic meters
Cubic inches	2.143×10^{-5}	Cubic yards
Cubic inches	4.329×10^{-3}	Gallons
Cubic inches	1.639×10^{-2}	Liters
Cubic inches	0.03463	Pints (liq.)
Cubic inches	0.01732	Quarts (liq.)
Cubic meters	10^{6}	Cubic centimeters
Cubic meters	35.31	Cubic feet
Cubic meters	61.023	Cubic inches
Cubic meters	1.308	Cubic yards
Cubic meters	264.2	Gallons
Cubic meters	10^{3}	Liters
Cubic meters	2113	Pints (liq.)
Cubic meters	1057	Quarts (liq.)
Degrees (angle)	60	Minutes
Degrees (angle)	0.01745	Radians
Degrees (angle)	3600	Seconds
Degrees/sec.	0.01745	Radians/sec.
Degrees/sec.	0.1667	Revolutions/min.
Degrees/sec.	0.002778	Revolutions/sec.
Fathoms	6	Feet
Feet	30.48	Centimeters
Feet	12	Inches
Feet	0.3048	Meters
Foot-pounds	1.286×10^{-3}	British Thermal Units
Foot-pounds	5.050×10^{-7}	Horsepower-hrs.
Foot-pounds	3.241×10^{-4}	Kilogram-calories
Foot-pounds	0.1383	Kilogram-meters
Foot-pounds	3.766×10^{-7}	Kilowatt-hrs.
Foot-pounds/min.	1.286×10^{-3}	BTU/min.
Foot-pounds/min.	0.01667	Foot-pounds/sec.
Foot-pounds/min.	3.030×10^{-5}	Horsepower
Foot-pounds/min.	3.241×10^{-4}	Kg-calories/min.
Foot-pounds/min.	2.260×10^{-5}	Kilowatts
Foot-pounds/sec.	7.717×10^{-2}	BTU/min.
Foot-pounds/sec.	1.818×10^{-3}	Horsepower
Foot-pounds/sec.	1.945×10^{-2}	Kg-calories/min.
Foot-pounds/sec.	1.356×10^{-3}	Kilowatts
Gallons	3785	Cubic centimeters
Gallons	0.1337	Cubic feet
Gallons	231	Cubic inches
Gallons	3.785×10^{-3}	Cubic meters
Gallons	4.951×10^{-3}	Cubic yards
Gallons	3.785	Liters
Gallons	8	Pints (liq.)
Gallons	4	Quarts (liq.)
Gallons-Imperial	1.20095	U.S. gallons
Gallons-U.S.	0.83267	Imperial gallons
Gallons water	8.3453	Pounds of water
Horsepower	42.44	BTU/min.
Horsepower	33,000	Foot-lbs./min.
Horsepower	550	Foot-lbs./sec.
Horsepower	1.014	Horsepower (metric)
Horsepower	10.70	Kg-calories/min.
Horsepower	0.7457	Kilowatts
Horsepower	745.7	Watts
Horsepower-hours	2547	BTU
Horsepower-hours	1.98×10^{6}	Foot-lbs.
Horsepower-hours	641.7	Kilogram-calories
Horsepower-hours	2.737×10^{5}	Kilogram-meters
Horsepower-hours	0.7457	Kilowatt-hours
Kilometers	10^{5}	Centimeters
Kilometers	3281	Feet
Kilometers	10^{3}	Meters
Kilometers	0.6214	Miles
Kilometers	1094	Yards
Kilowatts	56.92	BTU/min.
Kilowatts	4.425×10^{4}	Foot-lbs./min.
Kilowatts	737.6	Foot-lbs./sec.
Kilowatts	1.341	Horsepower
Kilowatts	14.34	Kg.-calories/min.
Kilowatts	10^{3}	Watts
Kilowatt-hours	3415	BTU
Kilowatt-hours	2.655×10^{6}	Foot-lbs.
Kilowatt-hours	1.341	Horsepower-hrs.
Kilowatt-hours	860.5	Kilogram-calories
Kilowatt-hours	3.671×10^{5}	Kilogram-meters
Lumber Width (in.) × $\frac{\text{Thickness (in.)}}{12}$	Length (ft.)	Board feet
Meters	100	Centimeters
Meters	3.281	Feet
Meters	39.37	Inches

TABLE 4

MULTIPLIERS FOR DRAFTERS (Concluded)

Multiply	By	To Obtain
Meters	10^{-3}	Kilometers
Meters	10^{3}	Millimeters
Meters	1.094	Yards
Meters/min.	1.667	Centimeters/sec.
Meters/min.	3.281	Feet/min.
Meters/min.	0.05468	Feet/sec.
Meters/min.	0.06	Kilometers/hr.
Meters/min.	0.03728	Miles/hr.
Meters/sec.	196.8	Feet/min.
Meters/sec.	3.281	Feet/sec.
Meters/sec.	3.6	Kilometers/hr.
Meters/sec.	0.06	Kilometers/min.
Meters/sec.	2.237	Miles/hr.
Meters/sec.	0.03728	Miles/min.
Microns	10^{-6}	Meters
Miles	5280	Feet
Miles	1.609	Kilometers
Miles	1760	Yards
Miles/hr.	1.609	Kilometers/hr.
Miles/hr.	0.8684	Knots
Minutes (angle)	2.909×10^{-4}	Radians
Ounces	16	Drams
Ounces	437.5	Grains
Ounces	0.0625	Pounds
Ounces	28.349527	Grams
Ounces	0.9115	Ounces (troy)
Ounces	2.790×10^{-5}	Tons (long)
Ounces	2.835×10^{-5}	Tons (metric)
Ounces (troy)	480	Grains
Ounces (troy)	20	Pennyweights (troy)
Ounces (troy)	0.08333	Pounds (troy)
Ounces (troy)	31.103481	Grams
Ounces (troy)	1.09714	Ounces (avoir.)
Ounces (fluid)	1.805	Cubic Inches
Ounces (fluid)	0.02957	Liters
Ounces/sq. inch	0.0625	Lbs./sq. inch
Pounds	16	Ounces
Pounds	256	Drams
Pounds	7000	Grains
Pounds	0.0005	Tons (short)
Pounds	453.5924	Grams
Pounds	1.21528	Pounds (troy)
Pounds	14.5833	Ounces (troy)
Pounds (troy)	5760	Grains
Pounds (troy)	240	Pennyweights (troy)
Pounds (troy)	12	Ounces (troy)
Pounds (troy)	373.24177	Grams
Pounds (troy)	0.822857	Pounds (avoir.)
Pounds (troy)	13.1657	Ounces (avoir.)
Pounds (troy)	3.6735×10^{-4}	Tons (long)
Pounds (troy)	4.1143×10^{-4}	Tons (short)
Pounds (troy)	3.7324×10^{-4}	Tons (metric)
Quadrants (angle)	90	Degrees
Quadrants (angle)	5400	Minutes
Quadrants (angle)	1.571	Radians
Radians	57.30	Degrees
Radians	3438	Minutes
Radians	0.637	Quadrants
Radians/sec.	57.30	Degrees/sec.
Radians/sec.	0.1592	Revolutions/sec.
Radians/sec.	9.549	Revolutions/min.
Radians/sec./sec.	573.0	Revs./min./min.
Radians/sec./sec.	0.1592	Revs./sec./sec.
Reams	500	Sheets
Revolutions	360	Degrees
Revolutions	4	Quadrants
Revolutions	6.283	Radians
Revolutions/min.	6	Degrees/sec.
Square yards	2.066×10^{-4}	Acres
Square yards	9	Square feet
Square yards	0.8361	Square meters
Square yards	3.228×10^{-7}	Square miles
Temp. (°C.) + 273	1	Abs. temp. (°C.)
Temp. (°C.) + 17.78	1.8	Temp. (°F.)
Temp. (°F.) + 460	1	Abs. temp. (°F.)
Temp. (°F.) – 32	5/9	Temp. (°C.)
Watts	0.05692	BTU/min.
Watts	44.26	Foot-pounds/min.
Watts	0.7376	Foot-pounds/sec.
Watts	1.341×10^{-3}	Horsepower
Watts	0.01434	Kg.-calories/min.
Watts	10^{-3}	Kilowatts
Watts-hours	3.415	BTU
Watts-hours	2655	Foot-pounds
Watts-hours	1.341×10^{-3}	Horsepower-hrs.
Watts-hours	0.8605	Kilogram-calories
Watts-hours	367.1	Kilogram-meters
Watts-hours	10^{-3}	Kilowatt-hours
Yards	91.44	Centimeters
Yards	3	Feet
Yards	36	Inches
Yards	0.9144	Meters

TABLE 4 *(Concluded)*

CIRCUMFERENCES AND AREAS OF CIRCLES
From 1/64 to 50, Diameter

Dia.	Circum.	Area	Dia.	Circum.	Area	Dia.	Circum.	Area	Dia.	Circum.	Area
1/64	.04909	.00019	8	25.1327	50.2655	17	53.4071	226.980	26	81.6814	530.929
1/32	.09818	.00077	8 1/8	25.5254	51.8485	17 1/8	53.7998	230.330	26 1/8	82.0741	536.047
1/16	.19635	.00307	8 1/4	25.9181	53.4562	17 1/4	54.1925	233.705	26 1/4	82.4668	541.188
1/8	.39270	.01227	8 3/8	26.3108	55.0883	17 3/8	54.5852	237.104	26 3/8	82.8595	546.355
3/16	.58905	.02761	8 1/2	26.7035	56.7450	17 1/2	54.9779	240.528	26 1/2	83.2522	551.546
1/4	.78540	.04909	8 5/8	27.0962	58.4262	17 5/8	55.3706	243.977	26 5/8	83.6449	556.761
5/16	.98175	.07670	8 3/4	27.4889	60.1321	17 3/4	55.7633	247.450	26 3/4	84.0376	562.002
3/8	1.1781	.11045	8 7/8	27.8816	61.8624	17 7/8	56.1560	250.947	26 7/8	84.4303	567.266
7/16	1.3744	.15033	9	28.2743	63.6173	18	56.5487	254.469	27	84.8230	572.555
1/2	1.5708	.19635	9 1/8	28.6670	65.3967	18 1/8	56.9414	258.016	27 1/8	85.2157	577.869
9/16	1.7671	.24850	9 1/4	29.0597	67.2007	18 1/4	57.3341	261.587	27 1/4	85.6084	583.207
5/8	1.9635	.30680	9 3/8	29.4524	69.0292	18 3/8	57.7268	265.182	27 3/8	86.0011	588.570
11/16	2.1598	.37122	9 1/2	29.8451	70.8822	18 1/2	58.1195	268.803	27 1/2	86.3938	593.957
3/4	2.3562	.44179	9 5/8	30.2378	72.7597	18 5/8	58.5122	272.447	27 5/8	86.7865	599.369
13/16	2.5525	.51849	9 3/4	30.6305	74.6619	18 3/4	58.9049	276.117	27 3/4	87.1792	604.806
7/8	2.7489	.60132	9 7/8	31.0232	76.5886	18 7/8	59.2976	279.810	27 7/8	87.5719	610.267
15/16	2.9452	.69029				19	59.6903	283.529	28	87.9646	615.752
1	3.1416	.78540	10	31.4159	78.5398	19 1/8	60.0830	287.272	28 1/8	88.3573	621.262
1 1/8	3.5343	.99402	10 1/8	31.8086	80.5156	19 1/4	60.4757	291.039	28 1/4	88.7500	626.797
1 1/4	3.9270	1.2272	10 1/4	32.2013	82.5159	19 3/8	60.8684	294.831	28 3/8	89.1427	632.356
1 3/8	4.3197	1.4849	10 3/8	32.5940	84.5408	19 1/2	61.2611	298.648	28 1/2	89.5354	637.940
1 1/2	4.7124	1.7671	10 1/2	32.9867	86.5902	19 5/8	61.6538	302.489	28 5/8	89.9281	643.548
1 5/8	5.1051	2.0739	10 5/8	33.3794	88.6641	19 3/4	62.0465	306.354	28 3/4	90.3208	649.181
1 3/4	5.4978	2.4053	10 3/4	33.7721	90.7626	19 7/8	62.4392	310.245	28 7/8	90.7135	654.838
1 7/8	5.8905	2.7612	10 7/8	34.1648	92.8856	20	62.8319	314.159	29	91.1062	660.520
2	6.2832	3.1416	11	34.5575	95.0332	20 1/8	63.2246	318.099	29 1/8	91.4989	666.226
2 1/8	6.6759	3.5466	11 1/8	34.9502	97.2053	20 1/4	63.6173	322.062	29 1/4	91.8916	671.957
2 1/4	7.0686	3.9761	11 1/4	35.3429	99.4020	20 3/8	64.0100	326.051	29 3/8	92.2843	677.713
2 3/8	7.4613	4.4301	11 3/8	35.7356	101.623	20 1/2	64.4027	330.064	29 1/2	92.6770	683.493
2 1/2	7.8540	4.9087	11 1/2	36.1283	103.869	20 5/8	64.7954	334.101	29 5/8	93.0697	689.297
2 5/8	8.2467	5.4119	11 5/8	36.5210	106.139	20 3/4	65.1881	338.163	29 3/4	93.4624	695.127
2 3/4	8.6394	5.9396	11 3/4	36.9137	108.434	20 7/8	65.5808	342.250	29 7/8	93.8551	700.980
2 7/8	9.0321	6.4918	11 7/8	37.3064	110.753				30	94.2478	706.858
3	9.4248	7.0686	12	37.6991	113.097	21	65.9735	346.361	30 1/8	94.6405	712.761
3 1/8	9.8175	7.6699	12 1/8	38.0918	115.466	21 1/8	66.3662	350.496	30 1/4	95.0332	718.689
3 1/4	10.2102	8.2958	12 1/4	38.4845	117.859	21 1/4	66.7589	354.656	30 3/8	95.4259	724.640
3 3/8	10.6029	8.9462	12 3/8	38.8772	120.276	21 3/8	67.1516	358.841	30 1/2	95.8186	730.617
3 1/2	10.9956	9.6211	12 1/2	39.2699	122.718	21 1/2	67.5442	363.050	30 5/8	96.2113	736.618
3 5/8	11.3883	10.3206	12 5/8	39.6626	125.185	21 5/8	67.9369	367.284	30 3/4	96.6040	742.643
3 3/4	11.7810	11.0447	12 3/4	40.0553	127.676	21 3/4	68.3296	371.542	30 7/8	96.9967	748.693
3 7/8	12.1737	11.7932	12 7/8	40.4480	130.191	21 7/8	68.7223	375.825	31	97.3894	754.768
4	12.5664	12.5664	13	40.8407	132.732	22	69.1150	380.133	31 1/8	97.7821	760.867
4 1/8	12.9591	13.3640	13 1/8	41.2334	135.297	22 1/8	69.5077	384.465	31 1/4	98.1748	766.990
4 1/4	13.3518	14.1863	13 1/4	41.6261	137.886	22 1/4	69.9004	388.821	31 3/8	98.5675	773.139
4 3/8	13.7445	15.0330	13 3/8	42.0188	140.500	22 3/8	70.2931	393.203	31 1/2	98.9602	779.311
4 1/2	14.1372	15.9043	13 1/2	42.4115	143.139	22 1/2	70.6858	397.608	31 5/8	99.3529	785.509
4 5/8	14.5299	16.8002	13 5/8	42.8042	145.802	22 5/8	71.0785	402.038	31 3/4	99.7456	791.731
4 3/4	14.9226	17.7206	13 3/4	43.1969	148.489	22 3/4	71.4712	406.493	31 7/8	100.1383	797.977
4 7/8	15.3153	18.6655	13 7/8	43.5896	151.201	22 7/8	71.8639	410.972			
5	15.7080	19.6350	14	43.9823	153.938	23	72.2566	415.476	32	100.5310	804.248
5 1/8	16.1007	20.6290	14 1/8	44.3750	156.699	23 1/8	72.6493	420.004	32 1/8	100.9237	810.543
5 1/4	16.4934	21.6476	14 1/4	44.7677	159.485	23 1/4	73.0420	424.557	32 1/4	101.3164	816.863
5 3/8	16.8861	22.6906	14 3/8	45.1604	162.295	23 3/8	73.4347	429.134	32 3/8	101.7091	823.208
5 1/2	17.2788	23.7583	14 1/2	45.5531	165.130	23 1/2	73.8274	433.736	32 1/2	102.1018	829.577
5 5/8	17.6715	24.8505	14 5/8	45.9458	167.989	23 5/8	74.2201	438.363	32 5/8	102.4945	835.971
5 3/4	18.0642	25.9672	14 3/4	46.3385	170.873	23 3/4	74.6128	443.014	32 3/4	102.8872	842.389
5 7/8	18.4569	27.1085	14 7/8	46.7312	173.782	23 7/8	75.0055	447.689	32 7/8	103.2799	848.831
6	18.8496	28.2743	15	47.1239	176.715	24	75.3982	452.389	33	103.6726	855.299
6 1/8	19.2423	29.4647	15 1/8	47.5166	179.672	24 1/8	75.7909	457.114	33 1/8	104.0653	861.791
6 1/4	19.6350	30.6796	15 1/4	47.9094	182.654	24 1/4	76.1836	461.863	33 1/4	104.4580	868.307
6 3/8	20.0277	31.9191	15 3/8	48.3020	185.661	24 3/8	76.5763	466.637	33 3/8	104.8507	874.848
6 1/2	20.4204	33.1831	15 1/2	48.6947	188.692	24 1/2	76.9690	471.435	33 1/2	105.2434	881.413
6 5/8	20.8131	34.4716	15 5/8	49.0874	191.748	24 5/8	77.3617	476.258	33 5/8	105.6361	888.003
6 3/4	21.2058	35.7847	15 3/4	49.4801	194.828	24 3/4	77.7544	481.106	33 3/4	106.0288	894.618
6 7/8	21.5985	37.1223	15 7/8	49.8728	197.933	24 7/8	78.1471	485.977	33 7/8	106.4215	901.257
7	21.9912	38.4845	16	50.2655	201.062	25	78.5398	490.874	34	106.8142	907.920
7 1/8	22.3839	39.8712	16 1/8	50.6582	204.216	25 1/8	78.9325	495.795	34 1/8	107.2069	914.609
7 1/4	22.7765	41.2825	16 1/4	51.0509	207.394	25 1/4	79.3252	500.740	34 1/4	107.5996	921.321
7 3/8	23.1692	42.7183	16 3/8	51.4436	210.597	25 3/8	79.7179	505.711	34 3/8	107.9923	928.058
7 1/2	23.5619	44.1787	16 1/2	51.8363	213.825	25 1/2	80.1106	510.705	34 1/2	108.3850	934.820
7 5/8	23.9546	45.6636	16 5/8	52.2290	217.077	25 5/8	80.5033	515.724	34 5/8	108.7777	941.607
7 3/4	24.3473	47.1730	16 3/4	52.6217	220.353	25 3/4	80.8960	520.768	34 3/4	109.1704	948.417
7 7/8	24.7400	48.7069	16 7/8	53.0144	223.654	25 7/8	81.2887	525.836	34 7/8	109.5631	955.253

TRIGONOMETRIC FORMULAS



FORMULAS FOR FINDING FUNCTIONS OF ANGLES	
$\frac{\text{Side opposite}}{\text{Hypotenuse}}$	= SINE
$\frac{\text{Side adjacent}}{\text{Hypotenuse}}$	= COSINE
$\frac{\text{Side opposite}}{\text{Side adjacent}}$	= TANGENT
$\frac{\text{Side adjacent}}{\text{Side opposite}}$	= COTANGENT
$\frac{\text{Hypotenuse}}{\text{Side adjacent}}$	= SECANT
$\frac{\text{Hypotenuse}}{\text{Side opposite}}$	= COSECANT

FORMULAS FOR FINDING THE LENGTH OF SIDES FOR RIGHT-ANGLE TRIANGLES WHEN AN ANGLE AND SIDE ARE KNOWN	
Length of side opposite	Hypotenuse × Sine Hypotenuse ÷ Cosecant Side adjacent × Tangent Side adjacent ÷ Cotangent
Length of side adjacent	Hypotenuse × Cosine Hypotenuse ÷ Secant Side opposite × Cotangent Side opposite ÷ Tangent
Length of hypotenuse	Side opposite × Cosecant Side opposite ÷ Sine Side adjacent × Secant Side adjacent ÷ Cosine

TABLE 6

RIGHT-TRIANGLE FORMULAS



TO FIND ANGLES	FORMULAS	
C	$\frac{c}{a}$ = Sine C	90°—B
C	$\frac{b}{a}$ = Cosine C	90°—B
C	$\frac{c}{b}$ = Tan C	90°—B
C	$\frac{b}{c}$ = Cot C	90°—B
C	$\frac{a}{b}$ = Secant C	90°—B
C	$\frac{a}{c}$ = Csc C	90°—B
B	$\frac{b}{a}$ = Sine B	90°—C
B	$\frac{c}{a}$ = Cosine B	90°—C
B	$\frac{b}{c}$ = Tan B	90°—C
B	$\frac{c}{b}$ = Cot B	90°—C
B	$\frac{a}{c}$ = Secant B	90°—C
B	$\frac{a}{b}$ = Csc B	90°—C

TO FIND SIDES	FORMULAS	
a	$\sqrt{b^2 + c^2}$	
a	c × Csc C	$\frac{c}{\text{sine C}}$
a	c × Secant B	$\frac{c}{\text{Cosine B}}$
a	b × Csc B	$\frac{b}{\text{Sine B}}$
a	b × Secant C	$\frac{b}{\text{Cosine C}}$
b	$\sqrt{a^2 - c^2}$	
b	a × Sine B	$\frac{a}{\text{Cosecant B}}$
b	a × Cos C	$\frac{a}{\text{Secant C}}$
b	c × Tan B	$\frac{c}{\text{Cotangent B}}$
b	c × Cot C	$\frac{c}{\text{Tangent C}}$
c	$\sqrt{a^2 - b^2}$	
c	a × Cos B	$\frac{a}{\text{Secant B}}$
c	a × Sine C	$\frac{a}{\text{Cosecant C}}$
c	b × Cot B	$\frac{b}{\text{Tangent B}}$
c	b × Tan C	$\frac{b}{\text{Cotangent C}}$

TABLE 7

OBLIQUE-ANGLED TRIANGLE FORMULAS



TO FIND	KNOWN	SOLUTION
C	A-B	$180° - (A + B)$
b	a-B-A	$\frac{a \times \text{Sin } B}{\text{Sin } A}$
c	a-A-C	$\frac{a \times \text{Sin } C}{\text{Sin } A}$
Tan A	a-C-b	$\frac{a \times \text{Sin } C}{b - (a \times \text{Cos } C)}$
B	A-C	$180° - (A + C)$
Sin B	b-A-a	$\frac{b \times \text{Sin } A}{a}$
A	B-C	$180° - (B + C)$
Cos A	a-b-c	$\frac{b^2 + C^2 - a^2}{2bc}$
Sin C	c-A-a	$\frac{c \times \text{Sin } A}{a}$
Cot B	a-C-b	$\frac{a \times \text{Csc } C}{b} - \text{Cot } C$
c	b-C-B	$b \times \text{Sin } C \times \text{Csc } B$

TABLE 8

RUNNING AND SLIDING FITS

VALUES IN THOUSANDTHS OF AN INCH

Nominal Size Range Inches		Class RC1 Precision Sliding			Class RC2 Sliding Fit			Class RC3 Precision Running			Class RC4 Close Running			Class RC5 Medium Running		
		Hole Tol. GR5	Minimum Clearance	Shaft Tol. GR4	Hole Tol. GR6	Minimum Clearance	Shaft Tol. GR5	Hole Tol. GR7	Minimum Clearance	Shaft Tol. GR6	Hole Tol. GR8	Minimum Clearance	Shaft Tol. GR7	Hole Tol. GR8	Minimum Clearance	Shaft Tol. GR7
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	.12	+0.15	0.10	-0.12	+0.25	0.10	-0.15	+0.40	0.30	-0.25	+0.60	0.30	-0.40	+0.60	0.60	-0.40
.12	.24	+0.20	0.15	-0.15	+0.30	0.15	-0.20	+0.50	0.40	-0.30	+0.70	0.40	-0.50	+0.70	0.80	-0.50
.24	.40	+0.25	0.20	-0.15	+0.40	0 20	-0.25	+0.60	0.50	-0.40	+0.90	0.50	-0.60	+0.90	1.00	-0.60
.40	.71	+0.30	0.25	-0 20	+0.40	0.25	-0.30	+0.70	0.60	-0.40	+1.00	0.60	-0.70	+1.00	1.20	-0.70
.71	1.19	+0.40	0.30	-0.25	+0.50	0.30	-0.40	+0.80	0.80	-0.50	+1.20	0.80	-0.80	+1.20	1.60	-0.50
1.19	1.97	+0.40	0 40	-0.30	+0.60	0.40	-0.40	+1.00	1.00	-0.60	+1.60	1.00	-1.00	+1.60	2.00	-1.00
1.97	3.15	+0.50	0.40	-0.30	+0.70	0.40	-0.50	+1.20	1.20	-0.70	+1.80	1.20	-1.20	+1.80	2.50	-1.20
3.15	4.73	+0.60	0.50	-0.40	+0.90	0.50	-0.60	+1.40	1.40	-0.90	+2.20	1.40	-1.40	+2.20	3.00	-1.40
4.73	7 09	+0 70	0.60	-0.50	+1.00	0 60	-0.70	+1.60	1.60	-1.00	+2.50	1.60	-1.60	+2.50	3.50	-1.60
7.09	9.85	+0.80	0 60	-0.60	+1.20	0.60	-0.80	+1.80	2.00	-1.20	+2.80	2.00	-1.80	+2.80	4.50	-1.80
9.85	12.41	+0.90	0.80	-0.60	+1.20	0.80	-0.90	+2.00	2.50	-1.20	+3.00	2.50	-2.00	+3.00	5.00	-2.00
12.41	15 75	+1.00	1.00	-0.70	+1.40	1.00	-1.00	+2.20	3.00	-1.40	+3.50	3.00	-2.20	+3.50	6.00	-2.20

Nominal Size Range Inches		Class RC6 Medium Running			Class RC7 Free Running			Class RC8 Loose Running			Class RC9 Loose Running		
		Hole Tol. GR9	Minimum Clearance	Shaft Tol. GR8	Hole Tol. GR9	Minimum Clearance	Shaft Tol. GR8	Hole Tol. GR10	Minimum Clearance	Shaft Tol. GR9	Hole Tol. GR11	Minimum Clearance	Shaft Tol. GR10
Over	To	-0		+0	-0		+0	-0		+0	-0		+0
0	12	+1 00	0.60	-0.60	+1.00	1.00	-0.60	+1.60	2.50	-1.00	+2.50	4.00	-1.60
12	24	+1.20	0.80	-0.70	+1.20	1.20	-0.70	+1.80	2.80	-1.20	+3.00	4.50	-1.80
.24	.40	+1.40	1.00	-0.90	+1.40	1.60	-0.90	+2.20	3.00	-1.40	+3.50	6.00	-2.20
40	.71	+1.60	1.20	-1.00	+1.60	2.00	-1.00	+2.80	3.50	-1.60	+4.00	6.00	-2.80
.71	1.19	+2.00	1 60	-1 20	+2.00	2.50	-1.20	+3.50	4.50	-2.00	+5.00	7.00	-3.50
1.19	1.97	+2.50	2.00	-1.60	+2.50	3.00	-1.60	+4.00	5.00	-2 50	+6.00	8.00	-4.00
1.97	3 15	+3 00	2.50	-1.80	+3.00	4.00	-1.80	+4.50	6.00	-3.00	+7.00	9.00	-4.50
3 15	4 73	+3 50	3.00	-2.20	+3 50	5.00	-2.20	+5.00	7.00	-3.50	+9.00	10.00	-5.00
4.73	7 09	+4.00	3.50	-2 50	+4.00	6.00	-2.50	+6.00	8.00	-4.00	+10.00	12.00	-6.00
7 09	9.85	+4 50	4.00	-2 80	+4.50	7.00	-2.80	+7.00	10.00	-4 50	+12.00	15 00	-7.00
9.85	12.41	+5 00	5.00	-3.00	+5.00	8.00	-3.00	+8.00	12.00	-5.00	+12.00	18.00	-8.00
12.41	15 75	+6.00	6.00	-3.50	+6.00	10.00	-3.50	+9.00	14.00	-6.00	+14.00	22.00	-9.00

VALUES IN MILLIMETERS

Nominal Size Range Millimeters		Class RC1 Precision Sliding			Class RC2 Sliding Fit			Class RC3 Precision Running			Class RC4 Close Running			Class RC5 Medium Running		
		Hole Tol. H5	Minimum Clearance	Shaft Tol. g4	Hole Tol. H6	Minimum Clearance	Shaft Tol. g5	Hole Tol. H7	Minimum Clearance	Shaft Tol. f6	Hole Tol. H8	Minimum Clearance	Shaft Tol. f7	Hole Tol. H8	Minimum Clearance	Shaft Tol. e7
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	3	+0.004	0.003	-0.003	+0.006	0.003	-0.004	+0.010	0.008	-0.006	+0.015	0.008	-0.010	+0.015	0.015	-0.010
3	6	+0.005	0.004	-0.004	+0.008	0.004	-0.005	+0.013	0.010	-0.008	+0.018	0.010	-0.013	+0.018	0.020	-0.013
6	10	+0.006	0.005	-0.004	+0.010	0.005	-0.006	+0.015	0.013	-0.010	+0.023	0.013	-0.015	+0.023	0.025	-0.015
10	18	+0.008	0.006	-0.005	+0.010	0.006	-0.008	+0.018	0.015	-0.010	+0.025	0.015	-0.018	+0.025	0.030	-0.018
18	30	+0.010	0.008	-0.006	+0.013	0.008	-0.010	+0.020	0.020	-0.013	+0.030	0.020	-0.020	+0.030	0.040	-0.020
30	50	+0.010	0.010	-0.008	+0.015	0.010	-0.010	+0.030	0.030	-0.015	+0.040	0.030	-0.030	+0.040	0.050	-0.030
50	80	+0.013	0.010	-0.008	+0.018	0.010	-0.013	+0.030	0.030	-0.020	+0.050	0.030	-0.030	+0.050	0.060	-0.030
80	120	+0.015	0.013	-0.010	+0.023	0.013	-0.015	+0.040	0.040	-0.020	+0.060	0.040	-0.040	+0.060	0.080	-0.040
120	180	+0.018	0.015	-0.013	+0.025	0.015	-0.018	+0.040	0.040	-0.030	+0.060	0.040	-0.040	+0.060	0.090	-0.040
180	250	+0.020	0.015	-0.015	+0.030	0.015	-0.020	+0.050	0.050	-0.030	+0.070	0.050	-0.050	+0.070	0.110	-0.050
250	315	+0.023	0.020	-0.015	+0.030	0.020	-0.023	+0.050	0.060	-0.030	+0.080	0.060	-0.050	+0.080	0.130	-0.050
315	400	+0.025	0.025	-0.018	+0.036	0.025	-0.025	+0.060	0.080	-0.040	+0.090	0.080	-0.060	+0.090	0.150	-0.060

Nominal Size Range Millimeters		Class RC6 Medium Running			Class RC7 Free Running			Class RC8 Loose Running			Class RC9 Loose Running		
		Hole Tol. H9	Minimum Clearance	Shaft Tol. e8	Hole Tol. H9	Minimum Clearance	Shaft Tol. d8	Hole Tol. H10	Minimum Clearance	Shaft Tol. e9	Hole Tol. GR11	Minimum Clearance	Shaft Tol. gr10
Over	To	-0		+0	-0		+0	-0		+0	-0		+0
0	3	+0.025	0.015	-0.015	+0.025	0.025	-0.015	+0.041	0.064	-0.025	+0.060	0.100	-0.040
3	6	+0.030	0.015	-0.018	+0.030	0.030	-0.018	+0.046	0.071	-0.030	+0.080	0.110	-0.050
6	10	+0.036	0.025	-0.023	+0.036	0.040	-0.023	+0.056	0.076	-0.036	+0.070	0.130	-0.060
10	18	+0.040	0.030	-0.025	+0.040	0.050	-0.025	+0.070	0.090	-0.040	+0.100	0.150	-0.070
18	30	+0.050	0.040	-0.030	+0.050	0.060	-0.030	+0.090	0.110	-0.050	+0.130	0.180	-0.090
30	50	+0.060	0.050	-0.040	+0.060	0.080	-0.040	+0.100	0.130	-0.060	+0.150	0.200	-0.100
50	80	+0.080	0.060	-0.050	+0.080	0.100	-0.050	+0.110	0.150	-0.080	+0.180	0.230	-0.120
80	120	+0.090	0.080	-0.060	+0.090	0.130	-0.060	+0.130	0.180	-0.090	+0.230	0.250	-0.130
120	180	+0.100	0.090	-0.060	+0.100	0.150	-0.060	+0.150	0.200	-0.100	+0.250	0.300	-0.150
180	250	+0 110	0.100	-0.070	+0.110	0.180	-0.070	+0.180	0.250	-0.110	+0.300	0.380	-0.180
250	315	+0.130	0 130	-0.080	+0.130	0.200	-0.080	+0.200	0.300	-0.130	+0.300	0.460	-0.200
315	400	+0.150	0.150	-0.090	+0.150	0.250	-0.090	+0.230	0.360	-0.150	+0.360	0.560	-0.230

TABLE 9 From *Drafting for Trades and Industry—Mechanical and Electronic,* Nelson. Delmar Publishers Inc.

LOCATIONAL CLEARANCE FITS

VALUES IN THOUSANDTHS OF AN INCH

Nominal Size Range Inches		Class LC1			Class LC2			Class LC3			Class LC4			Class LC5			Class LC6		
		Hole Tol. GR6	Minimum Clearance	Shaft Tol. GR5	Hole Tol. GR8	Minimum Clearance	Shaft Tol. GR7	Hole Tol. GR10	Minimum Clearance	Shaft Tol. GR9	Hole Tol. GR7	Minimum Clearance	Shaft Tol. GR6	Hole Tol. GR9	Minimum Clearance	Shaft Tol. GR8	Hole Tol. GR9	Minimum Clearance	Shaft Tol. GR8
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	.12	+0.25	0	-0.15	+0.4	0	-0.25	+0.6	0	-0.4	+1.6	0	-1.0	+0.4	0.10	-0.25	+1.0	0.3	-0.6
.12	.24	+0.30	0	-0.20	+0.5	0	-0.30	+0.7	0	-0.5	+1.8	0	-1.2	+0.5	0.15	-0.30	+1.2	0.4	-0.7
.24	.40	+0.40	0	-0.25	+0.6	0	-0.40	+0.9	0	-0.6	+2.2	0	-1.4	+0.6	0.20	-0.40	+1.4	0.5	-0.9
.40	.71	+0.40	0	-0.30	+0.7	0	-0.40	+1.0	0	-0.7	+2.8	0	-1.6	+0.7	0.25	-0.40	+1.6	0.6	-1.0
.71	1.19	+0.50	0	-0 40	+0.8	0	-0.50	+1.2	0	-0.8	+3.5	0	-2.0	+0.8	0.30	-0.50	+2.0	0.8	-1.2
1.19	1.97	+0.60	0	-0.40	+1.0	0	-0.60	+1.6	0	-1.0	+4.0	0	-2.5	+1.0	0.40	-0.60	+2.5	1.0	-1.6
1.97	3.15	+0.70	0	-0.50	+1.2	0	-0.70	+1.8	0	-1.2	+4.5	0	-3.0	+1.2	0.40	-0.70	+3.0	1.2	-1.8
3.15	4.73	+0.90	0	-0.60	+1.4	0	-0.90	+2.7	0	-1.4	+5.0	0	-3.5	+1.4	0.50	-0.90	+3.5	1.4	-2.2
4.73	7.09	+1.00	0	-0.70	+1.6	0	-1.00	+2.5	0	-1.6	+6.0	0	-4.0	+1.6	0.60	-1.00	+4.0	1.6	-2.5
7.09	9.85	+1.20	0	-0.80	+1.8	0	-1.20	+2.8	0	-1.8	+7.0	0	-4.5	+1.8	0.60	-1.20	+4.5	2.0	-2.8
9.85	12.41	+1.20	0	-0.90	+2.0	0	-1.20	+3.0	0	-2.0	+8.0	0	-5.0	+2.0	0.70	-1.20	+5.0	2.2	-3.0
12.41	15.75	+1.40	0	-1.00	+2.2	0	-1.40	+3.5	0	-2.2	+9.0	0	-6.0	+2.2	0.70	-1.40	+6.0	2.5	-3.5

Nominal Size Range Inches		Class LC7			Class LC8			Class LC9			Class LC10			Class LC11		
		Hole Tol. GR10	Minimum Clearance	Shaft Tol. GR9	Hole Tol. GR10	Minimum Clearance	Shaft Tol. GR9	Hole Tol. GR11	Minimum Clearance	Shaft Tol. GR10	Hole Tol. GR12	Minimum Clearance	Shaft Tol. GR11	Hole Tol. GR13	Minimum Clearance	Shaft Tol. GR12
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	12	+1.6	0.6	-1.0	+1.6	1.0	-1.0	+2.5	2.5	-1.6	+1.0	4.0	-2.5	+6.0	5.0	-4.0
.12	24	+1.8	0.8	-1.2	+1.8	1.2	-1.2	+3.0	2.8	-1.8	+5.0	4.5	-3.0	+7.0	6.0	-5.0
.24	.40	+2.2	1.0	-1.4	+2.2	1.6	-1.4	+3.5	3.0	-2.2	+6.0	5.0	-3.5	+9.0	7.0	-6.0
.40	.71	+2.8	1.2	-1.6	+2.8	2.0	-1.6	+4.0	3.5	-2.8	+7.0	6.0	-4.0	+10.0	8.0	-7.0
.71	1.19	+3 5	1.6	-2 0	+3.5	2.5	-2.0	+5.0	4.5	-3.5	+8.0	7.0	-5.0	+12.0	10.0	-8.0
1.19	1 97	+4.0	2.0	-2.5	+4.0	3.6	-2.5	+6.0	5.0	-4.0	+10.0	8.0	-6.0	+16.0	12.0	-10.0
1.97	3.15	+4.5	2.5	-3.0	+4.5	4.0	-3.0	+7.0	6.0	-4.5	+12.0	10.0	-7.0	+18.0	14.0	-12.0
3 15	4.73	+5.0	3.0	-3.5	+5.0	5.0	-3.5	+9.0	7.0	-5.0	+14.0	11.0	-9.0	+22.0	16.0	-14.0
4.73	7 09	+6.0	3.5	-4.0	+6.0	6.0	-4.0	+10.0	8.0	-6.0	+16.0	12.0	-10.0	+25.0	18.0	-16.0
7 09	9 85	+7.0	4 0	-4.5	+7.0	7.0	-4.5	+12.0	10.0	-7.0	+18.0	16.0	-12.0	+28.0	22.0	-18.0
9 85	12.41	+8.0	4.5	-5.0	+8.0	7.0	-5.0	+12.0	12.0	-8.0	+20.0	20.0	-12.0	+30.0	28.0	-20.0
12.41	15.75	+9.0	5.0	-6.0	+9.0	8.0	-6.0	+14.0	14.0	-9.0	+22.0	22.0	-14.0	+35.0	30.0	-22.0

VALUES IN MILLIMETERS

Nominal Size Range Millimeters		Class LC1			Class LC2			Class LC3			Class LC4			Class LC5			Class LC6		
		Hole Tol. H6	Minimum Clearance	Shaft Tol. h5	Hole Tol. H7	Minimum Clearance	Shaft Tol. h6	Hole Tol. H8	Minimum Clearance	Shaft Tol. h7	Hole Tol. H10	Minimum Clearance	Shaft Tol. h9	Hole Tol. H7	Minimum Clearance	Shaft Tol. g6	Hole Tol. H9	Minimum Clearance	Shaft Tol. f8
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	3	+0.006	0	-0.004	+0.010	0	-0.006	+0.015	0	-0.010	+0.041	0	-0.025	+0.010	0.002	-0.006	+0.025	0.008	-0.015
3	6	+0.008	0	-0.005	+0.013	0	-0.008	+0.018	0	-0.013	+0.046	0	-0.030	+0.013	0.004	-0.008	+0.030	0.010	-0.018
6	10	+0.010	0	-0.006	+0.015	0	-0.010	+0.023	0	-0.015	+0.056	0	-0.036	+0.015	0.005	-0.010	+0.036	0.013	-0.023
10	18	+0.010	0	-0.008	+0.018	0	-0.010	+0.025	0	-0.018	+0.070	0	-0.040	+0.018	0.006	-0.010	+0.041	0.015	-0.025
18	30	+0.013	0	-0.010	+0.020	0	-0.013	+0.030	0	-0.020	+0.090	0	-0.050	+0.020	0.008	-0.013	+0.050	0.020	-0.030
30	50	+0.015	0	-0.010	+0.025	0	-0.015	+0.041	0	-0.025	+0.100	0	-0.060	+0.025	0.010	-0.015	+0.060	0.030	-0.040
50	80	+0.018	0	-0.013	+0.030	0	-0.018	+0.046	0	-0.030	+0.110	0	-0.080	+0.030	0.010	-0.018	+0.080	0.030	-0.050
80	120	+0.023	0	-0.015	+0.036	0	-0.023	+0.056	0	-0.036	+0.130	0	-0.080	+0.036	0.013	-0.023	+0.090	0.040	-0.060
120	180	+0.025	0	-0.018	+0.041	0	-0.025	+0.064	0	-0.041	+0.150	0	-0.100	+0.041	0.015	-0.025	+0.100	0.040	-0.060
180	250	+0.030	0	-0.020	+0.046	0	-0.030	+0.071	0	-0.046	+0.180	0	-0.110	+0.046	0.015	-0.030	+0.110	0.050	-0.070
250	315	+0.020	0	-0.023	+0.051	0	-0.030	+0.076	0	-0.051	+0.200	0	-0.130	+0.051	0.018	-0.030	+0.130	0.060	-0.080
315	400	+0.036	0	-0.025	+0.056	0	-0.036	+0.089	0	-0.056	+0.230	0	-0.150	+0.056	0.018	-0.036	+0.150	0.060	-0.090

Nominal Size Range Millimeters		Class LC7			Class LC8			Class LC9			Class LC10			Class LC11		
		Hole Tol. H10	Minimum Clearance	Shaft Tol. e9	Hole Tol. H10	Minimum Clearance	Shaft Tol. d9	Hole Tol. H11	Minimum Clearance	Shaft Tol. c10	Hole Tol. GR12	Minimum Clearance	Shaft Tol. gr11	Hole Tol. GR13	Minimum Clearance	Shaft Tol. gr12
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	3	+0.041	0.015	-0.025	+0.041	0.025	-0.025	+0.064	0.06	-0.041	+0.10	0.10	-0.06	+0.15	0.13	-0.10
3	6	+0.046	0.020	-0.030	+0.046	0.030	-0.030	+0.076	0.07	-0.46	+0.13	0.11	-0.08	+0.18	0.15	-0.13
6	10	+0.056	0.025	-0.036	+0.056	0.041	-0.036	+0.089	0.08	-0.56	+0.15	0.13	-0.09	+0.23	0.18	-0.15
10	18	+0.070	0.030	-0.040	+0.070	0.050	-0.040	+0.100	0.09	-0.70	+0.18	0.15	-0.10	+0.25	0.20	-0.18
18	30	+0.090	0.040	-0.050	+0.090	0.060	-0.050	+0.130	0.11	-0.90	+0.20	0.18	-0.13	+0.31	0.25	-0.20
30	50	+0.100	0.050	-0.060	+0.100	0.090	-0.060	+0.150	0.13	-0.100	+0.25	0.20	-0.15	+0.41	0.31	-0.25
50	80	+0.110	0.060	-0.080	+0.110	0.100	-0.080	+0.180	0.15	-0.110	+0.31	0.25	-0.18	+0.46	0.36	-0.31
80	120	+0.130	0.080	-0.090	+0.130	0.130	-0.090	+0.230	0.18	-0.130	+0.36	0.28	-0.23	+0.56	0.41	-0.36
120	180	+0.150	0.090	-0.100	+0.150	0.150	-0.100	+0.250	0.20	-0.150	+0.41	0.31	-0.25	+0.64	0.46	-0.41
180	250	+0.180	0.100	-0.110	+0.180	0.180	-0.110	+0.310	0.25	-0.180	+0.46	0.41	-0.31	+0.71	0.56	-0.46
250	315	+0.200	0.110	-0.130	+0.200	0.180	-0.130	+0.310	0.31	-0.200	+0.51	0.51	-0.31	+0.76	0.71	-0.51
315	400	+0.230	0.130	-0.150	+0.230	0.200	-0.150	+0.360	0.36	-0.230	+0.56	0.56	-0.36	+0.89	0.76	-0.56

TABLE 10 From *Drafting for Trades and Industry—Mechanical and Electronic,* Nelson. Delmar Publishers Inc.

LOCATIONAL TRANSITION FITS

VALUES IN THOUSANDTHS OF AN INCH

Nominal Size Range Inches		Class LT1			Class LT2			Class LT3			Class LT4			Class LT5			Class LT6		
		Hole Tol. GR7	Maximum Interference	Shaft Tol. GR6	Hole Tol. GR8	Maximum Interference	Shaft Tol. GR7	Hole Tol. GR7	Maximum Interference	Shaft Tol. GR6	Hole Tol. GR8	Maximum Interference	Shaft Tol. GR7	Hole Tol. GR7	Maximum Interference	Shaft Tol. GR6	Hole Tol. GR8	Maximum Interference	Shaft Tol. GR7
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	.12	+0.4	0.10	-0.25	+0.6	0.20	-0.4	+0.4	0.25	-0.25	+0.6	0.4	-0.4	+0.4	0.5	-0.25	+0.6	0.65	-0.4
.12	.24	+0.5	0.15	-0.30	+0.7	0.25	-0.5	+0.5	0.40	-0.30	+0.7	0.6	-0.5	+0.5	0.6	-0.30	+0.7	0.80	-0.5
.24	.40	+0.6	0.20	-0.40	+0.9	0.30	-0.6	+0.6	0.50	-0.40	+0.9	0.7	-0.6	+0.6	0.8	-0.40	+0.9	1.00	-0.6
.40	.71	+0.7	0.20	-0.40	+1.0	0.30	-0.7	+0.7	0.50	-0.40	+1.0	0.8	-0.7	+0.7	0.9	-0.40	+1.0	1.20	-0.7
.71	1.19	+0.8	0.25	-0.50	+1.2	0.40	-0.8	+0.8	0.60	-0.50	+1.2	0.9	-0.8	+0.8	1.1	-0.50	+1.2	1.40	-0.8
1.19	1.97	+1.0	0.30	-0.60	+1.6	0.50	-1.0	+1.0	0.70	-0.60	+1.6	1.1	-1.0	+1.0	1.3	-0.60	+1.6	1.70	-1.0
1.97	3.15	+1.2	0.30	-0.70	+1.8	0.60	-1.2	+1.2	0.80	-0.70	+1.8	1.3	-1.2	+1.2	1.5	-0.70	+1.8	2.00	-1.2
3.15	4.73	+1.4	0.40	-0.90	+2.2	0.70	-1.4	+1.4	1.00	-0.90	+2.2	1.5	-1.4	+1.4	1.9	-0.90	+2.2	2.40	-1.4
4.73	7.09	+1.6	0.50	-1.00	+2.5	0.80	-1.6	+1.6	1.10	-1.00	+2.5	1.7	-1.6	+1.6	2.2	-1.00	+2.5	2.80	-1.6
7.09	9.85	+1.8	0.60	-1.20	+2.8	0.90	-1.8	+1.8	1.40	-1.20	+2.8	2.0	-1.8	+1.8	2.6	-1.20	+2.8	3.20	-1.8
9.85	12.41	+2.0	0.60	-1.20	+3.0	1.00	-2.0	+2.0	1.40	-1.20	+3.0	2.2	-2.0	+2.0	2.6	-1.20	+3.0	3.40	-2.0
12.41	15.75	+2.2	0.70	-1.40	+3.5	1.00	-2.2	+2.2	1.60	-1.40	+3.5	2.4	-2.2	+2.2	3.0	-1.40	+3.5	3.80	-2.2

VALUES IN MILLIMETERS

Nominal Size Range Millimeters		Class LT1			Class LT2			Class LT3			Class LT4			Class LT5			Class LT6		
		Hole Tol. H7	Maximum Clearance	Shaft Tol. js6	Hole Tol. H8	Maximum Clearance	Shaft Tol. js7	Hole Tol. H7	Maximum Clearance	Shaft Tol. k6	Hole Tol. H8	Maximum Clearance	Shaft Tol. k7	Hole Tol. H7	Maximum Clearance	Shaft Tol. n6	Hole Tol. H8	Maximum Clearance	Shaft Tol. n7
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	3	+0.010	0.002	-0.006	+0.015	0.005	-0.010	+0.010	0.006	-0.006	+0.015	0.010	-0.010	+0.010	0.013	-0.006	+0.015	0.016	-0.010
3	6	+0.013	0.004	-0.008	+0.018	0.006	-0.013	+0.013	0.010	-0.008	+0.018	0.015	-0.013	+0.013	0.015	-0.008	+0.018	0.020	-0.013
6	10	+0.015	0.005	-0.010	+0.023	0.008	-0.015	+0.015	0.013	-0.010	+0.023	0.018	-0.015	+0.015	0.020	-0.010	+0.023	0.025	-0.015
10	18	+0.018	0.005	-0.010	+0.025	0.008	-0.018	+0.018	0.013	-0.010	+0.025	0.020	-0.018	+0.018	0.023	-0.010	+0.025	0.030	-0.018
18	30	+0.020	0.006	-0.013	+0.030	0.010	-0.020	+0.020	0.015	-0.013	+0.030	0.023	-0.020	+0.020	0.028	-0.013	+0.030	0.036	-0.020
30	50	+0.025	0.008	-0.015	+0.041	0.013	-0.025	+0.025	0.018	-0.015	+0.041	0.028	-0.025	+0.025	0.033	-0.015	+0.041	0.044	-0.025
50	80	+0.030	0.008	-0.018	+0.046	0.015	-0.030	+0.030	0.020	-0.018	+0.046	0.033	-0.030	+0.030	0.038	-0.018	+0.046	0.051	-0.030
80	120	+0.036	0.010	-0.023	+0.056	0.018	-0.036	+0.036	0.025	-0.023	+0.056	0.038	-0.036	+0.036	0.048	-0.023	+0.056	0.062	-0.036
120	180	+0.041	0.013	-0.025	+0.064	0.020	-0.041	+0.041	0.028	-0.025	+0.064	0.044	-0.041	+0.041	0.056	-0.025	+0.064	0.071	-0.041
180	250	+0.046	0.015	-0.030	+0.071	0.023	-0.046	+0.046	0.036	-0.030	+0.071	0.051	-0.046	+0.046	0.066	-0.030	+0.071	0.081	-0.046
250	315	+0.051	0.015	-0.030	+0.076	0.025	-0.051	+0.051	0.036	-0.030	+0.076	0.056	-0.051	+0.051	0.066	-0.030	+0.076	0.086	-0.051
315	400	+0.056	0.018	-0.036	+0.089	0.025	-0.056	+0.056	0.041	-0.036	+0.089	0.062	-0.056	+0.056	0.076	-0.036	+0.089	0.096	-0.056

TABLE 11 From *Drafting for Trades and Industry—Mechanical and Electronic,* Nelson. Delmar Publishers Inc.

LOCATIONAL INTERFERENCE FITS

VALUES IN THOUSANDTHS OF AN INCH

Nominal Size Range Inches		Class LN1 Light Press Fit			Class LN2 Medium Press Fit			Class LN3 Heavy Press Fit			Class LN4			Class LN5			Class LN6		
		Hole Tol. GR6	Maximum Interference	Shaft Tol. GR5	Hole Tol. GR7	Maximum Interference	Shaft Tol. GR6	Hole Tol. GR7	Maximum Interference	Shaft Tol. GR6	Hole Tol. GR8	Maximum Interference	Shaft Tol. GR7	Hole Tol. GR9	Maximum Interference	Shaft Tol. GR8	Hole Tol. GR10	Maximum Interference	Shaft Tol. GR9
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	.12	+0.25	0.40	-0.15	+0.4	0.65	-0.25	+0.4	0.75	-0.25	+0.6	1.2	-0.4	+1.0	1.8	-0.6	+1.6	3.0	-1.0
.12	.24	+0.30	0.50	-0.20	+0.5	0.80	-0.30	+0.5	0.90	-0.30	+0.7	1.5	-0.5	+1.2	2.3	-0.7	+1.8	3.6	-1.2
.24	.40	+0.40	0.65	-0.25	+0.6	1.00	-0.40	+0.6	1.20	-0.40	+0.9	1.8	-0.6	+1.4	2.8	-0.9	+2.2	4.4	-1.4
.40	.71	+0.40	0.70	-0.30	+0.7	1.10	-0.40	+0.7	1.40	-0.40	+1.0	2.2	-0.7	+1.6	3.4	-1.0	+2.8	5.6	-1.6
.71	1.19	+0.50	0.90	-0.40	+0.8	1.30	-0.50	+0.8	1.70	-0.50	+1.2	2.6	-0.8	+2.0	4.2	-1.2	+3.5	7.0	-2.0
1.19	1.97	+0.60	1.00	-0.40	+1.0	1.60	-0.60	+1.0	2.00	-0.60	+1.6	3.4	-1.0	+2.5	5.3	-1.6	+4.0	8.5	-2.5
1.97	3.15	+0.70	1.30	-0.50	+1.2	2.10	-0.70	+1.2	2.30	-0.70	+1.8	4.0	-1.2	+3.0	6.3	-1.8	+4.5	10.0	-3.0
3.15	4.73	+0.90	1.60	-0.60	+1.4	2.50	-0.90	+1.4	2.90	-0.90	+2.2	4.8	-1.4	+4.0	7.7	-2.2	+5.0	11.5	-3.5
4.73	7.09	+1.00	1.90	-0.70	+1.6	2.80	-1.00	+1.6	3.50	-1.00	+2.5	5.6	-1.6	+4.5	8.7	-2.5	+6.0	13.5	-4.0
7.09	9.85	+1.20	2.20	-0.80	+1.8	3.20	-1.20	+1.8	4.20	-1.20	+2.8	6.6	-1.8	+5.0	10.3	-2.8	+7.0	16.5	-4.5
9.85	12.41	+1.20	2.30	-0.90	+2.0	3.40	-1.20	+2.0	4.70	-1.20	+3.0	7.5	-2.0	+6.0	12.0	-3.0	+8.0	19.0	-5.0
12.41	15.75	+1.40	2.60	-1.00	+2.2	3.90	-1.40	+2.2	5.90	-1.40	+3.5	8.7	-2.2	+6.0	14.5	-3.5	+9.0	23.0	-6.0

VALUES IN MILLIMETERS

Nominal Size Range Millimeters		Class LN1 Light Press Fit			Class LN2 Medium Press Fit			Class LN3 Heavy Press Fit			Class LN4			Class LN5			Class LN6		
		Hole Tol. GR6	Maximum Interference	Shaft Tol. gr5	Hole Tol. H7	Maximum Interference	Shaft Tol. p6	Hole Tol. H7	Maximum Interference	Shaft Tol. t6	Hole Tol. GR8	Maximum Interference	Shaft Tol. gr7	Hole Tol. GR9	Maximum Interference	Shaft Tol. gr8	Hole Tol. GR10	Maximum Interference	Shaft Tol. gr9
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	3	+0.006		-0.004	+0.010	0.016	-0.006	+0.010	0.019	-0.006	+0.015	0.030	-0.010	+0.025	0.046	-0.015	+0.041	0.076	-0.025
3	6	+0.008		-0.005	+0.013	0.020	-0.008	+0.013	0.023	-0.008	+0.018	0.038	-0.013	+0.030	0.059	-0.018	+0.046	0.091	-0.030
6	10	+0.010		-0.006	+0.015	0.025	-0.010	+0.015	0.030	-0.010	+0.023	0.046	-0.015	+0.036	0.071	-0.023	+0.056	0.112	-0.036
10	18	+0.010		-0.008	+0.018	0.028	-0.010	+0.018	0.036	-0.010	+0.025	0.056	-0.018	+0.041	0.086	-0.025	+0.071	0.142	-0.041
18	30	+0.013		-0.010	+0.020	0.033	-0.013	+0.020	0.044	-0.013	+0.030	0.066	-0.020	+0.051	0.107	-0.030	+0.089	0.178	-0.051
30	50	+0.015		-0.010	+0.025	0.041	-0.015	+0.025	0.051	-0.015	+0.041	0.086	-0.025	+0.064	0.135	-0.041	+0.102	0.216	-0.064
50	80	+0.018		-0.013	+0.030	0.054	-0.018	+0.030	0.059	-0.018	+0.046	0.102	-0.030	+0.076	0.160	-0.046	+0.114	0.254	-0.076
80	120	+0.023		-0.015	+0.036	0.064	-0.023	+0.036	0.074	-0.023	+0.056	0.122	-0.036	+0.102	0.196	-0.056	+0.127	0.292	-0.102
120	180	+0.025		-0.018	+0.041	0.071	-0.025	+0.041	0.089	-0.025	+0.064	0.142	-0.041	+0.114	0.221	-0.064	+0.152	0.343	-0.114
180	250	+0.030		-0.020	+0.046	0.081	-0.030	+0.046	0.107	-0.030	+0.071	0.168	-0.046	+0.127	0.262	-0.071	+0.178	0.419	-0.127
250	315	+0.030		-0.023	+0.051	0.086	-0.030	+0.051	0.119	-0.030	+0.076	0.191	-0.051	+0.152	0.305	-0.076	+0.203	0.483	-0.152
315	400	+0.036		-0.025	+0.056	0.099	-0.036	+0.056	0.150	-0.036	+0.089	0.221	-0.056	+0.152	0.368	-0.089	+0.229	0.584	-0.152

TABLE 12 From *Drafting for Trades and Industry—Mechanical and Electronic,* Nelson. Delmar Publishers Inc.

FORCE AND SHRINK FITS

VALUES IN THOUSANDTHS OF AN INCH

Nominal Size Range Inches		Class FN1 Light Drive Fit			Class FN2 Medium Drive Fit			Class FN3 Heavy Drive Fit			Class FN4 Shrink Fit			Class FN5 Heavy Shrink Fit		
		Hole Tol. GR6	Maximum Interference	Shaft Tol. GR5	Hole Tol. GR7	Maximum Interference	Shaft Tol. GR6	Hole Tol. GR7	Maximum Interference	Shaft Tol. GR6	Hole Tol. GR7	Maximum Interference	Shaft Tol. GR6	Hole Tol. GR8	Maximum Interference	Shaft Tol. GR7
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	.12	+0.25	0.50	-0.15	+0.40	0.85	-0.25				+0.40	0.95	-0.25	+0.60	1.30	-0.40
.12	.24	+0.30	0.60	-0.20	+0.50	1.00	-0.30				+0.50	1.20	-0.30	+0.70	1.70	-0.50
.24	.40	+0.40	0.75	-0.25	+0.60	1.40	-0.40				+0.60	1.60	-0.40	+0.90	2.00	-0.60
.40	.56	+0.40	0.80	-0.30	+0.70	1.60	-0.40				+0.70	1.80	-0.40	+1.00	2.30	-0.70
.56	.71	+0.40	0.90	-0.30	+0.70	1.60	-0.40				+0.70	1.80	-0.40	+1.00	2.50	-0.70
.71	.95	+0.50	1.10	-0.40	+0.80	1.90	-0.50				+0.80	2.10	-0.50	+1.20	3.00	-0.80
.95	1.19	+0.50	1.20	-0.40	+0.80	1.90	-0.50	+0.80	2.10	-0.50	+0.80	2.30	-0.50	+1.20	3.30	-0.80
1.19	1.58	+0.60	1.30	-0.40	+1.00	2.40	-0.60	+1.00	2.60	-0.60	+1.00	3.10	-0.60	+1.60	4.00	-1.00
1.58	1.97	+0.60	1.40	-0.40	+1.00	2.40	-0.60	+1.00	2.80	-0.60	+1.00	3.40	-0.60	+1.60	5.00	-1.00
1.97	2.56	+0.70	1.80	-0.50	+1.20	2.70	-0.70	+1.20	3.20	-0.70	+1.20	4.20	-0.70	+1.80	6.20	-1.20
2.56	3.15	+0.70	1.90	-0.50	+1.20	2.90	-0.70	+1.20	3.70	-0.70	+1.20	4.70	-0.70	+1.80	7.20	-1.20
3.15	3.94	+0.90	2.40	-0.60	+1.40	3.70	-0.90	+1.40	4.40	-0.70	+1.40	5.90	-0.90	+2.20	8 40	-1.40

VALUES IN MILLIMETERS

Nominal Size Range Millimeters		Class FN1 Light Drive Fit			Class FN2 Medium Drive Fit			Class FN3 Heavy Drive Fit			Class FN4 Shrink Fit			Class FN5 Heavy Shrink Fit		
		Hole Tol. GR6	Maximum Interference	Shaft Tol. gr5	Hole Tol. H7	Maximum Interference	Shaft Tol. s6	Hole Tol. H7	Maximum Interference	Shaft Tol. t6	Hole Tol. GR8	Maximum Interference	Shaft Tol. gr7	Hole Tol. H8	Maximum Interference	Shaft Tol. t7
Over	To	-0		+0	-0		+0	-0		+0	-0		+0	-0		+0
0	3	+0.006	0.013	-0.004	+0.010	0.216	-0.006				+0.010	0.024	-0.006	+0.015	0.033	-0.010
3	6	+0.007	0.015	-0.005	+0.013	0.025	-0.007				+0.013	0.030	-0.007	+0.018	0.043	-0.013
6	10	+0.010	0.019	-0.006	+0.015	0.036	-0.010				+0.015	0.041	-0.010	+0.023	0.051	-0.015
10	14	+0.010	0.020	-0.008	+0.018	0.041	-0.010				+0.018	0.046	-0.010	+0.025	0.058	-0.018
14	18	+0.010	0.023	-0.008	+0.018	0.041	-0.010				+0.018	0.046	-0.010	+0.025	0.064	-0.018
18	24	+0.013	0.028	-0.010	+0.020	0.048	-0.013				+0.020	0.053	-0.013	+0.030	0.076	-0.020
24	30	+0.013	0.030	-0.010	+0.020	0.048	-0.013	+0.020	0.053	-0.013	+0.020	0.058	-0.013	+0.030	0.084	-0.020
30	40	+0.015	0.033	-0.010	+0.025	0.061	-0.015	+0.025	0.066	-0.015	+0.025	0.079	-0.015	+0.041	0.102	-0.025
40	50	+0.015	0.036	-0.010	+0.025	0.061	-0.015	+0.025	0.071	-0.015	+0.025	0.086	-0.015	+0.041	0.127	-0.025
50	65	+0.018	0.046	-0.013	+0.030	0.069	-0.018	+0.030	0.082	-0.018	+0.030	0 107	-0.018	+0.046	0.157	-0.030
65	80	+0.018	0.048	-0.013	+0.030	0.074	-0.018	+0.030	0.094	-0.018	+0.030	0.119	-0.018	+0.046	0.183	-0.030
80	100	+0.023	0.061	-0.015	+0.035	0.094	-0.023	+0.035	0.112	-0.023	+0.036	0.150	-0.023	+0.056	0.213	-0.036

TABLE 13 From *Drafting for Trades and Industry—Mechanical and Electronic,* Nelson. Delmar Publishers Inc.

UNIFIED STANDARD SCREW THREAD SERIES

Sizes		Basic Major Diameter	THREADS PER INCH											Sizes
			Series with graded pitches			Series with constant pitches								
Primary	Secondary		Coarse UNC	Fine UNF	Extra fine UNEF	4UN	6UN	8UN	12UN	16UN	20UN	28UN	32UN	
0		0.0600	–	80	–	–	–	–	–	–	–	–	–	0
	1	0.0730	64	72	–	–	–	–	–	–	–	–	–	1
2		0.0860	56	64	–	–	–	–	–	–	–	–	–	2
	3	0.0990	48	56	–	–	–	–	–	–	–	–	–	3
4		0.1120	40	48	–	–	–	–	–	–	–	–	–	4
5		0.1250	40	44	–	–	–	–	–	–	–	–	–	5
6		0.1380	32	40	–	–	–	–	–	–	–	–	UNC	6
8		0.1640	32	36	–	–	–	–	–	–	–	–	UNC	8
10		0.1900	24	32	–	–	–	–	–	–	–	–	UNF	10
	12	0.2160	24	28	32	–	–	–	–	–	–	UNF	UNEF	12
1/4		0.2500	20	28	32	–	–	–	–	–	UNC	UNF	UNEF	1/4
5/16		0.3125	18	24	32	–	–	–	–	–	20	28	UNEF	5/16
3/8		0.3750	16	24	32	–	–	–	–	UNC	20	28	UNEF	3/8
7/16		0.4375	14	20	28	–	–	–	–	16	UNF	UNEF	32	7/16
1/2		0.5000	13	20	28	–	–	–	–	16	UNF	UNEF	32	1/2
9/16		0.5625	12	18	24	–	–	–	UNC	16	20	28	32	9/16
5/8		0.6250	11	18	24	–	–	–	12	16	20	28	32	5/8
	11/16	0.6875	–	–	24	–	–	–	12	16	20	28	32	11/16
3/4		0.7500	10	16	20	–	–	–	12	UNF	UNEF	28	32	3/4
	13/16	0.8125	–	–	20	–	–	–	12	16	UNEF	28	32	13/16
7/8		0.8750	9	14	20	–	–	–	12	16	UNEF	28	32	7/8
	15/16	0.9375	–	–	20	–	–	–	12	16	UNEF	28	32	15/16
1		1.0000	8	12	20	–	–	UNC	UNF	16	UNEF	28	32	1
	1 1/16	1.0625	–	–	18	–	–	8	12	16	20	28	–	1 1/16
1 1/8		1.1250	7	12	18	–	–	8	UNF	16	20	28	–	1 1/8
	1 3/16	1.1875	–	–	18	–	–	8	12	16	20	28	–	1 3/16
1 1/4		1.2500	7	12	18	–	–	8	UNF	16	20	28	–	1 1/4
	1 5/16	1.3125	–	–	18	–	–	8	12	16	20	28	–	1 5/16
1 3/8		1.3750	6	12	18	–	UNC	8	UNF	16	20	28	–	1 3/8
	1 7/16	1.4375	–	–	18	–	6	8	12	16	20	28	–	1 7/16
1 1/2		1.5000	6	12	18	–	UNC	8	UNF	16	20	28	–	1 1/2
	1 9/16	1.5625	–	–	18	–	6	8	12	16	20	–	–	1 9/16
1 5/8		1.6250	–	–	18	–	6	8	12	16	20	–	–	1 5/8
	1 11/16	1.6875	–	–	18	–	6	8	12	16	20	–	–	1 11/16
1 3/4		1.7500	5	–	–	–	6	8	12	16	20	–	–	1 3/4
	1 13/16	1.8125	–	–	–	–	6	8	12	16	20	–	–	1 13/16
1 7/8		1.8750	–	–	–	–	6	8	12	16	20	–	–	1 7/8
	1 15/16	1.9375	–	–	–	–	6	8	12	16	20	–	–	1 15/16
2		2.0000	4 1/2	–	–	–	6	8	12	16	20	–	–	2
	2 1/8	2.1250	–	–	–	–	6	8	12	16	20	–	–	2 1/8
2 1/4		2.2500	4 1/2	–	–	–	6	8	12	16	20	–	–	2 1/4
	2 3/8	2.3750	–	–	–	–	6	8	12	16	20	–	–	2 3/8
2 1/2		2.5000	4	–	–	UNC	6	8	12	16	20	–	–	2 1/2
	2 5/8	2.6250	–	–	–	4	6	8	12	16	20	–	–	2 5/8
2 3/4		2.7500	4	–	–	UNC	6	8	12	16	20	–	–	2 3/4
	2 7/8	2.8750	–	–	–	4	6	8	12	16	20	–	–	2 7/8
3		3.0000	4	–	–	UNC	6	8	12	16	20	–	–	3
	3 1/8	3.1250	–	–	–	4	6	8	12	16	–	–	–	3 1/8
3 1/4		3.2500	4	–	–	UNC	6	8	12	16	–	–	–	3 1/4
	3 3/8	3.3750	–	–	–	4	6	8	12	16	–	–	–	3 3/8
3 1/2		3.5000	4	–	–	UNC	6	8	12	16	–	–	–	3 1/2
	3 5/8	3.6250	–	–	–	4	6	8	12	16	–	–	–	3 5/8
3 3/4		3.7500	4	–	–	UNC	6	8	12	16	–	–	–	3 3/4
	3 7/8	3.8750	–	–	–	4	6	8	12	16	–	–	–	3 7/8
4		4.0000	4	–	–	UNC	6	8	12	16	–	–	–	4
	4 1/8	4.1250	–	–	–	4	6	8	12	16	–	–	–	4 1/8
4 1/4		4.2500	–	–	–	4	6	8	12	16	–	–	–	4 1/4
	4 3/8	4.3750	–	–	–	4	6	8	12	16	–	–	–	4 3/8
4 1/2		4.5000	–	–	–	4	6	8	12	16	–	–	–	4 1/2
	4 5/8	4.6250	–	–	–	4	6	8	12	16	–	–	–	4 5/8
4 3/4		4.7500	–	–	–	4	6	8	12	16	–	–	–	4 3/4
	4 7/8	4.8750	–	–	–	4	6	8	12	16	–	–	–	4 7/8
5		5.0000	–	–	–	4	6	8	12	16	–	–	–	5
	5 1/8	5.1250	–	–	–	4	6	8	12	16	–	–	–	5 1/8
5 1/4		5.2500	–	–	–	4	6	8	12	16	–	–	–	5 1/4
	5 3/8	5.3750	–	–	–	4	6	8	12	16	–	–	–	5 3/8
5 1/2		5.5000	–	–	–	4	6	8	12	16	–	–	–	5 1/2
	5 5/8	5.6250	–	–	–	4	6	8	12	16	–	–	–	5 5/8
5 3/4		5.7500	–	–	–	4	6	8	12	16	–	–	–	5 3/4
	5 7/8	5.8750	–	–	–	4	6	8	12	16	–	–	–	5 7/8
6		6.0000	–	–	–	4	6	8	12	16	–	–	–	6

TABLE 14

DRILL AND TAP SIZES

DECIMAL EQUIVALENTS AND TAP DRILL SIZES
OF WIRE GAGE LETTER AND FRACTIONAL SIZE DRILLS
(TAP DRILL SIZES BASED ON 75% MAXIMUM THREAD)

FRACTIONAL SIZE DRILLS INCHES	WIRE GAGE DRILLS	DECIMAL EQUIVALENT INCHES	TAP SIZES		FRACTIONAL SIZE DRILLS INCHES	WIRE GAGE DRILLS	DECIMAL EQUIVALENT INCHES	TAP SIZES		FRACTIONAL SIZE DRILLS INCHES	WIRE GAGE DRILLS	DECIMAL EQUIVALENT INCHES	TAP SIZES	
			SIZE OF THREAD	THREADS PER INCH				SIZE OF THREAD	THREADS PER INCH				SIZE OF THREAD	THREADS PER INCH
	80	.0135			9/64	.....	.1406			23/64	.....	.3594		
	79	.0145				27	.1440				U	.3680	7/16	14
1/64	.....	.0156				26	.1470			3/8	... .	.3750		
	78	.0160				25	.1495	10	24					
											V	.3770		
	77	.0180				24	.1520				W	.3860		
	76	.0200				23	.1540			25/64	.....	.3906	7/16	20
	75	.0210			5/32	....	.1562				X	3970		
	74	.0225				22	.1570							
											Y	.4040		
	73	.0240				21	.1590	10	32	13/32	. . .	.4062		
	72	.0250				20	.1610				Z	.4130		
	71	.0260				19	.1660			27/64	. . .	.4219	1/2	13
	70	.0280				18	.1695							
										7/16	. . .	.4375		
	69	.0292			11/64	.....	.1719			29/64	. .	.4531	1/2	20
	68	.0310				17	.1730			15/32	. . .	4687		
1/32	.....	.0312				16	.1770	12	24	31/64	. . .	.4844	9/16	12
	67	.0320				15	.1800							
										1/2	. .	.5000		
	66	.0330				14	.1820	12	28	33/64	.....	.5156	9/16	18
	65	.0350				13	.1850			17/32	. . .	.5312	5/8	11
	64	.0360			3/16	.....	.1875			35/64	.	.5469		
	63	.0370				12	.1890							
										9/16	.....	.5625		
	62	.0380				11	.1910			37/64	. .	.5781	5/8	18
	61	.0390				10	1935			19/32	. . .	.5937		
	60	.0400				9	.1960			39/64	. .	.6094		
	59	.0410				8	.1990							
										5/8	. .	.6250		
	58	.0420				7	.2010	1/4	20	41/64	. . .	.6406		
	57	.0430			13/64	.....	.2031			21/32	..	.6562	3/4	10
	56	.0465				6	.2040			43/64	. . .	.6719		
3/64	.....	.0469	0	80		5	.2055							
										11/16	....	.6875	3/4	16
	55	.0520				4	.2090			45/64	. .	7031		
	54	.0550				3	.2130	1/4	28	23/32	. . .	.7187		
	53	.0595	1	64	7/32	.....	.2187			47/64	. .	.7344		
1/16	.....	.0625		72		2	.2210							
										3/4	. .	.7500		
	52	.0635				1	.2280			49/64	. . .	7656	7/8	9
	51	.0670				A	.2340			25/32	. . .	.7812		
	50	.0700	2	56	15/64	.....	.2344			51/64	. . .	.7969		
	49	.0730		64		B	.2380							
										13/16	. . .	.8125	7/8	14
	48	.0760				C	.2420			53/64	.....	.8281		
5/64	.....	.0781				D	.2460			27/32	. .	.8437		
	47	.0785	3	48	1/4	E	.2500			55/64	.....	8594		
	46	.0810				F	.2570	5/16	18					
										7/8	. . .	.8750	1	8
	45	.0820	3	56		G	.2610			57/64	. . .	8906		
	44	.0860			17/64	.....	.2656			29/32	. . .	.9062		
	43	.0890	4	40		H	.2660			59/64	. . .	9219		
	42	.0935	4	48		I	.2720	5/16	24					
										15/16	.....	.9375	1	12
3/32	.....	.0937				J	.2770			61/64	....	.9531		
	41	.0960				K	.2810			31/32	..	.9687		
	40	.0980			9/32	.....	.2812			63/64	....	.9844	1 1/8	7
	39	.0995				L	.2900							
										1	. . .	1.0000		
	38	.1015	5	40		M	.2950							
	37	.1040	5	44	19/64	.....	.2969							
	36	.1065	6	32		N	.3020							
7/64	.....	.1094			5/16	....	.3125	3/8	16					
	35	.1100				O	.3160							
	34	.1110				P	.3230							
	33	.1130	6	40	21/64	.....	.3281							
	32	.1160				Q	.3320	3/8	24					
	31	.1200				R	.3390							
1/8	.....	.1250			11/32	.....	.3437							
	30	.1285				S	.3480							
	29	.1360	8	32		T	.3580							
	28	.1405		36										

TABLE 15

DRILLED HOLE TOLERANCE (UNDER NORMAL SHOP CONDITIONS)

STANDARD DRILL SIZE				TOLERANCE IN DECIMALS	
DRILL SIZE				PLUS	MINUS
Number	Fraction	Decimal	Metric (mm)		
80		0.0135	0.3412	0.0023	
79		0.0145	0.3788	0.0024	
–	1/64	0.0156	0.3969	0.0025	
78		0.0160	0.4064	0.0025	
77		0.0180	0.4572	0.0026	
76		0.0200	0.5080	0.0027	
75		0.0210	0.5334	0.0027	
74		0.0225	0.5631	0.0028	
73		0.0240	0.6096	0.0028	
72		0.0250	0.6350	0.0029	
71		0.0260	0.6604	0.0029	
70		0.0280	0.7112	0.0030	.0005
69		0.0292	0.7483	0.0030	
68		0.0310	0.7874	0.0031	
–	1/32	0.0312	0.7937	0.0031	
67		0.0320	0.8128	0.0031	
66		0.0330	0.8382	0.0032	
65		0.0350	0.8890	0.0032	
64		0.0360	0.9144	0.0033	
63		0.0370	0.9398	0.0033	
62		0.0380	0.9652	0.0033	
61		0.0390	0.9906	0.0033	
60		0.0400	1.0160	0.0034	
59		0.0410	1.0414	0.0034	
58		0.0420	1.0668	0.0034	
57		0.0430	1.0922	0.0035	
56		0.0465	1.1684	0.0035	
–	3/64	0.0469	1.1906	0.0036	
55		0.0520	1.3208	0.0037	
54		0.0550	1.3970	0.0038	
53		0.0595	1.5122	0.0039	
–	1/16	0.0625	1.5875	0.0039	
52		0.0635	1.6002	0.0039	
51		0.0670	1.7018	0.0040	
50		0.0700	1.7780	0.0041	
49		0.0730	1.8542	0.0041	.001
48		0.0760	1.9304	0.0042	
–	5/64	0.0781	1.9844	0.0042	
47		0.0785	2.0001	0.0042	
46		0.0810	2.0574	0.0043	
45		0.0820	2.0828	0.0043	
44		0.0860	2.1844	0.0044	
43		0.0890	2.2606	0.0044	
42		0.0935	2.3622	0.0045	
–	3/32	0.0937	2.3812	0.0045	
41		0.0960	2.4384	0.0045	
40		0.0980	2.4892	0.0046	
39		0.0995	2.5377	0.0046	
38		0.1015	2.5908	0.0046	
37		0.1040	2.6416	0.0047	
36		0.1065	2.6924	0.0047	
–	7/64	0.1094	2.7781	0.0047	

TABLE 16

DRILLED HOLE TOLERANCE (UNDER NORMAL SHOP CONDITIONS)

STANDARD DRILL SIZE				TOLERANCE IN DECIMALS	
DRILL SIZE				PLUS	MINUS
No./Letter	Fraction	Decimal	Metric (mm)		
35		0.1100	2.7490	0.0047	
34		0.1110	2.8194	0.0048	
33		0.1130	2.8702	0.0048	
32		0.1160	2.9464	0.0048	
31		0.1200	3.0480	0.0049	
—	1/8	0.1250	3.1750	0.0050	
30		0.1285	3.2766	0.0050	
29		0.1360	3.4544	0.0051	
28		0.1405	3.5560	0.0052	
—	9/64	0.1406	3.5719	0.0052	
27		0.1440	3.6576	0.0052	
26		0.1470	3.7338	0.0052	
25		0.1495	3.7886	0.0053	
24		0.1520	3.8608	0.0053	
23		0.1540	3.9116	0.0053	
—	5/32	0.1562	3.9687	0.0053	
22		0.1570	3.9878	0.0053	
21		0.1590	4.0386	0.0054	
20		0.1610	4.0894	0.0054	
19		0.1660	4.2164	0.0055	
18		0.1695	4.3180	0.0055	
—	11/64	0.1719	4.3656	0.0055	
17		0.1730	4.3942	0.0055	
16		0.1770	4.4958	0.0056	.001
15		0.1800	4.5720	0.0056	
14		0.1820	4.6228	0.0057	
13		0.1850	4.6990	0.0057	
—	3/16	0.1875	4.7625	0.0057	
12		0.1890	4.8006	0.0057	
11		0.1910	4.8514	0.0057	
10		0.1935	4.9276	0.0058	
9		0.1960	4.9784	0.0058	
8		0.1990	5.0800	0.0058	
7		0.2010	5.1054	0.0058	
—	13/64	0.2031	5.1594	0.0058	
6		0.2040	5.1816	0.0058	
5		0.2055	5.2070	0.0059	
4		0.2090	5.3086	0.0059	
3		0.2130	5.4102	0.0059	
—	7/32	0.2187	5.5562	0.0060	
2		0.2210	5.6134	0.0060	
1		0.2280	5.7912	0.0061	
A		0.2340	5.9436	0.0061	
—	15/64	0.2344	5.9531	0.0061	
B		0.2380	6.0452	0.0061	
C		0.2420	6.1468	0.0062	
D		0.2460	6.2484	0.0062	
E	1/4	0.2500	6.3500	0.0063	
F		0.2570	6.5278	0.0063	
G		0.2610	6.6294	0.0063	
—	17/64	0.2656	6.7469	0.0064	
H		0.2660	6.7564	0.0064	
I		0.2720	6.9088	0.0064	.002
J		0.2770	7.0358	0.0065	
K		0.2810	7.1374	0.0065	
—	9/32	0.2812	7.1437	0.0065	
L		0.2900	7.3660	0.0066	
M		0.2950	7.4930	0.0066	
—	19/64	0.2969	7.5406	0.0066	

TABLE 16 *(Continued)*

DRILLED HOLE TOLERANCE (UNDER NORMAL SHOP CONDITIONS)

STANDARD DRILL SIZE				TOLERANCE IN DECIMALS	
DRILL SIZE				PLUS	MINUS
Letter	Fraction	Decimal	Metric (mm)		
N		0.3020	7.6708	0.0067	
—	5/16	0.3125	7.9375	0.0067	
O		0.3160	8.0264	0.0068	
P		0.3230	8.2042	0.0068	
—	21/64	0.3281	8.3344	0.0068	
Q		0.3320	8.4328	0.0069	
R		0.3390	8.6106	0.0069	
—	11/32	0.3437	8.7312	0.0070	
S		0.3480	8.8392	0.0070	
T		0.3580	9.0932	0.0071	
—	23/64	0.3594	9.1281	0.0071	
U		0.3680	9.3472	0.0071	
—	3/8	0.3750	9.5250	0.0072	
V		0.3770	9.5758	0.0072	
W		0.3860	9.8044	0.0072	
—	25/64	0.3906	9.9219	0.0073	
X		0.3970	10.0838	0.0073	
Y		0.4040	10.2616	0.0073	
—	13/32	0.4062	10.3187	0.0074	
Z		0.4130	10.4902	0.0074	.002
	27/64	0.4219	10.7156	0.0075	
	7/16	0.4375	10.1125	0.0075	
	29/64	0.4531	11.5094	0.0076	
	15/32	0.4687	11.9062	0.0077	
	31/64	0.4844	12.3031	0.0078	
	1/2	0.5000	12.7000	0.0079	
	33/64	0.5156	13.0968	0.0080	
	17/32	0.5312	13.4937	0.0081	
	35/64	0.5469	13.8906	0.0081	
	9/16	0.5625	14.2875	0.0082	
	37/64	0.5781	14.6844	0.0083	
	19/32	0.5927	15.0812	0.0084	
	39/64	0.6094	15.4781	0.0084	
	5/8	0.6250	15.8750	0.0085	
	41/64	0.6406	16.2719	0.0086	
	21/32	0.6562	16.6687	0.0086	
	43/64	0.6719	17.0656	0.0087	
	11/16	0.6875	17.4625	0.0088	
	45/64	0.7031	17.8594	0.0088	
	23/32	0.7187	18.2562	0.0089	
	47/64	0.7344	18.6532	0.0090	
	3/4	0.7500	19.0500	0.0090	
	49/64	0.7656	19.4469	0.0091	
	25/32	0.7812	19.8433	0.0092	
	51/64	0.7969	20.2402	0.0092	
	13/16	0.8125	20.6375	0.0093	
	53/64	0.8281	21.0344	0.0093	
	27/32	0.8437	21.4312	0.0094	
	55/64	0.8594	21.8281	0.0095	
	7/8	0.8750	22.2250	0.0095	.003
	57/64	0.8906	22.6219	0.0096	
	29/32	0.9062	23.0187	0.0096	
	59/64	0.9219	23.4156	0.0097	
	15/16	0.9375	23.8125	0.0097	
	61/64	0.9531	24.2094	0.0098	
	31/32	0.9687	24.6062	0.0098	
	63/64	0.9844	25.0031	0.0099	
	1	1.0000	25.4000	0.0100	

TABLE 16 *(Concluded)* From *Drafting for Trades and Industry—Mechanical and Electronic,* Nelson. Delmar Publishers, Inc.

INCH-METRIC THREAD COMPARISON

INCH SERIES			METRIC			
Size	Dia.(In.)	TPI	Size	Dia. (In.)	Pitch (mm)	TPI (Approx)
			M1.4	.055	.3 .2	85 127
#0	.060	80				
			M1.6	.063	.35 .2	74 127
#1	.073	64 72				
			M2	.079	.4 .25	64 101
#2	.086	56 64				
			M2.5	.098	.45 .35	56 74
#3	.099	48 56				
#4	.112	40 48				
			M3	.118	.5 .35	51 74
#5	.125	40 44				
#6	.138	32 40				
			M4	.157	.7 .5	36 51
#8	.164	32 36				
#10	.190	24 32				
			M5	.196	.8 .5	32 51
			M6	.236	1.0 .75	25 34
1/4	.250	20 28				
5/16	.312	18 24				
			M8	.315	1.25 1.0	20 25
3/8	.375	16 24				
			M10	.393	1.5 1.25	17 20
7/16	.437	14 20				
			M12	.472	1.75 1.25	14.5 20
1/2	.500	13 20				
			M14	.551	2 1.5	12.5 17
5/8	.625	11 18				
			M16	.630	2 1.5	12.5 17
			M18	.709	2.5 1.5	10 17
3/4	.750	10 16				
			M20	.787	2.5 1.5	10 17
			M22	.866	2.5 1.5	10 17
7/8	.875	9 14				
			M24	.945	3 2	8.5 12.5
1"	1.000	8 12				
			M27	1.063	3 2	8.5 12.5

TABLE 17

ISO BASIC METRIC THREAD INFORMATION

	INTERNAL THREADS			EXTERNAL THREADS		
Basic Major DIA & Pitch	Tap Drill DIA	Minor DIA MAX	Minor DIA MIN	Major DIA MAX	Major DIA MIN	Clearance Hole
M1.6 × 0.35	1.25	1.321	1.221	1.576	1.491	1.9
M2 × 0.4	1.60	1.679	1.567	1.976	1.881	2.4
M2.5 × 0.45	2.05	2.138	2.013	2.476	2.013	2.9
M3 × 0.5	2.50	2.599	2.459	2.976	2.870	3.4
M3.5 × 0.6	2.90	3.010	2.850	3.476	3.351	4.0
M4 × 0.7	3.30	3.422	3.242	3.976	3.836	4.5
M5 × 0.8	4.20	4.334	4.134	4.976	4.826	5.5
M6 × 1	5.00	5.153	4.917	5.974	5.794	6.6
M8 × 1.25	6.80	6.912	6.647	7.972	7.760	9.0
M10 × 1.5	8.50	8.676	8.376	9.968	9.732	11.0
M12 × 1.75	10.20	10.441	10.106	11.966	11.701	13.5
M14 × 2	12.00	12.210	11.835	13.962	13.682	15.5
M16 × 2	14.00	14.210	13.835	15.962	15.682	17.5
M20 × 2.5	17.50	17.744	17.294	19.958	19.623	22.0
M24 × 3	21.00	21.252	20.752	23.952	23.577	26.0
M30 × 3.5	26.50	26.771	26.211	29.947	29.522	33.0
M36 × 4	32.00	32.270	31.670	35.940	35.465	39.0
M42 × 4.5	37.50	37.799	37.129	41.937	41.437	45.0
M48 × 5	43.00	43.297	42.587	47.929	47.399	52.0
M56 × 5.5	50.50	50.796	50.046	55.925	55.365	62.0
M64 × 6	58.00	58.305	57.505	63.920	63.320	70.0
M72 × 6	66.00	66.305	65.505	71.920	71.320	78.0
M80 × 6	74.00	74.305	73 505	79.920	79.320	86.0
M90 × 6	84.00	84.305	83.505	89.920	89.320	96.0
M100 × 6	94.00	94.305	93.505	99.920	99.320	107.0

TABLE 18

KEY AND KEYWAY SIZES





Shaft Nom. Size – DIA. – From	Shaft Nom. Size – DIA. – To & Incl.	Square (W = H)	Type	Square Key From	Square Key To & Incl.	Tolerance
5/16 (8)	7/16 (11)	3/32 (2.38)	Bar Stock	– –	3/4 (19.05)	+.000 - .002 (+.0000 - .0254)
7/16 (11)	9/16 (14)	1/8 (3.175)		3/4 (19.05)	1 1/2 (38.1)	+.000 - .003 (+.0000 - .0762)
9/16 (14)	7/8 (22)	3/16 (4.76)		1 1/2 (38.1)	2 1/2 (63.5)	+.000 - .004 (+.0000 - .1016)
7/8 (22)	1 1/4 (32)	1/4 (6.35)		2 1/2 (63.5)	3 1/2 (88.9)	+.000 - .006 (+.0000 - .1524)
1 1/4 (32)	1 3/8 (35)	5/16 (7.94)	Keystock	– –	1 1/4 (31.75)	+.001 - .000 (+.0254 - .0000)
1 3/8 (35)	1 3/4 (44)	3/8 (9.53)		1 1/4 (31.75)	3 (76.2)	+.002 - .000 (+.0508 - .0000)
1 3/4 (44)	2 1/4 (57)	1/2 (12.7)		3 (76.2)	3 1/2 (88.9)	+.003 - .000 (+.0762 - .0000)
2 1/4 (57)	2 3/4 (70)	5/8 (15.88)				
2 3/4 (70)	3 1/4 (82)	3/4 (19.05)				
3 1/4 (82)	3 3/4 (95)	7/8 (22.23)				

(Figures in parenthesis = mm)

Nom. Size (Inch)	– DIA. – (Shaft) Inch	(Shaft) mm	'X' (Collar) Inch	(Collar) mm	'Y' (Shaft) Inch	(Shaft) mm
1/2	.500	12.700	.560	14.224	.430	10.922
9/16	.562	14.290	.623	15.824	.493	12.522
5/8	.625	15.875	.709	18.008	.517	13.132
11/16	.688	17.470	.773	18.618	.581	14.757
3/4	.750	19.050	.837	21.259	.644	16.357
13/16	.812	20.640	.900	22.860	.708	17.983
7/8	.875	22.225	.964	24.485	.771	19.583
15/16	.938	23.820	1.051	26.695	.791	20.091
1	1.000	25.400	1.114	28.295	.859	21.818
1 1/16	1.062	26.985	1.178	29.921	.923	23.444
1 1/8	1.125	28.575	1.241	31.521	.986	25.044
1 3/16	1.188	30.165	1.304	33.121	1.049	26.644
1 1/4	1.250	31.750	1.367	34.722	1.112	28.244
1 5/16	1.312	33.340	1.455	36.957	1.137	28.879
1 3/8	1.375	34.923	1.518	38.557	1.201	30.505

From Drafting for Trades and Industry—Mechanical and Electronic. Nelson. Delmar Publishers Inc.

TABLE 19 From *Drafting for Trades and Industry—Mechanical and Electronic,* Nelson. Delmar Publishers Inc.

WOODRUFF KEY SIZES FOR DIFFERENT SHAFT DIAMETERS

Shaft Diameter	5/16 to 3/8	7/16 to 1/2	9/16 to 3/4	13/16 to 15/16	1 to 1 3/16	1 1/4 to 1 7/16	1 1/2 to 1 3/4	1 13/16 to 2 1/8	2 3/16 to 2 1/2
Key Numbers	204	304 305	404 405 406	505 506 507	606 607 608 609	807 808 809	810 811 812	1011 1012	1211 1212

TABLE 20

SHEET METAL AND WIRE GAGE DESIGNATION

GAGE NO.	AMERICAN OR BROWN & SHARPE'S A.W.G. OR B. & S.	UNITED STATES STANDARD	MANU-FACTURERS' STANDARD FOR SHEET STEEL	GAGE NO.
0000000	....	.500	....	0000000
000000	.5800	.469	....	000000
00000	.5165	.438	....	00000
0000	.4600	.406	....	0000
000	.4096	.375	....	000
00	.3648	.344	....	00
0	.3249	.312	....	0
1	.2893	.281	....	1
2	.2576	.266	....	2
3	.2294	.250	.2391	3
4	.2043	.234	.2242	4
5	.1819	.219	.2092	5
6	.1620	.203	.1943	6
7	.1443	.188	.1793	7
8	.1285	.172	.1644	8
9	.1144	.156	.1495	9
10	.1019	.141	.1345	10
11	.0907	.125	.1196	11
12	.0808	.109	.1046	12
13	.0720	.0938	.0897	13
14	.0642	.0781	.0747	14
15	.0571	.0703	.0673	15
16	.0508	.0625	.0598	16
17	.0453	.0562	.0538	17
18	.0403	.0500	.0478	18
19	.0359	.0438	.0418	19
20	.0320	.0375	.0359	20
21	.0285	.0344	.0329	21
22	.0253	.0312	.0299	22
23	.0226	.0281	.0269	23
24	.0201	.0250	.0239	24
25	.0179	.0219	.0209	25
26	.0159	.0188	.0179	26
27	.0142	.0172	.0164	27
28	.0126	.0156	.0149	28
29	.0113	.0141	.0135	29
30	.0100	.0125	.0120	30
31	.0089	.0109	.0105	31
32	.0080	.0102	.0097	32
33	.0071	.00938	.0090	33
34	.0063	.00859	.0082	34
35	.0056	.00781	.0075	35
36	.0050	.00703	.0067	36

TABLE 21

BEND ALLOWANCE FOR 90° BENDS (INCH)

Radii Thickness	.031	.063	.094	.125	.156	.188	.219	.250	.281	.313	.344	.375	.438	.500	.531	.625
.013	.058	.108	.157	.205	.254	.304	.353	.402	.450	.501	.549	.598	.697	.794	.843	.991
.016	.060	.110	.159	.208	.256	.307	.355	.404	.453	.503	.552	.600	.699	.796	.845	.993
.020	.062	.113	.161	.210	.259	.309	.358	.406	.455	.505	.554	.603	.702	.799	.848	.995
.022	.064	.114	.163	.212	.260	.311	.359	.408	.457	.507	.556	.604	.703	.801	.849	.997
.025	.066	.116	.165	.214	.263	.313	.362	.410	.459	.509	.558	.607	.705	.803	.851	.999
.028	.068	.119	.167	.216	.265	.315	.364	.412	.461	.511	.560	.609	.708	.805	.854	1.001
.032	.071	.121	.170	.218	.267	.317	.366	.415	.463	.514	.562	.611	.710	.807	.856	1.004
.038	.075	.126	.174	.223	.272	.322	.371	.419	.468	.518	.567	.616	.715	.812	.861	1.008
.040	.077	.127	.176	.224	.273	.323	.372	.421	.469	.520	.568	.617	.716	.813	.862	1.010
.050		.134	.183	.232	.280	.331	.379	.428	.477	.527	.576	.624	.723	.821	.869	1.017
.064		.144	.192	.241	.290	.340	.389	.437	.486	.536	.585	.634	.732	.830	.878	1.026
.072			.198	.247	.296	.346	.394	.443	.492	.542	.591	.639	.738	.836	.885	1.032
.078			.202	.251	.300	.350	.399	.447	.496	.546	.595	.644	.743	.840	.889	1.036
.081			.204	.253	.302	.352	.401	.449	.498	.548	.598	.646	.745	.842	.891	1.038
.091			.212	.260	.309	.359	.408	.456	.505	.555	.604	.653	.752	.849	.898	1.045
.094			.214	.262	.311	.361	.410	.459	.507	.558	.606	.655	.754	.851	.900	1.048
.102				.268	.317	.367	.416	.464	.513	.563	.612	.661	.760	.857	.906	1.053
.109				.273	.321	.372	.420	.469	.518	.568	.617	.665	.764	.862	.910	1.058
.125				.284	.333	.383	.432	.480	.529	.579	.628	.677	.776	.873	.922	1.069
.156					.355	.405	.453	.502	.551	.601	.650	.698	.797	.895	.943	1.091
.188						.427	.476	.525	.573	.624	.672	.721	.820	.917	.966	1.114
.203								.535	.584	.634	.683	.731	.830	.928	.976	1.124
.218								.546	.594	.645	.693	.742	.841	.938	.987	1.135
.234								.557	.606	.656	.705	.753	.852	.950	.998	1.146
.250								.568	.617	.667	.716	.764	.863	.961	1.009	1.157

EXAMPLE: MATERIAL THICKNESS = 1/8", INSIDE RADII = 1/4" R. WHERE THESE CROSS = .480" BEND ALLOWANCE (B/A) PLUS TOTAL OF STRAIGHT LENGTHS = DEVELOPED LENGTH.

BEND ALLOWANCE FOR 90° BENDS (MILLIMETER)

Radii Thickness	0.80	1.58	2.38	3.18	3.96	4.76	5.56	6.35	7.15	7.94	8.74	9.52	11.12	12.70	13.50	15.85
.330	1.46	2.74	3.98	5.22	6.45	7.73	8.96	10.20	11.44	12.71	13.95	15.19	17.70	20.18	21.42	25.16
.406	1.52	2.80	4.04	5.27	6.51	7.78	9.02	10.26	11.50	12.77	14.01	15.24	17.76	20.23	21.47	25.22
.508	1.59	2.87	4.11	5.34	6.58	7.86	9.09	10.33	11.57	12.84	14.08	15.32	17.83	20.30	21.54	25.29
.559	1.63	2.91	4.14	5.38	6.62	7.89	9.13	10.37	11.60	12.88	14.12	15.35	17.86	20.34	21.57	25.32
.635	1.68	2.96	4.20	5.43	6.67	7.95	9.18	10.42	11.66	12.93	14.17	15.40	17.92	20.39	21.63	25.38
.711	1.74	3.02	4.25	5.49	6.72	8.00	9.24	10.47	11.71	12.99	14.22	15.46	17.98	20.44	21.68	25.43
.813	1.81	3.08	4.32	5.56	6.79	8.07	9.30	10.54	11.78	13.05	14.29	15.53	18.04	20.52	21.75	25.50
.965	1.91	3.19	4.42	5.66	6.90	8.18	9.41	10.65	11.89	13.16	14.40	15.64	18.15	20.62	21.86	25.61
1.016	1.95	2.23	4.46	5.70	6.94	8.21	9.45	10.69	11.92	13.20	14.44	15.67	18.19	20.66	21.90	25.64
1.270		3.40	4.64	5.88	7.11	8.39	9.63	10.86	12.10	13.38	14.61	15.85	18.36	20.84	22.07	25.82
1.625		3.65	4.89	6.13	7.36	8.64	9.88	11.11	12.35	13.63	14.86	16.10	18.61	21.08	22.32	26.07
1.829			5.03	6.27	7.51	8.78	10.02	11.26	12.49	13.77	15.01	16.24	18.76	21.23	22.47	26.22
1.981			5.14	6.38	7.61	8.89	10.13	11.36	12.60	13.88	15.11	16.35	18.86	21.34	22.57	26.32
2.058			5.19	6.43	7.67	8.94	10.18	11.42	12.65	13.93	15.17	16.40	18.92	21.39	22.63	26.38
2.311			5.37	6.60	7.85	9.12	10.36	11.60	12.83	14.11	15.35	16.58	19.09	21.57	22.80	26.55
2.388			5.43	6.66	7.90	9.18	10.41	11.65	12.89	14.16	15.40	16.64	19.15	21.62	22.86	26.61
2.591				6.81	8.04	9.31	10.55	11.79	13.03	14.30	15.54	16.78	19.29	21.76	23.00	26.75
2.769				6.93	8.17	9.44	10.68	11.92	13.15	14.43	15.67	16.90	19.42	21.89	23.13	26.88
3.175				7.22	8.45	9.73	10.96	12.20	13.44	14.71	15.95	17.19	19.70	22.17	23.41	27.16
3.962					9.00	10.28	11.52	12.75	13.99	15.27	16.74	17.74	20.25	22.72	23.96	27.71
4.775					9.58	10.85	12.09	13.32	14.56	15.84	17.07	18.31	20.82	23.30	24.53	28.28
5.156						11.12	12.36	13.59	14.83	16.11	17.34	18.58	21.09	23.57	24.80	28.55
5.537								13.85	15.10	16.37	17.61	18.85	21.36	23.83	25.07	28.82
5.944								14.15	15.38	16.66	17.89	19.13	21.64	24.12	25.35	29.10
6.350								14.43	15.67	16.94	18.18	19.42	21.93	24.40	25.64	29.39

EXAMPLE: MATERIAL THICKNESS = 3.18 MM, INSIDE RADII = 6.35 MM R. WHERE THESE CROSS = 12.20 MM BEND ALLOWANCE (B/A) PLUS TOTAL OF STRAIGHT LENGTHS = DEVELOPED LENGTH.

TABLE 22 From *Drafting for Trades and Industry—Basic Skills*, Nelson. Delmar Publishers Inc.

BEND ALLOWANCE FOR EACH 1° OF BEND (INCH)

Radii Thickness	.031	.063	.094	.125	.156	.188	.219	.250	.281	.313	.344	.375	.438	.500	.531	.625
.013	.00064	.00120	.00174	.00228	.00282	.00338	.00392	.00446	.00500	.00556	.00610	.00664	.00774	.00883	.00937	.01101
.016	.00067	.00122	.00176	.00231	.00285	.00342	.00395	.00449	.00503	.00559	.00613	.00667	.00777	.00885	.00939	.01103
.020	.00069	.00125	.00179	.00233	.00287	.00343	.00397	.00452	.00506	.00561	.00616	.00670	.00780	.00888	.00942	.01106
.022	.00071	.00127	.00181	.00235	.00289	.00345	.00399	.00453	.00508	.00563	.00617	.00672	.00782	.00890	.00944	.01108
.025	.00074	.00129	.00184	.00238	.00292	.00348	.00402	.00456	.00510	.00566	.00610	.00674	.00784	.00892	.00946	.01110
.028	.00076	.00132	.00186	.00240	.00294	.00350	.00404	.00458	.00512	.00568	.00622	.00676	.00786	.00894	.00948	.01112
.032	.00079	.00134	.00189	.00243	.00297	.00353	.00407	.00461	.00515	.00571	.00625	.00679	.00789	.00897	.00951	.01115
.038	.00084	.00140	.00194	.00248	.00302	.00358	.00412	.00466	.00520	.00576	.00630	.00684	.00794	.00902	.00946	.01120
.040	.00085	.00141	.00195	.00249	.00303	.00359	.00413	.00468	.00522	.00577	.00632	.00686	.00796	.00904	.00958	.01122
.050		.00149	.00203	.00258	.00312	.00368	.00422	.00476	.00530	.00586	.00640	.00694	.00804	.00912	.00966	.01130
.064		.00160	.00214	.00268	.00322	.00378	.00432	.00486	.00540	.00596	.00650	.00704	.00814	.00922	.00976	.01140
.072			.00220	.00274	.00328	.00384	.00438	.00492	.00546	.00602	.00656	.00710	.00820	.00929	.00983	.01147
.078			.00225	.00279	.00333	.00389	.00443	.00497	.00551	.00607	.00661	.00715	.00825	.00933	.00987	.01152
.081			.00227	.00281	.00335	.00391	.00445	.00499	.00554	.00609	.00664	.00718	.00828	.00936	.00990	.01154
.091			.00235	.00289	.00343	.00399	.00453	.00507	.00561	.00617	.00671	.00725	.00835	.00944	.00998	.01162
.094			.00237	.00291	.00346	.00401	.00456	.00510	.00564	.00620	.00674	.00728	.00838	.00946	.00999	.01164
.102				.00298	.00352	.00408	.00462	.00516	.00570	.00626	.00680	.00734	.00844	.00952	.01006	.01170
.109				.00303	.00357	.00413	.00467	.00521	.00575	.00631	.00685	.00739	.00849	.00958	.01012	.01176
.125				.00316	.00370	.00426	.00480	.00534	.00588	.00644	.00698	.00752	.00862	.00970	.01024	.01188
.156					.00394	.00450	.00504	.00558	.00612	.00668	.00722	.00776	.00886	.00994	.01048	.01212
.188						.00475	.00529	.00583	.00637	.00693	.00747	.00802	.00911	.01019	.01073	.01237
.203								.00595	.00649	.00704	.00759	.00813	.00923	.01031	.01085	.01249
.218								.00606	.00660	.00716	.00770	.00824	.00934	.01042	.01097	.01261
.234								.00619	.00673	.00729	.00783	.00837	.00947	.01055	.01109	.01273
.250								.00631	.00685	.00741	.00795	.00849	.00959	.01068	.01122	.01286

EXAMPLE: MATERIAL THICKNESS = 1/8", INSIDE RADII = 1/4" R. WHERE THESE CROSS = .00534" IF THE INSIDE OF YOUR BEND IS 20° THE BEND ALLOWANCE (B/A) = .1068 (.00534 × 20°) BEND ALLOWANCE B/A PLUS TOTAL OF STRAIGHT LENGTHS = DEVELOPED LENGTH.

BEND ALLOWANCE FOR EACH 1° OF BEND (MILLIMETER)

Radii Thickness	0.80	1.58	2.38	3.18	3.96	4.76	5.56	6.35	7.15	7.94	8.74	9.52	11.12	12.70	13.50	15.85
.330	.0161	.0305	.0442	.0580	.0717	.0859	.0996	.1134	.1271	.1413	.1550	.1668	.1967	.2242	.2379	.2796
.406	.0169	.0311	.0448	.0586	.0723	.0865	.1002	.1140	.1277	.1419	.1556	.1694	.1973	.2248	.2385	.2802
.508	.0177	.0319	.0456	.0594	.0731	.0873	.1010	.1148	.1285	.1427	.1564	.1702	.1981	.2256	.2393	.2810
.559	.0181	.0323	.0460	.0598	.0735	.0877	.1014	.1152	.1289	.1431	.1568	.1706	.1985	.2260	.2397	.2814
.635	.0187	.0329	.0466	.0604	.0741	.0883	.1020	.1158	.1295	.1437	.1574	.1712	.1991	.2266	.2403	.2820
.711	.0193	.0335	.0472	.0610	.0747	.0889	.1026	.1164	.1301	.1443	.1580	.1718	.1997	.2272	.2409	.2826
.813	.0201	.0343	.0480	.0617	.0755	.0897	.1034	.1174	.1309	.1451	.1588	.1726	.2005	.2280	.2417	.2834
.965	.0213	.0355	.0492	.0629	.0767	.0909	.1046	.1183	.1321	.1463	.1600	.1737	.2017	.2291	.2429	.2845
1.016	.0217	.0358	.0496	.0633	.0771	.0913	.1050	.1187	.1325	.1467	.1604	.1741	.2021	.2295	.2433	.2849
1.270		.0378	.0516	.0653	.0790	.0932	.1070	.1207	.1345	.1486	.1624	.1761	.2040	.2315	.2453	.2869
1.625		.0406	.0543	.0681	.0818	.0960	.1097	.1235	.1372	.1514	.1652	.1789	.2066	.2343	.2480	.2897
1.829			.0559	.0697	.0834	.0976	.1113	.1251	.1388	.1530	.1667	.1805	.2084	.2359	.2496	.2913
1.981			.0571	.0709	.0846	.0988	.1125	.1263	.1400	.1542	.1679	.1817	.2096	.2371	.2508	.2925
2.058			.0577	.0715	.0852	.0994	.1131	.1269	.1406	.1548	.1685	.1823	.2102	.2377	.2514	.2931
2.311			.0597	.0734	.0872	.1014	.1151	.1288	.1426	.1568	.1705	.1842	.2122	.2396	.2534	.2950
2.388			.0603	.0740	.0878	.1020	.1157	.1294	.1432	.1574	.1711	.1848	.2128	.2402	.2540	.2956
2.591				.0756	.0894	.1035	.1173	.1310	.1448	.1589	.1727	.1864	.2143	.2418	.2556	.2972
2.769				.0770	.0907	.1049	.1187	.1324	.1461	.1603	.1741	.1878	.2157	.2432	.2570	.2986
3.175				.0802	.0939	.1081	.1218	.1356	.1493	.1635	.1772	.1910	.2189	.2464	.2601	.3018
3.962					.1001	.1142	.1280	.1417	.1555	.1696	.1834	.1971	.2250	.2525	.2663	.3079
4.775					.1064	.1206	.1343	.1481	.1618	.1760	.1897	.2035	.2314	.2589	.2726	.3143
5.156						.1235	.1373	.1510	.1648	.1789	.1927	.2064	.2344	.2618	.2756	.3172
5.537								.1540	.1677	.1819	.1957	.2094	.2373	.2648	.2785	.3202
5.944								.1572	.1709	.1851	.1988	.2126	.2405	.2680	.2817	.3234
6.350								.1603	.1741	.1883	.2020	.2157	.2437	.2711	.2849	.3265

EXAMPLE: MATERIAL THICKNESS = 3.175 MM, INSIDE RADII = 6.35 MM R. WHERE THESE CROSS = .1356 MM IF THE INSIDE OF YOUR BEND IS 20° THE BEND ALLOWANCE (B/A) = 2.712 MM (.1356 × 20°) BEND ALLOWANCE (B/A) PLUS TOTAL OF STRAIGHT LENGTHS = DEVELOPED LENGTH.

TABLE 23 From *Drafting for Trades and Industry—Basic Skills,* Nelson. Delmar Publishers Inc.

SPUR/PINION GEAR TOOTH PARTS

20 Degree Pressure Angles

Diametral Pitch	Circular Pitch	Circular Thickness	Addend.	Dedend.	Standard Fillet Radius
D.P.	C.P.	C.T.	A	D	
1	3.1416	1.5708	1.0000	1.2500	0.3000
2	1.5708	0.7854	0.5000	0.6250	0.1500
2.5	1.2566	0.6283	0.4000	0.5000	0.1200
3	1.0472	0.5236	0.3333	0.4167	0.1000
3.5	0.8976	0.4488	0.2857	0.3571	0.0857
4	0.7854	0.3927	0.2500	0.3125	0.0750
4.5	0.6981	0.3491	0.2222	0.2778	0.0667
5	0.6283	0.3142	0.2000	0.2500	0.0600
5.5	0.5712	0.2856	0.1818	0.2273	0.0545
6	0.5236	0.2618	0.1667	0.2083	0.0500
6.5	0.4833	0.2417	0.1538	0.1923	0.0462
7	0.4488	0.2244	0.1429	0.1786	0.0429
7.5	0.4189	0.2094	0.1333	0.1667	0.0400
8	0.3927	0.1963	0.1250	0.1563	0.0375
8.5	0.3696	0.1848	0.1176	0.1471	0.0353
9	0.3491	0.1745	0.1111	0.1389	0.0333
9.5	0.3307	0.1653	0.1053	0.1316	0.0316
10	0.3142	0.1571	0.1000	0.1250	0.0300
11	0.2856	0.1428	0.0909	0.1136	0.0273
12	0.2618	0.1309	0.0833	0.1042	0.0250
13	0.2417	0.1208	0.0769	0.0962	0.0231
14	0.2244	0.1122	0.0714	0.0893	0.0214
15	0.2094	0.1047	0.0667	0.0833	0.0200

TABLE 24

SURFACE TEXTURE ROUGHNESS



From Interpreting Engineering Drawings. Jensen. Delmar Publishers Inc

TABLE 25 From *Interpreting Engineering Drawings, Jensen.* Delmar Publishers Inc.

PROPERTIES, GRADE NUMBERS, AND USAGE OF STEEL ALLOYS

Class of Steel	*Grade Number	Properties	Uses
Carbon—Low 0.3% carbon	10xx	Tough—Less Strength	Rivet—Hooks—Chains – Shafts—Pressed Steel Products
Carbon—Medium 0.3% to 0.6% carbon	10xx	Tough & Strong	Gears—Shafts—Studs Various Machine Parts
Carbon—High 1.6% to 1.7%	10xx	Less Tough—Much Harder	Drills—Knives—Saws
Nickel	20xx	Tough & Strong	Axles—Connecting Rods—Crank Shafts
Nickel Chromium	30xx	Tough & Strong	Rings—Gears—Shafts – Piston Pins—Bolts – Studs—Screws
Molybdenum	40xx	Very Strong	Forgings—Shafts – Gears—Cams
Chromium	50xx	Hard W/Strength & Toughness	Ball Bearings—Roller Bearing—Springs – Gears—Shafts
Chromium Vanadium	60xx	Hard & Strong	Shafts—Axles—Gears – Dies—Punches—Drills
Chromium Nickel Stainless	60xx	Rust Resistance	Food Containers – Medical/Dental Surgical Instruments
Silicon—Manganese	90xx	Springiness	Large Springs

*The first two numbers indicate type of steel, the last two numbers indicate the approx. average carbon content—1010 steel indicates carbon steel w/approx. 0.10% carbon.

TABLE 26 From *Drafting for Trades and Industry—Mechanical and Electronic,* Nelson. Delmar Publishers Inc.

AMERICAN NATIONAL STANDARDS OF INTEREST TO DESIGNERS, ARCHITECTS, AND DRAFTERS

TITLE OF STANDARD	
Abbreviations	Y1.1-1989
American National Standard Drafting Practices	
Size and Format	Y14.1M-1995
Line Conventions and Lettering	Y14.2M-1992
Multi and Sectional View Drawings	Y14.3M-1994
Pictorial Drawing	Y14.4M-1989 (R1994)
Dimensioning and Tolerancing	Y14.5M-1994
Screw Threads	Y14.6-1978 (R1993)
Screw Threads (Metric Supplement)	Y14.6aM-1981 (R1993)
Gears and Splines	
Spur, Helical, and Racks	Y14.7.1-1971 (R1993)
Bevel and Hypoid	Y14.7.2-1978 (R1994)
Castings and Forgings	Y14.8M-1989 (R1993)
Springs	Y14.13M-1981 (R1992)
Electrical and Electronic Diagram	Y14.15-1966 (R1988)
Interconnection Diagrams	Y14.15a-1971 (R1988)
Information Sheet	Y14.15b-1973 (R1988)
Fluid Power Diagrams	Y14.17-1966 (R1980)
Digital Representation for Communication of Product Definition Data	Y14.26M-1989
Computer-Aided Preparation of Product Definition Data Dictionary of Terms	Y14.26.3-1975
Digital Representation of Physical Object Shapes	Y14 Report
Guideline—User Instructions	Y14 Report No. 2
Guideline—Design Requirements	Y14 Report No. 3
Ground Vehicle Drawing Practices	In Preparation
Chassis Frames	Y14.32.1-1994
Parts Lists, Data Lists, and Index Lists	Y14.34M-1990
Surface Texture Symbols	Y14.36-1978 (R1993)
Illustrations for Publication and Projection	Y15.1M-1979 (R1986)
Time Series Charts	Y15.2M-1979 (R1986)
Process Charts	Y15.3M-1979 (R1986)
Graphic Symbols for:	
Electrical and Electronics Diagrams	with 315A-1986 (a supplement to Y32.2-1975) (R1994)
Plumbing	Y32.4-1977 (R1994)
Use on Railroad Maps and Profiles	Y32.7-1972 (R1994)
Fluid Power Diagrams	Y32.10-1967 (R1994)
Process Flow Diagrams in Petroleum and Chemical Industries	Y32.11-1961 (R1993)
Mechanical and Acoustical Element as Used in Schematic Diagrams	Y32.18-1972 (R1985)
Pipe Fittings, Valves, and Piping	Y32.2.3-1949 (R1994)
Heating, Ventilating, and Air Conditioning	Y32.2.4-1949 (R1993)
Heat Power Apparatus	Y32.2.6-1950 (R1993)
Letter Symbols for:	
Glossary of Terms Concerning Letter Symbols	Y10.1-1972 (R1988)
Quantities Used in Electrical Science and Electrical Engineering	Y10.5-1968
Structural Analysis	Y10.8-1962
Illuminating Engineering	Y10.18-1967 (R1987)
Mathematical Signs and Symbols for Use in Physical Sciences and Technology	Y10.20-1990

TABLE 27

American National Standard Running and Sliding Fits (ANSI B4.1-1967, R1994)

Tolerance limits given in body of table are added or subtracted to basic size (as indicated by + or − sign) to obtain maximum and minimum sizes of mating parts.

Nominal Size Range, Inches	Class RC 1			Class RC 2			Class RC 3			Class RC 4		
		Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits	
Over To	Clearance*	Hole H5	Shaft g4	Clearance*	Hole H6	Shaft g5	Clearance*	Hole H7	Shaft f6	Clearance*	Hole H8	Shaft f7
	Values shown below are in thousandths of an inch											
0– 0.12	0.1 0.45	+0.2 0	−0.1 −0.25	0.1 0.55	+0.25 0	−0.1 −0.3	0.3 0.95	+0.4 0	−0.3 −0.55	0.3 1.3	+0.6 0	−0.3 −0.7
0.12– 0.24	0.15 0.5	+0.2 0	−0.15 −0.3	0.15 0.65	+0.3 0	−0.15 −0.35	0.4 1.12	+0.5 0	−0.4 −0.7	0.4 1.6	+0.7 0	−0.4 −0.9
0.24– 0.40	0.2 0.6	+0.25 0	−0.2 −0.35	0.2 0.85	+0.4 0	−0.2 −0.45	0.5 1.5	+0.6 0	−0.5 −0.9	0.5 2.0	+0.9 0	−0.5 −1.1
0.40– 0.71	0.25 0.75	+0.3 0	−0.25 −0.45	0.25 0.95	+0.4 0	−0.25 −0.55	0.6 1.7	+0.7 0	−0.6 −1.0	0.6 2.3	+1.0 0	−0.6 −1.3
0.71– 1.19	0.3 0.95	+0.4 0	−0.3 −0.55	0.3 1.2	+0.5 0	−0.3 −0.7	0.8 2.1	+0.8 0	−0.8 −1.3	0.8 2.8	+1.2 0	−0.8 −1.6
1.19– 1.97	0.4 1.1	+0.4 0	−0.4 −0.7	0.4 1.4	+0.6 0	−0.4 −0.8	1.0 2.6	+1.0 0	−1.0 −1.6	1.0 3.6	+1.6 0	−1.0 −2.0
1.97– 3.15	0.4 1.2	+0.5 0	−0.4 −0.7	0.4 1.6	+0.7 0	−0.4 −0.9	1.2 3.1	+1.2 0	−1.2 −1.9	1.2 4.2	+1.8 0	−1.2 −2.4
3.15– 4.73	0.5 1.5	+0.6 0	−0.5 −0.9	0.5 2.0	+0.9 0	−0.5 −1.1	1.4 3.7	+1.4 0	−1.4 −2.3	1.4 5.0	+2.2 0	−1.4 −2.8
4.73– 7.09	0.6 1.8	+0.7 0	−0.6 −1.1	0.6 2.3	+1.0 0	−0.6 −1.3	1.6 4.2	+1.6 0	−1.6 −2.6	1.6 5.7	+2.5 0	−1.6 −3.2
7.09– 9.85	0.6 2.0	+0.8 0	−0.6 −1.2	0.6 2.6	+1.2 0	−0.6 −1.4	2.0 5.0	+1.8 0	−2.0 −3.2	2.0 6.6	+2.8 0	−2.0 −3.8
9.85–12.41	0.8 2.3	+0.9 0	−0.8 −1.4	0.8 2.9	+1.2 0	−0.8 −1.7	2.5 5.7	+2.0 0	−2.5 −3.7	2.5 7.5	+3.0 0	−2.5 −4.5
12.41–15.75	1.0 2.7	+1.0 0	−1.0 −1.7	1.0 3.4	+1.4 0	−1.0 −2.0	3.0 6.6	+2.2 0	−3.0 −4.4	3.0 8.7	+3.5 0	−3.0 −5.2
15.75–19.69	1.2 3.0	+1.0 0	−1.2 −2.0	1.2 3.8	+1.6 0	−1.2 −2.2	4.0 8.1	+2.5 0	−4.0 −5.6	4.0 10.5	+4.0 0	−4.0 −6.5

See footnotes at end of table.

Nominal Size Range, Inches	Class RC 5			Class RC 6			Class RC 7			Class RC 8			Class RC 9		
		Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits	
Over To	Clearance*	Hole H8	Shaft e7	Clearance*	Hole H9	Shaft e8	Clearance*	Hole H9	Shaft d8	Clearance*	Hole H10	Shaft c9	Clearance*	Hole H11	Shaft
	Values shown below are in thousandths of an inch														
0– 0.12	0.6 1.6	+0.6 0	−0.6 −1.0	0.6 2.2	+1.0 0	−0.6 −1.2	1.0 2.6	+1.0 0	−1.0 −1.6	2.5 5.1	+1.6 0	−2.5 −3.5	4.0 8.1	+2.5 0	−4.0 −5.6
0.12– 0.24	0.8 2.0	+0.7 0	−0.8 −1.3	0.8 2.7	+1.2 0	−0.8 −1.5	1.2 3.1	+1.2 0	−1.2 −1.9	2.8 5.8	+1.8 0	−2.8 −4.0	4.5 9.0	+3.0 0	−4.5 −6.0
0.24– 0.40	1.0 2.5	+0.9 0	−1.0 −1.6	1.0 3.3	+1.4 0	−1.0 −1.9	1.6 3.9	+1.4 0	−1.6 −2.5	3.0 6.6	+2.2 0	−3.0 −4.4	5.0 10.7	+3.5 0	−5.0 −7.2
0.40– 0.71	1.2 2.9	+1.0 0	−1.2 −1.9	1.2 3.8	+1.6 0	−1.2 −2.2	2.0 4.6	+1.6 0	−2.0 −3.0	3.5 7.9	+2.8 0	−3.5 −5.1	6.0 12.8	+4.0 0	−6.0 −8.8
0.71– 1.19	1.6 3.6	+1.2 0	−1.6 −2.4	1.6 4.8	+2.0 0	−1.6 −2.8	2.5 5.7	+2.0 0	−2.5 −3.7	4.5 10.0	+3.5 0	−4.5 −6.5	7.0 15.5	+5.0 0	−7.0 −10.5
1.19– 1.97	2.0 4.6	+1.6 0	−2.0 −3.0	2.0 6.1	+2.5 0	−2.0 −3.6	3.0 7.1	+2.5 0	−3.0 −4.6	5.0 11.5	+4.0 0	−5.0 −7.5	8.0 18.0	+6.0 0	−8.0 −12.0
1.97– 3.15	2.5 5.5	+1.8 0	−2.5 −3.7	2.5 7.3	+3.0 0	−2.5 −4.3	4.0 8.8	+3.0 0	−4.0 −5.8	6.0 13.5	+4.5 0	−6.0 −9.0	9.0 20.5	+7.0 0	−9.0 −13.5
3.15– 4.73	3.0 6.6	+2.2 0	−3.0 −4.4	3.0 8.7	+3.5 0	−3.0 −5.2	5.0 10.7	+3.5 0	−5.0 −7.2	7.0 15.5	+5.0 0	−7.0 −10.5	10.0 24.0	+9.0 0	−10.0 −15.0
4.73– 7.09	3.5 7.6	+2.5 0	−3.5 −5.1	3.5 10.0	+4.0 0	−3.5 −6.0	6.0 12.5	+4.0 0	−6.0 −8.5	8.0 18.0	+6.0 0	−8.0 −12.0	12.0 28.0	+10.0 0	−12.0 −18.0
7.09– 9.85	4.0 8.6	+2.8 0	−4.0 −5.8	4.0 11.3	+4.5 0	−4.0 −6.8	7.0 14.3	+4.5 0	−7.0 −9.8	10.0 21.5	+7.0 0	−10.0 −14.5	15.0 34.0	+12.0 0	−15.0 −22.0
9.85–12.41	5.0 10.0	+3.0 0	−5.0 −7.0	5.0 13.0	+5.0 0	−5.0 −8.0	8.0 16.0	+5.0 0	−8.0 −11.0	12.0 25.0	+8.0 0	−12.0 −17.0	18.0 38.0	+12.0 0	−18.0 −26.0
12.41–15.75	6.0 11.7	+3.5 0	−6.0 −8.2	6.0 15.5	+6.0 0	−6.0 −9.5	10.0 19.5	+6.0 0	−10.0 −13.5	14.0 29.0	+9.0 0	−14.0 −20.0	22.0 45.0	+14.0 0	−22.0 −31.0
15.75–19.69	8.0 14.5	+4.0 0	−8.0 −10.5	8.0 18.0	+6.0 0	−8.0 −12.0	12.0 22.0	+6.0 0	−12.0 −16.0	16.0 32.0	+10.0 0	−16.0 −22.0	25.0 51.0	+16.0 0	−25.0 −35.0

All data above heavy lines are in accord with ABC agreements. Symbols H5, g4, etc. are hole and shaft designations in ABC system. Limits for sizes above 19.69 inches are also given in the ANSI Standard.

* Pairs of values shown represent minimum and maximum amounts of clearance resulting from application of standard tolerance limits.

TABLE 28 *ANSI standard running and sliding fits. (Courtesy ASME)*

American National Standard Clearance Locational Fits (ANSI B4.1-1967, R1994)

Tolerance limits given in body of table are added or subtracted to basic size (as indicated by + or – sign) to obtain maximum and minimum sizes of mating parts.

Nominal Size Range, Inches	Class LC 1			Class LC 2			Class LC 3			Class LC 4			Class LC 5		
		Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits	
Over To	Clearance*	Hole H6	Shaft h5	Clearance*	Hole H7	Shaft h6	Clearance*	Hole H8	Shaft h7	Clearance*	Hole H10	Shaft h9	Clearance*	Hole H7	Shaft g6
	Values shown below are in thousandths of an inch														
0– 0.12	0 0.45	+0.25 0	0 −0.2	0 0.65	+0.4 0	0 −0.25	0 1	+0.6 0	0 −0.4	0 2.6	+ 1.6 0	0 − 1.0	0.1 0.75	+0.4 0	−0.1 −0.35
0.12– 0.24	0 0.5	+0.3 0	0 −0.2	0 0.8	+0.5 0	0 −0.3	0 1.2	+0.7 0	0 −0.5	0 3.0	+ 1.8 0	0 − 1.2	0.15 0.95	+0.5 0	−0.15 −0.45
0.24– 0.40	0 0.65	+0.4 0	0 −0.25	0 1.0	+0.6 0	0 −0.4	0 1.5	+0.9 0	0 −0.6	0 3.6	+ 2.2 0	0 − 1.4	0.2 1.2	+0.6 0	−0.2 −0.6
0.40– 0.71	0 0.7	+0.4 0	0 −0.3	0 1.1	+0.7 0	0 −0.4	0 1.7	+1.0 0	0 −0.7	0 4.4	+ 2.8 0	0 − 1.6	0.25 1.35	+0.7 0	−0.25 −0.65
0.71– 1.19	0 0.9	+0.5 0	0 −0.4	0 1.3	+0.8 0	0 −0.5	0 2	+1.2 0	0 −0.8	0 5.5	+ 3.5 0	0 − 2.0	0.3 1.6	+0.8 0	−0.3 −0.8
1.19– 1.97	0 1.0	+0.6 0	0 −0.4	0 1.6	+1.0 0	0 −0.6	0 2.6	+1.6 0	0 −1	0 6.5	+ 4.0 0	0 − 2.5	0.4 2.0	+1.0 0	−0.4 −1.0
1.97– 3.15	0 1.2	+0.7 0	0 −0.5	0 1.9	+1.2 0	0 −0.7	0 3	+1.8 0	0 −1.2	0 7.5	+ 4.5 0	0 − 3	0.4 2.3	+1.2 0	−0.4 −1.1
3.15– 4.73	0 1.5	+0.9 0	0 −0.6	0 2.3	+1.4 0	0 −0.9	0 3.6	+2.2 0	0 −1.4	0 8.5	+ 5.0 0	0 − 3.5	0.5 2.8	+1.4 0	−0.5 −1.4
4.73– 7.09	0 1.7	+1.0 0	0 −0.7	0 2.6	+1.6 0	0 −1.0	0 4.1	+2.5 0	0 −1.6	0 10.0	+ 6.0 0	0 − 4	0.6 3.2	+1.6 0	−0.6 −1.6
7.09– 9.85	0 2.0	+1.2 0	0 −0.8	0 3.0	+1.8 0	0 −1.2	0 4.6	+2.8 0	0 −1.8	0 11.5	+ 7.0 0	0 − 4.5	0.6 3.6	+1.8 0	−0.6 −1.8
9.85–12.41	0 2.1	+1.2 0	0 −0.9	0 3.2	+2.0 0	0 −1.2	0 5	+3.0 0	0 −2.0	0 13.0	+ 8.0 0	0 − 5	0.7 3.9	+2.0 0	−0.7 −1.9
12.41–15.75	0 2.4	+1.4 0	0 −1.0	0 3.6	+2.2 0	0 −1.4	0 5.7	+3.5 0	0 −2.2	0 15.0	+ 9.0 0	0 − 6	0.7 4.3	+2.2 0	−0.7 −2.1
15.75–19.69	0 2.6	+1.6 0	0 −1.0	0 4.1	+2.5 0	0 −1.6	0 6.5	+4 0	0 −2.5	0 16.0	+10.0 0	0 − 6	0.8 4.9	+2.5 0	−0.8 −2.4

See footnotes at end of table.

Nominal Size Range, Inches	Class LC 6			Class LC 7			Class LC 8			Class LC 9			Class LC 10			Class LC 11		
		Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits	
Over To	Clearance*	Hole H9	Shaft f8	Clearance*	Hole H10	Shaft e9	Clearance*	Hole H10	Shaft d9	Clearance*	Hole H11	Shaft c10	Clearance*	Hole H12	Shaft	Clearance*	Hole H13	Shaft
	Values shown below are in thousandths of an inch																	
0– 0.12	0.3 1.9	+1.0 0	−0.3 −0.9	0.6 3.2	+ 1.6 0	− 0.6 − 1.6	1.0 2.0	+ 1.6 0	− 1.0 − 2.0	2.5 6.6	+ 2.5 0	− 2.5 − 4.1	4 12	+ 4 0	− 4 − 8	5 17	+ 6 0	− 5 − 11
0.12– 0.24	0.4 2.3	+1.2 0	−0.4 −1.1	0.8 3.8	+ 1.8 0	− 0.8 − 2.0	1.2 4.2	+ 1.8 0	− 1.2 − 2.4	2.8 7.6	+ 3.0 0	− 2.8 − 4.6	4.5 14.5	+ 5 0	− 4.5 − 9.5	6 20	+ 7 0	− 6 − 13
0.24– 0.40	0.5 2.8	+1.4 0	−0.5 −1.4	1.0 4.6	+ 2.2 0	− 1.0 − 2.4	1.6 5.2	+ 2.2 0	− 1.6 − 3.0	3.0 8.7	+ 3.5 0	− 3.0 − 5.2	5 17	+ 6 0	− 5 − 11	7 25	+ 9 0	− 7 − 16
0.40– 0.71	0.6 3.2	+1.6 0	−0.6 −1.6	1.2 5.6	+ 2.8 0	− 1.2 − 2.8	2.0 6.4	+ 2.8 0	− 2.0 − 3.6	3.5 10.3	+ 4.0 0	− 3.5 − 6.3	6 20	+ 7 0	− 6 − 13	8 28	+ 10 0	− 8 − 18
0.71– 1.19	0.8 4.0	+2.0 0	−0.8 −2.0	1.6 7.1	+ 3.5 0	− 1.6 − 3.6	2.5 8.0	+ 3.5 0	− 2.5 − 4.5	4.5 13.0	+ 5.0 0	− 4.5 − 8.0	7 23	+ 8 0	− 7 − 15	10 34	+ 12 0	− 10 − 22
1.19– 1.97	1.0 5.1	+2.5 0	−1.0 −2.6	2.0 8.5	+ 4.0 0	− 2.0 − 4.5	3.0 9.5	+ 4.0 0	− 3.0 − 5.5	5.0 15.0	+ 6 0	− 5.0 − 9.0	8 28	+ 10 0	− 8 − 18	12 44	+ 16 0	− 12 − 28
1.97– 3.15	1.2 6.0	+3.0 0	−1.0 −3.0	2.5 10.0	+ 4.5 0	− 2.5 − 5.5	4.0 11.5	+ 4.5 0	− 4.0 − 7.0	6.0 17.5	+ 7 0	− 6.0 − 10.5	10 34	+ 12 0	− 10 − 22	14 50	+ 18 0	− 14 − 32
3.15– 4.73	1.4 7.1	+3.5 0	−1.4 −3.6	3.0 11.5	+ 5.0 0	− 3.0 − 6.5	5.0 13.5	+ 5.0 0	− 5.0 − 8.5	7 21	+ 9 0	− 7 − 12	11 39	+ 14 0	− 11 − 25	16 60	+ 22 0	− 16 − 38
4.73– 7.09	1.6 8.1	+4.0 0	−1.6 −4.1	3.5 13.5	+ 6.0 0	− 3.5 − 7.5	6 16	+ 6 0	− 6 − 10	8 24	+10 0	− 8 − 14	12 44	+16 0	− 12 − 28	18 68	+25 0	− 18 − 43
7.09– 9.85	2.0 9.3	+4.5 0	−2.0 −4.8	4.0 15.5	+ 7.0 0	− 4.0 − 8.5	7 18.5	+ 7 0	− 7 − 11.5	10 29	+12 0	− 10 − 17	16 52	+18 0	− 16 − 34	22 78	+28 0	− 22 − 50
9.85–12.41	2.2 10.2	+5.0 0	−2.2 −5.2	4.5 17.5	+ 8.0 0	− 4.5 − 9.5	7 20	+ 8 0	− 7 − 12	12 32	+12 0	− 12 − 20	20 60	+20 0	− 20 − 40	28 88	+30 0	− 28 − 58
12.41–15.75	2.5 12.0	+6.0 0	−2.5 −6.0	5.0 20.0	+ 9.0 0	− 5 − 11	8 23	+ 9 0	− 8 − 14	14 37	+14 0	− 14 − 23	22 66	+22 0	− 22 − 44	30 100	+35 0	− 30 − 65
15.75–19.69	2.8 12.8	+6.0 0	−2.8 −6.8	5.0 21.0	+10.0 0	− 5 − 11	9 25	+10 0	− 9 − 15	16 42	+16 0	− 16 − 26	25 75	+25 0	− 25 − 50	35 115	+40 0	− 35 − 75

All data above heavy lines are in accordance with American-British-Canadian (ABC) agreements. Symbols H6, H7, s6, etc. are hole and shaft designations in ABC system. Limits for sizes above 19.69 inches are not covered by ABC agreements but are given in the ANSI Standard.

* Pairs of values shown represent minimum and maximum amounts of interference resulting from application of standard tolerance limits.

TABLE 29 *ANSI standard clearance locational fits.* (Courtesy ASME)

American National Standard Transition Locational Fits (ANSI B4.1-1967, R1994)

Nominal Size Range, Inches		Class LT 1			Class LT 2			Class LT 3			Class LT 4			Class LT 5			Class LT 6		
			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits			Std. Tolerance Limits	
Over	To	Fit*	Hole H7	Shaft js6	Fit*	Hole H8	Shaft js7	Fit*	Hole H7	Shaft k6	Fit*	Hole H8	Shaft k7	Fit*	Hole H7	Shaft n6	Fit*	Hole H7	Shaft n7
		Values shown below are in thousandths of an inch																	
0	0.12	−0.12 +0.52	+0.4 0	+0.12 −0.12	−0.2 +0.8	+0.6 0	+0.2 −0.2							−0.5 +0.15	+0.4 0	+0.5 +0.25	−0.65 +0.15	+0.4 0	+0.65 +0.25
0.12	0.24	−0.15 +0.65	+0.5 0	+0.15 −0.15	−0.25 +0.95	+0.7 0	+0.25 −0.25							−0.6 +0.2	+0.5 0	+0.6 +0.3	−0.8 +0.2	+0.5 0	+0.8 +0.3
0.24	0.40	−0.2 +0.8	+0.6 0	+0.2 −0.2	−0.3 +1.2	+0.9 0	+0.3 −0.3	−0.5 +0.5	+0.6 0	+0.5 +0.1	−0.7 +0.8	+0.9 0	+0.7 +0.1	−0.8 +0.2	+0.6 0	+0.8 +0.4	−1.0 +0.2	+0.6 0	+1.0 +0.4
0.40	0.71	−0.2 +0.9	+0.7 0	+0.2 −0.2	−0.35 +1.35	+1.0 0	+0.35 −0.35	−0.5 +0.6	+0.7 0	+0.5 +0.1	−0,8 +0.9	+1.0 0	+0.8 +0.1	−0.9 +0.2	+0.7 0	+0.9 +0.5	−1.2 +0.2	+0.7 0	+1.2 +0.5
0.71	1.19	−0.25 +1.05	+0.8 0	+0.25 −0.25	−0.4 +1.6	+1.2 0	+0.4 −0.4	−0.6 +0.7	+0.8 0	+0.6 +0.1	−0.9 +1.1	+1.2 0	+0.9 +0.1	−1.1 +0.2	+0.8 0	+1.1 +0.6	−1.4 +0.2	+0.8 0	+1.4 +0.6
1.19	1.97	−0.3 +1.3	+1.0 0	+0.3 −0.3	−0.5 +2.1	+1.6 0	+0.5 −0.5	−0.7 +0.9	+1.0 0	+0.7 +0.1	−1.1 +1.5	+1.6 0	+1.1 +0.1	−1.3 +0.3	+1.0 0	+1.3 +0.7	−1.7 +0.3	+1.0 0	+1.7 +0.7
1.97	3.15	−0.3 +1.5	+1.2 0	+0.3 −0.3	−0.6 +2.4	+1.8 0	+0.6 −0.6	−0.8 +1.1	+1.2 0	+0.8 +0.1	−1.3 +1.7	+1.8 0	+1.3 +0.1	−1.5 +0.4	+1.2 0	+1.5 +0.8	−2.0 +0.4	+1.2 0	+2.0 +0.8
3.15	4.73	−0.4 +1.8	+1.4 0	+0.4 −0.4	−0.7 +2.9	+2.2 0	+0.7 −0.7	−1.0 +1.3	+1.4 0	+1.0 +0.1	−1.5 +2.1	+2.2 0	+1.5 +0.1	−1.9 +0.4	+1.4 0	+1.9 +1.0	−2.4 +0.4	+1.4 0	+2.4 +1.0
4.73	7.09	−0.5 +2.1	+1.6 0	+0.5 −0.5	−0.8 +3.3	+2.5 0	+0.8 −0.8	−1.1 +1.5	+1.6 0	+1.1 +0.1	−1.7 +2.4	+2.5 0	+1.7 +0.1	−2.2 +0.4	+1.6 0	+2.2 +1.2	−2.8 +0.4	+1.6 0	+2.8 +1.2
7.09	9.85	−0.6 +2.4	+1.8 0	+0.6 −0.6	−0.9 +3.7	+2.8 0	+0.9 −0.9	−1.4 +1.6	+1.8 0	+1.4 +0.2	−2.0 +2.6	+2.8 0	+2.0 +0.2	−2.6 +0.4	+1.8 0	+2.6 +1.4	−3.2 +0.4	+1.8 0	+3.2 +1.4
9.85	12.41	−0.6 +2.6	+2.0 0	+0.6 −0.6	−1.0 +4.0	+3.0 0	+1.0 −1.0	−1.4 +1.8	+2.0 0	+1.4 +0.2	−2.2 +2.8	+3.0 0	+2.2 +0.2	−2.6 +0.6	+2.0 0	+2.6 +1.4	−3.4 +0.6	+2.0 0	+3.4 +1.4
12.41	15.75	−0.7 +2.9	+2.2 0	+0.7 −0.7	−1.0 +4.5	+3.5 0	+1.0 −1.0	−1.6 +2.0	+2.2 0	+1.6 +0.2	−2.4 +3.3	+3.5 0	+2.4 +0.2	−3.0 +0.6	+2.2 0	+3.0 +1.6	−3.8 +0.6	+2.2 0	+3.8 +1.6
15.75	19.69	−0.8 +3.3	+2.5 0	+0.8 −0.8	−1.2 +5.2	+4.0 0	+1.2 −1.2	−1.8 +2.3	+2.5 0	+1.8 +0.2	−2.7 +3.8	+4.0 0	+2.7 +0.2	−3.4 +0.7	+2.5 0	+3.4 +1.8	−4.3 +0.7	+2.5 0	+4.3 +1.8

All data above heavy lines are in accord with ABC agreements. Symbols H7, js6, etc. are hole and shaft designations in ABC system.
* Pairs of values shown represent maximum amount of interference (−) and maximum amount of clearance (+) resulting from application of standard tolerance limits.

TABLE 30 *ANSI Standard Transition Locational Fits.* (Courtesy ASME)

Tolerance limits given in body of table are added or subtracted to basic size (as indicated by + or − sign) to obtain maximum and minimum sizes of mating parts.

Nominal Size Range, Inches	Class LN 1			Class LN 2			Class LN 3		
	Limits of Interference	Standard Limits		Limits of Interference	Standard Limits		Limits of Interference	Standard Limits	
		Hole H6	Shaft n5		Hole H7	Shaft p6		Hole H7	Shaft r6
Over To	Values shown below are given in thousandths of an inch								
0– 0.12	0 0.45	+0.25 0	+0.45 +0.25	0 0.65	+0.4 0	+0.65 +0.4	0.1 0.75	+0.4 0	+0.75 +0.5
0.12– 0.24	0 0.5	+0.3 0	+0.5 +0.3	0 0.8	+0.5 0	+0.8 +0.5	0.1 0.9	+0.5 0	+0.9 +0.6
0.24– 0.40	0 0.65	+0.4 0	+0.65 +0.4	0 1.0	+0.6 0	+1.0 +0.6	0.2 1.2	+0.6 0	+1.2 +0.8
0.40– 0.71	0 0.8	+0.4 0	+0.8 +0.4	0 1.1	+0.7 0	+1.1 +0.7	0.3 1.4	+0.7 0	+1.4 +1.0
0.71– 1.19	0 1.0	+0.5 0	+1.0 +0.5	0 1.3	+0.8 0	+1.3 +0.8	0.4 1.7	+0.8 0	+1.7 +1.2
1.19– 1.97	0 1.1	+0.6 0	+1.1 +0.6	0 1.6	+1.0 0	+1.6 +1.0	0.4 2.0	+1.0 0	+2.0 +1.4
1.97– 3.15	0.1 1.3	+0.7 0	+1.3 +0.8	0.2 2.1	+1.2 0	+2.1 +1.4	0.4 2.3	+1.2 0	+2.3 +1.6
3.15– 4.73	0.1 1.6	+0.9 0	+1.6 +1.0	0.2 2.5	+1.4 0	+2.5 +1.6	0.6 2.9	+1.4 0	+2.9 +2.0
4.73– 7.09	0.2 1.9	+1.0 0	+1.9 +1.2	0.2 2.8	+1.6 0	+2.8 +1.8	0.9 3.5	+1.6 0	+3.5 +2.5
7.09– 9.85	0.2 2.2	+1.2 0	+2.2 +1.4	0.2 3.2	+1.8 0	+3.2 +2.0	1.2 4.2	+1.8 0	+4.2 +3.0
9.85–12.41	0.2 2.3	+1.2 0	+2.3 +1.4	0.2 3.4	+2.0 0	+3.4 +2.2	1.5 4.7	+2.0 0	+4.7 +3.5
12.41–15.75	0.2 2.6	+1.4 0	+2.6 +1.6	0.3 3.9	+2.2 0	+3.9 +2.5	2.3 5.9	+2.2 0	+5.9 +4.5
15.75–19.69	0.2 2.8	+1.6 0	+2.8 +1.8	0.3 4.4	+2.5 0	+4.4 +2.8	2.5 6.6	+2.5 0	+6.6 +5.0

All data in this table are in accordance with American-British-Canadian (ABC) agreements.

Limits for sizes above 19.69 inches are not covered by ABC agreements but are given in the ANSI Standard.

Symbols H7, p6, etc. are hole and shaft designations in ABC system.

* Pairs of values shown represent minimum and maximum amounts of interference resulting from application of standard tolerance limits.

TABLE 31 *ANSI Standard Interference Locational Fits.* (Courtesy ASME)

Nominal Size Range, Inches	Class FN 1			Class FN 2			Class FN 3			Class FN 4			Class FN 5		
		Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits	
Over To	Interference*	Hole H6	Shaft	Interference*	Hole H7	Shaft s6	Interference*	Hole H7	Shaft t6	Interference*	Hole H7	Shaft u6	Interference*	Hole H8	Shaft x7
	Values shown below are in thousandths of an inch														
0–0.12	0.05 0.5	+0.25 0	+0.5 +0.3	0.2 0.85	+0.4 0	+0.85 +0.6				0.3 0.95	+0.4 0	+0.95 +0.7	0.3 1.3	+0.6 0	+1.3 +0.9
0.12–0.24	0.1 0.6	+0.3 0	+0.6 +0.4	0.2 1.0	+0.5 0	+1.0 +0.7				0.4 1.2	+0.5 0	+1.2 +0.9	0.5 1.7	+0.7 0	+1.7 +1.2
0.24–0.40	0.1 0.75	+0.4 0	+0.75 +0.5	0.4 1.4	+0.6 0	+1.4 +1.0				0.6 1.6	+0.6 0	+1.6 +1.2	0.5 2.0	+0.9 0	+2.0 +1.4
0.40–0.56	0.1 0.8	+0.4 0	+0.8 +0.5	0.5 1.6	+0.7 0	+1.6 +1.2				0.7 1.8	+0.7 0	+1.8 +1.4	0.6 2.3	+1.0 0	+2.3 +1.6
0.56–0.71	0.2 0.9	+0.4 0	+0.9 +0.6	0.5 1.6	+0.7 0	+1.6 +1.2				0.7 1.8	+0.7 0	+1.8 +1.4	0.8 2.5	+1.0 0	+2.5 +1.8
0.71–0.95	0.2 1.1	+0.5 0	+1.1 +0.7	0.6 1.9	+0.8 0	+1.9 +1.4				0.8 2.1	+0.8 0	+2.1 +1.6	1.0 3.0	+1.2 0	+3.0 +2.2
0.95–1.19	0.3 1.2	+0.5 0	+1.2 +0.8	0.6 1.9	+0.8 0	+1.9 +1.4	0.8 2.1	+0.8 0	+2.1 +1.6	1.0 2.3	+0.8 0	+2.3 +1.8	1.3 3.3	+1.2 0	+3.3 +2.5
1.19–1.58	0.3 1.3	+0.6 0	+1.3 +0.9	0.8 2.4	+1.0 0	+2.4 +1.8	1.0 2.6	+1.0 0	+2.6 +2.0	1.5 3.1	+1.0 0	+3.1 +2.5	1.4 4.0	+1.6 0	+4.0 +3.0
1.58–1.97	0.4 1.4	+0.6 0	+1.4 +1.0	0.8 2.4	+1.0 0	+2.4 +1.8	1.2 2.8	+1.0 0	+2.8 +2.2	1.8 3.4	+1.0 0	+3.4 +2.8	2.4 5.0	+1.6 0	+5.0 +4.0
1.97–2.56	0.6 1.8	+0.7 0	+1.8 +1.3	0.8 2.7	+1.2 0	+2.7 +2.0	1.3 3.2	+1.2 0	+3.2 +2.5	2.3 4.2	+1.2 0	+4.2 +3.5	3.2 6.2	+1.8 0	+6.2 +5.0
2.56–3.15	0.7 1.9	+0.7 0	+1.9 +1.4	1.0 2.9	+1.2 0	+2.9 +2.2	1.8 3.7	+1.2 0	+3.7 +3.0	2.8 4.7	+1.2 0	+4.7 +4.0	4.2 7.2	+1.8 0	+7.2 +6.0
3.15–3.94	0.9 2.4	+0.9 0	+2.4 +1.8	1.4 3.7	+1.4 0	+3.7 +2.8	2.1 4.4	+1.4 0	+4.4 +3.5	3.6 5.9	+1.4 0	+5.9 +5.0	4.8 8.4	+2.2 0	+8.4 +7.0
3.94–4.73	1.1 2.6	+0.9 0	+2.6 +2.0	1.6 3.9	+1.4 0	+3.9 +3.0	2.6 4.9	+1.4 0	+4.9 +4.0	4.6 6.9	+1.4 0	+6.9 +6.0	5.8 9.4	+2.2 0	+9.4 +8.0

See footnotes at end of table.

Nominal Size Range, Inches	Class FN 1			Class FN 2			Class FN 3			Class FN 4			Class FN 5		
		Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits			Standard Tolerance Limits	
Over To	Interference*	Hole H6	Shaft	Interference*	Hole H7	Shaft s6	Interference*	Hole H7	Shaft t6	Interference*	Hole H7	Shaft u6	Interference*	Hole H8	Shaft x7
	Values shown below are in thousandths of an inch														
4.73– 5.52	1.2 2.9	+1.0 0	+2.9 +2.2	1.9 4.5	+1.6 0	+4.5 +3.5	3.4 6.0	+1.6 0	+6.0 +5.0	5.4 8.0	+1.6 0	+8.0 +7.0	7.5 11.6	+2.5 0	+11.6 +10.0
5.52– 6.30	1.5 3.2	+1.0 0	+3.2 +2.5	2.4 5.0	+1.6 0	+5.0 +4.0	3.4 6.0	+1.6 0	+6.0 +5.0	5.4 8.0	+1.6 0	+8.0 +7.0	9.5 13.6	+2.5 0	+13.6 +12.0
6.30– 7.09	1.8 3.5	+1.0 0	+3.5 +2.8	2.9 5.5	+1.6 0	+5.5 +4.5	4.4 7.0	+1.6 0	+7.0 +6.0	6.4 9.0	+1.6 0	+9.0 +8.0	9.5 13.6	+2.5 0	+13.6 +12.0
7.09– 7.88	1.8 3.8	+1.2 0	+3.8 +3.0	3.2 6.2	+1.8 0	+6.2 +5.0	5.2 8.2	+1.8 0	+8.2 +7.0	7.2 10.2	+1.8 0	+10.2 +9.0	11.2 15.8	+2.8 0	+15.8 +14.0
7.88– 8.86	2.3 4.3	+1.2 0	+4.3 +3.5	3.2 6.2	+1.8 0	+6.2 +5.0	5.2 8.2	+1.8 0	+8.2 +7.0	8.2 11.2	+1.8 0	+11.2 +10.0	13.2 17.8	+2.8 0	+17.8 +16.0
8.86– 9.85	2.3 4.3	+1.2 0	+4.3 +3.5	4.2 7.2	+1.8 0	+7.2 +6.0	6.2 9.2	+1.8 0	+9.2 +8.0	10.2 13.2	+1.8 0	+13.2 +12.0	13.2 17.8	+2.8 0	+17.8 +16.0
9.85–11.03	2.8 4.9	+1.2 0	+4.9 +4.0	4.0 7.2	+2.0 0	+7.2 +6.0	7.0 10.2	+2.0 0	+10.2 +9.0	10.0 13.2	+2.0 0	+13.2 +12.0	15.0 20.0	+3.0 0	+20.0 +18.0
11.03–12.41	2.8 4.9	+1.2 0	+4.9 +4.0	5.0 8.2	+2.0 0	+8.2 +7.0	7.0 10.2	+2.0 0	+10.2 +9.0	12.0 15.2	+2.0 0	+15.2 +14.0	17.0 22.0	+3.0 0	+22.0 +20.0
12.41–13.98	3.1 5.5	+1.4 0	+5.5 +4.5	5.8 9.4	+2.2 0	+9.4 +8.0	7.8 11.4	+2.2 0	+11.4 +10.0	13.8 17.4	+2.2 0	+17.4 +16.0	18.5 24.2	+3.5 0	+24.2 +22.0
13.98–15.75	3.6 6.1	+1.4 0	+6.1 +5.0	5.8 9.4	+2.2 0	+9.4 +8.0	9.8 13.4	+2.2 0	+13.4 +12.0	15.8 19.4	+2.2 0	+19.4 +18.0	21.5 27.2	+3.5 0	+27.2 +25.0
15.75–17.72	4.4 7.0	+1.6 0	+7.0 +6.0	6.5 10.6	+2.5 0	+10.6 +9.0	9.5 13.6	+2.5 0	+13.6 +12.0	17.5 21.6	+2.5 0	+21.6 +20.0	24.0 30.5	+4.0 0	+30.5 +28.0
17.72–19.69	4.4 7.0	+1.6 0	+7.0 +6.0	7.5 11.6	+2.5 0	+11.6 +10.0	11.5 15.6	+2.5 0	+15.6 +14.0	19.5 23.6	+2.5 0	+23.6 +22.0	26.0 32.5	+4.0 0	+32.5 +30.0

All data above heavy lines are in accordance with American-British-Canadian (ABC) agreements. Symbols H6, H7, s6, etc. are hole and shaft designations in ABC system. Limits for sizes above 19.69 inches are not covered by ABC agreements but are given in the ANSI standard.

* Pairs of values shown represent minimum and maximum amounts of interference resulting from application of standard tolerance limits.

TABLE 32 *ANSI Standard Force and Shrink Fits. (Courtesy ASME)*

Glossary

Abrasive Water Jet Machining (AWJM) Similar to WJM except that an abrasive is added to the water jet after it exits the nozzle.
Labrado Abrasivo con Chorro de Agua Similar al WJM, excepto que se le añade un abrasivo al chorro de agua luego que sale de la tobera.

Absolute System A type of numerical control system in which all coordinates are located from a fixed or absolute zero point.
Sistema Absoluto Un tipo de sistema de control numérico en el cual todas las coordenadas se localizan a base de un punto fijo o de cero absoluto.

Abstract Part of the written report to the client, this includes one or two sentences about the content of the report to capture a potential reader's interest.
Abstracto Parte de un informe escrito al cliente, éste incluye una o dos oraciones acerca del contenido del informe para capturar el interés de un posible lector.

Acme Screw thread form.
Acme Tipo de rosca de tornillo.

Active Coils The total coils minus the two end coils in a compression spring.
Espirales Activas El número total de espirales menos las dos espirales de los extremos en un resorte de compresión.

Actual Size Actual measured size of a feature.
Tamaño Real El tamaño real de un rasgo.

Acute Angle An angle less than 90°.
Ángulo Agudo Un ángulo menor de 90°.

Addendum The radial distance from the pitch diameter to the top of the tooth. It is equal to 1/P.
Altura de Cabeza La distancia radial desde el diámetro de paso hasta la altura del diente. Es igual a 1/P.

Adjustable Curve This instrument has a locking bow and is used to draw any radius from 6.75" to 200" (17 cm to 500 cm). It takes over where the ordinary compass leaves off and eliminates the beam compass.
Curva Ajustable Este instrumento tiene un arco con seguro que se usa para dibujar cualquier radio desde 6.75″ hasta 200″ (17 cm a 500 cm). Se puede usar donde el compás ordinario deja de ser útil y elimina al compás de viga.

Aligning of Features This occurs to correct the true projection concept. It is when the top hole is theoretically revolved to the cutting-plane line and projected to the sectional view.
Alineación de Rasgos Esto ocurre para corregir el concepto de proyección verdadera. Es cuando un agujero teoréticamente se revuelve al plano cortante y se proyecta en la vista seccional.

Alignment Chart A graphical representation of the relationship of two or more variables.
Gráfica de Alineamiento Una representación gráfica de la relación entre dos o más variables.

Allen Screw Special set screw or cap screw with hexagon socket in head.
Tornillo con Cabeza Hexagonal Un tornillo de fijación o tornillo pasante especial con una cavidad hexagonal en la cabeza.

Allowance Minimum clearance between mating parts. Specifically, the amount of room between two main parts, usually considered the tightest possible fit.
Concesión La separación mínima entre piezas apareadas. Específicamente, la cantidad de espacio entre dos partes principales, generalmente considerado como el encaje más apretado posible.

Alloy Two or more metals in combination, usually a fine metal with a baser metal.
Aleación Dos o más metales en combinación, generalmente un metal fino con un metal base.

Alloy Steel This is any steel that contains one or more alloying elements added to produce characteristics not available in unalloyed carbon steels.
Acero Aleado Esto es cualquier acero que contiene uno o más elementos de aleación, que se le añaden para producir características que no están disponibles en los aceros con carbón sin alearse.

Alphanumeric Refers to the totality of characters that are either alphabetic or numeric.
Alfanumérico Se refiere a la totalidad de los caracteres que son alfabéticos o numéricos.

Alternate Section Lining Combination of true projection and correct projection.
Revestimiento de Sección Alterna Una combinación de una proyección real y una proyección correcta.

Alternatives Convincing the client that a thorough investigation was done by the design group by including a brief summary of the alternatives that were considered but discarded and why.
Alternativas Convencer al cliente que se hizo una investigación exhaustiva por el grupo de diseño por medio de un resumen breve de las alternativas que se consideraron pero que se desecharon y por qué.

Altitude (of a prism) The perpendicular distance between its end polygons (or bases).
Altitud (de un prisma) La distancia perpendicular entre sus dos polígonos extremos o bases.

Aluminum A bright silvery metal that is very light. In addition to being light, it is an excellent conductor and able to resist corrosion. It is usually alloyed with copper to increase hardness and strength.
Aluminio Un metal plateado brilloso que es muy liviano. Además de ser liviano, es un excelente conductor eléctrico y es capaz de resistir la corrosión. Generalmente se alea con cobre para aumentar su dureza y resistencia.

Ammonia A colorless gas used in the development process of diazo and sepia prints.
Amoniaco Un gas incoloro que se usa en el desarrollo de las reproducciones de diazo y sepia.

Analysis Summarizing the major assumptions and calculations. Also, the study and evaluation of an object's characteristics.
Análisis Resumir las suposiciones principales y los cálculos. También, el estudio y evaluación de las características de un objeto.

Angle Gear Similar to a bevel gear except that the angles are at other than 90° to each other.
Engranaje Angular Similar a un engranaje de bisel, excepto que los ángulos son otros diferentes de 90° uno con respecto al otro.

Angle Iron A structural shape whose section is a right angle.
Hierro Angular Una forma estructural cuya sección transversal es un ángulo recto.

Angle of Thread The included angle between the sides of the thread.
Ángulo de Rosca El ángulo incluido entre los lados de una rosca.

Angle Plate Jig A modified form of a plate jig in which the surface to be machined is perpendicular to the locating surface.
Guía de Placa Angular Una forma modificada de una guía de placa en la cual la superficie a labrarse está perpendicular a la superficie de localización.

Angularity A feature control in which a given surface, axis, or center plane must form a specified angle other than 90° with a datum.
Angularidad Un rasgo de control en el cual una superficie, eje o plano central dado, debe pasar por un ángulo diferente de 90° respecto a una referencia.

Annealing The process of heating a part, soaking it until it is thoroughly heated, and slowly cooling it by turning off the furnace.
Recocer El proceso de calentar una pieza hasta que esté calentada completamente, y luego enfriarla lentamente al apagar el horno.

Anodizing The process of protecting aluminum by oxidizing in an acid bath using a direct current.
Anodizar El proceso de proteger el aluminio oxidándolo en un baño ácido usando una corriente directa.

Application A definable set of drafting tasks to be accomplished in a given drafting area; may be accomplished partly through manual procedures and partly through computerized procedures.
Aplicación Un grupo definible de tareas de dibujo industrial que deben ser llevadas a cabo en un área de dibujo dada; pueden lograrse parcialmente por medio de procedimientos manuales y parcialmente por medio de procedimientos computarizados.

Application Engineering This type of engineering takes previous designs into consideration when creating a new design. It is generally a team effort whose primary task is to modify and incorporate these existing concepts to meet the design requirements for the new system.
Ingeniería de Aplicación Este tipo de ingeniería considera los diseños previos al crear diseños nuevos. Generalmente es un esfuerzo en equipo cuya tarea primaria es modificar e incorporar aquellos conceptos existentes para cumplir con los requisitos del nuevo sistema.

Appliqué A generic term used to describe a variety of shortcut products used in drafting.

Aplicado Un término genérico usado para describir una variedad de productos de atajos que se usan en el dibujo industrial.

Arbor Press A machine that performs internal broaching operations using a push-type, rather than a pull-type broach.
Prensa de Husillo Una máquina que lleva a cabo las operaciones de brochado internas usando un broche de tipo de empuje en vez uno de tipo de halar.

Arc A part of a circle.
Arco Una parte de un círculo.

Arc-weld To weld by electric arc; the work is usually the positive terminal.
Soldadura de Arco Soldar por medio de un arco eléctrico; la pieza de trabajo generalmente es el terminal positivo.

Arrowhead The most commonly used termination symbol for dimension and leader lines.
Flecha El símbolo de terminación más común para las líneas de dimensión y directrices.

Artificial Intelligence The ability of a machine to improve its own operation or the ability of a machine to perform functions that are normally associated with human intelligence such as learning, adapting, reasoning, self-correction, and automatic improvement.
Inteligencia Artificial La habilidad de una máquina de mejorar su propia operación o la habilidad de una máquina para llevar a cabo funciones que normalmente están asociadas con la inteligencia humana, tales como el aprendizaje, adaptación, razonamiento, auto corrección y mejoría automática.

Assembled Isometric Assembly Drawings This style shows how a single product looks when assembled.
Dibujo de Ensamblaje Isométrico Ensamblado Este estilo muestra cómo un solo producto se vería ensamblado.

Assembly Drawing Illustrates how a product is assembled when completed.
Dibujo de Ensamblaje Ilustra como un producto se ensambla cuando completado.

Assembly Section This section occurs when a sectional drawing is made up of two or more parts. It shows how the various parts go together.
Sección de Ensamblaje Esta sección ocurre cuando se crea un dibujo seccional de dos o más piezas. Muestra cómo se unen la varias piezas.

Attribute Listing A systematic guide for checking the completeness of technical detail drawings. It includes the questions: What is the function? What size is it? What materials are used? Can it be made—how and with what processes? What other factors need to be checked?
Listado de Atributos. Una guía sistemática para verificar la plenitud de detalles técnicos en los dibujos. Incluye las preguntas: ¿Cuál es su función? ¿De que tamaño es? ¿Qué materiales se usan? ¿Puede hacerse—cómo y con qué procesos? ¿Qué otros factores necesitan verificarse?

Attributes The characteristics of a part.
Atributos Las características de una pieza.

Automated Assembly Assembly by means of operations performed automatically by machines that are controlled and monitored by computers.
Ensamblaje Automatizado Ensamblaje por medio de operaciones que se hace automáticamente por máquinas que son controladas y monitoreadas por computadoras.

Automated Process Planning Using a computer in developing a process plan.
Planificación Automática de Proceso Usar una computadora al desarrollar un plan de proceso.

Automation The conversion of a process or system to automatic operation.
Automatización La conversión de un proceso o sistema a una operación automática.

Auxiliary Section An auxiliary view in section.
Sección Auxiliar Una vista auxiliar en sección.

Auxiliary View An additional view of an object, usually of a surface inclined to the principal surfaces of the object to provide a true size and shape view.
Vista Auxiliar Una vista adicional de un objeto, generalmente de una superficie inclinada a las superficies principales de un objeto para proveer una vista del tamaño y forma real.

Axes Plural of axis.
Ejes El plural de eje.

Axis A longitudinal center line of the thread. Also, an imaginary line around which parts rotate or are regularly arranged.
Eje Una línea de centro longitudinal de una rosca. También, una línea imaginaria alrededor de la cual las piezas rotan o están ordenadas regularmente.

Axonometric Projection Three-dimensional drawings.
Proyección Axonométrica Dibujos tridimensionales.

Axonometric Sketching This type of sketching may be one of three types—isometric, dimetric, or trimetric. All relate to proportional scales and angle positions of length, width, and depth.
Croquis Axonométrico Este tipo de croquis puede ser de uno de tres tipos—isométrico, dimétrico o trimétrico. Todos se relacionan con las escalas de proporción y la posición angular del largo, ancho y profundidad.

Azimuth Bearing In this method, the total angle is used going clockwise from due north.

Orientación de Azimut En este método, el ángulo total se usa como si partiese a favor de las manecillas del reloj desde la dirección del norte.

Babbitt A soft alloy for bearings, mostly of tin with small amounts of copper and antimony.
Babbit Una aleación suave de cojinetes, hecha mayormente de estaño con pequeñas cantidades de cobre y antimonio.

Back Weld A weld applied to the opposite side of a joint after the major weld has been applied.
Soldadura trasera Una soldadura aplicada al lado posterior de la unión después de aplicar la soldadura principal.

Backlash Lost motion between moving parts, such as threaded shaft and nut or the teeth of meshing gears.
Contragolpe Perdida de movimiento entre partes móviles, tales como un eje de rosca y tuerca o los dientes de la malla de engranaje.

Balloon Number within a circle, used to identify parts.
Globo Número dentro de un círculo, utilizado para identificar las partes.

Base Circle Used to lay out an offset follower. It is a circle with a radius equal to the distance from the center of the shaft to the center of the follower at its lowest position.
Círculo de Base Utilizado para colocar un seguidor de desfase. Es un círculo con un radio igual a la distancia del centro del eje al centro del seguidor en su posición más baja.

Baseline The bottom line of the displacement diagram.
Línea de Base La línea inferior de un diagrama de desplazamiento.

Baseline Dimensioning A system of dimensioning where as many features of a part as are functionally practical are located from a common set of datums.
Dimensionamiento de Línea de Base Un sistema de dimensionamiento donde la mayoría de las características de una parte que sean funcionalmente prácticas están localizadas como un conjunto común de referencia.

Basic Dimension A theoretically "perfect" dimension similar to a reference or nominal dimension. It is used to identify the exact location, size, orientation, or shape of a feature.
Dimensión Básica Una dimensión teoréticamente perfecta similar a una referencia o una dimensión nominal. Esta es utilizada para identificar la localización exacta, tamaño, orientación o forma de una característica.

Basic Size The size from which the limits of size are derived by the application of allowances and tolerances.
Tamaño Básico El tamaño del cual los limites de tamaño se derivan por la aplicación de provisiones y tolerancias.

Batter The slope of the grade is used. For each unit of rise (R), there are four horizontal (H) units.
Batter La pendiente de un grado es utilizada. Para cada unidad de elevación (R), hay cuatro unidades horizontales (H).

Bearing A supporting member for a rotating shaft. Also, the bearing of a line is the direction of that line as it is drawn in the top view of a drawing.
Soporte Un miembro de apoyo para un eje que rota. También el rumbo de una línea es la dirección de esa línea como ésta es dibujada en vista superior de un dibujo.
Orientación La dirección de una línea según se dibuja en la vista superior de un dibujo.

Bend Allowance The amount of sheet metal required to make a bend over a specific radius.
Provisión de Curvatura La cantidad de plancha de metal requerida para doblar sobre un radio especifico.

Bend Allowance Charts Two basic types of charts used to calculate bend allowances in both the English and metric systems. One is used for 90° bends, and the other is used for bends from 1° to 180°.
Tablas de Concesión de Curvatura Son dos tipos básicos de tablas utilizadas para calcular la provisión de curvatura en el sistema métrico e inglés. Uno es utilizado para curvaturas de 90°, y el otro es utilizado para curvaturas entre 1° a 180°.

Bending An operation in which a metal part is simply bent to a desired angle.
Doblamiento Una operación en la cual una parte de metal es doblada a un ángulo deseado.

Between Symbol A symbolic means of indicating that the stated tolerance applies to a specified segment of a surface between designated points.
Entre Símbolo Un medio simbólico para indicar que la tolerancia establecida aplica a un segmento especifico de una superficie entre los puntos designados.

Bevel An inclined edge; not a right angle to joining surface.
Bisel Un borde inclinado, no en un ángulo recto a la superficie de unión.

Bevel Gear Cone-shaped in form with straight teeth that are on an angle to the axis of the shaft. It is used to transmit power and motion between intersecting shafts that are at 90° to each other.
Engranaje Biselado Coniforme con dientes rectos que están en un ángulo con el eje. Este es utilizado para transmitir potencia y movimiento entre ejes que se intersecan que están a 90° el uno del otro.

Beveled Rings These have a 15° bevel on the groove-engaging edge. They are installed in grooves having a comparable bevel on the load-bearing wall.

Anillos Biselados Estos tiene 15° de bisel en el borde de ranura de encaje. Estos están instalados en las ranuras con un bisel comparable a una pared de carga.

Bilateral Tolerance When this tolerance is applied to a dimension, the tolerance applies in both directions, but is not necessarily evenly distributed.
Tolerancia Bilateral Cuando esta tolerancia es aplicada a una dimensión, la tolerancia se aplica en ambas direcciones, pero no es necesariamente distribuida equitativamente.

Bisect To divide into two equal parts.
Bisecar Dividir en dos partes iguales.

Blanking An operation that produces a part cut completely by the punch and die. Also, a stamping operation in which a press uses a die to cut blanks from flat sheets or strips of metal.
Cortar Una operación que produce una parte cortada completamente por el perforador y el troquel. Una operación de estampado en la cual una presa es utilizada como troquel para cortar blancos de planchas planas o tiras de metal.

Blind Hole A hole that does not go completely through an object.
Agujero ciego Un agujero que no atraviesa completamente el objeto.

Blueprint A copy of a drawing.
Fotocalco Una copia de un dibujo.

Boardroom Sketching This technique works well with larger groups than the conversational style. Since there are more people involved, a larger surface—for better viewing—is needed. It can be a chalkboard, but more likely will be an enamel, glass, or dry-erase surface.
Sala de Conferencia de Croquis Esta técnica trabaja bien con grupos más grandes que los de estilo conversacional. Dado a que hay más personas involucradas, una superficie grande es necesaria para mejor visualización. Ésta puede ser una pizarra, pero más probable será una superficie de esmalte, cristal o del borrar seco.

Bolt A threaded fastener that passes directly through parts to hold them together, and uses a nut to tighten or hold the parts together. The tip of the nut is flat.
Perno Un sujetador de rosca que pasa directamente a través de las partes que sujeta juntas y utiliza una tuerca para sujetar estas partes. La punta de la tuerca es plana.

Bolt Circle A circular center line on a drawing, containing the centers of holes about a common center.
Círculo del Perno Una línea circular central en el dibujo que contiene los centros de los agujeros alrededor de un centro común.

Bore To enlarge a hole with a boring bar or tool in a lathe, drill press, or boring mill.

Taladrar Agrandar un agujero con una barra taladrante o herramienta en un torno, presa taladrante o fresadora taladrante.

Boring Mill A machine tool normally used to machine large workpieces.
Fresadora Taladrante Una maquinaria normalmente utilizada para fresar piezas de trabajo grandes.

Boss A cylindrical projection on a casting or a forging.
Saliente Cilíndrico Una proyección cilíndrica en una fundición o en una pieza forjada.

Bow Compass One of two types of compass. This type uses a spring and an adjusting screw to set the compass to the desired radius.
Compás de arco Uno de dos tipos de compás. Este tipo utiliza un resorte y un tornillo ajustador para colocar el compás en un radio deseado.

Bowed Rings They differ from conventional types in that they are bowed around an axis perpendicular to the diameter bisecting the gap. Their construction permits the rings to function as springs as well as fasteners.
Anillos arqueados Estos difieren de los tipos convencionales en que están arqueados alrededor del eje perpendicular al diámetro que biseca la apertura. La construcción de los anillos le permite funcionar como resortes al igual que como ajustadores.

Box Jig Designed to be used for parts that require machining on several sides.
Guía de cajón Diseñada para ser utilizada en las partes que requieren trabajos en varios lados.

Brass An alloy of copper and zinc.
Latón Una aleación de cobre y zinc.

Brazing The process of joining metals together with a nonferrous filler rod. A temperature above 1000°F, but just below the melting point, is used to join the parts.
Soldadura de Latón El proceso de unir metales con una varilla de relleno no ferrosa. Se utiliza una temperatura sobre 1000°F, pero justo por debajo del punto de fusión, para unir estas partes.

Breakdown (bender) It is the station 2 of the drop forging process—it forms the parts into special contours.
Rotura (dobladora) Es la estación 2 del proceso de forjamiento de caída, ésta forma las partes en un contorno especial.

Broach A tool for removing metal by pulling or pushing it across the work; the most common use is producing irregular hole shapes such as squares, hexagons, ovals, or splines.
Brocha Una herramienta para remover metal cuando esta es halada o empujada a través de la pieza. La más utilizada comúnmente produce agujeros irregulares tales como cuadrados, hexágonos, óvalos o estrías.

Broaching Machine Used to modify the shape of a workpiece by pulling tools called broaches across or through the part.
Brochadora Utilizada para modificar la forma de una pieza halando herramientas llamadas brochas a través de la parte.

Broken-Out Section A portion removed from the drawing in order to make a particular feature easier to understand.
Sección Removida Una porción removida de un dibujo para hacer que una característica en particular sea fácil de entender.

Bronze An alloy of eight or nine parts of copper and one part of tin.
Bronce Una aleación de ocho o nueve partes de cobre y una parte de estaño.

Buff To finish or polish on a buffing wheel composed of fabric with abrasive powders.
Lustrar Darle terminado o pulir en una rueda de pulido compuesta de tela con polvos abrasivos.

Burnish To finish or polish by pressure upon a smooth rolling or sliding tool.
Bruñir Darle terminado o pulir al presionar suavemente sobre una herramienta rodante o deslizante.

Burr The ragged edge or ridge left on metal after a cutting operation.
Borde No Terminado Borde sin acabar o saliente dejado en el metal luego de la operación de cortar.

Bushing A metal lining that acts as a bearing between rotating parts such as a shaft and pulley; also used on jigs to guide cutting tools.
Cojinete Revestimiento de metal que actúa como un cojinete entre las partes que rotan tales como el eje y la polea; también usado para guiar herramientas cortantes.

Butt Joint One of two kinds of basic rivet joints—the parts are butted and are held together by a cover plate or butt strap that is riveted to both parts.
Union de Tope Una de dos tipos de uniones básicas de remache—las partes se unen y se sujetan por una placa o banda que se remacha a ambas partes.

Cabinet Drawing Have the same range of receding axes as cavalier drawings, but the receding distances are drawn to half size.
Dibujo de Gabinete Tienen el mismo rango de ejes que se alejan tales como en los dibujos cavalier, pero las distancias que se alejan se dibujan a media escala.

CAD (Computer-Aided Drafting) The use of computers and peripheral devices to aid in the documentation of design projects.
CAD (Dibujo Industrial Asistido por Computadora) El uso de computadoras y aparatos periféricos para asistir en la documentación de los proyectos de diseño.

CAD System The hardware, software, and user in computer-aided drafting. It is usually referred to as a configuration of computer hardware. This is a misuse of the term. CAD hardware is just one of the previously mentioned three components needed to have a CAD system.
Sistema de CAD El equipo físico, software y el usuario en el dibujo asistido por computadora. Generalmente se conoce como la configuración del equipo físico de computadora. Esto es un uso inadecuado del término. El equipo físico para CAD es sólo uno de los tres componentes mencionados previamente necesarios para tener un sistema CAD.

CAE (Computer-Aided Engineering) Any use of a computer to assist in engineering tasks, analysis testing, calculating, design review, and experimentation.
Ingeniería Asistida por Computadora Cualquier uso de una computadora para asistir en las tareas de ingeniería, pruebas de análisis, cálculos, revisión de diseño y experimentación.

Calipers An instrument used for measuring diameters.
Calibrador Un instrumento usado para medir diámetros.

Callout A note on the drawing giving a dimension, specification, or machine process.
Nota Una nota en un dibujo que da una dimensión, especificación o proceso de labrado.

CAM (Computer-Aided Manufacturing) Refers to computer-controlled automation of the various manufacturing processes used in modern industry.
Manufactura Asistida por Computadora Se refiere a la automatización controlada por computadora de los varios procesos de manufactura usados en la industria moderna.

Cam A rotating shape for changing circular motion to reciprocating motion. Produces a simple means to obtain irregular or specified predictable, designed motion.
Leva Una figura que rota para cambiar el movimiento circular en un movimiento reciprocante. Produce una manera simple de obtener movimiento diseñado, irregular o predecible.

Cap Screw Usually used as a true screw, it passes through a clearance hole in one part and screws into another part.
Tornillo Pasante Generalmente se usa como un tornillo verdadero, pasa a través de un agujero pasante en una pieza y se atornilla en otra pieza.

Carburize To heat a low-carbon steel to approximately 2000°F in contact with material that adds carbon to the surface of the steel.
Carbonizar Calentar el acero bajo en carbón hasta aproximadamente 2000°F en contacto con material que le añade carbón a la superficie del acero.

Case Harden To harden the outer surface of a carburized steel by heating and then quenching.
Endurecer Endurecer la superficie exterior del acero carbonizado calentándolo y luego enfriándolo rápido.

Case Hardening The process of hardening the outside surface of a part to a preselected depth.
Endurecimiento Externo El proceso de endurecer la superficie exterior de una pieza hasta una profundidad predeterminada.

Cast Irons Metals in a family of cast ferrous metals.
Hierros de Fundición Metales en una familia de metales férreos de fundición.

Cast Steels Steels that are produced in ingot form by melting all component elements together and pouring the molten metal into a mold.
Aceros de Fundición Aceros que se producen en forma de lingotes derritiendo todos los elementos componentes juntos y vertiendo el metal derretido en un molde.

Casting A process of pouring molten metal into a mold that contains the desired shape in the form of a cavity.
Fundición de Molde Un proceso de verter metal derretido en un molde que contiene la forma deseada en la cavidad.

Cavalier Drawing A type of drawing in which a receding axis is drawn between 30° and 60° to the horizon, and the receding distances are drawn full size.
Dibujo Cavalier Un tipo de dibujo en el cual el eje que se aleja se dibuja entre 30° y 60° del horizonte y las distancias que se alejan se dibujan a escala completa.

CD-ROM Compact Disc, Read-Only Memory; a high-volume storage medium used to store drawing files electronically. Can be used to store large projects for permanent archiving.
CD-ROM Disco compacto, sólo para lecturas; un medio de almacenamiento de alta capacidad usado para almacenar archivos de dibujo electrónicamente. Puede usarse para almacenar grandes proyectos para archivo permanente.

Center Drill A special drill to produce bearing holes in the ends of a workpiece to be mounted between centers.
Taladro de Centro Un taladro especial para producir agujeros para cojinetes en los extremos de una pieza de trabajo montada entre centros.

Center Line A type of line used in drafting to indicate the center of an object; its main characteristic is that it is a broken line with one short dash in the center.
Línea de Centro Un tipo de línea que se usa en el dibujo industrial para indicar el centro de un objeto; su característica principal es que es una línea entrecortada con un guión corto en el centro.

Central Angle An angle formed by two radial lines from the center of the circle.
Ángulo Central Un ángulo formado por dos líneas radiales desde el centro del círculo.

Central Processing Unit (CPU) A unit of a computer that includes circuits controlling the interpretation and execution of instructions.
Unidad de Procesamiento Central Una unidad de una computadora que incluye circuitos que controlan la interpretación y ejecución de instrucciones.

Centrifugal Casting A process of pouring a measured amount of molten metal into a rotating mold.
Fundición Centrífuga El proceso de verter una cantidad medida de metal derretido en un molde que rota.

Ceramics Materials made by combining metallic and nonmetallic elements. Their main characteristics are that they have a high melting point, low conductivity, and are chemically and thermally stable. They are mainly used in electronics applications.
Cerámicas Materiales hechos combinando elementos metálicos y no metálicos. Sus características principales son que tienen un punto de fusión alto, conductividad eléctrica baja y son estables química y termalmente. Se usan mayormente para aplicaciones electrónicas.

Chain and Sprockets Used to transmit motion and power to shafts that are parallel to each other.
Cadena y Rueda Dentada Se usa para transmitir movimiento y poder a los ejes que están paralelos unos con otros.

Chain Dimensioning Successive dimensions that extend from one feature to another, rather than each originating at a datum.
Dimensionamiento de Cadena Dimensiones sucesivas que extienden de un rasgo al otro, en lugar de originarse cada uno de un conjunto común de referencia.

Chain Intermittent Weld A weld where each weld is applied directly opposite to each other on opposite sides of the joint.
Cadena de Soldadura Intermitente Una soldadura donde cada soldadura se aplica directamente opuesta una frente a la otra en lados opuestos de una unión.

Chamfer A beveled edge normally applied to cylindrical parts and a variety of different types of fasteners.
Chaflán Un borde biselado que normalmente se aplica a las partes cilíndricas y a una variedad de tipos de sujetadores.

Channel Jig A variation of the basic box jig (see also *Box Jig*).
Guía de Canal Una variación de la guía de cajón básica (vea también *Guía de Cajón*).

Character A letter, digit, or other symbol that is used as part of the organization, control, or representation of data.

Carácter Una letra, dígito u otro símbolo que se usa como parte de la organización, control o representación de datos.

Chase To cut threads with an external cutting tool.
Cincelar Cortar las roscas con una herramienta cortante externa.

Check Valves Used to restrict the flow of liquids through a pipe to one direction only.
Válvulas Reguladora Se usa para restringir el flujo de líquidos a través de una tubería hacia una dirección solamente.

Cheek In sand casting, this is a section that might be installed between the cope and the drag.
Mejilla En la fundición de molde en arena, esta es la sección que puede instalarse entre el armazón superior e inferior.

Chemical Milling A process that etches or shapes workpieces to close tolerances by chemically induced material removal.
Fresado Químico Un proceso que graba o forma las piezas de trabajo a tolerancias pequeñas por remoción de material químico.

Chill To harden the outer surface of cast iron by quick cooling, as in a metal mold.
Enfriar Endurecer la superficie externa del hierro fundido enfriándolo rápidamente, como en un molde de metal.

Chord Any straight line whose opposite ends terminate on the circumference of the circle.
Cuerda Cualquiera línea recta cuyos fines terminen en la circunferencia del círculo.

Chordal Addendum The distance from the top of the tooth to the point at which the chordal thickness is measured.
Altura de Cabeza Cordal La distancia desde la parte superior del diente al punto donde se mide el espesor cordal.

Chordal Thickness The length of the chord measured straight across at the pitch diameter. It is measured straight across tooth, not along the pitch diameter as is the circular thickness.
Espesor Cordal El largo de la cuerda medido directamente a través del diámetro de paso. Se mide directamente a través del diente, no a lo largo del diámetro de paso como es su espesor circular.

Chuck A device much like a vise, having movable jaws that grip and hold a rotating tool or workpiece.
Prensa de Sujeción Un aparato muy parecido a una prensa, que tiene mandíbulas movibles que aguantan una pieza o herramienta en rotación.

Circle A closed curve with all points at the same distance from the center point. Its major components are the diameter, the radius, and the circumference.
Círculo Una curva cerrada con todos los puntos a la misma distancia del punto central. Sus componentes principales son el diámetro, el radio y la circunferencia.

Circular Pitch The distance between corresponding points of adjacent teeth measured on the circumference of the pitch diameter. Also, the length of the arc along the pitch circle between the center of one gear tooth and the center of the next.
Largo de Paso Circular La distancia entre puntos correspondientes de dientes adyacentes medido en la circunferencia del diámetro de paso. También, el largo del arco a lo largo del círculo de paso, entre el centro de un diente de engranaje y el centro del próximo.

Circular Runout A tolerance that identifies an infinite number of elemental tolerance zones on a feature when the feature is rotated 360° for each element.
Excentricidad Circular Una tolerancia que identifica un número infinito de zonas de tolerancia elemental en un rasgo cuando el rasgo se rota 360° para cada elemento.

Circularity Sometimes referred to as roundness, it is a feature control for a surface of revolution (cylinder, sphere, cone, etc.). It specifies that all points of a surface must be equidistant from the center line or axis of the object in question.
Circularidad A veces se conoce como redondez, es un control de rasgo para una superficie de revolución (cilindro, esfera, cono, etc.). Especifica que todos los puntos en una superficie tienen que estar equidistantes de la línea de centro o eje del objeto en cuestión.

Circumference The distance around the outer surface of a circle.
Circunferencia La distancia alrededor de la superficie exterior de un objeto.

Civil Engineer's Scale Also called a decimal-inch scale; measurements are read directly from the scale. Each graduation is equal to 1/10 of an inch if the number in the corner is 10.
Escala de Ingeniero Civil También se conoce como la escala de pulgada decimal; las medidas se miden directamente de la escala. Cada gradación es equivalente a 1/10 de una pulgada si el número en la esquina es 10.

Clapper Box This is where the cutting tool is mounted on the end of the ram in this unit.
Caja de Badajo Esto es cuando la herramienta cortante se monta sobre el extremo del pistón en esta unidad.

Clearance Fit A condition between mating parts in which there is always a clearance assembly. This is when the least material condition of the shaft is subtracted from the least material condition of the hole.
Encaje de Separación Una condición entre partes apareadas en la cual siempre hay un ensamblaje de separación. Esto es cuando la condición de material

mínimo de un eje se resta de la condición de material mínimo de un agujero.

Clearly Defined Ground Rules In a team situation, these are rules that are thoroughly understood and subscribed to by all team members. They state clearly what behaviors are expected of team members, including what will be tolerated and what will not.

Normas Básicas Claramente Definidas En una situación de equipo, éstas son las reglas que se entienden claramente y que son acogidas por todos los miembros del equipo. Declaran claramente qué comportamiento se espera de cada miembro del equipo, incluyendo qué se tolerará y qué no.

Clockwise Rotation in the same direction as the hands of a clock.

A Favor de las Manecillas de Reloj Rotación en el mismo sentido que las manecillas del reloj.

Closed Jigs Jigs that enclose the part on more than one side, and are intended to machine the part on several sides without moving the part from the jig.

Guías Cerradas Guías que encierran la pieza en uno o más lados, y su intención es poder labrar la pieza en varios lados sin mover la pieza de la guía.

Coil (turn) One full turn or 360° of the wire about the corner axis.

Espiral Un giro complete o 360° de ún alambre alrededor del eje de esquina.

Coin To form a part in one stamping operation.

Moneda Formar una pieza en una operación de estampado.

Cold Rolled Steel Bessemer steel containing .12% to .20% carbon that has been rolled while cold to produce a smooth, quite accurate stock.

Acero Rodado en Frío Acero Bessemer que contiene .12% a .20% de carbón que se rueda mientras está frío para producir piezas en bruto que son lisas y bastante precisas.

Collar A round flange or ring fitted on a shaft to prevent sliding.

Collar Un reborde o anillo redondo que encaja en un eje para evitar deslizamiento.

Compass An instrument for describing circles or transferring measurements. It consists of two pointed branches joined at the top by a pivot.

Compás Un instrumento para describir círculos o transferir medidas. Consiste de dos ramas puntiagudas unidas en la parte superior por un pivote.

Composites Materials created by combining two or more materials.

Material Compuesto Materiales creados combinando dos o más materiales.

Compound This occurs when more than one operation takes place on a part during a single stroke.

Combinado Esto ocurre cuando ocurre más de una operación sobre una parte durante un solo tiro.

Compression Spring Offers resistance to a compressive force or applies a pushing action. In its free state, the coils of the spring do not touch.

Resorte de Compresión Ofrece resistencia a una fuerza de compresión o aplica una acción de empuje. En su estado libre, los espirales del resorte no se tocan.

Compressive Force A force that "goes into" the joint.

Fuerza de Compresión Una fuerza que actúa "hacia" la unión.

Computational Fluid Dynamics (CFD) A means of using computers to mathematically simulate physical events. This involves the study of fluids and their characteristics under a variety of conditions.

Dinámica de Fluido Computacional Una manera de usar computadoras para simular matemáticamente los eventos físicos. Esto consiste de estudiar los fluidos y sus características bajo una variedad de condiciones.

Computational Prototype A three-dimensional computer-generated model that possesses the characteristics of a comparable physical object.

Prototipo Computacional Un modelo tridimensional generado a computadora que posee las características de un objeto físico comparable.

Computer Graphics A term that is sometimes misused a great deal. CG means using the computer and peripheral devices for producing any type of graphic image, technical or artistic.

Graficas Computarizadas Un término que frecuentemente se usa mal. Graficas computarizadas significa el uso de computadoras y los aparatos periféricos para producir cualquier tipo de imagen gráfica, técnica o artística.

Concentric Having a common center, as with circles or diameters.

Concéntrico Que tiene el centro común, como en los círculos o diámetros.

Concentric Circle Two or more circles with a common center point.

Círculo Concéntrico Dos o más círculos con un punto central común.

Concentricity A tolerance in which the axis of a feature must be coaxial to a specified datum regardless of the datum's and the feature's size.

Concentricidad Una tolerancia en la cual el eje de un rasgo debe ser coaxial a una referencia independientemente de la referencia y del tamaño del rasgo.

Conceptual Design Much use is made of known technical information from such sources as reference books, technical journals, and handbooks.

Diseño Conceptual Hace mucho uso de la información técnica conocida de fuentes tales como libros de referencia, revistas técnicas y manuales.

Cone A pyramid with a central axis and an infinite number of sides, which form a continuous curved lateral surface.
Cono Una pirámide con un eje central y un número infinito de lados, los cuales forman una superficie lateral curva y continua.

Configuration A group of machines, devices, parts, etc., that makes up a system.
Configuración Un grupo de máquinas, aparatos, partes, etc. que forman un sistema.

Conic Section A section cut by a plane passing through a cone.
Sección Cónica Una sección cortada por un plano que pasa a través de un cono.

Continuous Path Machine controls that are used to control the movement of the tool throughout the cutting cycle.
Paso Continuo Controles de máquina que se usan para controlar el movimiento de la herramienta a través del ciclo de corte.

Contour Interval The difference in elevation between neighboring contour lines.
Intervalo de Contorno La diferencia en elevación entre líneas de contorno adyacentes.

Contour Lines Used on topographical maps to connect points of elevation. They are a constant elevation on the surface of the earth, above sea level.
Líneas de Contorno Se usan en los mapas topográficos para conectar puntos de elevación. Muestran elevación constante en la superficie del terreno, por encima del nivel del mar.

Contract A binding legal document.
Contrato Un documento legal vinculante.

Conventional Break An effective way of drawing long objects of constant cross section on a relatively small sheet of drawing paper.
Corte Convencional Un método efectivo de dibujar los objetos largos de sección transversal constante en una hoja relativamente pequeña de papel.

Conversational Sketching This occurs when two or more people are huddled around a drafting board or a cafeteria table. The person doing the talking combines several types of sketches in one drawing as the idea is talked through.
Croquis Conversacional Esto ocurre cuando dos o más personas están reunidas alrededor de una mesa de dibujo o mesa de cafetería. La persona que habla combina distintos croquis en un dibujo a medida que se discute la idea.

Coordinate An ordered set of data values, either absolute or relative, that specifies a location.
Coordenada Un grupo ordenado de valores de datos, ya sean absolutos o relativos, que especifican una localización.

Coordinate Dimensioning A type of rectangular datum dimensioning in which all dimensions are measured from two or three mutually perpendicular datum planes; all dimensions originate at a datum and include regular extension and dimension lines and arrowheads.
Dimensionamiento Coordinado Un tipo de dimensionamiento de referencia rectangular en el cual las dimensiones se miden desde dos o tres planos de referencia mutuamente perpendiculares; todas las dimensiones se originan en una referencia e incluyen líneas de dimensión y de extensión regulares y flechas.

Cope In sand casting, this is the top half of the flask.
Armazón Superior En la fundición de molde en arena, ésta es la mitad superior del armazón.

Copper A heavy metal that is salmon pink in its pure form. It is nonmagnetic and has excellent conductivity.
Cobre Un metal pesado que es de color rosado como el salmón en su estado puro. No es magnético y tiene conductividad eléctrica excelente.

Core To form a hollow portion in a casting by using a dry-sand core or a green-sand core in a mold.
Poner Núcleo Formar una porción hueca en una fundición de molde usando un centro de arena seca o un centro de arena verde en el molde.

Core Prints When sand cores are intended to be installed in a cavity, core prints must also be provided to locate and anchor the sand cores during the casting process. They are a simple extension of the pattern.
Impresos de Centro Cuando se tienen que instalar los centros de arena en una cavidad, también deben proveerse impresos de centro para localizar y anclar los centros de arena durante el proceso de fundición. Son simples extensiones del patrón.

Costs This item is part of the written report to the client. It details the basic direct costs that the client will have to lay out to have the design made.
Costos Este artículo es parte del informe escrito al cliente. Detalla los costos básicos directos que el cliente tiene que pagar para hacer el diseño.

Counterbore The enlargement of the end of a hole to a specified diameter and depth.
Avellanar Engrandecer un extremo de un agujero a un diámetro y profundidad específica.

Counterbored Hole Usually a plain through hole with an upper portion enlarged cylindrically to a specified diameter and depth.
Agujero Avellanado Generalmente un agujero pasante simple con la porción superior engrandecida cilíndricamente a un diámetro y profundidad específica.

Countersink To chamfer the end of a hole to receive a flathead screw.
Escariar Biselar un extremo de un agujero para recibir un tornillo de cabeza plana.

Countersunk Hole Usually a plain through hole with an upper portion enlarged conically, most often to 82°, to accommodate standard flathead machine screws.
Agujero Escariado Generalmente un simple agujero pasante con la porción superior engrandecida cónicamente, frecuentemente a 82°, para acomodar la cabeza estándar de los tornillos de máquina.

CPU Central Processing Unit (see also *Central Processing Unit*).
CPU Unidad Central de Procesamiento (vea también *Unidad Central de Procesamiento*).

Creative Process A process designed to produce a finished design. The elements include: accumulating the necessary information about the problem; "incubating" this information with other ideas that the brain retrieves from memory; illuminating its presence until a potential/probable solution is found; verifying its workability.
Proceso Creativo Un proceso diseñado para producir un diseño terminado. Los elementos incluyen el acumular la información necesaria acerca del problema; "incubar" esta información con otras ideas que el cerebro tiene en memoria; iluminar su presencia hasta que se encuentre una solución potencial/probable; verificar su viabilidad.

Crest The top point joining the sides of a thread.
Cresta El punto superior que une los lados de una rosca.

Cursor (1) On a CRT, a movable marker that is visible on the viewing surface and is used to indicate a position at which an action is to take place or the position on which the next device operation would normally be directed. (2) On digitizers, a movable reference, usually optical crosshairs used by an operator to indicate manually the position of a reference point or line where an action is to take place.
Cursor (1) En un tubo de rayos catódicos, un marcador movible que se puede ver en la pantalla y que se usa para indicar la posición donde se llevará a cabo una acción o la posición adonde normalmente se dirigirá la próxima operación. (2) En los digitalizadores, una referencia movible, generalmente un "hilo de cabello" óptico usado por un operador para posicionar manualmente un punto o línea de referencia donde se llevará a cabo la acción.

Cutoff Saw Used to cut rough bar stock to lengths suitable for machining in other machine tools.
Sierra Tronzadora Se usa para cortar en bruto las barras de materiales en largos apropiados para labrarse con otras herramientas de labrado.

Cuts and Fills Leveling out a surface by excavating the earth of some of the higher points and using it to fill in the low points.
Cortar y Rellenar Aplanar una superficie excavando el terreno en los puntos más altos y usándola para rellenar los puntos bajos.

Cutting Off A cutting operation that is performed on a part to produce an edge other than a straight edge.
Cortar Una operación de corte que se hace en una pieza para producir un borde diferente a un borde recto.

Cutting-Plane Line Indicates that path an imaginary cutting plane follows to slice through an object.
Línea Plano Cortante Indica el camino que sigue el plano cortante imaginario para cortar el objeto.

Cylindrical A design where a shaft rotates exactly as it does in the radial design, but the action or direction of the follower differs greatly.
Cilíndrico Un diseño en el cual el eje rota exactamente como en el diseño radial, pero la acción o dirección del seguidor varía grandemente.

Cylindrical Grinder Used to precisely grind cylindrical or conical workpieces.
Moledora Cilíndrica Se usa para moler piezas de trabajo cilíndricas o cónicas.

Cylindricity A tolerance that simultaneously controls the surface of revolution for straightness, parallelism, and circularity of a feature, and is independent of any other features on a part. Also a feature control in which all elements of a surface of revolution form a cylinder. It gives the effect of circularity extended the entire length of the object, rather than just a specified cross section.
Cilindricidad Una tolerancia que simultáneamente controla la superficie de revolución para rectitud, paralelismo y circularidad de un rasgo, y que es independiente de cualquier otro rasgo en la pieza. También un rasgo de control al en el cual todos los elementos de una superficie de revolución forman un cilindro. Proporciona el efecto de circularidad extendida a lo largo del largo completo de un objeto en lugar de sólo en la sección transversal.

Data A representation of facts, concepts, or instructions in a formalized manner suitable for communication, interpretation, or processing by human or automatic means.
Datos Una representación de los hechos, conceptos o instrucciones, en un formato adecuado para la comunicación, interpretación o procesamiento por medios automáticos o humanos.

Datum Points, lines, planes, cylinders, and the like, assumed to be exact for purposes of computation, from which the location or geometric relationship (form) of features of a part may be established.
Referencia Puntos, líneas, planos, cilindros y así por estilo, que se asume que son exactos para propósitos de computación, desde los cuales se puede establecer la localización o forma geométrica de los rasgos de una parte.

Datum Feature The actual physical feature on a part used to establish a datum.
Rasgo de Referencia El rasgo físico real de una pieza que se usa para establecer una referencia.

Datum Feature Simulator A surface, the form of which is of such precise accuracy that it is used to simulate the datum.
Simulador de Rasgo de Referencia Una superficie, cuya forma es de tanta precisión que se usa para simular la referencia.

Datum Feature Symbol This symbol identifies datum features. It consists of a capital letter enclosed in a square frame. A leader line extends from the frame to the selected feature.
Símbolo de Rasgo de Referencia Este símbolo identifica los rasgos de referencia. Consiste de una letra mayúscula en un cuadro cuadrado. Una directriz se extiende desde el cuadro hasta el rasgo seleccionado.

Datum Identification Symbol A special rectangular box that contains the datum reference letter.
Símbolo de Identificación de Referencia Un cuadro rectangular especial que contiene la letra de la referencia.

Datum Plane A theoretically perfect plane from which measurements are made.
Plano de Referencia Un plano teóricamente perfecto desde el cual se hacen las medidas.

Datum Reference Frame A hypothetical three-dimensional frame that establishes the three axes of an X-Y-Z coordinate system into which the object being produced fits and from which measurements can be made.
Marco de Referencia Un marco de referencia tridimensional e hipotético, que establece los tres ejes de un sistema de coordenadas X-Y-Z sobre el cual encaja el objeto en producción y desde el cual se hacen las medidas.

Datum Surface (feature) A surface, the form of which is of such precise accuracy that it is used to simulate the datum.
Superficie de Referencia (rasgo) Una superficie, cuya forma es de tal precisión que se usa para simular la referencia.

Datum Target Symbol Identifies datum targets. It consists of a circle divided in half with a horizontal line.
Símbolo de Blanco de Referencia Identifica los blancos de referencia. Consiste de un círculo dividido en dos con una línea horizontal.

Decimal-Inch Dimensioning Frequently used in the dimensioning of technical drawings. It is much less cumbersome than fractional and still used more than metric.
Dimensionamiento de Pulgada Decimal Se usa frecuentemente en el dimensionamiento de los dibujos técnicos. Es mucho menos incómodo que el dimensionamiento fraccional y se usa más que el métrico.

Decimal-Inch Scale Also called a civil engineer's scale (see *Civil Engineer's Scale*).
Escala de Pulgada Decimal También se conoce como la escala de ingeniero civil (vea *Escala de Ingeniero Civil*).

Decision Table A table that systematically compares solution alternatives with every other alternative as to how well each one satisfies the constraints and specifications from the definition of the problem.
Tabla de Decisiones Una tabla que sistemáticamente compara las alternativas de soluciones con otras alternativas acerca de cuán bien cada una satisface las restricciones y especificaciones de la definición del problema.

Dedendum The radial distance from the pitch diameter to the bottom of the tooth.
Altura de Cabeza Baja La distancia radial desde el diámetro de paso a la parte inferior del diente.

Delineation Pictorial representations; a chart, a diagram, or a sketch.
Delineación Representaciones pictóricas; una gráfica, un diagrama o un croquis.

Depth of Thread The distance between the crest and the root of the thread, as measured at a right angle to the axis.
Profundidad de Rosca La distancia entre la cresta y la raíz de la rosca, medida a ángulos rectos del eje.

Design File A file that includes freehand sketches, machine copies of technical information, copies of related drawings, summaries of telephone conversations, interviews, and vendor brochures.
Archivo de Diseño Un archivo que incluye dibujos a pulso, copias a máquina de información técnica, copias de dibujos relacionados y resúmenes de conversaciones telefónicas, entrevistas y folletos de vendedores.

Design Hints Simple ideas used to help create the finished product. They help in initial designing and become checklists as the project progresses.
Sugerencias de Diseño Ideas simples usadas para ayudar a crear el producto final. Ayudan en el diseño inicial y se convierten en listas de comprobación a medida que el proyecto progresa.

Design Procedure Acts as a general guideline for a team of designers, engineers, and drafters on the best way to accomplish the procedure sequentially.
Procedimiento de Diseño Sirve como una guía general para un equipo de diseñadores, ingenieros y delineantes acerca de la mejor manera de lograr el procedimiento secuencialmente.

Design Section This section illustrates the uses of the drawing and the related engineering practices. It includes: preparing assembly, detail, and layout drawings; following design procedures; making comprehensive parts lists; executing engineering revisions; handling invention agreements; keeping personal technical files; and preparing quotations.
Sección de Diseño Esta sección ilustra los usos del dibujo y las prácticas de ingeniería relacionas. Incluye: el preparar dibujos del ensamblaje, de detalles y del arreglo; seguir los procedimientos de diseño; hacer listas de partes comprensivas; ejecutar revisiones de ingeniería; manejar los acuerdos de invención; mantener archivos técnicos personales; y el preparar cotizaciones.

Design Size The size of a feature after an allowance for clearance has been applied and tolerances have been assigned.
Tamaño de Diseño El tamaño de un rasgo después de aplicarle una concesión para separación y asignar las tolerancias.

Detail Drawing A drawing of a single part that provides all the information necessary in the production of that part.
Dibujo Detallado Un dibujo de una sola pieza que provee toda la información necesaria en la producción de esa pieza.

Detail Notes Specific notes that pertain to one particular element or characteristic of a part.
Notas de Detalles Notas específicas relacionadas a un elemento o característica particular de una pieza.

Developed Length The total length of a pattern.
Largo de Desarrollo El largo total de un patrón.

Development Drawing of the surface of an object unfolded on a plane. Also, the pattern or template of a shape that is laid out in a single flat plane in preparation for the bending or folding of a material to a required shape.
Desarrollo Dibujo de la superficie de un objeto desdoblado en un plano. También, el patrón de una figura que se traza en un solo plano liso en preparación para el doblez de un material a una forma deseada.

Development Surface The exterior and/or interior of the sheet material used to form an object.
Superficie de Desarrollo El exterior y/o interior del material en hoja usado para formar un objeto.

Deviation The variance from a specified dimension or design requirement.
Desviación La variación de una dimensión o requisitos de dimensión especificada.

DFA (Design for Assembly) Procedure An iterative loop that occurs simultaneously with the DFM loop. The emphasis is on assembly of parts. The DFA loop first considers which parts should be assembled automatically, and next considers which parts need to be assembled manually.
Procedimiento de Diseño para Ensamblaje Un ciclo iterativo que ocurre simultáneamente con el ciclo DFM. El énfasis está en el ensamblaje de las piezas. El ciclo DFA considera primero cuáles partes deberían ser ensambladas manualmente, y después considera cuáles partes deberían ser ensambladas por mano.

DFD (Design for Disassembly) A design program with the goal of designing products that can be disassembled so that the greatest amount of reusable or recyclable materials, such as metal and plastic, can be recovered.
Diseño para Despiezado Un programa de diseño con el propósito de diseñar productos que pueden desensamblarse de manera que se pueda recuperar la cantidad más grande de materiales reciclables o reusables, tales como metales o plásticos.

DFM (Design for Manufacturability) A procedure in the form of an iterative loop that acts as a guide for a design team.
Diseño para Manufacturabilidad Un procedimiento en forma de un ciclo iterativo que actúa como una guía para el equipo de diseño.

DFR (Design for Recyclability) A design program with the goal of designing products made from materials that can be recycled for a variety of purposes.
Diseño para Reciclabilidad Un programa de diseño con el propósito de diseñar productos hechos de materiales que pueden reciclarse para una variedad de propósitos.

Diagram A figure or drawing that is marked out by lines; a chart or outline.
Diagrama Una figura o dibujo que está marcado por líneas; una gráfica o bosquejo.

Diameter The length of a straight line passing through the center of a circle and terminating at the circumference on each end.
Diametro El largo de una línea recta que pasa a través del centro de un círculo y que termina en la circunferencia en cada extremo.

Diametral Pitch A ratio equal to the number of teeth (N) on a gear per inch of pitch diameter (D).
Largo de Paso Diametral Una razón equivalente al número de dientes (N) en un engranaje por pulgada del diámetro de paso (D).

Diazo Material that is either a film or paper sensitized by means of azo dyes used for photocopying.
Diazo Material que es o una película o un papel hecho sensitivo por medio de tintes azo usados para fotocopias.

Die The term has a double meaning. It can be used to describe the entire assembled tool or the lower cutting part of the tool. Also a hardened metal piece shaped to cut or form a required shape in a sheet of metal by pressing it against a mating die.
Troquel El término tiene significado doble. Puede usarse para describir una entera herramienta ensamblada o la parte inferior de la herramienta que corta. También es un pedazo de metal endurecido formado para cortar la figura necesaria en una hoja de metal presionándolo contra otro troquel.

Die Casting A process in which molten metal is forced into metal dies under pressure, producing very accurate and smooth castings.
Fundición a Presión Un proceso en el cual el metal derretido se fuerza en discos metálicos bajo presión, produciendo piezas de fundición muy precisas y suaves.

Die Stamping The process of cutting or forming a piece of sheet metal with a die.
Estampado de Troquel El proceso de cortar y formar un pedazo de hojalata con un troquel.

Digitize To use numeric characters to express or represent data.
Digitalizar Usar caracteres numéricos para expresar o representar data.

Digitizer A device for converting positional information into digital signals; typically, a drawing or other graphic is placed on the measuring surface of the digitizer and traced by the operator using a cursor.
Digitalizador Un aparato para convertir la información posicional en señales digitales; típicamente, se coloca un dibujo u otra gráfica en la superficie de medida del digitalizador y se traza por operador usando un cursor.

Dimension Measurements given on a drawing, such as size and location.
Dimensión Medidas dadas en un dibujo, tales como tamaño y localización.

Dimension Line This line is drawn as a solid, thin line of approximately the same width as a hidden line. It should be broken for dimensions and have arrowheads for terminations. It is used to indicate graphically the linear distance being dimensioned.
Línea de Dimensión Esta línea se dibuja como una línea sólida y fina de aproximadamente el mismo espesor que una línea escondida. Debería ser entrecortada para dimensiones y debería tener flechas para las terminaciones. Se usa para indicar gráficamente la distancia lineal que se está dimensionando.

Dimensioning The process whereby size and location data for the subject of a technical drawing are provided.
Dimensionamiento El proceso en el cual se provee información de tamaño y localización para el sujeto de un dibujo técnico.

Dimetric Drawing Differs from isometric drawing in that only two angles are equal.
Dibujo Dimétrico Difiere de los dibujos isométricos en que sólo dos ángulos son iguales.

Dip The downward angle of the vein with respect to a horizontal plane at the site of the ore vein.
Depresión El ángulo hacia abajo de una vena con respecto al plano horizontal en el lugar de la vena de mineral.

Direct Numerical Control (DNC) The use of a common host computer for the distribution of part programs to remote machine tools.
Control Numérico Directo El uso de una computadora común para la distribución de programas de parte para las herramientas de labrado remotas.

Direction This is originally handed down from higher management. It outlines where the team should be going, what they are hoping to accomplish, and specific as well as general guidelines as to how to get there.
Dirección Esto originalmente se envía desde la administración superior. Delinea adónde debería dirigirse un equipo, lo qué esperan lograr y guías específicas y generales de cómo llegar a ese punto.

Direction of Winding The direction in which a spring is wound. It can be wound right or left hand.
Dirección de Enrollado La dirección en la cual está enrollado un resorte. Puede estar enrollado a mano derecha o a mano izquierda.

Displacement Diagram A designated layout of the required motion of a cam. It is laid out on a grid, and its length represents one complete revolution of the cam.
Diagrama de Desplazamiento Una disposición designada que enseña la moción requisita de una leva. Se presenta sobre una rejilla, y su largo representa una revolución completa de la leva.

Display Monitor An output device resembling a television that displays the information on which the CAD technician is working.
Monitor de Despliegue Un aparato de salida parecido a un televisor que despliega la información en la cual el técnico de CAD está trabajando.

Double Weld Similar to a multiweld, the same type of weld may be used on opposite sides of a single joint; for example, double V, double U, or double J welds. Used for strength and appearance.
Soldadura Doble Similar a una soldadura múltiple, el mismo tipo de soldadura se puede usar en lados opuestos

de una unión; por ejemplo, soldaduras V doble, U doble o J doble. Se usa para fortaleza y apariencia.

Double-Curved Surface An object fully formed by curved lines with no straight lines.
Superficie de Doble Curva Un objeto completamente formado por líneas curvas sin ninguna línea recta.

Dowel A cylindrical pin, commonly used to prevent sliding between two contacting flat surfaces.
Clavija Un perno cilíndrico, comúnmente usado para evitar el deslizamiento entre dos superficies planas en contacto.

Draft The slope or taper of the sides of a pattern, which permits it to be removed from the cope and drag without disturbing the cavity.
Calada La pendiente o declive de los lados de un patrón, lo cual le permite que se remueva el armazón superior e inferior sin perturbar la cavidad.

Drafters People who do drafting.
Delineante Personas que hacen dibujos industriales.

Drafting Creating technical drawings to support the design process.
Dibujo Industrial El crear dibujos técnicos para apoyar al proceso de diseño.

Drag In sand casting, this is the bottom half of the flask.
Armazón Inferior En la fundición de molde en arena, ésta es la mitad inferior del armazón.

Draw To temper steel.
Estirar Templar el acero.

Drawing A process of stretching and forming a metal sheet into a shape similar to a cup or top hat.
Estirado El proceso de estirar y formar una hoja de metal en una forma similar a una taza o un sombrero de copa.

Drawing Surface Whether a tabletop or drawing board, it must be flat, smooth, and large enough to accommodate the drawing and some drafting equipment.
Superficie de Dibujo Ya sea la superficie de la mesa o tabla de dibujo, debe ser plana, lisa y lo suficientemente grande para acomodar el dibujo y el equipo de dibujo.

Drill To cut a cylindrical hole with a drill; a blind hole does not go through the piece.
Taladrar Cortar un agujero cilíndrico con una taladradora; un agujero ciego no atraviesa completamente la pieza.

Drill Bushings Used to position and guide the cutting tools used in jigs. The three basic types are press-fit bushings, renewable bushings, and liner bushings.
Cojinetes de Taladro Se usan para posicionar y guiar las herramientas de corte que se usan en guías. Los tres tipos básicos son los cojinetes de encaje a presión, los renovables y los de revestimiento.

Drill Press A machine that is used mainly for producing holes.
Taladradora de Columna Una máquina que se usa mayormente para producir agujeros.

Drop Forging The process of forming a heated metal bar, or billet, into dies by using a drop hammer or with great pressure.
Forjado El proceso de formar una barra de metal calentada, o lingote, en matrices usando un martillo de forja o con gran presión.

Drop-Bow Compass This compass is used for circles with diameters of .3″ (0.08 cm) to .50″ (1.3 cm). It is rotated by holding the knurled head between the thumb and the second finger.
Compás de Arco Caído Este compás se usa para círculos con diámetros de .3″ (0.08 cm) a .50″ (1.3 cm). Se rota aguantando la cabeza estriada entre el dedo pulgar y el segundo dedo.

Dry Transfer Sheet Designed according to the same principles as transfer cards. The only major difference is that they are sheets—not cards.
Hoja de Transferencia en Seco Diseñado de acuerdo a los mismos principios de las tarjetas de transferencia. La única diferencia mayor es que son hojas y no tarjetas.

Duplex Feature A method of indexing the fixture to the machine in two parts. In use, the first part is machined while the second is loaded. The fixture is then rotated, and the first is unloaded while the second is worked on, while a third is loaded on the empty side.
Rasgo Doble Un método de fijar un aditamento para labrar dos piezas. En uso, se labra la primera pieza mientras se carga la segunda. Luego se rota el aditamento, se descarga la primera pieza mientras se trabaja en la segunda y se carga una tercera pieza en el lado vacío.

Dwell The period of time during which the follower does not move.
Tiempo de Permanencia El periodo de tiempo durante el cual el seguidor no se mueve.

Eccentric Not having the same center; off center.
Excéntrico Que no tiene el mismo centro; fuera de centro.

ECO (Engineering Change Order) An order for a change in a drawing to make improvements or correct an error. An ECO is issued by an Engineering Change Request (ECR) committee after all departments concerned have agreed to the change.
ECO (Orden de Cambio de Ingeniería) Una orden para cambiar un dibujo para hacer mejoras o para corregir un error. Se emite una Orden de Cambio de Ingeniería por medio de un comité de Petición de Cambio

de Ingeniería después que todos los departamentos involucrados están de acuerdo con el cambio.

ECR (Engineering Change Request) A request to make a change in a drawing to make improvements or correct an error. The ECR explains what change is to be made, what it was before, why the change is to be made, whether it affects other parts, and who suggested the change. The request is made to an ECR committee, which issues an ECO after all departments concerned have agreed to the change.

ECR (Petición de Orden de Cambio) Una petición para hacer un cambio en un dibujo para hacer mejoras o para corregir un error. La Petición de Cambio de Ingeniería explica qué cambios se harán, cómo era antes, por qué se harán los cambios, si afecta a otras piezas y quién sugirió el cambio. La petición se la hace ante un comité de Petición de Cambio de Ingeniería, el cual emite una Orden de Cambio de Ingeniería después que todos los departamentos involucrados están de acuerdo con el cambio.

Elastomers Linear polymers that are able to stretch and return to their original shape and size (like an elastic band).

Elastómero Polímeros lineales que pueden estirarse y que regresan a su forma y tamaño original (como una banda elástica).

Electrical Discharge Grinding (EDG) A nontraditional machining process similar to EDM in that it employs rapidly recurring electrical discharges between an electrode and the workpiece in a dielectric fluid. The difference is that with EDG the electrode is a rotating wheel made of graphite or brass.

Amoladura por Descarga Eléctrica Un proceso de labrado no tradicional similar al labrado por descarga eléctrica (EDM) en que utiliza descargas eléctricas rápidas y recurrentes entre un electrodo y la pieza de trabajo en un líquido dieléctrico. La diferencia es que con la amoladura por descarga eléctrica el electrodo es una rueda rotativa hecha de grafito o azófar.

Electrical Discharge Machining (EDM) A nontraditional machining process that removes metal using a series of rapidly recurring electrical discharges between an electrically charged cutting tool and the workpiece submerged in a dielectric fluid.

Labrado por Descarga Eléctrica Un proceso de labrado no tradicional que remueve metal usando una serie de descargas eléctricas rápidas y recurrentes entre una herramienta cortante cargada eléctricamente y la pieza de trabajo sumergida en un líquido dieléctrico.

Electrical Discharge Wire Cutting (EDWC) A nontraditional machining process that is similar to the bandsawing process. Material removal occurs as the result of an electrical discharge as a wire electrode is drawn through the workpiece.

Corte con Alambre por Descarga Eléctrica Un proceso de labrado no tradicional que es similar al proceso de corte con sierra de cinta. La remoción de material ocurre como resultado de una descarga eléctrica de un electrodo de alambre, a medida que se lo pasa a través de la pieza de trabajo.

Electrical Plan This plan shows the house's electrical system superimposed on a floor plan without dimensions.

Plano Eléctrico Este plano muestra el sistema eléctrico de la casa sobrepuesto en el plano de distribución sin dimensiones.

Electrochemical Discharge Grinding (ECDG) A combination of two nontraditional machining processes: electro-chemical grinding (ECG) and electrical discharge grinding (EDG). In ECDG, alternating current or pulsating direct current moves from a bonded graphite wheel to a positively charged workpiece.

Amoladura por Descarga Electroquímica Una combinación de dos procesos de labrado no tradicionales: amoladura electroquímica y amoladura por descarga eléctrica. En la amoldadura por descarga electroquímica, una corriente alterna o corriente directa pulsante se mueve de una rueda de grafito a la pieza de trabajo cargada positivamente.

Electrochemical Grinding (ECG) A nontraditional machining process that combines abrasion with an electrochemical reaction that occurs on the surface of the metal.

Amoladora Electroquímica Un proceso de labrado no tradicional que combina la abrasión con una reacción electroquímica que ocurre en la superficie del metal.

Electrochemical Honing (ECH) A nontraditional machining process similar to ECG. It combines electrochemical oxidation of surface metal and abrasion. The primary difference is that honing is a process of removing material inside a drilled hole.

Afinación Electroquímica Un proceso de labrado no tradicional similar a la amoladura electroquímica. Combina la oxidación electroquímica de una superficie de metal y abrasión. La diferencia primaria es que la afinación es un proceso de remover material dentro de un agujero taladrado.

Electrochemical Machining (ECM) The process, with many variations, of removing metal by combining electricity with a chemical to cause a reaction that is the opposite of metal plating.

Labrado Electroquímico El proceso, con muchas variaciones, de remover metal combinando electricidad con un químico para causar una reacción que es lo opuesto del enchapado de metal.

Electrochemical Turning (ECT) A variation of ECM. The primary difference is that the workpiece rotates.

Torneado Electroquímico Una variación del labrado electroquímico. La diferencia principal es que la pieza de trabajo rota.

Electromechanical Machining (EMM) A process that improves the performance of traditional machining processes. Metal removal is accomplished in the traditional manner except that the workpiece is electrochemically polarized by applying a controlled voltage across the connection point between the workpiece and an electrolyte. This changes the surface of the workpiece, making it easier to machine.

Labrado Electromecánico Un proceso que mejora el rendimiento de los procesos de labrado tradicional. La remoción de metal se logra de una manera tradicional, excepto que la pieza de trabajo se polariza electroquímicamente aplicándole un voltaje controlado a través de un punto de conexión entre la pieza de trabajo y un electrolito. Esto cambia la superficie de la pieza de trabajo, haciéndola más fácil de labrar.

Electron Beam Machining (EBM) A thermal energy process. It uses thermal energy to remove metal.

Labrado con Rayo de Electrones Un proceso de energía termal. Usa energía termal para remover metal.

Elevations Orthographic views of the front, back, and sides of a structure. Most are exterior views; however, interior elevations of the kitchen, bathrooms, and utility areas are frequently included in residential plans.

Elevaciones Vistas ortográficas del frente, la parte trasera y los lados de una estructura. La mayoría son vistas exteriores; sin embargo, elevaciones interiores de las cocinas, baños y áreas útiles se incluyen frecuentemente en los planos residenciales.

Engineering Materials In modern manufacturing settings this term refers to the raw materials.

Materiales de Ingeniería En el ambiente de manufactura moderna, este término de refiere a los materiales brutos.

Epicycloid If the span of a cycloid is convex, an epicycloid is drawn.

Epicicloide Si la envergadura de un cicloide es convexa, se dibuja un epicicloide.

Equilateral Triangle A triangle having three sides of equal length, as well as three equal interior angles.

Triángulo Equilátero Un triángulo que tiene tres lados de largos iguales, al igual que tres ángulos interiores iguales.

Expanded Diameter When metal is displaced to each side, forming a raised portion or flute extending along each side of the groove, the crest of the flute creates this diameter. The diameter is a few thousandths larger than the nominal diameter of the stock.

Diámetro Expandido Cuando se despliega el metal a cada lado, formando una porción levantada o canaladura que se extiende a cada lado de la ranura, la cresta de la canaladura crea este diámetro. El diámetro es unas cuantas milésimas más grande que el diámetro nominal del material.

Exploded Isometric Drawing This style shows all the components of an assembly as individual isometric drawings, including fasteners; however, the components are aligned in space the identical way they are to be assembled.

Dibujo Isométrico Despiezado Este estilo muestra todos los componentes de un ensamblaje como dibujos isométricos individuales, incluyendo los sujetadores; sin embargo, los componentes se alinean en el espacio idénticamente como serán ensamblados.

Extension Lines Solid, thin lines of approximately the same width as hidden lines.

Líneas de Extensión Líneas sólidas y finas de aproximadamente el mismo grueso que las líneas escondidas.

Extension Spring A spring that offers resistance to a pulling force. In its free state the coils are usually touching or very close.

Resorte de Extensión Un resorte que ofrece resistencia a una fuerza de tirada. En su estado libre las espirales están tocándose o están muy cerca.

External Broaching Typically used to produce some gear teeth, plier jaws, and other similar details.

Brochado Externo Se usa típicamente para producir algunos dientes de engranajes, las mandíbulas de alicates y otros detalles similares.

External Client A large variety of people and organizations, both in classrooms and in industry.

Cliente Externo Una gran variedad de personas y organizaciones, tanto en los salones de clases y en la industria.

External Rings For axial assembly, rings that are expanded with pliers so they may be slipped over the end of a shaft, stud, or similar part.

Anillos Externos Para los ensamblajes axiales, los anillos que se expanden con alicates de manera que puedan colocarse alrededor de un extremo de un eje, un perno o una parte similar.

External Threads Threads located on the outside of a part, such as those on a bolt.

Roscas Externas Roscas que están localizadas en el exterior de la parte, tales como aquellos en los pernos.

Extruding A process of forcing metal through a die of a desired form and cross section.

Formar por Extrusión Un proceso de forzar metal a través de un troquel de la forma y corte transversal deseado.

Extrusion Metal that has been shaped by forcing it in its hot or cold state through dies of the desired shape.

Extrusión Metal que se forma forzándolo en su estado frío o caliente a través de troqueles de la forma deseada.

Fabrication A term used to distinguish production operations from assembly operations.
Fabricación Un término que se usa para distinguir las operaciones de producción de las operaciones de ensamblaje.

Face To finish a surface at right angles, or nearly so, to the center line of rotation on a lathe.
Encarar Acabar en un torno una superficie a un ángulo recto, o casi a un ángulo recto, de la línea de rotación de centro.

FAO Finish All Over.
Acabar por Todos Lados Acabar por Todos Lados.

Fastener A mechanical device for holding two or more bodies in definite positions with respect to each other.
Sujetador Un aparato mecánico para sujetar dos o más cuerpos en posiciones definidas, una con respecto a la otra.

Feature A portion of a part, such as a diameter, hole, keyway, or flat surface.
Rasgo Una porción de una parte, tal como un diámetro, agujero, muesca de posicionamiento o superficie plana.

Feature Control Symbol A rectangular box in which all data referring to the subject feature control are placed. These include the symbol, datum references, the feature control tolerance, and modifiers.
Símbolo del Control de Rasgo Una caja rectangular en que están colocados todos los datos que refieren al control del rasgo especificado. Puede incluir el símbolo, referencias del datum, la tolerancia del control de rasgo, y los modificadores.

Ferrous A metal having iron as its base material.
Ferroso Un metal que tiene hierro como su material base.

Field Weld Any weld not made in the factory; that is, a weld that is to be made at a later date, perhaps at final assembly on-site.
Soldadura de Campo Cualquier soldadura que no se hace en la factoría; esto es, una soldadura que se hará en algún punto en el futuro, quizás en el lugar del ensamblaje final.

File To finish or smooth with a file.
Limar Acabar o suavizar con una lima.

Fillet An interior rounded intersection between two surfaces.
Filete Una intersección interior redondeada entre dos superficies.

Fillet Weld A weld made at a concave junction formed where two metal parts meet.
Soldadura de Filete Una soldadura que se hace en una unión cóncava donde se encuentran dos piezas de metal.

Fin A thin extrusion of metal at the intersection of dies or sand molds.
Aleta Una extrusión fina de metal en la intersección de los troqueles o moldes de arena.

Finish General finish requirements such as paint, chemical, or electroplating, rather than surface texture or roughness (see *Surface Texture*).
Terminado Requisitos generales de terminado tales como pintura, químico o galvanización, en lugar de una textura de superficie o aspereza (ver *Textura de Superficie*).

Finishing Impression The final station on a drop forge die. It is used to finish the part to the desired shape and size.
Impresión Final La estación final en un troquel de forja. Se usa para terminar la pieza a la forma y tamaño deseada.

Finite-Element Analysis (FEA) A virtual means of analyzing the structural response of objects. In this method, a model of a part is broken up into a finite number of polygonal elements called a mesh.
Análisis de Elementos Finitos Un método virtual de analizar la respuesta estructural de los objetos. En este método, un modelo de una pieza se divide en un número finito de elementos poligonales llamados una malla.

Finite-Element Model (FEM) A three-dimensional model of an object, with nodes containing specific information about the characteristics of the object at that point. The nodes are connected together to create an FEA mesh, which is then analyzed.
Modelo de Elementos Finitos Un modelo tridimensional de un objeto, con nodos que contienen información específica acerca de las características del objeto en ese punto. Los nodos están conectados para crear una malla de análisis de elementos finitos, que luego se analiza.

Fit The clearance or interference between two mating parts.
Encaje La separación o interferencia entre dos partes que encajan.

Fixed-Renewable Bushing Used for applications where the bushings do not need to be changed often, but where they are changed more often than press-fit bushings.
Cojinete Fijo Renovable Se usa para aplicaciones donde los cojinetes no necesitan cambiarse frecuentemente, pero que se cambian más frecuentemente que los cojinetes de encaje a presión.

Fixture A workholding tool that references the cutting tool to the workpiece by means of a set block.
Aditamento Una herramienta de trabajo que refiere la herramienta cortante a la pieza de trabajo por medio de un bloque.

Flange A relatively thin rim around a piece.
Reborde Un borde relativamente fino alrededor de una pieza.

Flange Weld Used to join thin metal parts together. Instead of welding to the surfaces of the parts to be joined, the weld is applied to the edges of thin material.
Soldadura de Reborde Se usa para unir piezas finas de metal. En lugar de soldar en las superficies a unirse, la soldadura se aplica a los bordes del material.

Flask In sand casting, this is a two-part box, or frame, used to contain the sand.
Armazón En los modelos de fundación de arena, ésta es la caja de dos partes, o armadura, que se usa para contener arena.

Flat Pattern A layout showing true dimensions of a part before bending; may be actual-size pattern on polyester film for shop use.
Patrón Plano Un trazado que muestra las dimensiones verdaderas de una pieza antes de doblarse; puede ser un patrón de tamaño real en una película de poliéster para usarse en el taller.

Flat Spring This spring is usually flat. Made of spring steel, it is designed to perform a special function. It is considered a power spring, and it resists a pressure.
Resorte Plano Este resorte generalmente es plano. Está hecho de acero de resorte, está diseñado para llevar a cabo una función específica. Se considera un resorte de potencia y resiste a la presión.

Flatbed Plotter A plotter that draws an image on a data medium such as paper or film mounted on a table.
Trazador Gráfico Plano Un trazador gráfico que dibuja una imagen en un medio tal como papel o película sobre una mesa.

Flatness A tolerance that controls the amount of variation that the perfect plane on a feature independent of any other features on the part. Also, a feature control of a surface that requires all elements of the surface to lie within two hypothetical parallel planes.
Llanura Una tolerancia que controla la cantidad de variación del plano perfecto en un rasgo independiente de otros rasgos en la pieza. También, un control de rasgo de una superficie que requiere que todos los elementos de la superficie estén dentro de dos planos paralelos hipotéticos.

Flat-Plane Surface A surface where all points can be interconnected to form straight lines without exception.
Superficie Plana Una superficie donde todos los puntos pueden conectarse para formar líneas rectas sin excepción.

Floor Plan A plan view of the structure in section with the ceiling and roof removed.
Plano de Distribución Una vista aérea de la estructura en sección con el techo removido.

Flute Groove, as on twist drills, reamers, and taps.
Acanaladura Ranura, como en las barrenas, escariadores y los machos de rosca.

Fold Line The place where the imaginary perpendicular-orthographic viewing planes meet each other along the straight edge of intersection.
Línea de Doblez El lugar dónde los planos de vista imaginarios perpendiculares y ortográficos se encuentran a lo largo de los bordes rectos de intersección.

Foolproofing A method used to prevent parts from being loaded incorrectly. It involves a simple pin, which is normally enough to ensure proper loading of every part.
Hacer Infalible Un método usado para evitar que las partes sean cargadas incorrectamente. Consiste de un pasador simple, que normalmente es suficiente para asegurar que cada pieza esté cargada apropiadamente.

Foreshortening A phenomenon wherein the lengths of edges are shorter in the image than their actual lengths.
Escorzo Un fenómeno en el cual los largos de los bordes son más cortos en la imagen que sus largos actuales.

Forge To force metal while it is hot to take on a new shape by hammering or pressing.
Forjar Forzar el metal mientras está caliente para darle una nueva forma por medio de martilleo o prensado.

Form The form of a screw thread is actually its profile shape.
Forma La forma de una rosca de tornillo es en realidad su figura de perfil.

Forming An operation in which a part is bent or formed into a complex shape.
Moldeado Una operación en la cual una pieza se dobla o se forma en una figura compleja.

Form Tolerancing The permitted variation of a feature from the perfect form indicated on the drawing.
Tolerancia de Forma La variación permisible de un rasgo de su forma perfecta indicada en un dibujo.

Foundation Plan A plan view in section that shows the understructure of the building.
Plano de Cimiento Una vista aérea en sección que muestra la subestructura del edificio.

Fractional Dimensioning Generally not used on technical drawings, its primary use is on architectural or structural engineering drawings.
Dimensionamiento Fraccional Generalmente no se usa en los dibujos técnicos, su uso primario es en los dibujos arquitectónicos o estructurales.

Free Length The overall length of a spring when it is in its free state of unloaded condition.
Largo Libre El largo completo de un resorte cuando está en su estado libre de una condición sin carga.

Free-State Variation The concept that some parts cannot be expected to be contained.
Variación de Estado Libre El concepto de que no se puede esperar que algunas partes estén contenidas.

French Curve A thin plastic tool that comes in an assortment of curved surfaces. It is used to produce curved lines that cannot be made with a compass.
Curva Francesa Una herramienta plástica delgada que tiene una variedad de superficies curvas. Se usa para producir líneas curvas que no pueden hacerse con un compás.

Front View The orthographic view showing the front elevation.
Vista Frontal La vista ortográfica que muestra la elevación frontal.

Front View Auxiliary An auxiliary view projected from the front view.
Vista Frontal Auxiliar Una vista auxiliar proyectada desde la vista frontal.

Full Section A section of one of the regular multiviews that is sliced (cut) in two.
Sección Completa Una sección de una de las vistas múltiples regulares que fue cortada en dos.

Full Threads Threads that do not extend to the bottom of the hole.
Rosca Completa Las roscas que no se extienden hasta el fondo del agujero.

Full-Divided Scale A scale in which the units of measurements are subdivided throughout the length of the scale.
Escala Completa Dividida Una escala en la cual las unidades de medida están subdivididas a lo largo de la escala.

Fuller The first station on a drop forge die. This station is used to rough-form the part to fit the other cavities.
Batán La primera estación en un troquel de una forja. Esta estación se usa para formar la parte en bruto para que quepa en las otras cavidades.

Fusion Weld The intimate mating of molten metals producing the type of weld where a lot of heat is used to melt and fuse the joint.
Soldadura de Fusión La unión íntima de metales fundidos produciendo un tipo de soldadura en la cual se usa mucho calor para derretir y fundir los metales.

Gage A system of numbers used to specify the thickness of sheet metal.
Calibre Un sistema de números que se usan para especificar el espesor de una hoja de metal.

Galvanize To cover a surface with a thin layer of molten alloy, composed mainly of zinc.
Galvanizar Cubrir una superficie con una capa fina de una aleación derretida, compuesta mayormente por zinc.

Gasket A thin piece of rubber, metal, or some other material placed between surfaces to make a tight joint.
Junta Un pedazo fino de goma, metal u otro material que se coloca entre superficies para formar una unión fuerte.

Gate Valves Used to turn the flow of liquids through a pipe on or off without restricting the flow of the liquids through the valve or with as little restriction as possible.
Válvulas de Compuerta Se usan para encender o detener el flujo de metal derretido a través de una tubería sin restringir el flujo de los líquidos a través de la válvula o con tan poca restricción como sea posible.

Gear Tooth Caliper Used to check and measure an individual gear tooth.
Calibrador de Dientes de Engranaje Se usa para verificar y medir un diente de engranaje individual.

Gear Train Two or more gears used to achieve a designed RPM.
Tren de Engranajes Dos o más engranajes que se usan para obtener un número de revoluciones por minutos designado.

General Notes Broad items of information that have a job- or project-wide application rather than relating to one element or part.
Notas Generales Artículos amplios de información que tienen una aplicación a nivel del trabajo o de un proyecto en lugar de estar relacionadas con sólo un elemento o una parte.

General Oblique Drawing Similar to cabinet drawing except that the lines drawn along the direction of the receding distances may be at any scale the drafter chooses.
Dibujo Oblicuo General Similar a un dibujo de gabinete excepto que las líneas que se dibujan a lo largo de la dirección que se aleja pueden estar a cualquier escala escogida por el delineante.

Geometric Dimensioning and Tolerancing A means of dimensioning and tolerancing a drawing with respect to the actual function or relationship of part features that can be most economically produced; it includes positional and form dimensioning and tolerancing. It allows designers to set tolerance limits not just for the size of an object, but for all of the various critical characteristics of the part.

Dimensionamiento y Tolerancia Geométrica Un medio de dimensionamiento y de tolerar un dibujo con respecto a la función o relación actual de los rasgos de la pieza que pueden producirse más económicamente; incluye dimensionamiento y tolerancia de posición y de forma. Le permite a los diseñadores establecer límites de tolerancia no sólo para los tamaños de un objeto, pero para todas las características críticas de la parte.

Globe Valves Used to turn the flow of liquids through a pipe on and off.
Válvulas de Globo Se usan para permitir y detener el flujo de líquidos a través de una tubería.

Grade The ratio of the vertical rise (R) to the horizontal run (H).
Pendiente La razón entre la elevación vertical (R) y el tiro horizontal (H).

Graphic Communication Using visual material to relate ideas.
Comunicación Gráfica El uso de materiales visuales para comunicar ideas.

Graphical Method A method of approximating areas by dividing them into convenient shapes, e.g., trapezoids and triangles, scaling appropriate lengths, and calculating the areas.
Método Gráfico Un método de aproximar las áreas dividiéndolas en formas convenientes, por ejemplo, trapezoides y triángulos, ajustando los largos a la escala apropiada, y luego calculando las áreas.

Green Sand A type of sand used in sand casting. The mold is prepared by ramming the green sand around a model of a part.
Arena Verde Un tipo de arena que se usa en la fundición en moldes de arena. Los moldes se preparan compactando la arena verde alrededor de un modelo de una pieza.

Grind To remove metal by means of an abrasive wheel, often made of carborundum; used where accuracy is required.
Moler Remover material por medio de un material abrasivo, frecuentemente hecho de carborundo; se usa dónde se requiere precisión.

Groove Weld Seven types of welds are considered to be groove welds: square, V, bevel groove, J, U, flare V, and flare bevel.
Soldadura de Ranura Siete tipos de soldaduras se consideran soldaduras de ranuras: cuadrada, V, ranura bisel, J, U, V acampanado y bisel acampanado.

Grooved Fasteners Used to solve metal-to-metal pinning needs with shear application.
Sujetadores con Ranura Se usan para resolver las necesidades de sujetar metales a metales en aplicaciones con esquilado.

Grooved Studs Widely used for fastening light metal or plastic parts to heavier members or assemblies.
Clavija Ranurada Usado frecuentemente para sujetar partes de metal o plástico livianas a miembros de ensamblajes más pesados.

Group Technology Grouping of parts into families based on similarities in design or production processes.
Tecnología de Grupo Una agrupación de partes en familias basadas en similaridades de diseño o en el proceso de producción.

Gusset A small plate used in reinforcing assemblies.
Placa de Refuerzo Una pequeña placa que se usa para reforzar los ensamblajes.

Half Section A type of section view in which the object is cut only halfway through and a quarter section is removed.
Media Sección Un tipo de vista seccional en la cual el objeto se corta sólo hasta la mitad y se remueve un cuarto de sección.

Hard Copy A copy of output in a visually readable form (e.g., printed reports, listings documents, summaries, and drawings).
Copia Impresa Una copia de la salida en una forma leíble (por ejemplo, informes impresos, documentos de listados, resúmenes y dibujos).

Hard Disk Drive A storage device used in computers; it may be contained within the computer console or in an external cabinet that is attached to the processing unit. Key concerns relating to hard disk drives are storage capacity (typically measured in megabytes and gigabytes of memory) and access time.
Unidad de Disco Duro Un aparato de almacenamiento usado en las computadoras; puede estar contenido dentro de la consola de la computadora o en un gabinete externo que está conectado a la unidad de procesamiento. Las preocupaciones principales relacionadas a las unidades de disco duro son su capacidad de almacenamiento (típicamente medida en megabytes y gigabytes de memoria) y el tiempo de acceso.

Hardening The process of heating a metal to a predetermined temperature, allowing the part to soak until thoroughly heated, and cooling it rapidly in a cooling material.
Endurecimiento El proceso de calentar el metal a una temperatura predeterminada, permitiéndole que absorba el calor hasta estar calentado completamente, y luego enfriándolo rápidamente en un material de enfriamiento.

Hardness Test Techniques used to measure the degree of hardness of heat-treated materials.
Prueba de Dureza Técnicas usadas para medir el grado de dureza de materiales tratados con calor.

Hardware The tools available to users of CAD for input, processing, and output.
Equipo Físico Las herramientas disponibles a los usuarios de CAD para entrada, procesamiento y salida.

Harmonic Motion A type of motion that is very smooth starting and stopping, but the speed is not uniform. It is good for fast speed.
Movimiento Harmónico Un tipo de movimiento que ès muy suave al comenzar y al detenerse, pero la velocidad no es uniforme. Es bueno para una velocidad rápida.

Heading See *Bearing*.
Rumbo Vea *Azimut*.

Heat Treatment A series of processes used to alter or modify the existing properties in a metal to obtain a specific condition required for a workpiece. Also, to change the properties of metals by heating and then cooling.
Tratamiento de Calor Una serie de procesos usados para alterar o modificar las propiedades existentes en un metal para obtener una condición especifica requerida para una pieza de trabajo. También, para cambiar las propiedades de los metales calentándolos y luego enfriándolos.

Heating/Ventilating/Air-Conditioning Plan This plan shows the ductwork for the house's heating and cooling system superimposed on the floor plan without dimensions.
Plano de Calefacción/Ventilación/Aire Acondicionado Este plano muestra los conductos para el sistema de calefacción y de enfriamiento superpuestos sobre el plano de distribución sin dimensiones.

Helical Gear Operates on parallel shafts and transmits rotary motion in a manner identical to spur gears. The teeth have an involute shape but are not parallel to their rotational axis.
Engranaje Helicoidal Opera en ejes paralelos y transmite el movimiento rotativo en una manera idéntica a los engranajes de dientes rectos. Los dientes tienen una forma intricada pero no son paralelos a su eje de rotación.

Helical Spring Usually cyclindrical or conical in shape, there are three types: compression, extension, and torsion springs.
Resorte Helicoidal Generalmente de forma cilíndrica o cónica, hay tres tipos: resortes de compresión, de extensión y de torsión.

Helix A form of spiral used in screw threads, worm gears, and spiral stairways, among other things.
Hélice Una forma de espiral que se usa en las roscas de tornillos, o engranaje de tornillo y las escaleras espirales, entre otras cosas.

Hemisphere Hemispheres occur when a sphere is cut into two equal parts.
Hemisferio Los hemisferios ocurren cuando una esfera se corta en dos partes iguales.

Herringbone Gear A type of gear in which left-hand and right-hand teeth are combined.
Engranaje Doble Helicoidal Un tipo de engranaje en el cual se combinan los dientes de vuelta derecha y de vuelta izquierda.

Hexagon A polygon having six angles and six sides.
Hexágono Un polígono que tiene seis ángulos y seis lados.

Hidden Lines Lines not used in isometric drawings unless needed to show an important feature that otherwise would not be seen. Also feature outlines (for example, intersections of plane surfaces, real but invisible); used in each viewing plane where appropriate.
Líneas Escondidas Líneas que no se usan en los dibujos isométricos a menos que sea necesario para mostrar rasgos importantes que no se verían de otra manera. También los bordes de rasgos (por ejemplo, las intersecciones de planos, reales pero invisibles); usados en cada plano de vista dónde sea apropiado.

High-Performance Alloys A group of metals that have high strength and/or high corrosion resistance over a broad range of temperatures.
Aleación de Alto Rendimiento Un grupo de metales que tienen alta resistencia y/o alta resistencia a la corrosión sobre un rango de temperaturas.

Holography This process produces images that simulate the effect of seeing the three-dimensionality of an object from multiple viewpoints.
Holografía Este proceso produce imágenes que simulan el efecto de ver la tridimensionalidad de un objeto desde múltiples puntos de vista.

Hone A method of finishing a hole or other surface to a precise tolerance by using a spring-loaded abrasive block and rotary motion.
Afinar Un método de terminar un agujero u otra superficie a una tolerancia precisa usando un bloque accionado por resorte y un movimiento giratorio.

Horizontal Parallel to the horizon.
Horizontal Paralelo al horizonte.

Horizontal Boring Mills These machines perform a wide variety of different machining tasks normally associated with a milling machine but on a much larger scale.
Fresadoras de Taladrado Horizontal Estas máquinas llevan a cabo una variedad de diferentes tareas de labrado normalmente asociadas con una fresadora pero a una escala mucho más grande.

Human Factors Published tabulations of body dimensions of average males, females, and children.

Factores Humanos Tablas publicadas de dimensiones corporales de los varones, mujeres y niños promedios.

Hydrodynamic Machining (HDM) A nontraditional machining process that removes material using a high-velocity, high-pressure stream of liquid solution. It is used primarily for slitting and cutting nonmetallic materials.
Labrado Hidrodinámico Un proceso de labra no tradicional que remueve material usando un chorro de una solución líquida de alta velocidad y alta presión. Se usa principalmente para cortar en tiras y para cortar materiales no metálicos.

Icon A standardized graphical image designed to represent and communicate a computer application operation or function.
Icono Una imagen gráfica estandarizada diseñada para representar y comunicar la operación o función de una aplicación de computadora.

Inclined A line or plane at an angle to a horizontal line or plane.
Inclinado Una línea o plano a cualquier ángulo de una línea o plano horizontal.

Increment The length of a weld.
Incremento El largo de una soldadura.

Incremental System A system of numerically controlled machining that always refers to the preceding point when making the next movement; also known as continuous path or contouring method of NC machining.
Sistema Incremental Un sistema de labrado controlado numéricamente que siempre se refiere al punto anterior al hacer el próximo movimiento; también se conoce como el método de paso continuo o de contorno del labrado controlado numéricamente.

Indexing Jig Used primarily to machine parts that have machined details at intervals around the part.
Guía de Gradación Se usa principalmente para labrar partes que tienen detalles labrados a intervalos alrededor de una pieza.

Input The transfer of information into a computer or machine control unit (see *Output*).
Entrada La transferencia de información a una computadora o unidad de control de labrado (ver *Salida*).

Inside Diameter The inside diameter of a spring.
Diámetro Interior El diámetro interior de un resorte.

Intelligent Robot A robot that can make decisions based on data received from sensing devices.
Robot Inteligente Un robot que puede tomar decisiones basadas en los datos que recibe de los aparatos de sensores.

Interactive The capability of a computer application to permit an operator to change variables or test a design while the application is running. Virtual reality is an extreme example of an operator being able to interact with a computer application.
Interactiva La capacidad de una aplicación de computadora para permitirle a un operador cambiar variables o probar un diseño mientras la aplicación está ejecutándose. Realidad virtual es un ejemplo extremo de un operador capaz de interactuar con una aplicación de computadora.

Interchangeable Refers to a part made to limit dimensions so that it will fit any mating part similarly manufactured.
Intercambiable Referente a una pieza que fue hecha a dimensiones límites de manera que pueda encajar en cualquier pieza de acoplamiento manufacturada de manera similar.

Interface The means of interacting with a computer. Graphical user interfaces are becoming more prevalent and are designed to simplify applications by using graphical icons to guide the interaction with computer applications.
Interfaz El medio de interactuar con una computadora. Los interfaces de uso gráfico están convirtiéndose más comunes y son diseñados para simplificar las aplicaciones usando iconos para guiar la interacción con las aplicaciones de computadora.

Interference Fit This represents the smallest amount of interference.
Encaje de Interferencia Esto representa la cantidad más pequeña de interferencia.

Intermediate A translucent reproduction made on vellum, cloth, or film from an original drawing to serve in place of the original for making other prints.
Intermedio Una reproducción transparente hecha en vitela, tela o película desde un dibujo original para funcionar en lugar del original para hacer otras reproducciones.

Intermittent Weld A series of short welds. When this type of weld is needed, an extra dimension is added to the welding symbol.
Soldadura Intermitente Una serie de soldaduras cortas. Cuando se necesita este tipo de soldadura, se añade una dimensión al símbolo de soldadura.

Internal Clients These clients can be instructors in classrooms and supervisory persons in industry.
Clientes Internos Estos clientes pueden ser instructores en los salones de clases y supervisores en la industria.

Internal Rings For axial assembly, these are compressed for insertion into a bore or housing.
Anillos Internos Para un ensamblaje axial, éstos se comprimen para insertarlos en un agujero o un cárter.

Internal Thread Threads located on the inside of a part, such as those on a nut.
Rosca Interna Roscas ubicadas en el interior de una pieza, tales como las de una tuerca.

Invention Agreement This form is signed by the drafter. It gives the company the right to any new invention designed while working with the company. It also (1) specifies that the employee will not reveal any of the company's discoveries or projects, and (2) is generally binding on the employee from six months to two years after leaving the company.
Acuerdo de Invención Este formulario lo firma el delineante y le provee a la compañía el derecho de cualquier invención nueva diseñada por éste mientras trabaja con la compañía. También (1) especifica que el empleado no revelará ninguno de los descubrimientos o proyectos de la compañía, y (2) es generalmente obligatorio en el empleado desde seis meses hasta dos años después de irse de la compañía.

Investment Casting A casting process in which a wax pattern is placed in a sand mold and the mold is fired to melt out the wax pattern, leaving a cavity into which molten metal is then poured.
Fundición en Molde de Cera Un proceso de fundición en el cual se coloca un patrón de cera dentro de un molde de arena y se calienta el molde para derretir la cera, dejando una cavidad dentro de la cual se vierte el metal derretido.

Involute Curve May be considered the path traced by the end of a string as it is unwound from a circle called a base circle. Also a spiral curve generated by a point on a chord as it unwinds from a circle or a polygon.
Curva Intricada Puede considerarse como el camino trazado por el extremo de un hilo mientras se desenrolla de un círculo llamado un círculo base. También es una curva espiral generada por un punto en una cuerda a medida que se desenrolla de un círculo o un polígono.

Irregular Curve The name for the type of curve that is drawn using a French curve.
Curva Irregular El nombre dado al tipo de curva que se dibuja usando una curva francesa.

Isometric Assembly These drawings appear in two popular formats: exploded and assembled (see *Exploded Isometric Drawing* and *Assembled Isometric Assembly Drawings*).
Ensamblaje Isométrico Estos dibujos aparecen en dos formatos populares: despiezado y ensamblado (ver *Dibujo Isométrico Despiezado* y *Dibujo Isométrico Ensamblado*).

Isometric Drawing The most used of the three common pictorials. They are easier to draw than perspective drawings, and they illustrate objects almost as well as perspective drawings. The drawings are so positioned that all three axes make equal angles with the picture plane, and measurements on all three axes are made to the same scale.
Dibujo Isométrico El más usado de los tres tipos de dibujos pictóricos. Son más fáciles de dibujar que los dibujos de perspectiva e ilustran los objetos casi tan bien como los dibujos de perspectivas. Los dibujos se ubican de manera que los tres ejes forman ángulos iguales con el plano de dibujo, y las medidas en los tres ejes se hacen a la misma escala.

Isometric Projection Causes dimensions along the three principal edges to be foreshortened to approximately 82% of their true length.
Proyección Isométrica Causa que las dimensiones a lo largo de los tres ejes principales se acorten a aproximadamente un 82% de su largo verdadero.

Isometric Sketching Sketching in which the length and width lines recede at 30° to the horizontal and the height lines are vertical.
Croquis Isométrico Croquis en el cual las líneas de largo y ancho de las líneas retroceden a un ángulo de 30° de la horizontal y las líneas de alto son verticales.

Isopleth The lines used to locate values in a nomogram.
Isolínea Las líneas que se usan para localizar los valores en un nomograma.

Iteration A procedure in which repetition of a sequence of operations yields results successively closer to a desired result.
Iteración Un procedimiento en el cual la repetición de una secuencia de operaciones provee resultados sucesivamente más cercanos al resultado deseado.

Jig A workholding tool that guides the cutting tool through a hardened drill bushing during the cutting cycle.
Guía Una herramienta que agarra piezas y guía la herramienta cortante a través de los cojinetes de taladro endurecidos durante el ciclo de corte.

Journal Portion of a rotating shaft supported by a bearing.
Muñequilla Porción de un eje que rota que está apoyada por un cojinete.

Just-in-Time Manufacturing (JIT) An approach to manufacturing that seeks to completely eliminate waste.
Manufactura Justo a Tiempo Un método de manufactura que busca eliminar el desperdicio por completo.

Kerf Groove or cut made by a saw.
Corte Ranura o corte hecho por una sierra.

Key A small piece of metal sunk partly into both shaft and hub to prevent rotation of mating parts. It is a demountable part that provides a positive means of transferring torque between a shaft and a hub.

Lave Un pedazo pequeño de metal parcialmente empotrado y en el eje y en el cubo para prevenir la rotación de partes que encajan. Es una parte removible que provee un medio positivo para transferir la fuerza de torsión entre un eje y un cubo.

Keyboard The part of a CAD computer used for entering commands, text, annotation, and dimensions.
Teclado La parte de una computadora de CAD que se usa para ingresar comandos, texto, anotaciones y dimensiones.

Keying The process used for entering text on drawings, certain system commands, dimensions not entered automatically, and for logging on to the system.
Tecleo El proceso usado para ingresar texto en los dibujos, ciertos comandos, dimensiones que no se ingresan automáticamente y para entrar al sistema.

Keyseat An auxiliary-located rectangular groove machined into the shaft and/or hub to receive the key.
Asiento de Llave Una ranura auxiliar rectangular que se labra en un eje y/o cubo para recibir la llave.

Keyslot The slot machined in a shaft for Woodruff-type keys.
Ranura de Llave Una ranura labrada en un eje para aceptar las llaves tipo Woodruff.

Keyway A slot in a hub or portion surrounding a shaft to receive a key.
Muesca de Posicionamiento Una ranura en un cubo o la porción que rodea a un eje para recibir una llave.

Kilo Prefix meaning 1,000 units, as in kilometers (1,000 meters).
Kilo Prefijo que significa 1,000 unidades, como en kilómetros (1,000 metros).

Knurl A diamond-shaped or parallel pattern cut into cylindrical surfaces to improve gripping, the bonding between parts for permanent press fits and decoration.
Estrías Un patrón en forma de diamante o paralelo que se corta en las superficies cilíndricas para mejorar su agarre, la adherencia de partes para encajes de presión permanentes y para decoración.

Laser Beam Machining (LBM) A process that uses lasers for performing operations that are traditionally performed with cutting tools.
Labrado con Rayo Láser Un proceso que usa láseres para llevar a cabo las operaciones que tradicionalmente se llevan a cabo con herramientas cortantes.

Lathe One of the most commonly used and versatile machine tools in the shop. It can perform such operations as straight and taper turning, facing, straight and taper boring, drilling, reaming, tapping, threading, and knurling.
Torno Una de las herramientas de labrado más frecuentemente usadas y más versátiles en el taller mecánico. El mismo puede llevar a cabo tales operaciones como el tornado, la cara, el taladrar derecho y gradualmente estrechado, el perforar, el escariar, el roscar y el estriar.

Layout Lines drawn on material as guides for subsequent operations.
Trazado Líneas que se dibujan en un material como guías para las operaciones subsiguientes.

Layout Development Drawing A designer's freehand sketch redrawn to scale with instruments or a computer.
Dibujo de Desarrollo de Trazado Un croquis hecho a mano libre por un diseñador dibujado nuevamente a escala con instrumentos o con una computadora.

Lead (noun, pronounced led) A dark gray metal with the following characteristics: high density, low melting point, corrosion resistance, chemical stability, malleability, lubricity, and electrical properties.
Plomo Un metal grisáceo oscuro con las siguientes características: densidad alta, punto de fundición bajo, resistencia a la corrosión, estabilidad química, maleabilidad, lubricidad y propiedades eléctricas.

Lead Time The interval from the time the shop receives the drawing until production begins.
Tiempo de Acción El intervalo de tiempo desde que el taller recibe el dibujo hasta que comienza la producción.

Leader Line A thin line used to direct the information contained in notes or dimensions to the appropriate surface, feature, or point on a drawing.
Directriz Una línea que se usa para dirigir la información contenida en notas o dimensiones a la superficie, rasgo o punto apropiado en un dibujo.

Least Material Condition (LMC) A condition that exists when the least material is available for the features being dimensioned. It is the lower limit for an external feature and the upper limit for an internal feature.
Condición de Material Mínimo Una condición que existe cuando está disponible la cantidad mínima de material para los rasgos que se dimensionan. Es el límite inferior para un rasgo externo y el límite superior para un rasgo interno.

Letter of Transmittal A letter to a client, separate from but enclosed with a report, which states that the project has been completed, the report is enclosed, and that working with the client on future projects is anticipated.
Carta de Trámite Una carta a un cliente, aparte de pero que incluye un informe que afirma que el proyecto fue completado, que se incluye el informe, y que se anticipa trabajar con el cliente en proyectos futuros.

Lettering Machine A machine that outputs letters on a clear tape that is pressed onto the drawing surface.
Máquina de Letrado Una máquina que produce letras en una cinta transparente que se presiona sobre una superficie de dibujo.

Light Pen A handheld data-entry device used only with refresh displays. It consists of an optical lens and photocell, with associative circuitry mounted in a wand. Most light pens have a switch allowing the pen to be sensitive to light from the screen.
Pluma de Luz Un aparato de entrada de datos manual que se usa solamente con las pantallas refrescadas. Consiste de un lente óptico y una fotocelda, con el circuito asociado colocado en el mango. La mayoría de las plumas de luz tienen un interruptor que le permite a las plumas a ser sensibles a la luz de la pantalla.

Limit Dimensioning A tolerancing method that shows only the maximum and minimum dimensions that establish the limits.
Dimensionamiento de Límite Un método de tolerar que muestra sólo las dimensiones máximas y mínimas que establecen los límites.

Limits The maximum and minimum allowable sizes of a feature.
Límites Los tamaños máximos y mínimos permisibles para un rasgo.

Line Work A generic term given to all of the various techniques used in creating the graphic data on technical drawings.
Trabajo de Línea Un término genérico que se le da a todas las varias técnicas usadas en la creación de datos gráficos en los dibujos técnicos.

Liner Bushings Used in conjunction with renewable bushings; they provide a hardened, wear-resistant mount for renewable bushings.
Cojinetes de Revestimiento Se usan en conjunto con los cojinetes renovables; proveen una montura endurecida, resistente al desgaste para los cojinetes renovables.

Loaded Length The overall length of a spring with a special given or designed load applied to it.
Largo con Carga El largo completo de un resorte con una carga dada o de diseño aplicada sobre él.

Location Tolerance A tolerance that specifies the allowable variation from the perfect location.
Tolerancia de Localización Una tolerancia que especifica la variación permisible de una localización perfecta.

Log A record of activities completed and the time spent on each activity. It should take the who, where, what, when, and why style.
Registro Un registro de actividades completadas y el tiempo usado en cada actividad. Debería tener el estilo de quién, dónde, qué, cuándo y por qué.

Lowercase End Points Each line in space is identified by two of these.
Puntos de Extremos Minúsculos Cada línea en el espacio está identificada por dos de éstos.

Lowercase Letters Each point in space is called out by these.
Letras Minúsculas Cada punto en el espacio se llama por una de éstas.

Lug An irregular projection of metal, but not round as in the case of a boss; usually with a hole in it for a bolt or screw.
Saliente Una proyección de metal irregular, pero no redonda como en el caso de un saliente cilíndrico; generalmente con un agujero en él para aceptar un tornillo o un perno.

Machine Screw Used for screwing into thin materials. Most are threaded within a thread or two to the head. They sometimes incorporate a hex-head nut to fasten parts together.
Tornillo de Máquina Se usa para atornillar materiales finos. La mayoría tiene una rosca dentro de una rosca hasta la cabeza. A veces incorporan una tuerca hexagonal para unir las piezas.

Machining The process of removing metal with machine tools and cutters to achieve a desired form or feature.
Labrar El proceso de remover material con herramientas de labrado y cortantes para lograr una forma o un rasgo deseado.

Magnaflux A nondestructive inspection technique that uses a magnetic field and magnetic particles to locate internal flaws in ferrous metal parts.
Magnaflux Una técnica de inspección no destructiva que usa campos magnéticos y partículas magnéticas para localizar los defectos internos en las piezas de metales ferrosos.

Magnesium A soft, silvery white metal that is extremely light and machinable, but lacks the strength needed for structural uses. To increase its strength, it can be alloyed with various metals.
Magnesio Un metal blando, plateado blancuzco que es extremadamente liviano y fácil de labrar, pero carece de la fortaleza necesaria para usos estructurales. Para aumentar su fortaleza, se puede alear con varios metales.

Main Storage The general-purpose storage of a computer; usually main storage can be accessed directly by the operating registers.
Almacenamiento Principal El almacenamiento de aplicación general en una computadora; generalmente el almacenamiento principal lo pueden acceder directamente los registros operacionales.

Major Diameter The largest diameter of a screw thread, both external and internal.
Diámetro Mayor El diámetro más grande de una rosca de tornillo, tanto externo como interno.

Malleable Casting A casting that has been made less brittle and tougher by annealing.
Fundición Maleable Una fundición que se hizo menos quebradiza y fuerte por medio del recocido.

Manual of Steel Construction This manual contains the dimensions and other design and drafting-related information for structural steel shapes.
Manual de Construcción en Acero Este manual contiene las dimensiones y otra información relacionadas al dibujo industrial de las formas estructurales en acero.

Manufacturing The enterprise through which raw materials are converted into finished products.
Manufactura La empresa a través de la cual los materiales en bruto se convierten en productos acabados.

Manufacturing Resource Planning (MRPII) A concept that allows companies to systematically plan for the resources needed in manufacturing (i.e., materials, capacity of production systems, personnel, time, etc.).
Planificación de Recursos de Manufactura Un concepto que le permite a las compañías a planificar sistemáticamente para los recursos necesarios en la manufactura (esto es, materiales, capacidad de los sistemas de producción, personal, tiempo, etc.).

Maraging Steel A special class of high-strength steels in which nickel is the primary alloy.
Acero Marginizado Una clase especial de aceros de alta resistencia en los cuales el níquel es la aleación principal.

Mass Production Company An organization that produces large quantities of a product.
Compañía de Producción en Masa Una organización que produce grandes cantidades de un producto.

Mass Properties Analysis A process involving performing analysis computations concerning mass properties such as weight, volume, surface area, moment of inertia, and center of gravity.
Análisis de Propiedades de Masa Un proceso que consiste de hacer cálculos analíticos acerca de las propiedades de masa tales como peso, volumen, área de superficie, momento de inercia y centro de gravedad.

Material Handling The movement and handling of materials, either manually or through the use of powered equipment.
Manejo de Materiales El movimiento y manejo de materiales, ya sea manualmente o mediante el uso de equipo de potencia.

Maximum Material Condition (MMC) When a feature contains the maximum amount of material; that is, minimum hole diameter and maximum shaft diameter. It is the upper limit for an external feature and the lower limit for an internal feature.
Condición de Material Máximo Cuando un rasgo contiene la cantidad máxima de material, esto es, el diámetro de agujero mínimo y diámetro de eje máximo. Es el límite superior para un rasgo externo y el límite inferior para un rasgo interno.

Mean Diameter The theoretical diameter of the spring measured to the center of the wire diameter.
Diámetro Promedio El diámetro teórico de un resorte medido hasta el centro del diámetro del alambre.

Mechanical Method A method of approximating areas by using a planimeter.
Método Mecnico Un método de aproximar las áreas usando un planímetro.

Menu A list of options that are displayed either on the CRT or on a plastic or paper overlay.
Menú Una lista de opciones que se despliegan en el CRT o en una cubierta de plástico o papel.

Metes and Bounds A system used to identify the perimeters of any property. A metes and bounds land survey begins at a selected known point of origin called the point-of-beginning or POB and then describes property boundaries in relation to this by using distance measurements, compass bearings, and boundaries such as streets, fences, and rivers.
Medidas y Límites Un sistema usado para identificar los perímetros de cualquier propiedad. Cualquier estudio de planimetría de medidas y límites comienza con un punto conocido de origen llamado el punto de comienzo y luego describe las relaciones de límites en relación a éste usando medidas de distancia, orientaciones de compás y demarcaciones tales como calles, cercas y ríos.

Metric Dimensioning One of three dimensioning systems used on technical drawings.
Dimensionamiento Métrico Uno de tres sistemas de dimensionamiento que se usa en los dibujos técnicos.

Microcomputer A computer that is constructed using a microprocessor as a basic element of the CPU; all electronic components are arranged on one printed circuit board.
Microcomputadora Una computadora que se construyó usando un microprocesador como un elemento básico del CPU; todos los componentes electrónicos están puestos sobre una tarjeta de circuitos impresos.

Microprocessor The central processing unit of a microcomputer. The microprocessor is contained on a single integrated circuit chip.

Microprocesador La unidad de procesamiento central de una microcomputadora. El microprocesador está en un solo chip de circuito integrado.

Mill To remove material by means of a rotating cutter on a milling machine.
Fresar Remover material por medio de una cuchilla que rota en una fresadora.

Milli Prefix meaning one one-thousandth unit, as in millimeters (.001 meter).
Mili Prefijo que significa una milésima de unidad, como en milímetros (.001 metro).

Milling Machine Used to machine workpieces by feeding the part into a rotating cutter.
Fresadora Se usa para labrar las piezas de trabajo insertando la pieza en una cortadora giratoria.

Minor Diameter The smallest diameter of a screw thread, both external and internal.
Diámetro Menor El diámetro más pequeño de una rosca de un tornillo, tanto externa como interna.

Miter Gear Exactly the same as a bevel gear except that both mating gears have the same number of teeth. The shafts are at 90° to each other.
Engranaje de Inglete Exactamente igual al engranaje de bisel, excepto que los engranajes que se conectan tienen el mismo número de dientes. Los ejes están a 90° el uno del otro.

Modified Uniform Velocity It smoothes out the roughness slightly by adding a radius to the ends of the high and low points.
Velocidad Uniforme Modificada Suaviza la aspereza un poco añadiéndole un radio a los extremos de los puntos altos y bajos.

Modifier The application of MMC or RFS to alter the normally implied interpretation of a tolerance specification. There are symbols that can be attached to the standard geometric building block to alter their application or interpretation.
Modificador Una aplicación del MMC o RFS para alterar la interpretación normal implicada de una especificación de tolerancia. Los símbolos que se pueden adjuntar al bloque de construcción para alterar su aplicación o interpretación.

Mold The mass of sand or other material that forms the cavity into which molten metal is poured.
Molde La masa de arena u otro material que forma la cavidad en la cual se vierte el metal derretido.

Mouse A device that typically rolls on the desktop and directs the cursor on the display screen.
Ratón Un aparato que típicamente rueda sobre el escritorio y dirige el cursor en la pantalla del monitor.

Multiple Reference Lines Used when there will be more than one operation on a particular joint. The first operation goes on the first line, the second on the second, and so on.
Líneas de Referencias Múltiples Se usan donde habrá más de una operación un una unión particular. La primera operación se indica en la primera línea, la segunda en la segunda y así sucesivamente.

Multiple Thread A type of screw threading in which two or more continuous ridges follow side-by-side. Used when speed or travel distance is an important design factor.
Rosca Múltiple Un tipo de rosca de tornillo en que dos o más resaltos continuos siguen uno al lado del otro. Usado cuando velocidad o distancia de viaje es un factor importante del diseño.

Multiweld A weld where more than one type of weld may be applied to a single joint—for example, a groove V weld on one side, and a backing weld on the other side. The weld is usually for strength or appearance.
Soldadura Múltiple Una soldadura en la cual más de un tipo de soldadura se puede aplicar a una sola unión—por ejemplo una soldadura de ranura V en un lado y una soldadura de espalda en el otro lado. Esta soldadura tiene usualmente el propósito de fuerza o apariencia.

Neck To cut a groove called a neck around a cylindrical piece.
Collarín Cortar una ranura llamada cuello alrededor una pieza cilíndrica.

Nodes Points of an object that contain specific information about the characteristics at that particular point.
Nodos Puntos en un objeto que contienen información específica acerca de las características de ese punto particular.

Nominal Dimension A dimension that represents a general classification size given to a part or product.
Dimensión Nominal Una dimensión que representa un tamaño de clasificación general que se le da a una pieza o producto.

Nonferrous A description of metals not derived from an iron base or an iron alloy base; nonferrous metals include aluminum, magnesium, and copper, among others.
No Ferroso Una descripción de los metales que no se derivan de una base de hierro o una base de una aleación de hierro; los metales no ferrosos incluyen aluminio, magnesio y cobre, entre otros.

Nonisometric Line A line not parallel or perpendicular to any of the three principal edges in an isometric drawing.
Línea No Isométrica Una línea que no es paralela o perpendicular a ninguno de los tres bordes principales de un dibujo isométrico.

Nonroutine Designs Problems that are assigned to experienced engineers, designers, technologists, and drafters.
Dibujos No de Rutina Problemas que se asignan a los ingenieros, diseñadores, tecnólogos y delineantes con experiencia.

Nontraditional Machining Advanced machining processes that have been developed in response to the demands of modern manufacturing for more effective, more efficient ways to machine the many new materials that have been, and are still being, developed.
Labrado No Tradicional Procesos de labrado avanzados que se han desarrollado en respuesta a las demandas de la manufacturación moderna para maneras más efectivas y eficientes para labrar los muchos materiales que se han desarrollado o que aún se están desarrollando.

Normalize To heat steel above its critical temperature, and then cool it in air.
Normalizar Calentar el acero más allá de su temperatura crítica, y luego dejarlo enfriar en aire.

Normalizing The process used to remove the effects of machining or cold-working metals. The process in which ferrous alloys are heated and then cooled in still air to room temperatures to restore the uniform grain structure free of strains caused by the cold working or welding.
Normalizado Un proceso usado para remover los efectos del labrado o del trabajado en frío en los metales. El proceso en el cual las aleaciones férreas se calientan y luego se enfrían en aire quieto a temperatura ambiente para restaurar la estructura granular uniforme libre de la tensión causada por el trabajo en frío o de soldadura.

North/South Deviation A method of marking a drawing in which north is at the top of the page and south is at the bottom.
Desviación Norte/Sur Un método de marcar un dibujo en el cual el norte está en la parte superior de la página y el sur en la parte inferior de la página.

Notations Labeling that keeps track of all views and points in space and provides brief explanations/information on a drawing.
Notación Rótulos que llevan cuenta de todas las vistas y puntos en el espacio y proveen explicaciones breves o información en un dibujo.

Numerical Control A system of controlling a machine or tool by means of numeric codes that direct commands to control devices attached or built into the machine or tool.
Control Numérico Un sistema para controlar una máquina o herramienta por medio de códigos numéricos que dirigen los comandos que controlan aparatos que están conectados a o que están dentro de la máquina o herramienta.

Numerically Controlled Machine Tools Machine tools that are controlled by means of numeric codes that direct commands to control devices attached or built into the machine or tool.
Herramientas de Labrado Controladas Numéricamente Herramientas de labrado que se controlan por medio de códigos numéricos que dirigen los comandos que controlan aparatos que están conectados a o que están dentro de la máquina o herramienta.

Oblique Drawing A style of pictorial drawing in which one surface of the object, usually the front view, is drawn exactly as it would appear in a multiview drawing. One of its principal faces is parallel to the plane of projection and is projected in its true size and shape; the third set of edges is oblique to the plane of projection at some convenient angle.
Dibujo Oblicuo Un estilo de dibujo pictórico en el cual una superficie del objeto, generalmente la vista frontal, se dibuja exactamente como aparecería en un dibujo de vistas múltiples. Una de las caras principales está paralela al plano proyección y se proyecta en tamaño y forma real; el tercer grupo de bordes está oblicuo al plano de proyección en un ángulo conveniente.

Oblique Projection It shows the full size of one view.
Proyección Oblicua Muestra el tamaño completo de una vista.

Oblique Sketching A type of sketching involving a combination of a flat, orthographic front with depth lines receding at a selected angle (usually 45°).
Croquis Oblicuo Un tipo de croquis que consiste de una combinación de un frente plano y ortográfico con líneas de profundidad que van disminuyendo en un ángulo seleccionado (generalmente 45°).

Oblique Surfaces Surfaces that are not perpendicular to any of the three principal projection planes.
Superficies Oblicuas Superficies que no son perpendiculares a ninguno de los tres planos de proyección.

Obtuse Angle An angle larger than 90°.
Ángulo Obtuso Un ángulo mayor de 90°.

Obtuse Angle Triangle A triangle having an obtuse angle greater than 90° with no equal sides.
Triángulo de Ángulo Obtuso Un triángulo que tiene un ángulo obtuso mayor de 90° sin lados iguales.

Octagon A polygon having eight angles and eight sides.
Octágono Un polígono que tiene ocho ángulos y ocho lados.

Offset Measurements Used to locate one feature in relationship to another.

Medida de Compensación Se usa para localizar un rasgo en relación a otro.

Offset Section This section is accomplished by bending or offsetting the cutting-plane line. It is similar to a full section except that the cutting-plane line is not straight.
Sección de Compensación Esta sección se logra doblando o desplazando el plano cortante. Es similar a una sección completa, excepto que la línea del plano cortante no es recta.

Ogee Curve Used to join two parallel lines. It forms a gentle curve that reverses itself in a neat symmetrical geometric form.
Curva de "S" Se usa para unir dos líneas paralelas. Forma una curva suave que vira en si misma en una forma geométrica muy simétrica.

Open Jigs Jigs that cover only one side of a part and are used for relatively simple operations.
Guías Abiertos Guías que cubren sólo un lado de una pieza y se usan para operaciones relativamente simples.

Open-Carriage Typewriter Any brand of typewriter that has been especially designed to hold larger-than-normal media.
Máquina de Escribir de Transporte Abierto Cualquier marca de máquina de escribir que se ha diseñado para sostener hojas de papel más grandes de lo normal.

Open-Divided Scale It has its first unit of measurement subdivided, but the remaining units are open or free from subdivision.
Escala Abierta y Dividida Tiene la primera unidad de medida subdividida, pero las unidades restantes están abiertas o libres de subdivisiones.

Opitz System One of the most widely used classification and coding systems. It uses characters in 13 places to code the attributes of parts, and hence, to classify them.
Sistema Opitz Uno de los sistemas de clasificación y codificación más usado. Usa caracteres en 13 lugares para codificar los atributos de una pieza y por ende, clasificarlos.

Optimization The process of improving a process or system to its maximum functionality.
Optimización El proceso de mejorar un proceso o sistema a su funcionalidad máxima.

Ordinate The Y coordinate of a point (i.e., its vertical distance from the X axis measured parallel to the Y axis, or the vertical axis of a graph or chart).
Ordenada La coordenada Y de un punto (esto es, la distancia vertical desde el eje de X, medido paralelo al eje de Y o eje vertical de la gráfica).

Orthographic Projection A projection on a picture plane formed by perpendicular projectors from the object to the picture plane; third-angle projection is used in the United States, while first-angle projection is used in most countries outside the United States.
Proyección Ortográfica Una proyección en un plano de dibujo que está formado por proyecciones perpendiculares desde el objeto al plano de dibujo; en los Estados Unidos se usa la proyección de tercer ángulo, mientras que la proyección de primer ángulo se usa en la mayoría de los países fuera de Estados Unidos.

Orthographic Sketching This type of sketching deals with flat, graphic facsimiles of a subject showing no depth. The views selected depend on the nature of the subject and the judgment of the sketcher.
Croquis Ortográfico Este tipo de croquis trata con copias planas y gráficas de un sujeto que no muestra profundidad. Las vistas que se seleccionan dependen de la naturaleza del sujeto y el juicio de la persona que hace el croquis.

Output Data that have been processed from an internal storage to an external storage; opposite of input.
Salida Datos que se han procesado de un almacenamiento interno a un almacenamiento externo; lo opuesto a entrada.

Outside Diameter The measurement over the extreme outer edge of teeth. It is equal to the pitch diameter, plus two times the addendum.
Diámetro Externo La medida alrededor del extremo externo de los dientes. Es igual al diámetro de paso más dos veces la altura de cabeza.

Overlay Drafting A complete drafting process that uses advanced reproduction techniques to reduce the amount of time spent in preparing drafting documentation.
Dibujo Industrial por Superposición Un proceso de dibujo técnico completo que usa técnicas de reproducción avanzadas para reducir la cantidad de tiempo que se dedica en preparar la documentación de dibujo.

Parallel Having the same direction, such as two lines which, if extended indefinitely, would never meet.
Paralelo Que tiene la misma dirección, tales como dos líneas que, si se extienden infinitamente, nunca se encontrarían.

Parallel Alignment Chart The procedure for preparing a set of three parallel scales for a three-variable equation. The derivation aims at obtaining relationships from two of the scales so that the third can be located and graduated.
Gráfica de Alineación Paralela El procedimiento para preparar tres escalas paralelas para una ecuación de tres variables. La derivación aspira a obtener relaciones de

dos de las escalas de manera que se pueda localizar y graduar la tercera.

Parallel Line Development Used for objects having parallel fold lines.
Desarrollo de Líneas Paralelas Se usa para objetos que tienen líneas de doblez paralelas.

Parallel Projection Is subdivided into the following three categories: orthographic, oblique, and axonometric projections.
Proyección Paralela Se subdivide en las siguientes tres categorías: proyección ortográfica, oblicua y axonométrica.

Parallel Station Lines A baseline that must always be 90° from the fold lines. Used for objects having parallel fold lines.
Líneas de Estación Paralelas Una línea base que siempre tiene que estar a 90° de las líneas de doblez. Se usa para los objetos que tienen líneas de doblez paralelas.

Parallelism A feature control that specifies that all points on a given surface, axis, line, or center plane must be equidistant from a datum.
Paralelismo Un control de rasgo que especifica que todos los puntos de una superficie dada, eje, línea o plano central, deben estar equidistantes de una referencia.

Parallelogram A quadrilateral whose opposite sides are parallel.
Paralelogramo Un cuadrilátero cuyos lados opuestos son paralelos.

Parallelogram Law Two vectors, not parallel, drawn to scale, having the same units, and acting at the same point, can be added or subtracted.
Ley del Paralelogramo Dos vectores, que no son paralelos, que están dibujados a escala, tienen las mismas unidades, y actúan sobre un mismo punto, pueden sumarse o restarse.

Parametric Design This allows drafters and designers to change dimensions in three-dimensional computer models and have all affected dimensions change accordingly.
Diseño Paramétrico Éste le permite al delineante y a los diseñadores cambiar las dimensiones de los modelos tridimensionales de computadora y que como consecuencia se cambien todas las dimensiones afectadas.

Part Individual component of an assembly.
Pieza Un componente individual de un ensamblaje.

Part Family A group of parts similar in design and/or the manufacturing process used to produce them.
Familia de Piezas Un grupo de piezas de diseños y/o procesos de manufactura similares.

Partial Auxiliary View A partial view makes it possible to eliminate one or more of the regular views which, in turn, saves drafting time and cost.
Vista Parcial Auxiliar Una vista parcial hace posible el eliminar una o más vistas regulares, lo que a su vez ahorra tiempo y gastos del proceso de dibujo industrial.

Parting Operation used to finish the edges of a part.
Partir Una operación que se usa para terminar los bordes de una pieza.

Parting Line This is the plane of division between the cope and drag.
Línea Divisoria Es el plano de división entre la caja superior y la caja inferior del molde.

Parts This is a listing, identified first by number, part name, and quantity needed. It also contains a cross reference to the corresponding balloon number.
Piezas Este es un listado de piezas, identificadas primero por número, nombre de la pieza y cantidad necesaria. También tiene una referencia al número de globo correspondiente.

Parts List A bill of material that itemizes the parts needed to assemble one complete full assembly of a product.
Lista de Piezas Una factura de materiales que desglosa las piezas necesarias para ensamblar un producto completo.

Patent Drawings A drawing that must accompany a patent application for a new idea or invention. Its purpose is to illustrate and then explain the invention's function. It must be mechanically correct and must adhere to strict patent drawing regulations.
Dibujos de Patentes Un dibujo que debe acompañar la aplicación para patente de una nueva idea o invención. Su propósito es ilustrar y explicar la función de la invención. Debe ser mecánicamente correcta y debe cumplir con los reglamentos estrictos para los dibujos de patentes.

Pattern A model, usually of wood, used in forming a mold for casting. In sand casting, this is a model of a part.
Patrón Un modelo, generalmente de madera, que se usa para formar el molde para la fundición. En la fundición en moldes de arena, éste es el modelo para una pieza.

Peen To hammer into shape with a ball peen hammer.
Martillar Formar mediante martillazos de un martillo de bola.

Pentagon A polygon having five angles and five sides.
Pentágono Un polígono que tiene cinco ángulos y cinco lados.

Perforating A punching operation performed on sheets to produce either a uniform hole pattern or a decorative form in the sheet.

Perforar Una operación de perforado que se hace en hojas para producir un agujero de patrón uniforme o una forma decorativa en una hoja.

Permanent Fasteners Used when parts will not be disassembled.
Sujetadores Permanentes Se usan cuando las partes no serán desensambladas.

Perpendicular A type of motion of the follower specific to the radial arm cam design. Also, lines or planes at a right angle to a given line or plane.
Perpendicular Un tipo de movimiento del seguidor que es específico al diseño de levas de brazo radial. También, líneas o planos que están a ángulos rectos de una línea o un plano dado.

Perpendicularity A feature control that specifies that all elements of a surface, axis, center plane, or line form a 90° angle with a datum.
Perpendicularidad Un control de rasgo que especifica que todos los elementos de una superficie, eje, plano central o línea forman un ángulo de 90° con una referencia.

Perspective Drawing A three-dimensional drawing of an object or scene that shows visible lines almost as a person's eyes would perceive them from one particular viewing location. Also a pictorial drawing in which receding lines converge at vanishing points on the horizon; the most natural of all pictorial drawings.
Dibujo de Perspectiva Un dibujo tridimensional de un objeto o escena que muestra las líneas visibles casi como los ojos de una persona las percibiría desde un punto de vista particular. También es un dibujo pictórico en el cual todas las líneas que se alejan convergen en puntos en el horizonte; el más natural de todos los dibujos pictóricos.

Perspective Projection A distortion phenomenon that occurs because the visual rays used to create the image in the viewer's eye are not parallel.
Proyección de Perspectiva Un fenómeno de distorsión que ocurre debido a que los rayos visuales que se usan para generar la imagen no son paralelos.

Perspective Sketching Involves creating a graphic facsimile of the subject in one- , two-, or three-point perspective using only a pencil.
Croquis de Perspectiva Consiste en crear una copia gráfica del sujeto en perspectiva de uno, dos y tres puntos, usando sólo un lápiz.

Phantom Line A type of line that resembles a center line except that it has two dashes.
Línea Fantasma Un tipo de línea que se parece a la línea de centro excepto que tiene dos guiones.

Photochemical Machining Also known as chemical blanking, this involves producing parts by chemical action. The chemical dissolves all of the metal except the desired part.
Labrado Fotoquímico También se conoce como troquelado químico, y consiste en producir piezas por acción química. El químico disuelve todo el metal excepto la parte deseada.

Photorealism A term used to describe images that are created in such a fashion that they might fool the viewer into thinking that they are photographs.
Fotorealismo Un término que se usa para describir las imágenes que se crean de tal manera que podrían engañar al espectador a pensar que están viendo fotografías.

Physical Prototype A real, physical object that can be handled, analyzed, and tested.
Prototipo Físico Un objeto real y físico que puede manipularse, analizarse y probarse.

Pickle To clean forgings or castings in dilute sulfuric acid.
Limpiar con Ácido Limpiar las piezas forjadas o de fundición en ácido sulfúrico diluido.

Pictorial Drawing A drawing that depicts the object in a three-dimensional format; these drawings are typically isometric or perspective but may also be dimetric, trimetric, or oblique.
Dibujo Pictórico Un dibujo que muestra un objeto en tres dimensiones; estos dibujos típicamente son isométricos o de perspectiva pero también pueden ser dimétricos, trimétricos u oblicuos.

Piercing An operation similar to punching, except that no scrap is produced.
Agujerar Una operación similar al perforado, excepto que no produce material de desecho.

Piercing Point This is the exact location of the intersection of a surface and a line.
Punto Penetrante Ésta es la localización exacta de la intersección entre una superficie y una línea.

Pilot A piece that guides a tool or machine part.
Guía Una pieza que guía una herramienta o parte de una máquina.

Pilot Hole A small hole used to guide a cutting tool for making a larger hole.
Agujero Guía Un pequeño agujero que guía una herramienta cortante para hacer un agujero más grande.

Pinion Gear Exactly like the spur gear but usually smaller and with fewer teeth.
Engranaje de Piñón Exactamente como un engranaje de dientes rectos pero generalmente más pequeño y con menos dientes.

Pitch The distance from a point on a screw thread to a corresponding point on the next thread, as measured parallel to the axis. The center-to-center distance between increments.
Paso La distancia desde un punto en una rosca de un tornillo al punto correspondiente en la próxima rosca,

medido paralelo al eje. La distancia centro a centro entre incrementos.

Pitch Circle An imaginary circle corresponding to the circumference of the friction gear from which the spur gear is derived.
Círculo de Paso Un círculo imaginario que corresponde a la circunferencia del engranaje de fricción del cual se deriva el engranaje de dientes rectos.

Pitch Diameter The diameter of an imaginary diameter centrally located between the major diameter and the minor diameter.
Diámetro de Paso El diámetro de un diámetro imaginario localizado centralmente entre el diámetro mayor y el diámetro menor.

Placing Drawings Shop drawings of concrete structural members that are poured on site; they show the placement of reinforcing bars in the on-site form. Shop drawings and placing drawings are the same; the difference is in where the work occurs, in a shop or on site.
Dibujos de Colocación Dibujos de taller de los miembros estructurales de concreto que se fundirán en el lugar de construcción; muestran la localización de las barras de refuerzo en el molde que está en el lugar. Los dibujos de taller y los dibujos de colocación son los mismos; la diferencia está en dónde se lleva a cabo el trabajo, en el taller o en el lugar de construcción.

Plane To remove material by means of a planer.
Acepillar Remover material por medio de una acepilladora.

Plane Surface If any two points anywhere on a surface are connected to form a straight line, and that line rests upon the surface, it is a plane surface.
Superficie Plana Si cualesquiera dos puntos en cualquier lugar en una superficie se conectan para formar una línea recta, y esa línea esta sobre la superficie, entonces es una superficie plana.

Planer Single-edged cutting tool used to perform a cutting operation. It is normally much larger than a shaper, and the work, rather than the cutter, moves on the planer. Seldom used today.
Acepilladora Una herramienta cortante de un solo filo que se usa para llevar a cabo una operación cortante. Normalmente es mucho más grande que una conformadora, y el trabajo en vez de la cortadora, se mueve en la acepilladora. Muy poco usado hoy día.

Planning Chart A method of visually displaying when phases and steps are scheduled to begin and end. Some steps on the chart (within a phase) may overlap.
Gráfica de Planificación Un método de mostrar visualmente cuándo las fases y pasos están programadas para comenzar y terminar. Algunos pasos en la gráfica (dentro de una fase) pueden solaparse.

Plasma A gas that has been heated to the point that it ionizes and becomes electrically conductive.
Plasma Un gas que se ha calentado hasta el punto que se ioniza y conduce electricidad.

Plasma Arc Machining (PAM) A process that makes use of a plasma arc to remove material.
Labrado con Arco de Plasma Un proceso que usa un arco de plasma para remover material.

Plastics Nonmetal materials that are made from either natural or synthetic resins. Their main characteristics are: thermal, mechanical, chemical and corrosion resistance, and fabricability; the ability to sustain high mechanical loads; and predictable performance.
Plásticos Materiales no metálicos que están hechos de resinas naturales o sintéticas. Sus características principales son: resistencia termal, mecánica, química y a la corrosión, habilidad para fabricación; habilidad para soportar grandes cargas mecánicas; y funcionamiento predecible.

Plate To coat a metal piece with another metal, such as chrome or nickel, by electrochemical methods.
Enchapar Cubrir un pedazo de metal con otro metal, tal como cromo o níquel, por métodos electroquímicos.

Plate Jig The most common form of jig. It consists of a simple plate that contains the required drill bushings, locators, and clamping elements.
Guía de Placa La forma más común de guía. Consiste de una placa sencilla que contiene los cojinetes de taladro, localizadores y elementos de fijación necesarios.

Plot Plan A plan view of the building site showing where the structure is located on the lot.
Plano del Terreno Una vista plana del lugar de construcción que muestra dónde está ubicada la estructura en el lote de terreno.

Plotter An output device that makes a drawing by converting digital data into text and graphics.
Trazador Gráfico Un aparato de salida que crea un dibujo convirtiendo los datos digitales en texto y gráficos.

Plug Weld A weld made through a round hole. The symbols are the same. (See also *Slot Weld*).
Soldadura de Tapón Una soldadura que se hace a través de un agujero. Los símbolos son los mismos. (Vea también *Soldadura de Ranura*).

Point An exact location in space or on a drawing surface.
Punto Una localización exacta en el espacio o en la superficie de dibujo.

Point-to-Point A variation in the machine (along with continuous-path machines). In this type, the machine operates on a series of preprogrammed coordinates to locate the position of the tool. When the tool

finishes at one point, it automatically goes to the next point by the shortest route.
Punto a Punto Una variación en la máquina (junto con las máquinas de camino continuo). En este tipo, la máquina opera con una serie de coordenadas preprogramadas para localizar la posición de la herramienta. Cuando la herramienta termina en un punto, automáticamente se mueve al próximo punto por el camino más corto.

Poles Two reference measuring positions on the surface of the sphere on opposite sides of its center.
Polos Dos posiciones de referencia en la superficie de la esfera en lados opuestos de su centro.

Polish To produce a highly finished or polished surface by friction, using a very fine abrasive.
Pulir Producir una superficie bien acabada o pulida por fricción, usando un abrasivo fino.

Polygon A plane geometric figure with three or more sides.
Polígono Una figura geométrica con tres o más lados.

Polyhedron A solid object bounded by plane surfaces. Each surface is called a face.
Poliedro Un objeto sólido definido por superficies planas. Cada superficie se llama una cara.

Positional Tolerance A tolerance that controls the position of a feature relative to the true dimension specified for the features, as related to a datum or datums.
Tolerancia de Posición Una tolerancia que controla la posición de un rasgo relativo a la dimensión real especificada para los rasgos, según se relacionan con una referencia o referencias.

Powder Metallurgy A process similar to casting in which metal particles, or powder, are blended and mixed. The powder is then forced into a die of the desired form under intense pressure. The resulting heat fuses the powder into a solid piece that can be machined.
Metalurgia de Polvo Un proceso similar al proceso de moldes de fundición en el cual las partículas de metales o el polvo se mezclan. El polvo entonces se pasa a fuerza dentro de un troquel con la forma deseada bajo una presión intensa. El calor resultante funde el polvo en una pieza sólida que puede labrarse.

Powdered Metals Metal powders that are produced by atomization, electrolysis, chemical reduction, or oxide reduction. They can be mixed or sintered to produce alloys with an almost endless number of compositions. The properties of products made from powdered metals depend on which metals are mixed, in what amounts, and by what processes.
Metales en Polvo Polvos metálicos que se producen por atomización, electrólisis, reducción química o reducción de óxido. Las propiedades de los productos que se hacen de los metales en polvo dependen de cuáles metales se mezclan, en qué cantidades y por cuál proceso.

Power Saw A generic term for all types of electric or gas-operated saws. The types of power saws used most often in the machine shop are the contour band machine, or band saw, and the cutoff saw.
Sierra de Potencia Un término genérico para todo tipo de sierras eléctricas u operadas con gasolina. Los tipos de sierras de potencia que se usan con más frecuencia en un taller mecánico son la sierra de cinta de contorno o sierra de cinta y la sierra tronzadora.

Precision The quality or state of being precise or accurate; mechanical exactness.
Precisión La calidad o estado de ser preciso; exactitud mecánica.

Precision Grinder Grinders that are used for precision work. The principal types used are surface and cylindrical grinders.
Moledora de Precisión Moledoras que se usan para trabajo de precisión. Los tipos principales que se usan son las moledoras de superficie y cilíndricas.

Press Forging A single-step process in which the heated metal bar or billet is forced into a single die and is completed in a single press stroke.
Forjado a Presión Un proceso de un solo paso en el cual una barra de metal o un lingote caliente se presiona contra un troquel y se completa en un solo ciclo de presión.

Press-Fit Bushings A type of bushing used to position and guide the cutting tools used in jigs. They are pressed directly into the jig plate. They are used for short-run jigs or in applications where the bushings are not likely to be replaced frequently.
Cojinete de Encaje a Presión Un tipo de cojinete que se usa para posicionar y guiar las herramientas cortantes que se usan en las guías. Se encajan a presión directamente en la placa del guía. Se usan en las guías cortas o en las aplicaciones donde los cojinetes no serán reemplazados frecuentemente.

Primary Auxiliary View Views that have been projected perpendicular from an inclined surface and viewed looking directly at that surface.
Vista Primaria Auxiliar Vista que se proyecta perpendicularmente desde una superficie inclinada y se ve directamente en la superficie.

Principal Viewing Planes The top, front, and right-side planes; they are all perpendicular to each other.
Planos de Vistas Principales Los planos superior, frontal y del lado derecho; todos están perpendiculares unos a otros.

Printer A device that prints the output of a computer.
Impresora Un aparato que imprime el resultado de una computadora.

Prism A solid whose bases or ends are any congruent and parallel polygons, and whose sides are parallelograms.
Prisma Un sólido cuyas bases o extremos son cualesquiera polígonos paralelos y congruentes, y cuyos lados son paralelogramos.

Prismatic Pertaining to or like a prism.
Prismático Perteneciente a o parecido a un prisma.

Process Synchronization The state that has been achieved when all processes involved in producing a product are in balance and synchronized so that production flows smoothly and continuously.
Sincronización de Proceso El estado que se ha logrado cuando todos los procesos involucrados en producir un producto están balanceados y sincronizados de manera que su producción fluye suavemente y continuamente.

Processor The computer in a CAD system.
Procesador La computadora en un sistema de CAD.

Profile A feature control that specifies the amount of allowance variance of a surface or line elements on a surface.
Perfil Un control de rasgo que especifica la cantidad de variación permisible de una superficie o los elementos de línea en una superficie.

Profile of a Line A tolerance that controls the allowable variation of a surface from a basic profile or configuration. It establishes a tolerance for a given single element of a surface.
Perfil de una Línea Una tolerancia que controla la variación permisible en una superficie del perfil o configuración básica. Establece la tolerancia para un elemento de una superficie.

Profile of a Surface A tolerance that controls the allowable variation of a surface from a basic profile or configuration. It applies to the entire surface. The difference between the profile of a line and surface is similar to the difference between circularity and cylindricity.
Perfil de una Superficie Una tolerancia que controla la variación permisible en una superficie del perfil o la configuración básica. Se aplica a toda la superficie. La diferencia entre el perfil de una línea y la superficie es similar a la diferencia entre la circularidad y la cilindricidad.

Program A set of step-by-step instructions telling the computer to solve a problem with the information input to it or contained in memory.
Programa Un grupo de instrucciones paso por paso que le dicen a una computadora que resuelva un problema con la información que le es dada o que está contenida en memoria.

Progress Report A written report, directed to the client, to inform him/her of the things that have been done to complete the job and the things that still need to be done. They can be issued at agreed-upon intervals, depending on the length of the project.
Reportaje del Estado del Proyecto Un reportaje escrito, dirigido al cliente, para informarle sobre las cosas que habían hecho para completar el trabajo, y las cosas que todavía necesitan completarse. Pueden publicarse a intervalos convenidos, dependiendo del largo del proyecto.

Progressive Die A die in which several operations take place sequentially.
Troquel Progresivo Un troquel en el cual se llevan a cabo varias operaciones en secuencia.

Projected Tolerance Zone A modifier that allows a tolerance zone established by a locational tolerance to be extended a specified distance beyond a given surface.
Zona de Tolerancia Proyectada Un modificador que permite que se establezca una zona de tolerancia por medio de una tolerancia que se extenderá una distancia más allá de una superficie dada.

Projection Weld Similar to a spot weld and using the same welding symbol. This weld allows more penetration and, as a result, is a much better weld.
Soldadura de Proyección Similar a una soldadura de punto y usa el mismo símbolo de soldadura. Esta soldadura permite más penetración y como resultado, es una soldadura mucho mejor.

Projectors Imaginary lines of sight.
Proyecciones Líneas de vista imaginarias.

Proposal This is a combination of the selling price, specifications, delivery schedules, and the boilerplate.
Propuesta Es la combinación del precio de venta, especificaciones, horarios de entregas y el texto modelo.

Prototype An original model on which something is patterned.
Prototipo Un modelo original según el cual se hace un patrón de algo.

Punch To cut an opening of a desired shape with a rigid tool having the same shape.
Perforar Cortar una abertura de una forma deseada con una herramienta rígida de la misma forma.

Punching An operation that cuts a hole in a metal sheet or strip.
Perforado Una operación que corta un orificio en una hoja o tira de metal.

Purchased Part An item made elsewhere that is required to create a final product. Purchased parts are drawn on assembly drawings, usually in outline form, to show their function and relationship to the product.
Pieza Comprada Un artículo que fue hecho en otro lugar y que se requiere para crear el producto final. Las

piezas compradas se dibujan en dibujos de ensamblaje, generalmente en silueta, para mostrar su función y relación con el producto.

Pyramid A polyhedron having a polygon as its base.
Pirámide Un poliedro que tiene un polígono como su base.

Quadrant A sector with a central angle of 90° and usually with one of the radial lines oriented horizontally.
Cuadrante Un sector con un ángulo central de 90° y generalmente con una de las líneas radiales horizontales.

Quadrilateral A plane figure bounded by four straight lines.
Cuadrilátero Una figura plana bordeada por cuatro líneas rectas.

Quench The rapid cooling of a machined part in a cooling material. To immerse a heated piece of metal in water or oil in order to harden it.
Enfriamiento Rápido El enfriamiento rápido de una parte labrada en un material de enfriamiento. Sumergir un pedazo de metal calentado en agua o aceite para endurecerlo.

Quotation Department This department takes all factors, such as labor costs, material costs, manufacturing expenses, sales salaries and expenses, and general overhead costs, and uses them to arrive at the total cost to produce a product. It then adds the desired profit to the total cost to establish the selling price.
Departamento de Cotización Este departamento toma todos los factores, tales como los costos de mano de obra, costos de materiales, gastos de manufactura, gastos y salarios de ventas y los costos operativos generales, y los usa para llegar al costo total de producir un producto. Entonces le suma la ganancia deseada al costo total para establecer el precio de venta.

Rack A flat bar with gear teeth in a straight line to engage with teeth in a gear.
Cremallera Una barra plana con dientes de engrane alineados que encajan con los dientes de un engranaje.

Rack Gear A type of spur gear whose teeth are in a straight line or flat.
Engranaje de Cremallera Un tipo de engranaje de dientes rectos cuyos dientes están alineados o en un plano.

Radial Arm Design that changes rotary motion into either an up-and-down motion or a rocking action.
Brazo Radial Diseño que cambia el movimiento rotativo a un movimiento hacia arriba y hacia abajo o un movimiento de mecedora.

Radial Line Development A development in which the fold lines radiate from one point.
Desarrollo de Línea Radial Un desarrollo en el cual las líneas de doblez parten desde un punto.

Radius The distance from the center point of a circle to the outside curved surface. It is half the diameter.
Radio La distancia desde el punto central de un círculo a la superficie exterior curva. Es la mitad del diámetro.

RAM Random Access Memory.
RAM Memoria de Acceso Aleatorio.

Rapid Prototyping A prototyping process that builds the final product layer by layer by an electronic-laser process that uses data from 3-view drawings.
Creación Rápida de Prototipo Un proceso de creación de prototipo que construye el producto final capa por capa con un proceso electrónico con láser que usa datos de dibujos de 3 vistas.

Raster The coordinate grid dividing the display area of a graphics display.
Cuadrícula La cuadrícula coordinada que divide el área de una pantalla.

Real Time Response times in the interaction between humans and computers that are, for all intents and purposes, equal to real-world response times.
Tiempo Real Tiempos de respuesta en la interacción entre humanos y computadoras que son, para todo propósito práctico, iguales a los tiempos de respuesta del mundo real.

Rectangular System A method of surveying in which a large area of land is surveyed beginning from one basic reference point and divided into a grid of six-mile-square blocks called townships. Townships are further divided into 36 one-mile-square blocks called sections; these are subsequently divided into smaller and smaller rectangular sections of land.
Sistema Rectangular Un método de planimetría en el cual se mide un área grande de terreno, comenzando desde un punto básico de referencia y dividido en una cuadrícula de bloques de seis millas cuadradas llamados municipios. Los municipios se subdividen en 36 bloques de una milla cuadrada llamados secciones; éstos a su vez se subdividen en secciones de terreno cada vez más pequeñas.

Reference Dimension A nontoleranced dimension used for information purposes only, which does not govern production or inspection operations.
Dimensión de Referencia Una dimensión sin tolerar que se usa con propósitos informativos solamente y que no gobierna las operaciones de producción o inspección.

Reference Line A line that is always placed through the center of any symmetrical object.
Línea de Referencia Una línea que siempre se coloca a través del centro de cualquier objeto simétrico.

Refractory Metals Metals with an exceptional ability to withstand high temperatures; they also have a low coefficient of expansion, high modulus of elasticity, high resistance to thermal shock, high conductivity, and excellent hardness properties at high temperatures. Tungsten and molybdenum are two of the best known.
Metales Refractarios Metales con una habilidad excepcional para resistir altas temperaturas; también tienen un coeficiente de expansión termal bajo, un módulo de elasticidad alto, alta resistencia a shock termal, alta conductividad y propiedades excelentes de dureza a altas temperaturas. El tungsteno y el molibdeno son dos de los más conocidos.

Refresh Display A CRT device that requires the refreshing of its screen presentation at a high rate so that the image will not fade or flicker.
Pantalla Refrescada Un aparato de tubo de rayos catódicos (CRT) que requiere refrescar su presentación en pantalla a alta velocidad para que la imagen no se desvanezca o parpadee.

Regardless of Feature Size (RFS) The condition in which tolerance of position or form must be met irrespective of where the feature lies within its size tolerance. It tells machinists that the tolerance must be maintained regardless of the actual produced size of the object.
Independiente de Tamaño de Rasgo La condición en la cual la tolerancia de posición o forma debe de cumplirse independientemente de dónde caiga el rasgo dentro de la tolerancia de tamaño. Le dice a los labradores que las tolerancias deben mantenerse independiente del tamaño de producción del objeto.

Relief An offset of surfaces to provide clearance.
Relieve Un desbalance entre superficies para proveer separación.

Removed Section This section is very similar to a rotated section except that it is drawn removed or away from the regular views.
Sección Removida Esta sección es muy similar a la sección rotada excepto que se dibuja removida o separada de las vistas regulares.

Rendering Finishing a drawing to give it a realistic appearance; a representation.
Rendición Acabar un dibujo dándole una apariencia realista; una representación.

Renewable Bushing A type of drill bushing that is used in high-volume applications or where the bushings must be changed to suit different cutting tools used in the same hole.
Cojinete Renovable Un tipo de cojinete de taladro que se usa en las aplicaciones de alto volumen en el cual los cojinetes tienen que cambiarse para cumplir con las diferentes herramientas cortantes que se usan en el mismo agujero.

Repeatability The ability to redraw lines without creating a double image.
Reproducibilidad La habilidad de volver a dibujar líneas sin crear una imagen doble.

Resistance Welding The process of passing an electric current through the exact location where the parts are to be joined. This is usually done under pressure. Also, the process of welding metals by using the resistance of the metals to the flow of electricity to produce the heat for fusion of the metals.
Soldadura de Resistencia El proceso de pasar corriente eléctrica a través de una localización exacta dónde se unirán las partes. Esto generalmente se hace bajo presión. Además, el proceso de soldar los materiales usando la resistencia de los materiales al flujo de electricidad para producir calor para fundir los metales.

Retaining Rings Precision-engineered fasteners. They provide removable shoulders for positioning or limiting the movement of parts in an assembly.
Anillos Retenedores Sujetadores diseñados con precisión. Éstos proveen bordes removibles para posicionar o limitar el movimientos de las partes de un ensamblaje.

Revolved Section Sometimes referred to as the rotated section, this is used to illustrate the cross section of ribs, webs, bars, arms, spokes, or other similar features of an object.
Sección Revuelta A veces llamada la sección girada, ésta es usada para ilustrar la sección transversal de costillas, entramados, barras, rayos o otros rasgos similares de un objeto.

Rib A relatively thin, flat member acting as a brace or support.
Costilla Un miembro plano y relativamente fino que sirve como refuerzo o apoyo.

Right Angle An angle of 90°.
Ángulo Recto Un ángulo de 90°.

Right Profile The right-side view of a drawing.
Perfil Derecho La vista del lado derecho de un dibujo.

Right Triangle A triangle having a right angle or an angle of 90°.
Triángulo Recto Un triángulo que tiene un ángulo recto o de 90°.

Right-Side View The orthographic view that is projected to the right of the front view; the right profile.
Vista Lateral La vista ortográfica que se proyecta al lado derecho de la vista frontal; el perfil derecho.

Ring Gear Similar to the spur, pinion, and rack gears, except that the teeth are internal.

Engranaje de Anillo Similar a un engranaje de dientes rectos, un piñón o un engranaje de cremallera, excepto que los dientes son internos.

Riser In sand casting, used to vent the mold and to allow gases to escape; also serves as a small reservoir for excess material so that the mold cavity will remain full as the metal begins to shrink during the cooling process.
Tubo de Subida En la fundición en moldes de arena, se usan como respiradero del molde para permitir el escape de los gases; también sirve como un pequeño estanque para el material en exceso de manera que la cavidad del molde permanezca llena a medida que el metal comienza a contraerse durante el proceso de enfriamiento.

Rivet (verb) To connect with rivets or to clench over the end of a pin by hammering.
Remachar Unir con remaches o remachar el extremo de un pasador martillándolo.

Rivets (noun) Permanent fasteners, usually used to hold sheet metal together.
Remache Sujetador permanente, generalmente se usa para sujetar hojalata.

Robot A reprogrammable multifunction manipulator designed to move material parts, tools, or specialized devices through variable programmed motions for the performance of a variety of tasks.
Robot Un manipulador multifuncional programable diseñado para mover partes de material, herramientas o aparatos especializados a través de movimientos variables programados para el funcionamiento de una variedad de tareas.

Rolling A process where the heated metal bar is formed by passing through rollers having the desired form impressed on their surfaces.
Rodar Un proceso en el cual se le da forma a una barra de metal caliente pasándola a través de rodillos que tienen la forma deseada en su superficie.

ROM (Read-Only Memory) Refers to computer chips that have programs built into them at the factory.
ROM (Memoria Sólo Lectura) Se refiere a un chip de computadora en el cual se almacenan los programas en la fábrica.

Roof Plan A plan view showing the location and spacing of rafters and/or trusses. It is superimposed on the floor plan without dimensions.
Plano de Techo Una vista de plano que muestra la localización y separación de las vigas y/o armaduras. Está sobrepuesta sobre el plano de distribución sin dimensiones.

Root The bottom point joining the sides of a thread.
Raíz El punto inferior que une los lados de una rosca.

Root Diameter The measurement over the extreme inner edges of teeth.
Diámetro de Raíz La medida sobre el extremo interior de los dientes.

Root Opening The allowed space between parts.
Abertura de Raíz El espacio permisible entre piezas.

Rotary Ultrasonic Machining (RUM) A nontraditional machining process whereby the grinding motion is rotary and diamond tools remove material. It is used in the development of prototypes.
Labrado Ultrasónico Rotativo Un proceso de labrado no tradicional en el cual el movimiento moledor es rotativo y las herramientas de diamante remueven el material. Se usa en el desarrollo de prototipos.

Rotate To revolve through an angle relative to an origin.
Rotar Girar por un ángulo relativo a un origen.

Round An exterior rounded intersection of two surfaces.
Redondo Una intersección exterior redondeada de dos superficies.

Routine Designs Relatively basic projects and problems used to introduce new members of an organization to the various people in the company and to the routes design information needs to flow through.
Diseños de Rutina Proyectos y problemas relativamente básicos que se usan para introducir a los nuevos miembros de la organización a las diferentes personas en la compañía y a las rutas por las cuales debe fluir la información de diseño.

Runout A feature control that limits the amount of deviation from perfect form that is allowed on surfaces or rotation through one full rotation of the object about its axis.
Excentricidad Un control de rasgo que limita la cantidad de desviación de una forma perfecta que es permisible en las superficies o en la rotación de un objeto alrededor de su eje a través de una rotación completa.

Sandblast To blow sand at high velocity with compressed air against castings or forgings to clean them.
Pulir con Chorro de Arena Soplar arena a alta velocidad con aire comprimido contra las piezas de moldes de fundición o forjadas para limpiarlas.

Sandwich Jig A variation of the plate jig in which the workpiece is held between two plates.
Guía de Sándwich Una variación de la guía de placa en la cual la pieza de trabajo se aguanta entre dos placas.

Scalars Magnitudes without directions, such as temperature and pressure.
Escalares Magnitudes sin direcciones, tales como temperaturas y presiones.

Scalene Triangle A triangle having no equal sides or angles.
Triangulo Escaleno Un triángulo que no tiene lados o ángulos iguales.

Scientific Design A design process that uses concepts from physics, mechanics, materials science, chemistry, and mathematics.
Diseño Científico Un proceso de diseño que usa conceptos de física, mecánica, ciencia de materiales, química y matemática.

Scissors Drafting A technique used if any part of a set of drawings has been drawn previously; instead of redrawing this part, a slick is created and the details and other data needed from the slick are cut out and taped to a carrier sheet. A new slick is then created using the carrier sheet as the original.
Dibujo Industrial por Tijeras Una técnica que se usa si alguna parte de un grupo de dibujos ya se ha dibujado; en lugar de volver a dibujar esta parte, se crea una reproducción en película, y los detalles y otros datos que se requieren de dicha reproducción se recortan y se adhieren a la hoja portadora. Entonces se crea una nueva reproducción en película usando la hoja portadora como original.

Scrape To remove metal by scraping with a hand scraper, usually to fit a bearing.
Raspar Remover metal raspándolo con raspador de mano, generalmente para que encaje en un cojinete.

Screw A fastener that does not use a nut and is screwed directly into a part.
Tornillo Un sujetador que no usa una tuerca y se atornilla directamente en una pieza.

Scriber Templates Templates consisting of laminated strips with engraved grooves that are used to form letters. A tracing pin on the scriber moves in the grooves and guides the scriber in forming the letters.
Plantillas Inscribidas Plantillas que consisten de tiras laminadas con ranuras grabadas que son usadas para formar letras. Un pasador de trazar en el puzón se mueve en las ranuras y guía el puzón en formar las letras.

Seam Weld Like a spot weld, except that the weld is actually continuous from start to finish.
Soldadura Continua Como una soldadura de punto, excepto que la soldadura es continua desde el principio hasta el fin.

Seams The points at which two pieces of material are joined together by gluing, soldering, riveting, welding, and so on.
Junta Los puntos dónde se unen dos pedazos de material por medio de pegamento, soldadura, remaches y así por el estilo.

Secondary Auxiliary View A view that is projected directly from the primary auxiliary view; used when a primary auxiliary view is not enough to fully illustrate an object.
Vista Auxiliar Secundaria Una vista que se proyecta directamente desde la vista primaria auxiliar; se usa cundo la vista primaria auxiliar no es suficiente para ilustrar un objeto completamente.

Section Lining In welding, used to indicate where the weld is to be placed when a weld is not continuous and is needed in only a few areas. Otherwise, it shows where an object is sliced or cut by the cutting-plane line.
Línea de Sección En soldadura, se usa para indicar dónde se debe colocar la soldadura cuando la soldadura no es continua y se necesita sólo en unas áreas. De lo contrario, muestra dónde se corta el objeto por la línea del plano cortante.

Sectional View A view of an object obtained by the imaginary cutting away of the front portion of the object to show the interior detail.
Vista Seccional Una vista de un objeto que se obtiene al hacer un corte imaginario y removiendo la porción frontal de un objeto para mostrar los detalles interiores.

Sector The area of a circle lying between two radial lines and the circumference.
Sector El área de un círculo que queda entre dos líneas radiales y la circunferencia.

Segment The smaller portion of a circle separated by a chord.
Segmento La porción más pequeña de un círculo separada por una cuerda.

Self-Locking Rings A type of retaining ring; they do not require any grooves because they exert a frictional hold against axial displacement.
Anillos de Bloqueo Automático Un tipo de anillo retenedor; no requieren ranuras porque ejercen un agarre de fricción contra el movimiento axial.

Selling Price Prepared by the quotation department. The result of adding basic costs such as labor, engineering materials, salaries, sales costs, general overhead, and so on to come up with the cost of manufacturing the product, and then adding the desired profit to the cost.
Precio de Venta Es preparado por el departamento de cotización. Es el resultado de sumar los costos básicos tales como mano de obra, materiales de ingeniería, salarios, gastos de venta, costos operativos y cosas por el estilo, para obtener el costo de manufacturar el producto y luego añadirle al costo la ganancia deseada.

Semicircle Half of a circle.
Semicírculo Mitad de un círculo.

Set Screw A screw used to prevent motion between mating parts, such as the hub of a pulley on a shaft. It is screwed into and through one part so that it applies pressure against another part, thus preventing motion.

Tornillo de Fijación Un tornillo para prevenir el movimiento entre piezas apareadas, tales como el centro de una polea en un eje. Se atornilla a través de una pieza de manera que aplica presión contra otra pieza, evitando de esta manera el movimiento.

Shape To remove metal from a piece with a shaper.
Conformar Remover metal de una pieza con una conformadora.

Shaper A machine tool that uses a single-point cutting tool to perform the cutting operation. It is much smaller than the planer (see also *Planer*). The workpiece is mounted on a table or vise, and the cutter is driven by a reciprocating ram. Seldom used today.
Conformadora Una maquina de labrado que usa una herramienta cortante de un solo punto para la operación cortante. Es mucho más pequeña que la acepilladora (ver también Acepilladora). La pieza de trabajo se monta sobre una mesa y el cortador lo maneja con un martinete reciprocante. Casi no se usa hoy día.

Shaving An operation performed on a blanked part to produce an exact dimensional size or to square a blanked edge.
Rasurar Una operación que se hace en una parte en una pieza bruta para producir un tamaño dimensional o para cuadrar un borde de una pieza bruta.

Shearing A cutting action performed along a straight line. It uses two blades in sliding contact.
Cizallar La acción cortante a lo largo de una línea recta. Usa dos cuchillas en contacto deslizante.

Shim A thin piece of metal or other material used as a spacer in adjusting two parts.
Calce Un pedazo fino de metal u otro material que se usa como espaciador para ajustar dos partes.

Shrink Rule A standard steel rule that has the graduations marked for a specific amount of shrinkage.
Regla de Contracción Una regla estándar de acero que tiene gradaciones marcadas para determinar la contracción.

Shrinkage The percentage of size lost of a particular cast metal as it cools.
Contracción El porcentaje del tamaño perdido en un metal fundido mientras se enfría.

Side View Auxiliary An auxiliary view that is projected from the right-side view.
Vista Lateral Auxiliar Una vista auxiliar que es proyectada desde la vista del lado derecho.

Simulation The computer-generated emulation of a system or process.
Simulación Una emulación generada a computadora de un sistema o proceso.

Single Thread A screw thread type that is composed of one continuous ridge.
Rosca Sencilla Un tipo de rosca de tornillo que consiste de un resalto contínuo.

Single-Curved Surface A surface that can be unrolled to form a plane.
Superficie de una Curva Una superficie que puede desenrollarse para formar un plano.

Size Tolerance A tolerance where an ideal size is considered acceptable if it does not exceed certain parameters; for example, a size tolerance of ±.01″ for a piece that is ideally 4″ long means that it is acceptable if it is no longer than 4.01″ and no shorter than 3.99″.
Tolerancia de Tamaño Una tolerancia en la cual el tamaño ideal se considera aceptable si no excede ciertos parámetros; por ejemplo, una tolerancia de tamaño de ±.01″ para una pieza que idealmente es de 4″ de largo significa que es aceptable si no es más larga de 4.01″ ni más corta de 3.99″.

Sketches Rough drawings of what will be the final drawing.
Croquis Dibujos rudos de lo qué será el dibujo final.

Slick In drafting, a reproduction of a base sheet original drawing made on sensitized polyester film by fastening the two pieces of film together and exposing them to light. Used as a base sheet over which other types of plans may be overlaid while the base sheet original is being completed.
Reproducción en Película En dibujo industrial, la reproducción de un dibujo original de hoja base que se hace sobre una película de poliéster sujetando los dos pedazos de película y exponiéndolos a la luz. Se usa como una hoja base sobre la cual se pueden sobreponer otros tipos de planos mientras la hoja base original se completa.

Slip-Renewable Bushings A type of renewable drill bushing used where the bushing must be changed quickly. It is held in place by a lock screw but can be removed by turning it counterclockwise to the release position and lifting it out of the hole.
Cojinetes Deslizables Renovables Un tipo de cojinete de taladro renovable que se usa dónde se debe cambiar un cojinete rápidamente. Se aguanta en su lugar por un tornillo de seguridad, pero puede removerse por girarlo de derecha a izquierda hasta la posición de libertad y después levantarlo desde su agujo.

Slitting Performed on large sheets to produce thin stock strips. It may be performed by rollers or straight blades.
Cortar en Tiras Se hace con hojas grandes para producir tiras finas de material. Puede hacerse por medio de rodillos o cuchillas rectas.

Slope The angle, in degrees, that a line makes with a level plane.

Pendiente El ángulo, en grados, que forma una línea con el plano de nivel.

Slot Weld (see also *Plug Weld*) A weld made through an elongated hole. The symbols are the same.
Soldadura de Ranura (ver también *Soldadura de Tapón*) Una soldadura hecha a través de un agujero alongado. Los símbolos son los mismos.

Software A set of programs, procedures, rules, and possibly associated documentation concerned with the operation of a CAD system.
Software Un grupo de programas, procedimientos, reglas y la posible documentación asociada con la operación de un sistema de CAD.

Solder To join with solder, a compound usually composed of lead and tin.
Estañar Unir con soldadura, un compuesto generalmente compuesto por plomo y estaño.

Solid Length The overall length of the spring when all coils are compressed together so they touch.
Largo Sólido El largo completo de un resorte cuando todas las espirales se comprimen de manera que estén tocándose.

Solid Modeling A type of modeling that involves actually constructing a mathematical, geometric model of a design part and displaying it on the monitor screen.
Modelado Sólido Un tipo de modelado que consiste en construir un modelo matemático y geométrico de una parte diseñada y mostrarlo en la pantalla del monitor.

Solution Description Describes the final solution, including the performance specifications and the design specifications.
Descripción de Solución Describe la solución final, incluyendo las especificaciones de funcionamiento y de diseño.

Specifications A detailed, precise presentation of something or a proposal for something. Usually divided into two main categories: performance and design. Performance specs describe what the design is supposed to accomplish; design specs describe how the product is made and the materials used.
Especificaciones Una presentación detallada y precisa de algo o una propuesta para algo. Generalmente se divide en dos categorías principales: funcionamiento y diseño. Las especificaciones de funcionamiento describen qué se supone que logre el diseño; las especificaciones de diseño describen cómo se hará el producto y qué materiales se usarán.

Sphere A closed surface, every point on which is equidistant from a common point or center.
Esfera Una superficie cerrada, cada punto de la cual está equidistante de un punto común o centro.

Spin To form a rotating piece of sheet metal into a desired shape by pressing it with a smooth tool against a rotating form.
Rotar Formar una pieza de hojalata que rota en la forma deseada prensándola con una herramienta lisa contra un molde que rota.

Spiral Bevel Gear Any bevel gear with curved teeth.
Engranaje Cónico en Espiral Cualquier engranaje cónico con los dientes curvos.

Spot Welding A resistance-type weld that joins pieces of metal by welding separate spots rather than using a continuous weld.
Soldadura de Punto Un tipo de soldadura de resistencia que une pedazos de metal soldando puntos separados en lugar de formar una soldadura continua.

Spotface To produce a round spot or bearing surface around a hole, usually with a spotfacer; similar to a counterbore.
Avellanar Producir una superficie redonda o de apoyo alrededor de un agujero, generalmente con un avellanador.

Spotfaced Hole A plain through hole with a shallow counterbore deep enough to provide a flat surface for the head of a bolt or machine screw, or a nut for a threaded member.
Agujero Avellanado Un agujero pasante avellanado lo suficientemente para proveer una superficie plana a la cabeza de un tornillo o para la tuerca de un miembro con rosca.

Spring A mechanical device that is used to store and apply mechanical energy.
Resorte Un aparato mecánico que se usa para almacenar y aplicar energía mecánica.

Spring Pin A type of fastener; manufactured by cold forming strip metal in a progressive roll-forming operation. They are larger in diameter than the hole into which they are to be inserted and compress themselves as they are driven into the hole so that they exert radial forces around the entire circumference of the hole.
Pasador de Resorte Un tipo de sujetador, manufacturado por trabajo en frío en una operación de formación por rodillo. Son más grandes en diámetro que el agujero en el cual se van a insertar y se comprimen a medida que se meten a presión dentro del agujero de manera que ejercen fuerzas radiales a lo largo de toda la circunferencia del agujero.

Sprue Hole The hole in the top half of a mold flask through which the molten metal is poured to reach the gate or gates, which direct the metal to the cavity of the mold.
Orificio de Colada El orificio en la mitad superior de un molde a través del cual se vierte el metal derretido

para que llegue a los canales que dirigen al metal a la cavidad del molde.

Spur Gear The most commonly used gear. It is cylindrical in form, with teeth that are cut straight across the face of the gear. All teeth are parallel to the axis of the shaft.
Engranaje de Dientes Rectos El tipo de engranaje más común. Es de forma cilíndrica, con dientes que se cortan rectos en la cara del engranaje. Todos los dientes están paralelos al eje.

Staggered Intermittent Weld A type of intermittent weld in which the welds are staggered directly opposite each other on opposite sides.
Soldadura Intermitente Alterna Un tipo de soldadura intermitente en la cual las soldaduras están alternadas directamente opuestas una de otra en lados opuestos.

Stainless Steels Steels that contain 10.5% or more chromium.
Aceros Inoxidables Aceros que contienen 10.5% o más de cromo.

Stamping A process of using dies to cut or form metal sheets or strips into a desired form.
Acuñado Un proceso de usar troqueles para cortar o formar hojas o tiras de metal en una forma deseada.

Station Lines These line segments must be assumed or chosen on the lateral surface.
Líneas de Estación Estos segmentos de línea tienen que asumirse o escogerse en la superficie lateral.

Statistical Process Control (SPC) A process that uses statistical control charts in monitoring production processes in an attempt to reduce the amount of scrap and rework.
Control de Proceso Estadístico Un proceso que usa tablas de control estadístico en el monitoreo de los procesos de producción en un intento de reducir la cantidad de desperdicio y de trabajo repetido.

Statistical Tolerancing Symbol A symbolic means of indicating that the stated tolerance is based on statistical process control (SPC).
Símbolo de Tolerancia Estadística Un medio simbólico de indicar que la tolerancia indicada está basada en un proceso de control estadístico.

Steps (in the Design Process) A set of recognizable tasks in the design process that must be done in a specific order.
Pasos (en el Proceso de Diseño) Un grupo de tareas reconocibles en el proceso de diseño que tienen que hacerse en un orden específico.

Stereolithography A process whereby solid models are created layer by layer by an electronic-laser process in a special liquid solution.
Estereolitografía Un proceso mediante el cual los modelos sólidos se crean capa por capa en un proceso electrónico por láser en una solución líquida especial.

Straightness A tolerance that controls the allowable variation of a surface or an axis from a theoretically perfect plane or line. It can be used to control surface elements, an axis, or a center plane.
Rectitud Una tolerancia que controla la variación permisible de una superficie o un eje de un plano o línea perfecta. Puede usarse para controlar los elementos de superficies, un eje o un plano central.

Stress Relieving Heating a metal part to a suitable temperature and holding that temperature for a determined time, then gradually cooling it in air; this treatment reduces the internal stresses induced by casting, quenching, machining, cold working, or welding.
Alivio de Tensión Calentar una pieza metálica a una temperatura adecuada y mantenerla a esa temperatura por un tiempo determinado y luego enfriarla gradualmente; este tratamiento reduce las tensiones inducidas por los procesos de fundición, enfriado, labrado, trabajado en frío o de soldadura.

Stretchout A flat pattern development for use in laying out, cutting, and folding lines on flat stock, such as paper or sheet metal, to be formed into an object.
Patrón Extendido Un patrón de desarrollo plano que se usa para establecer las líneas de corte y de dobleces en material plano, tales como papel u hojalata, para formarlos en un objeto.

Strike A compass direction of a horizontal line lying in the plane of an ore vein.
Dirección de Descubrimiento La dirección de compás de una línea horizontal que está en el plano de una vena de mineral.

Structure Anything constructed of parts.
Estructura Cualquier cosa que está formada de partes.

Stud A fastener that is a steel rod with threads at both ends. It is screwed into a blind hole and holds other parts together by a nut on its free end.
Perno Un sujetador que es una barra de metal con roscas en ambos extremos. Se atornilla en un agujero ciego y sujeta otras piezas por medio de una tuerca en su extremo libre.

Subassembly Drawing A drawing of two or more parts permanently fastened together; very similar to an assembly drawing.
Dibujo de Subensamblaje Un dibujo de dos o más partes que están permanentemente unidas; muy similar al dibujo de ensamblaje.

Surface Grinder A grinder mainly used to produce flat, angular, or special contours on flat workpieces.
Moledora de Superficie Una moledora que se usa principalmente para producir contornos planos, angulares o especiales en las piezas de trabajos planas.

Surface Texture The roughness, waviness, lay, and flaws of a surface.
Textura de Superficie La aspereza, ondulación y fallas de una superficie.

Surface Weld This weld is done when a surface must have material added to it or built up.
Soldadura de Superficie Esta soldadura se hace cuando hay que añadirle material a una superficie o ésta tiene que acrecentarse.

Swage To hammer metal into shape while it is held over a swage or die that fits into a hole in the swage block or anvil.
Estampar Martillar el metal para darle forma mientras se aguanta sobre un estampador o un troquel que encaja en un agujero en el bloque de estampar o yunque.

Sweat To fasten metal together by the use of solder between the pieces and the application of heat and pressure.
Soldadura Sudada Unir metal por medio del uso de soldadura entre los pedazos y la aplicación de calor y presión.

Symbol A letter, character, or schematic design representing a unit or component.
Símbolo Una letra, carácter o diseño esquemático que representa una unidad o componente.

Tabular Dimension A type of rectangular datum dimensioning in which dimensions from mutually perpendicular datum planes are listed in a table on the drawing instead of on the pictorial portion.
Dimensión Tabular Un tipo de dimensionamiento de referencia rectangular en el cual las dimensiones de planos de referencia mutuamente perpendiculares se enumeran en una tabla en el dibujo en lugar de en la parte pictórica del dibujo.

Tangent Plane This concept uses a modifying symbol with an orientation tolerance to modify the intended control of the surface.
Plano Tangente Este concepto usa un símbolo modificado con una tolerancia de orientación para modificar el control intencionado de una superficie.

Tap A tool used to produce internal threads by hand or machine.
Macho de Rosca Herramienta que se usa para producir las roscas internas a mano o por máquina.

Taper Pin A small, tapered pin for fastening, usually to prevent a collar or hub from rotating on a shaft.
Pasador Cónico Un pasador pequeño y cónico que se usa para sujetar, generalmente para evitar que un collar o cubo rote sobre un eje.

Taper Reamer A reaming tool that produces accurately tapered holes, as for a taper pin.
Escariador Cónico Una herramienta para escariar que produce agujeros cónicos precisos, como para un pasador cónico.

Tapered Hole A hole that must first be drilled .015″ smaller in diameter than the smallest diameter of the tapered hole, and then reamed.
Agujero Cónico Un agujero que tiene que taladrarse .015″ más pequeño que el diámetro más pequeño del agujero cónico y luego tiene que escariarse.

Tempering The process of heating a hardened workpiece to a temperature below the hardening temperature, allowing the part to soak for a specific time period, and cooling.
Templar El proceso de calentar una pieza de trabajo endurecida a una temperatura por debajo de su temperatura de endurecimiento, permitiéndole a la pieza que se remoje por un tiempo específico y se enfríe.

Template A guide or pattern used to mark out the work.
Plantilla Una guía o patrón que se usa para marcar el trabajo.

Temporary Fasteners Used when the parts will be disassembled at some future time.
Sujetadores Provisionales Se usan cuando las piezas se desarmarán en algún momento futuro.

Tensile Force A force that "goes away from" the joint.
Fuerza en Tensión La fuerza que "es hacia fuera" de una unión.

Tensile Strength The maximum load (pull) a piece supports without breaking or failing.
Resistencia a la Tensión La carga máxima (en tensión) que una pieza aguanta sin romperse o fallar.

Tesselation Flat shading, where any curved surfaces on a model are broken up into facets.
Mosaico Sombrado plano donde cualquier superficie curva de un modelo se divide en facetas.

Thermal Analysis A means of evaluating the thermal characteristics of a part or product.
Análisis Termal Una manera de evaluar las características termales de una pieza o producto.

Thickness Gage A standard gage used for determining what type of metal to use on any given project. It deals with the thickness—rather than the weight—of various metals used in construction. In current usage, it replaced the older but more confusing weight gage system.

Calibre de Espesor Un calibre estándar que se usa para determinar qué tipo metal usar en cualquier proyecto. Utiliza el espesor—en lugar del peso—de varios metales que se usan en construcción. En su uso actual, reemplazó al sistema más viejo y más confuso del calibre de peso.

Thinwall Section This section is any very thin object that is drawn in section. It should be filled in solid black.
Sección de Pared Fina Esta sección es cualquier objeto muy fino que se dibuja en secciones. Debería ser rellenado de negro sólido.

Through Hole As its name implies, this hole goes completely through an object.
Agujero Pasante Como su nombre implica, es un agujero que pasa completamente a través de un objeto.

Time Interval The time it takes a cam to move the follower to the designed height.
Intervalo de Tiempo El tiempo que le toma a una leva mover al palpador a la altura designada.

Time-Dependent Variables Variable characteristics that change over time; time-dependent variables are frequently best viewed as animations.
Variables Dependientes del Tiempo Características variables que cambian con el tiempo; las variables dependientes del tiempo se ven mejor como animaciones.

Timing Diagram A diagram used to visualize graphically and study the interaction of cams on the same shaft by placing the different displacement diagrams in a column with the starting and ending points in line.
Diagrama de Sincronización Un diagrama que se usa para visualizar gráficamente y estudiar la interacción de las levas en el mismo eje colocando los diferentes diagramas de desplazamiento en una columna con los puntos de comienzo y de fin en línea.

Tin A silvery white metal that is soft and ductile. It is too weak to be used in its pure form, so it is alloyed with other metals such as antimony, copper, lead, zinc, or silver. It is most commonly used to coat steel containers used to preserve food.
Estaño Un metal plateado blancuzco que es blando y dúctil. Es muy débil para usarse en su estado puro, así que se alea con otros metales tales como antimonio, cobre, plomo, zinc o plata. Comúnmente se usa para recubrir los envases de acero que se usan para preservar alimentos.

Title Block A section on the drawing sheet whose primary function is to provide information not normally given on the drawing itself.
Bloque Titular Una sección en una hoja de dibujo cuya función principal es proveer información que normalmente no se provee en el dibujo mismo.

Tolerance Regarding locators, acceptable deviation limits determined by the specific size of the part to be machined. As a general rule, the tolerance of jigs and fixtures should be approximately 30% to 50% of the part tolerance.
Tolerancia Referente a los localizadores, son los límites aceptables de desviación determinados por un tamaño específico de la pieza a ser labrada. Como regla general, la tolerancia de las guías y aditamentos debería ser aproximadamente 30% a 50% de la tolerancia de la pieza.

Tolerancing Setting acceptable limits of deviation.
Tolerar Establecer los límites aceptables de desviación.

Tool Forces Those forces generated by the cutting tool during the machining cycle.
Fuerzas de Corte Aquellas fuerzas que son generadas por la herramienta de corte durante el ciclo de labrado.

Tooling Standard and/or special tools for producing a particular part, including jigs, fixtures, gauges, cutting tools, and so on.
Herramientas Herramientas estándares y/o especiales para producir una pieza particular, incluyendo guías, aditamentos, instrumentos de medición, herramientas cortantes, y cosas por el estilo.

Top Auxiliary View An auxiliary view projected from the top view.
Vista Superior Auxiliar Una vista auxiliar que es proyectada desde la vista superior.

Top View A viewing plane that is usually above the object and perpendicular to the other two; the plan view.
Vista Superior Un plano de vista que generalmente está encima el objeto y perpendicular a los otros dos planos; vista aérea.

Torque The rotational or twisting force in a turning shaft.
Fuerza de Torsión La fuerza rotacional o de torsión en un eje que rota.

Torsion Spring Offers resistance to a torque or twisting action. In its free state, the coils are usually either touching or very close.
Resorte de Torsión Ofrece resistencia a una fuerza de torsión o a una acción de torcer. En su estado libre, las espirales del resorte se están tocando o están muy cerca.

Total Runout A tolerance that simultaneously controls a surface related to a datum in all directions.
Excentricidad Total Una tolerancia que simultáneamente controla una superficie en relación a una referencia en todas las direcciones.

Trade-off A compromise, usually between costs and materials.

Concesión Un compromiso, generalmente entre costos y materiales.

Trammel An instrument consisting of a straightedge with two adjustable fixed points for drawing curves and ellipses.
Elipsógrafo Un instrumento que consiste de una regla con dos puntos fijos ajustables y se usa para dibujar curvas y elipses.

Transfer Cards Cards containing lettering or any frequently used type of graphic data. They are designed to fit against a straightedge for ease of alignment, and the symbols are transferred to the drawing by rubbing them with a blunt point.
Tarjetas de Transferencia Tarjetas que contienen letras o cualquier tipo de datos gráficos usados frecuentemente. Están diseñadas para encajar contra una regla para fácil alineación, y los símbolos se transfieren al dibujo frotando las tarjetas con una punta roma.

Transition Fit A condition in which two parts are toleranced so that either a clearance or an interference can result when the parts are assembled.
Encaje de Transición Una condición en la cual dos piezas se han tolerado de manera que resulte en una separación o una interferencia cuando se ensamblen las piezas.

Translucent A quality of material that passes light but diffuses it so that objects are not identifiable.
Translúcido La cualidad de un material que permite que la luz pase pero que la difunde de manera que los objetes no son identificables.

Triangle A closed plane figure with three straight sides.
Triángulo Una figura de plano cerrado con tres lados rectos.

Triangulation A method of dividing a surface into a number of triangles and then transferring each triangle's true size and shape to the development.
Triangulación Un método de dividir una superficie en un número de triángulos y luego transferir el tamaño real y forma de cada triangulo al desarrollo.

Triangulation Development The development process of breaking up an object into a series of triangular plane surfaces.
Desarrollo de Triangulación El proceso de desarrollo de romper un objeto en una serie de superficies planas triangulares.

Trimetric Drawing A pictorial drawing technique that uses axes that are rotated so that each axis is drawn at a different angle, and each axis uses a different scale.
Dibujo Trimétrico Una técnica de dibujo pictórico en el que se rotan los ejes de manera que cada eje se dibuja a un ángulo diferente y a una escala diferente.

Trimming An operation performed on formed or drawn parts to remove the ragged edge of the blank.
Desorillar Una operación que se hace en las piezas formadas para remover el borde irregular de una pieza bruta.

True Distance The true actual straight distance between any two points.
Distancia Real La distancia recta real entre cualesquiera dos puntos.

True Length True length of a line is the actual straight distance between its two ends.
Largo Real El largo real de una línea es la distancia recta real entre sus dos extremos.

True Position The basic or theoretically exact position of a feature.
Posición Real La posición básica o teórica exacta de un rasgo.

True Size True actual size of a surface or object.
Tamaño Real El tamaño real de una superficie u objeto.

True Slope This slope can only be seen in the view that has a level line and where it is drawn at a true length.
Pendiente Real Esta pendiente sólo puede verse en una vista que tiene una línea nivelada y que se dibujó al largo real.

Truncated Having the apex, vertex, or end cut off by a plane.
Truncado Que tiene un ápice, vértice o un extremo cortado por un plano.

Trusses Frames that are usually two-dimensional and are made of structural shapes, such as angles, tubes, rounds, and channels.
Armadura Armazones que generalmente son de dos dimensiones y que están compuestas por formas estructurales como ángulos, tubos, círculos y canales.

T-Square A piece of equipment used with a drafting board. It is used to provide horizontal lines. Used mainly by the beginning drafter.
T Cuadrada Un pedazo de equipo que se usa con una mesa de dibujo industrial. Se usa para proveer líneas horizontales. Lo usan mayormente los delineantes principiantes.

Turn To produce on a lathe a cylindrical surface parallel to the center line.
Tornear Producir en un torno una superficie cilíndrica paralela a la línea de centro.

Two-Force Members Members that have force at each end. The forces are equal in magnitude, in opposite directions, and collinear.

Miembros de Dos Fuerzas Miembros que tienen una fuerza en cada extremo. Las fuerzas son iguales en magnitud, en direcciones opuestas y son colineles.

Typical This term, when associated with any dimension or feature, means the dimension or feature applies to the locations that appear to be identical in size and shape.
Típico Este término, al asociarlo con algún rasgo o dimensión, significa que el rasgo o dimensión se aplica a los lugares que parecen ser idénticos en tamaño y forma.

Ultrasonic Machining (USM) A nontraditional machining process that removes material using an abrasive slurry driven by a special tool vibrating at a high frequency along a longitudinal axis.
Labrado Ultrasónico a Maquina Un proceso no tradicional de labrar a máquina que remueve material usando una lechada abrasiva que la guía una herramienta especial que vibra a altas frecuencias a lo largo del eje longitudinal.

Ultrasonically Assisted Machining (UAM) A nontraditional machining process that involves assisting such traditional machining processes as drilling and turning by coupling the tool with an external source of vibrating energy.
Labrado a Maquina Asistido por Ultrasonido Un proceso no tradicional de labrar a máquina que consiste en asistir un proceso de labrado tradicional, tal como el taladrado o el torneado, acoplando la herramienta a una fuente externa de energía vibratoria.

Uniform Having the same form or characteristic; unvarying.
Uniforme Que tiene la misma forma o característica; invariante.

Uniform Acceleration The smoothest motion of all cams, and its speed is constant through the cam travel. The acceleration curve is actually a parabolic curve; the first half of the curve is exactly the reverse of the second half. This form is best for high speed.
Aceleración Uniforme El movimiento más suave de todos las levas, y su velocidad es constante a través del viaje de la leva. La curva de aceleración es en realidad una curva parabólica; la primera mitad de la curva es exactamente el reverso de la segunda mitad. Esta forma es la mejor para velocidad alta.

Uniform Velocity Regarding a cam, a type of motion. That is, it rises and falls at a constant speed, but the start and stop are very abrupt and rough.
Velocidad Uniforme Referente a una leva, un tipo de movimiento. Esto es, sube y baja a una velocidad constante, pero el comenzar y el detener son muy abruptos y ásperos.

Unilateral Tolerance When applied to a dimension, the tolerance applies in one direction (for example, the object may be larger but not smaller, or it may be smaller but not larger).
Tolerancia Unilateral Cuando se aplica a una dimensión, la tolerancia aplica en una dirección (por ejemplo, el objeto puede ser más grande pero no más pequeño, o puede ser más pequeño pero no más grande).

Unlimited Plane A term meaning that there is a limitless extension beyond the indicated boundaries.
Plano Ilimitado Un término que significa que hay una extensión ilimitada más allá de los bordes indicados.

Uppercase Letters A lettering system where all the letters are uppercase. It is used on the viewing plane.
Letras Mayúsculas Un sistema de letras en el cual todas las letras son mayúsculas. Se usa en el plano de vista.

Upset To form a head or enlarged end on a bar by pressure or by hammering between dies.
Recalcar Formar una cabeza o un extremo engrandecido en una barra por medio de presión o martillando entre troqueles.

Upsetting A process used to enlarge selected sections of a metal part.
Recalcadura Un proceso usado para engrandecer secciones selectas de una parte metálica.

Vendor Catalogs Catalogs published by vendors of materials that list materials and their typical uses to aid in their selection.
Catálogos de Vendedores Catálogos publicados por los vendedores de materiales que listan materiales y sus usos típicos para ayudar en su selección.

Verification A technique used in preparing notes on drawings; the notes are first written down on a print of the drawing, and then another drafter checks the notes to ensure that they are accurate and not open to multiple interpretations.
Verificación Una técnica que se usa para preparar notas en los dibujos; las notas se escriben primero en una impresión del dibujo y luego otro redactor verifica las notas para asegurar que son precisas y no están abiertas a interpretaciones múltiples.

Vernier Scale A small, movable scale, attached to a larger fixed scale, for obtaining fractional subdivisions of the fixed scale.
Escala Vernier Una escala pequeña y movible que está pegada a una escala más grande, y se usa para obtener subdivisiones fraccionales de la escala fija.

Vertex The highest point of something; the top; the summit. Plural: vertices.
Vértice La posición más alta de algo; la cimbre; la cumbre. Plural: vértices.

Vertical Perpendicular to the horizon.
Vertical Perpendicular al horizonte.

Vertical Boring Mill A machine tool commonly used to turn, bore, and face large parts in much the same way as a lathe.
Fresa de Taladrado Vertical Una herramienta para labrar que se usa comúnmente para tornar, taladrar y encarar partes grandes de manera similar a un torno.

Vertical Turret Lathe A variation of the vertical boring mill. Rather than using a single tool, this machine uses a turret arrangement to mount and position the cutting tools.
Torno de Torre Vertical Una variación de la fresa de taladrado vertical. En lugar de usar una herramienta sola, esta máquina usa un arreglo de torre para montar y posicionar las herramientas cortantes.

Virtual Condition A condition of a feature in which all tolerances of location, size, and form are considered. Also, where straightness applied to the axis or center line of a feature creates a boundary condition.
Condición Virtual Una condición de algún rasgo en la cual se consideran todas las tolerancias de localización, tamaño y forma. También, dónde la rectitud aplicada al eje o la línea central de un rasgo crea una condición de frontera.

Virtual Reality A technology designed to simulate either a physical or hypothetical environment. It is intended to involve all the natural senses.
Realidad Virtual Una tecnología diseñada para simular un ambiente físico o hipotético. Su intención es involucrar a todos los sentidos.

Visible Line One of twelve basic types of lines, it is thin and dark.
Línea Visible Una de doce tipos básicos de líneas. Es fina y oscura.

Visualization A pictorial representation of data for the purpose of more clearly and concisely communicating information.
Visualización Una representación pictórica de los datos con el propósito de comunicar información más clara y concisamente.

Vorticity The stage of a fluid in vortical (rotational) motion; the whirling of a fluid (like blood in the heart).
Vorticidad El estado de un fluido en movimiento voraginoso (rotacional); el arremolinar de un fluido (como la sangre en el corazón).

Warped Surface A surface that cannot be developed because it is neither a plane surface nor a curved surface.
Superficie Combada Una superficie que no puede desarrollarse porque no es una superficie plana ni es una superficie curva.

Waste Used here in the broadest sense and encompasses rejected parts, wasted personnel time, wasted machine time, excessive inventory, and any other situation that wastes time, material, or any other manufacturing resource.
Desperdicio Aquí se usa en el sentido más amplio y comprende las partes rechazadas, el tiempo perdido del personal, el tiempo perdido de las máquinas, el inventario en exceso y cualquier otra situación que desperdicia tiempo, material o cualquier otro recurso manufacturero.

Water Jet Machining (WJM) A nontraditional machining process used with nonmetal workpieces. It uses a thin, pressurized jet of water against the workpiece.
Labrado con Chorro de Agua Un proceso no tradicional de labrado que se usa con piezas que no son de metal. Usa un chorro fino de agua presurizada contra la pieza de trabajo.

Web A thin, flat part joining larger parts; also known as a rib.
Entremado Una pieza plana y fina que une piezas más grandes; también se conoce como una costilla.

Weight Gage An obsolete system for determining metal usage. It was based on the weight of wrought iron. It has been replaced by the thickness gage.
Calibre de Peso Un sistema obsoleto para determinar el uso de metal. Estaba basado en el peso del hierro forjado. Se ha reemplazado por el calibre de espesor.

Welded Tool The bodies offer a faster lead time, but must be machined frequently to remove any distortion caused by the heat of welding.
Herramienta Soldada Las piezas ofrecen un tiempo de procesamiento más rápido, pero tienen que labrarse a máquina frecuentemente para remover cualquier distorsión causada por el calor de la soldadura.

Welding The process of holding two pieces of metal together, permanently, by means of pressure or fusion-welding processes.
Soldadura El proceso de unir dos pedazos de metal, permanentemente, por medio de procesos de soldadura a presión o por fusión.

Welding Symbol A symbol used to convey welding instructions on a drawing. It consists of a reference line, a leader line and arrow, and, if needed, a tail.
Símbolo de Soldadura Un símbolo que se utiliza para comunicar las instrucciones de soldadura en un dibujo. Consiste de una línea de referencia, una línea principal y una flecha y, si es necesario, una cola.

Whiteprinter A machine that reproduces a drawing through a chemical process. An original drawing is placed on a sheet of coated whiteprint paper and exposed to light, and the exposed sheet is passed through ammonia vapor for developing. This causes the portions of the sheet that were shielded from the light by the lines on the original to turn blue or black.
Impresora de Blanco Máquina que reproduce los dibujos por medio de un proceso químico. El dibujo original se coloca sobre una hoja de papel de impresión en blanco y se expone a la luz, y la hoja expuesta se pasa por vapor de amoníaco para revelarse. Esto causa que las partes de la hoja que fueron bloqueadas de la luz por las líneas en el dibujo original se tornen azul o negras.

Whole Depth The total depth of a tooth space.
Profundidad Total La profundidad total de un espacio de engranaje.

Wire Size The diameter of the wire used to make up the spring.
Tamaño de alambre El diámetro del alambre usado para formar un resorte.

Woodruff Key A semicircular flat key.
Llave Woodruff Una llave plana y semicircular.

Working Circle Considered a distance equal to the distance from the center of the camshaft to the highest point on the cam.
Círculo de Trabajo Se considera como una distancia igual a la distancia desde el centro del eje de levas al punto más alto de la leva.

Working Depth The distance that a tooth projects into the mating space. It is equal to gear addendum (a) plus pinion addendum (a).
Profundidad de Trabajo La distancia que se proyecta un diente dentro de su pieza de engrane. Es igual a la altura de cabeza del engranaje (a) más la altura de cabeza del piñón (a).

Working Drawings A set of drawings that provides details for the production of each part, and information for the correct assembly of the finished product.
Dibujos de Trabajo Grupo de dibujos que provee detalles para la producción de cada pieza e información para el ensamblaje correcto del producto final.

Workpiece A part in any stage of manufacturing before it becomes a finished part.
Pieza de Trabajo Un parte en cualquier paso de la manufactura antes de convertirse en una pieza acabada.

Workstation The assigned location where a worker performs his or her job (i.e., the keyboard and the system display).
Estación de Trabajo El lugar asignado dónde un trabajador hace su trabajo (esto es, el teclado y la pantalla del sistema).

Worm Gear Used to transmit power and motion at a 90° angle between nonintersecting shafts. It is normally used as a speed reducer.
Engranaje de Tornillo Se usa para transmitir potencia y movimiento a un ángulo de 90° entre los ejes que no se cruzan. Normalmente se usa como un reductor de velocidad.

Written Notes Brief, carefully worded statements placed on drawings to convey information not covered or not adequately explained using graphics.
Notas Escritas Declaraciones cortas, redactadas cuidadosamente que se colocan en los dibujos para comunicar información que no está cubierta o que no se explica adecuadamente usando gráficos.

Wrought Iron Iron of low carbon content; useful because of its toughness, ductility, and malleability.
Hierro Forjado Hierro con poco contenido de carbón; es útil debido a su dureza, ductilidad y maleabilidad.

Yards Volume in cubic yards; used in construction.
Yardas Volumen en yardas cúbicas; utilizado en construcción.

Zinc A bluish-white metal that is widely used in manufacturing. It is produced in castings and is widely used for coating other materials. Its advantages include ease of casting, strength, ductility, and the ability to hold close tolerances.
Zinc Un metal azul-blancuzco que se usa extensamente en la manufactura. Se produce en moldes fundidos y se usa extensamente para recubrir otros materiales. Sus ventajas incluyen la facilidad de fundición, fortaleza, ductilidad y su habilidad para mantener tolerancias pequeñas.

Index

A
Abrasive water jet machining (AWJM), 757–758
Accelerations, 28
Acme thread from, 513
Active coils, 561
Actual local size, 467
Actual mating size, 467
Actual size, 400, 467
Addendum (A), 596
Adjustable curves, 45, 48
Adjustable triangles, 46–47
Airbrushes, 63–64
Aligned dimensioning, 374
Aligned features, 178, 213–214
Aligned sections, 214–215
All around symbol, 475, 495
Allowance, 400, 401, 467
Alloy steels, 725
Aluminum, 726
American Institute of Steel Construction (AISC), 796
American National Standards Institute (ANSI), 13, 404, 512
American Society of Mechanical Engineers (ASME), 13, 470
American Standard threads, 512
American Welding Society, 705
Analog computers, 24
Anchor bolt plan, 804
Anderson, Mary, 183
Anderson Aviation Company, 526
Andrews, John, 353
Andrews Sheet Metal Fabrication (ASMF), 353
Angle gears, 592
Angle plate fixtures, 741
Angle plate jigs, 739–740
Angles, 104–105, 281–282, 379–380, 660
Angularity, 467
  of an axis or center plan, 489–490
  of a surface, 489
Angular lines, 84
Animation, 450
Annealing, 751
ANSI standard clearance locational fits, 406f10–117
ANSI standard force and shrink fits, 409f10–120
ANSI standard interference locational fits, 408f10–119
ANSI standard running and sliding fits, 405f10–116
ANSI standard transition locational fits, 407f10–118
Application engineering, 621
Applied descriptive geometry, 284–311
Appliqués, 68
Arbor presses, 738
Architect's scales, 52
Architectural drafting, 811–817
  commercial plans, 817
  electrical plans, 817
  elevations, 812
  floor plans, 811–812
  foundation plans, 811
  HVAC plans, 812, 816–817
  plot plans, 811
  residential plans, 811
  roof plan, 817
Architectural drawings, 11, 12, 19
Arcs, 379–380
Arrowheads, 378
Artistic drawings, 3
ASME Y14.5M-1994, 470
Assembly drawing, 615–616
Assembly sections, 210–211
Attribute data, 827–828
Attribute queries, 830
Attributes, 422
Automation and integration, 758
Auxiliary sections, 209–210, 245
Auxiliary views
  auxiliairy sections, 245
  defined, 237
  drawing, 237–239
  drawing with fold lines, 239–240
  half auxiliary views, 245
  hidden lines in, 237
  irregular curved surfaces, 243–244
  notations for, 262
  oblique surfaces, 245–246
  primary, 261
  projecting round surfaces from inclines, 241–242
  of round surfaces, 242
  secondary, 244
Axonometric drawings
  trimetric drawings, 672
Axonometric projections, 4, 8f11, 8f12, 8f13
  isometric assemblies, 671
  isometric projections, 671
Axonometric sketching, 87, 90–91
Azimuth bearings, 279–280

B
Babbage, Charles, 24
Backing welds, 710
Back welds, 710
Band saws, 736
Base angles, 801, 804
Base circle, 576, 599
Base line dimensioning, 386
Basic dimension, 467, 479–480
Basic welding symbol, 699
  contour symbol, 705–706
Batter, 281
Beam compass, 45
Beams, 804
Bearings, 278–284
  azimuth bearing method, 279–280
  north/south deviation, 279
Belt drives, 593
Bend allowance charts, 353
Bender, 731
Bending, 733
Bends, 353–355
  finding all straight sides of 90° bends, 354
  finding bend allowance of 90° bend, 354
  finding bend allowance of other than 90°, 355
  finding total straight-side length adjoining bends other than 90°, 354–355
Between symbol, 475
Bevel, 281
Beveled rings, 541
Bevel gears, 592, 604
Bidding and contractor selection, 1
Bilateral tolerance, 400, 467, 470
Blanking, 733
Blanks, producing, 732–733
Blind holes, 179, 384
Boardroom sketching, 78
Boilerplate, 621
Bolts, 518, 522
Bonus tolerance, 467
Boolean operators, 448
Borders, 64
Boring mills, 737–738
Bosses, 394–395
Bounds, 817
Bow compass with lead clutch, 44
Bowed rings, 541
Box construction for irregular objects, 663
Box jigs, 740
Brass pipes, 771
Breakdown, 731
Broaching machines, 738
Broken-out sections, 207, 209
Buffering, 830
Built-up tool bodies, 748
Burnishing plates, 68–69
Bushings, 750
Butterfly scribers, 62–63
Butt joints, 523
Button head rivets, 523
Buttress thread form, 514

C
Cabinet drawings, 672
Cabinet oblique, 7f9
CAD/CAM process, 26
CAD systems, 8, 16, 20
  key concepts, 24–26
  overview, 24
  workstation components, 26–30
Cams
  dimensioning of, 581–582
  drawing with flat-faced followers, 579–581
  drawing with offset followers, 579
  followers, 575
  laying out from displacement diagram, 578–581
  mechanisms of, 575–576
  motions of, 576–578
  offset followers, 578
  principles of, 575
  terms, 576
Cap screws, 519, 520
Carbon spring steel, 542
Carbon steels, 725
Career profile, 1
Case hardening, 751
Casting, 729–731
  centrifugal, 730
  die, 730
  investment, 730
  powder metallurgy, 730–731
  sand, 729
Cast iron pipes, 771
Cast irons, 726
Cast steels, 726
Cast tool bodies, 748
Cavalier drawings, 672
Cavalier oblique, 7f10
Center lines, 83, 169
Center-to-center distance, 599
Central angles, 106
Centrifugal casting, 730
Ceramics, 728
Chain and sprockets, 593
Chain dimensioning, 386
Chain intermittent weld, 704
Chamfer angle, 710
Chamfers, 391–392, 626
Channel jigs, 740
Check valves, 772, 776
Cheeks, 729
Chemical milling, 757
Chordal addendum, 603
Chordal thickness, 603
Chords, 107, 379–380
Circles, 106, 128
Circular construction
  arcs tangent to an acute ankle, 122
  arcs tangent to an obtuse angle, 122–123
  arcs tangent to a right angle, 121–122
  arcs tangent to a straight line and a curve, 123–124
  arcs tangent to two radii or diameters, 124–125
  circles, 128
  conic sections, 128
  ellipse, 129
  ellipses, concentric circle method, 129
  foci ellipse, 131–132
  hyperbolas, 137–139
  joining points by a parabolic curve, 139
  locating major and minor axes of given ellipse, 132–133
  locating the center of a given circle, 120
  ogee curves, 125–127
  parabolas, 135–137
  tangent points, 120–121
  tangents to ellipse at a point on the ellipse, 133–134
  tangent to an ellipse from distant points, 134–135
  trammel ellipse, 129–131
  triangles, 128

Circularity, 467, 487–488
Circular pitch (p), 595
Circular runout, 467, 496
Circumference, 106
Civil engineering drafting, 817–826
  contour lines, 824–825
  legal descriptions, 817
  lot and block descriptions, 817, 823
  metes and bounds systems, 817
  plot plans, 823–824
  plotting legal descriptions, 817, 823
  rectangular system, 825
  section subdivision, 825–826
  township subdivision, 825
Civil engineer's scale, 54
Clamping principles, 745–748
Clamps, 748
Clapper boxes, 737
Classes of fit, 518, 525
Clearance (C), 596
Clearance fit, 401, 467
Closed jigs, 739
CNC applications, 760–761
Coaxiality, 467
Coil (turn), 561
Columns, 804
Commercial plans, 817
Compasses, 43–45, 68
Composites, 728
Compound datum features, 467
Compound operations, 732
Compression springs, 558–559
  drawing instructions, 561–562
  with ground closed ends, 564–565
  with plain closed ends, 562–563
Compton, John, 245
Computational fluid dynamics (CFD), 455–456
Computer-aided design and drafting (CADD), 26
Computer-aided manufacturing (CAM), 26, 758–761
Computer graphics (CG), 26
Computer-integrated manufacturing (CIM), 13, 763–766
Computer numerical control (CNC), 758–760
Computers, 24–26
Concentric circles, 107
Concentricity, 467, 496–500
Conceptual design, 613
Cones, 107–108, 395–396
Conic sections, 128
Consolidated Waterworks District 1, Terrebonne Parish, LA, 465
Construction documents, 1
Construction principles, 108–117, 748–750
  bisecting a line, 108
  bisecting an angle, 108–109
  dividing a line equally, 111–112
  dividing a line proportionally, 113–114
  drawing arcs or circles through three points, 109
  drawing curved parallel lines, 110–111
  drawing parallel lines, 109
  drying perpendicular lines, 111
  proportionally enlarging or reducing shapes, 115
  transferring an angle, 114
  transferring an odd shape, 114
  transferring complex shapes, 115
Continuous paths, 738
Contour intervals, 286
Contour lines, 285–286, 824–825
Contour symbols, 705, 715
Contracts, 623
Contraints, 449
Conventional breaks, 180
Conversational sketching, 78
Copper, 726–727
Copper pipes, 771
Copper tubing, 771
Core prints, 729
Counterbored holes, 180, 387
Countersunk holes, 180, 387
Countersunk rivets, 523
CPU (central processing unit), 30
Cross-hatching lines, 83
Cross-sectional views, 206
Curved surfaces, 381
Curve plotting, 176
Curves, 660
Cutoff saws, 736
Cutting off, 732
Cutting-plane lines, 202
Cycloidal curves, 143
Cylinders, 388, 660
Cylindrical, 575
Cylindrical grinders, 737
Cylindrical helix, 140
Cylindrical intersections, 177–178
Cylindricity, 467, 488–489

D

Data, understanding, 446
Datum, primary, 468, 500
Datum, secondary, 469, 500
Datum, simulated, 467
Datum, tertiary, 469, 500
Datum axis, 467
Datum dimensioning, 386
Datum feature, 467, 477
Datum feature of size, 467
Datum feature simulator, 467, 477
Datum identification symbol, 467
Datum plan, 477
Datum reference, 467
Datum reference frame, 467, 480
Datums, 400, 467
  defined, 476
  establishing, 476–478
  review of, 500–501
  targets, 478–481
Datum simulation, 467
Datum surface, 477
Datum target area, 467
Datum target line, 467
Datum target point, 467
Datum targets, 467, 478–481
Datum target symbol, 478–479, 500
Decimal-inch dimensioning, 373
Dedendum (B), 596
Descriptive geometry projections, 261
Design development, 1
Design development layout drawins, 613
Design for assembly (DFA)
  guidelines, 626–627
  procedure, 625–626
Design for manafacturability (DFM), 16, 20, 623–625
  guidelines, 624–625
  procedure, 623–624
Design improvements, 424
Design location, 403
Design procedure, 612–613
Design process, 6–9
  Computer Assisted Design (CAD), 8f18
  manual, 8f17

Design section, 612
Design size, 402
Design software, 33–35
Detail drawings, 617
Detail notes, 412–414
Detroit Automation, 765
Developments, 338–339
  bends in, 353–355
  design practices, 338–339
  laps and seams, 338
  notches in, 353
  surfaces, 338
  thickness of materials, 339
Development surfaces, 338
DFM guidelines, 624–625
DFM procedure, 623–624
Diameter, 106
Diameter, expanded, 526
Diametral pitch (P), 595–596
Diamond, John, 118
Die casting, 730
Diesel, John, 206
Difference Engine, 24
Digital computers, 24
Digitizers, 28
Dihedral angles, 271
Dimension components
  arrowheads, 378
  dimension lines, 375–377
  extension lines, 374–375
  leader lines, 377
Dimensioning, 372
  callouts for counterbored holes, 387
  callouts for countersunk holes, 387
  callouts for tapered holes, 386–387
  chords, arc, and angles, 379–380
  concentric and nonconcentric shafts, 396
  cones, 395–396
  contours not defined as arc, 382
  curved surfaces, 381
  cylinders, 388
  double, 389
  drill size tolerancing, 384
  external chamfers, 391–392
  flat tapers, 394
  foreshortening radii, 381
  head fits for undercuts and chamfers, 392
  hidden lines, 391
  hole locations, 384–386
  holes on a bolt center diameter, 396–397
  internal chamfers, 392
  internal slots, 389–390
  irregular curves, 382
  isometric, 669
  keyways, 393
  knurls, 392–393
  locating holes about a bolt center, 385
  locating holes on center lines and concentric arcs, 385–386
  multiple holes on same center line, 386
  multiple radii, 382
  necks and undercuts, 392
  not-to-scale (NTS), 391
  by offset (flat objects), 383
  by offset (round objects), 383
  offsets, 381
  pads and bosses, 394–395
  pipe drawings, 778
  pyramids, 395
  radii, 380–381
  rectangular coordinates, 396
  reference, 389
  repetitive features, 386
  rounded ends, 390–391
  round holes, 383
  round tapers, 394
  sectional views, 395
  sheet metal bends, 395
  simple hole callouts, 384
  specific techniques, 379–399
  spheres, 383
  spotfaced holes, 387–388
  spot welds, 714–715
  squares, 389
  steps in, 378–379
  symbols, 379
  threads, 394
Dimensioning rules, summary of, 410–411
Dimensioning systems, 372–373, 372–374
  decimal-inch dimensioning, 373
  fractional dimensioning, 373–374
  orienting, 374
Dimension lines, 83, 375–377
Dimensions
  laying out, 378
  staggered, 392
Dimetric, 8f12
Dimetric drawings, 32, 671
Direction of winding, 561
Displacement diagram, 576
Display monitors, 27
Dividers, 45
Dot-matrix plotters, 29
Dot matrix printers, 29
Double-curved surfaces, 338
Double dimensioning, 389
Double welds, 707–708
Dowel pins, 750
Draft, 729
Drafters, 8
Drafting, 8, 25–26
Drafting brush, 51
Drafting equipment
  care of, 67–68
Drafting instruments, 38–70
Drafting machines, 40–43
Drafting software, 31–32
Drafting standards, 13, 15
Drafting tables, 68
Drafting technicians, 8
Drag, 729
Drawing (metal), 733
Drawing revisions, 620–621
Drawings
  centering, 172–173
  described, 3
  numbering, 173–174
  planning for, 171–172
  positioning views in work area, 172
  structural concrete, 801
  structural steel, 796
  three-view, preparing, 171
  types of, 3
Drawings, checking, 618–619
Drawing sets, 43–51
Drawing surfaces, 39
Drill bushings, 749–750
Drill presses, 735–736
Drill size tolerancing, 384

Drop-bow compasses, 44
Drop forging, 731
Drum plotters, 28
Dry cleaning powder, 51
Dry transfer sheets, 68
Dugan, John, 567
Duplex fixture, 742
Dwell, 576
3D wireframe modeling, 447, 461

E
Eave struts, 801
  connection details, 809–811
Eccentric circles, 107
Edge view of plane surfaces, 268–269
Efficiency, 40
Elastomers, 728
Electrical discharge grinding (EDG), 756
Electrical discharge machining (EDM), 755
Electrical discharge wire cutting (EDWC), 755–756
Electrical plans, 817
Electric erasers, 50
Electrochemical grinding (ECG), 753–754
Electrochemical machining (ECM), 754
Electrochemical turning (ECT), 754–755
Electromechanical discharge grinding (ECDG), 753
Electromechanical honing (ECH), 754
Electromechanical machining (EMM), 753
Electron beam machining (EBM), 755
Electrostatic plotters, 29
Elevations, 812
Ellipse on an inclined plane, 669
Ellipses instruments, 57
Endwall framing and sheeting plans, 806
  drawing, 806–808
Engineering change orders (ECO), 620
Engineering change requests (ECR), 620
Engineering departments
  application engineering, 621–623
  mass protection company, 623–629
  quotation department, 621–623
  systems company, 611–623
Engineering drawings, 11, 12
Engineering materials, 724–728
  alloy steels, 725
  aluminum, 726
  carbon steels, 725
  cast irons, 726
  cast steels, 726
  ceramics, 728
  composites, 728
  copper, 726–727
  elastomers, 728
  high-performanc alloys, 726
  high-strength, low-alloy steels, 725
  lead, 727
  magnesium, 727
  maraging steels, 726
  metals, 725
  molybdenum, 726
  nonmetals, 727
  plastics, 727
  powedered metals, 727
  refractory metals, 726
  stainless steels, 725
  thermoplastics, 727–728
  thermosets, 727
  tin, 727
  titanium, 726
  tungsten, 726
  zinc, 727
Engineering visualization applications
  automotive crash simulations, 457
  computational fluid dynamics (CFD), 455–456
  design, 454
  finite-element analysis (FEA), 454
  kinematic simulations, 457
  pre-assembly analysis, 456–457
  thermal analysis, 454–455
Engineering visualization case studies, 458–460
  biomedical visualization, 458–459
  product design, 459–460
Enlargement of the auxiliary view, 246–247
Envelope, actual mating, 467–468
Equilateral triangle, 105
Erasers, 50
Erasing shields, 50
Expanded diameter, 526
Exploded isometric drawings, 671
Extension lines, 83, 374–375
Extension springs, 559
  drawing instructions, 565–566
External broaching, 738
External rings, 540
Extracting, 830
Extruding, 732

F
Fasteners, classification of, 512
Fasteners and shafts, 215
Fastening devices, 750
Fastening systems, 530
Feature, 468
Feature, axis of, 468
Feature, center plane of, 468
Feature, derived median line of, 468
Feature, derived median plane of, 468
Feature control symbols, 481
Feature of size, 468
Field welds, 706–707
Files, 66–67
Fillets, 174, 670
Fillet welds, 708
Finishing impression, 731
Finish marks, 397–399
Finish symbols, 715
Finite-element analysis (FEA), 33, 454
Finite-element model (FEM), 454
First-angle projection, 182–183
Fit, 400, 403, 468
Fitness Equipment Corporation (FEC), 715
Fit tables, using, 407–410
Fixed-renewable bushings, 749
Fixtures, 740–742
Flagstone, Margaret, 425
Flanged fittings and joints, 772
Flange welds, 712–713
Flasks, 729
Flatbed plotters, 28
Flatness, 468, 483–484
Flat-plane surfaces, 338
Flat springs, 560
Flat tapers, 394
Flexible manufacturing systems (FMS), 13, 763–766
Floor plans, 811–812
Fold lines, 162–163, 239–240, 262–263
Foolproofing, 743
Foreshortening, 161

Forge welding, 699
Forging, 731
Forming, 733
Form tolerance, 468
Foundation plans, 811
Fractional dimensioning, 373–374
Freehand break lines, 83, 180
Freehand lettering, 78, 81–83
Free length, 560
Free-state variation, 468, 474
French curves, 47–48
Friction-joint compasses, 43
Frontal viewing plane (R), 262
Front views, 163
Full-divided scales, 51
Fuller, 731
Full indicator movement (FIM), 483–484
Full sections, 204–205
Fulton, Doug, 582
Fusion welding, 699
Fusion welds, 699

G
Gage numbers, 339
Gates, 729
Gate valves, 772
Gear blanks, 598–599
Gear ratio, 593–594
Gears
  bevel, 604
  blanks, 598–599
  design and layout of, 606
  gear train, 601–602
  materials, 605–606
  rack gears, 601
  required tooth-cutting data, 602
  types of, 591–593
  worm, 604–605
Gear templates, 598
Gear tooth calipers, 602–604
Gear trains, 601–602
Generalizing, 830
General notes, 412
General oblique drawings, 672
General tolerancing, 469–470
Geographic information systems (GIS), 465, 826–830
  attribute queries, 830
  and CAD, 830
  key concepts, 827–828
  spatial analysis, 829–830
  using, 828–829
Geometric dimensioning and tolerancing
  defined, 470–471
  terms, 467–469
Geometric nomenclature, 104–108
Girt connection details, 809
Girts, 801
Globe valves, 772
Gothic lettering, single-stroke, 79–80
Gourad shading, 449
Grade percents, 280–281
Grades, 278–284
Graphic communication, 3
Graph paper, 88
Gravity, 626
Green sand, 729
Grinders, 737
Grooved fasteners, 526–527
Grooved studs, 527
Groove radius, 710
Groove welds, 708–710
Ground line (GL), 674
Group technology, 420
  advantages and disadvantages of, 424–425
Guide for Patent Drawings, A (U.S. Government Printing Office), 629
Guidelines, lettering, 81–82

H
Half auxiliary sections, 245
Half sections, 206–207
Hardening, 751
Harmonic motion, 577
Headings, 281–282
Heating-ventilation/air-conditioning plan (HVAC), 812, 816–817
Heat treatment of steels, 750–751
Helical gears, 593
Helical springs
  compression springs, 558–559
  extension springs, 559
  torsion springs, 560
Helix, 139–140
Hemispheres, 108
Herringbone gears, 593
Hexagons, 118–119
Hex-head bolts, 521–522
Hidden-line calculations, 447
Hidden lines, 83, 168–169, 237, 391, 664
High-performance alloys, 726
High-strength, low-alloy steels, 725
Hole callouts, simple, 384
Hole limits, 401
Hole locations, 384
Holes
  producing, 733
  representation of, 178–180
Holography, 451
Horizon (H), 674
Horizontal boring mills, 738
Horizontal lines, 83–84
Hydrodynamic machining, 751–752
Hyperbola, 129

I
Illustrations. *See also* renderings, 3
Inch spur gears, 598
Incomplete views, 178
Indexing fixtures, 742
Indexing jigs, 740
Industrial robots, 761–766
Inkjet printers/plotters, 29
Ink tools, 57
Input devices, 28
Inside diameter, 561
Instruments, conventional, 38–70
Integrated circuit (IC) chip, 25
Interference fit, 401–402
Intermittent welds, 703–704
Internal broaching, 738
Internal rings, 540
Internal slots, 389–390
International Organization for Standardization (ISO), 512
Internship development program (IDP), 1
Intersecting surfaces, 175, 215–216
Intersections, finding
  cylinder and plane surface by line projection, 277–278
  spheres and plane surfaces, 278

two planes by line projections, 277
two prisms, 278
Interval, 824–825
Invention agreements, 628–629
Investment casting, 730
Involute curves, 594–595
Involutes, 141–143
Irregular curved surfaces, 243–244, 382
Irregularly shaped objects, 664–665
ISO 9000, 13
Isometric
arcs, 665–669
assemblies, 671
circles, 665–669
curves, 664
dimensioning, 669
drawings, 32, 660–662, 671
ellipse templates, 665–669
fillets, 669, 670
intersections, 669
knurls, 670
mechanical drawings, 14
piping schematics, 15
projections, 8f11, 671
rounds, 669, 670
ISO metric thread form, 513
Isosceles triangle, 105

J
Jigs, 739–740
Johnson, Dan, 88
Joints and fittings, 771–772
Just-in-time manufacturing (JIT), 13, 766–767
process synchronization, 766–767
simplicity, 767

K
Keyboards, 28
Keys, 525
Keyseats, 525
Key sizes, 525
Keyways, 214, 393
Kinematic simulations, 457
Kinematic software, 33–35
Knuckle thread form, 514
Knurls, 392–393, 670
Konrad, Betty, 209
Kroy machine, 70

L
Lap joints, 523
Laps, 338
Laser beam machining (LBM), 756
Laser printer/plotters, 29
Lathes, 734, 738
Layout drawings, 613–614
Lead, the (of helix), 140
Leader lines, 377
Lead holders and leads, 49
Lead (metal), 727
Leaf jigs, 740
Least material condition (LMC), 400, 468, 474
Left-handed drafters, 40
Left-hand threads, 515–516
Left-side viewing plane (L), 262
Legal descriptions, 817, 823
Lettering
characteristics of, 80–81
guidelines, 81–82
machines, 70
styles, 78–81
Letter sizes, 61
Lighting, 39
Limit dimensions, 468, 470
Limited planes, 268
Limits, 400, 468
Liner bushings, 749
Lines, 104
characteristics of, 83
profile of, 468
Lines, constructing
with specified bearing, percent of grade, and length, 284
with specified bearing, slope angle, and length, 282–284
Line visibility, determining, 272
Line work, 83–85
Loaded length, 561
Location limits, 402–403
Location tolerance, 468
Locators, positioning of, 742
Locators, types of, 745
Lot and block descriptions, 817, 823
Lowercase letters, 261–262

M
Machine screws, 519, 520
Machining, traditional, 734–739
Machining processes, nontraditional, 751–758
Magna-Tech Manufacturing, 425
Magnesium, 727
Malone, Mark, 678
Manufacturing, 724–725
Manufacturing part family, 420–422
Manufacturing precision, 410
Manufacturing processes, 728–729
Manufacturing resource planning (MRPII), 767
Maraging, 726
Maraging steels, 726
Martensite age hardening, 726
Martinez, Juan, 425
Mass production company, 623–629
Matching parts, 403–404
Material requirements planning (MRP), 767
Materials handling, 425
Maximum and minimum locations, 403
Maximum and minimum sizes, 402
Maximum material condition (MMC), 400, 468, 471–472
McCrory, Marge, 582
McDaniels, Carla, 715
McRae, John, 61
Mean diameter, 561
Measuring line (M), 674
Mechanical break lines, 83
Mechanical drawings, 10, 14
Mechanical engineer's scale (decimal), 53
Mechanical engineer's scale (fraction), 52
Mechanical illustration, 6f5, 6f6
Mechanical lettering sets, 59–62
Metals, 725
Metal Tech Manufacturing Company (MTM), 20
Metes, 817
Metes and bounds systems, 817
Metric dimensioning, 372–373
Metric scales, 54
Metric spur gears, 598
Microfinish comparator, 57
Microgrip plotters, 28
Micrometers, reading, 54–56
Micro-miniaturization, 25

MicroTron Engineering, 61
Milling machines, 734–735
Minot Machine Tool Company, 567
Miter gears, 592
Modeling
  3D, 447
  defined, 446
  3D wireframe, 461
  parametric solid, 448–449
  solid, 447–448, 461
  surface, 447
  techniques, 446–449
Modified angle plate fixtures, 741
Modified angle plate jigs, 740
Modified purchased parts, 618
Modified uniform velocity, 577
Modifiers, 468
  all around symbol, 475
  datums, 476–481
  free-state variation, 474
  least material condition (LMC), 474
  maximum material condition (MMC), 471–472
  projected tolerance zone, 474, 482–483
  regardless of feature size (RFS), 472–473
  statistical tolerancing symbol, 475–476
  between symbol, 475
  tangent plane, 474–475
Mold lines, 395
Molybdenum, 726
Montgomery Engineering Company (MEC), 245
Mouse, 28
Movement, 453, 743–744
Multiple reference lines, 713
Multiple threads, 515
Multisection views, 204
Multistation jigs, 740
Multiwelds, 707–708

N
NASA Ames Research Center, 450
Necks, 392
Network analysis, 830
Nominal dimensions, 391, 400
Nominal size, 400
Nonisometric lines, 663
Nonmetals, 727
Nontraditional machiningi, 751
Normalizing, 751
North/south deviation, 279
Notations, 261–262
  detail notes, 412–414
  general notes, 412
  rules for applying, 411–412
  sample notes, 414–420
  specifications, 414
  writing, 414
Notches, 353
Not-to-scale (NTS) dimensions, 391
Numbering systems, 620
Numerically controlled machines, 738–739
Nuts, 522

O
Oblique drawings, 32, 660
  cabinet drawings, 672
  cavalier drawings, 672
  general oblique drawings, 672
Oblique projections, 4
  cabinet, 7f9
  cavalier, 7f10
Oblique sketching, 87, 91–92
Oblique surfaces, 245–246
Obtuse angle triangle, 105
Octagons, 119–120
Offset followers, 578
Offset measurements, 662
Offsets, 381
Offset sections, 205–206
Ogee curves, 125–127
One-point perspective, 8f14, 93
Open-carriage typewriters, 69–70
Open-divided scales, 51–52
Open jigs, 739
Opitz system, 423–424
Optical comparators, 495
Orienting dimensions, 374
Orthgraphic sketching, 90
Orthographic drawings, 31
Orthographic projections, 4
  center lines, 169
  dimension transfer methods, 167–168
  hidden lines, 168–169
  labeling two views, 163–165
  multiple views, 165–167
  multiview drawings, 7f8
  normal surfaces, 161–162
  object description requirements, 167
  surface categories, 170
  two views, 162–163
Orthographic sketching, 86–87
Output devices, 28–29
Outside diameter (OD), 561, 596

P
Pads, 394–395
Pan head rivets, 523
Paper sizes, 64–66
Parallel, 575
Parallelism, 468
  of an axis or center plane, 491–492
  of a surface, 490–491
Parallel line developments, 338, 339–346
  truncated cylinders, 343–346
  truncated prisms, 342–343
Parallel lines, 85
Parallel projections, 4
Parallel straightedges, 40
Parameters, 448
Parametric solid modeling, 448–449
Part families, 420–422
Partial auxiliary views, 244
Parting, 732–733
Parting lines, 729
Parts
  bending, 733
  forming, 733
  locating principles, 742–745
  matching, 403–404
Parts classification and coding
  combined attribute groups, 422
  design attribute groups, 422
  manufacturing attribute groups, 422
  sample systems, 422
Parts lists, 211, 619
Patent drawings, 629
Patterns, 729–730
Pencils and leads, 49
Pens, 62
Pensacola Prestressed Concrete
    Company, 678

Pen speed, 28
Pentagons, 118
Perforating, 733
Permanent fasteners, 512
Perpendicular, 575
Perpendicularity, 468
  of an axis or center plane, 493–494
  of a surface, 492–493
Perpendicular lines, 85
Personal technical files, 627–628
Perspective drawings, 32, 673–677
  presketching, 674
  terms, 674
  two-point perspective drawing, 675–677
Perspective projections, 4–5, 159
  one-point, 8f14
  three-point, 8f16
  two-point, 8f15
Perspective sketching, 88, 92–95
Perspective views, 677–678
  circles and arcs, 677–678
  irregular curves, 677
Phantom lines, 83
Phong shading, 449
Photochemical machining, 757
Photorealism, 449
Pictorial drawings
  isometric drawings, 660
  oblique drawings, 660
  purpose of, 660
Picture plane (PP), 674
Piercing points, determining
  by construction, 273–274
  by inspection, 273
  by line projection, 274–277
Pinion gears, 591
Pipe drawings, 776–778
  single-line, 776–778
  single-line isometric, 785
Pipes, 771
Piping drawings, 17
Pitch, 281, 515
Pitch diameter (D), 595
  terminology, 595–598
Pixels, 27
Placing drawings, 801
Plain holes, 179
Planers, 737
Planes, projecting, 268
Plane surfaces, 338
Plasma arc machining (PAM), 756–757
Plastic pipes, 771
Plastic tools, 67–68
Plate fixtures, 741
Plate jigs, 739
Plot plans, 811, 823–824
Plotters, 28, 32
Plug welds, 711–712
Pocket steel rulers, 54
Point-in-polygon responses, 829
Points, 104
Points in space, locating, 263–264
Point-to-point machines, 738
Point view of a line, constructing, 264–266
Polygon, 105
Polygon construction
  equilateral triangles, 116–117
  hexagons, 118–119
  octagons, 119–120
  pentagons, 118
  squares, 117
  triangles with known lengths of sides, 116
Polygon overlay, 830
Polyhedron, 107
Positioning locators, 742
Position tolerance, 468
Position tolerancing, 470, 498–500
Powdered metals, 727
Powder metallurgy, 730–731
Power saws, 736
Pre-assembly analysis, 456–457
Precision grinders, 737
Precision Machining, Inc., 88
Precision Metal Components (PMC), 183
Pre-engineered metal buildings, 801–811
  anchor bolt plans, 804
  connection details, 808–811
  eave strut connection details, 809–811
  girt connection details, 809
  materials used in, 801–804
  purlin connection details, 809
  rigid-frame cross sections, 804–806
  roof framing and sheeting plans, 806
  sidewall and endwall framing and sheeting plans, 806
Press-fit bushings, 749
Press forging, 731
Pressure angle, 599
Prestressed concrete drawings, 18
Primary datum, 468, 500
Principal viewing planes, 166–167
Printers, 28
Prism, 107
Process synchronization, 766–767
Production scheduling, 425
Profile, 494–496
  of a line, 468, 495
  of a surface, 468, 495
  tolerances, 495
  tolerance zone, 468
Projected tolerance zone, 468, 474, 482–484
Projection plane, 7f7
Projections, 4–5
Projection welds, 715
Proportional dividers, 46
Proposals, 621
Protractors, 49
Punching, 733
Purchased parts, 617–618
Purlin, 801
Purlin connection details, 809
Pyramids, 107–108, 395

Q

Quadrant, 107
Quadrilateral, 105
Quality control, 425
Quench, 751
Quotation departments, 621–623

R

Rack gears, 591, 601
Radial line developments, 338
  truncated cones using, 347–349
  truncated pyramids using, 346–347
Radii, 380–381, 382
Radiosity, 450
Radius, 106
Raster display monitors, 27
Raster displays, 27
Raster scanning, 27

Ray tracing, 450
Real estate, plotting boundaries of, 284–285
Rectangular system, 825
Reference dimensioning, 389
Reference dimensions, 468
Refractory metals, 726
Regardless of feature size (RFS), 469, 472–473, 472–474
Relational database management systems (RDBMS), 828
Relational data models, 827–828
Relationships, 453
Removed sections, 209–210
Renderings. *See also* illustrations, 3
Renewable bushings, 749
Repeatability, 742
Residential plans, 811
Resistance welding, 699
Resolution, 27, 29
Retaining rings, 539–549
Revolved sections, 207–209
Reynolds Manufacturing, Inc. (RMI), 744
Reynolds Tool and Die Company, 526
Ribs and webs, 212–214
Right-hand threads, 515–516
Right-side viewing plane (R), 262
Right-side views, 163
Right triangle, 105
Rigid-frame cross sections, 804–806
Ring gears, 592
Risers, 729
Rivet joints, 523
Rivets, 523–525
  drawing, 523–524
  end points, 525
Rivet symbols, 523
Roberts, Mark, 744
Robots, 626, 761–766
Robot systems
  controller, 762–763
  end-of-arm tooling, 763
  mechanical arms, 763
  power sources, 763
Rolling, 731
Roof framing plans, 806
Roof panels, 804
Roof plans, 817
Root diameter (DR), 597
Root openings, 709–710
Rotary ultrasonic machining (RUM), 752–753
Rotation, 576
Rounded V notch, 353
Round holes, 383
Roundness, 487–488
Rounds, 174, 670
Round surfaces, 241–242
Round tapers, 394
Rule #1, 485
Runouts, 174, 469, 496

S

Sand casting, 729
Sandpaper paddles, 50
Sandwich jigs, 739
Saws, 736
S breaks, 180
Scalene triangle, 105
Scales, 51–57
Schematic phase, 1
Schultz, Terry, 697
Scientific design, 613
Screwed fittings, 772
Screws, 518
Screw thread forms, 513–514
Screw threads, 670
Scriber templates, 59–60
Seams, 338
Seam welds, 716
Secondary auxiliary views, 244
Secondary datum, 469, 500
Sectional views, 202, 395
Section lines, 83
Section lining, 83, 203, 703
Sections, 825–826
Sector, 107
Segment, 107
Self-locking rings, 541
Semicircle, 107
Set blocks, 750
Set screw, 520–521
Shaft limits, 401
Shafts and fasteners, 215
Shapers, 737
Sharp V notch, 353
Shaving, 733
Shearing, 732
Sheeting angles, 801, 804
Sheeting plans, 806
Shrinkage, 729
Shrink rule, 729
Sidewall framing and sheeting plans, 806–808
Sight, direction of, 202–203
Simple hole callouts, 384
Sims, Maria, 88
Simulation software, 35
Single-curved surfaces, 338
Single-stroke Gothic lettering, 79–80
Single threads, 515
Size, virtual control of, 469
Size control, 733
Size limits, 402
Size tolerance, 469
Sketches, 614, 621
Sketching, 85–88
  axonometric, 90–91
  circles, 89
  ellipses, 89–90
  materials for, 88
  oblique, 91–92
  orthographic, 90
  perspective, 92–95
  procedures, 172
  proportion in, 90
  straight lines and curves, 89
  techniques for, 88–95
Sketchpad, the, 24
Slip-renewable bushings, 749
Slitting, 733
Slope, 278–284, 281
Slope angles, 280
Slots, internal, 389–390
Slot welds, 711–712
Smooth shading, 449
Socket-head cap screws, 750
Software, 30–35
Solid length, 560
Solid modeling, 33–35, 447–448, 461
Spatial analysis, 829–830
Spatial data, 827–828
Spatial queries, 829

Spatial visualization
one-dimensional, 159–160
three-dimensional, 160–161
Spheres, 108, 383, 670
Spiral bevel gears, 592
Spokane CAD Consultants, 697
Spokes and keyways, 214
Spotfaced holes, 180, 387–388
Spot welding, 713–714, 713–715
Spring-bow compasses, 43
Spring classification, 558
Spring design layouts, other, 566
Spring pins, 527–530
Springs, 558
drawing data required, 561
flat, 559
helical, 558–560
isometric views of, 566–568
other design layouts, 566
section views of, 566
standard drafting practices, 566
terminology of, 560–561
Sprue holes, 729
Spur gears, 591
drawing teeth, 597–598
drawing two teeth in contact, 599–601
metric, 598
Square bolts, 521–522
Squares, 389
Square thread form, 513
Staggered dimensions, 392
Staggered intermittent welds, 704
Stainless steels, 726
Stamped rings, 539
Stamping, 732–733
Standard drafting practices, 566
Standard fits
clearance locational fits (LC), 404
force and shrink fits (FN), 407
interference locational fits (LN), 404
running or sliding clearance fits (RC), 404
transition locational fits (LT), 404
Standardization, 424–425
Standards of practice, 13, 15
Standard templates, 61
Station point (SP), 674
Statistical process control (SPC), 13, 767
Statistical tolerancing symbol, 475–476
Steel pipes, 771
Stereo images, 450–451
Still images, 449–450
Stitch line, 83
Storage devices, 29
Storage-tube displays, 27
Straightedges, parallel, 40
Straightness, 469, 484
of axis or center plane, 486–487
of cylindrical surfaces, 484–486
of flat surfaces, 484
Straight pipe threads, 772
Stress, 454
Stretchout lines, 340
Structural concrete drawings, 801
Structural drafting, 788–801
Structural drawings, 11, 16, 799
Structural members, connecting, 794–796
Structural products, 789–794
Structural steel drawing, 799
Structures, 788
Students
learning checklist for, 15
requirements of, 13
Studs, 518
Subassembly drawings, 616–617
Superfluous dimensioning, 389
Supplementary construction
cycloidal curves, 143
helices, 140–141
involutes, 141–143
spirals, 139–140
Surface, profile of, 468
Surface categories, 170
Surface grinders, 737
Surface modeling, 447
Surface welds, 712
Surveys, 284
Sutherland, Ivan, 24
Sutton, Mark, 33
Symbols, 379
Symmetry, 469, 498

T

Table jigs, 739
Tabular dimensioning, 399
Tabular drawing, 399
Talking sketching, 78
Tangent plane, 469, 474–475
Tap and die, 514
Tapered holes, 179
Tapered pipe threads, 772
Tapers, 394, 626
Technical drawings, 3
aligned features, 178
applications of, 9–13
architectural, 10
civil, 11
conventions, 174–180
curve plotting, 176
cylindrical intersections, 177–178
electrical, 11
engineering departments and, 611
HVAC, 11
incomplete views, 178
intersecting surfaces, 175
purpose of, 5–9
quality and competitiveness, 13–20
regulation of, 13
rounds and fillets, 174
runouts, 174
structural, 11
types of, 4–5
Technical pens, 57–59
Tempering, 751
Template jigs, 739
Templates, 47
Temporary fasteners, 512
Tertiary datum, 469, 500
Tessellation, 449
Text, 78
Texture mapping, 449
Thermal analysis, 454–455
Thermoplastics, 727–728
Thermosets, 727
Thickness gage, 339
Thinwall sections, 210
Thompson Engineering International (TEI), 461
Thread call-offs, 522–523
Threaded fasteners, 394

Thread relief (undercut), 517–418
Thread representation, 516–517
  schematic system of, 516–517
  simplified system of, 517
  standard external, 517
  standard internal, 517
Threads, 512
Threads per inch (TPI), 514–515
Three-dimensional (3D) drawings, 32
Three-point perspective, 8f16
Through holes, 179, 384
Time interval, 576
Timing diagrams, 581
Tin, 727
Titanium, 726
Title blocks, 618
Tolerance, 400, 469, 743
Tolerance zones, 468
Tolerancing, 399–401
Tool forces, 747
Tools, plastic, 67–68
Top covers, 39
Topographic topics, 284–311
Topology, 446, 828
Top viewing plane (T), 262
Torres, Alexander, 157
Torsion springs, 560
Total runout, 469, 496
Touch-panel displays, 28
Townships, 825
Tracing pens, 61
Trahan, Mary, 465
Train value, 601
Transfer cards, 68
Transition fit, 401, 402, 469
Triangles, 46–47, 105, 128
Triangulation, 349
Triangulation development, 349
  transitional pieces, 349–350
  transitional pieces with no fold lines, 351–353
  transitional pieces with round ends, 350–351
Triangulation developments, 338
Trimetric, 8f13
Trimetric drawings, 32, 672
Trimming, 733
True angles, 271
True distance, 349
  between line and point, 266
  between nonparallel (or skewed) lines, 267–268
  between parallel lines, 266–267
  between plane surface and point, 270–271
True geometric counterpart, 469
True length, 264, 280, 349
True-length diagrams, 349–353
True position, 469, 481–482
True slope, 280
Truss head rivets, 523
T-squares, 39, 40
Tungsten, 726
Two-and-one-half-dimensional (21/2D) tasks, 32
Two-dimensional (2D) tasks, 31–32
Two-point perspective, 8f15, 94–95, 675–677
Typewritten text, 69–70

U

Ultrasonically assisted machining (UAM), 753
Ultrasonic machining (USM), 752
Undercuts, 392
Unidirectional dimensioning, 374
Unified National thread form, 513
Unified Screw Thread, 512
Uniform acceleration, 577
Uniform velocity, 577
Unilateral tolerance, 400, 469, 470
United States Air Defense Command, 24
United States Standard Gage, 339
Upsetting, 731
U.S. Bureau of Land Management, 825
U.S. Department of Defense (DOD) standard, 13
U.S. Military (MIL) standard, 13

V

Valdez, Anna, 245
Valves, 772, 776
Vanishing point (VP), 674
Vargas, Juanita, 799
Variable representation
  color, 452
  shapes, 452–453
  symbols, 453
Verification, 414
Vernier caliper, 56
Vertical boring mills, 738
Vertical lines, 83–84
Vertical turret lathes, 738
Vibration, 626
Viewing planes, 83, 246
Virtual condition, 469, 486
Virtual reality, 451–452
Vise jaw fixtures, 741–742
Visible rays (VR), 674
Visualization, 180–182
  defined, 445
  factors in, 445–446
Visualization images
  animation, 450
  holography, 451
  stereo images, 450–451
  still images, 449–450
  virtual reality, 451–452
Voice recognition, 28
VRML (Virtual Reality Modeling Language), 451–452

W

Wall sheeting panels, 804
Walton, Peter, 607
Warped surfaces, 338
Water jet machining (WJM), 757
Webs and ribs, 213–214
Weight gage, 339
Welded fittings and joints, 772
Welding
  processess, 699
  process references, 705
Welding joints, 707
Welding templates, 716
Weldments, 716–717
Welds
  depth of, 709
  length of, 702–703
  placement of, 703
  size of, 700–702, 708–709
  types of, 707–713
White, Jerry, 715
Whiteprinters, 66
Whitworth, Joseph, 512
Whitworth Threads, 512
Whole depth (HT), 596

Winding, direction of, 561
Wire-formed rings, 539
Wireframe drawings, 32
Wireframe modeling, 33
Wire size, 561
Working circle, 576
Working depth (HK), 596
Working drawings, 615–618
  assembly drawings, 615–616
  detail drawings, 617
  modified purchased parts, 618
  purchased parts, 617–618
  subassembly drawings, 616–617
Worm, 604–605
Worm gears, 592–593, 604–605
Worm thread form, 513
Written notes, 414

X
X-Y-Z coordinates, 399

Z
Z breaks, 180
Zero tolerance at MMC or LMC, 469
Zinc, 727
Zoning, 64–66

SIXTH EDITION

TECHNICAL DRAWING
AND ENGINEERING COMMUNICATION

Develop the drawing skills you need for a successful career in CAD, drafting, or design with this comprehensive, widely successful book, now in its 6th edition! ***Technical Drawing and Engineering Communication,*** 6th Edition offers readers the "total technical drawing experience," with coverage that spans from basic to advanced aspects of engineering and industrial technology. It provides a fundamental exposure to design and visualization for computer modeling, while still presenting thorough coverage of more traditional methods of technical drawing. With revisions that reflect the very latest information on CAD, GIS, the Internet, ISO 9000, and solid modeling, this book is a valuable resource, with applications to various disciplines.

Features of this book

- new, updated photographs ensure readers view the technologies that accurately reflect what they will see on the job
- in-depth coverage of mechanical, architectural, and civil drafting is featured, with discipline-specific icons that easily denote the drawing and math problems that pertain to a reader's specific area of study
- modern design practices and standards are examined, with coverage that is updated to the latest ANSI standards
- back-of-book CD contains mechanical (CAD) drawing files that are correlated to various exercises and problems in the book

Also Available from Delmar Cengage Learning

Visualization, Modeling & Graphics for Engineering Design/Lieu & Sorby/ISBN 978-1-4018-4249-9
Structural Steel Drafting and Design, 2E/ MacLaughin & Estrada/ISBN 978-1-4018-9032-2
The Successful Drafting Technician/Goetsch/ ISBN 978-1-4354-1330-6
Engineering Drawing & Design, 4E/Madsen/ ISBN 978-1-4180-2987-6

About the Authors

David L. Goetsch has received the Secretary of Educator's Award in the Outstanding Technical Program in the U.S., as well as the Outstanding Technical Educator Award in Florida. He is a member of the American Management Association, the Florida Association of Community Colleges, and the American Society for Quality.

William S. Chalk holds a master's degree in mechanical engineering from the University of Washington. He taught for 31 years in the College of Engineering at the University of Washington and is a recipient of the Western Electric's Outstanding Instructor of the Year award Professor Chalk was also the Director of Nuclear Engineering Laboratories from 1976 to 1983. He continues to be active in engineering by lecturing to engineers who plan to take engineering license examinations and by lecturing in summer programs.

John A. Nelson has more than 31 teaching experience and was New Hampshire's Vocational Teacher of the Year. This is his 57th book.

Raymond L. Rickman is the chairman of the Manufacturing and Technology Department and Professor of Design and Drafting at Okaloosa-Walton College. Professor Rickman has extensive experience in the private sector and in the classroom and is a consultant on the subject of geometric dimensioning and tolerancing. He is a member of the ANSI Y14.5 technical committee.



DELMAR CENGAGE Learning

To learn more about Delmar, visit **www.cengage.com/delmar**
To learn more about Cengage Learning, visit **www.cengage.com**
Purchase any of our products at your local bookstore or at our preferred online store **www.ichapters.com**